

UNIT LOG

1. Project:
Toston Maudlow
Salvage Sale

2. Date Visited:
1/8/03

Prepared:
1/13/03

3. Visited:
Unit #: 32 Helicopter
Road #: 4190 and 4190B1
Other Activity:

T6N R4E Sec 1
T6N R4E Sec 1

4. Project Area
Ridgetop above Sulphur Bar
Drainage

5. (Name and Position)
Sue Farley, Soil Scientist

Helena N. F.
Townsend Ranger District
Townsend Ranger District

7. Parties Involved

Name	Position
Vince Archer	Soil Scientist
Rachel Fiegley	Wildlife Biologist
Alicia Kitto	Biological Technician

8. Activity Log

Activity Reviewed	
Helicopter Logging in unit 2	<p>Trees were hand-felled, with limbs and tops processed on site, and distributed across the unit. Patches of green trees were left intact; thus not all acres within the unit were harvested.</p> <p>We measured standing snags (Bate et al. 1999) on one, 100 meter transect across the unit. We measured down woody material (Browns method) on five, 75 foot transects as spurs spaced at regular intervals along the 100 meter transect.</p> <p>Calculations of field data for down woody material document that an average of 4.2 tons per acre of fine woody material (<3 inch diameter) plus 5.2 tons per acre coarse woody material (>3 inch diameter) have been retained following helicopter salvage harvest. These measurements of down woody material demonstrate remaining coarse woody material is in compliance with mitigation specified in the FEIS (page 97) to retain 5-12 tons per arce of CWM in the dry forest types.</p> <p>Calculated results of the snag monitoring are not available yet. The raw field data shows snags retained in the harvested portion of the unit are numerous, but are all less than 3-4 inch diameter at breast height. These snags will provide a source for future recruitment of organic material on the ground within harvested areas, and will thus facilitate long-term nutrient cycling on the site. Larger snags are present in untreated portions of the unit, and on adjacent areas.</p> <p>Visual observations document no detrimental soil surface disturbance.</p>
Main Blacktail Road 4190, and spur 4190B1	Roads are almost completely snow or ice- covered, and frozen solid (had to chain-up, as well as 4WD, for safe driving) – no resource issues were identified in association with roads

9 Findings and/or Recommendations

Helicopter units	Implementation monitoring documents compliance with mitigation specified in the FEIS for retention of coarse woody material in helicopter units (FEIS pg. 97). Visual observations document no detrimental soil surface disturbance.
Tractor units	Most tractor units are currently covered by snow, and the soil surface is not visible. It is recommended that implementation monitoring for soil quality be conducted in tractor units when ground conditions are visible after snow-melt occurs.

10. Prepared By: Sue Farley

Unit 32 - Woody Material Inventory - 01/14/2003

WOODY MATERIAL INVENTORY - DATA CALCULATIONS FOR 14-Jan-03 date printed													
Project Name	Maudlow Salvage Sale			INVENTORIED BY:	S. Parley and V. Aisher								
Unit Number	Helicopter unit 32			DATE INVENTORIED:	Jan. 8, 2003								
O - 3" LOAD tons/acre	4.20			Average Fuelbed Depth	#DIV/0!			inches					
3" + LOAD tons/acre	5.23			Average Duff Depth	0.2			inches					
Total Load tons/acre	9.43												
PLOT #	FUEL LOADING 0" - 3" Diameter				FUEL LOADING 3 plus " Diameter					Rotten Logs	DOWN WOODY	DUFF DEPTH	AVERAGE HIGH PARTICLE DEPTH
	0" - .25"	.25" - 1"	1" - 3"	Total 0" - 3"	3" - 5.9"	6" - 8.9"	9" - 20"	20" plus	Total Sound 3" plus				
1	0.08	1.76	6.78	8.61	0.00	7.10	0.00	0.00	7.10	0.00	15.71	0.3	#DIV/0!
2	0.05	1.17	2.90	4.13	0.00	0.00	0.00	0.00	0.00	0.00	4.13	0.0	#DIV/0!
3	0.42	2.05	1.94	4.41	5.29	3.18	0.00	0.00	8.47	0.00	12.88	0.3	#DIV/0!
4	0.27	0.29	1.94	2.50	4.88	0.00	0.00	0.00	4.88	0.00	7.38	0.3	#DIV/0!
5	0.09	0.29	0.97	1.35	5.68	0.00	0.00	0.00	5.68	0.00	7.03	0.3	#DIV/0!
MEAN	0.18	1.11	2.90	4.20	# 3.17	2.06	0.00	0.00	5.23	# 0.00	# 9.43	# 0.20	# #DIV/0!
S.D.	0.14	0.73	2.03	2.47	# 2.60	2.81	0.00	0.00	2.89	# 0.00	# 4.23	# 0.10	# #DIV/0!
S.E.	0.06	0.33	0.91	1.10	1.16	1.26	0.00	0.00	1.29	0.00	1.89	0.04	#DIV/0!
% Error	35.1%	29.2%	31.3%	26.3%	36.7%	61.1%	#DIV/0!	#DIV/0!	24.7%	#DIV/0!	20.1%	22.4%	#DIV/0!

INPUT														
DOWN WOODY MATERIAL INVENTORY - DATA INPUT SECTION														
PLOT #	% SLOPE	0 - .25'	.25' - 1'	1' - 3'	DUFF DEPTH		3' PLUS SOUND LOGS				ROTTEN LOGS	HIGH PARTICLE DEPTH		
					1	2	3' - 5.9'	6' - 8.9'	9' - 20'	20' +		1	2	3
1	6	6	6	7	0	0.5					7.2			
								6.3						
2	6	4	4	3	0	0								
3	6	33	7	2	0	0.5				4.2				
							4.3		6.4					
							4.2							
							3.6							
4	6	21	1	2	0	0.5				5.2				
							5							
							3.3							
5	6	7	1	1	0	0.5				3.6				
							4.9							
							4.5							
							4							

Project Name
Unit Number
INVENTORIED BY:
NUMBER OF PLOTS TAKEN
DATE INVENTORIED:

Maudlow Salvage Sale
Helicopter unit 32
S.Farley and V.Archer
5
Jan. 8, 2003

0" to .25" transect length	6	feet
.25" to 1" transect length	6	feet
1" to 3" transect length	15	feet
3 plus" transect length	60	feet

FUEL INVENTORY PARAMETERS

	diameter squared	a	s
0" to .25"	0.0120	1.15	0.48
.25" to 1"	0.2780	1.13	0.48
1" to 3"	2.8300	1.10	0.40
3 plus" SOUND		1.00	0.40
3 plus" ROTTEN		1.00	0.30

Date: 1/8/2003 Site Name/Code: MANTLEWOOD - UNIT 32 BARNED/ HELI-LOGGED

Farley / Archer

Downed Fuel Inventory Form

Block artment	Sub-compartment	Aspect	S
	Stand Elevation	Cover Type	DF - CARU
		Habitat Type	

Size Class (In):	0-1	1-3	3+
Length of Sampling Plane (Ft):	15 - 21 ft.	15 - 30 ft.	15 - 75 ft.

Plot No.	Slope	No. of Intersections			Duff Depth		3+ Diameter					Fuel Depth				
		0-25"	25-1"	1-3"	First	Second	I Sound	II Sound	III Sound	IV Rotten	V Rotten	Rotten	First	Second	Third	
1-1	40	6	6	7	D 0	0.5		7.2								
					L 0.5	0.5		6.5								
1-2	40	4	4	3	D 0	0										
					L 0	0										
1-3	40	33	7	2	D 0	0		4.3								
					L 0	0.5		4.2								
								6.4								
								4.2								
								5.2								
1-4	40	21	1	2	D 0	0		5.2								
					L 0	1.0.5		5.0								
								3.3								
1-5	40	7	1	1	D 0	0.5		3.6								
					L 0	0.5		4.9								
								4.5								
								4.0								

Ground Fuel Composition:

If heavy slash, code 1:

Species	Percent
1.	
2.	

GENERAL FORM

PROJECT: PRESCRIBED FIRE AND BIRDS OF PONDEROSA PINE FORESTS IN THE INTERIOR WEST

STUDY LOCATION MT UNIT NAME 32 TREATMENT Heli PERIOD STRATUM

DATE 1/8/03 RANDOM PT# RECORDERS Feigley, Kitto, Farley

GPS LOCATION: N Top of unit on NE corner

REFERENCE POINT:

COMMENTS:

Downy woodpecker activity within and adjacent to unit.
Hairy woodpeckers (2) observed on Douglas fir snag, ~ 8" dbh

SPECIAL DIRECTIONS TO LOCATION:

MAP:

UNIT LOG

1. Project:
Toston Maudlow
Salvage Sale

2. Date Visited:
1/8/03

Prepared:
1/13/03

3. Visited:
Unit #: 29, 30, and 31
Road #: 147, 147A1 and
4187
Other Activity:
T7N R4E Sec 35,36 - Unit # 29
T6N R4E Sec 1,2 - Unit # 30
T6N R4E Sec 1,2 Unit # 31

4. Project Area
Sulphur Bar Drainage

5. (Name and Position)
Sue Farley, Soil Scientist

7. Parties Involved T7N R4E Sec 35, 36 - Unit 29
T6N R4E Sec 1, 2 - Unit 30
T6N R4E Sec 1, 2 - Unit 31

Name	Position
Vince Archer	Soil Scientist
Rachel Fiegley	Wildlife Biologist
Alicia Kitto	Biological Technician

8. Activity Log

Activity Reviewed	
Helicopter Logging in units 29, 30 and 31	Trees were hand-felled, with limbs and tops processed on site, and distributed across the unit. Patches of green trees were left intact; thus not all acres within the units were harvested. We visually compared conditions in helicopter units 29, 30, and 31 with what we measured in unit 32. Post-harvest conditions appeared to be similar in these visually inspected units. Qualitative observations suggest down woody material is adequate for nutrient cycling (Graham et al. 1994), and is in compliance with mitigation specified in the FEIS (page 97). Snags retained in the harvested portion of the units are all small diameter (i.e. less than about 3-4 inch diameter at breast height). However, larger snags are present in untreated portions of the units, and on adjacent areas. Visual observations document no detrimental soil surface disturbance.
Log landing at bottom of helicopter unit 31 (or 30?)	This landing has been constructed with cut and fill that partially crosses the ephemeral stream channel. It is recommended that erosion control or reclamation work at this landing be completed before the period when spring runoff occurs, to prevent stream runoff from eroding the cut and fill material at this landing.
Main Sulphur Bar Road 147, with spur 147A1, and Black Butte Road 4187	Roads are almost completely snow or ice- covered, and frozen solid (had to chain-up, as well as 4WD, for safe driving) – no resource issues were identified in association with roads

9 Findings and/or Recommendations

Helicopter units	Implementation monitoring documents compliance with mitigation specified in the FEIS for retention of coarse woody material in helicopter units (FEIS pg. 97). Visual observations document no detrimental soil surface disturbance.
Log landing at bottom of helicopter unit 31 (or 30?)	It is recommended that erosion control or reclamation work at this landing be completed before the period when spring runoff occurs, to prevent stream runoff from eroding the cut and fill material at this landing.
Tractor units	Most tractor units are currently covered by snow, and the soil surface is not visible. It is recommended that implementation monitoring for soil quality be conducted in tractor units when ground conditions are visible after snow-melt occurs.

10. Prepared By: Sue Farley

UNIT LOG

1. Project: Toston
Maudlow Salvage
Sale

2. Date Visited:
7/18/02
Prepared:
7/23/02

3. Visited:

Unit #: 53
Road #: Sulphur Bar Road
Other Activity:

4. Project Area

Sulphur Bar Drainage

5. (Name and Position)

T7N R4E Sec 35
T7N R4E Sec 35

7. Parties Involved

Name

Position

Bo Stuart

Hydrologist

Sue Farley

Soil Scientist

8. Activity Log

Activity Reviewed

Sulphur Bar Road

Runoff from unit and road – adequate filtration zone in SMZ to catch sediment, but could use slash filter windrow below culvert to promote infiltration of water which is causing erosion of slope above stream

Tractor Log 3 acres

Slash spread at bottom of unit, but thin on skidding routes above, needs water bars on skid routes due to bare ground – moderate rilling on skid routes. Slope 26%, photo #3

9 Findings and/or Recommendations

Had difficulty tracking this unit in the FEIS.

10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart

UNIT LOG

1. Project:
Toston Maudlow
Salvage Sale

2. Date Visited:
7/18/02

Prepared:
7/23/02

3. Visited:
Unit #: 4
Road #: Sulphur Bar
Other Activity:

T7N R4E Sec 35
T7NR 4E Sec 35

4. Project Area
Sulphur Bar Drainage

5. (Name and Position)

7. Parties Involved

Name	Position
Bo Stuart	Hydrologist
Sue Farley	Soil Scientist

8. Activity Log

Activity Reviewed	
Tractor Log on 1 acre	Equipment tracks on hillslope had some slash placement for erosion but needs water bars; top 1/2 end of unit 35% slope; moderate rilling in skid routes. Photo #1 & 2.
Main Sulphur Bar Road	Rock on inside of ditch ☺. Culvert partially blocked -- entrance cleared with shovel, but still needs maintenance

9 Findings and/or Recommendations

	Had difficulty tracking this unit in the FEIS.

10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart

UNIT LOG		1. Project: Toston Maudlow Salvage Sale	2. Date Visited: 7/18/02 Prepared: 7/23/02	3. Visited: Unit #: 52 Road #: Sulphur Bar Road Other Activity:
4. Project Area Sulphur Bar Drainage		5. (Name and Position)		T6N R 4E Sec 2 T6N R4E Sec 2
7. Parties Involved				
Name		Position		
Bo Stuart		Hydrologist		
Sue Farley		Soil Scientist		
8. Activity Log				
Activity Reviewed				
Main Sulphur Bar Road		Erosion of inside ditch below unit – culvert partially blocked, but entrance was cleaned w/ shovel – steep back at outlet of culvert needs erosion mitigation, such as slash filter windrows and inlet ditch needs armoring (has evidence of recent substantial erosion w/ sediment delivery (fines) to Sulphur Bar		
Tractor log 2 acres		Unit has gentle terrain – 15% - some slash on skid routes; minor sheet wash on bare ground; no water bars. SMZ marked, but not necessary © Photo #4		
9 Findings and/or Recommendations				
		Had difficulty tracking this unit in the FEIS.		
10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart				

UNIT LOG

1. Project: Toston Maudlow Salvage Sale

2. Date Visited: 7/18/02
Prepared: 7/23/02

3. Visited:

Unit #: 51
Road #: Sulphur Bar Road
Other Activity:

4. Project Area

Sulphur Bar Drainage

5. (Name and Position)

T6N R4E Sec 2
T6N R4E Sec 2

7. Parties Involved

Name	Position
Bo Stuart	Hydrologist
Sue Farley	Soil Scientist

8. Activity Log

Activity Reviewed	
Sulphur Bar Road	Inside ditch partially blocked, but cleared w/ shovel; outlet @ culvert has small rill; adequate filtration zone between culvert & stream
Tractor log 1 acre	Fairly good slash distribution, w/ hummocky terrain = minor sheet wash on bare soil, but no major erosion, slope 22%, equipment access on road cut partially filled ditch already & may continue
	Photo # 5

9. Findings and/or Recommendations

	Had difficulty tracking this unit in the FEIS.

10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart

UNIT LOG		1 Project: Toston Maudlow Salvage Sale	2. Date Visited: 7/18/02 Prepared: 7/23/02	3. Visited: Unit #: 37 Road #: Sulphur Bar Other Activity:
		4. Project Area Sulphur Bar Drainage	5. (Name and Position)	T6N R4E Sec 12 NE 1/4 T6N R4E Sec 12, NE 1/4
7. Parties Involved				
Name		Position		
Bo Stuart		Hydrologist		
Sue Farley		Soil Scientist		
8. Activity Log				
Activity Reviewed				
Access route		Skid road has no functional water bars, two water bars at bottom not functional, logs lengthwise on skid road, slope of main skid road 31% - bare soil and minor sheet wash evident, slash placed up and down slope rather than on contour - no water bars		
Main Sulphur Bar Road		Drain dips in main Sulphur Bar Road needed below main skid road & before stream, sediment delivery has occurred. Under State BMP audit procedure this would have been noted as a major departue.		
		Photo #'s 6-8		
9 Findings and/or Recommendations				
		Place slash on contour, repair water bars, and place water bars on skid trails. Install drain dips on approaches to Sulphur Bar Creek.		
10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart				

UNIT LOG

1 Project: Toston
Maudlow Salvage
Sale

**2. Date
Visited:**
7/18/02
Prepared:
7/23/02

3. Visited:

Unit #:
Road #: Reconstruction
#147-A1
Other Activity:

4. Project Area

Trib to Sulphur Bar

5. (Name and Position)

7. Parties Involved

Name	Position	
Bo Staurt	Hydrologist	
Sue Farley	Soil Scientist	

8. Activity Log

Activity Reviewed	
Road 147-A1	9 drain dips armored @ outlet and show evidence of properly functioning ☺. 1 drain dip – non-functional or partially functional – needs maintenance
	SMZ designation on sale map – really not an SMZ via State law - no violation because it is not a stream, but if it was a stream then would need a site specific exemption for reconstruction or it would be a violation.

9 Findings and/or Recommendations

10. Prepared By: Notes taken by Sue Farley, Prepared by Bo Stuart

UNIT LOG

1. Project:
Toston Maudlow
Salvage Sale

2. Date Visited:
10/16/03

Prepared:
10/17/03

3. Visited:
Unit #: 17 Winter Tractor Log
Road #:
Other Activity:

T6N R4E Sec 3 NW 1/4

4. Project Area
Sulphur Bar

5. (Name and Position)
Vince Archer, Soil Scientist

T6N R4E Sec 3, NW 1/4

7. Parties Involved

Name	Position
Vince Archer	Soil Scientist
Sue Farley	Soil Scientist

8. Activity Log

Activity Reviewed	Monitoring BMP Effectiveness
skyline Summer Logging	Trees were hand fallen and then skidded using a skyline cable system during summer. Photos documented log skid trails. Based on ocular estimation, best management practices (BMPs) limited bare soil displacement below 15% threshold. BMPs had not yet been implemented for erosion control on yarding corridors at the time of this field review. However, waterbars were subsequently installed on skyline cable yarding corridors. Observations found evident skid trails with no water bars present and downward oriented logs along the skidding corridor. This log orientation would not check gully erosion as effectively as cross orientation. From above, the skid trails were not as evident as from below.
skyline Winter Logging	Trees were hand fallen and skidded using a skyline cable system. Activities took place during winter. Photos documented finished work. Observations found the best compliance of BMPs. Minimal soil was disturbed in yarding corridors and overall disturbance well below the 15% threshold. Overall, the low soil disturbance of the unit resembled higher standards of soil conservation achieved with Helicopter logging.
Winter Tractor Logging in unit 17	<p>Trees were felled using feller buncher and tractor skidded down to log landing. Temporary roads were used to haul logs to main forest road. Work was done over winter 2002/2003. Temporary roads have since been decommissioned to full recontour. Pre-existing non-system roads were ripped and seeded. BMP monitoring was initiated to check for compaction and document soil strength for future comparisons between non-logged and logged sites. In addition, this data will serve to contrast impacts of various logging systems. The data also investigates the correlation between re-emergence of sterile triticales (<i>Triticosecale rimpau</i> Wittm.) two years after planting and winter logging activities. Possibly, an unknown ecological threshold was passed that enabled triticales re-emergence.</p> <p>Soil strength measures were taken using a cone penetrometer (model 29-3739(CN-970)). Resistance and depth measures were taken throughout the unit along with information on soil cover type, presence of triticales, soil moisture, and soil disturbance class (Howes, 2000). Sampling was done at sixty gridded points to account for variability. Nine bulk density measures were taken stratified by triticales presence and topography. Sets of three samples were gathered at flat ground with triticales, moderate slope ground with triticales and moderate slope ground without triticales.</p> <p>Calculations for soil groundcover showed bare areas tended to have higher strength measures than areas with duff/litter, moss, or wood (see Figure 1). Twenty four of the sixty points had bare soil, though higher penetration resistance here cannot be directly tied to management effects. Bare soil in these areas may have topsoil loss from sheet erosion following wildfire. In</p>

addition, lack of fine roots may lead to higher penetration resistance with less soil "churning" from roots and associated soil biological activity.

Comparing soil strength data for triticale presence and absence, no significant influences were evident using a student t-test (Figure 2, $P \geq 0.1$). Field observations found less remnant duff material and overall soil cover in the triticale areas. Possibly, wildfire burning was more severe in these areas. Grid sampling picked up only 2 out of 60 points with high soil displacement (see Table 3).

Calculated results of the bulk densities found no significant differences between bulk density samples for areas of triticale and native vegetation (see Figure 3, $P=0.8$). More variability was found associated with steeper ground, probably due to greater displacement observed in these areas. The range of bulk density was high compared to sampling in non-burn areas. The loss of top litter and organics from fire may relate to higher bulk density.

9 Findings and/or Recommendations

Skyline units Both skyline units appeared to have not exceeded soil quality guidelines with bare soil below 15%. The winter logged skyline units appeared to have much less bare soil than the summer skidded skyline units. Summer skyline units need erosion control in skidtrail corridors.

Winter tractor unit Field observations found no conclusive evidence for compaction from winter logging at this unit. Penetrometer data did validate the importance of groundcover for soil conservation. Future sampling will help contrast the degree of compaction between summer and winter logged sites. Winter logging successfully minimized soil displacement to affect only 3% of the winter tractor unit. Minimal displacement occurred on this 3% of the unit in areas with skid trails with greater than 1-2 tractor passes and steeper areas of the unit.

The data serves as a baseline to reference for future monitoring in unlogged areas and against different logging systems. The interaction of winter logging and triticale re-emergence should be given further investigation.

10. Prepared By: Sue Farley (final document produced Feb. 13, 2004)

ICS 214

Table 1: Mean and standard error of soil strength associated with types of soil cover. Measures taken with cone penetrometer (lbs/in depth).

Cover	Pressure	Pressure_depth	Pressure_se	Pressure_depth_se
	AVE	AVE	SE	SE
Bare Soil	157.97	57.51	2.63	4.29
Duff/Litter	147.27	44.04	2.29	3.15
Moss	155.33	41.05	0.95	7.97
Vegetation	170.13	108.03		
Wood	146.46	43.93	6.67	4.36




Figure 1: Shows average and standard error of penetrometer measures for types of soil cover.

Table 2: Soil strength mean and standard error associated with presence of grass. Measures taken with cone penetrometer (lbs/cm depth).

Triticale	Pressure/depth	
	AVE	SE
N	56.12	5.2
Y	48.11	2.93




Figure 2: Shows presence and absence of triticale grass and average penetrometer scores. A student t-test suggested not enough evidence for differences between mean penetrometer scores for areas with or without triticale. Error bars display standard error.




Figure 3: Average bulk density for areas with triticale on low slope ground, native pinegrass and elk sedge on low slope ground, and triticale on steep slopes. Error bars display standard error. A one-way ANOVA found no differences amongst the areas for bulk density ($P = 0.80$).

Table 3: Raw and derived penetrometer data along with attributes for cover and disturbance classification.

#	Penetrometer raw	Penetrometer Depth (in)	Cover	Grass	Force (lbs)	Force/depth (lbs/inch)	Howe's Class
1	400	5D	Y		129.18	65.62	2
2	396	25D	Y		127.92	13.00	2
3	450	7B	Y		144.93	52.59	2
4	470	6D	N		151.23	64.02	2
5	342	9W	Y		110.91	31.30	2
6	478	9B	Y		153.75	43.39	2
7	508	8D	N		163.20	51.82	2
8	500	6B	Y		160.68	68.02	2
9	515	9W	Y		165.41	46.68	2
10	439	8D	Y		141.47	44.92	2
11	446	7B	N		143.67	52.13	2
12	491	7B	N		157.85	57.28	4
13	485	10B	Y		155.96	39.61	2
14	460	7B	Y		148.08	53.73	2
15	416	7D	Y		134.22	48.70	2
16	478	9D	N		153.75	43.39	2
17	461	6D	N		148.40	62.82	2
18	429	11D	Y		138.32	31.94	2
19	446	8B	Y		143.67	45.62	2
20	505	7D	N		162.26	58.88	2
21	496	13B	Y		159.42	31.15	2
22	486	12M	Y		156.27	33.08	2
23	508	5B	Y		163.20	82.91	2
24	465	7W	Y		149.66	54.30	2
25	482	7B	Y		155.01	56.25	2
26	446	7D	Y		143.67	52.13	2
27	450	10D	Y		144.93	36.81	2
28	512	12D	Y		164.46	34.81	2
29	381	19D	Y		123.20	16.47	2
30	494	13D	Y		158.79	31.03	2
31	450	12D	Y		144.93	30.68	2
32	498	10D	Y		160.05	40.65	2
33	492	8B	Y		158.16	50.22	2

#	Penetrometer raw	Penetrometer depth	Cover*	Triticale Presence	Force (lbs)	Force/depth (lbs/inch)	Howe's Class
34		503	9W	Y	161.63	45.62	2
35		492	14D	N	158.16	28.70	2
36		480	8M	N	154.38	49.02	2
37		545	4B	Y	174.86	111.03	2
38		470	5D	N	151.23	76.83	2
39		450	6W	Y	144.93	61.35	2
40		457	10D	Y	147.14	37.37	2
41		520	6B	N	166.98	70.69	2
42		595	5B	Y	190.61	96.83	2
43		465	7D	Y	149.66	54.30	2
44		465	7B	Y	149.66	54.30	2
45		512	7B	Y	164.46	59.68	2
46		468	8D	N	150.60	47.82	2
47		465	7B	Y	149.66	54.30	2
48		449	12W	Y	144.62	30.61	2
49		460	10W	Y	148.08	37.61	2
50		502	13B	Y	161.31	31.52	4
51		415	16D	N	133.91	21.26	2
52		530	4P	N	170.13	108.03	2
53		505	7D	Y	162.26	58.88	2
54		520	5B	N	166.98	84.83	2
55		420	6D	Y	135.48	57.35	2
56		520	9B	N	166.98	47.13	2
57		430	12B	N	138.63	29.34	2
58		468	11D	Y	150.60	34.78	2
59		425	11B	Y	137.06	31.65	2
60		560	6B	Y	179.58	76.02	2

* Cover includes bare soil (B), litter-duff(D), rock >3 inch (R), plant basal cover (P), gravel (G), wood > 3 inch (W), and moss (M).

References:

Howes, S.W. 2000. Proposed Soil Resource Condition Assessment. Wallowa-Whitman National Forest. Baker City, OR. 9p.

UNIT 17

Timber Unit Soil Condition Assessment

Area Maudlow Salvage

Date 10/16/03

Area covered (acres) _____

Plot MTW1

Observer SF

Habitat _____

Dist_Class

Penetrometer (raw)

Depth (cm)

Cover

Moisture (%)

Azimuth

Pace

Notes

	A1	B2	C3	D4	E5	F6	G7	H8	I9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	X24	Y25
	400	390	450	470	342	470	508	500	515	439	446	491	495	460	416	473	461	424	446	505	496	486	503	466	482
	5	25	7	6	9	4	8	6	9	8	7	7	10	7	7	9	6	11	8	7	13	12	5	7	7
	D	D	B	D	W	B	D	B	W	D	B	B	B	D	D	D	D	B	D	B	M	B	W	B	B
	T	T	T	NT	T	T	NT	T	T	T	NT	NT	T	T	T	NT	NT	T	T	NT	T	T	T	T	T

Dist_Class

Penetrometer (raw)

Depth (cm)

Cover

Moisture (%)

Azimuth

Pace

Notes

	Z26	AA27	AB28	AC29	AD30	AE31	AF32	AG33	AH34	AI35	AJ36	AK37	AL38	AM39	AN40	AO41	AP42	AQ43	AR44	AS45	AT46	AU47	AV48	AW49	AX50
	446	450	512	381	494	450	498	492	503	492	480	545	470	450	467	520	595	465	465	512	468	465	449	460	502
	7	10	12	19	13	12	10	8	9	14	8	4	5	6	10	6	5	7	7	7	8	7	12	10	13
	D	D	D	D	D	D	D	B	W	D	M	B	D	W	D	B	B	D	B	B	D	B	W	W	B
	T	T	T	T	T	T	T	T	NT	NT	T	NT	T	T	NT	T	T	T	T	T	T	NT	T	T	T

(4)

(3-4)

Cover=

Rock (>3 inch) (R), Duff/litter (D), Bare soil (B), Plant (basal cover) (P), Gravel (G) Wood (W) Moss (M)

Disturbance Class=

0 (Undisturbed), 1 (Slight Disturbance), 2 (Some Disturbance), 3 (Moderate Disturbance), 4 (High Disturbance), 5 (Sever Disturbance), 6 (Altered Drainage)

X Pounds=

0.315 * (Penetrometer Reading) + 3.183

UNIT LOG	1. Project: Toston Maudlow Salvage Sale	2. Date Visited: 10/29/03	3. Visited: Unit #: 8 Winter Tractor Log Road #: Other Activity:
		Prepared: 10/29/03	T 7N R4E Sec 34
4. Project Area Sulpher Bar	5. (Name and Position) Vince Archer, Soil Scientist		T 6N R4E Sec 3 T7N R4E Sec 34 T6N R4E Sec 3
7. Parties Involved			
Name		Position	
Vince Archer		Soil Scientist	
Sue Farley		Soil Scientist	
8. Activity Log			
Activity Reviewed	Monitoring BMP Effectiveness		
Winter Tractor Logging in Unit 8	<p>Trees were felled using feller buncher and tractor skidded down to log landing. Temporary roads were used to haul logs to main forest road. Work was done over winter 2002/2003. Temporary roads have since been decommissioned to full recontour. Pre-existing non-system roads were ripped and seeded. BMP monitoring was initiated to document coarse woody debris standards and amount of ground cover</p> <p>Sampling was done to verify standards for coarse wood debris and characterize surface organic fractions. Fuel sampling was done following FIREMON protocol (Lutes, 2003, http://www.fire.org/firemon/). Groundcover data was estimated at one foot intervals along 50 foot transects. Weather at time of sampling was less than agreeable with some snow accumulation. Sue had warm food; Lois and Vince did not.</p> <p>Results found coarse wood debris (CWD) at 7.4 tons per acre, within range of the recommended standard for this habitat type (Graham et al, 1994, see Figure 1). In considering the distribution of CWD throughout the unit, the range was fairly even with values from 4-10 tons/acre (Figure 1). Duff and litter had appreciable amounts at 4.3 and 2.3 tons/acre, though much lower than unburned areas. The fine fuel fraction was the lowest at 1.3 tons/acre showing that most of the resident wood material resides as larger >3 inch diameter material (see Figure 1).</p> <p>Groundcover values showed 35% bare soil in addition to duff/litter cover at 39% (Figure 2). The variability was quite high with bare ground measures ranging between 4% and 56% (Table 2).</p> <p>Moderate amounts of groundcover and adequate downed wood debris may minimize erosion potential at this unit, especially given the lower slope angle and ridge position. However, the lopsided distribution of organic</p>		

	<p>matter stores, favoring CWD may impact soil processes at the site. Readily decomposable substrate may be limited at this site. This limited amount of fine woody material is due to effects of wildfire, and not post-fire salvage logging. Additional information on plant species abundance and cover during the growing season with inferences to carbon substrate would help ascertain the status of soil productivity.</p>
9	Findings and/or Recommendations
<p>Winter tractor unit</p>	<p>Coarse woody debris standards were met with measures averaging 7.4 +/- 2.2 tons/acre, within range of the target 7 tons/acre. This CWD acts to slow erosion at the unit, though moderate amounts of bare soil exists, possibly remnant from severe burning by wildfire. Lower amounts of fine organic matter stores may impact nutrient cycling at this location, though this is due to effects of wildfire and not salvage logging. We recommend sampling vegetation during the growing season for better inferences about short-term nutrient cycling.</p>
<p>10. Prepared By: Vince Archer, Sue Farley (updated 12-2-03 by Sue Farley)</p>	

ICS 214




Figure 1: Fuel fractions measured at Unit 8. Classifications define coarse wood as > 3 inch diameter and fines including 1 hr (0-0.25 inches diameter), 10 hr (0.25-1 inch diameter) and 100 hr (1-3 inches diameter) wood pieces. For coarse wood, the majority sampled had decayed much and retained structure integrity.




Figure 2: Groundcover percentages from 50 foot transects at Unit 8. Measures were taken at every foot. See Table 1 for average +/- standard error.

Table 2: Groundcover average percent for Unit 8.

Transect	Bare Ground	Litter/Duff	Basal Veg	Moss	Wood	Gravel	Rock
Average	35.33	40.00	8.67	0.67	16.00	0.00	0.00
Standard Error	15.93	19.29	2.91	0.67	7.02	0.00	0.00

Reference:

Graham, R.T., A.E. Harvey, M.F. Jurgenson, T.B. Jain, J.R. Tonn, and D.S. Page-Dumroese. 1994. Managing coarse woody debris in forests of the Rocky Mountains. Res. Pap. INT-RP-477. Intermountain Research Station, USDA Forest Service: 1-13

Lutes, D. 2003. Fire Effects Monitoring and Inventory Protocol: Sampling Methods. Systems for Environmental Management. Missoula, Montana. [Online]. Available: http://www.fire.org/firemon/FLv3_Methods.pdf [2003].

UNIT 8

ENTERED

Date: 10-30-03 Site Name/Code:

Mudlow Salvage Downed Fuel Inventory Form

Block artment	Sub-compartment Stand Elevation		Aspect												
			Cover Type		Habitat Type										
Size Class (In):			0-1	1-3	3+										
Length of Sampling Plane (Ft):															
Plot No.	Slope	No. of Intersections			Duff Depth		3+ Diameter						Fuel Depth		
		0-25"	25-1"	1-3"	First	Second	Sound	Sound	Sound	Rotten	Rotten	Rotten	First	Second	Third
T-5		5	7	4	2-1 cm	3-3 cm				4"					
					duff-litter					III					
T-6		0	0	0	1cm-1cm	1cm-1cm				4"	4"	4"			
										III	III	III			
										4"	4"	3"			
										III	II	III			
										3"	4"	4"			
										II	II	III			
										6"					
										II					

Ground Fuel Composition:		If heavy slash, code 1:
Species	Percent	

BULK DENSITIES

Manslow T.

Wght. TRACTOR UNIT

MTW		S_w
1	1A	407.4
"	1B	431.3
	1C	364.4
	2A	424.8
	2B	377.1
	2C	411.3

TRIT	3A	375.2
↓	3B	349.3
↓	3C	423.9

MTW		S_{at}	t_{in}
TRIT	3A	371.6	19.3
TRIT	3B	319.3	18.1
	3C	405.6	18.6
?	1A	359.1	17.8
	1B	397.1	17.9
	1C	328.9	17.7
	2A	395.6	18.0
	2B	368.5	18.3
	2C	368.8	17.6

PINE
GRASS
EUKSEIDGIE

