

Compact image sensor camera



User's Manual (Function and Operation)



Thank you for purchasing the SHARP IV-S30J compact image sensor camera. Read this introductory user's manual carefully to thoroughly familiarize yourself with the functions and proper procedures for operation. Store this user's manual in a safe place. We are confident that the manual will be helpful whenever you encounter a problem.

In addition to this manual, there are two other IV-S30J manuals as follows. Read them in conjunction with this manual.

IV-S30J — User's Manual (Introduction and Hardware)

— Instruction Manual

Manual type	Major subjects	How to use
IV-S30J User's Manual (Introduction and Hardware)	 Outline of the IV-S30J (features and functions) Description of the hardware Startup method General performance specifications. Example of operation and instruction 	 Become acquainted with the IV-S30J Learn how to install the IV-S30J and wire it up When mastering the outline of operation.
 - Detailed explanations of all the measurement functions. - How to make menu selections for each measurement - Details of inputting and outputting data and communications with other devices. - Troubleshooting 		 Learn how to specify measurement /inspection conditions, good or NG judgment conditions, etc. Lear how to connect a programmable controller or personal computer. Learn what to do if a problem occurs.

Notes

- This manual was written with the utmost care. However, if you have any questions or inquiries concerning the product, please feel free to contact our dealers or service agents.

- Copying all or part of this booklet is prohibited.

- The contents of this manual may be revised or modified for improvement without prior notice.

Chapter 1: Setting and Operating Outline

Chapter 2: Setting the Operating and System Conditions

Chapter 3: Setting Measurement Conditions

Chapter 4: Positional Deviation Measurement

Chapter 5: Degree of Match Inspection

Chapter 6: Lead Inspection

Chapter 7: Area Measurement by Binary Conversion

Chapter 8: Object Counting by Binary Conversion

Chapter 9: Object Identification by Binary Conversion

Chapter 10: Existence Inspection by Point Measurement

Chapter 11: Multiple Positional Measurement

Chapter 12: Multiple Degree of Match Inspection

Chapter 13: Distance and Angle Measurement

Chapter 14: Numerical Calculations

Chapter 15: PC Function

Chapter 16: Setting the Input/Output Conditions

Chapter 17: Communication (General Purpose Serial Interface)

Chapter 18: Computer Link

Chapter 19: Troubleshooting

Alphabetical Index

Table of Contents

Chapter 1: Setting and Operating Outline	1-1 to 23
1-1 Setting and operating procedures	
1-2 Method for selecting the menu configuration	
[1] Menu configuration	
[2] Configuration of the setting conditions	
[3] Configuration of Set Wizard	
1-3 Description of the Operation screen	
1-4 Setting the measurement programs	
1-5 Common operations for each menu	
[1] Operations to return to the operation screen	
[2] Saving data	
1-6 Power ON setting menu	
[1] Operations menu lock	
[2] Change the Japanese or English display mode	
1-7 Remote keypad (IV-S30RK1)	
1-8 Operation flow	
[1] Power ON and main loop processing	
[2] Operation flow after the measurement start input is turned ON.	
1-9 Table of controller functions	
	I-ZZ
Chapter 2: Setting the Operating and System Conditions	2-1 to 17
2-1 Setting the operating conditions	2-1
[1] Monitor output	
[2] Image capture	
[3] Message display	2-5
[4] Pattern display	
[5] Binary image display	2-7
[6] q angle correction image display	
[7] Operation main display	2-9
[8] Evaluation change display	2-10
[9] PC monitor screen	2-11
[10] Through display	2-11
[11] Extension functions	2-12
2-2 Setting the system conditions	2-14
[1] Manually setting the object type	
[2] Gain/offset adjustment	2-15
2-3 Editing Operation screen	2-16
2-4 Option	
Chapter 3 : Setting Measurement Conditions	
3-1 Outline	
3-2 Shared settings	
[1] Window shape selection and settings	
[2] Image settings	
[3] Evaluation conditions	
[4] Image pre-processing	
[5] Image adjustment	3-24

[6] Binary image mask	
[7] Position correction	
[8] Title registration	
3-3 Input & Output / System settings	
[1] Illuminance (light level) monitor	
[2] Setting the shutter speed	
[3] Copying	
[4] Halt on NG measurement	
[5] Window group move	
Chapter 4: Positional Deviation Measurement	4-1 to 13
4-1 Outline	
4-2 Setting operation	
[1] Set the register conditions for a gray search	
[2] Setting the register conditions for edge detection	
	4-7
Chapter 5: Degree of Match Inspection	5-1 to 9
5-1 Outline	5-1
5-2 Setting operation	
Chapter 6: Lead Inspection	6-1 to 8
6-1 Outline	
6-2 Setting operation	
Chapter 7: Area Measurement by Binary Conversion	7-1 to 9
7-1 Outline	
7-2 Setting operation	
Chapter 8: Object Counting by Binary Conversion	8-1 to 8
8-1 Outline	
8-2 Setting operation	-
6-2 Setting Operation	
Chapter 9: Object Identification by Binary Conversion	
9-1 Outline	
9-2 Setting operation	
Chapter 10: Existence Inspection by Point Measurement	10-1 to 9
10-1 Outline	
10-2 Setting operation	
Chapter 11: Multiple Positional Measurements	11-1 to 11
11-1 Outline	
11-2 Setting operation	
[1] Set the register conditions for a gray search	
[2] Setting the register conditions for edge detection	
Chapter 12: Multiple Degree of Match Inspection	12-1 to 8
12-1 Outline	12-1
12-2 Setting operation	12-2


Chapter 13: Distance and Angle Measurement	13-1 to 8
13-1 Outline	
13-2 Setting operation	13-2
Chapter 14: Numerical Calculations	.14-1 to 15
- 14-1 Outline	14-1
14-2 The individual numerical calculations for each measuring program	14-1
14-3 Final numerical calculations	
14-4 Setting examples	
Chapter 15: PC Function	. 15-1 to 18
• 15-1 Outline	
15-2 Operation cycle	
[1] Power ON sequence	
[2] PC scan cycle	
[3] Measurement processing cycle	
15-3 Ladder circuit program creation	
[1] Procedure for creating measurement output condition and a ladder circuit	
[2] A list of the "OUTPUT COND" screen displays	
[3] Procedure for creating the final output conditions in a ladder circuit	
15-4 Program examples (shape and positional deviation inspection)	
15-5 Examples of a final output conditions ladder circuit	
15-6 PC monitor screen	15-18
Chapter 16: Setting the Input/Output Conditions	. 16-1 to 32
16-1 Outline	16-1
16-2 Measurement start input and result output settings	16-5
16-3 CCD trigger	16-18
[1] Outline	16-18
[2] Setting procedure	16-18
16-4 Setting for serial communications	16-21
16-5 Computer link	
16-6 Output block assignment (Computer link output and general purpose serial output)	
[1] Data in specified blocks	
[2] Setting (operating) procedure	
16-7 Setting the data output	
[1] Select "ANY" for the serial output	
[2] Select "YES" or "NO" for output data	
16-8 Calibrating the IV-S30J	
	10-20
Chapter 17: Communication (General Purpose Serial Interface)	
17-1 List of processing functions	
17-2 Data flow	17-3
[1] Measurement execution 1: Command codes 10, 11, or 12	17-3
[2] Measurement execution 2: Response processing for command 11	17-3
[3] Measurement execution 3: Command 14	17-4
[4] Processing other than measurement execution processing	17-4
17-3 Communication format	17-5
17-4 Processing functions	17-7

[1] Measurement execution functions	17-7
[2] Result reading	17-9
[3] Setting, initialization, and diagnosis of the operation screen	17-12
[4] Setting numerical data of the any output measuring	17-16
Chapter 18: Computer Link	18-1 to 34
18-1 Compatible models	18-1
18-2 Data flow	18-2
18-3 Register setting	18-3
18-4 Measurement data blocks	18-5
[1] Number of blocks	18-5
[2] Contents of the measurement result block (for each measurement function)	18-6
18-5 Specifications for any output data	
18-6 Interface	18-19
[1] Setting items for the IV-S30J	18-19
[2] Connection with a Sharp PC	
[3] Connection with a Mitsubishi PC	18-26
[4] Connection with an OMRON PC	18-29
18-7 Program examples	18-31
Chapter 19: Troubleshooting	19-1 to 6
[1] Symptoms and checks	19-1
[2] Causes of termination codes (when an error occurs) and remedies	19-3
[3] Maintenance	19-6
Alphabetical Index	I-1 to 7

Chapter 1: Setting and Operating Outline

1-1 Setting and operating procedures

This paragraph describes the rough operation sequence of the IV-S30J.




1-2 Method for selecting the menu configuration

(1) Set wizard

The IV-S30J has a "Set Wizard" function to assist beginners in setting the measurement conditions.

Select "SET WIZARD" from the "MAIN MENU" and the wizard will show the items ^{IVS30J} needed for each step. You only need to make selections according the instructions on the screen. Using the wizard, you can establish the minimum required settings for making measurements.

SYS-CND OBJECT TYPE COND SET WIZARD EDIT MAIN OPS MENU OPTION



The steps that the set wizard takes you through are displayed as lists on the "operation chart." At any point you can return to the previous step to make a change if you want to.


TYPE00


Start STEP1:PARALLEL+SERIAL STEP2:CAPTURE IMG/PARTIAL-IMG STEP3:MEAS1/CAM1 STEP4:MEAS1/BIN-AREA STEP5:MEAS1/WINDOW/MASK,1 STEP6:MEAS1/MEAS CND STEP7:MEAS1/EVALUATION STEP8:MEAS1/CALC STEP9:MEAS1/OUT STEP10:FINAL NUMERIC CALC STEP11:FINAL OUTPUT COND STEP12:SERIAL OUTPUT/ANY STEP13:OPS MENU COND STEP14:CALIBRATION/YES STEP15:MOVE ALL WINDOW/YES STEP16:TITLE/YES End

Wizard

The "Wizard" is a program that helps users make settings for measurement operations easily and without making mistakes. The controller asks you a series of questions at each step and you simply answer these to complete the settings.


The wizard is convenient for making settings when beginners and inexperienced operators are operating the machine. However, operators who are familiar with the operation may save a lot of time by using other setting methods.






- *1: MEAS0 is only for making for "positional deviation measurements."
- *2: MEAS01 to 04 can be set to make any type of measurement from "positional deviation measurements" to "multiple degree of match inspections."


[2] Configuration of the setting conditions





[3] Configuration of Set Wizard

The Set Wizard has the following screen configuration.










1-3 Description of the Operation screen

When the IV-S30J is started, the operation screen shown below will appear. Each area of the operation screen is described below.



- (1) Displays the number of the currently selected object.
- (2) Select whether to display captured images on the screen as freeze images or through images.

Display method		
Through image	 Displays the stream of images captured by the camera. Used for adjusting the camera focus and image properties. 	
Freeze image		

To switch the image between "Through" and "Freeze" modes, press the SEL key on the remote keypad, and then press the up and down arrow keys.

③ Indicates which camera is currently selected

C1: Camera 1 (the camera connected to the "CAMERA1" connector)

C2: Camera 2 (the camera connected to the "CAMERA2" connector)

(4) The brightness of the captured image can be set to one of two levels.

Screen display	Description	
Bright	Display the captured image without changing its brightness.	
Dark Display the captured image at 1/2 the actual brightness		

How to select the brightness level

On any screen, except the operation screen, move the cursor to the "F" (freeze) or "T" (through) position on the upper part of the screen by pressing the SEL key. Then, press the left or right arrow key to move the cursor to the "BRT" (bright) or "DRK" (dark) indicator. Press the up or down arrow key to switch between bright and dark.

►

- (5) Displays the software version.
- (6) Displays the measurement time currently assigned.

4	Actual measurement time -
	Actual measurement time

(Only when changing the object type)				
Time to change object type	CCD exposure time (Shutter operation time)	CCD image capture time	Image processing time	Result output time

- Serial communication time is not included.

- Set the controller as follows to reduce the measurement time.
- 1. Increase the shutter speed.
- 2. Select the "partial" image capture feature for the CCD.
- 3. Select "NO" for the measurement results display (message display, pattern display, and binary image display).
- \bigcirc Display setting details of each measurement.

CAM1	NO
↑	1
Camera 1 or camera 2	Measurement program name
	↑ Camera 1 or

- ⑧ Displays the status of input relays X0 to X6: OFF [□], ON []. Displays the status of output relays Y0 to Y7: OFF [□], ON [■].
- (9) Displays the status of the ready output: OFF [□], ON [].

(1) The menu bar at the bottom has two rows. When this menu is selected, the second row will appear.

MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE
Ļ
MNU-CHG CHG-C1 CHG-C2 MANL-MEAS SHORTCUT

The details of each item on this menu bar are shown on the next page.

Details of each item on the menu bar

Item on the menu bar	Description	Display detail on the screen
MAIN-COND (main conditions)	Displays the MAIN screen.	IVS30J SYS-CND OBJECT TYPE COND SET WIZARD EDIT MAIN OPS MENU OPTION
CHG-MEA (Change measurement)	Press the up and down arrow keys to change the display of the evaluation results for each measurement number. (Measurement 0 camera 1 -> measurement 0 camera 2 -> Measurement 1 -> Measurement 2 -> Measurement 3 -> Measurement 4)	MEASURED CAM1 NO
COND-CHG (Change the measurement conditions)	Displays the condition change selection list. Change the conditions that get displayed by pressing the up and down arrow keys.COND-CHG (Change the measurementFor details about the measurement conditions, see pages 8-3 and 8-8 in Introduction and Hardware and Chapter 3 in this manual.	
CHNG-REG (change registration)	Change the display of the set of stored details between [A00] - [A07] and [A08] - [A15] using the up and down arrow keys	$\begin{array}{ccc} A0= & A08= \\ to & \longleftrightarrow & to \\ A07_2 & A07_2 \end{array}$
SCREEN-CHG (change screen)	Displays the screen change selection list. Select a screen using the up and down arrow keys. Note: The OPS-MAIN, JDG-COND-CHG,and PC-MNTR do not appear on the popup menu unless "YES" is selected. for each corresponding item on "TYPE RUN COND" menu. Only the currently available screens are listed.	OPS-MAIN PC-MNTR SCREEN-CHG CHG-TYPE
CHG-TYPE (change the object type)	Displays the object type selection list. Select an object type by pressing the up and down keys. This is enabled when Manual Object Type Change is set to "YES."	(TYPE <u>00)</u> This part changes.
CHG-C1 (change the Camera 1 image position)	Moves the image from Camera 1 up and down the screen using the up and down arrow keys. Note: This is enabled when "CAM1&2" is selected in ①MONITOR OUTPUT on the TYPE RUN COND menu (operating conditions).	
CHG-C2 (change the Camera 2 image position)	Moves the image from Camera 2 up and down the screen using the up and down arrow keys. Note: This is enabled when "CAM1&2" is selected in ①MONITOR OUTPUT on the TYPE RUN COND menu (operation conditions).	
MANL-MEAS (Manual measurement)	Manually move the two crosshair cursors, and measure distance between these two points, as well as coordinate distance on X and Y axes. Note: Unless "MANL-MEAS" is selected on the "①EXTENSION FUNC" line in the TYPE RUN COND (operation conditions), this screen cannot be displayed.	MANL-MEAS ①CURSOR1-COORD MOVE(224.208) ②CURSOR2-COORD MOVE(287.271) DIST-BETW-2PT 089.0 + DIST-BETW-X 063.0 + DIST-BETW-Y 063.0 +
SHORTCUT	Displays a short cut screen.	[PLACE] SHORTCUT1 NO SHORTCUT2 NO SHORTCUT3 NO

1-4 Setting the measurement programs


To execute a specific measurement program (positional deviation measurement, degree of match inspection, etc.), select MEASUREMENT 0 to 4 on the "MEA-CND" line.

- MEASUREMENT 0 only allows you to measure positional deviation.
- For details about the settings for each measurement program, see Chapters 4 to 13.
- Specify the conditions for distance and angle measurement in the positional deviation measurement, the degree of match inspection, object identification by binary conversion (MEAS GRAV CENTR:
 - YES), multiple position measurement, and for multiple degree of match inspection.
- (1) Operation main screen (see page 1-10).



Move the cursor to the "MAIN COND" item using the left and right arrow keys and press the SET key.

(2) Select the "OBJECT TYPE COND" using the up and down arrow keys and press the SET key.



(3) Move the cursor to the "TYPE(NEW)" item on the "OBJECT TYPE COND" line and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND ET TYPE00 TYPE(NEW)	

- (4) Move the cursor to "TYPE00" on the "SELECT OBJECT TYPE COND" line and press the SET key. To select "TYPE01" and others, move the cursor to "TYPE(NEW)" and press the SET key.
- (5) Select "MEAS0 to 4" (MEAS0 is only used for positional deviation measurements) on the "MEAS COND (CAM1)" line and a popup menu will appear. Select any desired measurement program from this popup menu and then press the SET key.

1-5 Common operations for each menu

[1] Operations to return to the operation screen

You can return to the operation screen, MAIN MENU, or setting screen from any menu by a single operation.

Menu display

[TYPE RUN COND] menu

$\times \times \times \times$	SCREEN	SAVE	
	OPS-MENU MAIN SELECT RETURN	 Return to the operation screen Return to the MAIN screen. Return to the currently selected s Return to the previously selected 	

[2] Saving data

All of the data such as measurement and evaluation conditions entered on the "TYPE RUN COND," "MEA-CND," and "SYSTEM COND" menus, can be saved into the IV-S30J flash memory.

Operation procedure

[SYS-CND] menu

××××	SCREEN SAVE
	DATA SAVE?(YES=[SET],NO=[ESC])

- 1. On each menu screen, move the cursor to "SAVE" using the up/down and left/right keys, and press the SET key.
 - The following message will be displayed on the lower part of the screen.

DATA SAVE? (Do you want to save the data?) (YES=[SET]/NO=[ESC])

- 2. Press the SET key.
 - The IV-S30J will start saving the data and the progress will be displayed on the bottom of the screen.



When the data has been saved in the IV-S30J flash memory, the display will change from "SAVING" to "COMPLETE SAVE."

1-6 Power ON setting menu


[1] Operations menu lock


To prevent accidental changes to conditions you have set, the operation screen can be locked so that the screen cannot be changed to setting screen. The operation can only be carried out on the [POWER ON SETTING] menu.

Display procedure

Follow the procedure described below when turning ON the power to the controller (IV-S30J), and the [POWER ON SETTING] menu will be displayed on the monitor.

- 1. Turn ON the power to the IV-S30J controller, while holding down the ESC key.
- 2. Keep pressing the ESC key down for approx. 9 sec., after turning ON the power and the menu will be displayed.






1 MAIN OPS MENU	Description
UNLOCK	All of the operating conditions for the IV-S30J can be changed.
LOCK	The MAIN OPS MENU is locked and no change can be made.

Operation procedure

- 1. On the [POWER ON SETTING] menu, move the cursor to item "①MAIN OPS MENU" with the up and down keys, and press the SET key.
- 2. Move the cursor to "UNLOCK" or "LOCK" with the left and right keys, and press the SET key.
- 3. Move the cursor to item "③OPERATION" with the up and down keys, and press the SET key. Press the SET key once more.
- ⇒ The IV-S30J saves the settings in the flash memory and the screen will return to the operation screen.

Display when the operation screen is locked




[2] Change the Japanese or English display mode

Change display between Japanese and English. Use the [POWER ON SETTING] menu for the selection.

Display procedure

Follow the procedure described below when turning ON the power to the controller (IV-S30J), and the [POWER ON SETTING] menu will be displayed on the monitor.


- 1. Turn ON the power to the controller, while holding down the ESC key.
- 2. Keep pressing the ESC key down for approx. 9 sec., and the following menu will be displayed.



Operating procedure

- 3. Move the cursor to item "②DISPLAY MODE" (display mode) with the up and down keys, and press the SET key.
- 4. Move the cursor to "JAPANESE" or "ENGLISH" with the left and right keys.
- 5. Move the cursor to "③OPERATION" using up and down keys and press the SET key. Then, again press the SET key.
- \Rightarrow The screen will change to operation screen.


1-7 Remote keypad (IV-S30RK1)




$\overline{\ }$	Key name Function Description		Description
		Selecting an item on a menu screen	Select an item with the up, down, left and right keys.
	Direction keys*	Setting a window	Set each coordinate.
1	(up, down, left and right)	Setting a value	 Select a digit or an item with the left and right keys, and then specify a value with the up and down keys. Specify a value with the up, down, right and left keys.
		To enter nested menus	
2	SET key	Determine a highlighted item	
	SLI Key	Determine the setting value	
3	ESC key	Returning a setting to its original state before be- ing changed	On the REG-COND screen, - Press the left arrow key + ESC key to change between a display of all items and just one
		Returning to the previous menu	item at a time.
4	SEL key	Use to select the display of object images: choose between "F" (Freeze) and "T" (Through) and between "BRT" (bright) and "DRK" (dark).	 When the screen is changed from "Through" to "Freeze," the IV-S30 will capture an image. Change the brightness of the image displayed on the screen. On the setting screen, Press the left arrow key and the SEL key to change between Through and Freeze. Press the right arrow key and the SEL key to change between Bright and Dark.
		Start measurement input	Press this key on the run screen, and a new measurement is triggered.
5	TRG/BRT key	Move the cursor to the function menu at the upper area.	
		Displays popup menu.	


* The direction keys have an auto-repeat function.


1-8 Operation flow [1] Power ON and main loop processing






[2] Operation flow after the measurement start input is turned ON.









- When the halt NG measurement option is set to "YES" (page 3-38), the controller stops measuring when an error occurs.

1-9 Table of controller functions

Shown below are the functions for the controller (IV-S30J).

- For details about the controller hardware (cameras, peripheral devices), see the "IV-S30J User's Manual, Instruction and Hardware."

		Specifications
Item		IV-S30J
Image sampling system		256 level gray scale, binary conversion, edge detection
	Image memory	One screen for displaying captured images. One monochrome screen for displaying camera information and messages
No. d	of assignable object type	16 object types
image	num number of reference s stored / number of screens stored	200 / 2 screens
	Image scan time	33.3 ms
	Gray search time *	15 ms
Gray	/ search, edge detection precision	Pixel, sub-pixel
ing	Shading correction	Dividing, subtracting, and filtering
mage pre-processing	Comparative calculation between images	Subtracting, absolute value of difference (between camera 1 and reference image, between camera 2 and reference image, between camera 1 and camera 2)
-erd e	Gray level changes	Magnification by "n" processing, γ (+/-) correction, histogram widening, mid-range emphasis
Image	Space filter	Smoothing (center/average), edge emphasis, edge extraction, horizontal edge, vertical edge
B	inary threshold value	Fixed and threshold value corrections (variation difference/variation rate)
Bi	nary noise elimination	Expansion \Rightarrow contraction, contraction \Rightarrow expansion, area filter
Binary image mask		Specified window(rectangle, circle, oval), any binary image mask
Posi	tional correction method	X/Y correction, rotation correction
	Positional deviation measurement	XY coordinate, deviation amount in X and Y axes, degree of match (1-point search, 2-point search, 1-point edge, 2-point edge, 1-point search and 1-point edge) Angle: $\pm 15^{\circ}$, $\pm 30^{\circ}$, $\pm 45^{\circ}$, 360° (1-point search, 1-point search + 1-point edge)
		[Maximum 8 windows x 2 models]
_ ح	Degree of match inspection	Degree of match, XY coordinate, density (1-point search, 2-point search) [Maximum 16 windows x 2 models]
ogram	Area measurement by binary conversion	Area [Maximum 16 windows]
ent pr	Object counting by binary conversion	Quantity (maximum 3,000 items per window), total area [Maximum 4 windows]
Measurement pr	Object identification by binary conversion	Quantity (maximum 128 per window), total area, area of each object identified, gravity center, main axis angle, fillet diameter, peripheral length, center point [Maximum 4 windows]
Me	Point measurement	Number in binary image (maximum 256 points), average density (maximum 128 points)
	Lead inspection	Number of leads, distance between leads (max., min.), lead width (max., min.), lead length (max., min.) [Maximum 16 windows]
	Multiple position inspection	Number of objects (max. 128), degree of match, XY coordinate (1-point search, 1-point edge) [Maximum 4 windows]
	Multiple degree of match inspection	Number of objects (max. 128), degree of match, XY coordinate, density (1- point search) [Maximum 4 windows]

* The gray search time is true when the search area is 256 x 256 pixels, the model size is 64 x 64 pixels, and the contraction function is set to 3.

		Specifications	
Item		IV-S30J	
Num	ber of measurement programs	Maximum 6 per object type (measurement 0 - camera 1, measurement 0 - camera 2, measurements 1 to 4) Note: Measurement 0 is only used for positional deviation measurement.	
	Window shape	Rectangle, circle, oval (when using area measurement by binary conversion, object counting by binary conversion, object identification by binary measurement), polygon window (maximum 32 sided polygons: When binary area measurement, counting after binary conversion, or object identification (labeling) after binary conversion is selected.)	
D	istance and angle measurement	Measure distance (between two points, X coordinate, Y coordinate), measure angle (3 points, 2 points against horizontal line, 2 points against vertical line), auxiliary point (center, circle center, gravity center, line over 2 points, crossing point of two straight lines)	
Ar	ithmetic operation	Four basic operations (+, -, X, /), root, absolute value, TAN, ATAN, maximum, minimum, average , total.	
	Other functions	Display measuring time, light level monitor function, crosshair cursor display, change display language between Japanese and English, Run screen lock function, setting menu display "yes/no", change image display (through/freeze), change image brightness (bright/dark)	
c	Input relays	Parallel input: 7 points (X0 to X6)	
section	Output relays	Parallel output: 8 points (Y0 to Y7) General-purpose serial interface, computer link: 16 points (Y0 to Y15)	
Ű	Auxiliary relays	128 points (C0 to C127), special area 18 points (C110 to C127)	
Micro PC section	Timers	8 points (TM0 to TM7), timer setting range: 0.01 to 9.99 seconds (countdown timer)	
2	Counters	8 points (CN0 to CN7), counter setting range: 001 to 999 (counts down)	
al ce	Parallel interface	Input: 7 points, 12/24 VDC Output: 9 points, 12/24 VDC	
External interface	General-purpose serial interface	RS232C/RS422 (2.4 to 115.2 kbps)	
	Computer link	Built-in compatibility with certain SHARP, OMRON, and Mitsubishi models	
	Image output	1 channel, EIA 525 lines, 2:1 interlace	
N	umber of cameras	Maximum of 2	
	Make settings	Using the IV-S30RK1 remote keypad and/or the IV-S30SP parameter setting support software	
Measu- rement	Internal trigger	CCD trigger (using the CCD camera)	
start input	External trigger	Trigger input (parallel I/F), general-purpose serial I/F, keypad trigger (for manual measuring)	
	Interrupt processing input	1 point: External trigger (X0)	
Terminal block	Inputs	4 points: Object type change (X1 to X4) 2 points: External input (X5, X6)	
nal	Common for input	1 point: + common	
j mi	Output	9 points: 1 READY , 8 user settable logical outputs (Y0 to Y7)	
Te	Common for output	1 point: + common	
	Power supply	2 points: +24 VDC, 0 V	
Power v	oltage/consumption	24 VDC (±10 %) 7 W	
L	U 1		

Chapter 2: Setting the Operating and System Conditions

2-1 Setting the operating conditions

Set the following operating condition items on the [TYPE RUN COND] menu for each object type.

Item to set	Reference page
Monitor output	2-2
Image capture	2-4
Message display	2-5
Pattern display	2-6
Binary image display	2-7
θ angle correction image display	2-8
Operation main display	2-9
Evaluation change display	2-10
PC monitor screen	2-11
Through display	2-11
Extension function	2-12

■ How to display the TYPE RUN COND screen

On the "MAIN MENU," select "OBJECT TYPE COND", "TYPE 00", and "TYPE RUN COND" in this order.

OBJECT TYPE COND	SELECT OBJECT TYPE COND	F C1	BRT
	TYPE00 TYPE RUN COND HAGE-ADJ HOMEA-CND(CAMERA1) FOMEA-CND(CAMERA2) FINAL NUM.CALC FINAL OUTPUT COND OBJ-TYPE I/0 OBJ-TYPE SYS.	OCAPTURE IMG OMESSAGE DISPLAY OPATTERN DISPLAY OSHOW BINARY IMG OSHOW Ø FIX IMG OPS MAIN DESP ODESP CHG-EVAL OPC-MNTR OTHROUGH DISPLAY TEXTENSION FUNC. ODISPLAY+CURSOR 1 OSC CURSOR COORD ODISPLAY+CURSOR 2	

The "TYPE RUN COND" screen will appear.

①MONITOR OUTPUT CAM1 ②CAPTURE IMG PARTIAL-IMG ③MESSAGE DISPLAY YES(NUMERIC) ④PATTERN DISPLAY YES ⑤SHOW BINARY IMG YES ⑥SHOW Ø FIX IMG YES ⑧DISP CHG-EVAL NO ⑨PC-MNTR NO ⑩THROUGH DISPLAY NO ⑪EXTENSION FUNC. NO

[1] Monitor output

When two cameras have been connected to IV-S30J, you can switch back and forth between the image from the cameras on one monitor. Also, the monitor screen can be divided into two parts to display the two images simultaneously.

- Purpose of the setting

To set the conditions in which an image captured during measurement will be displayed on the operation screen.

- Output monitor switching

There are two methods for changing the monitor output: change the TYPE RUN COND settings, use external input signals through the parallel port to make changes from outside.

TYPE RUN COND SCREE	N SAVE	F C1 BRT
① MONITOR OUTPUT ② CAPTURE IMG ③ MESSAGE DISPLAY ④ PATTERN DISPLAY ⑤ SHOW BINARY IMG ⑥ SHOW Ø FIX IMG ⑦ DPS MAIN DISP ⑧ DISP CHG-EVAL ⑨ PC-MNTR ⑪ THROUGH DISPLAY ① EXTENSION FUNC.	YES YES YES NO NO NO	32
SET=SELECT A MENU ESC	-BACK SEL=CHNG IMG TR	G=FUNC

(1) Change the monitor output by changing the TYPE RUN COND settings

Select the "①MONITOR OUTPUT" item on the "TYPE RUN COND" screen and then select an item from the popup menu.

1 MONITOR OUTPUT	Description
CAM1	Display the camera 1 image on the whole screen.
CAM2	Display the camera 2 image on the whole screen.
	Display the camera 1 image on upper half, and the camera 2 image on lower half.


Display examples on the operation screen

- Camera 1 on the whole screen

(When "CAM1" has been specified in item ①MONITOR OUTPUT.)




- Simultaneous display on a divided screen (When "CAM1&2" has been specified in item "(1)MONITOR OUTPUT.")



- Camera 2 on the whole screen.

(When "CAM2" has been specified in item ①MONITOR OUTPUT.)



Setting the Operating and System Conditions

(2) Output monitor switching by parallel input On the operation screen, select "MAIN-COND" -> "SYS-CND" -> "I/O CONDITIONS" in that order. Move the cursor to the "⑤PARALLEL INP X6" line using up/down arrow keys and press the SET key. Select "CHNG-IMG-OUT-CAM" on the popup menu that is displayed and then press the SET key.

Every time the X6 signal is turned from OFF to ON, the selected camera display will be changed.

CAM1	CAM2	CAM1&2(HORIZ) _
whole screen	whole screen	divided screen

The display example of the operation screen is the same as in section (1).

	I/O CONDITION SCREE	EN COND SAVE	F C1 BRT
•	①MEAS INP I/F	PARALLEL+SERIAL	
)	2 OUT I/F(PARAL) 3 MANL TYPE CHNG 4 PARALLEL INP X5 5 PARALLEL INP X6 6 STROBE OUT 7 'READY'ON	NO	EXT-INP CHNG-IMG-OUT-CAM CAM-MEAS 2 IMAGES
	SET=SELECT A MENU	ESC=BACK SEL=CHNG	MG TRG=FUNC

[2] Image capture


In item "②CAPTURE IMG" on the "TYPE RUN COND" screen, specify the range which will be captured during operation.

TYPE RUN COND SCREE	N SAVE	F (C1 BRT
1 MONITOR OUTPUT 2 CAPTURE IMG 3 MESSAGE DISPLAY 4 PATTERN DISPLAY 5 SHOW BINARY IMG 6 SHOW & FIX IMG 7 OPS MAIN DISP 8 DISP CHG-EVAL 9 PC-MNTR 10 THROUGH DISPLAY 11 EXTENSION FUNC.	CAM1 PARTIAL-IMG —— YES(NUMERIC) YES YES YES NO NO NO NO NO	PARTIAL-IMG WHOLE-IMG NO	

CAPTURE IMG	Description
PARTIAL-IMG (partial image)	 An image of the specified lines, required for inspection or measurement, will be captured. The processing time is shorter than in the "WHOLE-IMG" mode.
WHOLE-IMG (whole image)	 A whole image will be captured, irrespective of the window settings for inspection or measurement. This mode is used to monitor portions of an image outside the window set up for inspection or measurement
NO (no image)	 No image will be captured during operation. Measurements will be carried out with an image being displayed. This mode only used to carry out measurements on an image transmitted from a personal computer to the IV-S30J.

Example of a comparison of the capture times

- When "WHOLE-IMG" is selected: 33.3 ms



- When the "PARTIAL-IMG" is selected (when there are 240 scan lines): 16.6 ms

Capture partial image

[3] Message display

Select "YES" or "NO" to display messages on the operation screen.


MESSAGE DISPLAY	Description
YES (NUMERIC)	All data will be displayed.
YES (NO NUMERIC)	Data other than the numerical result will not be displayed.
NO	No messages will be displayed.

Setting to "NO" reduces the processing time. Processing time: YES(NUMERIC) > YES(NO NUMERIC) > NO


TYPE RUN COND SCREE	N SAVE	F C1 BRT
(1) MONITOR OUTPUT (2) CAPTURE IMG (3) MESSAGE DISPLAY (4) PATTERN DISPLAY (5) SHOW BINARY IMG (6) SHOW ∂ FIX IMG (7) OPS MAIN DISP (8) DISP CHG-EVAL (9) PC-MNTR (10) THROUGH DISPLAY (11) EXTENSION FUNC.	CAM1 PARTIAL-IMG YES(NUMERIC)	YES(NUMERIC) YES(NO NUMERIC) NO
SET=SELECT A MENU ESC	=BACK SEL=CHNG IN	AG TRG=FUNC


Display examples

- When "YES(NUMERIC)" is selected



- When "YES(NO NUMERIC)" is selected





The menu bar will disappear.

Can be deleted by pressing the SET key.


The menu bar will be displayed.

[4] Pattern display

Select "YES" or "NO" to determine whether to show the pattern display (solid lines and dashed lines of the rectangles in the window) over an image displayed on the operation screen.


Note: When the "CAM1&2" is selected on the "①MONITOR OUTPUT" (page 2-2), pattern display cannot be selected.

PATTERN DISPLAY	Description
YES	Displays patterns in the window, such as the rectangles defined for the inspection area and the search area.
NO	Patterns will not be displayed on the operation screen.



Display examples

- When "YES" is selected for PATTERN DISPLAY.



- When "NO" is selected for PATTERN DISPLAY

(TYPE00) OK		F C1 L VX.X
MEAS XXXXm MEASURE 0 C	s AM1 POSI-DEVIATION	
REGST. NO.		
X0=176.0	OK	
Y0=322.0		
x0=+000.0		
y0=+000.0	OK	
M0=+10000	ОК	
B0=+001.7	ок	
X1=534.0	ОК	
Y1=480.0	ок	
x1=+001.0	OK	
y1=+001.0	OK	
M1=+09999	OK	
X0~6 0000000 Y0~7 0000000 READY 0		
MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE		

Setting the Operating and System Conditions

[5] Binary image display

Select "YES" or "NO" to display a binary image on the operation screen.


- Note: When "CAM1&2" is selected on the "MONITOR OUTPUT" (page 2-2), the binary image display cannot be selected.
- When "NO" is selected on the "④PATTERN DISPLAY," the "⑤SHOW BINARY IMG" item will not appear.

SHOW BINARY IMG	Description
YES	A binary image will be displayed on the operation screen.
NO	A binary image will not be displayed on the operation screen.


TYPE RUN COND SCREE	N SAVE		F	C1	BRT
① MONITOR OUTPUT ② CAPTURE IMG ③ MESSAGE DISPLAY ④ PATTERN DISPLAY ⑤ SHOW BINARY IMG ⑥ SHOW Ø FIX IMG ⑦ OPS MAIN DISP ⑧ DISP CHG-EVAL ⑨ PC-MNTR ⑩ THROUGH DISPLAY ① STRENSION FUNC.	YES YES YES NO NO NO NO	YES NO			
SET=SELECT A MENU ESC	BAUN SELECHING	ING ING=FUNC			

Display examples

- When "YES" is selected for the "5)SHOW BINARY IMG"



- When "NO" is selected for the "⑤SHOW BINARY IMG"




[6] θ angle correction image display

Select "YES" or "NO" to display a θ angle corrected image on the operation screen.

SHOW FIX θ IMG	Description
VEO	A θ angle corrected image will be
YES	displayed on the operation screen.
	A θ angle corrected image will not be
NO	displayed on the operation screen.

TYPE RUN COND SCREE	N SAVE	F	C1	BRT
 (1) MONITOR OUTPUT (2) CAPTURE IMG (3) MESSAGE DISPLAY (4) PATTERN DISPLAY (5) SHOW <i>θ</i> FIX IMG (7) OPS MAIN DISP (8) DISP CHG-EVAL (9) PC-MNTR (10) THROUGH DISPLAY (1) EXTENSION FUNC. 	PARTIAL-IMG YES(NUMERIC) YES YES YES NO NO NO			

Display examples



[7] Operation main display

When the operation screen was set to display other screens (such as the "DISP CHG-EVAL" and "PC-MNTR" screens), this item should be selected to return to the main display from other screens. On the "TYPE RUN COND" screen, select "⑦OPS MAIN DISP" and then "YES" on the popup menu. That will return you to the main operation screen.

Note: When other screens are set to "YES" (such as the "®DISP CHG-EVAL" and "@PC-MNTR" screens), make sure to select "YES" from the ⑦OPS MAIN DISP.

TYPE RUN COND SCREE	N SAVE	F C1 BRT
 ① MONITOR OUTPUT ② CAPTURE IMG ③ MESSAGE DISPLAY ④ PATTERN DISPLAY ⑤ SHOW BINARY IMG ⑥ SHOW Ø FIX IMG ⑦ OPS MAIN DISP ⑧ DISP CHG-EVAL ④ PC-MNTR ⑪ THROUGH DISPLAY ① EXTENSION FUNC. 	PARTIAL-IMG YES(NUMERIC) YES YES YES YES NO NO NO	

Press the TRG/BRT key to move the cursor to the upper function menu. Select "SCREEN" and press the SET key. Then select "OPS-MENU."

TYPE RUN COND SCREE	N SAVE	F C1 BRT
① MONITOR OUTPUT ② CAPTURE IMG ③ MESSAGE DISPLAY ④ PATTERN DISPLAY ⑤ SHOW BINARY IMG ⑥ SHOW Ø FIX IMG ⑦ OPS MAIN DISP ⑧ DISP CHG-EVAL ⑨ PC-MNTR ⑪ THROUGH DISPLAY ⑪ EXTENSION FUNC.	CAM1 PARTIAL-IMG YES(NUMERIC) YES YES YES NO NO NO NO NO	OPS-MENU MAIN SELECT RETURN

Select "SCREEN-CHG" on the lower menu on the operation screen and press the SET key. "OPS-MAIN" will be displayed in the lower right corner of the screen. While the "OPS-MAIN" line is highlighted, press the SET key. The main display will then change back to the operation screen from the other screens (e.g. the JDG-COND-CHG and PC-MNTR screens).



[8] Evaluation change display

Specify whether the evaluation condition change menu can be displayed on the operation screen or not.

Select the "⑧DISP CHG-EVAL" line on the "TYPE RUN COND" screen and select "YES" on the popup menu.

TYPE RUN COND SCREEN	SAVE	F	C1	BRT
② CAPTURE IMG F ③ MESSAGE DISPLAY M ④ PATTERN DISPLAY M ⑤ SHOW BINARY IMG M ⑥ SHOW Ø FIX IMG M ⑦ OPS MAIN DISP M ⑧ DISP CHG-EVAL M ⑨ PC-MNTR M ⑩ THROUGH DISPLAY M	CAM1 PARTIAL-IMG YES(NUMERIC) YES YES YES YES NO NO NO NO			
SET=SELECT A MENU ESC=B	ACK SEL=CHNG IMG TRG=FUNC			

Press the TRG/BRT key to move the cursor to the upper function menu. Select "SCREEN" and press the SET key. Then select "OPS-MENU."

TYPE RUN COND SCREE	N SAVE	F C1 BRT
	CAM1 PARTIAL-IMG YES(NUMERIC) YES YES YES NO NO NO NO	OPS-MENU MAIN SELECT RETURN

Select "SCREEN-CHG" on the lower menu on the operation screen, and press the SET key. "JDG-COND CHG" will be displayed in the lower right corner of the screen. You can display the evaluation condition change menu by pressing the up and down keys.

- Press the SET key. The cursor will move to the area containing the phrase "evaluation condition change menu during operation." You can change the settings for the evaluation conditions.
- At this time, the screen display will look the same as the normal operation main screen, except for the area marked "evaluation condition change menu shown during operation."



Setting the Operating and System Conditions

[9] PC monitor screen (TYPE00)AREA1 T C1 DRKO Specify whether to display the PC monitor LOCK FULL V*.** C1=002.2 OK on the operation screen. OK MEAS XXXXms C2=100.0 OK Select the "9PC-MNTR" line on the "TYPE X00~ 06 000000 (1) RUN COND" screen and select "YES" on Y000~007 000000; READY 0 (2) the popup menu. Now the PC monitor 3 ►¦C000~007 [[[[[[[[[[[screen can be displayed. [NUMERIC CALC] (4) [TMR] [CNTR] AN00= +00000250.0 OK TM0:200 CN0:100 Select "SCREEN-CHG" on the lower menu AN01=-00000300.0 OK FM1:300 CN1:150 AN02=NOT SET TM2:NOT SET CN2:NOT SET bar of the operation screen and then select (5) AN03=NOT SET TM3:NOT SET CN3:NOT SET "PC-MNTR" on the popup menu. The PC AN04=NOT SET TM4:NOT SET CN4:NOT SET monitor will be displayed. AN05=NOT SET TM5:NOT SET CN5:NOT SET AN06=NOT SET TM6'NOTSET CN6·NOT SET 6 AN07=NOT SET TM7:NOT SET CN7:NOT SET (7)MMU-CHG MAIN-COND SEL-OUT SEL-AUX SEL-NUM SCREEN-CHG CHG-TYPE

- (1) The ON (\blacksquare) or OFF (\Box) status of the input relays (X00 to X07) is displayed.
- (2) The ON (\blacksquare) or OFF (\Box) status of the output relays (Y00 to Y15) is displayed.
- (3) The ON (\blacksquare) or OFF (\Box) status of the auxiliary relays (C000 to C127) is displayed.
- $(\underline{4})$ The results (AN00 to AN15) of the final numerical calculations are displayed.
- (5) The current timer value is displayed.
- 6 The current counter value is displayed.

⑦ Menu bar

Menu bar	Description
SEL-OUT	Change the output relay address (Y00 to Y15) using the up and down keys (in units of 8 points).
SEL-AUX	Change the auxiliary relay address (C000 to C127) using the up and down keys (in units of 8 points).
SEL-NUM	Change the final numerical calculation address (AN00 to AN15) using the up and down keys (in units of 8 points).

The other data displayed is the same as on the operation screen. ⇒See page 1-10.

[10] Through display

Select the desired measurement image status (FREEZE or THROUGH) by choosing either "YES" or "NO" on the operation screen.

THROUGH DISPLAY	Description
NO	Measurements can be made on a frozen image.
YES	Measurements can be made on a through image.

①MONITOR OUTPUT CAM1 ②CAPTURE IMG PARTIAL-IMG ③MESSAGE DISPLAY YES(NUMERIC) ④PATTERN DISPLAY YES ⑤SHOW BINARY IMG YES ⑥SHOW Ø FIX IMG YES ⑧DISP CHG-EVAL NO ⑨ PC-MNTR NO ⑩ THROUGH DISPLAY NO YESTENSION FUNC. NO

[11] Extension functions

The extension function has crosshair cursor display and manual display functions.


(1) Crosshair cursor display

- The crosshair cursor can be displayed on any position.
- "1" equals a 16-pixel line. "2" equals a full line.
- The initial coordinates of the crosshair cursor center are (256,240)

Operation procedure

- On the "TYPE RUN COND" screen, move the cursor to item
 "①EXTENSION FUNC." using the up and down keys, and press the SET key.
- 2. Select "DISPLAY+CURSOR" on the popup menu and press the SET key.
- 3. Press the SET key on the "12DISPLAY+CURSOR 1" line and select "1" or "2" on the popup menu. Then press the SET key.
- Select "(3)CROSS CURSOR COORD" and press the SET key. Now, the crosshair appear on the screen. Move the crosshair cursor using the up/down/left/right arrow keys. (It moves one pixel at a time)
- 5. When the cursor is positioned where you want it, press the SET key to confirm the position.

If you select "①DISPLAY+CURSOR 2," you can display two cursors when you output monitor images from Cameras 1 and 2.



(2) Manual measurement

With this function, you can measure distance between two points, the distance between X coordinates, or the distance between Y coordinates that were selected manually on the operation main screen.

Operation procedure


- 1. Select "①EXTENSION FUNC." on the "TYPE RUN COND" menu using the up and down arrow keys. Then press the SET key.
- 2. Select "MANL-MEAS" on the popup menu and press the SET key.

TYPE RUN COND SCREEN SAVE			F C1	BRT
		CAM1 PARTIAL-IMG YES(NUMERIC) YES YES YES NO NO NO MANL-MEAS	NO DISPLAY+CURSOR MANL-MEAS	

 Move the cursor to the upper function menu by pressing the TRG/BRT key and select "SCREEN." Then press the SET key. Select "OPS-MENU" on the popup menu and return to the operation screen.

TYPE RUN COND SCREE	N SAVE	F C1 BRT
1 MONITOR OUTPUT 2 CAPTURE IMG 3 MESSAGE DISPLAY 4 PATTERN DISPLAY 5 SHOW BINARY IMG 6 SHOW 6 FIX IMG 7 OPS MAIN DISP 8 DISP CHG-EVAL 9 PC-MNTR 10 THROUGH DISPLAY 11 EXTENSION FUNC.	CAM1 PARTIAL-IMG YES(NUMERIC) YES YES YES NO NO NO NO	OPS-MENU MAIN SELECT RETURN

- 4. Move the cursor to the "MNU-CHG" (menu change) item on the bottom of the operation screen and press the SET key to change the bottom menu display. Move the cursor to "MANL-MEAS" (manual measurement) and press the SET key.
- 5. The menu items for manual measurements will appear on the screen.
- Select "①CURSOR1-COORD" or "
 ②CURSOR2-COORD" and press the SET key.
- 7. Move cursor 1 or cursor 2 using the up/down/left/right keys. (They move one pixel at a time.)
 ⇒ The distance between the two points, and between the X coordinates and Y coordinates for the two points, will change on real time basis.



- 8. After the positions of the points are determined, press the SET key.
- 9. When the operation is complete, press the ESC key.

⇒ The manual measurement menu items will disappear.


2-2 Setting the system conditions

Set the following items on the "SYS-CND" menu to set the system conditions for the controller.

Setting item

- Input/output conditions
- Communication setting
- Computer link
- Gain/offset
- For the following items, see the pages listed below.

 - Communication setting Chapter 17
 - Computer link Chapter 18




[1] Manually setting the object type

On the operation screen, the object type (00 to 15) can be changed manually (using the remote keypad).

SYSTEM COND SET		F C1 BRT
SYS-COND		
- I/O CONDITIONS	(1)MEAS INP I/F	
- COMM-SET	2)OUT I/F(PARAL.)	
- COMPUTER LINK	(3) MANL TYPE CHNG	
GAIN-OFFSET	(4) PARALLEL INP X5	
OAIN-OFF DET	(5) PARALLEL INP X6	
	(6) STROBE OUT	
	(7)'READY'ON	
	() READY ON	
SET=SELECT A MENU ESC=B	ACK SEL=CHNG IMG TRG=POPU	IP

On the MAIN MENU, select "SYS-CND" -> "I/O CONDITIONS" -> "③MANL TYPE CHNG" in that order and then select "YES" or "NO" on the popup menu.

MANL TYPE CHNG	Description	
	The type can be manually changed on the operation screen. Note: If the "③MANL TYPE CHNG" is set to "YES," the type cannot be changed with an external interface (parallel I/O or general purpose serial interface).	
NO	The type cannot be manually changed on the operation screen.	



[2] Gain/offset adjustment

The gain and offset of the IV-S30J can only be adjusted by our service engineers. Users must not try to change them.

The data which can be adjusted is shown below for reference purpose only.

Generally, an image from the CCD camera can be optimized by adjusting the optical system, such as the lens iris. To make fine adjustments, the IV-S30J is equipped with functions to adjust the offset and gain of image signals from cameras 1 and 2 and the contrast on an external monitor screen.

- The gain and offset are adjusted by checking the display on the screen.

- The screen is kept in the through mode.

• Setting method

On the MAIN MENU, select "SYS-CND" -> "GAIN OFFSET" and the following message will appear on the screen.

CHANGING A SETUP MAY LEAD TO A MACHINE FAILURE. DO YOU CHANGE IT?

(YES=SET, NO=ESC)

GAIN-OFFSET SCREEN COND SAVE	F C1	BRT
$\begin{array}{c} \textcircled{1} \text{OFFSET} (CAM1) +(\uparrow) -(\downarrow) (026) \\ \textcircled{2} \text{GAIN} (CAM1) +(\uparrow) -(\downarrow) (245) \\ \textcircled{3} \text{OFFSET} (CAM2) +(\uparrow) -(\downarrow) (026) \\ \textcircled{4} \text{GAIN} (CAM2) +(\uparrow) -(\downarrow) (245) \\ \textcircled{6} \text{COMDUCT} (MND) +(\uparrow) -(\downarrow) (255) \\ \end{array}$		
(5) CONTRAST (MNTR) $+(\uparrow) -(\downarrow)$ (055)		~
\sim		
SET=VALUE INPUT_ESC=BACK_SEL=CHNG IMG_TRG=FUNC		


Press the SET key the "GAIN OFFSET" screen at the right appears.

Gain and offset adjustment	Details of adjustment (selection)	
①OFFSET (CAM1)	 The offset for camera 1 is adjusted with the up and down keys. The complete signal level is shifted leaving the amplitude of the image signals from the CCD camera unchanged. As the offset value is increased, the whole screen will becomes more white. 	
②GAIN (CAM1)	The gain for camera 1 is adjusted with the up and down keys. - The amplitude of the image signals from the CCD camera is changed. As the gain value is reduced, the screen will become lighter, and as the gain value is increased, the screen will become darker.	
③OFFSET (CAM2)	The offset for camera 2 is adjusted with the up and down keys The adjustment procedure is the same as that in Item $①$.	
④GAIN (CAM2)	The gain for camera 2 is adjusted with the up and down keys. - The adjustment procedure is the same as that in Item ②.	
⑤CONTRAST (MNTR)	The monitor contrast is adjusted with the up and down keys. - The intensity of image signals sent to the monitor is adjusted. As the contrast value is increased, the contrast on the screen will become stronger.	

2-3 Editing Operation screen

In this controller, the operation screen display can be changed. You can move, enlarge, reduce, or hide any block of text.

- (1) Move the cursor to "MAIN-MENU" on the operation screen and press the SET key.
- (2) Move the cursor to "EDIT MAIN OPS MENU" and press the SET key.



(3) Now the operation screen will appear. Select a block of text you want to edit using the up, down, left, and right arrow keys, and press the SET key. A pop up menu will appear and you can select from move, enlarge, reduce, and hide. (In this example, the block of text "OK" is selected.)

- MOVE

Select "MOVE" using the SET key. Now the highlighted block of text can be moved using the up, down, left, and right arrow keys. When the text is in the desired new position, press the SET key again.

- MAGNIFICATION/REDUCTION

Move the cursor to the "MAGNIFCATION" or "REDUCTION" line and press the SET key. The highlighted block of text can be enlarged or reduced.

- NON-DISP

Move the cursor to the "NON-DISP" line and press the SET key. The highlighted block of text will be deleted.

OPS-MAIN SCREEN OBJECT S/	AVE RESET F C1 BRT
(TYPE00) SAMPLE00 OK MEAS XXXXms MEAS1 MEAS-BIN-AREA MOVE MAGNIFCATION REDUCTION NON-DISP	AVE RESET F C1 BRT F C1 DRK ○ LOCK FULL V*.* ■ C1=002.2 OK C2=100.0 OK NG-IMG 00(00)
X0~6 Y0~7 READY	

2-4 Option

With the IV-S30J, you can initialize the measurement settings, and run a self-diagnosis from the option menu.

Setting method

1) Display the "OPTION" from the "MAIN MENU."

MAIN MENU	F C1 BR
IVS30J	
SYS-CND OBJECT TYPE COND SET WIZARD EDIT MAIN OPS MENU OPTION	

2) Select the operation you want, such as "①INITIALIZATION" or "②SELF DIAGNOSIS."

OPTION SCR	EEN SAVE		F C1 BRT
1 INITIALIZATION 2 SELF DIAGNOSIS	ALL-INIT EXEC	INIT-RAM	

Select any of the "ALL-INT" (initialize both FROM and RAM), or "INT-RAM" and the following message will appear.

()MEM INIT?(YES=[SET], NO=[ESC])

Press the SET key to start the initialization. The bar shown below will appear and display the progress of the initialization.

	INITIALIZATION	
REFERENCE IMG		
SYSTEM I/O		
OBJECT TYPE COND		

After the initialization is complete, the word "INITIALIZING" will change to "COMPLETE INIT." Press the ESC key to return to main screen.

(2) SELF DIAGNOSIS

Select "②SELF DIAGNOSIS" and press the SET key twice. The controller will execute a selfdiagnosis and display the results of the diagnosis, as shown right. If the diagnosis results are normal, "OK" will be displayed. If the results are abnormal, "NO" will be displayed.

When the diagnosis is complete, the "DIAGNOSING" display will change to "COMPLETE DIAGNOSIS."

;	OPTION SCRI	EEN SAVE	F C1 BRT
	①INITIALIZATION ②SELF DIAGNOSIS		INIT-RAM
		"D	hen the diagnosis is complete, the IAGNOSING" display will change to OMPLETE DIAGNOSIS ."
	VRAM SDRAM	DIAGNOSIN OK OK	G
	TYPE COND REFFERENCE IMG	OK OK	
	BOOT-PROG SYSTEM-PROG	OK OK	
	SET=EXEC ESC=BACk	SEL=CHNG	IMG TRG=FUNC


Chapter 3 : Setting Measurement Conditions

3-1 Outline

The measuring conditions for each object type are set on the "OBJECT TYPE COND" SELECT OBJECT TYPE COND (conditions for object type) menu. A maximum of 16 object type numbers can be registered.

OBJECT TYPE COND +-TYPE00 TYPE05

I ABEL-BIN-OBJ POINT-MEAS MULTI-POSI MULTI MATCHES




available (from 1 to 4) will be assigned. "MEAS0" is dedicated to positional deviation measurements.

Setting procedure

A general outline of the setting procedures is shown below. For details, see each chapter.

Setting the measurement program conditions	MEASURI MEASURI MEASURI MEASURI MEASURI	= 1 = 2 > Jun = 3	np to the next page
Select the image pre-processing method	Image pre-	processing ⊏> S	ee page 3-19
₩			
Set final numerical calculation	"FINAL NU	M.CALC" 🖒 See	e Chapter 14
▼			·
Set final output condition	"FINAL OU	TPUT COND" 너	> See Chapter 15
<u>↓</u>			
Setting the input/output conditions	"OBJ-TYPE	∃ I/O" 🖒 See Cł	napter 16
¥			
Setting the system conditions	"OBJ-TYPI	E SYS"	
Save the settings in the flash memory	"SAVE" ⊏>	See page 1-14	
Return to the MAIN OPS MENU	"OPS-MEN	U"	




3

3-2 Shared settings

[1] Window shape selection and settings


This section describes how to select and set the EX: Register conditions of "Positional deviation window shapes used for image processing (e.g. rectangular windows, horizontal or vertical line boundaries, circle windows, elliptical windows, and polygonal windows). This can be done using the up, down, left, and right setting keys on the remote key pad.

measurement.'



(1) Rectangular window

Line type	Image processing used	Measurement programs	
Solid lines	Reference image for gray scale search and binary image matching	Positional deviation measurement (gray scale search), degree of match inspection, lead inspection, multiple position measurement (gray scale search), and multiple degree of match inspection.	
	Window containing a binary image	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion.	
	Gray scale search area detection	Positional deviation measurement (gray scale search), degree of match inspection, lead inspection (criteria search), multiple position measurement (gray scale search) and multiple degree of match inspection.	
Dotted lines	Edge of an area detection	Positional deviation measurement (edge detection), multiple position measurement (edge detection).	
	Binary image window mask	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion.	



To register reference images

To register reference images, the system should be in the "Freeze" mode. \Rightarrow See page 1-10

Window specifications

	Line type	Move	Size	Minimum	Maximum
Reference image	Solid line	One pixel at a time	In unit of one pixel	16 x 16 (pixel)	X x Y (X*Y = 65536 pixels)
Search area	Dotted line	One pixel at a time	In unit of one pixel	16 x 16 (pixel)	512 x 480 pixels


(2) Horizontal/vertical lines

Line type	Image processing used Measurement programs	
Solid lines Gray scale search (reference image)		Positional deviation measurement (gray scale search), degree of match inspection, lead inspection (criteria search).
Solid lines	Edge of an area detection	Lead inspection
Dotted lines	Gray scale search line detection	Positional deviation measurement (gray scale search), degree of match inspection, lead inspection (criteria search).

How to set horizontal lines

The following items on the settings menu can be used to define lines: MOVE, S.PT, E.PT. Shown here is an example of how to define a solid line.

1. Move



- Left key

- Up key

3. Specifying the ending point

same as in the move item)


(The left and right keys function the

- Right key

- Down key

How to set vertical lines

1. Move



2. Specifying the starting point - Up key - Down key



(The left and right keys function the same as in the move item)

To register reference images

To register reference images, the system should be in the "Freeze" mode. \Rightarrow See page 1-10.

Window specifications

Horizontal lines						
	Line type	Move	Length	Min. length	Max. length	
Reference image	Solid line	Horizontal direction: One pixel at a time	In units	8	512	
Search area	Dotted line	Vertical direction: One pixel at a time	of pixels	pixels	pixels	

- Vertical lines

	Line type	Move	Length	Min. Iength	Max. length
Reference image	Solid line	Horizontal direction: One pixel at a time	In units	8	480
Search area	Dotted line	Vertical direction: One pixel at a time	of pixels	pixels	pixels

When setting the horizontal and vertical lines, specify the line length as follows: The reference image must shorter than the search area lines.


(3) Circle window


Line type	Image processing used	Measurement programs
Solid lines	Window containing a binary image	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion
Dotted lines	Binary image window mask	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion

How to set a circle window


The following items on the settings menu can be used to define the circle window: CENTER, RAD. Shown here is an example of how to define a solid line circle window.

1. Specifying the center






- Left key



2. Specifying the radius



(4) Elliptical window

Line type	Image processing used	Measurement programs
Solid lines	Window containing a binary image	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion
Dotted lines	Binary image window mask	Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion


How to set an elliptical window


The following items on the settings menu can be used to define the elliptical window: CENTER, RAD. Shown here is an example of how to define a solid line elliptical window.


1. Specifying the center



- Up key










- Right key

2. Specifying the radius

- Up key








(5) Polygonal window

With the binary area measurement function, object counting after binary conversion function, object identification after binary conversion function, or point measurement after binary conversion function, you can create any shape of polygonal window with up to 32 sides, in addition to the rectangles, circles, and ovals that were available in previous versions.




Any polygonal window (up to 32 sides)

How to create a window

On the "POLYGON" setting screen, specify a coordinate using the up, down, left, and right arrow keys, and then press the SET key. Thereafter, specify points 02, 03 and so on, in numerical order. After specifying the last coordinate, press the SET key again to confirm the polygonal shape you have drawn.


To edit the polygonal shape, select a point to modify using the up and down arrow keys, and press the SET key. A popup menu will appear. Select CHANGE, INSERT or DELETE.




[2] Image settings

What follows is a description of how to use the image settings to control the measuring program.

(1) Pixel contraction and detection precision (gray scale processing)



Note: At the "DETAIL" item in the upper function menu, select "CONTR.PIXEL." Then, "(5) or (9)CONTR.PIXL" will appear on the screen.



- To increase the speed of your search, you must take into account the settings listed below.


- 1. When using the high precision setting, a smaller image should be used.
- 2. Reduce the size of the scanned image.
- After considering what the maximum out of position dimension would be, make the search area as small as possible.
- 4. If the size of the object is larger than 8 pixels then set the pixel contraction to "3."

Measurement programs which are affected by these settings

Positional deviation measurement (gray scale search), degree of match inspection, lead inspection, multiple position measurement, and multiple degree of match inspection.

(2) Threshold value setting

The IV-S30J treats the "areas darker than the lower limit value" or "brighter than the upper limit value" as "black." It treats that the areas between the upper limit value and lower limit value as "white." However, if the white-black reverse function is enabled, conversion to white/black will be reversed. Normally, if you want to use only one threshold value for binary conversion, set the upper limit value to "255." Then you only need to adjust the lower limit value to a threshold value that works for our application.




Setting the threshold value automatically The binary threshold value can be set automatically.

In the binary area condition of each measurement program, execute the "AUTO REG" function (lower limit only or upper and lower limits) and the optimum threshold values will be set in each measurement area automatically.

⇒ The binary area conditions (binary image mask) menu in the binary area measurement.


Measurement programs which are affected by these settings

Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion, point measurement (binary images) - Binary area condition (binary image mask) menu of the binary area measurement



(3) Setting window boundaries (enable/disable)


This function enables and disables the labeling (object identification) of binary images located that cross over the window frame boundary.



Select "DETAIL" in the upper function menu on the REG COND screen. Select "BOUNDARY PROCESS" from the popup menu and then press the SET key.

(4) Object identification and numbering function (labeling)


Object identification and numbering (labeling) is a process for locating separate object and assigning serial numbers (labels) one at a time in a binary image. By this process, multiple objects in the same binary image can be handled separately or as a group.



Measurement programs which are affected by these settings Object counting by binary conversion, object identification by binary conversion

(5) Binary processing (fixed/threshold value correction)

By setting THRESHOLD-ADJ (threshold adjustment function), the IV-S30 can cope with variations in lighting.



Note: In order to use the THRESHOLD-ADJ(threshold adjustment function), the monitor brightness functions must be selected to measure variations in lighting. If you don't select the monitor brightness function, a LIGHT LVL NOT SET (correcting binary value: monitor illumination not selected) error will occur.

Fails to convert the image due to a variation in lighting

Threshold correction using either VAR-DIFF (enter variations in lighting as value) and VAR-RATE (enter variations in lighting as a rate) can be selected the THRESHOLD-ADJ (the threshold adjustment function).

Set (selection) item		Details of correction
	Variation difference	Correct the threshold value by adding the previously specified threshold value to the light level variation difference. (Measured light level — reference light level) + specified threshold value
adjustment Variation rate		Correct the threshold value by multiplying the previously threshold value to the light level variation rate. (Measured light level ÷ reference light level) x specified threshold value

Measurement programs which are affected by these settings

Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion, point measurement (binary images)

Setting method

Select "③THRESHOLD" on the "REG COND" screen and then change the upper and lower limit values using the up, down, left, and right arrow keys.

REG COND SCREE	N COND SAVE DETAIL	F C1 BRT			
(1) MEAS SHAPE	RECTANGLE				
2 MEAS AREA	SET (224,208)~(287,271)				
③THRESHOLD	SET [U.LM255 L.LM100(0~255)]				
④INVERT B/W	NO 🛉 🛉				
Change using the up and					
	down arrow keys.				

(6) The expansion/contraction method of eliminating noise in binary images

When converting an image to binary values, it is often the case that dots of noise will show up in the converted image. This noise may be eliminated during pre-processing by using the smoothing function. However, it can also be dealt with through the expansion/contraction noise elimination method.

1 Expansion

A single white dot, or small groups of white dots, in the middle of a black background can be eliminated from the image.


(2) Contraction

A single black dot, or small groups of black dots, in the middle of a white background can be eliminated from the image.

The IV-S30J has both "contraction \rightarrow expansion" and "expansion \rightarrow contraction" functions for eliminating binary noise.


(1) Expansion \rightarrow contraction

When isolated dots of noise are eliminated by expansion, the areas enlarged by the expansion are returned to their original size by contracting them again.



2 Contraction \rightarrow expansion

When isolated white noise is eliminated by contraction, the areas shrunk by contraction are returned to their original size by expanding them again.



- Number of times of expansion and number of times of contraction can be set independently. When the number of contraction cycles is set to 0, and the number of expansion cycles is one or greater, then only the expansion function will be used.


On the other hand, if the number of expansion cycles is set to 0 and the number of contraction cycles is one or greater, then only the contraction function will be used.

Measurement programs which are affected by these settings

Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion

Setting method


Select "DETAIL" in the upper function menu on the REG COND screen, and choose "BINRY NOISE FILT" to change the blank box to a filled box. Then, "⑤BINRY NOISE FILT" will appear on the REG COND screen. Press the SET key on this line and select "EXPD. -> CONTR." or "CONTR -> EXPD." from the popup menu.



(7) Edge detection

The "edge" refers to the boundaries between the brighter (white) and darker (black) parts in an image. The "edge detection" function is used to detect this boundary by processing the image.

An example of detecting a point using the edge detection function and user specified criteria




- The edge detection point coordinates are used as a reference point to detect an out of position condition.
- Edge detection in binary images is much quicker than in a gray scale search. However, the binary image detection process is less precise at detecting position.

- Setting the threshold value automatically By executing an "AUTO.REG" (automatic setting) for the edge detection condition in each measurement program, the IV-S30J can automatically detect edges in the measurement areas, and set the optimum threshold values automatically (density difference and edge width).
- Measurement programs which are affected by these settings

Positional deviation measurement (edge detection), lead inspection, multiple position measurement (edge detection).

- Edge detection menu of the lead inspection




(8) Artifact processing

Artifact processing is a method of processing that eliminates the false detection of the edge of the target object when an artifact is in the line being scanned. This process can be used during edge detection. The real edge of the target object is detected by computing the average duration of the dark area in the scan line, which is much longer for a target object than for an artifact.

Example of detection

An example of light to dark averaging (DTCT MODE:BRT DRK) while scanning horizontally (SEARCH DIR:HORIZ), with artifact processing (enabled) (ARTIF).



Edge detection point (with artifact processing: enabled)

When artifact processing is disabled (NO ARTIF) in the above example, the edge detection point changes.



Edge detection point (with artifact processing off)


Measurement programs which are affected by these settings

Positional deviation measurement (edge detection), lead inspection, and multiple position measurement (edge detection).

(9) Contrast search in the reference image

Using the reference image area setting in the gray scale search mode, the area of maximum contrast can be identified automatically in the captured image.

- While moving the selected reference image area within the specified search area on the captured image one pixel at a time, the IV-S30J determines the density in each area in the reference image, and automatically picks the area with the largest difference.
- This function may be used for sorting printed objects.




Find the area having the maximum features in the reference image area.

Measurement programs available that use this setting

Positional deviation measurement (gray scale search), degree of match inspection, multiple position measurements (gray scale search), and multiple degree of match inspection.

Setting method


Move the cursor to the "④REFERENCE IMG" with up and down arrow keys on the reference image area setting screen. Next, select "CONTRAST SRCH." Finally, press the SET key.



[3] Evaluation conditions

The setting details and procedures for setting the evaluation conditions are the same for all measurement programs.

Evaluation conditions [EVALUATION COND] menu for measuring degree of match



while adjusting for positional deviation. rightarrow pages 3-30 to 3-32.

The "degree of match + 09000" refers to a degree of match (match between individual pixels) between the registered image and the measured image that is equal to 90.00% or more of the total.

Using the up and down keys, you can set the output to NO (no output), Y0 to 7 (output on these relays), or C000 to C127 (output on these secondary relays), in the output area of the menu. (If the test result returns OK, then the output is turned ON. If it is NG, then it is turned OFF).

When carrying out a test using item (1) TEST, on the menu, the resulting measurement values and the evaluation (OK or NG) will be displayed.

Condition setting

Upper and lower limit values of the all evaluation condition items can be set automatically with the following processes.

After testing more than one good workpieces, the IV-S30J automatically set the limits based on the test results.

Condition settings	Details
AUTO (±**%)	 Multiple the specified rate (±%) on the newly tested good workpieces, and compared this value with the range between the current upper and lower limits. If it is outside the upper and lower limits, the IV-S30 renews the maximum or minimum value with this value. At the first setting, the first test result will be the upper and lower limit without any condition. [±**%] The value from ±00% to ±99% can be entered to the "±**%" in units of 1%. (Default value = ±10%) To enter this position, move the cursor to the "AUTO" position and press the up and down keys to change the value. After determining the value, press the SET key, upper and lower limits of each item will be automatically set with tis %.be the upper and lower limit without any condition.

3-17

Setting method

There are two ways to get to the evaluation condition setting screen.

 Select "CND" in the upper function menu on the MEAS CND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the "EVALUAT COND" screen.

MEAS CND SCREEN COND SAVE	F C1 BRT			
1 DTECT PRECISION STANDARD 2 REGISTER NO. 0(0-7) 3 MODE 1P-SCH 4 DTECT ANGL -15; 5 ANGLE UNIT 10 REGISTER NO. 6 MDL 0 7 MDL 1 00010203040506075 S 1 1 1	IMG PRE-PROC REG-COND(S) REG-COND(E) POSITION CORRECTION EVALUATION DST&ANGL NUM-CALC OUT			
SET=VALUE INPUT ESC=BACK SEL=CHNG IMG TRG=FUNC				

 Move the cursor to the "EVALUATION COND" item on the Menu tree screen and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT			
OBJECT TYPE COND TYPE RUN COND TYPE RUN COND MAGE-ADJ MEA-CND(CAMERA1) MEA-CND(CAMERA1) MEASO(POSI-DEVIATION) MEASO(POSI-DEVIATION) MEASO(POSI-DEVIATION) MEASO(POSI-DEVIATION) MEA-CND(CAMERA1) EVALUATION COND EVALUATION COND POSI-CORRECT MEAS(NEW) MEA-CND(CAMERA2) FINAL NUM.CALC FINAL OUTPUT COND OBJ-TYPE I/O	1 REGISTER NO. 2 CONDITION SET 3 X COORD. (BDL0) 4 Y COORD. (MDL0) 5 X DEVIATE (MDL0) 6 y DEVIATE (MDL0) 7 MATCH LVL (MDL0) 8 ANGULAR DEVIATE 9 X COORD. (MDL1) 10 Y COORD. (MDL1) 11 X DEVIATE (MDL1) 12 y DEVIATE (MDL1) 13 MATCH LVL (MDL1) 14 TEST			
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP				

[4] Image pre-processing


A comparative calculation between images, gray level changes, and space filter are available for image pre-processing.

Comparative calculation between images	Subtracting, absolute value of difference (between camera 1 and reference image, between camera 2 and reference image, between camera 1 and camera 2)
Gray level changes	Magnification by "n" processing, γ (+/-) correction, histogram widening, midrange emphasis
Space filter	Smoothing (center/average),edge emphasis,edge extraction, horizontal edge,vertical edge


How to get to the "IMG PRE-PROC" screen

Select "OBJECT TYPE COND" and then "TYPE00" or "TYPE(NEW)" on the "MAIN COND" screen. Then select "MEA-CND(CAMERA1)" and "MEAS" to open a measurement screen. At the "①MEAS SELECTION" item, press the SET key and choose a measurement program from the popup menu. Note: If the "①MEAS SELECTION" is set to "NO," the image pre-processing cannot be specified.

MEASUREMENT 1 SCREEN COND SAVE



Press the ESC key to return to the OBJECT TYPE COND screen. Then select "IMG PRE-PROC."



The "IMG PRE-PROC" screen will appear.

- ⇒ For details about "COMPARE IMGS" (compare images), see page 3-20.
- ⇒ For details about "CHNG GRAY LEVEL" (change gray level), see page 3-22.
- ⇒ For details about "SPACE FILTER," see page 3-23.

	IMG PRE-PROC SCREEN	COND SAVE	F C1 BRT
Э	COMPARE IMGS	NO	
	(2) CHNG GRAY LEVEL	NO	
	③SPACE FILTER	NO	

(1) Comparative calculations between images


It is possible to run calculations on the differences between the images taken by camera 1 and camera 2, as well as on the differences between the current image and the already stored reference image.

There are two types of calculation: "subtraction" and the "absolute value of the differences."

Subtraction	Light level in image 1 (0 to 255) - Light level in image 2 (0 to 255) ⇒ Light level after calculation However, a result less than 0 will give a result of 0.
The absolute value of the differences	Light level in image 1 (0 to 255) - Light level in image 2 (0 to 255) ⇒ Light level after calculation (0 to 255)

COMPARE IMGS	SCREEN	SAVE		F	C1 BRT
1 CALC.TYPE 2 CALC.AREA		2,216)-(279,263)	NO SUBI1-T1 DIFF.ABS I1-T1		

Example of comparative calculations between images



3

Setting details	
1. Select the camera to be used for	IMG PRE-PROC SCREEN COND SAVE F C1 BRT
"①COMPARE IMGS" from the popup menu. Then select the "②COMP IMGS COND" item to get to the setting screen.	1 COMPARE IMGS CAM1 (2) COMP IMGS COND (TO NEXT SUB-MENU) (3) CHNG GRAY LEVEL CONTRAST MAGNI (4) CONTRAST MAGNI 00.0TIMES (5) SPACE FILTER SMOOTH(AVE) (6) NUM.OF FILTER 1(0-5)
	SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TRG=FUNC
	COMPARE IMGS SCREEN SAVE F C1 BRT
2. Select "①CALC.TYPE" and then set "②CALC.AREA."	①CALC.TYPE NO ②CALC.AREA SET (232,216)-(279,263)
	SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TRG=FUNC

The list of settings which may be selected at item "①COMPARE IMGS" is as follows.

SELECT CAMERA	①CALC.TYPE	Contents
NO (none)		Comparative calculations of differences between images will not be carried out.
CAM 1	None	Comparative calculations of differences between images will not be carried out.
(camera 1)	Subtraction I1-T1	The reference image T1 (* 1) is subtracted from the image taken by camera 1.
	The absolute value of the difference between I1-T1	The absolute value of the difference is calculated between the reference image T1 (* 1) and the image taken by camera 1.
CAM 2	None	Comparative calculations of differences between images will not be carried out.
(camera 2)	Subtraction I2-T2	The reference image T2 (* 1) is subtracted from the image taken by camera 2.
	The absolute value of the difference between I2-T2	The absolute value of the difference is calculated between the reference image T2 (* 1) and the image taken by camera 2.
CAM 1&2	Subtraction I1-I2	The image taken by camera 1 is subtracted from the image taken by camera 2.
(cameras	Subtraction I2-I1	The image taken by camera 2 is subtracted from the image taken by camera 1.
1 & 2) (*2)	The absolute value of the difference between I2-I2	The absolute value of the difference is calculated between the image taken by camera 1 and the image taken by camera 2.

The reference images T1 and T2 (*1) and the size of the areas covered by I1 and I2 (the images taken by cameras 1 and 2) (*2) may be set in item "②CALC. AREA."

(2) Gray level change

To change the gray level, you can change the "**.*TIMES" (magnification by N processing), the " γ +," " γ -" (γ (positive/negative) correction), the "CHNG-L" (widening histogram), and the "INCRS-M" (mid emphasis) functions.

IMG PRE-PROC SCREEN COI	ND SAVE	F	C1 BRT
①COMPARE IMGS	NO		
② CHNG GRAY LEVEL →	NO CONTRAST MAGNI		
③SPACE FILTER	γ+		
	γ- CHNG-L		
	INCRS-M		

Gray level change		Details	
Magnification by N processing (**.* TIMES)	 To improve the contrast (the ratio of high value gray levels to low value gray levels), specify a magnification rate (00.0 to 99.9) for multiplying the image data. If the magnified gray level exceeds 255, the system will correct the value to 255. 		
γ (positive/negative) correction	- γ positive correction: used when the mid gray level is too low. 255 394 406 900 1000 1000 255 255 $7 negative correction: used when the mid gray level is too high.$ 255 1000		
Histogram widening	This is a method to widen the histogram of an image in which the histogram is at part of it, thus improve its contrast. $ \begin{array}{c} $		
Mid emphasis	- The input image density (G) of with the following formulas:	remaining the background image. can be converted to the output image density Output image gray level $(G \div 127)^2 \times 127$ $(\sqrt{(G-128)} \div 127 \times 127) + 127$	

(3) Space filter

Space filter includes various image manipulation processes that create more readable images by removing noise and distortion in the image data. And, by extracting or emphasizing certain image features, it is easier to evaluate or identify target objects by converting the images into standard patterns.

In the IV-S30J, you can select from "smoothing (average, center)," "edge emphasis," "edge extraction," "horizontal edge," and "vertical edge."

IMG PRE-PROC SCREEN	COND SAVE	F	C1 BRT
	NO		
2 CHNG GRAY LEVEL	NO	NO	_
③SPACE FILTER ④NUM.OF FILTER	SMOOTH(AVE)	NO SMOOTH(AVE) SMOOTH(CENT) EMPHAS EDGE EXTRACT EDGE HORIZ-EDGE VERT-EDGE	

Item	Contents		
Smoothing (center)	 Specify the median pixel gray level from the surrounding 3 x 3 area. Since noise elements are difficult to select, they will not affect the output. 	 Display smooth images with decreased noise. Used to eliminated surface flaws and unevenness in the reflected light caused by 	
Smoothing (average)	 Specify the average pixel gray level from the surrounding 3 x 3 area. Since noise elements are included in the average, the noise will affect the output. 	 This type of smoothing (averaging) is faster than the median smoothing. 	
Edge emphasis	 Display images with sharp boundaries between brighter and darker areas. Used to stabilize and create a binary outline around unclear objects. 		
Edge extraction	 Display images after extracting and clarifying the boundaries between the brighter and darker areas. 		
Horizontal edge	 Horizontal edge extraction: Display only the horizontal boundaries of an object. 	 Used to measure objects with low contrast. 	
Vertical edge	- Vertical edge extraction: Display only the vertical boundaries of an object.		

Example of an image



- Edge emphasis



- Edge extraction (horizontal)



- Smoothing



- Edge extraction (All)



- Edge extraction (vertical)



[5] Image adjustment

How to set the image adjustment function Select "IMAGE-ADJ" on the "SELECT OBJECT

TYPE COND" screen and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND TYPE00 TYPE RUN COND IMAGE-ADJ E→ MEA-CND(CAMERA1) FINAL NUM.CALC FINAL OUTPUT COND OBJ-TYPE I/O OBJ-TYPE SYS. TYPE(NEW)	 ADJ.IMG GRAY(CAM1) ADJ.COND(CAM1) ADJ.IMG GRAY(CAM2) ADJ.COND(CAM2)

Shading correction

This process removes unevenness from images that have gray level unevenness caused by an illumination.

Adjustment condition

To set the adjustment conditions for gray level corrections, select "②ADJ-COND" and then press the SET key to show the sub menu.

IMAGE-ADJ SCREEN SAVE	F C1 BRT
(1) ADJ.IMG GRAY(CAM1) YES → YES ② ADJ-COND(CAM1) (TO NEXT SUB-MENU) ③ ADJ.IMG GRAY(CAM2) NO	
ADJ.IMG GRAY SCREEN SAVE	F C1 BRT

1 ADJ.MODE	SUBTRACTING
2 ADJ.AREA	SET (224,208)-1287,271)
3 SET STD.GRAY LV	SET (224,208)-(287,274) GRAY(000)
	SUBTRACTING DECREASING FILTERING

Correction mode	Details
SUBTRACTING	 Divide a scanned image with the reference image that expresses changes of dark and bright as a whole, and correct the brightness throughout the image. {(Each gray level of scanned image) X reference gray level} / (Each gray level of reference image) Divide a scanned image that is shot under the uneven light by a blank image that is shot under the same light condition, you can change the image to the one that is shot under the even light.
DECREASING	 Subtract a scanned image with the reference image that expresses changes of dark and bright as a whole, and correct the brightness throughout the image. {(Each gray level of scanned image) + reference gray level} - (Each gray level of reference image) Subtract a scanned image that is shot under the uneven light by a blank image that is shot under the same light condition, you can change the image to the one that is shot under the even light.
FILTERING	 Filter a scanned image with the maximum value, and then with an average value, to make a brightness image. [Max. value filter: Max. gray level of 3 x 3] ⇒ [Average value filter: Average gray level of 3 x 3] - Use this filter when a brightness distribution image (reference image) for the scanned image cannot be obtained.

[6] Binary image mask

Use the binary image mask when an object to measure by binary conversion cannot be measured using rectangle, circle, or ellipse window.

Mask a scanned image (AND) with the registered binary image.

Binary image mask	Gray level in the scanned image	Gray level output after masking
1	0 to 255	0 to 255 (gray level in the scanned image)
0	0 to 255	0 (black fixed)

Measurement programs which are affected by this setting

Area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion

Setting method

- 1. On the SELECT OBJECT TYPE COND screen, select "MEAS CND" (measurement conditions) and press the SET key. The MEA-CND screen will appear. Select "①WINDOW" and press the SET key. Select "BINARY-IMG-MASK" from the popup menu.
- Highlight the "④MASK BINARY IMG" item and press the SET key. A popup menu will appear. Select "REF-IMG" or "MANUAL" and the "⑤BIN IMG MASK" line will appear. Selecting "REF-IMG" I See page 3-26 to 27. Selecting "MANUAL" I See page 3-28 to 29.
- Select "⑤BIN IMG MASK" (binary image masking condition) and press the SET key. The, MASK BINARY IMG screen will appear.

MEA-CND SCREEN	COND SAVE	* NUM-OF-MASK 1	F C1 BRT
WINDOW REGISTER NO. REGISTER EXIST MASK BINARY IMG	NO	NUM-OF-MASK 2 NUM-OF-MASK 4 BINARY-IMG-MASK POLYGON	
REGISTER NO. ⑤ BINARY AREA	0001020304050 ×	060708091011121	31415
MEA-CND SCREEN	COND SAVE		F C1 BRT
() WINDOW (2) REGISTER NO. (3) REGISTER EXIS (4) MASK BINARY II (5) BIN IMG MASK REGISTER NO. (6) BINARY AREA	T NO MG REF-IMG (TO NEXT SUB-M	NO REF-IMG	31415
MEA-CND SCREEN	COND SAVE		F C1 BRT
(1) WINDOW (2) REGISTER NO. (3) REGISTER EXIS (4) MASK BINARY IN (5) BIN IMG MASK	T NO //G REF-IMG (TO NEXT SUB-M	ENU)	
REGISTR NO. (6) BIN AREA COND		060708091011121	31415

4. Here you can set the masking conditions. First move the cursor to "①MASK AREA" and press the SET key. Specify and confirm the position and size of a masking area. On the "②THRESHOLD" line, adjust the threshold value between 0 and 255. At "③MASK INVERT B/W," select whether or not to invert the masking area. When a mask noise removing method is specified in "④MASK NOISE FILTR," the "⑤NUM.OF MASK FILT" (number of times to filter) line will appear. Set the number of times from 0 to 5.

MASK BINARY IMGCREEN S	AVE	F C1 BRT
MASK AREA SET ② THRESHOLD SET ③ MASK INVERT B/W NO ④ MASK NOISE FILTR EXPE ⑤ NUM.OF MASK FILT EXPE		NO EXPD. → CONTR. CONTR. → EXPD
	MA	ASK AREA

Setting example


• When "4 MASK BINARY IMG" is set to "REF-IMG."

Shown below is an example of how to specify a binary image mask for a star shape.



1) Store a binary image mask on the "BINARY IMG MASK" menu (mask setting = standard) shown above.


1. Specify the mask outline for the object to be measured.



Mask outline

2. For correcting minor positional deviations, store an enlarged image as the binary image mask.





 Star-shaped object to be measured (inside boundary)


3. Return to the "TYPE MEAS COND" menu. Select "MEAS-COND" in the "⑤ MEAS-BIN-AREA" item

2) Settings on the "TYPE MEAS COND" menu

- 1. Select "YES" from the popup menu at "③ REGISTER EXIST."
- 2. Select "O" (00) at the "6BINARY AREA" item and press the SET key to bring up the "REG COND" menu.

REGIST COND SCREEN COND SAVE	F C1 BRT
1 WINDOW BINARY-IMG-MASK (2) REGISTER EXIST YES (4) MASK BINARY IMG REF-IMG NO (5) BIN IMG MASK (TO NEXT SUB-MENU) REGISTR NO. 0001020304050607980910111 (6) BINARY AREA 0	
SET=SELECT(YES/NO) ESC=BACK SEL=CHNG IMG TRG=FU	INC

3) Setting the binary area conditions




1. Specify a measurement area smaller than the mask area and specify the binary conditions.



-Measuring area

2. Return to the MAIN OPS MENU.

4) Measure the binary area



White dots (six)

Image after executing a measurement



Binary mask image (registered in step 1)-2)

- The white dots will be converted to black dots by applying the binary image mask.

• When "④MASK BINARY IMG" is set to "MANUAL."

Shown below is an example of a binary image mask that matches the following shape (an 8 pointed star).



MEA-CND SCREEN	COND SAVE	F C1 BRT
	BINARY-IMG-MASK	
2 REGISTER NO.	0 NO	
③ REGISTER EXIST ④ MASK BINARY IMG	NO REF-IMG MANUAL MANUAL	
REGISTER NO. 5 BIN AREA COND	0001020304050607080910 ×	1112131415

- 1. Select "④MASK BINARY IMG" and press the SET key. Select "MANUAL" from the popup menu.
- 2. Select "5 BIN IMG MASK" (binary mask conditions) and press the SET key twice.

MEA-CND SCREEN C	OND SAVE	F C1 BRT
	BINARY-IMG-MASK	
2 REGISTER NO.	0	
③REGISTER EXIST	NO	
(4) MASK BINARY IMG	REF-IMG	
5 BIN IMG MASK	(TO NEXT SUB-MENU)	
REGISTR NO.	001020304050607080910111213	1415
6 BIN AREA COND	×	

3. The "MASK BINARY IMG" screen will appear. Select "①MASK AREA" and press the SET key twice.


MASK BINARY IMG SCR	EEN SAVE	F C1 BRT
2 MASK IMVERT B/W	SET NO REG DISP	

4. The "POLYGON" setting screen will appear.

POLYGON	RESET MOVE	RETURN	F C1 BRT
1 POINT01	(255,255)		
			X:224 Y:208

Setting the Conditions for Each Object Type


5. Select "0" using the up and down keys and then select "MOVE" using the left and right keys. Finally, press the SET key.



3

- 6. Move vertex 02 to 08 a little outside of the first point on the star using the up, down, left, and right keys, and then press the SET key.





- After creating a mask area, press the ESC key to return to the "MASK BINARY IMG" screen. Select "③MASK REGIST" and press the SET key. The cursor will move to the "REG" position. Press the SET key to register the mask.
 - The area inside the mask will change to white. To invert the inside and outside shades (change white to black and black to white), select "YES" on the "②MASK INVERT B/W" line.

MASK BINARY IMG SCREE	N SAVE	F C1 BRT
1 MASK AREA SE 2 MASK IMVERT B/W NC 3 MASK REGIST. RE)	

[7] Position correction


Based on the positional deviation data measurement 0 (positional deviation measurement), the correction of the image coordinates is dealt with using measurements 1 to 4.

(1) Correction details


The types of position correction available are: XY correction, angular correction (standard) and angular correction (high precision)

Туре	Details
XY correction	 The position is adjusted according to the amount of deviation in X and Y at the first point (model 0) detected in measurement 0. There are three correction directions: X axis correction, Y axis correction and X and Y axis correction. X axis correction Adjusted misalignment in the X axis Y axis correction Adjusted misalignment in the Y axis
Angular correction (standard)	The position is adjusted because of a detected angular deviation q in rotation [2-point search/2-point edge/1-point search + 1-point edge] from measurement 0. - When "YES" is selected in the DTECT ANGL item specifying a "1P- SCH" or a "1P-SCH+1P-EDGE" in measurement 0, the position will be corrected according to the angle detected.
Angular correction (high precision)	The position is adjusted because of a detected angular deviation qin rotation [2-point search/2-point edge/1-point search + 1-point edge] from measurement 0. The high precision angular correction settings allows the IV-S30 to display a very precisely corrected image. But, this selection lowers rotation processing speed. - When "YES" is selected in the DTECT ANGL item specifying a "1P- SCH" or a "1P-SCH+1P-EDGE" in measurement 0, the position will be corrected according to the angle detected.

[Example of a comparison between standard and high precision angular correction]





3



(3) Correction example

- Example of correcting the first X and Y point
 - 1. Amount of correction (X2-X1, Y2-Y1) specified by measurement 0 (positional deviation measurement)







3-31

Example of angular correction

1. Detection of the amount of angular deviation (using measurement 0, 2 point search (positional deviation measurement).


- Registration image





2. Performing measurement 1 to 4 (of distance and angle measurement) on an image that has been rotated around its center by the amount of angular deviation detected in step 1.

- Image that has been rotated around its center in step 1



[8] Title registration

A title for a object type number can be entered and saved when the object type number is displayed on the screen.

Purpose

The title is used to make it easier to control the details of the settings for the object type.

Title characters

A maximum of 16 letters and symbols may be entered.


Operation method

Select "OBJECT TYPE COND" on the "MAIN MENU" screen and then select "TYPE00" (the current type). Then press the "TRG/BRT" key. Select "TITLE" from the popup menu and press the SET key.

1	SELECT OBFECT TYPE COND	F C1 DRK
-	OBJECT TYPE COND	
t	E- TYPE00	
_	OPS-MENU SAVE COPY PASTE DEL SPECIFY NUMBER TITLE	
	STR OBJ TITLE SCREEN SAVE	F C1 DRK

STORE OBJCT TITLE	Setting details
A to Z	-
0 to 9	These characters and symbols are used to enter the title name.
= to >	
SP (space bar)	This is used to make spaces.
$\leftarrow \rightarrow$	These are used to move the cursor
DEL. (delete)	This is used to delete the character to the right of the cursor.
END	Exit the title registration screen.

The title that has been entered will be displayed in the top left corner of the operation screen and "SELECT OBJECT TYPE COND" screen.



Operation screen

(TYPE00) AREA



MEAS XXXXms MEASURE 0 CAM1 POSI-DEVIATION

SELECT OBJECT TYPE COND screen

SELECT OBJECT TYPE COND	F C1 BRT	
SELECT OBJECT TYPE COND OBJECT TYPE COND TYPE OU(AREA) TYPE RUN COND MAGE-ADJ MAG	F C1 BRT	
EVALUATION COND		

F C1 DRK V*.**

3-3 Input & Output / System settings

[1] Illuminance (light level) monitor

(1) Purpose

1. Allows the system to monitor changes the lighting of the environment

If the light level exceeds the preset lighting range, it will be regarded as a change in the environment and "OVR ILLM RANGE" will be displayed on the MAIN OPS MENU.

2. Automatic adjustment of the threshold values used for binary conversions can follow changes in the lighting environment.

The threshold value is modified from the user's setting due to changes in the actual brightness measured in the environment.

(2) Applications

Used when the level of illumination changed due to changes in voltage or when the influence of sunlight in the workplace cannot be ignored.

(3) Setting procedure

Select "OBJECT TYPE COND" → "TYPE00" (current type) and "OBJ-TYPE SYS," in that order, on the "MAIN MENU" screen.

5 LIGHT LV COND

- 1. Select "2)MNTR LIGHT LVL (CAM1)" (monitor OBJ-TYPE SYS. SCREEN SAVE light level). Select "YES" from the popup menu. 1 HALT ON NG MEAS YES Then, the "3LIGHT LV COND" item will 2 MNTR LIGHT LVL(CAM1) YES appear on the screen. 3 LIGHT LV COND (TO NEXT SUB-BENU) (4) MNTR LIGHT LVL(CAM2) YES
 - 2. Select "③LIGHT LV COND" and press the SET key. The "LIGHT LV COND" screen and monitoring window will appear.
 - 3. Press the SEL key and move the cursor to the upper function menu. Set the image mode to "T" (Through).

LIGHT LV COND SCREEN SAVE		F C1 BRT
1 SIZE	Y08(4~32)X08(4~65)	
2 POSITION	(248,232)	
③THRESHOLD VALUE	U.LM255 L.LM000(0~255)	
	MEAS.AVG.GRA=000.0	
(4) REG AVG.GRAY LV	EXEC REG.AVG.GRAY=000.0	
Monitor window		

NO

YES

(TO NEXT SUB-MENU)

(6) MOVE ALL WINDOW (TO NEXT SUB-MENU)

F C1 BRT

- 4. Select item "①SIZE", and item "②POSITION", using the up and down keys, and press the SET key. Then, set the size and position of the monitoring window using the direction keys.
 - The monitoring window should be placed in a location with medium brightness, which does not contain any objects to be measured.
 - The monitor window is a rectangle 4 to 32 pixels tall and 4 to 64 pixels wide (se in multiples of 4 pixels). The monitor window can be moved one pixel at a time.
 - The average light level in the monitoring window is displayed on "MEAS.AVG.GRAYS (average measured light level) in item (3)."

[When monitoring changes in the lighting environment] ... If not, go to item 6.

5. Select item "③THRESHOLD VALUE", using the up and down keys, and press the SET key.

- Select the upper and lower limits using the left and right keys, and set the light level range (0 to 255) using the up and down keys. Then, press the SET key.
- ⇒ When the average light level in the monitoring window is out of the preset light level range, "OVR ILLM. RANGE (light level over range)" will be displayed on the MAIN OPS MENU.

[When the threshold value for binary conversion is automatically modified to take into account changes in the lighting environment] If not, go to item 8.

- 6. Press the SEL key to enter freeze frame the image.
 - "F.IMG (freeze)" will be displayed in the upper right corner of the screen.
 - Before reading and storing the next average light level sample, it is necessary to enter the freeze frame.
- 7. Select item "④REG AVG. GRAY LVL (average light level registration)," using the up and down keys, and press the SET key twice. When the SET key is pressed again, the "REG. AVG. GRAYS (average light level)" will be registered.
 - This average light level is required when threshold value correction is selected in the binary conversion method.
 - If the average light level has not been registered, you will see "error 22: BIN MON. LIGHT LVL NOT SET (the light level check function has not been enabled)."
 - The registered light level is the reference value used when threshold values are modified.
 - If the current screen is not a frozen image, "CHANGE TO FREEZE MODE (change to freeze)" will be displayed.
- 8. Move the cursor to the upper function menu by pressing the TRG/BRT key and select the "SAVE" item using the left and right arrow keys. Then press the SET key.
 - A message "SAVE DATA? (YES = [SET], NO = [ESC])" will appear on the screen. Press the SET key to save the data.

After the measurement monitoring function is turned ON and images have been captured, the lighting monitoring function set above will be active.

[2] Setting the shutter speed

The shutter speed can be set independently for each object type.

Since the shutter speed can be set continuously in the range of 1/30 to 1/10,000 of a second, very fine adjustment is possible.

- If you want to measure moving objects and increase the image processing speed, set the shutter speed to around 1/1000 or 1/2000 seconds. However, if you use a faster shutter speed than you need, very bright lights will be necessary, and bright lighting is not economical.
- For details about the relationship between the brightness of objects (objects to be measured) and the shutter speed, see IV-S30J User's Manual (Introduction and Hardware) "5-1 [2] Illumination and shutter speed."

[Example]

- When the shutter speed is slow (1/60 of a second)



- When the shutter speed is fast (1/1000 of a second)



The object is blurred across the screen.

The object is frozen on the screen.

Setting procedure

On the MAIN MENU screen, select "OBJECT TYPE COND," "TYPE00" (current type) and "OBJ-TYPE I/O," in that order.

You can specify any value in the range of 1/30 to 1/ 0 10000 seconds (initial value 1/60) for the shutter speed.

- 1. Move the cursor to the "③SHUTTER SPEED" item on the OBJECT TYPE I/O using the up and down keys, and press the SET key.
- 2. Press the SET key again, and move the cursor to the digit you want, using the left and right keys.

1/00060

This cursor will move to the left and right.


- 3. Set the value using the up and down keys.
- 4. Repeat steps 2 and 3 to set each digit. After setting all of the digits, press the SET key.

OBJ-TYPE I/O SCREEN SAVE		F C1 DRK
①TRIG CCD START ②CCD TRIG COND ③SHUTTER SPEED ④SERIAL OUTPUT	BIN (TO NEXT SUB MENU) 1/00060(1/30~1/10000) ANY	
5 CAMNO 6 CALIBRATION	NO 1(1~2) NO	

[3] Copying

When there are many common parameters between object types, it is most efficient to access those existing sets of parameters in order to copy and then modify them.

The parameters of a previously specified object type are copied into another object type, after which they can be modified.



Operation procedure

On the "MAIN MENU" screen, select "OBJECT TYPE COND" and then "TYPE00" (current type). At this point, press the TRG/BRT key to display the popup menu. Select "COPY" from the popup menu and press the SET key.

SELECT OBJECT TYPE COND	F C1 DRK
OBJECT TYPE COND OPS-MENU SAVE COPY PASTE DEL SPECIFY NUMBER TITLE SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=PO	DID
JULI TO NEAT SUD-WEINU ESUEDAUN SELECTING IMG TRGEPU	FUF

Notes

- Do not disconnect the power while the IV-S30J is copying.
- Once data has been corrupted it will be necessary to start after initializing the setting, all over again. Unless this is done it will not be possible to restart the machine.
- The reference images used for the gray scale search function are not copied with the operation above. Make sure reset them.

[4] Halt on NG measurement


You can stop all measurements when an NG image (according to the final evaluation results) occurs while operating the IV-S30J. Select "①HALT ON NG MEAS" on the "OBJECT TYPE SYS." menu.

OBJ-TYPE SYS. SCREEN SAVE	F C1 BRT
HALT ON NG MEAS YES WANTR LIGHT LVL(CAM1) YES (3) LIGHT LV COND (TO NEXT SUB-BENU) (4) MNTR LIGHT LVL(CAM2) YES (5) LIGHT LV COND (TO NEXT SUB-MENU) (6) MOVE ALL WINDOW (TO NEXT SUB-MENU)	

(1) HALT ON NG MEAS	Description
NO	Even if an NG image (final evaluation result) is detected while operating the IV-S30J, the system will continue making measurements.
YES	When an NG image is detected (according to the final evaluation result) while operating the IV-S30J, the controller will stop making measurements.
NO (NG MEAS DISP)	Even if an NG image (final evaluation result) is detected while operating the IV-S30J, the system will continue making measurements. But, it displays the occurred NG measurements at first.

Shown below is an example of an NG image that occurred during measurement 1.

(Setting whether to stop measurements when an NG occurs)



[5] Window group move

All the window positions set in the measurement programs for the same object type number can be shifted horizontally by a specified amount as a group. [Example of use] Shift the coordinate positions used as data for another object type.

(After copying the data between object types, move the windows as a group.)

To set the amount, use "6 MOVE ALL WINDOW" in the" OBJECT TYPE SYS" menu.

1. While "(1)SELECT CAMERA" is selected, press the up and down arrow keys to select either "CAM1" or "CAM2." Then press the SET key.


OBJ-TYPE SYS. SCREEN SAV	Έ	F
0	YES	
2 MNTR LIGHT LVL(CAM1)		
-	TO NEXT SUB-BENU)	
(4) MNTR LIGHT LVL(CAM2)		
-	(TO NEXT SUB-MENU)	
6 MOVE ALL WINDOW	(TO NEXT SUB-MENU)	

MOVE ALL WIN SCREEN SAVE F C1 BRT **1**SELECT CAMERA CAM1 MOVE(256,240) COORDINATES STORED STR COORD POSI 3 MOVE ALL WINDOW MOVE (256,240) EXEC


- 2. Select "2STR COORD POSI" (store coordinate position) and press the SET key. Then select "MOVE" by using the left and right arrow keys and finally, press the SET key.
- 3. Move the cursor (solid line) to the original coordinates before the move using the up, down, left, and right keys, and press the SET key.
- 4. Select "COORDINATES STORED" using the left and right keys, and press the SET key. After that press the ESC key.

 \Rightarrow The coordinates before the move are now registered.

- 5. Select "③MOVE ALL WINDOW" using the up and down keys and press the SET key. Select "MOVE" using the left and right keys and press the SET key.
- 6. Move the cursor (dotted line) to the new coordinates you are moving to use the up, down, left, and right keys and press the SET key.



- 7. Select "EXEC" (execute) using the left and right keys and press the SET key.
 - \Rightarrow All the windows registered to the same object type will be shifted horizontally at the same time by the distance between the original coordinates to the new coordinates. After the move is complete, a "Window group move is complete" message will be displayed.




 When some part of the window to be moved will move outside of the image display area, the "Out of range" message will be displayed together with the measurement number and register number. In this case, select "Continue" or "Halt.'

If "Continue" is selected, the window will be shifted to the limit within the image display area.

C1 BRT

Chapter 4: Positional Deviation Measurement

4-1 Outline




4-2 Setting operation

Setting the measurement conditions

Select "MAIN COND" -> "OBJECT TYPE COND" -> "TYPE00" -> "MEA CND (CAMERA1) " -> "MEAS0," in that order.

On the "1 MEAS SELECTION" line, select "POSI-DEVIATION" from the popup menu. Press the ESC key to return to the OBJECT TYPE COND (menu tree) screen, and select the "MEAS CND" item to enter the MEAS CND screen.

⇒ For details, see "Chapter 8: Setting examples using the menu tree" in Introduction and Hardware.



Note: "POSI-DEVIATION" (positional deviation) measurement can be specified in the "MEAS0" (measurement 0) and "MEAS1" (measurement 1) to "MEAS4" (measurement 4) functions. If you choose "MEAS(NEW)," the smallest available measurement number will be chosen automatically ("MEAS1" to "MEAS4").

(1) DTECT PRECISON

Select detection precision. You can select one of two levels (standard/high), according to your conditions, the desired precision level for detection results, and the detection speed.


 \Rightarrow For details, see page 3-9.

(2) REGISTER NO.

Enter a register number. When making positional deviation measurements, you can select any register from 0 to 7 (a total of 8 registers).

(3) MODE

Select a mode for detection. The details of each mode are as follows.



SET=SELECT A MENU FOR	ESC=BACK SEL=CHNG IMG TRG=FUNC

Detection Mode	Details	Usable models
NO (None)	Does not detect.	
1P-SCH	Detect the positional deviation of one point in the scanned image	Model 0 only
(1-point search)	compared to a single reference image, after performing a gray search.	
2P-SCH	Detect the positional deviation of two points in the scanned image	Model 0 and 1
(2-point search)	compared to two reference images, after performing a gray search.	
1P-EDGE (1-point edge)	Detect the positional deviation of one point in the scanned image compared to a single reference image, after performing edge detection.	Model 0 only
2P-EDGE (2-point edge)	Detect the positional deviation of two points in the scanned image compared to two reference images, after performing edge detection.	Model 0 and 1
1P-SCH + 1P-EDGE (1-point search and 1-point edge)	Detect the positional deviation of two points, one point after performing a gray search and one point after performing edge detection.	Model 0 and 1

Gray search \Rightarrow See page 3-9.

Edge detection \Rightarrow See page 3-14.

(4) DTECT ANGL and (5) ANGLE UNIT

When the "1P-SCH" or "1P-SCH + 1P-EDGE" is selected in "③MODE," you can specify angle detection.

 \Rightarrow For details about angle detection, see page 4-12.


Select a detection range on the "4DTECT ANGL" line and select the units at "5ANGLE UNIT."

REGISTER NO. (6MDL 0, 7MDL 1)

The specified modes are displayed for each register number on these lines. When a 1-point search or 1-point edge is specified, only "6 MDL 0" will be available. When a 2-point search, 2-point edge, or 1-point search and 1-point edge is specified, "7 MDL 1" is also available.

The "S" in the table indicates a gray search, and the "E" indicates edge detection. "X" means not used.

An example of mode settings



How to set the register conditions


- How to enter the REG-COND setting screen There are three methods for getting to the REG-COND setting screen.
- On the MEAS CND setting screen, move the cursor to "[©] MDL 0" or "[¬] MDL 1" and press the SET key. The cursor will move into the table. Move the cursor to the "S" or "E" column and press the SET key.

Note: If you press the SET key in the "X" column, the setting will be invalid.

About "S" \Rightarrow See pages 4-4 to 6. About "E" \Rightarrow See pages 4-7 to 8.


2) On the MEAS CND setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG-COND(S)" or "REG-COND(E)" item and press the SET key.

About "REG-COND(S)" ⇒ See pages 4-4 to 6. About "REG-COND(E) ' ⇒ See pages 4-7 to 8.



3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG-COND(S)" and "REG-COND(E)" items will appear. Move the cursor to either of these items and press the SET key.

About "REG-COND(S)" ⇒ See pages 4-4 to 6. About "REG-COND(E)" ⇒ See pages 4-7 to 8.



[1] Set the register conditions for a gray search


(2) MEAS SHAPE


Select a window shape to be used for the positional deviation measurement. Select "RECTANGLE," "X-LINE," or "Y-LINE" from the popup menu on the "②MEAS SHAPE" line.

RECTANGLE	Specify coordinates for the upper left and lower right corners. The window will be a rectangular area defined by these coordinates.
X-LINE	Length of a line from the start point to the end point on the X axis.
Y-LINE	Length of a line from the start point to the end point on the Y axis.

③ REFIMG ARE

Move the cursor to "③REFIMG ARE(MDL0)" and press the SET key. When the SET item is highlighted, press the SET key again to bring up the setting screen.






When a rectangle is selected

Specify the upper left and lower right corners of the reference image area. Move the cursor to the "①UP.L" and press the SET key. Lines for the X and Y axes will appear on the reference image area (shown as a solid line). Move the X and Y lines to the desired position using the up/down/ left/right arrow keys to set the coordinates for the upper left corner. When correct, press the SET key.

- To leave the coordinates at their previous position, press the ESC key.

Next, move the cursor to the"②LO.R" and press the SET key to determine the lower right corner of the rectangle. The range inside the rectangle of the solid line becomes the reference image.

Setting screen (RECTANGLE)




When a horizontal line is selected

Specify the start and end points on the X axis. Specify the start and end points using the up/ down/left/right arrow keys. The points will move along the X axis (while keeping the same Y coordinate).

Note: Specify a search area longer than the reference image area. Specifying a shorter search area may cause an error message to be displayed.






When a vertical line is selected


Specify the start and end points on the Y axis. Specify the start and end points using the up/ down/left/right arrow keys. The points will move along the Y axis (while keeping the same X coordinate).

Note: Specify a search area longer than the reference image area. Specifying a shorter search area may cause an error message to be displayed.



Register a reference image

After setting the reference image area, store an image in the controller as a reference image. Select "④REFERENCE IMG" using the up/ down arrow keys and select "REG" from the popup menu.




CONTRAST SRCH (contrast search)	After changing to a gray search, automatically search for the area with the most features (maximum contrast) in the captured image.
REG (register)	Store the currently displayed image as a reference image.
DISP (display)	Select any one of the registered reference images using the up/down/left/right arrow keys, the selected reference image will be displayed in the lower right of the screen.

(4) SEARCH ARE


Specify the search area (inside the dotted lines) on the "④SEARCH ARE (MDL0)" line, using the same procedures used for setting the reference image area.

If you are selecting a 2-point search, also set the points the same way as for MDL1.



An example of storing

- This is an example of a 2-point search when the detection shape is a rectangle.



Note: When setting the horizontal and vertical lines, specify the line length as follows: The reference image must shorter than the search area lines.

⑤ REFIMG

Move the cursor to the function menu on the REG COND screen by pressing the TRG/BRT key. Move the cursor to "DETAIL." Press the SET key on the "REFERENCE IMG" line in the popup menu. The white square on the left will change to a black square. Then, the "⑤REF IMG" item will appear on the screen. - You can use the same procedures to show "DTECT CRD" (detection coordinates) and "CONTR.PIXL" (contraction pixels) on the screen.

On the "5 REF IMG" line, select a reference image from the reference images already registered.

Ex: 015 (000 to 026)

Select reference image No. 15 from the 26 registered reference images (000 to 026).

6 DTECT CRD (detection coordinates)

Select whether to use the detection coordinates as the center of the reference area or to allow the point to be set freely.

(7) CONTR.PIXL (contraction pixels)

When "RECTANGLE" was selected at "2 MEAS SHAPE," you can select items 1 to 3 below. When "X-LINE" or "Y-LINE" was selected, you can select items 1 or 2 below.

- 1: Search the image in units of 2 pixels.
- 2: Search the image in units of 4 pixels.
- 3: Search the image in units of 8 pixels.

[2] Setting the register conditions for edge detection

2 MEAS SHAPE (MDL 1)

Select a measurement shape.


RECTANGLE LINE (straight line) CIRC-L (circle) ELIP-L (ellipse)


line)) Select a pattern to be used for image processing. ⇒ See pages 3-4 to 3-8.

NO ARTF/ARTIF: Select whether to detect edge or not with average density. ⇒ See page 3-15.

③ SEARCH AREA

Select "③SEARCH AREA (MDL1)" and press the SET key to go to the setting screen.





4-7

When a rectangle is selected

Highlight "①UP.L" and press the SET key. The X and Y axes will appear in the detection area. Move the X/Y axes using the up/down/left/right arrow keys to identify the upper left corner. When correct, press the SET key.


- To return to the previous coordinates, press the ESC key.

Next, highlight "②LO.R" and press the SET key. Identify the lower right corner the same way.

(4) DTECT MODE

Select an image processing method for the edges.

CHNG POINT — DRK -> BRT BRT -> DRK CENT (BRT) CENT (DRK) —



5 SEARCH DIR

Specify a search direction. The direction for searching varies with each detection shape.

• When "RECTANGLE" is selected

Horizontal (→)	Scan the reference line from left to right (\rightarrow)
Horizontal (-)	Scan the reference line from left to right (\leftarrow)
Vertical (↓)	Scan the reference line from top to bottom (\downarrow)
Vertical (†)	Scan the reference line from bottom to top (\uparrow)

• When "LINE" is selected

Start point → End point	Scan along a straight line from the starting point to the end point
End point → Start point	Scan along a straight line from the end point to the starting point


• When "CIRC-L" or "ELIP-L" is selected

Clockwise direction	Scan around the circumference clockwise
Counter-clockwise direction	Scan around the circumference counter-clockwise

 \Rightarrow For details, see page 3-14.

6 THRESHOLD

Specify a threshold value for binary conversion. \Rightarrow For details, see page 3-10.



Automatic setting

Select "AUTO-REG" from the upper function menu on the THRESHOLD setting screen. The controller will set the optimum value automatically. \Rightarrow For details, see page 3-15.

⑦ REF COORD (reference coordinates)

You can change the reference coordinates to any desired position.


Set the evaluation conditions

• How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the MEAS COND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the EVALUAT COND screen.

 Move the cursor to the "EVALUATION COND" item on the Menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-17.

EVALUAT COND SCREEN CO	ND SAVE EDIT	SEL	F C1 BRT
1 REGISTER NO. 2 CONDITION SET	0(0~7) AUTO(–10%)	[TEST RESULT]	[OUTPUT]
(3)X COORD.(MDL0)	000.0~511.0	X0=	NO
(4)Y COORD.(MDL0)	000.0~479.0	Y0=	NO
5x DEVAITE(MDL0)	-511.0~+511.0	x0=	NO
6y DEVAITE(MDL0)	-479.0~+479.0	y0=	NO
⑦MATCH LVL(MDL0)	-10000~+10000	M0=	NO
®TEST	EXEC(WITH-PO	SI.ADJ WITHOUT-P	OSI.ADJ)
SET=VALUE INPUT ESC=BACK	SEL=CHNG IMC	G TRG=FUNC	

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- See "Chapter 14: Numerical calculations."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions.

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.



 \Rightarrow For display examples of measurement results using other modes, see the next page.

The displays for other modes are shown in the next page.

	-point search
Registration number	► REGST NO. 0(0~7)
Detection coordinates in the	► X0=176.0 OK
reference image for model 0	LY0=322.0 OK
Amount of deviation from	x0=+000.0 OK
the reference image for model 0	_y0=+000.0 OK
Degree of match with the reference image for model 0	► M0=+10000 OK
* Rotation angle	► B0=+002.6 OK

1-point search



* Angle will be displayed when "DTECT ANGL" is set to "YES."

-	2-point search	
Registration number	► REGST NO. 0(0~7)	
Detection coordinates in the	► X0=176.0 OK	
reference image for model 0	LY0=322.0 OK	
Amount of deviation from	×0=+000.0 OK	
the reference image for model 0	_y0=+000.0 OK	
Degree of match with the reference image for model 0	► M0=+10000 OK	
Amount of angular deviation ——	► B0=+001.7 OK	
Coordinates in the detect	X1=534.0 OK	
point for model 1	_Y1=480.0 OK	
Amount of deviation in the	► x1=+001.0 OK	
detect point for model 1	_y1=+001.0 OK	
The number of the detect point for model 1	► K1=1 OK	


Model 1

	1-point edge	
Registration number)(0~7)
$\[$ Coordinates in the detect $\]$	X0=176.0	OK
point for model 1	Y0=322.0	OK
Amount of deviation in the	x0=+000.0	OK
detect point for model 1	_y0=+000.0	OK
The number of the detect —	→ K0=1	OK
point for model 1	B0=	
	L	

2-point edge

	_	
Registration number ————	REGST NO.	0(0~7)
Coordinates in the detect	X0=176.0	OK
point for model 0	LY0=322.0	OK
Amount of deviation in the	×0=+000.0	OK
detect point for model 0	_y0=+000.0	OK
The number of the detect point for model 0	► K0=1	OK
Amount of angular deviation ——	► B0=+001.7	OK
Coordinates in the detect	×TX1=534.0	OK
point for model 1	LY1=480.0	OK
Amount of deviation in the	<mark>,</mark> x1=+001.0	OK
detect point for model 1	_y1=+001.0	OK
The number of the detect point for model 1	► K1=1	OK





Angle detection

You can detect the angle of an object by selecting 1P-SCH (1-point search) in the POSI-DEVIATION item (measurement 0 to 4) .

(1) Angle detection by object shape


There are some objects whose angle cannot be detected, due to the shape of the object and the compression level used for the gray scale search, as shown in the table below.

Object shape	Angle detection	Difficulty level
	The angle cannot be detected.	×
	The angle can be detected using a compression level of 2 for the gray scale search.	
	The angle can be detected.	\bigcirc

- The information given above is true when the measurement conditions are as follows: the size of the reference image to be registered is approximately 64 X 64, and the search size is approximately 100 X 100.

(2) Setting method

On the [MEAS CND] screen, select the "1P-SCH" or "1P-SCH+1P-EDGE" mode on the "3MODE" and then select the "4DTECT ANGL" item. \Rightarrow See page 4-2.




- 1. Select the "1P-SCH" or "1P-SCH+1P-EDGE" mode on the "③MODE".
- 2. Select the angle search range (±15°, ±30°, ±45°, ±360°) on the "④DTECT ANGL" item. The larger the angle search range, the slower the processing will be.
- 3. Select a rotation step size in degrees in "(5)ANGLE UNIT," using the up and down keys. The relationship between the detection range (unit) of the rotation angle and the reference images to be created is shown below:

Rotation a	angle	ngle Reference image created	
Detection range	Unit	Rotation angle	Quantity
	1	-17, -16, -15, -14, • • • • • • • • +14, +15, +16, +17	35
±15°	3	-21, -18, -15, -12, • • • • • • • • +12, +15, +18, +21	15
±13	5	-25, -20, -15, -10, -5, 0, +5, +10, +15, +20, +25	11
	10	-15, -10, 0, +10, +15	5

Rotation a	angle	ngle Reference image created	
Detectio- n range	Unit	Rotation angle	Quantity
	2	-34, -32, -30, -28, • • • • • • • • +28, +30, +32, +34	35
	3	-36, -33, -30, -27, • • • • • • • • +27, +30, +33, +34	25
±30°	5	-40, -35, -30, -25, • • • • • • • • +25, +30, +35, +40	17
	6	-42, -36, -30, -24, • • • • • • • • +24, +30, +36, +42	15
	10	-30, -20, -10, 0, +10, +20, +30	7
	3	-51, -48, -45, -42, • • • • • • • • +42, +45, +48, +51	35
±45°	5	-55, -50, -45, -40, • • • • • • • • +40, +45, +50, +55	23
	10	-45, -40, -30, -20, -10, 0, +10, +20, +30, +40, +45	11
Full angle	10	-170, -160, -150, • • • • • • +150, +160, +170, +180	36

4. On the settings for the gray scale search conditions (page 4-4), register the object by surrounding it with a square window, regardless of the shape of the object to be measured.





When triggered to store the reference image, the system will store various views of the object in memory by rotating the image, 10 degrees at a time.

• When the angle range is set to -360° (Rotation angle unit : 10)


Reference image








5. Specify a search area that is large enough to include various positional deviations of the object.



6. When starting the measurement, the system will execute a gray scale search of the captured image based on the stored reference images, which were created by rotating the basic image, 10 degrees at a time in step 3 above.



Note: When "NO" is selected for the "DTECT ANGL" (rotation angle detection) in the previous page after registering the reference image, a "Reference image condition mismatch" error will occur when executing the measurement.

Chapter 5: Degree of Match Inspection

5-1 Outline


Purpose	The gray search function is capable of finding the differences between the non- defective reference image and the image to be inspected evaluating the degree of match. (The acceptability of the workpiece is evaluated based on its level of similarity to the reference model.)		
Applications	Checking for misalignment of labels, checking for entry of wrong parts, checking that electronic components have been precisely mounted on PC boards, checking for misprints, checking for missing metallic parts, such as terminals, and simple inspection of lettering		
Examples	[Checking for label misalignment on package] Reference Search area for positioning Image for positioning Image fo		

5-2 Setting operation

Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" -> "MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "CHK-DEG-MATCH" from the popup menu.

MEASUREMENT1 SCREEN COND SAVE	F C1 BRT
①MEAS SELECTION CHK-DEG-MATCH	NO POSI-DEVIATION CHK-DEG-MATCH INSPECT-LEAD MEAS-BIN-AREA CNT-BIN-OBJ LABEL-BIN-OBJ POINT-MEAS MULTI-POSI MULTI MATCHES
SET=SELECT A MENU ESC=BACK SEL=CHNG IMG T	RG=FUNC

Press the ESC key to return to the OBJECT TYPE COND (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (CHK-DEG-MATCH)" to go to the MEAS CND screen.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.


• Setting the measurement conditions

1 DTECT PRECISON

Select detection precision. You can select one of two levels (standard/high), according to your conditions, the desired precision level for detection results, and the detection speed. \Rightarrow For details, see page 3-10.

2 REGISTER NO.

16 registers are available for the degree of match inspection (Registers 0 to 15). If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.



3 MODE

Select a detection mode. Detail of each mode are as follows.

MODE	Details
NO (None)	Does not detect.
1P-SCH	Detect the positional deviation of one point in the scanned image
(1-point search)	compared to a single reference image, after performing a gray search.
2P-SCH	Detect the positional deviation of two points in the scanned image
(2-point search)	compared to two reference images, after performing a gray search.

Gray search \Rightarrow See page 3-9.

(4) SEARCH

Specify whether or not to use the search function.

(5) MATCHING

Select a density for comparison when inspecting the image. The details are as follows.

	Description
Average light level	Obtain average light level of the image in the area detected using the gray search.
Difference absolute value	Calculate the difference of the absolute values from the image detected using the gray search and the reference image. The result is light level difference. By obtaining this value, you can get an idea of the total change in light level. Total light level difference = $S (Ni - Nt)$ Ni : Light level of the captured image (contraction 3) Nt : Light level of the reference image (contraction 3)

REGISTER NO. (6MDL 0, 7MDL 1)

The specified modes are displayed for each register number on these lines. When a 1-point search is specified, only "⁶MDL 0" will be available. When a 2-point search is specified, "⁷MDL 1" is also available. The "S" in the table indicates a gray search. "X" means not used.

• An example of mode selection

REGISTER NO.	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	S: Gray search
6 MDL0	S	S	\times	Х	Х	\times	\times	Х	Х	Х	Х	\times	X	Х	X	X	imes : No setting
⑦MDL1	\times	S	\times	Х	Х	X	\times	Х	Х	\times	Х	Х	X	Х	$ \times$		
REGISTER00 : 1P-SCH REGISTER01 : 2P-SCH																	

How to set the register conditions

How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

- On the "MEAS CND" setting screen, move the cursor to "⁶ MDL 0" or "⁷ MDL 1" and press the SET key. The cursor will move into the table. Move the cursor to the "S" column and press the SET key.
 - Note: If you press the SET key in the "X" column, the setting will be invalid.

MEAS CND S	SCRI	EEN	١	CO	ND	S	AVI	Ε							F	= C	I BRT
①DTECT PRECISION ②REGISTER NO. ③MODE ④SEARCH ⑤MATCHING	ST 00(2P YE AV	0~^ -SC S	15) H			/				RE EV/ DS	G-C ALU T&/ M-C	RE- JAT ANC CAL	ID ION GL				
REGISTER NO.	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	
MDL 1	S	×	×	\times	×	×	X	\times	×	×	×	\times	\times	\times	\times	\times	
	S	×	×	\times	×	×	×	\times	×	×	×	×	×	×	×	\times	

- On the "MEAS CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG-COND" item and press the SET key.
- 3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG-COND" items will appear. Move the cursor to this item and press the SET key.

SELECT OBJECT TYPE COND	F C1 DRK
OBJECT TYPE COND	(GCONTR.FIAL (MDLI)
SETETO NEXT SUD-WILMU LOCEDACK SELECTING IMIG TR	G=r OF OF

• How to set register conditions

(1) REGISTER NO.

The currently selected register number is displayed.

If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.

2 MEAS SHAPE(MLD0)

Select a shape (rectangle, horizontal line, or vertical line) for the reference image area and search area.

⇒ For details about each shape, see pages 3-4 to 3-8.


REG COND SCRE	EN COND SAVE DETAIL	F C1 BRT				
1 REGISTER NO. 2 MEAS SHAPE (MDL0) 3 REFIMG ARE (MDL0) 4 SEARCH ARE (MDL0) 5 REFIMG (MDL0) 6 DTECT CRD (MDL0) 7 CONTR.PIXL (MDL0) 8 MEAS SHAPE (MDL1) 9 REFIMG ARE (MDL1) 10 REFIMG (MDL1) 11 REFIMG (MDL1) 13 CONTR.PIXL (MDL1)	SET (224.208)~(287.271) SET (216.200)~(295.279) 001 (000~001) CENTER (250.229) 1 RECTANGLE SET (224.208)~(287.271) SET (216.200)~(295.279) 001 (000~001)	RECTANGLE X-LINE Y-LINE REFERENCE IMG * DTECT COORD CONTR.PIXEL				
* Make □ to ■ on the popup menu, the respective item will be added to the "REG COND" menu.						
SEL=SELECT A MENU ES	C=BACK SEL=CHNG IMG TR	RG=FUNC				

③ REFIMG ARE (MDL0)

Move the cursor to "③REFIMG ARE(MDL0)" and press the SET key. When the SET item is highlighted, press the SET key again to bring up the setting screen.

• When a rectangle is selected

Specify the upper left and lower right corners of the reference image area.



• When a horizontal line is selected


Specify the start and end points on the X axis. Specify the start and end points using the up/down/left/right arrow keys. The points will move along the X axis (while keeping the same Y coordinate).

Setting screen (X-LINE)

 Setting screen (X-LINE) 		
X-LINE RESET RETURN MDL 0	F	C1 BRT
(1)S.PT (199.245)		
(2)E.PT (328.245)		
(3)MOVE		
A REFERENCE IMG		
Crosshair cursor (detection coordinate) Solid line (reference line) Dotted line (search line)	SHARP SERIAL NO POPEL VOTEL V-S30J	
	X:194 Y:24	5
SET=MOVE ESC=BACK SEL=CHNG	IMG TRG=FUNC	

When a vertical line is selected


Specify the start and end points on the Y axis. Specify the start and end points using the up/down/left/right arrow keys. The points will move along the Y axis (while keeping the same X coordinate).



Register a reference image

After setting the reference image area, store an image in the controller as a reference image.


Select "④REFERENCE IMG" using the up/ down arrow keys and select "REG" from the popup menu.



④ SEARCH ARE

Specify the search area (inside the dotted lines) on the "④SEARCH ARE (MDL0)" line, using the same procedures used for setting the reference image area.

Note: Set the menu for MDL1. Setting procedures are the same as MDL0.



5

(5) REFIMG

On the "⑤REF IMG (MDL0)" line, select a reference image from the reference images already registered.

- Ex. 015 (000 to 026) Select reference image No. 15 from the 26 registered reference images (000 to 026).
- Note: This item is displayed only when the "REFERENCE IMG" is selected on the "DETAIL" in the upper function menu. ⇒ See page 5-4.

REG COND SCRE	EN COND SAVE DETAIL	F C1 BRT
1) REGISTER NO. (2) MEAS SHAPE (MDL0) (3) REFIMG ARE (MDL0) (4) SEARCH ARE (MDL0) (5) REFIMG (MDL0) (6) DTECT CRD (MDL0) (7) CONTR.PIXL (MDL0) (9) REFIMG ARE (MDL1) (10) SEARCH ARE (MDL1) (11) REFIMG (MDL1) (12) DTECT CRD (MDL1) (13) CONTR.PIXL (MDL1) (13) CONTR.PIXL (MDL1)	00 (0~15) RECTANGLE SET (131.122)~(217.201) SET (119.114~(224.214) 15 (000-026) CENTER (176.164) RECTANGUERE SET (224.204)~(372.349) SET (274.209)~(381.368) 003 (000-026)	
SEL=SELECT A MENU ES	C=BACK SEL=CHNG IMG TRG=FUNC	

(6) DTECT CRD (detection coordinates)

Select whether to use the detection coordinates as the center of the reference area or to allow the point to be set freely. Note: This item is displayed only when the "DTECT COORD" is selected on the "DETAIL" in the upper function menu.

⇒ See page 5-4.

REG COND SCRE	EN COND SAVE DETAIL	F C1 BRT
1 REGISTER NO. 2 MEAS SHAPE (MDL0) 3 REFIMG ARE (MDL0) 4 SEARCH ARE (MDL0) 5 REFIMG (MDL0) 6 DTECT CRD (MDL0) 7 CONTR.PIXL (MDL0) 8 MEAS SHAPE(MDL1) 9 REFIMG ARE (MDL1) 10 SEARCH ARE (MDL1) 11 REFIMG (MDL1) 12 DTECT CRD (MDL1) 13 CONTR.PIXL (MDL1)	SET (119.114~(224.214) 003 (000-026) CENTER (176.164) LETANGLEPER SET (224.299)~(372.349) SET (224.299)~(372.349) SET (276,259)~(381.368) 003 (000-026) CENTER (384.913)	CENTER SET
SEL=SELECT A MENU ESC	C=BACK SEL=CHNG IMG TRG=	FUNC

(7) CONTR.PIXL


Select "CONTR.PIXL" (pixel contraction). Note: This item is displayed only when the "CONTR.PIXEL" is selected on the "DETAIL" in the upper function menu. ⇒ See page 5-4.

⇒ For detail about the "CONTR.PIXEL," see page 3-9.

REG COND S	REEN COND SAVE DETAIL	F C1 BRT
1 REGISTER NO. 2 MEAS SHAPE (MD 3 REFING ARE (MDL 6 DTECT CRD (MDL) 7 CONTR.PIXL (MDL 8 MEAS SHAPE(MDL 9 REFING ARE (MDL 10 SEARCH ARE (MDL 11 REFING (MDL1) 12 DTECT CRD (MDL) 13 CONTR.PIXL (MDL	 SET (131.122)~(217.201) SET (119.114~(224.214) 003 (000-026) CENTER (176.164) RÉCTANSLERCE 1) RÉCTANSLERCE 1) SÉT (224.298)%(372.349) SÉT (274.298)~(381.358) 003 (000-026) SET (176.134.319) 	
SEL=SELECT A MENU	ESC=BACK SEL=CHNG IMG TRG=FUNC	

Set the evaluation conditions

- How to move to the evaluation condition setting screen There are two methods for getting to the evaluation condition setting screen.
 - 1) Select "COND" in the upper function menu on the "MEAS COND" (or "REG COND") screen and press the SET key. Select "EVALUATION" on the popup menu to go to the "EVALUAT COND" screen.



2) Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.

SELECT OBJECT TYPE COND	F C1 DRK					
OBJECT TYPE COND TYPE00 TYPE01 TYPE RUN COND MAGE-ADJ MEA-CND(CAMERA1) MEA-CND(CAMERA1) MEASON POSI-CORRECT MEASONCH-DEG-MATCH) FINAL NUM-CALC OUT-COND MEAS(NEW) THAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL NUM-CALC						
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP						

The "EVALUAT COND" (evaluation conditions) will appear.

⇒ For details about "EVALUAT COND," see page 3-17.

EVALUAT COND SCREEN CO	F C1 BRT		
1 REGISTER NO. 2 CONDITION SET	()	[TEST RESULT]	[OUTPUT]
3 MATCH LVL(MDL0)	-10000~+10000	M0=	NO
(4) X COORD. (MDL0)	000.0~511.0	X0=	NO
(5) Y COORD.(MDL0)	000.0~479.0	Y0=	NO
⑥GRAY LVL(MDL0)	000.0~255.0	G0=	NO
⑦MATCH LVL(MDL1)			NO
(B)X COORD.(MDL1)			NO
9 Y COORD.(MDL1)			NO
10 GRAY LVL(MDL1)			NO
(1) TEST	EXEC(WITH-PO	SI.ADJ WITHOUT-P	OSI.ADJ)
SET=VALUE INPUT ESC=BAC	K SEL=CHNG IMG	TRG=FUNC	

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- See "Chapter 14: Numeric calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 15: Set the Input/Output Conditions."

Display the inspection results

Return to the operation screen and press the TRG/BRT key. The inspection results will be displayed on the screen.



Chapter 6: Lead Inspection

6-1 Outline

Purpose	Inspect the condition of IC leads and connector pins based on positional information obtained from the gray scale search function. (No. of leads or pins that can be detected: Max. 128 pieces)		
Applications	Inspect IC leads or connector pins		
Examples	 Inspect the layout of the IC leads and connector pins Lead measurement limit line Lead Lead Lead K1 K2 K3 Signal Number of leads K D0 to D2: Distance between leads W0 to W3: Lead width L0 to L3: Lead length Unspection procedure 1 Determine the measurement points (K0 to K3) from the mid points of the leads and the reference line. Calculate the maximum and minimum lead lengths (L0 to L3), starting from the measurement points (K0 to K3) and measuring toward the lead measurement limit line. Calculate the maximum and minimum lead widths (W0 to W3) from the measurement points. 		

6-2 Setting operation

Setting the measurement conditions


• How to enter the measurement conditions setting screen

```
Select "MAIN-COND" -> "OBJECT TYPE
COND" -> "TYPE00" -> "MEA-CND (CAM-
ERA1) " -> "MEAS(NEW)," in that order. Then
press the SET key to bring up the "MEAS1"
screen.
```

Move to the "①MEAS SELECTION" line on

the "MEASUREMENT1" screen and select

"INSPECT-LEAD" from the popup menu.



Press the ESC key to return to the "OBJECT TYPE COND" (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (INSPECT-LEAD)" to go to the "MEAS CND" screen. ⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in Introduction and Hardware.

• Setting the measurement conditions

1 REGISTER NO.

16 registers are available for the lead inspection (Registers 0 to 15). If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.

② REGISTER EXIST Select whether to register or not.

③ DTECT PRECISON

Select detection precision. You can select one of two levels (standard/high),

MEAS CND	SCREEN COND	SAVE	F C1 BRT
1 REGISTER NO. 2 REGISTER EXIST 3 DTECT PRECISIO	YES	NO YES	STANDARD HIGH
REGISTER NO. (4) MEAS OBJECT LEAD LENGTH	00010203040 	50607080910 <××××× <××××	1112131415 ××××× ×××××
SET=VALUE INPUT ES	C=BACK SEL=CHNG	IMG TRG=FUNC	

according to your conditions, the desired precision level for detection results, and the detection speed. \Rightarrow For details, see page 3-9.

REGISTER NO. (4) MEAS OBJECT, LEAD LENGTH)

Register setting conditions are shown for each register number. Circles mean that "REGISTER NO." has set to "YES."

• Setting (display) of items to be inspected

REGISTER NO.		, When item "②REGISTER EXIST" has set "YES," a
(4) MEAS OBJECT		circle is displayed.
LEAD LENGTH	<u> </u>	On the "REG COND" screen, when the "⑦EXTENSION
	X : No setting	MEAS" is set to "LEAD-LENGTH," or "BALL-WIDTH," a
	X. No coung	circle is displayed.

How to set the register conditions


• How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

- On the MEAS CND setting screen, move the cursor to "④MEAS OBJECT" and press the SET key. The cursor will move into the table. Move the cursor to the "○" column and press the SET key. Note: If you press the SET key in the "X" column, the setting will be invalid.
- On the "MEAS CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG-COND" item and press the SET key.

MEAS CND	SCREEN	COND	SAVE	F C1 BRT
1 REGISTER NO. 2 REGISTER EXIS 3 DTECT PRECIS	ST YES			
REGISTER NO. (4) MEAS OBJECT LEAD LENGTH	$\begin{array}{c} 000102\\ \bigcirc \times \times\\ \times \times \times\end{array}$	03040 ××> ××>		$\begin{array}{c} 1112131415 \\ \times \times \times \times \times \\ \times \times \times \times \end{array}$
			IMG PRE- REG-CON EVALUAT	ION
			NUM-CAL OUT	C
SEL=VALUE INPUT E	SC=BACK SE	I =CHNG	IMG TRG=FUNC	

3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to either of these items and press the SET key.



Set the register conditions


1 REGISTER NO.

The currently selected register number is displayed.

If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.

(2) DTECT SHAPE

Select a detection shape. Three shapes are available: "RECT(ARTIFACT)," "LINE," and "CIRC-L." Depending on which item is selected, the choices on lines "③SEARCH AREA" and "⑤SEARCH DIRECT" will change.




RECT (ARTIFACT)	Specify the coordinates of the upper left and lower right corners. The controller will detect an edge inside this rectangle. For details about processing artifacts, see page 3-15.
LINE	Specify the coordinates of the starting and end points. The controller will detect an edge along this straight line.
CIRC-L	Specify the coordinates of the center and radius. The controller will detect an edge inside this circle.


③ SEARCH AREA

Specify a search area. Move the cursor to this line and press the SET key. The currently SET item will be highlighted. Press the SET key again to enter the setting screen.

• When the "RECT (ARTIFACT)" is selected Specify the upper left and lower right corners

of the rectangular search area.






(4) DTECT MODE

Select a detection mode.

CENT(DRK)	Detect the center of a dark area found by the detection search.
CENT(BRT)	Detect the center of a bright area found by the detection search.

Search direction



(5) SEARCH DIRECT (search direction)

Specify a search direction. The direction for searching varies with each detection shape.

• When "RECTANGLE" is selected

Horizontal (→)	Scan along the reference line from left to right (\rightarrow)
Horizontal (+-)	Scan along the reference line from left to right (-)
Vertical (↓)	Scan along the reference line from top to bottom (\downarrow)
Vertical (1)	Scan along the reference line from bottom to top (†)

• When "LINE" is selected


Start point → End point	Scan along a straight line from the starting point to the end point
End point → Start point	Scan along a straight line from the end point to the starting point

• When "CIRC-L" or "ELIP-L" is selected


Clockwise direction	Scan around the circumference clockwise
Counter-clockwise direction	Scan around the circumference counter-clockwise

Example of settings

- Example when (6)DTECT MODE (detection mode) is set to "CENT (BRT)" (center dark) and (5)SEARCH DIRECT (search direction) is set to "HORIZ (horizontal)."



- Example when ⑥DTECT MODE (detection mode) is set to "CENT (DRK)" (center dark) and ⑤SEARCH DIRECT (search direction) is set to "HORIZ (horizontal)."



(6) THRESHOLD

Specify a threshold value. Move the cursor to this line and press the SET key. The currently SET item will be highlighted. Press the SET key again to enter the setting screen.


Move to each of the following items and press the SET key: "①GRYS." (difference of gray level) "②EDGE.W" (edge width), and "③FLAT.W" (flat width). The current value for that item will be highlighted and it can be changed using the up and down keys. After the value is correct, press the ESC key to confirm it.

The values above can be reset to an appropriate level automatically. Move the cursor to the upper function menu by pressing the TRG/BRT key and select "AUTO-REG". Then press the SET key to set the levels automatically.

 \Rightarrow For details, see page 3-15.

⑦ EXTENSION MEAS, ⑧ EXT. MEAS DIRECT

Extension measurements can be made for "LEAD-LENGTH" or "BALL-WIDTH" in line "⑦ EXTENSION MEAS. Then, the "⑧EXT. MEAS DIRECT" item will appear. At the "⑧EXT. MEAS DIRECT" item, set the position for the extension measurement direction, relative to the reference line.




Note: This line is only displayed when "RECT" or "LINE" was selected for the "DTECT SHAPE." To display this line, move the cursor to the upper function menu and select "DETAIL." Press the SET key and select "EXTENSION MEAS" from the popup menu. Then press the SET key.

Set the evaluation conditions


• How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the "MEAS CND" (or "REG COND") screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the "EVALUAT COND" screen.



 Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-17.

EVALUAT COND SCREEN CO	OND SAVE EDIT	SEL	F C1 BRT
 REGISTER NO. CONDITION SET 	00(0~15) AUTO(±10%)	[TEST RESULT]	[OUTPUT]
3 NUMBER OF OBJ	000~128	K=	NO
	000.0~702.0	D=	NO
(5) LEAD WIDTH (6) LEAD LENGTH	000.0~702.0	W=	NO
(7)TEST		L= DSI.ADJ WITHOUT-F	
TEST	EXEO(WITH C		001.603)

SET=VALUE INPUT ESC=BACK SEL=CHNG IMG TRG=FUNC

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- See "Chapter 14: Numeric calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Set the Input/Output Conditions."

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen. **Example when a straight line is selected as**



MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE

Chapter 7: Area Measurement by Binary Conversion

7-1 Outline

Purpose	 This function is used to determine the existence and or size of a workpiece when the workpiece is always found in the same place or when it has a fixed measurement position. This function measures the area of the white field after the image has been converted to binary values (i.e. black and white). 	
Applications	Checking for correctly inserted ball bearings, preventing foreign objects from becoming mixed in with parts being processed, distinguishing between different types of waterproof lids, checking the existence of labels on packages, checking the printing on electric cables, checking for adequate coatings of grease and checking the existence of frozen foods.	
Examples	Workpiece [Measurement result] • The area of the workpiece	
	- Checking sequence Capture an image → Convert it to binary → Measure (area)	


1

7-2 Setting operation

Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" -> "MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "MEAS-BIN-AREA" from the popup menu.

MEASUREMENT1 SCREEN COND SAVE	F C1 BRT
①MEAS SELECTION MEAS-BIN-AREA	NO POSI-DEVIATION CHK-DEG-MATCH INSPECT-LEAD MEAS-BIN-AREA CNT-BIN-OBJ LABEL-BIN-OBJ POINT-MEAS MULTI-POSI MULTI MATCHES
SET=SELECT A MENU ESC=BACK SEL=CHNG IMG T	KG=FUNC

Press the ESC key to return to the OBJECT TYPE COND (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01(MEAS-BIN-AREA)" to go to the MEA-CND screen.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

Area Measurement by Binary Conversion

7

		Area we	asurement by E	Sinary Conve
WINDOW Select a window type. C move the cursor any of MASK1,2,4," "BINARY-I "POLYGON," and press select the item.	"NUM-OF- IMG-MASK," or	MEA-CND ①WINDOW ②REGISTER NO. ③REGISTER EXIST	SCREEN COND SAVE NUM-OF-MASK 1	F C1 BRT NUM-OF-MASK 1 NUM-OF-MASK 2 NUM-OF-MASK 4 BINARY-IMG-MASK POLYON
		REGISTER NO.	0001020304050607p80s	1011112131415 ×××××××
		SET=SELECT A MENU	J ESC=BACK SEL=CHNG IMG TR	G=FUNC
NUM-OF-MASK 1	Bring one mask area in	side the meas	suring area.	
NUM-OF-MASK 2	Bring two mask areas i	nside the mea	suring area.	

NUM-OF-MASK 1	Bring one mask area inside the measuring area.
NUM-OF-MASK 2	Bring two mask areas inside the measuring area.
NUM-OF-MASK 4	Bring four mask areas inside the measuring area.
BINARY-IMG-MASK	Select this item if the captured image is other than a rectangle, circle, or ellipse. This function masks the captured image using a stored binary image. ⇒ For details, see pages 3-25 to 29.
POLYGON	You can manually create any freeform polygon for the measurement area.

2 REGISTER NO.

(1)

Select register number to measure. Number of selectable registers varies with window shape selected.

NUM-OF-MASK 1	0 to 15
NUM-OF-MASK 2	0 to 7
NUM-OF-MASK 4	0 to 4
BIMARY-IMG-MASK	0 only
POLYGON	0 only

To save the measurement conditions using a different register number, press the SET key and highlight the number. Change this number by pressing the up and down arrow keys.

③ REGISTER EXIST

Select whether to register or not.

REGISTER NO. (④BIN AREA COND)

Register setting conditions are shown for each register number. Circles mean that "REGISTER EXIST" has set to "YES."

• Setting (display) of binary area conditions


 REGISTER NO.
 Image: Constraint of the image: Constraintof the image: Constraint of the image: Constr


How to set the register conditions

• How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

- On the "MEA-CND" setting screen, move the cursor to the "④BIN AREA COND" and press the SET key. The cursor will move into the table. Move the cursor to the "○" column and press the SET key. Note: If you press the SET key in the "X" column, the setting will be invalid.
- On the "MEA-CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG COND" item and press the SET key.
- 3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to this item and press the SET key.





• Set the register conditions

1 REGISTER NO.

The currently selected register number is displayed.

If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection. Note: When the "BINARY-IMG-MASK" or the

> "POLYGON" is selected at "①WINDOW" on the "MEA-CND" screen, the "①REGISTER NO." line will not be displayed and the other item numbers are decrement by one since the register number for "BINARY-IMG-MASK" and "POLYGON" is fixed.

REG COND S	CREEN COND SAVE DETAIL	F C1 BRT
1 REGISTER NO. 2 MEAS SHAPE 3 MEAS AREA 4 THRESHOLD 5 INVERT BW	RECTANGLE SET (224,208)~(287,271)	
SET=VALUE INPUT ES	C=BACK SEL=CHNG IMG TRG=FUNC	

2 MEAS SHAPE

Specify shape of measuring range.


RECTANGLE	Specify the coordinates for the upper left and lower right corners. The measurement area will be the area enclosed by this rectangle.
CIRCLE	Specify the center and the radius. The measurement area will be the area enclosed by this circle.
ELLIPSE	Specify the center and the radius. The measurement area will be the area enclosed by this ellipse.

③ MEAS AREA

Specify a search area.

• When "RECTANGLE" is selected

Specify the upper left and lower right corners of the rectangular search area.



(4) THRESHOLD

Specify a threshold value.

Nove the cursor to "①U.LM" and press the SET key. Then move the cursor to "②L.LM" and press the SET key again. The current value will be highlighted for each item. You can increase or decrease the value by pressing the up and down arrow keys. Press the ESC key to confirm the value you want.

The values above can be reset to an appropriate level automatically. Move the cursor to the upper function menu by pressing the TRG/BRT key and select "AUTO-REG". Then press the SET key to set the levels automatically. \Rightarrow For details, see page 3-15.

(5) INVERT B/W

Select whether to invert the display of black and white inside the measurement area.

Setting the mask details


On the "REG COND" screen, move the cursor to the upper function menu by pressing the TRG/BRT key. Select "DETAIL" by pressing the left and right arrow keys and then press the SET key. On the popup menu, you can select "MASK REGIST.," "BINARY PROCESS," and "BINRY NOISE FILT." The items selected here will be displayed on the "MEA-CND" menu.

6 MASK NO.

Select a mask number.

Note: This line is displayed when "NO. OF MASK 2" or "NO. OF MASK 4" is selected at "①WINDOW" on the "MEA-CND" screen.





7 MASK SHAPE

Select mask shape.

- Select "NO," "RECTANGLE," "CIRCLE," or "ELLIPSE."
- When "BINARY-IMG-MASK" is selected on the "①WINDOW" line, this line will not appear, since this is already selected on the "MASK BINARY IMG" screen.
- When "POLYGON" is selected on the "①WINDOW" line, specify the polygonal shape of the mask.

(8) BINARY PROCESS


Select a binary processing method. Move the cursor to "FIXED," "THRES-ADJ (VAR-DIFF)" {adjustable threshold value (variation difference)}, or "THRES-ADJ (VAR-RATE)" {adjustable threshold (variation rate)}, and press the SET key to continue.

9 BINARY NOISE FILTER

Select a binary noise filter type. Move the cursor to "NO," "EXPD. \rightarrow CONTR." (expansion \rightarrow contraction), or "CONTR. \rightarrow EXPD" (contraction \rightarrow expansion), and press the SET key to continue.

 \Rightarrow For details, see page 3-13.

Setting example of measurement area and mask area



- The inside of the measurement area (excluding the mask area) is converted to binary data.

Mask area

Set the evaluation conditions

How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the MEAS COND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the EVALUAT COND screen.

MEA-CND SCI	REEN COND	SAVE	F C1 BRT
(1) WINDOW (2) REGISTER NO. (3) REGISTER EXIST (4) MASK BINARY IMG (5) BIN IMG MASK	YES REF-IMG		IMG PRE-PROC REG COND EVALUATION NUM-CALC OUT
REGISTER NO. ⑥BIN AREA COND		4050607080	9101112131415
SET=SELECT A MENU ES	SC=BACK SEL=	CHNG IMG TRG	=FUNC

7

2) Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND TYPE00 TYPE01 TYPE01 TYPE01 MAGE-ADJ MEA-CND(CAMERA1) MEAS0 POSI-DEVIATION MEAS01(MEAS-BIN-AREA) MEASCND KEASCND WEASCND WIM-CALC OUT-COND MEAS(NEW) TFINAL NUM. CALC FINAL OUTPUT COND OBJ-TYPE I/O OBJ-TYPE SYS.	1 CHNG REG 2 CONDITION SET 3 REGISTER 00 4 REGISTER 01 5 REGISTER 02 6 REGISTER 03 7 REGISTER 04 8 REGISTER 05 9 REGISTER 06 10 REGISTER 07 11 TEST
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG	RG=POPUP

The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-17.

① CHNG REG [TEST RESULT] [OUTPUT] ② CONDITION SET AUTO(±10%) NO ③ REGISTER 00 000000-245760 A00= NO ④ REGISTER 01 000000-245760 S S ⑤ REGISTER 02 00000-245760 S S ⑥ REGISTER 03 000000-245760 S S ⑧ REGISTER 04 000000-245760 S S ⑨ REGISTER 05 000000-245760 S S ⑨ REGISTER 06 000000-245760 S S ⑨ REGISTER 07 000000-245760 S S ⑨ REGISTER 06 000000-245760 S S ⑨ REGISTER 07 000000-245760 S S ⑨ REGISTER 07 D00000-245760 S S

• Set the evaluation conditions

The display details vary with the setting of each window.

When WINDOW has been set to "NUM-OF-

MASK 1" and "	NUM-OF-I	MASK 2"			
EVALUAT COND SCREE	N COND SAVE	EDIT SEL	F	C1 BRT	
1 CHNG REG 2 CONDITION SET RESET 3 REGISTER00 4 REGISTER01 5 REGISTER02 6 REGISTER03 7 REGISTER03 9 REGISTER05 9 REGISTER06 10 REGISTER07 11 TEST	00000-245760 00000-245760 00000-245760 00000-245760 00000-245760 00000-245760 00000-245760 00000-245760	[TEST RESULT] A00=000200 A01=000201 A02=000202 A03=000203 A04=000204 A05=000205 A06=000206 A07=000207 ADJ WITHOUT-PC	[OUT OK OK OK OK OK OK OK OSI.ADJ	NO NO NO NO NO NO NO NO	 Change the display of items ③ to ① from REGISTER00 to 07" to REGISTER08 to 15." You can set the output destinations using the up and down keys. (NO, Y0 to Y7, C000 to C127)

• When WINDOW has been set to "NUM-OF-MASK 4"

VALUAT COND SCREEN COND SAVE EDIT SEL	F C1 BRT	
OCHNG REG [TEST RESULT] OCONDITION SET RESET AUTO(+10%) (CONDITION SET RESET AUTO(+10%)) PREGISTER00 000000-245760 A00=000200 OREGISTER01 000000-245760 A01=000201 OREGISTER02 000000-245760 A02=000202 OREGISTER03 000000-245760 A03=000203 OTEST EXEC(WITH-POSI.ADJ WITHOUT-P	[OUTPUT] OK NO OK NO OK NO OK NO OSI.ADJ)	— You can set the output destinations using the up and down keys. (NO, Y0 to Y7, C000 to C127)

• When WINDOW has been set to "BINARY-IMG-MASK or "POLYGON"

EVALUAT COND SCREEN COND SAVE	EDIT SEL	F C1 BRT	
①CHNG REG ②CONDITION SET RESET AUTO(+10%)	[TEST RESULT]	[OUTPUT]	
③REGISTER00 000000~245760	A00=000200	OK NO —	 You can set the output destinations
(4) TEST EXEC(WITH-POSI.ADJ WITH	OUT-POSI.ADJ)		using the up and down keys. (NO, Y0 to Y7, C000 to C127)

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- ⇒ See "Chapter 14: Numerical calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions."

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.



Chapter 8: Object Counting by Binary Conversion

8-1 Outline

Purpose	Checks the number of objects (max. 3000 items.) when there is more than one object in an image. Measurement of the object's position is optional. - When the specified pixel field has been converted to a binary image, the white areas are measured or identified as separate objects and counted.			
Applications	Counting the number of food products or parts.			
Examples	Objects Image: Convert it to a c			
	Capture an image binary image objects/total area			

8-2 Setting operation


Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" ->"MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND TYPE RUN COND MAGE-ADJ MEA-CND(CAMERA1) POSI-CORRECT MEAS(NEW) THAL NUM. CALC FINAL NUM. CALC FINAL OUTPUT COND OBJ-TYPE I0 OBJ-TYPE SYS. TYPE(NEW)	(T)MEAS SELECTION
SET=WINDOW SET ESC=BACK SEL=CHNG IMC	G TRG=POPUP

Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "CNT-BIN-OBJ" from the popup menu.



Press the ESC key to return to the OBJECT TYPE COND (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (CNT-BIN-OBJ)" to go to the MEA-CND screen.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

• Setting the measurement conditions

(1) WINDOW

Select a window type. On the popup menu, move the cursor to "NORMAL," "BINARY-IMG-MASK," or "POLYGON," and press the SET key to select the item.

NORMAL	Normal window
BINARY-IMG-MASK	Select this item if the captured image is other than a rectangle, circle, or ellipse. This function masks the captured image using a stored binary image. ⇒ For details, see pages 3-25 to 29.
POLYGON	You can manually create any freeform polygon for the measurement area.

MEA-CND	SCREEN COND SAVE	F C1 BRT
1 MEAS GRAV CENT 2 WINDOW 3 REGISTER NO. 4 REGISTER EXIS 5 LABEL ORDER 6 AX.ANGL 7 FILT 8 CIRC-L 9 MID-PNT	NORMAL NORMAL NO B	NO NORMAL SINARY-IMG-MASK POLYGON SIZE ORDER SIZE ORDER CENT-GRAVTY-ORDER
REGISTER NO. (1) BIN AREA COND	000102030405060708091 ○×××	01112131415
SET=SELECT A MENU E	ESC=BACK SEL=CHNG IMG TRG=	=FUNC

② REGISTER NO.

Select register number to measure. Number of selectable registers varies with window shape selected.

NORMAL	0 to 3
BINARY-IMG-MASK	0 only
POLYGON	0 only

To save the measurement conditions using a different register number, press the SET key and highlight the number. Change this number by pressing the up and down arrow keys.

③ REGISTER EXIST

Select whether to register or not.

REGISTER NO. (4BIN AREA COND)

Register setting conditions are shown for each register number. Circles mean that "REGISTER EXIST" has set to "YES."

Setting (display) of binary area conditions

REGISTER NO.00 01 02 03(4) BIN AREA COND $\bigtriangledown \times \times$ \checkmark : No settingset to "YES," a circle is displayed.

How to set the register conditions


How to enter the REG-COND setting screen


There are three methods for getting to the REG-COND setting screen.

 On the "MEA-CND" setting screen, move the cursor to the "④BIN AREA COND" and press the SET key. The cursor will move into the table. Move the cursor to the "○" column and press the SET key. Note: If you press the SET key in the "X"

column, the setting will be invalid.

- On the "MEA-CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG COND" item and press the SET key.
- 3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to this item and press the SET key.






1 REGISTER NO.

The currently selected register number is displayed.

If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection. Note: When the "BINARY-IMG-MASK" or the

"POLYGON" is selected at "①WINDOW" on the "MEA-CND" screen, the "①REGISTER NO." line



will not be displayed and the other item numbers are decrement by one since the register number for "BINARY-IMG-MASK" and "POLYGON" is fixed.



- 3 MEAS AREA 4 THRESHOLD
- (5) INVERT B/W

8


2 MEAS SHAPE

Specify shape of measuring range.

RECTANGLE	Specify the coordinates for the upper left and lower right corners. The measurement area will be the area enclosed by this rectangle.
	Specify the center and the radius. The measurement area will be the area enclosed by this circle.
	Specify the center and the radius. The measurement area will be the area enclosed by this ellipse.

③ MEAS AREA

Specify a search area.



(4) THRESHOLD

Specify a threshold value.

Move the cursor to "①U.LM" and press the SET key. Then move the cursor to "②L.LM" and press the SET key again. The current value will be highlighted for each item. You can increase or decrease the value by pressing the up and down arrow keys. Press the ESC key to confirm the value you want.

The values above can be reset to an appropriate level automatically. Move the cursor to the upper function menu by pressing the TRG/BRT key and select "AUTO-REG." Then press the SET key to set the levels automatically.

 \Rightarrow For details, see page 3-15.

(5) INVERT B/W

Select whether to invert the display of black and white inside the measurement area.

Setting the mask details

On the "REG COND" screen, move the cursor to the upper function menu by pressing the TRG/BRT key. Select "DETAIL" by pressing the left and right arrow keys and then press the SET key. On the popup menu, you can select "MASK REGIST.," "BINARY PROCESS," "BINRY NOISE FILT," "BOUNDARY PROCESS, " and "AREA FILTER." The items selected here will be displayed on the "REG COND" menu.

(6) MASK NO.

Select a mask number. Note: This is available when "NORMAL" is selected on the "1)WINDOW" line.

(7) MASK SHAPE

Select mask shape.

- Select "NO," "RECTANGLE," "CIRCLE," or "ELLIPSE."
- REG COND SCREEN COND SAVE DETAIL F C1 BRT 1)REGISTER NO. 0(0~3) 2 MEAS SHAPE RECTANGLE (3) MEAS AREA SET (224,208)~(287,271 (4) THRESHOLD SET [U.LM255 L.LM100 (0~255)] (5) INVERT B/W NO MASK REGIST 6 MASK NO. $0(0 \sim 3)$ BINARY PROCESS (7) MASK SHAPE NO -NO BINRY NOISE FILT RECTANGLE BOUNDARY PROCESS 8 BINARY PROCESS FIXED CIRCLE AREA FILTER 9 BINARY NOISE FILT NO ELLIPSE **(10) BOUNDARY PROCESS** VALID (1) AREA FILTER U.LM245760 L.LMQ00000(0~245760) NO FIXED VALID ' EXPD.→CONTR. THRES-ADJ (VAR-DIFF) INVAL ID THRES-ADJ (VAR-RATE) CONTR → FXPD SET=VALUE INPUT ESC=BACK SEL=CHNG IMG TRG=FUNC

- When "BINARY-IMG-MASK" is selected on the "①WINDOW" line, this line will not appear, since this is already selected on the "MASK BINARY IMG" screen.
- When "POLYGON" is selected on the "(1)WINDOW" line, specify the polygonal shape of the mask.

(8) BINARY PROCESS

Select a binary processing method. Move the cursor to "FIXED," "THRES-ADJ (VAR-DIFF)" {adjustable threshold value (variation difference)}, or "THRES-ADJ (VAR-RATE)" {adjustable threshold (variation rate)}, and press the SET key to continue. \Rightarrow For details, see page 3-12.

(9) BINARY NOISE FILTER

Select a binary noise filter type. Move the cursor to "NO," "EXPD. \rightarrow CONTR." (expansion \rightarrow contraction), or "CONTR. \rightarrow EXPD" (contraction \rightarrow expansion), and press the SET key to continue.

 \Rightarrow For details, see page 3-13.


10 BOUNDARY PROCESS

Select whether objects crossing the boundary of the window will be "VALID" or "INVALID." \Rightarrow For details, see page 3-11.

(1) AREA FILTER

This function is used to exclude an object from measurement if its area is outside of the upper or lower limits. Specify a number from 0 to 245760.

Example of register measurement area and area mask




The inside of the measurement area (excluding the mask area) is converted to binary data.

Set the evaluation conditions


• How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the MEA-CND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the EVALUAT COND screen.



 Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-17.

EVALUAT COND SCREEN C	OND SAVE EDIT	SEL	F C1 BRT
1 REGISTER NO. 2 CONDITION SET		[TEST RESULT]	[OUTPUT]
③NUMBER OF OBJ	0000~3000	K=	NO
(4) TOTAL AREA	000000~245760		NO
(5) TEST	EXEC(WITH-PO	SI.ADJ WITHOUT-F	OSI.ADJ)

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- ⇒ See "Chapter 14: Numerical calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions."

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.



Chapter 9: Object Identification by Binary Conversion

9-1 Outline


Purpose	 When there are several objects and their positions are random, the presence or absence of objects and the size of the objects can be determined. The specified pixel area is converted to a binary image. The number of objects, total size of the white area (the objects) and the area, center of gravity, main axis angle, fillet diameter, circumference and center of each white area can be measured.
Applications	Counting the number of food products or parts, measuring the angle of rotation or the center of gravity of parts, and measuring the size of food products
Examples	[Measurement of 6 objects] Objects No.1 No.2 No.3 Objects No.4 No.5 No.6
	Image capture Convert it to a binary image Object identification (labeling and numbering) → Measure the area, center of gravity, main axis angle, fillet diameter, circumference, and center

9-2 Setting operation


Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" ->"MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "LABEL-BIN-OBJ" from the popup menu.



Press the ESC key to return to the OBJECT TYPE COND (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (LABEL-BIN-OBJ)" to go to the "MEA-CND" screen.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

• Setting the measurement conditions

(1) MEAS GRAV CENTR Select whether or not to measure the center of gravity. MEA-CND SCREEN COND SAVE MEA-CND NORMAL NORMAL NORMAL MEA-CND NO(0~3) NO NORMAL MEA-CND O(0~3) NO NORMAL MEA-CND SCREEN SCREEN NO

② WINDOW

Select a window type. On the popup menu, move the cursor to "NORMAL," "BINARY-IMG-MASK," or "POLYGON," and press the SET key to select the item.

MEA-CND SCI	REEN COND SAVE	F C1 BRT
1 MEAS GRAV CENTER 2 WINDOW 3 REGISTER NO. 4 REGISTER EXIST 5 LABEL ORDER 6 AX.ANGL 7 FILT 8 CIRC-L 9 MID-PNT	0(0~3) NO B	NO VORMAL VOLYGON SCAN-ORDER SIZE ORDER CENT-GRVTY-ORDER
REGISTER NO. 000	$\times \times $	01112131415

NORMAL	Normal window
BINARY-IMG-MASK	Select this item if the captured image is other than a rectangle, circle, or ellipse. This function masks the captured image using a stored binary image. ⇒ For details, see pages 3-25 to 29.
POLYGON	You can manually create any freeform polygon for the measurement area.

③ REGISTER NO.

Select register number to measure. Number of selectable registers varies with window shape selected.

NORMAL	0 to 3
BINARY-IMG-MASK	0 only
POLYGON	0 only

To save the measurement conditions using a different register number, press the SET key and highlight the number. Change this number by pressing the up and down arrow keys.


(4) REGISTER EXIST

Select whether or not to register the measurement conditions. When "YES" is selected, items (5) to (9) will be displayed on the "MEA-CND" menu.

(5) LABEL ORDER

Set the order for displaying the measured results. Select "SCAN-ORDER," "SIZE-ORDER," or "CENT-GRVTY-ORDER" and then press the SET key.

	Assigns label numbers in the order in which objects were scanned (from top to bottom) in the measurement range.
SIZE-ORDER	Assigns label numbers by the size of the objects found in the measurement range, from largest to smallest.
CENT-GRVTY-ORDER	Assigns label numbers by the of center gravity of the objects found in the measurement range, from heaviest to lightest.



6 AX.ANGL (axis angle)

Select whether to measure the angle of the longitudinal line (drawn through the gravity center of the workpiece) to the horizontal.

(7) FILT (fillet diameter)


(8) CIRC-L (peripheral length)

perimeter of the workpiece.


Select whether to measure the diameters of horizontal and vertical fillets on the workpiece.

Select whether to count the number of pixels in the


Main axis angle




· Fillet width



Peripheral



The number of pixels in the boundary line of an object (stepped are counted as $x\sqrt{2}$ pixels)



REGISTER NO. (10 BIN AREA COND)

Register setting conditions are shown for each register number. Circles mean that "REGISTER EXIST" has set to "YES."

Setting (display) of binary area conditions


REGISTER NO.	00	01	02	03		
10 BIN AREA COND	Ο	Х	Х		When item "④REGISTER EXIST" is	,
_	\times	: 1	No	se	ting set to "YES," a circle is displayed.	


How to set the register conditions

• How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

- On the "MEA-CND" setting screen, move the cursor to the "⁽¹⁾BIN AREA COND" and press the SET key. The cursor will move into the table. Move the cursor to the "⁽⁻⁾" column and press the SET key. Note: If you press the SET key in the "X" column, the setting will be invalid.
- On the "MEA-CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG COND" item and press the SET key.
- On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to this item and press the SET key.





(1) REGISTER NO.

The currently selected register number is displayed.

If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection. Note: When the "BINARY-IMG-MASK" or the

"POLYGON" is selected at

"①WINDOW" on the "MEA-CND" screen, the "①REGISTER NO." line will not be displayed and the other item numbers are decrement by one since the register number for "BINARY-IMG-MASK" and "POLYGON" is fixed.



9-5


(2) MEAS SHAPE

Specify shape of measuring range.

RECTANGLE	Specify the coordinates for the upper left and lower right corners. The measurement area will be the area enclosed by this rectangle.
CIRCLE	Specify the center and the radius. The measurement area will be the area enclosed by this circle.
ELLIPSE	Specify the center and the radius. The measurement area will be the area enclosed by this ellipse.

(3) MEAS AREA

Specify a search area.



Specify a threshold value.

Move the cursor to "①U.LM" and press the SET key. Then move the cursor to "②L.LM" and press the SET key again. The current value will be highlighted for each item. You can increase or decrease the value by pressing the up and down arrow keys. Press the ESC key to confirm the value you want.

The values above can be reset to an appropriate level automatically. Move the cursor to the upper function menu by pressing the TRG/BRT key and select "AUTO-REG". Then press the SET key to set the levels automatically. \Rightarrow For details, see page 3-15.

(5) INVERT B/W

Select whether to invert the display of black and white inside the measurement area.

Setting the mask details

On the "REG COND" screen, move the cursor to the upper function menu by pressing the TRG/ BRT key. Select "DETAIL" by pressing the left and right arrow keys and then press the SET key. On the popup menu, you can select "MASK REGIST.," "BINARY PROCESS," "BINRY NOISE FILT," "BOUNDARY PROCESS, " and "AREA FILTER." The items selected here will be displayed on the "REG COND" menu.

 \Rightarrow See page 8-6.

6 MASK NO.

Select a mask number.

Note: This is available when "NORMAL" is selected on the "①WINDOW" line.

(7) MASK SHAPE

Select mask shape.

- Select "NO," "RECTANGLE," "CIRCLE," or "ELLIPSE."
- When "BINARY-IMG-MASK" is selected on the "①WINDOW" line, this line will not appear, since this is already selected on the "MASK BINARY IMG" screen.
- When "POLYGON" is selected on the "①WINDOW" line, specify the polygonal shape of the mask.

(8) BINARY PROCESS

Select a binary processing method. Move the cursor to "FIXED," "THRES-ADJ (VAR-DIFF)" {adjustable threshold value (variation difference)}, or "THRES-ADJ (VAR-RATE)" {adjustable threshold (variation rate)}, and press the SET key to continue. \Rightarrow For details, see page 3-12.

9 BINARY NOISE FILTER

Select a binary noise filter type. Move the cursor to "NO," "EXPD. \rightarrow CONTR." (expansion \rightarrow contraction), or "CONTR. \rightarrow EXPD" (contraction \rightarrow expansion), and press the SET key to continue.

 \Rightarrow For details, see page 3-13.

10 BOUNDARY PROCESS

Select whether objects crossing the boundary of the window will be "VALID" or "INVALID." \Rightarrow For details, see page 3-11.


(1) AREA FILTER

This function is used to exclude an object from measurement if its area is outside of the upper or lower limits. Specify a number from 0 to 245760.

Example of register measurement area and area mask

Measurement area-(Rectangle)

> Mask area (Rectangle)




- The inside of the measurement area (excluding the mask area) is converted to binary data.

Set the evaluation conditions

• How to move to the evaluation condition setting screen There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the MEA-CND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the EVALUAT COND screen.



 Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT	
OBJECT TYPE COND TYPE00 TYPE01 TYPE01 TYPE RUN COND MAGE-ADJ MEA-CND(CAMERA1) MEAS0 POSI-DEVIATION MEAS01(CNT-BIN-OBJ) MEAS CND REG-COND EVALUATION COND NUM-CALC OUT-COND MEA-CND(CAMERA2) FINAL OUTPUT COND OBJ-TYPE I/O OBJ-TYPE SYS.	1 REGISTER NO. 2 CONDITION SET 3 NUMBER OF OBJ 4 TOTAL AREA 5 TEST	
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP		

The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-19.

EVALUAT COND SCREEN COND SAVE EDIT SEL			F C1 BRT	
1 REGISTER NO. (2) CONDITION SET	0(0~3) AUTO(±10%)	[TEST RESULT]	[OUTPUT]	
③NUMBER OF OBJ	000~128	K=	NO	
(4) TOTAL AREA (5) LABEL NO.	000000~245760 000(0~000)	A=	NO	
6 OBJECT AREA	000000~245760	R=	NO	
MAIN AXIS ANGL		B=		
FILLET WIDTH		FX=		
		FY=		
PERIPHERAL MID POINT		CR= CX=		
MIDPOINT		CX= CY=		
(7) TEST	EXEC(WITH-PO	SI.ADJ WITHOUT-PO	OSI.ADJ)	
SET=VALUE INPUT ESC=BACK SEL=CHNG IMG TRG=FUNC				

Numeric calculation setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- See "Chapter 14: Numerical calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions."

("YES" has been selected) on the "MEAS COND" menu

(page 10-2).

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.

	(TYPE00) F C1 BRT
Final evaluation result Measurement program Registration number in the measurement condition NUMBER OF OBJECTS TOTAL AREA LABEL NUMBER OBJECT AREA CENTER OF GRAVITY COORDINATE MAIN AXIS ANGLE FILLET DIA PERIPHERAL	• OK • MEAS XXXXms • MEASUREMENT 1 LABEL-BIN-OBJ • REGISTER NO.0(0~3) • K=004 OK • A=006168 OK • LABEL NUMBER 000(000~003) • R=001542 OK • $[GX=206.0 OK]$ [GX=206.0 OK] [GX=303.0] • B=+028.0° • $[FX=042]$ [FX=042] [FX=042] [FX=042] [CX=] CX= [CX=]
- CENT OF GRAV, MAIN AXIS ANGL, FILLET WIDTH, PERIPHERAL, or MID POINT are displayed when measurement of these parameters has been specified	X0~6 00000000 Y0~7 ∎0000000 READY 0 MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE

Chapter 10: Existence Inspection by Point Measurement

10-1 Outline


Purpose	 The presence or absence of target objects is examined. A simple black and white evaluation is made in the specified pixel area of binary images. The light level in the specified pixel area is averaged, and a decision is made whether or not it is within the specified range of brightness for gray scale images. 		
Applications	Checking the presence or absence of packed parts, inspecting the working condition of LEDs or fluorescent character display tubes, and sorting household electric appliances		
Examples	 Inspection of 6 points Image capture Binary image Binary image (m, n = 1 to 16) 		

10-2 Setting operation


Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" -> "MEA-CND (CAM-ERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "POINT-MEAS" from the popup menu.



Press the ESC key to return to the "OBJECT TYPE COND" (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (POINT-MEAS)" to go to the "MEA-CND" screen.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

• Setting conditions (mode selection)

Select a mode on the "①MODE" line. By selecting either "BINARY" or "AVG-GRAYS," the details of the settings will vary.

When the "BINARY" mode is selected

(2) BINARY PROCESS	2 BINARY PF
Select a binary processing procedure. Select	3 THRESHO
"FIXED," "THRES-ADJ(VAR-DIFF)," or	
"THRES-ADJ(VAR-RATE)."	(4) CHNG-REC
· · · · · · ·	REGISTER

MEA-CND SC	A-CND SCREEN COND SAVE					
1 MODE 2 BINARY PROCESS 3 THRESHOLD	BINARY	BINARY AVG-GRAYS FIXED				
 ④ CHNG-REG REGISTER NO. ⑤ POINT COND 	CHNG-REG	THRES-ADJ(VAR-DIFF) THRES-ADJ(VAR-RATE)				

FIXED	Does not correct the threshold value.		
	Effective in preventing binary processing failures since it applies adjustments according to changes in the lighting conditions for		
	individual workpieces.		

 \Rightarrow For details, see page 3-12.

③ THRESHOLD

Specify a threshold value. Select this line and press the SET key to enter the "THRESHOLD" screen. Move the cursor to "(1)U.LM" and "(2)L.LM" each, then press the SET key. The current value will be highlighted for each item. You can increase or decrease the value by pressing the up and down arrow keys. Press the ESC key to confirm the value you want. \Rightarrow For details, see page 3-10.

AUTO SETTING

The values above can be reset to an appropriate level automatically. Move the cursor to the upper function menu by pressing the TRG/BRT key and select "AUTO-REG". Then press the SET key to set the levels automatically.

When the "AVG-GRAYS" mode is selected

(2) AVG. GRAY PROC

Select an average gray processing method. Select "FIXED," "GRAY-ADJ (VAR-DIFF)," or "GRAY-ADJ(VAR-RATE)."

MEA-CND	SCREEN COND SAVE	F C1 DRK
(1)MODE	AVG-GRAYS	
2 AVG.GRAY PROC		FIXED
		GRAY-ADJ(VAR-DIFF)
_		GRAY-ADJ(VAR-RATE)
③CHNG-REG	CHNG-REG	
REGISTER NO.	00000100200300400500	06007
④ POINT COND		< ×

FIXED	Does not correct the gray level.		
GRAY-ADJ(VAR-DIFF)Corrects the gray level by adding a specified threshold value t reference for variation in the light level. (Measured light level) - (reference light level) + (specified threshold value)			
GRAY-ADJ(VAR-RATE)	Corrects the gray level by multiplying a specified threshold value times the reference for variation in the light level. (Measured light level) / (reference light level) x (specified threshold value)		

③ CHNG-REG

Changes the display of the registration numbers for the "④POINT COND." Move the cursor to this line and press the SET key. "CHNG-REG" will be highlighted. Then, press the up and down arrow keys to change the register number series shown in the table as follows "000 to 007," "008 to 015," "016 to 023," ... up to "248 to 255".

- If the "BINARY" mode was selected, a maximum of 256 points (0 to 255) can be registered.
- If the "AVG-GRAYS" mode was selected, a maximum of 128 points (0 to 127) can be registered.



④ POINT COND

- Points which have been registered are marked with an "O."
- After being registered on the point condition setting screen, an "O" will be displayed in the corresponding cells.
- \Rightarrow For details, see next page.

Setting the conditions (by selecting the point conditions)

How to enter the REG COND setting screen

This paragraph describes the setting for each point condition. There are three ways to bring up the "REG COND" screen.

 On the "MEA-CND" setting screen, move the cursor to the "⑤POINT COND" and press the SET key. The cursor will move into the table. Move the cursor to the "X" column and press the SET key.

Note: After being registered, the "X" mark in a corresponding cell is changed to "O."

 On the "MEA-CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG COND" item and press the SET key.

MEA-CND SC	CREEN COND SAVE	F C1 DRK
(1)MODE	BINARY	IMG PRE-PROC
(2) BINARY PROCESS	FIXED	REG COND
(3)THRESHOLD	SET [U.LM255 L.LM100(0~255)]	EVALUATION
0		NUM-CALC
(4)CHNG-REG	CHNG-REG	OUT
REGISTER NO.		
(5)POINT COND		
	$ \mathbf{X} \times \mathbf{X} \times \mathbf{X} \times \mathbf{X} $	×
SET=SELECT A MENU ES	C=BACK SEL=CHNG IMG TRG=FUN	С

3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to this item and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND	① SIZE ② EVALUATION ③ EVAL-SPEC(RATIO %) ④ REGISTER NO.
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG	TRG=POPUP

• Setting the point measurement conditions

1 SIZE

Specify the point size. Highlight the numbers next to "X" and "Y" and increase or decrease the value using the up and down arrow keys. To confirm the new value, press the SET key twice. When the settings are complete, press the ESC key. The point size can be set between 2 and 32, in units of one pixel.

REG COND SCREEN COND SAVE DETAIL	F C1 BRT
	MAJORITY AND OR

2 EVALUATION

Set the evaluation condition. Select "MAJORITY," "AND," or "OR." The details for the evaluation settings are as follows.

②EVALUATION	Description		
MAJORITY	When white occupies more than the specified percentage of pixels in a point, it is treated as white. Under any other conditions than the above it is treated as black. The value can be set between 0 and 100%, in units of 1%.		
AND	When all the pixels are white, this point will be treated as white.		
OR	When even one pixel is white, this point will be treated as white.		

3 EVAL-SPEC

Select the number and highlight it. Then increase or decrease the number using the up and down arrow keys. To confirm the new value, press the SET key twice. When the changes are complete, press the ESC key.

④ REGISTER NO.

When you want to change the number already registered, highlight the number and increase or decrease the number by pressing the up and down arrow keys. Next, move the cursor to the "NO" position and press the SET key. A popup menu will appear. Select "YES" on this popup menu to store this register number.

Specify the position of the point

After storing the register number using "④REGISTER NO.," a point will appear on the screen. Move the cursor on the "⑤UPPER LEFT" line and press the SET key. Then highlight the "MOVE" item and press the SET key. Now you can move the point anywhere on the screen using the up/down, left/right arrow keys.

REG COND	SCREEN COND SAVE DETAIL	F C1 BRT
(1)SIZE	Y08 × X08(2~32)	
2 EVALUATIO	(<i>'</i> , <i>'</i> ,	
③EVAL-SPEC	C(RATIO %) 050%	
(4) REGISTER	NO. 000(0~255)YES	
(5) UPPER LEI	FT MOVE(224.208)	

• STORE BLOCK COND

Press the TRG/BRT key to move the cursor to the upper function menu. Select "DETAIL" and press the SET key. Select "STORE BLCK OF PNTS" from the popup menu and press the SET key. Now, items (6) to (10) will be displayed on the "REG COND" menu.

This function is used to set a group of points at the same time, after specifying the number of points horizontally and vertically and their spacing.

④ REGISTER NO.

When "AND" or "OR" is selected on the "2 EVALUATION" line, select "YES" at the 4 REGISTER NO" item. Then, "5 UPPER LEFT" will be displayed.

(5) UPPER LEFT

Specify the coordinates of the upper left corner of the block you want to register.

(6) BLOCK ARRANGEMENT

Enter the number of points along the X (horizontal) and Y (vertical) axes.

7 BLOCK SPACING

Specify the distance between the points in the horizontal and vertical rows.

(8) STORE BLCK OF PTS

Select "EXEC" and press the SET key to register the block.

(9) DEL BLOCK OF PTS


Delete all the points that were registered at the same time.


10 MOVE BLOCK OF PTS

Move the group of points that were registered at the same time.


Example of a block registration

 \checkmark Set the starting point in item (5) above.





Enter 002 (vertical) · 003 (horizontal) in item "⑥BLOCK ARRANGEMENT," and enter the vertical (Y) and horizontal (X) intervals in item "⑦BLOCK SPACING." Then select item "⑧STORE BLOCK OF PTS" to store the settings for the block.



Set the evaluation conditions


• How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the MEA-CND (or REG COND) screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the EVALUAT COND screen.

MEA-CND SC	REEN COND SAVE	F C1 DRK
O MODE O BINARY PROCESS O THRESHOLD O CHNG-REG REGISTER NO. O POINT COND	BINARY FIXED SET [U.LM255 L.LM100(0-255)] CHNG-REG 0000010020030040050060	IMG PRE-PROC RED COND EVALUATION NUM-CALC OUT
SET=SELECT A MENU ESC	C=BACK SEL=CHNG IMG TRG=FUNC)

 Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear.

 \Rightarrow For details about the evaluation conditions, see page 3-17.

				,	Acceptance (OK/NG) criteria
					WHITE: Acceptable when a majority of the inspected
					pixels are white.
• When MOI	DE has been	set to "BINARY	<u> </u>	/	BLACK: Acceptable when a majority of the inspected
EVALUAT COND SCR	REEN COND SAVE ED	IT SEL	/ F	C1 DRK	pixels are black.
①PAGE CHNG	٥	[TEST RESULT]	[OUTPU]	<u>ŋ</u>	Ex.: When the point to be inspected is 8 X 8 (64 pixels)
(2)P000	WHITE	OK 🖌	NO		and WHITE is specified, if 33 white pixels are
③P001	WHITE	OK	NO		detected, the point is accepted.
④P002	WHITE	ОК	NO		Many and the enderst deptications using the sur-
(5)P003	WHITE	OK	NO	-	You can set the output destinations using the up
@P004	WHITE	OK	NO		and down keys. (NO, Y0 to Y7, C000 to C127)
⑦P005	· · · · · ·			'	Not displayed for unregistered point numbers.
(8)P006					Not displayed for diffegistered point numbers.
(9)P007	L				
10TEST	EXEC (WITH-PO	si.adj without-posi.adj)			
1					Average light level for each point
• When MO	DE has been	set to AVG-GRA	YS		
	REEN COND SAVE ED			C1 DRK	
1)PAGE CHNG		[TEST RESULT]	[OUTPUT]	
②CONDITION SE	ET REST(+10%)				
3P000	200~210	200	OK	NO	
④P001	200~210	200	OK		
(5)P002	200~210	200	OK	NO	-You can set the output destinations using the up
6P003	200~210	200	OK	NO	and down keys. (NO, Y0 to Y7, C000 to C127)
⑦P004	200~210	200	OK	NO	
8P005	1				
9P006					Average light level for each point
10P007		-1 -1			
1)TEST	EXEC(WITH	POSI.ADJ WITHOUT-POSI	.ADJ)		

1

- Numeric calculation setting Press the TRG/BRT key to move the cursor to
 - Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
 - Select "NUM-CALC" on the menu tree.
 - ⇒ See "Chapter 14: Numerical calculation."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions."

Display the measurement results Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen. • When MODE has been set to BINARY

	-	
	(TYPE00)	F C1 DRK V*.**
Final evaluation result Measuring time Measurement program number	→OK → MEAS XXXXms → MEASUREMENT 1 POINT-MEAS	• ·
Evaluation of the correct black or white		
color detected at registration No.000	► P000=WHITE OK	
001	► P001=WHITE OK	
002	► P002=WHITE OK	
003	► P003=WHITE OK	
004	► P004=WHITE OK	
005 ———	► P005=	
006	► P006=	
007	► P007=	
L		
 Areas will not be displayed for unspecified registration numbers. 		

X0~60000000 Y0~70000000 READY0 MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE

When MODE has been set to AVG-GRAYS

WEAS XXXXms MEASUREMENT 1 P000=115 OK P001=120 OK P002=114 OK P003=118 OK P004=116 P005=115 OK P006= P007=	(TYPE00)	F C1 DRK V* **
P001=120 OK P002=114 OK P003=118 OK P004=116 OK P005=115 OK P006= P007= X0~60000000 Y0~70000000 READY0	MEAS XXXXms	
P002=114 OK P003=118 OK P004=116 OK P005=115 OK P006= P007= X0~60000000 Y0~70000000 READY0	P000=115 OK	
P003=118 OK P004=116 OK P005=115 OK P006= P007= X0~60000000 Y0~70000000 READY0	P001=120 OK	
P004=116 OK P005=115 OK P006= P007= X0~60000000 Y0~700000000 READY0	P002=114 OK	
P004=116 OK P005=115 OK P006= P007= X0~60000000 Y0~70000000 READY0	P003=118 OK	
P006= P007= X0~60000000 Y0~70000000 READY0	P004=116 OK	
P007= X0~60000000 Y0~70000000 READY0	P005=115 OK	
X0~60000000 Y0~700000000 READY0	P006=	
	P007=	
MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE	X0~6 0000000 Y0~7 0000000	READY
	MNU-CHG MAIN-COND CHG-MEA COND-CHG	CHNG-REG SCREEN-CHG CHG-TYPE

Chapter 11: Multiple Positional Measurements

11-1 Outline The IV-S30J can detect up to 128 workpieces whose images exceed the specified matching level (gray search) or threshold value (edge detection) from the reference image. - The positional deviation measurement needs to have a number of positions registered for Purpose measurement. However, this measurement only requires you to register one position and reduces the set up time. Measure the position of workpieces with a complicated light level that cannot be converted Applicainto binary images. tion Gray search Reference image Four workpieces detected [Measurement results] - Number of images detected - Coordinates and degree of match detected for each image Edge detection Example [Measurement results] - Number of images detected - Coordinates detected L2 L1 L3 This is useful for obtaining the distance between the coordinates of a position. - L1 to L3 can be calculated by measuring distances and angles.


11

11-2 Setting operation



• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" -> "MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "MULTI-POSI" from the popup menu.

MEASUREMENT1 SCREEN COND SAVE	F C1 BRT
Improvemental screen cond save	NO POSI-DEVIATION CHK-DEG-MATCH INSPECT-LEAD MEAS-BIN-AREA CNT-BIN-OBJ LABEL-BIN-OBJ POINT-MEAS MULTI-POSI MULTI MATCHES
SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TR	RG=FUNC


Press the ESC key to return to the "OBJECT TYPE COND" (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (MULTI-POSI)" to go to the "MEAS CND" screen. ⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

1 DTECT PRECISION

Select detection precision. You can select one of two levels (standard/high), according to your conditions, the desired precision level for detection results, and the detection speed. \Rightarrow For details, see page 3-9.

2 REGISTER NO.

4 registers are available for the multiple position measurement (Registers 0 to 3). If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.



3 MODE

Select a mode.

The details of each mode are as follows.

NO	No measurement is made.
	Uses the gray search function to detect a shape in the captured images that matches the reference image.
EDGE DTECT	Uses the edge detection function to look for shapes in the captured images that have a value larger than the specified threshold value.

④ DETECT ORDER (when GRAY-SRC is selected)

When "GRAY-SRC" is selected on line "③MODE," select "SCAN-ORDER" or "MATCH LVL" on the "④DETECT ORDER" line.

SCAN-ORDER (in the order scanned): Searches in the order scanned.

MATCH LVL (degree of match): Searches by comparing levels with the reference image.

REGISTER NO. (5) DTECT OBJECT)

Shows the specified mode(s) for each register. S: gray search E: edge detection \times : means no setting

00	01	02	03
S	Е	S	\times

How to set the register conditions

How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

 On the "MEAS CND" setting screen, move the cursor to "5 DTECT OBJECT" and press the SET key. The cursor will move into the table. Move the cursor to the "S" or "E" column and press the SET key.

Note: If you press the SET key in the "X" column, the setting will be invalid.

About "S" \Rightarrow See pages 11-5 to 7. About "E" \Rightarrow See pages 11-7 to 9.

2) On the "MEAS CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG-COND(S)" or "REG-COND(E)" item and press the SET key.


About "REG-COND(S)" ⇒ See pages 11-5 to 7.

About "REG-COND(E) " ⇒ See pages 11-7 to 9.

3) On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG-COND(S)" and "REG-COND(E)" items will appear. Move the cursor to either of these items and press the SET key.

About "REG-COND(S)" ⇒ See pages 11-5 to 7.

About "REG-COND(E)" ⇒ See pages 11-7 to 9.



SELECT OBJECT TYPE COND	F C1 DRK
OBJECT TYPE COND OBJECT TYPE COND — TYPE00 — TYPE RUN COND — MEA-CND(CAMERA1) — MEAS01(MULTI-POSI) — MEAS01(MULTI-POSI) — MEAS01(MULTI-POSI) — MEASO1(MULTI-POSI) — MEASO1(MULTI-POSI) — MEASO1(MULTI-POSI) — MEASCND — MEASCND — MEASCND — MEASCND — MEASON(MULTI-POSI) — MEASCND — MEASON(MULTI-POSI) — MEASCND — MEASCND — MEASCOND(S) — MEASUNT COND — MEAS(NEW) — MEA-CND(CAMERA2) — FINAL NUM. CALC — FINAL OUTPUT COND — OBJ-TYPE VO — OBJ-TYPE SYS.	①REGISTER NO.
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IN	IG TRG=POPUP


[1] Set the register conditions for a gray search

Set a reference image

Move the cursor to "②REF-IMG AREA" and press the SET key. When the SET item is highlighted, press the SET key again to bring up the setting screen.


REG COND SCREI	EN COND SAVE DETAIL	F C1 DRK
①REGISTER NO.	0(0~3)	
②REF-IMG AREA ③SEARCH AREA	SET (224.208)~(287.271) SET (216.200)~(295.279)	
④MATCH LVL(CONTR) ⑤MATCH LVL	+05000 +07000	
		- Object to measure - Search area
		Search direct
SEL=WINDOW SET ESC=BA	ACK SEL=CHNG IMG TRG=FU	NC

Set the coordinates for "(1)UP.L" and "(2) LO.R." The rectangle inside the solid lines is the reference image.



Register a reference image

After setting the reference image area, store an image in the controller as a reference image. Select "④REFERENCE IMG" using the up/ down arrow keys and select "REG" from the popup menu.



Select a reference image

Move the cursor to the function menu on the "REG COND" screen by pressing the TRG/BRT key. Move the cursor to "DETAIL." Press the SET key on the "REFERENCE IMG" line in the popup menu. The white square on the left will change to a black square. Then, the

"②REFERENCE IMG" item will appear on the screen.

You can use the same procedures to show "DETECT CRD" (detection coordinates) and "CONTR.PIXL" (contraction pixels) on the screen.

On the "2 REFERENCE IMG" line, select a reference image from the reference images already registered.

Ex: 015 (000 to 026)


Select reference image No. 15 from the 26 registered reference images (000 to 026).

REG COND SCREEN	N COND SAVE	DETAIL	F C1 BRT
(1) REGISTER NO. (2) REFERENCE IMG (3) REF-IMG AREA (4) SEARCH AREA (5) DIRECT COORD (6) CONTR.PIXEL (7) MATCH LVL(CONTR) (8) MATCH LVL	0(0~3) 015(000-026) SET (224.208) SET (216.200) CENTER (234.2 3 ← +05000 +07000	~(287.271) ~(295.279) 2(19) (
SEL=VALUE INPUT ESC=B	ACK SEL=CHNG	IMG TRG=FUN	IC

(4) SEARCH ARE

Specify the search area (inside the dotted lines) on the "④SEARCH AREA (MDL0)" line, using the same procedures used for setting the reference image area.

An example




(5) DTECT COORD (detection coordinates)

Select whether to use the detection coordinates as the center of the reference area or to allow the point to be set freely.

6 CONTR.PIXEL (contraction pixels)

- 1: Search the image in units of 2 pixels.
- 2: Search the image in units of 4 pixels.
- 3: Search the image in units of 8 pixels.



Set degree of match

(7) MATCH LVL (CONTR)

Specify the degree of match used for detection in the contracted images (detects contracted shapes in images whose value is larger than the specified reference value).

(8) MATCH LVL

Specify a degree of match used for detection in the original images of the contracted images that were detected in the search at line "⑦MATCH LVL" (detects original images which are larger than the specified value).

EG COND SCREEN	I COND SAVE	DETAIL	F C1 BRT
THEGISTER NO. THE REPORT OF THE PARTY OF THE PAR	0(0~3) 015(000-026) SET (224.208) SET (216.200) CENTER (234.2 3 +05000 +07000	~(295.279)	


[2] Setting the register conditions for edge detection

2 MEAS SHAPE

Select a measurement shape.

	Select a pattern to be used for image processing. ⇒See pages 3-4 to 3-8.
--	---

NO ARTF/ARTIF: Select whether to detect edge or not with average density. ⇒ See page 3-15.



③ SEARCH AREA

Select "③SEARCH AREA" and press the SET key to go to the setting screen.

• When "RECTANGLE" is selected Highlight "①UP.L" and press the SET key. The X and Y axes will appear in the search area. Move the X/Y axes using the up/down/ left/right arrow keys to identify the upper left corner. When correct, press the SET key.


- To return to the previous coordinates, press the ESC key.

Next, highlight "②LO.R" and press the SET key. Identify the lower right corner the same way.

4 dtect mode

Select an image processing method for the edges. CHNG POINT \neg

DRK \rightarrow BRT BRT \rightarrow DRK CENT (BRT) CENT (DRK)



5 SEARCH DIRECT

Specify a search direction. The direction for searching varies with each detection shape.

• When "RECTANGLE" is selected

Horizontal (→)	Scan the reference line from left to right (\rightarrow)
Horizontal(←)	Scan the reference line from left to right $(-)$
Vertical (↓)	Scan the reference line from top to bottom (\downarrow)
Vertical (†)	Scan the reference line from bottom to top (†)

When "LINE" is selected

Start point → End point	Scan along a straight line from the starting point to the end point
End point → Start point	Scan along a straight line from the end point to the starting point


• When "CIRC-L" or "ELIP-L" is selected

Clockwise direction	Scan around the circumference clockwise
Counter-clockwise direction	Scan around the circumference counter-clockwise

 \Rightarrow For details, see page 3-14.


6 THRESHOLD

Enter the threshold value for binary conversion. Move the cursor to "⁽⁶⁾THRESHOLD" and press the SET key. Then highlight the "SET" position on this line and press the SET key and the "REG COND" setting screen will appear.




Automatic setting

Select "AUTO-REG" from the upper function menu on the THRESHOLD setting screen. The controller will set the optimum value automatically.



• Example of register

Shown below is an example detected with "2MEAS SHAPE" set to "LINE," and "4DETECT MODE" set to "CHNG POINT."




Set the evaluation conditions

• How to move to the evaluation condition setting screen There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the "MEAS COND (or REG COND)" screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the "EVALUAT COND" screen.

MEAS CND	SCREEN	COND	SAVE	F C1 BRT
①DTECT PRECISI ②REGISTER NO. ③MODE ④DTECT ORDER REGISTER NO. ⑤DTECT OBJECT	0(0~3 GRAY- SCAN) SRC ORDER	40506	070809101112131415
				IMG PRE-PROC REG-COND(S) REG-COND(E) EVALUATION DST&ANGL NUM-CALC OUT
SET=SELECT A ME	NU ESC=B	ACK SEL	_=CHNG	IMG TRG=FUNC

 Move the cursor to the "EVALUATION COND" item on the Menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear. \Rightarrow For details about the evaluation conditions, see page 3-17.

- When "GRAY-SRC" is selected on line "③ MODE."

EVALUAT COND SCREEP	N COND SAVE EDIT	SEL	F C1 BRT
1 REGISTER NO. 2 CONDITION SET	0(0~3) AUTO(–10%)	[TEST RESULT]	[OUTPUT]
③ NUMBER OF OBJ	000~128	K=	NO
(4) DTECT NUMBER (5) MATCH LVL	000~(0~000) -10000~+1000	M0=	NO
X COORD. Y COORD.	X0= Y0=		
[®] TEST	EXEC(WITH-PC	SI.ADJ WITHOUT-F	POSI.ADJ)

- When "EDGE DTECT" is selected on line "③ MODE."

EVALUAT COND SCREEN	COND SAVE EDIT	SEL	F C1 BRT
1 REGISTER NO. 2 CONDITION SET	0(0~3) AUTO(–10%)	[TEST RESULT]	[OUTPUT]
③NUMBER OF OBJ ④DTECT NUMBER	000~128 000~(0~000)	K=	NO
X COORD. Y COORD. ⑤TEST	X0= Y0= EXEC(WITH-PC	DSI.ADJ WITHOUT-F	POSI.ADJ)

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- ⇒ See "Chapter 14: Numerical calculations."


Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions.

Display the measurement results


Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.





- * 1 The detection order can be set to either "SCAN-ORDER " or "MATCH LVL" on item "④DETECT ORDER" on the "MEAS CND" screen. I See page 11-3.
- * 2 The inspection number corresponds to the image of the solid line.

An example of the display when "gray search" is selected.



Chapter 12: Multiple Degree of Match Inspection

12-1 Outline

Purpose	Using the gray search function, the IV-S30J can detect up to 128 workpieces whose captured image exceeds the required degree of match with the reference image.						
Applica- tion	Inspect (or count) workpieces that have complicated light level and cannot be converted into binary images.						
Exam- ple	Reference image Image: Constraint of the second						


12

12-2 Setting operation


Setting the measurement conditions

• How to enter the measurement conditions setting screen

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree)-> "TYPE00" ->"MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select "MULTI MATCHES" from the popup menu.



Press the ESC key to return to the "OBJECT TYPE COND" (menu tree) screen, and select the "MEAS CND" item shown under "MEAS01 (MULTI MATCHES)" to go to the "MEAS CND" screen.


Hardware.

1 DTECT PRECISION

Select detection precision. You can select one of two levels (standard/high), according to your conditions, the desired precision level for detection results, and the detection speed. \Rightarrow For details, see page 3-9.

2 REGISTER NO.

4 registers are available for the multiple degree of match inspection (Registers 0 to 3). If you want to set the measurement conditions for a different register number, press the SET key to highlight the register number currently selected. Then press the up and down arrow keys to select the register number whose measurement conditions you want to set. Press the SET key to confirm your selection.



3 MODE

Select detection precision.

4 matching

Select a density for comparison when inspecting the image. The details are as follows.

	Description
Average light level	Obtain average light level of the image in the area detected using the gray search.
Difference absolute value	Calculate the difference of the absolute values from the image detected using the gray search and the reference image. The result is light level difference. By obtaining this value, you can get an idea of the total change in light level. Total light level difference = Σ (Ni — Nt) Ni : Light level of the captured image (contraction 3) Nt : Light level of the reference image (contraction 3)

(5) DETECT ORDER

Select "SCAN-ORDER" or "MATCH LVL" on the "⑤DETECT ORDER" line. SCAN-ORDER (in the order scanned): Searches in the order scanned. MATCH LVL (degree of match): Searches by comparing levels with the reference image.

(6) DTECT OBJECT

"S" will be displayed for the objects to be detected.

00	01	02	03
S	×	×	×

How to set the register conditions


• How to enter the REG-COND setting screen

There are three methods for getting to the REG-COND setting screen.

 On the "MEAS CND" setting screen, move the cursor to the "6 DETECT OBJECT" and press the SET key. The cursor will move into the table. Move the cursor to the "S" column and press the SET key.

Note: If you press the SET key in the "X" column, the setting will be invalid.

- 2) On the "MEAS CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "REG COND" item and press the SET key.
- On the menu tree, move the cursor to the "MEAS CND" item, and press the right arrow key. The sub menu which contains the "REG COND" item will appear. Move the cursor to this item and press the SET key.



OBJECT TYPE COND TYPE 00 TYPE RUN COND MAGE-ADJ MEASO1(MULTI MATCHES) MEASO1(MULTI MATCHES) MEASO1(MULTI MATCHES) MEASO1(MULTI MATCHES) MEASOND MEASCND MEA	SELECT OBJECT TYPE COND	F C1 BRT
	OBJECT TYPE COND TYPE00 TYPE RUN COND MAGE-ADJ MEA-CND(CAMERA1) MEAS0 POSI-CORRECT MEAS01(MULTI MATCHES)	
	MEAS CND REG-COND EVALUATION COND T- DISTANCE&ANGLE COND NUM-CALC OUT-COND	
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP	H MEA-CND(CAMERA2) FINAL NUM. CALC FINAL OUTPUT COND OBJ-TYPE I/O	
	SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=F	OPUP

REG COND	SCREEN CO	OND SAVE	DETAIL	F C1 BRT
() REGISTER NO	. 0(0-	~3)		
2 REF-IMG AREA 3 SEARCH AREA		(224.208)	, ,	
④MATCH LVL(CO ⑤MATCH LVL	0NTR) +05 +07			
		+		 Object to measure Search area Search direct

Register a reference image

After setting the reference image area, store an image in the controller as a reference image.


Select "②REF-IMG AREA" using the up/ down arrow keys and select "REG" from the popup menu. Set the coordinates for "①UP.L" and "② LO.R." The rectangle inside the solid lines is the reference image.

MDL 0 ①UP.L ②LO.R ③MOVE ④REFERENCE	(224.208) (287.271)			
	IMG			
		-		
		Y	:224 Y:208	2

Register a reference image

After setting the reference image area, store an image in the controller as a reference image.

Select "④REFERENCE IMG" using the up/ down arrow keys and select "REG" from the popup menu.




Select a reference image

Move the cursor to the function menu on the "REG COND" screen by pressing the TRG/ BRT key. Move the cursor to "DETAIL." Press the SET key on the "REFERENCE IMG" line in the popup menu. The white square on the left will change to a black square. Then, the "2REFERENCE IMG" item will appear on the screen.

On the "②REFERENCE IMG" line, select a reference image from the reference images already registered.


Ex : 015 (000 to 026)

Select reference image No. 15 from the 26 registered reference images (000 to 026).



(4) SEARCH AREA

Specify the search area (inside the dotted lines) on the "④SEARCH AREA" line, using the same procedures used for setting the reference image area.



- (5) **DTECT COORD (detection coordinates)** Select whether to use the detection coordinates as the center of the reference area or to allow the point to be set freely.
 - CENTER: The center of the rectangular area will automatically be used for the detection coordinates.
 - SET: You can specify any position in the rectangular area to be used for the detection coordinates.

REG COND	SCREEN	I COND	SAVE	DETAIL		F C	1 BRT
① REGISTER NO ② REFERENCE II ③ REF-IMG AREA ④ SEARCH AREA ⑤ DTECT COORTI ⑥ CONTR.PIXEL ⑦ MATCH LVL(CC ⑧ MATCH LVL	MG A D		4.208)~ 6.200)~	~(287.271) ~(295.279) 41)		CENTER SET	
			+]			
SEL=WINDOW SET E	ESC=BAC	K SEL=CI	HNG IM	G TRG=FUI	NC		

Set degree of match

7 MATCH LVL (CONTR)

Specify the degree of match used for detection in the contracted images (detects contracted shapes in images whose value is larger than the specified reference value).

(8) MATCH LVL

Specify a degree of match used for detection in the original images of the contracted images that were detected in the search at line "⑦MATCH LVL" (detects original images which are larger than the specified value).

Set the evaluation conditions


• How to move to the evaluation condition setting screen

There are two methods for getting to the evaluation condition setting screen.

 Select "COND" in the upper function menu on the "MEAS COND (or REG COND)" screen and press the SET key. Select "EVALUATION" on the pop up menu to go to the "EVALUAT COND" screen.

MEAS CND S	CREEN COND	SAVE	F C1 BRT
ODTECT PRECISION (2) REGISTER NO. (3) MODE (4) MATCHING (5) DETECT ORDER		IMG PRE-F REG-CONI EVALUATIO DST&ANG NUM-CALO OUT	D DN L
REGISTER NO. (6) DTECT OBJECT	$\frac{000102030}{S \times \times \times}$	40506070809101	112131415
SET=VALUE INPUT ESC=E	ACK SEL=CHNO	IMG TRG=FUNC	

 Move the cursor to the "EVALUATION COND" item on the menu tree screen and press the SET key.



The "EVALUAT COND" (evaluation conditions) screen will appear.

⇒ For details about the evaluation conditions, see page 3-17.

EVALUAT COND SCREEN	COND SAVE EDIT	SEL	F C1 BRT
1 REGISTER NO. 2 CONDITION SET	0(0~3) AUTO(-10%)	[TEST RESULT]	[OUTPUT]
③NUMBER OF OBJ ④DTECT NUMBER	000~128 000~(0~000)	K=	NO
5 MATCH LVL	-10000~+1000	M0=	NO
6 GRAY LVL	000.0~255.0	G0=	NO
X COORD.		X0=	
Y COORD.		Y0=	
(7) TEST	EXEC(WITH-PO	SI.ADJ WITHOUT-F	POSI.ADJ)
SET=VALUE INPUT ESC=B	ACK SEL=CHNG IMC	G TRG=FUNC	

Numeric calculation setting


- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- See "Chapter 14: Numerical calculations."

Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions.

Display the measurement results

Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.




Chapter 13: Distance and Angle Measurement

13-1 Outline

You can specify the settings for distance and angle measurement on the "MEAS COND" menu in the positional deviation measurement, degree of match inspection, object identification by binary conversion (select "YES" for center of gravity measurement), multiple position measurement, and multiple degree of match inspection.

⇒ See page 4-3, 5-4, 9-5, 11-4, and 12-4.




For details about measuring the distance between two points, X coordinate distance, and Y coordinate distance manually, see the MANL-MEAS (manual measurement) section (page 2-13) for the crosshair cursor display.

13-2 Setting operation

Setting distance and angle conditions

Select "MAIN-COND" -> "OBJECT TYPE COND" (menu tree) -> "TYPE00" -> "MEA-CND (CAMERA1)" -> "MEAS (NEW)," in that order. Then press the SET key to bring up the "MEAS1" screen.



Move to the "①MEAS SELECTION" line on the "MEASUREMENT1" screen and select any of "POSI-DEVIATION," "CHK-DEG-MATCH," "LABEL-BIN-OBJ," "MULTI-POSI," or "MULTI MATCHES" from the popup menu.

⇒ For details, see "Chapter 8: Setting Examples Using the Menu Tree" in the Introduction and Hardware.

MEASUREMENT1 SCREEN COND SAVE	F (C1 DRK
①MEAS SELECTION CHK-DEG-MATCH	NO POSI-DEVIATION CHK-DEG-MATCH INSPECT-LEAD MEAS-BIN-AREA CNT-BIN-OBJ LABEL-BIN-OBJ POINT-MEAS MULTI-POSI MULTI MATCHES	

- How to display the distance and angle conditions setting screen There are two methods for displaying the distance and angle conditions setting screen.
 - On the "MEASUREMENT 1", "MEAS CND", or "REG COND" screen, press the TRG/BRG key to move the cursor to the upper function menu. Select "COND' using the left and right keys and press the SET key. Select "DST&ANGL" from the popup menu.


2) On the SELECT OBJECT TYPE COND

CND(CAMERA1)" -> "MEAS01(POSI-

DEVIATION)" -> "DISTANCE&ANGLE

screen, select "TYPE00" -> "MEA-

COND," in that order.



Setting the distance and angle conditions

(1) OBJ

Select object type you want to measure. The object types available are: "AUX" (auxiliary), "DST" (distance), and "ANGL" (angle). The setting details are different for each type.

⇒ "AUX": See page 13-4. "DST": See page 13-6. "ANGL": See page 13-7.

F C1 BRT DIST&AGL COND SCREEN COND SAVE (1)0BJ DST AUX 2 DISTANCE NO DST 00(0~15) ANGI (3) DESTANCE NO [TEST RESULT] [OUTPUT] REGISTER NO. 00010203040506070809101112131415 DISTANCE SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TRG=FUNK

(1) When "AUX" is selected.

2 AUXILIARY NO.

Enter a register number. The register numbers available are 0 to 15.

DIST&AGL COND SCREE	N COND SAVE		F C1 BRT
1 OBJ 2 AUXILIARY NO. 3 AUXILIARY 4 COND.1 5 COND.2 6 COND.3	AUX 01(0~15) CIRC-C REG NO MDL 0 REG NO MDL 0 REG NO MDL 0	NO MID-PNT CIRC-C GRAV LINE-2P INTERSECTN	
 ⑦AUX JUDGEMENT1 ⑧AUX JUDGEMENT2 ⑨RUN A TEST 		[TEST RESULT] X= Y=	[OUTPUT] NO

3 AUXILIARY

Select an auxiliary point.

Selection	Description	Measurement position	Display on the screen
NO	Do not select auxiliary point.		
MID-PNT	The center point is the coordinate half way between points 1 and 2 that are specified on (4) and (5) (COND. 1 and 2).	Point 1 (X1, Y1) + Point 2 (X2, Y2) Center point $\left(\frac{X1+X2}{2}, \frac{Y1+Y2}{2}\right)$	③ AUXILIARY MID-PNT ④ COND.1 REG NO MDL 0 ⑤ COND.2 REG NO MDL 0 ⑥ AUX JUDGEMENT1 000.0~511.0 ⑦ AUX JUDGEMENT2 000.0~479.0 ⑦ AUX JUDGEMENT2 EXEC
CIRC-C	The center of the circle is the central coordinate of three points positioned on the circumference of the circle that are specified between ④ and ⑥ (conditions 1 to 3).	Point 1 Point 2 Center of the circle Point 3	③AUXILIARY CIRC-C ④COND.1 REG NO MDL 0 ⑤COND.2 REG NO MDL 0 ⑥COND.3 REG NO MDL 0 『TEST RESULT] [OUTPUT] ⑦AUX JUDGEMENT1 000.0-511.0 X= ⑧AUX JUDGEMENT2 000.0-479.0 Y= ⑨RUN A TEST EXEC
GRAV	the center of gravity between points 1 to 3 that are specified beween ④ and ⑥ is calculated as the mean of the three coordinates (conditions 1 to 3).	Point 1 (X1, Y1) Point 2 (X2, Y2) + Point 3 (X3, Y3) Center of Gravity $\left(\frac{X1+X2+X3}{3}, \frac{Y1+Y2+Y3}{3}\right)$	③ AUXILIARY GRAV ④ COND.1 REG NO MDL 0 ⑤ COND.2 REG NO MDL 0 ⑥ COND.3 REG NO MDL 0 ⑦ AUX JUDGEMENT1 000.0-511.0 ⑧ AUX JUDGEMENT2 000.0-479.0 ⑨ RUN A TEST EXEC
LINE-2P	The line passing through two points is the line that passes through points 1 and 2 specified in items ④ and ⑤ (COND.1/2). In this system, the angle of the slope is referred to as a negative angle if it is W from the horizontal (X axis), and as a positive angle if it is CCW from the horizontal (X axis).	Slice through the Y axis (Y axis coordinate) Zero position (0, 0) 512 Point 1 Point 2 Y axis (Units used above: Pixel) Y axis Line passing through two points	③AUXILIARY LINE-2P ④COND.1 REG NO MDL 0 ⑤COND.2 REG NO MDL 0 (ITEST RESULT] [OUTPUT] AUX.1:SLOPE ANGL 000.0-511.0 d1= AUX.2:Y INDENT 000.0-479.0 Y= ⑥RUN A TEST EXEC
INTERS- ECTN	The intersection of two lines is the point where lines 1 and 2, specified in items ④ and ⑤ (COND.1/2),cross.	Line 1 Line 2 Intersection	③AUXILIARY INTERSECTN ④COND.1 AUX NO ⑤COND.2 AUX NO 『TEST RESULT] [OUTPUT] ⑥AUX JUDGEMENT1 000.0~511.0 X= NO ⑦AUX JUDGEMENT2 000.0~479.0 Y= ⑧RUN A TEST EXEC

(4) COND. 1, (5) COND. 2, (6) COND.3)

Specify conditions for the auxiliary points that were selected in the "③AUXILIARY" item.

How to enter COND.1 and COND.2.

(4)COND.1	REG NO MD	
5 COND.2	REG NO MD	L0
		Ť
	А	В

A: Enter a register number from one of the measurement programs already registered. B: Select a model: 0 or 1.

7 AUX JUDGEMENT1, 8 AUX JUDGEMENT2

Specify judgment conditions for X and Y.

[TEST RESULT]:When executing a test from the "
(9) RUN A TEST" line the result will be
displayed here.[OUTPUT]:Specify a destination for the output of test results: "NO," "Y," or "C."

(9) RUN A TEST

Press the SET key to execute a test.

(2) When "DST" is selected.


(2) DISTANCE NO.

Enter a register number. The register numbers available are 0 to 15.

DIST&AGL COND SCREE	N COND SAVE	F C1 BRT
OBJ OBJ ODISTANCE NO. ODISTANCE ODISTANCE ODISTANCE ODISTANCE EVALUAT	DST 01(0-15) DIST-BETW-2PT REG NO MDL 0 [TEST RESULT] 000.0~702.0	NO DIST-BETW-2PT DIST-BETW-X DIST-BETW-Y [OUTPUT] NO
(7) RUN A TEST	EXEC	
REGISTER NO. DISTANCE	000102030405060708091011 XXXXXXXXXXXXXXXX	$\begin{array}{c} 12131415 \\ \times \times \times \end{array}$
SET=SELECT A MENU E	SC=BACK SEL=CHNG IMG TRG=FUN	C

③ DISTANCE

Select an distance.



(4) COND. 1 (5) COND. 2

Specify conditions for the distance that were selected in the "③DISTANCE" item.

(6) DISTANCE EVALUAT

Specify judgment conditions for distance.

[TEST RESULT]: When executing a test from the "⑦RUN A TEST" line the result will be displayed here.

[OUTPUT]: Specify a destination for the output of test results: "NO," "Y," or "C."

7 RUN A TEST

Press the SET key to execute a test.

(3) When "ANGL" is selected.

(2) ANGL NO.

Enter a register number. The register numbers available are 0 to 15.

DIST&AGL COND SCREE	EN COND SAVE	F C1 BRT
 OBJ ANGL NO. ANGL COND.1 COND.2 COND.3 	ANGL 00(0-15) 3PT-ANGL REG NO MDL 0 REG NO MDL 0 REG NO MDL0 [TEST RES	NO 3PT-ANGL 2PT-H-ANGL 2PT-V-ANGL SULT] [OUTPUT]
 (7) ANGL EVALUATION (8) RUN A TEST 	-180.0~+180.0; B= ; EXEC	NO
REGISTER NO. DISTANCE		309101112131415 ×××××××

3 ANGL

Select the angle specifying method.

NO	Do not select angle.	
3PT-A- NGL	Point 1 is the point of inter section of the two lines. Relative to the line between points 1 and 2, the line between points 1 and 3 will be said to be at a positive angle if the angle is measured in a counterclockwise direction, and it will be at a negative angle if it is measured in a clockwise direction.	+Angle (~+180.0) Point 2 Point 3 Point 1 Point 1 Point 2 Point 2
2PT-H- ANGL	When a 2-point horizontal angle is specified, relative to the horizontal line, the line from point 2 that intersects point 1 will be said to at a positive angle if the angle is measured in a counterclockwise direction and at a negative angle if it is measured in a clockwise direction.	Point 2 +angle Point 1 Horizontal line
2PT-V- ANGL	When a 2-point vertical angle is specified, relative to the vertical line, the line from point 2 that intersects point 1 will be said to at a positive angle if the angle is measured in a counterclockwise direction and at a negative angle if it is measured in a clockwise direction.	Point 2 +angle Point 1

(4) COND. 1, (5) COND. 2, (6) COND.3

Specify conditions for the angle that were selected in the "③ANGL" item.

⑦ ANGL EVALUATION

Specify judgment conditions for angle.

[TEST RESULT]: When executing a test from the "⑦RUN A TEST" line the result will be displayed here.

[OUTPUT]: Specify a destination for the output of test results: "NO," "Y," or "C."

8 RUN A TEST

Press the SET key to execute a test.

Numeric calculation setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to show the popup menu. Select "NUM-CALC" from the popup menu.
- Select "NUM-CALC" on the menu tree.
- ⇒ See "Chapter 14: Numerical calculation."


Output condition setting

- Press the TRG/BRT key to move the cursor to the upper function menu, and highlight "COND" using the left and right arrow keys. Press the SET key to display the popup menu. Select "OUT" from the popup menu.
- Select "OUT-COND" on the menu tree.
- ⇒ See "Chapter 16: Setting the Input/Output Conditions."

Display the measurement results


Return to the operation screen and press the TRG/BRT key. The measurement results will be displayed on the screen.

To display the measurement results, select "COND-CHG" or "DIST&ANG COND..." on the lower menu bar and press the right arrow key. On the popup menu, select which item you want to display: "AUX," "DST," or "ANGL." Then press the SET key. On the "CHNG-REG" item, press the up and down arrow keys and the display will change.



• Example of the results displayed for a distance measurement

• Example of the displayed of angle results



Example of the displayed of auxiliary results

Measurement object	AUX
Angle of auxiliary number	00 → 00: (259.0, 178.0) OK
	01 → 01: (466.0, 178.0) OK
"	02 → 02: (361.0, 228.0) OK
"	03
"	04 → 04: (362.5, 178.0) OK
"	05
"	06 → 06:
"	07
L	

Chapter 14 Numerical Calculations

14-1 Outline

Numeric calculation function of the IV-S30J consists of "numeric calculations," which is set individually for each measurement program, and "final numeric calculations," which are set according to object type. The N00 to N15 results of the calculations which are set individually for each measuring program may be used according to the "TYPE" and "FORMULA" settings of the final numerical calculation.


14-2 The individual numerical calculations for each measuring program

How to display the numerical calculation conditions setting screen

There are two methods for displaying the numerical calculation conditions setting screen.

 Select "MAIN COND" -> "OBJECT TYPE COND" (menu tree) -> "TYPE00" -> "MEA-CND (CAMERA1)" -> "MEAS(NEW)," in that order. On the "①MEAS SELECTION" line, select any of the measurement programs. Note: When "①MEAS SELECTION" is left set to "NO," you cannot specify a numerical


calculation function.



On either the MEAS CND, or REG-COND screen, press the TRG/BRT key to move the cursor to the upper function menu. Select "COND" and then from the popup menu, select the "NUM-CALC" item.

- Note: The items shown in the popup menu will vary with the measurement program selected.
- Open the sub menu for "MEAS0" or "MEAS1" on the menu tree, and select "NUM-CALC." Then press the SET key.

 When the position deviation measurement is selected



Note

- Numeric calculation errors (deviation from the exact value) after digitizing the image Since the IV-S30J` uses 64-bit, floating-point arithmetic operations in its calculations, small quantization errors may occur when converting the images into numbers.

Setting details

The setting details and procedures for numerical calculations are the same for all measurement programs with the exception of the point measurement program. In this section we explain the use of the numerical calculations menu [NUMERIC CALC] for positional measurements.

"CHG-CALC"

Move the cursor to the "CHG-CALC" item. Each time you press the SET key the display in the left most column will alternate between "AN00 to AN07" and "AN08 to AN15."

(1) RUN A TEST

Pressing the SET key will store the setting details as well as run a test The numerical results of the tests will be displayed at position [F] and the OK or NG judgment will be displayed at position [E].

A: TYPE

Select the type of data being calculated. The details displayed for each measuring program.

⇒ See page 14-5 to 14-8.

- [NUMERIC CALC] screen on positional deviation measurement

NUMERI	NUMERIC CALC SCREEN COND SAVE F C1 BRT				
CHG-C	[N00-N07] CHG-CALC C F E D ① RUN A TEST (SET KEY)				
	TYPE FORMULA				
N00	<u>C</u> +000002				
N01	X 0X0 * N00	.0000~+0000410.0000 +0000406	.0000 ОК		
N02					
N03	CRD-X CRD-Y				
N04	DEV-x	CALC RESULT			
N05	DEV-y MATCH M	- SUM			
N06	ANGL-B NUM-CAL[NC]	AVG CBP			
N07	CNST[C]	CBM DEL			
SET=EXEC ESC=BACK SEL=CHNG IMG TRG=FUNC					

B: FORMULA

Select the formula to apply. Select formula using the left and right arrow keys and enter numerical values using the up and down arrow keys.

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Item selections	Selection on line
CRD-X, CRD-Y, DEV-x, DEV-y, MATCH M, ANGL B	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL [NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST [C]	+0000000.0000 (second line is not displayed)

⇒ For details about the items that can be selected with other measurement programs, see pages 14-5 to 14-8.

C: UPR&LOW LIMIT

Enter the upper and lower limits for making a judgment.


D: OUTPUT

Setting the output of the calculation results. Select an output target: "NO," "Y," or "C." The output can be set to Y0 to Y7 or C000 to C107.

- The number of styles may be set as follows, depending on the selections made in items A and Β.

OBJECT TYPE	Model 0	Model 1	
CRD [X Y]	00X0 to 07X0 / 00Y0 to 07Y0	00X1 to 07X1 / 00Y1 to 07Y1	
DEV [x y]	0x0 to 7x0 / 0y0 to 7y0	0x1 to 7x1 / 0y1 to 7y1	Corresponds to page 14-4.
MATCH [M]	00M0 to 07M0	00M1 to 07M1	page 14-4.
ANGL [B]	OE	B to 7B	
NUM-CAL [NC]	NUM-CAL [NC] ABS / SQRT / TAN / ATAN (00 to 14) MAX/MIN (00 to 14) MAX/MIN (00 to 14)		These are the same as for the
CNST [C]	-9999999.9999 to +9999999.9999		other measurement
The numbers from 00 to 07 in front of the characters are registration			programs.

The numbers from 00 to 07 in front of the characters are registration



An error will be output if there are too many digits as well as if there is an attempt to divide by zero.

• Order of calculation

The calculation results are produced in order, from N00 to N15.

• Parallel output based on the output conditions

It is possible to use the parallel output for the evaluation results from the calculations by selecting the PC function in the output conditions (the final output conditions are taken from the output conditions set for each measurement program)

• Types and number of styles of entered for each measurement program

The table shown below contains the numeric formulas that can be assigned in "TYPE" and "FORMULA" on the "NUMERIC CALC" screen, for each measurement program.

		Measurement program					
Input types	Symbol	Positional deviation measurement	Degree of match inspection	Lead inspection			
Degree of match	М	Model 0: 0M0 to 7M0 Model 1: 0M1 to 7M1	Model 0: 00M0 to 15M0 Model 1: 00M1 to 15M1				
Coodinate	Х	Model 0: 0X0 to 7X0 Model 1: 0X1 to 7X1	Model 0: 00X0 to 15X0 Model 1: 00X1 to 15X1				
Coodinate	Y	Model 0: 0Y0 to 7Y0 Model 1: 0Y1 to 7Y1	Model 0: 00Y0 to 15Y0 Model 1: 00Y1 to 15Y1				
Deviation	х	Model 0: 0x0 to 7x0 Model 1: 0x1 to 7x1					
Deviation	У	Model 0: 0y0 to 7y0 Model 1: 0y1 to 7y1					
Angle	В	Model 0: 0B0 to 7B0 Model 1: 0B1 to 7B1					
Light level	G		Model 0: 00G0 to 15G0 Model 1: 00G1 to 15G1				
Number of objects	К			00K to 31K			
Distance	MAX: MXD			00MXD to 15MXD			
Distance	MIN: MND			00MND to 15MND			
Lead width	MAX: MXW			00MXW to 15MXW			
Lead width	MIN: MNW			00MNW to 15MNW			
Lead length	MAX: MXL			00MXL to 15MXL			
/Lead width 2	MIN: MNL			00MNL to 15MNL			
Numeric culculation results	N	N0 to N15	N0 to N15	N0 to N15			

			Measurement program				
Input types Symbol		BGA/CSP Area measurement by binary inspection conversion		Counting quantities by binary conversion			
Total area	A	0A to 3A	Number of masks= 1: 00A to 15A Number of masks= 2: 0A to 7A Number of masks= 4: 0A to 3A	0A to 3A			
Number of objects	K	0K to 3K		0K to 3K			
Area of each label	MAX: MXR	0MXR to 3MXR					
Area or each laber	MIN: MNR	0MNR to 3MNR					
Distance between	MAX: XDX	0XDX to 3XDX					
gravity centers X	MIN: NDX	0NDX to 3NDX					
Distance between	MAX: XDY	0XDY to 3XDY					
gravity centers Y	MIN: NDY	0NDY to 3NDY					
Fallet diameter V	MAX: XFX	0XFX to 3XFX					
Fellet diameter X	MIN: NFX	0NFX to 3NFX					
	MAX: XFY	0XFY to 3XFY					
Fellet diameter Y	MIN: NFY	0NFY to 3NFY					
Numerical calculation result	N	N0 to N15	N0 to N15	N0 to N15			

		Measurement program				
Input types	Symbol	Label measurement by binary conversion	Point measurement			
Total area	А	0A to 3A				
Number of objects	К	0K to 3K				
Area of each label	R	0R000 to 0R1273R000 to 3R127				
X coordinate of gravity center	GX	0GX000 to 0GX127 3GX000 to 3GX127				
Y coordinate of gravity center	GY	0GY000 to 0GY1273GY000 to 3GY127				
Main axis angle	В	0B000 to 0B1273B000 to 3B127				
Fellet diameter X	FX	0FX000 to 0FX1273FX000 to 3FX127				
Fellet diameter Y	FY	0FY000 to 0FY1273FY000 to 3FY127				
Perimeter of each object	CR	0CR000 to 0CR1273CR000 to 3CR127				
Center point X	СХ	0CX000 to 0CX127 3CX000 to 3CX127				
Center point Y	CY	0CY000 to 0CR127 3CY000 to 3CY127				
Average light level	G		000G to 127G			
Counting white objects	WC		(Count all the objects registered)			
Number of registers	RC		(Corresponds to the whole number of registers)			
Numerical calculation results	N	N0 to N15	N0 to N15			

Input types	Input types Symbol		Measurement program		
input types	Symbol	Multiple positions measurement	Multiple degree of match inspection	angle measurements	
Number of objects	K	0K to 3K	0K to 3K		
Degree of match	М	0M000 to 3M127	0M000 to 3M127		
Coordinate	Х	0X000 to 3X127	0X000 to 3X127		
Coordinate	Y	0Y000 to 3Y127	0Y000 to 3Y127		
Density	G		0G000 to 3G127		
Auxiliary 1	H1			00H1 to 15H1	
Auxiliary 2	H2			00H2 to 15H2	
Distance	D			00D to 15D	
Angle	В			00B to 15B	
Numerical calculation result	Ν	N0 to N15	N0 to N15	N0 to N15	

[1] Display lists on the "NUMERIC CALC" screen

This section displays the "NUMERIC CALC" screen for each measuring program. The details displayed for "FORMULA" will depend on the "TYPE" selected.

(1) Positional deviation measurement

See page 14-2.

(2) Degree of match inspection

NUMER	C CALC	C SCR	EEN COND	SAVE	F C1 BRT
[N00-N CHG-(①RU		σT	(SET KEY)		
	TYPE	FOR	MULA		
N00			MATCH M CRD-X		
N01			CRD-Y LVL G		
N02			NUM-CAL[NC		
N03			CNST[C] NO		
N04					

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selection of type	Selection of formula
MATCH M CRD-X CRD-Y LVL G	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000

(3) Lead inspection

NUMERI	NUMERIEC CALC SCREEN COND SAVE F C1 BRT							
[N00-N07] CHG-CALC ①RUN A TEST (SET KEY)								
	TYPE	FORMULA						
N00	-	OBJ-K						
[]		DISTANCE MAX MXD						
N01								
N02		LEAD-WIDTH MIN MNW						
		LEAD-LENGTH MAX MXL						
N03		F LEAD-LENGTH MIN MNL F						
N04		NUM-CAL[NC]						
		CNST[C]						
N05		NO						
N06		L						

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selection of type	Selection of formula
OBJ-K DISTANCE MAX MXD/MIN MND LEAD WIDTH MAX MXW/MIN MNW LEAD-LENGTH MAX MXL/MIN MNL	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+000000,000

(4) Area measurement by binary conversion

NUMERIC CALC SCREEN COND SAVE F C1 BRT									
[N00-N CHG-C ①RUI		T	(SET KEY)						
	TYPE	FOR	MULA						
N00	-		TOTAL-AREA-A	.				 	
			NUM-CAL[NC]						
N01			CNST[C]					 	
			NO						
N02		L						 	
NU3									

Selection of type	Selection of formula
TOTAL-AREA-A	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000

(5) Object counting by binary conversion

NUMERI	UMERIC CALC SCREEN COND SAVE F C1 BRT								
CHG-([N00-N07] CHG-CALC ①RUN A TEST (SET KEY)								
	TYPE	FORMULA							
N00		TOTAL-AREA-A OBJ-K							
N01		NUM-CAL[NC]							
N02		CNST[C]							
N03									
N04									
N05									
N06									
N07									
SET=EX	EC ES	C=BACK SEL=CHNG IMG TRG=FUNC							

(6) Object identification of binary conversion

NUMERIC CALC SCREEN COND SAVE F C1 BRT									
CHG-0	[N00-N07] CHG-CALC ① RUN A TEST (SET KEY)								
	TYPE	FORMULA							
N00		TOTAL-AREA-A							
N01		OBJ-K OBJECT-AREA-R							
N02		C-GRAVS X GX							
N03		X FILLET-W FX							
N04		AX.ANGL[B] LB-CIRCUM[CR]							
N05		MID-PNT X CX MID-PNT Y CY							
N06		NUM-CAL[NC]							
N07		NO							

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selection of type	Selection of formula
TOTAL-AREA-A OBJ-K	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+000000,000

Selection of type	Selection of formula
TOTAL-AREA-A OBJ-K OBJCT-AREA-R C-GRAVS GX/GY X FILLET-W FX/FY AX.ANGL[B] LB-CIRCUM[CR] MID-PNT CX/CY	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000

(7) Point measurement

• When "BINARY" is selected on the "①MODE"

C CALC	SCREEN COND SAVE	F C1 BR	۲
CALC	T (SET KEY)		
TYPE	FORMULA		
	WHT.CNT/REG.NO[WRC]		
	NUM-CAL[NC]		
	NO		
	07] CALC N A TES	07] CALC N A TEST TYPE FORMULA	07] 2ALC N A TEST (SET KEY) TYPE FORMULA

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selection of type	Selection of formula
WHT.CNT/REG.NO[WRC]	WHT.CNT[WC], REG.NO[WRC], NUM-CAL, CNST,DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+000000,000

• When "AVG-GRAYS" is selected on the "①MODE"

NUMERI	C CALC	SCREE	N COND	SAVE		F	C1	BRT
[N00-N CHG-0 ①RU		Т	(SET KEY)					
	TYPE	FORM	JLA					
N00	-	A	VG-GRAYS	[G]]			
		0	BJ TYPES F	REG.LIST				
N01		N	UM-CAL[NC]				
		c	NST[C]					
N02		N						
			-					
N03								

Selection of type	Selection of formula
AVG-GRAYS[G]	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
WHT.CNT/REG.NO[WRC]	WHT.CNT[WC], REG.NO[WRC], NUM-CAL, CNST,DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+000000,000

(8) Multiple positional measurement

NUMERI	C CALC	SCI	REEN	COND	SA	/E			F	C1	BRT
[N00-N CHG-0 ①RU		T	(SE	ET KEY)							
	TYPE	FOF	RMULA	4							
N00	-		OBJ-ł MATO		7-		 	 	 		
N01			CRD-	Х	-		 	 	 		
N02				CAL[NC] -		 	 	 		
N03			CNST NO	[C]	-		 	 	 		
N04							 	 	 		

(9) Multiple degree of match inspection

NUMERI	C CALC	SCREEN COND S	AVE F C1 BRT				
[N00-N07] CHG-CALC ①RUN A TEST (SET KEY)							
	TYPE	FORMULA					
N00	-	OBJ-K]				
		MATCH M					
N01		LVL G					
		CRD-X					
N02		CRD-Y					
		NUM-CAL[NC]					
N03		CNST[C]					
N04							
N05			11				

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selection of type	Selection of formula
OBJ-K MATCH M CRD X/Y	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000

14

Selection of type	Selection of formula
OBJ-K MATCH M LVL G CRD X/Y	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000

(10) Distance and angle measurement

NUMER	IC CALC	SCREEN COND SA	AVE	F C1 BRT
[N00-N CHG-(①RU		T (SET KEY)		
N00	TYPE	FORMULA	7	
		ANGL[B]		
N01		AUX H1 AUX H2		
N02		NUM-CAL[NC]		
N03		CNST[C]		
N04				
N05				
N06				
N07				
SET=EX	EC ES	I C=BACK SEL=CHNG IN	IG TRG=FUNC	

Selection of type	Selection of formula
DST[D] ANGL[B] AUX[H1/H2]	OBJECT TYPE, CALC RESULT, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+000000,000

14-3 Final numerical calculations

Final numerical calculations can be set at item "FINAL NUM-CALC" on the menu tree. The setting procedure, error output settings, calculation sequence and parallel output based on the output conditions are exactly the same as those used for item "14-2 The individual numerical calculations for each measuring program."

• How to display the final numerical calculation screen.

Open the sub menu for "TYPExx" on the menu tree and select "FINAL NUM. CALC." Then press the SET key.

SELECT OBJECT TYPE COND F								
	AN00							
	AN01							
MEA-CND(CAMERA1)	AN02							
+- MEA-CND(CAMERA2) FINAL NUM.CALC	AN03							
FINAL OUTPUT COND OBJ-TYPE I/O	AN04							
OBJ-TYPE SYS.	AN05							
	AN06							
	AN07							
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP								

• Settings on the final numerical calculation screen.

The display positions of each item selected are the same as in section "14-2 The individual numerical calculation for each measurement program." ⇒ See the next page for the display details.

••	
NUMERIC CALC SCREEN COND SAVE	F C1 BRT
[N00-N07] CHG-CALC ① RUN A TEST (SET KEY)	E
TYPE FORMULA	$\backslash \backslash$
AN00 N +000002.0000	
AN01 AN 000 * N00 +0000400.0000~+0000410.0000 +000040	6.0000 ОК
AN02AB	
AN03 MEAS-CAL-RESULT[N] A-CAL-RESULT[AN] OBJECT TYPE	
AN04 NUM-CAL[NC] CNST CNST CNST[C] SUM	
AN05 NO AVG CBP	
AN06 CBM	
AN07 DEL	
SET=EXEC ESC=BACK SEL=CHNG IMG TRG=FUNC	

"CHG-CALC"

Move the cursor to the "CHG-CALC" item. Each time you press the SET key the display in the left most column will alternate between "AN00 to AN07" and "AN08 to AN15."

1 RUN A TEST

Pressing the SET key will store the setting details as well as run a test The numerical results of the tests will be displayed at position [F] and the OK or NG judgment will be displayed at position [E].

A: TYPE

Select the type of data being calculated.

B: FORMULA

A number of style settings are used. The style type is selected using the left and right keys and the numerical values are entered using the up and down keys.

The details displayed for "FORMULA" will depend on the "TYPE" selected.

Selected of type	Formula
MEAS-CAL-RESULT[N] A-CAL-RESULT[AN]	OBJECT TYPE, CNST, SUM, AVG, CBP, CBM, DEL
NUM-CAL[NC]	ABS, SQRT, TAN, ATAN, MAX, MIN, DEL
CNST[C]	+0000000,000 (second line is not displayed)

Note: When "SUM" (total) or "AVG" (average) is selected for calculating the results, specify the range from 0 to 15.

C: UPR&LOW LIMIT

Enter the upper and lower limits for making a judgment

D: OUTPUT


Setting the output of the calculation results.

Based on the settings at items "TYPE" and "FORMULA," the number of styles may be entered as follows.

OBJECT TYPE	Number of styles
MEAS-CAL-RESULT [N] (Results of the calculations for measurements)	01N00 to 01N15 (Calculation result for measurement 0, camera 1: N00 to 15) 02N00 to 02N15 (Calculation result for measurement 0, camera 2: N00 to 15) 10N00 to 10N15 (Calculation result for measurement 1: N00 to 15) 20N00 to 20N15 (Calculation result for measurement 2: N00 to 15) 30N00 to 30N15 (Calculation result for measurement 3: N00 to 15) 40N00 to 40N15 (Calculation result for measurement 4: N00 to 15)
A-CAL-RESULT [AN] (Results of final calculations)	AN00 to AN15
NUM-CAL [NC] (Numerical calculations)	ABS / SQRT / TAN / ATAN (00 to 15) MAX/MIN (00 to 15)
CNST [C] (Constant)	-9999999.99 to +9999999.99

14-4 Setting examples

The example below shows the settings used to evaluate and output the X-Y coordinates (differences) of the detection points in images 0 and 1, using the evaluation calculation. (Degree of match inspection \Rightarrow See Chapter 5: Output \Rightarrow See Chapter 15: PC Function.)



(1) Image setting

After specifying the images, return to the "MEA CND" screen for the degree of match inspection.

(2) Operations on the "MEA CND" screen

Press the TRG/BRT key to move the cursor to the upper function menu. Select "COND" and press the SET key. Select "NUM-CALC" from the popup menu and then press the SET key.


MEA CND SCREEN	COND SAVE	F C1 BRT
0	00(0~15) 1P-SCH YES	IMG PRE-PROC REG COND EVALUATION DST&ANGL NUM-CALC OUT
REGISTER NO. (©MDL 0 (?)MDL 1	0001020304050607 SXXXXXX XXXXXXX	0809101112131415 ××××××××× ××××××××

(3) Operations on the "NUMERIC CALC" screen

- 1. Select position "A" (2nd cell in the "TYPE" column) on the "N00" line using the up and down arrow keys. Select "CRD-X" from the popup menu and then press the SET key.
- Move the cursor to position "B" (2nd cell in the "FORMULA" column) and press the SET key. "00X0" will be displayed in the "FORMULA" column. Select a digit using the left and right arrow keys. Press the SET key. Then change the selected digit "01X0" by using the up and down keys.

N00	Х	01X0
		+0000000.00~+0000000.00

"01X0" is referring to the X coordinate of register number 01 (image 1) and model 0.



Press the SET key, the cursor will move to the right. Press the SET key again and a popup menu will appear. Select the "-" and press the SET key.

- The cursor will appear to the right of the "-." Press the SET key and a popup menu will appear. Select a "TYPE" and press the SET key.

 \Rightarrow 00X0 will be displayed in the formula field.

N	00	Х	01X0-00X0
			+000000.00~+000000.00

00x0 refers to the X coordinate of the detection point in model 0, stored in register NO.00 (image 0).

3. Move the cursor to the 2nd line using the up and down arrow keys and set the upper limit value using the left and right arrow keys. Then press the SET key. Then select a digit to change using the left and right arrow keys. Repeat this procedure to set the value to +160.0000 and then press the SET key.

+000000.0000~+0000160.0000

Upper limit

Move the cursor to the lower limit using the left and right keys, and press the SET key. Select a digit using the left and right keys Enter the number +140.00 using the up and down keys, and press the SET key.

+0000140.0000~+0000160.0000

Lower limit

 \Rightarrow +0000140.0000 to +0000160.0000 will be displayed in the lower and upper limit fields.

4. Move the cursor to the "N01" line and the "TYPE" column using the up/down keys.
- As described in steps 2 to 3, enter 01Y0 to 00Y0 in the formula field, and inter +0000090.0000 to +0000095.0000 in the upper and lower limit fields.

N00	Х	01X0-00X0
		+0000140.00~+0000160.00
N01	Y	01Y0-00Y0
		+0000090.00~+0000095.00

5. Move the cursor to the "①RUN A TEST" item using the up and down keys, and press the SET key.

Press the SET key once more. Then the settings will be stored, and the test will be executed. \Rightarrow The evaluation result (OK/NG) of the calculations will be displayed.

N00	X	01X0-00X0
		+0000140.00~+0000160.00 +0000147.00 OK
N01	Y	01Y0-00Y0
		+0000090.00~+0000095.00 +0000091.00 OK


OK: When the test result based on the calculations is within the specified range NG: When the test result based on the calculations is outside of the specified range

6. Press the ESC key to return to the "MEA-CND" setting screen.

(4) Operation on the "OUTPUT COND" screen

 On the "MEA CND" setting screen, press the TRG/BRT key to move the cursor to the upper function menu. Select the "COND" item and then select the "OUT" item and press the SET key.

2.	Select the "INPUT00" line and row 0. Then
	press the SET key. Select "NUM-CAL[NC]"
	from the popup menu and press the SET key.



 Move the cursor to the "LOGIC" line on the same row and press the SET key. Select "⊣⊢" from the popup menu and press the SET key.

The log	ical	condition	will be	displa	iyed i	n the	left mo	ost d	column of the LOGIC row under INPUT 0.
[PAGE0]	0	1	2	3	4	5	6	7	OUTPUT
INPUT0									
LOGIC	\dashv		—						-

- N00 refers to the N00 calculation result, that was entered on the "NUMERIC CALC" screen.

4. Select the "INPUT00" line and row 1. Then press the SET key. Set "NUM-CAL[NC]" using the same procedures as in Steps 2 and 3 above. Since "N00" will appear first, press the SET key and change "N00" to "N01," using the up/down/left/right arrow keys.
[PAGE0] 0 1 2 3 4 5 6 7 OUTPUT


PAGE0]	0	1	2	3	4	5	6	7	OUTPU
INPUT0	N00	N01							
LOGIC	$\dashv \vdash$	$\dashv\vdash$							

- 5. Move the cursor to the "OUT" row using the left and right arrow keys, and press the SET key. Select "AUX-RLY" from the popup menu and press the SET key.
- 6. A list of auxiliary relays will be displayed. Select "C000" using the up and down arrow keys and press the SET key.

⇒ The output	ut coil f	for INP	UT 0	will be	displa	yed.			AUX-RLY	Use place
[PAGE0] 0 INPUT0 N00 LOGIC ⊣⊢	1 N01 ⊣⊣				-	6	7	OUTPUT C000	C000 C001 C002 C003	MEAS1/OUTPUT COND NO NO NO
7. Press the ES	C key	to mov	e to th	ne "ME	A-CNI	D" sett	ting s	screen.	C004 C005 C006 C007	NO NO NO



1. Select "FINAL OUTPUT COND" on the "SELECT OBJECT TYPE COND" screen, to display the final output conditions screen.



SELECT OBJECT TYPE COND

 Move the cursor to "INPUT00" and row 0, and press the SET key. Select "AUX. RLY-C." from the popup menu and press the SET key.

- 3. Move the cursor to the "OUT" row using the left and right arrow keys, and press the SET key. Select "OUTPUT Y" from the popup menu and press the SET key.
- 4. Now, a list of the Y outputs will be displayed. Select "Y0" using the up and down arrow keys, and press the SET key.

 \Rightarrow The output coil for INPUT 0 will be displayed. 0 5 3 4 6 [PAGE0] 1 2 7 OUTPUT Y00 **INPUT0** C000 $\dashv \vdash$ LOGIC 5. Press the TRG/BRT key to move the cursor to the upper function menu. Then select "SCREEN" and press the SET key. Select "OPS-

MENU" from the popup menu and press the SET key. \Rightarrow Select the operation screen.

Y OUTPUT	Use place
Y0	FINAL OUTPUT COND
Y1	NO
Y2	NO
Y3	NO
Y4	NO
Y5	NO
Y6	NO
Y7	NO

(6) Degree of match inspection

Press the TRG/BRT key, and the will calculate the X-Y coordinates of the detection points in images 0 and 1, and then evaluate and output the results.

(TYPE00) F C1 BRT	
MEAS XXXXms MEASUREMENT 1 CHK-DEG-MATCH	
REGISTER N00(0~15)	
M0=+09735 OK	
X0= 090.0 OK	
Y0= 092.0 OK	
G0=_018.0OK	
MNU-CHG MAIN-COND CHG-MEA COND-CHG CHNG-REG SCREEN-CHG CHG-TYPE	
If the difference in the X and Y coordin	ates is within the <u>range</u> set on the numeric
	I, and a filled box will be displayed. If the
	vill be turned OFF, and an empty box [] will be
displayed.	
N00 N01	C000 - If the result is within the ra
Output conditions $\dashv \vdash \dashv \vdash$	- $ -$
\checkmark	(OK) the auxiliary relay C(
C000	Y00 (OIV), the advinary relay of

+

Final output conditions

- If the result is within the range, N00 and N01 will be turned ON (OK), the auxiliary relay C000 will be turned ON, and output Y00 will be turned ON.

Chapter 15: PC Function


15-1 Outline

The PC function is designed to create a ladder circuit program based on the data (coordinates, distance, degree of match, and results of numerical calculations) obtained from the measurements and calculations made by the IV-S30J. Then it outputs the results of the calculations performed by the circuit.

Use of the PC function enables the IV-S30J to output measurement results to an external equipment such as a lamp by itself, without the need for an external PC.

15-2 Operation cycle

The operation cycle of the IV-S30J is outlined below. This flowchart contains only the operations related to the PC function, and does not show communications with external devices.



[1] Power ON sequence

The parallel output terminals (Y0 to Y7) are reset, and the data memories (input relays, output relays, auxiliary relays, timer and counter) are cleared.

[2] PC scan cycle

In the PC scan cycle, the following three operations (1) to (3) are repeated cyclically.

(1) Input refresh

The ON/OFF data from the parallel input terminals (X0 to X7) is written into the data memory (input relays).

(2) Ladder circuit calculation (final output conditions)

The calculations are executed by the ladder circuit program which contains the data from input relays, output relays, auxiliary relays (incl. output which are obtained by the ladder circuit program calculation in the measurement processing cycle), timer and counter.

(3) Output refresh

The ON/OFF data of the output relays, obtained in calculation (2), is output to the parallel output terminals (Y0 to Y7).

- The processing time for the three steps described above is called "1PC scan time," and ranges from 0.3 to 3.0 ms, depending on the settings.

[3] Measurement processing cycle

When the measurement start input signal is given, the measurement processing is carried out, and the calculations of the ladder circuit program for measurements 0 to 3 are executed.


(1) Measurement processing (measurement 0 to 4)

- The coordinates, distance, and degree of match are determined by the measurement programs. If the numerical calculation conditions have been set, calculations will be executed.
- Each measurement obtained is judged to be OK or NG, based on the criteria entered by the user. If it is OK, 1 (ON) will be used as the input condition for the following calculation on the ladder circuit, and if it is NG, 0 (OFF) will be used.

(2) Ladder circuit calculation (based on output conditions for measurements 0 to 4)

- The values obtained from the measurement processing are used as the input conditions for the ladder circuit. Calculations will be executed by a ladder circuit. The output relays are the auxiliary relays that will be used for calculation by the ladder circuit in the PC scan cycle.

The relationship between the ladder circuit in the measurement processing cycle and the ladder circuit in the PC scan cycle



Notes

- 128 auxiliary relays, C000 to C127, can be set. However, identical auxiliary relay numbers cannot be used for measurement 0 using camera 1, and measurement 0 using camera 2, or for measurement 1, measurement 2, measurement 3 and measurement 4.
- The auxiliary relays C110 to C127 are special relays. The special relays are used on the PC scan cycle ladder circuit. Do not use them for the measurement processing cycle ladder circuit.

15-3 Ladder circuit program creation

[1] Procedure for creating measurement output condition and a ladder circuit


A separate ladder circuit can be created for positional deviation measurement, degree of match inspection, lead inspection, area measurement by binary conversion, object counting by binary conversion, object identification by binary conversion, point measurement, multiple position measurement, and multiple degree of match inspection.

The procedure for creating a ladder circuit for positional deviation measurement is given below. A ladder circuit can be created the same way for other measurement just change the input contact point setting.


(1) How to display the output conditions setting screen.

There are two methods for displaying the output conditions setting screen, as follows.

1. On the menu tree, open the sub menu at "MEAS01(POSI-DEVIATION)." Press the SET key on the "OUT-COND" line.




2. On the screen used for selecting the measurement program, or on the screens used for setting the measurement conditions or the register conditions, press the TRG/BRT key to move the cursor to the upper function menu. Then, move the cursor to the "COND" and press the SET key. Select "OUT" from the popup menu.




(2) How to specify the input conditions for ladder circuit diagrams


- 1. While "CHANGE INPUT" is selected, each press of the SET key will change the display in the left most row. The display will cycle through the following choices: "INPUT00 to INPUT07," "INPUT08 to INPUT15," and "INPUT16 to INPUT19." When the input group you want is displayed, press the down arrow key to move the cursor to the ladder circuit display section.
- 2. Move the cursor to a line number (INPUTxx) and a row using the up/down/left/right arrow keys, and press the SET key. Select a type to input from the popup menu.
 - ⇒ The input types for each measurement program are shown on pages 16-6 to 16-7.

Note: "00M0" means the following:



3. After selecting an input type, press the SET key and move the cursor to a logic line.





4. Press the SET key and select a logic symbol from the popup menu.

Logic symbol	Function					
	a contact on a series circuit (ON, when the evaluation result is OK)					
	b contact on a series circuit (OFF, when the evaluation result is OK)					
	Deletes a contact on the cursor. (Contacts after the deleted contact will not be brought forward.) Note: This symbol cannot be used on the first row.					
L	Used to create an OR circuit.					
	Used to create an OR circuit					
DEL	Deletes the contact on the cursor. (Contacts after the deleted contact will be brought forward.) When a contact exists only on the first row, if the contact is deleted, also the output relay will be deleted.					

(3) How to specify the output conditions for ladder circuit diagrams

Move the cursor to the "OUT" row for the desired line number and press the SET key. Press the SET key while the cursor is on "AUX-RLY" and select the auxiliary relays you want to use from the table that is displayed.

Note: Only the lines which have a specified input signal can be selected for output.

Creation example:


	0	1	2	3	4	5	6	7	OUT
INPUT00	OOMO								C000
LOGIC	- 1F -								\bigcirc

(4) Creating a ladder circuit is complete

Create a ladder circuit for the page numbers registered in step (1), repeating the operations in steps (2) and (3).

Creation example: 0 1 2 3 4 5 6 7 OUT INPUT0 00M0 C001 C000 LOGIC +++INPUT1 0X0 LOGIC $\neg \vdash - \neg$ INPUT2 N01 N02 C001 LOGIC -||-||+INPUT3 N03 N04 LOGIC

Note: Output relays cannot be used in series on a ladder circuit. Change circuit a to circuit b.



		Measurement program					
Kind of input	Symbol	Positional deviation measurement	Degree of match inspection	Lead inspection	Point measurement		
Degree of match	М		Model 0 : 00M0 to 15M0 Model 1 : 00M1 to 15M1				
Coordinate	Х	Model 0: 00X0 to 07X0 Model 1: 00X1 to 07X1	Model 0 : 00X0 to 15X0 Model 1 : 00X1 to 15X1				
Coordinate	Y		Model 0 : 00Y0 to 15Y0 Model 1 : 00Y1 to 15Y1				
Deviation	x	Model 0: 0x0 to 7x0 Model 1: 0x1 to 7x1					
Deviation	у	Model 0: 0y0 to 7y0 Model 1: 0y1 to 7y1					
Angle	В	0B to 7B					
Light level	G		Model 0 : 00G0 to 15G0 Model 1 : 00G1 to 15G1				
Number of objects	К			00K to 15K			
Distance	D			00D to 15D			
Lead width	W			00W to 15W			
Lead length / lead width 2	L			00L to 15L			
Binary point					P000 to P255		
Average light level point					P000 to P127		
Numerical calculation results	N	N0 to N15	N0 to N15	N0 to N15	N0 to N15		
Auxiliary relay	Ν	C000 to C127					

		Measurement	orogram			
Kind of input	Symbol	Area measurement by binary conversion	Object counting by binary conversion	Object identification by binary conversion		
Total area	А	Number of masks=1: 00A to 15A Number of masks=2: 0A to 7A Number of masks=4: 0A to 3A	0A to 3A	0A to 3A		
Number of objects	К		0K to 3K	0K to 3K		
Area of each label	R			0R000 to 0R127 …3R000 to 3R127		
Fillet diameter X	FX					
Fillet diameter Y	FY					
Distance between gravity centers X	DX					
Distance between gravity centers Y	DY					
Numerical calculation results	N	N0 to N15	N0 to N15	N0 to N15		
Auxiliary relay	С	C000 to C127				

Kind of input	Our mark of	Measurer	nent program		
Kind of input	Symbol	Multiple positions measurement	Multiple degree of match inspections		
Number of objects	K	0K to 3K	0K to 3K		
Numerical calculation results	N	N0 to N15	N0 to N15		
Auxiliary relay	С	C000 to C127			

Kind of input	Symbol	Distance and angle measurement *
Auxiliary	Н	00H to 15H
Distance	D	00D to 15D
Angle	В	00B to 15B
Numerical calculation results	N	N0 to N15
Auxiliary relay	С	C000 to C127

* The measurement programs that can use these inputs are the positional deviation measurement, degree of match measurement, object identification by binary conversion (center of gravity: YES) multiple positions measurement, and multiple degree of match inspections.

15

Auxiliary relay C000 to C127 The functions of the auxiliary relays (C000 to C127), which can be used for input and output signals, are explained below.

	Function
Use for input signals	Use for output signals
 Relays for internal calculation For the final output conditions, relays also used for o processing cycle can be used. 	output in the measurement
Normally OFF	
	- When C111 is ON, C000 to C109 are cleared.
 Turned ON when all of the evaluation items have been judged OK, and turned OFF if any single item has been judged NG. If C116 is not used, OK/NG will be displayed on the operation screen which correspond to ON/OFF of C112. * If an error occurs (C118 is turned ON),C112 will be turned OFF (NG). 	
	- When C113 is ON, continuous measurements will be executed. Ex.: When X0 is ON, continuous measurements will be executed. X0 C113
Output the CCD trigger status to C114, regardless of the Yes/No setting for the start of the measurement. - When "binary conversion" is specified, if the white area is 50% or more of the image, C114 will be turned ON, and if it is less than 50 %, C114 will be turned OFF. - When the "average light level" is specified, C114 will be turned ON when the image is within the specified level range, and turned OFF when it is out of the range.	
- The same signal as the READY signal is output internally.	
	 If an output signal is passed to C116, the display of the OK/NG result on the operation screen will depend on the ON/OFF state of C116. Ex.: "OK" is displayed on the operation screen when C000 is ON, and "NG" when the C000 is OFF. C000 C116 If C116 relay is not used, the display of the OK/NG result will depend on of the final evaluation result
- Turned OFF when the illumination exceeds the upper or lower warning level of the illuminance monitor set on the "MONITOR LIGHT LVL" menu. Warning light levels can be set for each of the cameras 1 and 2 separately. This relay is turned OFF when either one of them exceeds the upper or lower level.	(C112). *
 Turned ON when a measurement processing error occurs.(However, except the end code 34/35/36/3E. ⇒ See page 20-4.) 	
- Turned ON upon termination of measurement processing, and turned OFF when a measurement start input signal is given.	
- Do not use these relays for input signals.	 They are turned ON to reset counters CN0 to CN7. C120 to C127 correspond to CN0 to CN7. Create a circuit for sending an output signal to one of these relays on the row following a row that contains a counter instruction. (Counter instruction □⇒ See page 16-14.) G displayed on the operation screen □⇒ See page 1-10.
	 Relays for internal calculation For the final output conditions, relays also used for or processing cycle can be used. Normally OFF

[2] A list of the "OUTPUT COND" screen displays Shown below are the "OUTPUT COND" screen displays for each program.

(1) Positional deviation measurement

⇒ See page 15-4.

(2) Degree of match inspection

OUTPUT COND	SCREEN SAVE	F C1 BRT			
INPUT00-07 CHANGE INP	UT				
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC	0 1 2 3 4 5 6 MATCH M. CRD-X CRD-Y LVL G NUM-CAL[NC] AUX.RLY-C	7 OUT			
SET=SELECT TYPE SEC=BACK SEL=CHNG IMG TRG=FUNC					

(3) Lead inspection

OUTPUT COND	SCREEN SAVE	F C1 BRT
INPUT00-07 CHANGE INPI	т	
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC	0 1 2 3 4 5 6 → DBJ-K DST-D LEAD WIDTH W LEAD LENGTH L NUM-CAL[NC] AUX.RLY-C	7 OUT
SET=SELECT TY	PE SEC=BACK SEL=CHNG IMG TRG=FUNC	


(4) Area measurement by binary conversion


OUTPUT COND	SCREEN SAVE	F C1 BRT			
INPUT00-07 CHANGE INPU	т				
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC	0 1 2 3 4 5 6 TOTAL-AREA-A NUM-CAL[NC] AUX.RLY-C	7 OUT			
SET=SELECT TYPE SEC=BACK SEL=CHNG IMG TRG=FUNC					

(5) Object counting by binary conversion


OUTPUT COND	SCREEN SAVE	F C1 BRT
INPUT00-07 CHANGE INPU	т	
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC	0 1 2 3 4 5 6 TOTAL-AREA-A OBJ-K NUM-CAL[NC] AUX.RLY-C	7 OUT
SET=SELECT TYP	PE SEC=BACK SEL=CHNG IMG TRG=FUNC	

(7) Point measurement





(8) Multiple positional measurement




(10) Distance and angle measurement

OUTPUT COND SCR	REEN SAVE	F C1 BRT
INPUT00-07 CHANGE INPUT		
0 INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05	1 2 3 4 5 6 AUX-H DST-D ANGL-B NUM-CAL[NC] AUX.RLY-C	7 OUT


(6) Object identification by binary conversion

OUTPUT COND	SCREEN SAVE	F	C1 BRT
INPUT00-07 CHANGE INPL			
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC	0 1 2 3 4 5 6 TOTAL-AREA-A OBJ-K OBJECT-AREA-R NUM-CAL[NC] AUX.RLY-C	7	OUT
SET=SELECT TY	PE SEC=BACK SEL=CHNG IMG TRG=FUNC		

• When "AVG-GRAY" is selected in "MODE" line.



(9) Multiple degree of match inspections



[3] Procedure for creating the final output conditions in a ladder circuit

This section describes the ladder circuit creation procedures for each object type number.

(1) How to display the final output conditions setting screen

1. Select an object type from 00 to 15 on the menu tree and then move the cursor to "FINAL OUTPUT COND." Press the SET key.


SELECT OBJECT TYPE COND	F C1 BRT				
SELECT OBJECT TYPE COND OBJECT TYPE COND TYPE RUN COND MAGE-ADJ 	F C1 BRT				
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP					

2. The "OUTPUT COND" screen will appear.

OUTPUT COND	SCREE	N SAV	٧E					F C1 BRT
INPUT00-07 CHANGE INPUT O	1	2	3	4	5	6	7	OUT
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC								
SET=EXEC SEC=BACK SEL=CHNG IMG TRG=FUNC								

(2) How to specify the input conditions for ladder circuit diagrams

- 1. While "CHANGE INPUT" is selected, each press of the SET key will change the display in the left most row. The display will cycle through the following choices: "INPUT00 to INPUT07," "INPUT08 to INPUT15," "INPUT16 to INPUT23," and "INPUT24 to INPUT31." When the input group you want is displayed, press the down arrow key to move the cursor to the ladder circuit display section.
- 2. Move the cursor to a line number (INPUTxx) and a row using the up/down/left/right arrow keys, and press the SET key. Select a type to input from the popup menu.
- OUTPUT COND SCREEN SAVE F C1 BRT INPUT00-07 CHANGE INPUT Column No. 0 to 7 OUT 2 3 4 5 6 7 0 00M0 INPUT00 LOGIC -1 F INPUT01 I OGIC AUX.RLY-C INPUT02 Row No. LOGIC EXT-INP X INPUT03 TMR TM Ladder circuit LOGIC CNTR CN display area INPUT04 AN LOGIC (OUTPUT Y INPUT05 LOGIC INPUT06 LOGIC INPUT07 LOGIC SET=SELECT TYPE SEC=BACK SEL=CHNG IMG TRG=FUNC
- 3. After selecting an input type, press the SET key and move the cursor to a logic line.
- 4. Press the SET key and select a logic symbol from the popup menu.



Logic symbol	Function
	a contact on a series circuit (ON, when the evaluation result is OK)
	b contact on a series circuit (OFF, when the evaluation result is OK)
	Deletes a contact on the cursor. (Contacts after the deleted contact will not be brought forward.) Note: This symbol cannot be used on the first row.
	Used to create an OR circuit.
	Used to create an OR circuit
DEL	Deletes the contact on the cursor. (Contacts after the deleted contact will be brought forward.) When a contact exists only on the first row, if the contact is deleted, also the output relay will be deleted.

15

(3) How to specify the output conditions for ladder circuit diagrams

Move the cursor to "OUT" and press the SET key. Select a target for the output signals from the popup menu. Detail of the registration table that will appear varies, depending on the target selected for output.

When "AUX.RLY-C" is selected

When "TMR TM" is selected

OUTPUT COM	ND SCREEN	SAVE					F C1 BRT
INPUT00-07 CHANGE II	NPUT O 1	2	3	4	5	6	7 OUT
INPUT00 LOGIC INPUT01 LOGIC INPUT02 LOGIC INPUT03 LOGIC INPUT04 LOGIC INPUT05 LOGIC INPUT05 LOGIC INPUT07 LOGIC	00M0 		Use NO NO NO NO NO NO NO NO			 	OUTPUT Y AUX-RLY-C TMR TM CNTR CN DEL
SET=SELECT (DUTPUT RELAY SE	C=BAC	K SEL	=CHN	IG IM	G TRG=	=FUNC

When "CNTR CN" is selected

OUTPUT COND	SCREEN	SAVE					F C1 BRT
INPUT00-07 CHANGE INPUT INPUT00 LOGIC INPUT01 LOGIC TM INPUT02 LOGIC CM INPUT03 CM LOGIC CM INPUT04 CM LOGIC CM LOGIC CM	0 1 00M0 ⊣ ⊢ — TIME REG 10 11 12 13 14 15	2	3 Use p NO NO NO NO NO NO		5	6	F C1 BRT
INPUT06 CN			NO				
INPUT07 LOGIC							
SET=SELECT OUTP	JT RELAY SE	C=BAC	K SEL	=CHN	IG IMO	G TRG=	FUNC

Creation example:

	0	1	2	3	4	5	6	7	OUT
INPUT00	OOMO								C000
LOGIC	±L -								\bigcirc

Kind of output signal	Data memory No.	Function
External output	Y0 to Y7	Output to the parallel I/F, general purpose serial I/F and computer link.
instructions	Y8 to Y15	Output to the general purpose serial I/F or computer link
		A timer terminal will be turned ON for a set amount of time (set value 000 to 999, unit 10 ms) after the timer instruction is input. (Decrementing type) When the timer instruction input is turned OFF, the timer terminal will be turned OFF.
		[Ex.] C001 TM0 ← Timer instruction →
Timer instructions	TM0 to TM7	(2.5 sec.)
Instructions		$TM0 \longrightarrow Y00 \longrightarrow Output instruction$
		Timer terminal (external output)
		C001
		TM0 [Y00]
		While the counter reset relay is OFF, if a counter instruction input is cycled from OFF to ON, the number of times you set (set value 000 to 999), the counter terminal will be turned ON. (Decrementing type) When the counter reset relay is turned ON, the counter terminal is turned OFF. Create a circuit to turn the counter reset relay ON and OFF on the row following a row that containing a counter instruction.
Counter		[Ex.] C002 CN0 ← Counter instruction → 0003 ← Counter set value
instructions	CN0 to CN7	X5 $$ $$ $C120$ $$ Resetting the CN0
	CN0 → ⊢ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─ ─	
		X5 [C120]
		C0021 2 3 4 5 CN0
Dele	etion	The output relay on the row where the cursor is located will be deleted.


 \Rightarrow See page 16-8 for details about the auxiliary relays C000 to C127.

(4) Creating a ladder circuit is complete

Create a ladder circuit for the page numbers registered in step (1), repeating the operations in steps (2) and (3).

		·	·							!
	0	1	2	3	4	5	6	7	OUT	ĺ
INPUT0	C000 (001							Y00	
LOGIC		\mathbb{X}^{1}							\sim	
INPUT1	XO									
LOGIC										1
INPUT2	C001	X1							TMO	
LOGIC	$\dashv \vdash -$	╢┝╶							0150	
INPUT3	ТМО								Y01	
LOGIC									\square	


Note: Output relays cannot be used in series on a ladder circuit. Change circuit a to circuit b.




15-4 Program examples (shape and positional deviation inspection)

(1) Outline


The positional deviation measurement (one point search) in measurement 0 allows the degree of match and coordinates to be measured, and the result, OK or NG, is output.



(2) Output conditions and ladder circuit for measurement 0 using camera 1 When the X coordinate, Y coordinate and degree of match are within acceptable ranges, the auxiliary relay C000 is turned ON.




(3) Final output conditions and ladder circuit




15-5 Examples of a final output conditions ladder circuit


(1) Circuit for keeping the external output ON until the next external trigger is received



(2) Circuit for controlling the ON time of the external output using the timer



(3) An example of a circuit that can output a signal when the IV-S30 is operating normally.



15-6 PC monitor screen

Move the cursor to "SCREEN-CHG" on the operation screen and press the SET key. A popup menu will appear and you can select "PC-MNTR" or "PC-MNTR 2", and press the SET key. Then the PC monitor screen will be displayed.

However, before you can display this screen, you have to set "YES" on the "⑨PC-MNTR" on the "TYPE RUN COND" menu. ▷ See page 2-11.

- The ON (■) or OFF (□) status of the input relays (X00 to X07) is displayed.
- (2) The ON (■) or OFF (□) status of the output relays (Y00 to Y15) is displayed.
- (3) The ON (■) or OFF (□) status of the auxiliary relays (C000 to C127) is displayed.
- (3) The results (AN00 to AN15) of the final numerical calculations are displayed.
- (5) The current timer value is displayed.
- (6) The current counter value is displayed.
- ⑦ Menu bar

	(TYPE00)		F C1 DRK
	OK		
_	MEAS XXXXms		
<u>1</u> -	► X00~ 06	_	
2– 3–	► Y000~007	READY	
9-	► C000~007		
(4) -	► [NUMERIC CALC]	JF [TMR]	[CNTR]
<u> </u>	AN00-NOT SET	IMO.NOT SET	CN0:NOT SET
6-	AN01-NOT SET	TM1:NOT SET	
	AN02=NOT SET	TM2:NOT SET	
	AN03=NOT SET AN04=NOT SET	TM3:NOT SET TM4:NOT SET	
	AN04-NOT SET	TM4.NOT SET	
	AN06=NOT SET	TM6:NOT SET	0.10.10.02.
	AN07=NOT SET	TM7:NOT SET	CN7:NOT SET
			OPS-MAIN
			PC-MNTR 2
7	•		
	MNU-CHG MAIN-COND SEL-C	DUT SEL-AUX SEL-NUM SO	CREEN-CHG CHG-TYPE
			、 、
	Change the output	Change the Ch	ange the final
	relay address		nerical calculation
	,	address add	lress
	Telay address		

Menu bar	Description
SEL-OUT	Change the output relay address (Y00 to Y15) with the up and down keys (in units of 8 points).
SEL-AUX	Change the auxiliary relay address (C000 to C127) with the up and down keys (in units of 8 points).
SEL-NUM	Change the final numerical calculation address (AN00 to AN15) with the up and down keys (in units of 8 points).

The other data displayed is the same as on the operation screen. \Rightarrow See page 1-10.

Chapter 16: Setting the Input/Output Conditions

16-1 Outline

This section describes the input and output settings on the IV-S30J when connecting it for communication with other equipment (a personal computer or a programmable controller).

How to display the "I/O CONDITIONS" setting screen

	•	
To display the "I/O CONDITIONS" screen, select	SELECT SYSTEM COND	F C1 BRT
"MAIN COND" -> "SYS-CND" -> "I/O CONDITIONS," in that order.	SYS-CND VO CONDITIONS COMM.SET COMPUTER LINK GAIN-OFFSET	①MEAS INP I/F ②OUT I/F(PARAL.) ③MANL TYPE CHNG ④PARALLEL INP X5
		G INTOLEEEE INT NO

How to set the input and output conditions

The items you will need to set depend on whether you selected "PARALLEL+SERIAL" or "TRIG CCD START" on the "①MEAS INP I/F" line.


I/O CONDITION	SCREEN COND SAVE	F C1 BRT
①MEAS INP I/F	PARALLEL+SERIAL	\backslash
②OUT I/F(PARAL.)③MANL TYPE CHNG④PARALLEL INP X6	NO NO EXT-INP	PARALLEL+SERIAL TRIG CCD START
⑤ PARALLEL INP X7 ⑥ STROBE OUT ⑦ 'READY'ON	EXT-INP NO CAPTURE COMPLET	Έ

(5) PARALLEL INP X6 (6) STROBE OUT (7) 'READY'ON

• When you want to select the " PARALLEL +SERIAL" on the "MEAS INP I/F" line.

1 MEAS INP I/F

Select "PARALLEL+SERIAL" for the interface, in order to allow an external device to provide trigger signals for the IV-S30J.



② OUT I/F(PARAL.)

Select a signal output interface, in order to output the measured results externally. The choices are: "NO," "PC-LINK" or "SERIAL."

NO	No connection. (No output.)
PC-LINK	Connect to the parallel input on a programmable controller.
SERIAL	Connect to a standard serial port.

③ MANL TYPE CHNG

The object type can be changed manually using the remote keypad on the operation screen.

NO Means that you cannot change the object type manually on the operation screen.

YES Means that you will be allowed to change the object type manually on the operation screen. Move the cursor to the "CHG-TYPE" item on the operation screen, and select the object type No., displayed on the upper part of the screen, using the up and down keys. ⇒ See page 1-10.

④ PARALLEL INP X5

Select the type of input terminal (INPUT) X5.

EXT-INP	External input: The PC function uses the terminal as an external input signal. 与See Chapter 15.
REG REF	 When X5 is turned from OFF to ON, and gray search is selected, the reference image will be registered in the SDRAM. When edge detection is selected, the reference coordinates will also be registered. To store the reference image in flash memory Select the SAVE key on any sub menu or use a general purpose serial command. Available measurement programs (gray scale search) Positional deviation measurement, the degree of match inspections for register No. 0, model 0 Applicable measurement program (edge detection) Positional deviation measurement If a reference image has not been specified, an "UNABLE REGISTER REF.IMG" (X5 reference image register error (code3E)) will occur.
COMPARE-IMGS	On the operation screen, when parallel input X5 is turned ON, the controller will transfer a previously registered reference image into its flash memory for use in performing calculations that compare images.
AREA EVAL CORECT	 Total area evaluation correction When X5 is ON, the upper and lower limits for the total area evaluation conditions will be corrected automatically. Measurement programs: Area measurement, object counting, and object identification by binary conversion

5 PARALLEL INP X6

Select the type of input terminal (INPUT) X6.


Input/output condition	Setting details				
EXT-INP	The PC function uses the terminal as an external input signal.				
CHNG-IMG-OUT-CAM	 Every time X6 is switched from OFF to ON, the selected camera will change. ⇒ page 2-4. When the object type measurement condition is "CAMERA 1" only. "CAMERA 2" only, you are not allowed to change the camera used for output. 				
CAM-MEAS	- On starting a measurement, if X6 is OFF "CAMERA 1" will execute the measurement, and if X6 is ON Camera 2 will execute the measurement.				
2 IMAGES	 Before starting a measurement, you must set the following parameters. Measurement execution: MEASURE 0 CAMERA 1 conditions Gray scale search conditions MEASURE 1 CAMERA 2 conditions MEASURE 1 CAMERA 2 conditions Area conditions (dummy) Image selection: Camera 1 and 2 are through modes. When "2 IMAGES (overlap)" is selected, overlap processing will be executed according to the following timing. Note: Even if "2 IMAGES (overlap)" has not been selected, and regardless of which mode Camera 1 and Camera 2 are in, when a trigger (X0: Manual trigger) is received, the measurement will be executed. 				
	Camera 1 Through image				
	Overlap input X6 Freeze image				
	Monitor output Camera 2 Overlapped image				

(6) STROBE OUT

When the strobe output setting is specified as "Y*" and the shutter is opened, the output (Y*) will be turned ON. When the shutter is closed, the output will be turned OFF. Y*= Y0 to Y7

Note: When you want to use the strobe output, specify a shutter speed between 1/30 and 1/250 seconds.

Strobe output timing



\bigcirc 'READY'ON

Set the time to turn ON the READY output signal.


(When the measurement start input source is set to parallel, the object type change signal will also be parallel, and results will be output as parallel signals.)


At the end of an image capture	When the controller stops capturing the image, the READY signal turns ON.
At the end of a measurement	When the controller stops measuring, the READY signal turns ON.


• When you want to select the "TRIG CCD START" on the "MEAS INP I/F" line.

The display details and items offered for selection on line (3) will depend on the selections made on the "2)START CCD SAMPL" line.

• When "AUTO(EDGE or LEVEL)" is selected







The details of the individual items on the "I/O CONDITION" menu are the same as described on pages 16-1 to 16-3.

• When "SERIAL" is selected

When "PARALLEL" is selected


16-2 Measurement start input and result output settings The combinations of various settings for item "①MEAS INP I/F," item "②START CCD SAMPL," and item "②(③)OUT I/F (PARAL.)" on the "I/O CONDITIONS" screen (page 16-1 to 4) are explained below.

Measurement start input interface	Result output		
- Parallel	- Parallel → (1)		
_	- Computer link/paralle	el → (2)	
	General purpose serial/parallel \rightarrow (3)		
- General purpose serial	 General purpose ser 	ial/parallel → (4)	
- CCD trigger –		Object type	
	Start sampling	change	Result output
	Parallel	— (Parallel) —	⊤ Parallel → (5)
			— Computer link/parallel \rightarrow (6)
			□ General purpose serial/parallel \rightarrow (7)
	General purpose	(General purpose serial)	— General purpose serial/parallel \rightarrow (8)
	Auto —	– Parallel –	— Parallel → (9)
		General purpos <u>e</u> serial	— General purpose serial/parallel \rightarrow (10)


The time required to change object types is calculated differently according to the type of measurement start input I/O, as follows:

Measurement start input I/F	Time to change object type	
Parallel	Included in the measurement execution time	
General-purpose serial	Not included in the measurement execution time	
CCD trigger	Not included in the measurement execution time	

(1) Measurement start input = parallel, object type change = parallel, result output = parallel




- The conditions for outputting the results to the output signals Y0 to Y7 are set by the PC function. (See "Chapter 15 PC Function.")



Note: When the READY signal is turned ON, the measurement start input will be enabled. To detect the end of the measurement, you have to create a ladder circuit pointing at the Y output for auxiliary relay C119 (end of the measurement).

Custom: Final output condition




- (2) Measurement start input = parallel, object type change = parallel, result output = computer link/parallel **Setting order** $(1) (\rightarrow (2))$ Configuration example Camera 1 (image capturing) [I/O CONDITIONS] PARALLEL+SERIAL (1)MEAS INP I/F TRIG CCD START Camera 2 (image capturing) Monitor 2 OUT I/F(PARAL.) -NO PC-LINK Data Remote keypad SERIAL (Computer link) \$ % Controller Power supply Programmable (24 VDC) controller Object type change (parallel IF) External trigger X0 See page 16-5. (photo sensor or proximity sensor)
 - The data in a specified block No., set in item "⑤SET SERIAL BLOCK" on the "OBJ-TYPE I/O" screen, will be output through the computer link. ⇒See page 16-23.

Time chart	10 ms		
	or more		
Type selection			
input ⊏> See page	K		
16-5.	Specified object type nu	mber Specified object type number	
READY output (While measuring Terminate _ measurement (C119)	g or setting = L)	READY signal is turned O conclusion of the result ou	
	PPPHalt PC operation/du	uring PPPPPPPH Halt PC operation/during	
ch au	hen the object type is anged, all Y output and ixiliary relays turn OFF.	Parallel output is valid for PC control after the measurement result is determined.	
Parallel output — (Y0 to Y7)	·>	Result output	Result output
_			
Computer link ou	tput	Result output	Result output


When a Sharp PC is used, a write enable command (EWR) is transmitted from the IV-S30J to the PC in the following cases.

- When the power is applied to the IV-S30J.
- When a write mode nonconformity error (code 10(H)) occurs after a result write command (WRG) is transmitted (when the power is disconnected from the PC).
- When the output method is changed from the "OUT I/F (PARAL.)" to the "COMPUTER LINK."

(3) Measurement start input = parallel, object type change = parallel, result output = general purpose serial/parallel




- The data in a block No., set in item "⑤SET SERIAL BLOCK" on the "OBJ-TYPE I/O" screen, will be output from the IV-S30J to the personal computer.
¬> See page 16-23.




Note - Result output: The data to be sent to the personal computer will be response of general-purpose serial command (code 11_(H)).


(4) Measurement start input = general-purpose serial, object type change = general-purpose serial, result output = general-purpose serial/parallel



- See Chapter 17: Communications (General Purpose Serial Interface for details about the measurement execution commands (codes 10,11,12 and 14(H)).



(5) Measurement start input = CCD trigger, start sampling = parallel, object type change = parallel, result output = parallel




- Note 1: When the settings listed in section "16-3 CCD trigger" have not been made, a "CCD TRIG NOT SET. (error 34)" will occur.
- Note 2: Start sampling input (X0)
 - 1. Sampling will be performed while this terminal is ON. When it is turned OFF, the sampling will stop.
 - During sampling, O will flash in the upper right corner of the operation screen.
 - 2. After the measurement is terminated, the sampling will be restarted when the X0 terminal is changed from OFF to ON.

Time chart							
Measurement start input (X0)			pling by turning ON start input (X0).				- Halt CCD
CCD trigger cycle				` `			sampling by turning OFF measurement start input (X0).
Type selection input							1
See page		Specifi	ed object type number				
16-5.							
CCD trigger window	Black		White		Black		
(not highlighted))	1		1	I		1
		Trigge	er	Trigger			
READY output (While measurir	ng or setting	= L)	<i>(</i>		,		-
	is O	s valid of a me	ement result at the end – asurement				
PC calculation	P P P P P P C C C C C C	PPH CCd	alt PC operation PPP uring measurement CCC	PPPPPPHalt PC CCCCCCduring	Coperation PP measurement CC	P P P P P P P F C C C C C C C C C	
i	When the ob	oject ty	pe is changed, xiliary relays	Parallel output is control after the n result is determined	valid for PC		-
Parallel output (Y0 to Y7)	<-	/	<u>بر</u> ۲	esult output		Result output	-


16

(6) Measurement start input = CCD trigger, start sampling = parallel, object type change = parallel, result output = computer link/parallel

When the start sampling input (X0) is turned ON, the CCD trigger is enabled. (Sampling starts)



- Note 1: When the settings listed in section "16-3 CCD trigger" have not been made, a "CCD TRIG NOT SET. (error 34)" will occur.
- Note 2: Start sampling input (X0)
 - 1. Sampling will be performed while this input terminal is ON. When it is turned OFF, the sampling will stop. During sampling, O will flash in the upper right corner of the operation screen.
 - 2. After the measurement is terminated, the sampling will be restarted when the X0 terminal is changed from OFF to ON.




When a Sharp PC is used, a write enable command (EWR) is transmitted from the IV-S30J to the PC in the following cases.


- When the power is applied to the IV-S30J.
- When a write mode nonconformity error (code 10(H)) occurs after a result write command (WRG) is transmitted (when the power is disconnected from the PC).
- When the output method is changed from the "OUT I/F (PARAL.)" to the "COMPUTER LINK."

(7) Measurement start input = CCD trigger, start sampling = parallel, object type change = parallel, result output = general purpose serial/parallel

When the start sampling input (X0) is turned ON, the CCD trigger is enabled. (Sampling starts)




- Note 1: When the settings listed in section "16-3 CCD trigger" have not been made, a "CCD TRIG NOT SET. (error 34)" will occur.
- Note 2: Start sampling input (X0)
 - 1. Sampling will be performed while this input terminal is ON. When it is turned OFF, the sampling will stop.
 - During sampling, O will flash in the upper right corner of the operation screen.
 - 2. After the measurement is terminated, sampling will be restarted when the X0 terminal is changed from OFF to ON.




Note: Result output: The data in the block No., set in item "⑤SET SERIAL BLOCK" on the "OBJ-TYPE I/O" screen, will be transmitted to the personal computer. □ See page 16-23. (8) Measurement start input = CCD trigger, start sampling, object type change = general purpose serial, result output = general purpose serial/parallel

The CCD trigger is enabled after a measurement execution command is entered.




- See Chapter 17 for details about the measurement execution commands (codes 10, 11, 12 and 14(H)).
- When one of the measurement execution commands (codes 10, 11, 12 and 14_(H)) is normally received during sampling, the sampling will stop.
 - Note: When the settings listed in section "16-3 CCD trigger" have not been made, a "CCD TRIG NOT SET. (error 34)" will occur.



Time chart


Note: Result output: The data in the block No., set in item "⑤SET SERIAL BLOCK" on the "OBJ-TYPE I/O" screen, will be transmitted to the personal computer.
⇒ See page 16-23. (9) Measurement start input = CCD trigger, start sampling = auto, object type change, result output = parallel


Setting order (
①MEAS INP I/F →	PARALLEL+SERIAL Camera 1 (image capturing + CCD trigger) TRIG CCD START Image capturing + CCD trigger)
	Camera 2 (image capturing) Monitor
②START CCD SAM	
Select one of	of AUTO(LEVEL) Remote key pad
these.	PARALLEL Image: Constraint of the second s
3 OUTPUT OBJ TYP	Power supply date sampling input
	SERIAL (24 VDC) TRANSFORMENT X0 (photo sensor or
	Warning lamp proximity sensor)
	External output (Y0 to Y7) Type selection switch
	(Y0 to Y7) Type selection switch
	Measurement is started when the CCD trigger level is ON.
	Measurement is started when a CCD trigger signal is received.
	Work Black White
	CCD trigger —
	Edge
	Measurement
Time chart (wh	en auto mode (edge) is selected for as the CCD sampling start)
	Restarts CCD sampling automatically after measurement is completed.
CCD trigger	
-	
Type selection	
input ⊏> See page	Specified object type number
16-5.	
CCD trigger Black	ck White Black White Black
(not highlighted)	
	Trigger Trigger
(While measuring	
or setting = L)	
	Measurement result is valid
PC calculation PP condition CC	P Halt PC operation P </td
	When the object type is changed, all Y ~ Parallel output is valid for PC control after
(output and auxiliary relays turn OFF.
Parallel output (Y0 to Y7)	Result output



(10) Measurement start input = CCD trigger, start sampling = auto, object type change = general purpose serial, result output = general purpose serial/parallel


The general purpose serial command (code 55(H)) is used to change the object type.





Note: Result output; The data in the block No., set in item "⑤SET SERIAL BLOCK" on the "OBJ-TYPE I/O" screen, will be transmitted to the personal computer.
⇒ See page 16-23.

Time chart (when auto mode (level) is selected for as the CCD sampling start)



16-3 CCD trigger

[1] Outline

This function samples a specified part (trigger window) of an image captured by the CCD camera at a high rate, and starts the measurement when the sampled image changes. Therefore, moving objects can be measured without requiring an external trigger, such as a photo sensor.


To use this function, set the input/output the CCD trigger on the "I/O CONDITIONS" menu (pages 16-1 to 16-17), and set item "①TRIG CCD START" and item "②CCD TRIG COND" on the "OBJ-TYPE I/O" screen.

- There are four methods for starting the measurement when there is a change in a sampled image, i.e. a "BIN" (binary method), an "AVG-GRAYS" (average light level method), "GRAY-SRC" (gray search) and "EDGE DTECT" (edge detection).

Binary method	 When a sampled binary image changes (the white area exceeds 50%), the measurement is started. A change in a binary image means a change in a binary image from black (background) to white (workpiece) or from white (background) to black (workpiece). 			
Average light level method	When the average light level of a sampled image enters a specified range, the measurement is started.			
Gray search	 When the degree of match exceeds the specified value (threshold value), the measurement will start after the trigger event is detected. This is useful when workpieces have complicated shading and cannot be converted to binary or use a fixed brightness range. 			
Edge detection	Detects edge with gray search function, and the measurement is started.			

- The trigger window can be set in any position for each object type.

In the past, the position of an external sensor had to be adjusted every time the object type was changed. However, since this function eliminates the necessity of physical position adjustments, the changeover time can be reduced.



- The internal CCD trigger can be used with camera 1. (It cannot be used with camera 2.)
- An image that can be used to set the sample window conditions is obtained when the display mode is switched from the through mode to the freeze mode.

[2] Setting procedure

- How to display the setting screen
- On the menu tree, select "TYPE00" and then "OBJ-TYPE I/O," to display the OBJ-TYPE I/O screen.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND TYPE RUN COND MAGE-ADJ — MEA-CND(CAMERA1) — MEA-CND(CAMERA2) — FINAL NUM.CALC — FINAL OUTPUT COND — OBJ-TYPE I/O — OBJ-TYPE SYS. — TYPE(NEW)	

Setting methods

(1) TRIG CCD START

Select a triggering method for the CCD camera used to capture images. The choices are: "BIN," "AVG-GRAYS," "GRAY-SRC," and "EDGE DTECT." ⇒ For details, see page 16-18.

Then the "(2)CCD TRIG COND" line will appear.

(2) CCD TRIG COND

Select the trigger conditions from the sub menu on this line.

The items in the sub menu will depend on the selection made on the "①TRIG CCD START" line. Note: When "NO" was selected on the "①TRIG CCD START" line, the "②CCD TRIG

COND" line will not appear and the following line numbers will each be one less.

OBJ-TYPE I/O SCREEN SAVE F C1 BRT ① TRIG CCD START NO ② CCD TRIG COND (TO NEXT SUB-MENU) BIN AVG-GRAYS GRAY-SRC ④ SERIAL OUTPUT GRAY-SRC ⑤ CAM NO ⑥ CALIBRATION

SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TRG=FUNC

(1) When "BIN" or "AVG-GRAYS" is selected on the "①TRIG CCD START" line

Capture an image

Press the SEL key to move the cursor to the "F" position on the upper function menu. Then press the up or down arrow key to change the image mode from "T" to "F", to capture an image.

1 SIZE

Specify the size of the window used for the CCD trigger.

While "①SIZE" is selected, press the SET key. The three digits for the X-axis will be

highlighted. Change the X-axis value using the up and down arrow keys.

To change value for an individual digit, press the SET key again. The cursor will move to the left most digit. Adjust each digit using the up/down/ left/right arrow keys.

When the value is correct, press the SET key. Now all three digits will be highlighted again. Next, press the left or right arrow key to move the cursor to the next three digits for the Y-axis. Adjust this value the same way you adjusted the X-axis value. When "BIN" is selected

CCD TRIG COND SCRE	F C1 BRT	
SIZE EVALUATION SIZE EVALUATION SIZE UP.L COORD THRESHOLD VAL EINVERT B/W	Y008(4-480) × X008(4-512) MAJORITY	MAJORITY AND OR

When "AVG-GRAYS" is selected

CCD TRIG COND SCRE	EN SAVE	F C1 BRT
1 SIZE 2 UP.L COORD 3 THRESHOLD VALUE	Y008(4~480) XX008(4~512) MOVE(248.232) [U.LM255 L.LM100(0~255)] MEAS.AVG.GRA=000.0	

2 EVALUATION

Select an evaluation condition, "MAJORITY", "AND," or "OR," from the popup menu.

②EVALUATION	Description	
MAJORITY	Based on the number of pixels in an area, the controller will decide that the whole area is white if the specified percentage of pixels in that area is white. If the percentage of white pixels is less than this amount, the area will be treated as black. Specify the percentage (%), from 0 to 100% (in units of one percent) in the "③EVAL-SPEC (RATIO%)" item.	•
AND	Treat as white only when all of the pixels in an area are white.	
OR	Treat as white if one or more of the pixels in an area is white.	

③ EVAL-SPEC(RATIO %)

when "MAJORITY" is selected on the "②EVALUATION" line, enter the ratio % used to determine the color of an area.

④ UP.L COORD


Specify the upper left corner coordinates of the CCD trigger window. By changing these values, the position of the CCD trigger window will be moved.

5 THRESHOLD VAL

Specify the threshold value for binary conversion. Select this line and press the SET key. The "THRESHOLD VAL" setting screen will appear. ⇒ For details, see pages 3-10.

⑥ INVERT B/W

	Do not reverse black and white areas.
YES	The area detected by binary conversion will be displayed as white.



(2) When "GRAY-SRC" is selected on the "①TRIG CCD START" line.


- 1 REF-IMG AREA
- **2 SEARCH AREA**
- (3) DETECT CRD
- (4) CONTR. PIXEL
- ⇒ For details, see pages 5-5 to 5-7.

5 MATCH LEVEL

Specify the range for the degree of match While "⑤MATCH LEVEL" is selected, press the SET key. The five digits for the lower limit will be highlighted. Change the number using the up and down arrow keys.

To change the value of individual digits, press the SET key again. The cursor will move to the left most digit. Adjust the value of each digit using the up/down/left/right arrow keys.

When the value is correct, press the SET key. All five digits will be highlighted again.



Then, press the left or right arrow key to move the cursor to the next five digits, which are the upper limit. Adjust this number the same way.

(3) When "EDGE DTECT" is selected on the "①TRIG CCD START" line.

- (1) SEARCH AREA
- 2 DTECT MODE
- 3 SEARCH DIRECT
- (4) THRESHOLD VAL
- ⇒ For details, see pages 11-7 to 11-9.

CCD TRIG COND	SCREEN SAVE	F C1 BRT
SEARCH AREA DITECT MODE SEARCH DIRECT 4 THRESHOLD VAL	CHNĠ POINT HORIZ (→)	
SEL=WINDOW SET ESC=	BACK SEL=CHNG IMG TRG=FU	INC

16-4 Setting for serial communications

When "PARALLEL+SERIAL" (general purpose serial) has been specified in item "①MEAS INP I/F" on the "I/O CONDITIONS" menu (page 16-1), and when "SERIAL" or "PC-LINK" has been specified in item "②OUT I/F (PARAL.)" the serial communication conditions must be set on the "COMM.SET" screen.

• Set the items to match the communication conditions of the other device.


Select "MAIN COND" -> "SYS-CND" ->	SELECT SYSTEM COND	F C1 BRT
"COMM.SET," in that order.	SYS-CND - IO CONDITIONS - COMM.SET - COMPUTER LINK - GAIN-OFFSET	 COMM.STANDARD BAUDRATE(k.bps) NO. OF DATE BITS PARITY CHECK NO. OF STOP BITS STATION NO.
	SET=TO=NEXT SUB-MENU ESC=BACK SEL=CH	HNG IMG TRG=POPUP
How to set the communication settings Adjust each item to match the equipment used to communicate.	COMM.SET SCREEN COND SAVE	F C1 BRT
 COMM. STANDARD Select "RS232C," "RS422:4LINE," or "RS422:2LINE." 	②BAUDRATE(k.bps) 115.2 ③NO. OF DATE BITS 7BIT ④PARITY CHECK EVEN ⑤NO. OF STOP BITS 2BIT ⑥STATION NO. 00(0-7F) ODD	
② BAUDRATE (kbps) Set the communication speed: 2.4 Kbps, 4.8 Kbps, 9.6 Kbps, 19.2 Kbps, 38.4 Kbps, 57.6 Kbps, or 115.2 Kbps.	2BIT 1BIT	9.6 19.2 38.4 57.6 115.2
③ NO.OF DATA BITS Select either 7-bit or 8-bit.		
④ PARITY CHECK Select "EVEN," "ODD," or "NO."	SET=SELECT A MENU ESC=BACK SEL=CHNG	3 IMG TRG=FUNC

- (5) NO.OF STOP BITS Set it to 1-bit or 2-bits.
- **(6)** STATION NO.

Select the station number for communication using the up and down arrow keys.

16-5 Computer link

When "PC-LINK" has been specified in item "②OUT I/F (PARAL.)" on the "I/O CONDITIONS" screen (page 16-1), the computer link conditions must be set on the "COMPUTER LINK" screen.



See "Chapter 18: Computer Link" for applicable models made by these manufacturers. Note 1: Use an even address as the write start address.

Note 2: When 512 bytes are used for a write register on a Sharp model, select a write start address from the following addresses.

09000, 19000, 29000, 39000, 49000, 59000, 69000, 79000, 89000 , 99000

16-6 Output block assignment (Computer link output and general purpose serial output)

When measurement is controlled by a computer link or a communication interface (general purpose serial IF: * 1), in addition to other block 0, blocks can be specified whose measurement data will be output from the IV-S30J to a programmable controller or a personal computer.


* 1 In the case of a communication interface (general purpose serial IF), output blocks can be specified only when the measurement is started by a CCD trigger or a parallel IF signal and the results are set by a general purpose serial IF signal. ⇒ See page 17-3. Specify the settings above on the "OBJ-TYPE I/O" screen ⇒ See the next page.

[1] Data in specified blocks

(1) In the case of a computer link

Data in the specified blocks will be output after the data (block 0) from measurement numbers 0 to 4 is output by the write register of the PC. (See page 18-3.)

Write register map



- * 3 The top address to which the data in the specified blocks will be written is obtained by adding 512 bytes to the result top write address.

- Setting examples for various manufacturers

	Sharp		Mitsubishi	OMRON
Result top write address	09000	09300	D0000	DM0000
Top address of data in specified blocks	19000	19300	D0256	DM0256

(2) When the measurement is started by a CCD trigger or a parallel I/F signal and the results are output by a general purpose serial I/F signal

When the IV-S30J responds, data in a specified block is output after the output data (block 0) from the measurement No. 0 to 4, in response to the measurement run command 2 (processing code 11(H)).

1 Response Object Output evaluation Measurement 0 leasurement leasurement leasurement leasurement results type : 1 1 RCIRC Camera 1 Camera 2 Y0¦Y1¦ Y15 $(H)_{i}^{l}(L)$ Measurement 0 Data from Data from Data from Data from Data in the SC SC CR Camera 2 data 2 measurement 1 measurement 2 measurement 3 measurement 4 specified Camera 1 data (2) data (2) data (2) data (2) block (H)¦(L) data (2)

 \Rightarrow See page 17-7 for details about (1) and (2).

Note: The response returned by the measurement run command 2 (processing code 11(H)) will not contain the specified block.

[2] Setting (operating) procedure

Setting (operating) procedure

 Select "MAIN COND" -> "OBJECT TYPE COND" -> "TYPE00" -> "OBJ-TYPE I/O" in that order.

SELECT OBJECT TYPE COND	F C1 BRT			
OBJECT TYPE COND	(1) TRIG CCD START (2) CCD TRIG COND (3) SHUTTER SPEED (4) SERIAL OUTPUT (5) SET SERIAL BLOCK (6) CAM NO (7) CALIBRATION (8) CALIBRATION			
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TRG=POPUP				

2. The "OBJ-TYPE I/O" screen will appear. Move the cursor to "③SERIAL OUTPUT" and press the SET key. A popup menu will appear. Select "BLOCK-ASSIGN" and press the SET key.

OBJ-TYPE I/O SCREEN	SAVE	F C1 BRT
(1) TRIG CCD START	NO	
②SHUTTER SPEED ③SERIAL OUTPUT	1/00060(1/30-1/10000) BLOCK-ASSIGN BLOCK00 MEAS0 CAM1 1(1-2) NO	ANY BLOCK-ASSIGN
SET=SELECT A MENU ES	SC=BACK SEL=CHNG IMG TF	RG=FUNC

- 3. The "④SET SERIAL BLOCK" line will appear. Select this line and press the SET key. Enter the block No., measurement No. and camera No. of the measurement data to be output, using the left, right, up and down keys.
 - Specify a block number to be returned in addition to block 0 (00). If block 00 is specified, data from block 00 will not be returned a second time. After the settings are complete, press the SET key.

OBJ-TYPE I/O SCREEN	SAVE	F	C1 BRT
(1) TRIG CCD START	NO		
SHUTTER SPEED SERIAL OUTPUT SET SERIAL BLOCK SCAM NO CALIBRATION	1/00060(1/30-1/10000) BLOCK-ASSIGN BLOCK00 MEAS0 CAM1 1(1-2) NO		
SET=SELECT A MENU ES	C=BACK SEL=CHNG IMG TRG=FUNC		

16-7 Setting the data output

When you communicate with the IV-S30J using a computer link or a serial communication interface (general purpose serial IF) in the following conditions, perform steps (1) and (2) below to enable serial output.

- Computer link: When outputting any data \Rightarrow Pages 18-16.
- Communication interface (general purpose serial IF): When executing a measurement run command 4 (processing code 14(H)) => Pages 17-8 and 17-10.

[1] Select "ANY" for the serial output

Select "ANY" in the "③SERIAL OUTPUT" item on the "OBJECT TYPE I/O" menu.

Setting (operating) procedure

1. Select "MAIN COND" -> "OBJECT TYPE COND" -> "TYPE00" -> "OBJ-TYPE I/O" in that order.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND TYPE RUN COND MAGE-ADJ MAGE-ADJ MEA-CND(CAMERA1) FINAL NUM.CALC FINAL OUTPUT COND OBJ-TYPE I/O OBJ-TYPE SYS. TYPE(NEW)	1 TRIG CCD START 2 CCD TRIG COND 3 SHUTTER SPEED 4 SERIAL OUTPUT 5 SET SERIAL BLOCK 6 CAM NO 7 CALIBRATION 8 CALIBRATION
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG	GIMG TRG=POPUP

2. The "OBJ-TYPE I/O" screen will appear. Move the cursor to "③SERIAL OUTPUT" and press the SET key. A popup menu will appear. Select "ANY" and press the SET key.

OBJ-TYPE I/O SCREEN	SAVE	F C1 BRT			
(1) TRIG CCD START	NO				
②SHUTTER SPEED ③SERIAL OUTPUT	1/00060(1/30~1/10000) ANY	ANY			
(4) CAM NO (5) CALIBRATION	1(1~2) NO	BLOCK-ASSIGN			
SET=SELECT A MENU ESC=BACK SEL=CHNG IMG TRG=FUNC					

[2] Select "YES" or "NO" for output data

Select "YES" or "NO" on the following menu screens that are displayed as "locked" screens to output serial data. See the next page for instructions about how to lock the screen.

On any condition setting screen, press the TRG/BRT key and the cursor will move to the upper function menu. Select "SCREEN" and press the SET key. A popup menu will appear. Select "SERIAL OUTPUT" and press the SET key.

- The "EVALUATION COND" screen for individual measurement program


EVALUAT COND SCREEN	SAVE		F C1 BRT
	[SERIAL	OUTPUT]	
①X COORD(MDL0)	NO	NO	
(2) Y COORD(MDL0)	NO	YES	
③x DEVIATE(MDL0)	NO		
④y DEVIATE(MDL0)	NO		
(5) MATCH LVL(MDL0)	NO		
6 ANGULAR DEVIATE	NO		
⑦X COORD(MD1)	NO		
(8)Y COORD(MDL1)	NO		
(9)x DEVIATE(MDL1)	NO		
10y DEVIATE(MDL1)	NO		
1 MATCH LVL(MDL1)	NO		
SEL=VALUE INPUT ESC=BAG	CK SEL=CH	NG IMG TRG=FUNC	
L			

- The "NUMERIC CALC" or "FINAL NUM. CALC" screen for individual measurement program

NUMERIC CALC SCRREN	SAVE	F C1 BRT
	[SERIAL OUTPUT]	
(1)OUTPUT	NO	
() A / b a m th a m	un artical calculation as	ا مانانه م
•	umerical calculation co	nation
menu is disp	layed)	

(When measuring positional deviation)

- The "DIST&AGL COND" screen



- When the serial output setting is "NO," no data (block 0) will be output (the space will be filled by the next item).


(To measure an object's "distance" on the distance and angle condition menu)

16-8 Calibrating the IV-S30J

The IV-S30J calibration can be adjusted, e.g. "1 pixel = 1 mm", and the data can be displayed as actual dimensions.

• How to display the CALIBRATION setting screen

1) Select "MAIN COND" and then "OBJECT TYPE COND."



F C1 BRT

2) On the "OBJECT TYPE COND" screen, move the cursor to any "TYPExx" that you want to calibrate, and press the SET key.

SELECT OBJECT TYPE COND

OBJECT TYPE COND

 Move the cursor to the "OBJ-TYPE I/O" line and press the SET key.

TYPE RUN COND IMAGE-ADJ IMAGE-A
--

4) On the "OBJ-TYPE I/O" setting screen, move the cursor to the "⑦CALIBRATION" line and press the SET key twice, to bring up the submenu.

Note: Depending on settings for the "①TRIG CCD START" and "④SERIAL OUTPUT" items, the number of the "CALIBRATION" line will vary between ⑥ and ⑧.


5) Set the calibration details on the "CALIBRATION" setting screen. Put a ruler in the camera's field of view.

OBJ-TYPE I/O SCREEN	SAVE	F C1 BRT
1 TRIG CCD START 2 CCD TRIG COND 3 SHUTTER SPEED 4 SERIAL OUTPUT 5 SET SERIAL BLOCK 6 CAM NO 7 CALIBRATION 8 CALIBRATION	BIN (TO NEXT SUB-MENU) 1/00060(1/30~1/10000) BLOCK-ASSIGN BLOCK00 MEAS0 CAM1 1(1~2) MANUAL (TO NEXT SUB-MENU)	NO MANUAL EDGE DTECT

CALIBRATION SCREEN	SAVE	F C1 BRT
1) CURSOR1-COORD (2) CURSOR2-COORD (3) SCALE (4) SCALE(UNIT) (5) REG 1PIXEL 1mm	SET (256.240) SET (256.240) 000.00 mm EXEC CBP 000.0000 mm CBM 000.0000 PIXEL	

• When "MANUAL" is selected on the "CALIBRATION" line

1. Move the cursor to "①CURSOR1-COORD" and press the SET key.



- 4. Select the "③SCALE" line and enter the actual value of the distance between coordinates 1 and 2. In this example, the distance is 10 mm. Therefore, enter "10."
- 5. Select the "④SCALE(UNIT)" line and select the unit of distance between coordinates 1 and 2. In this example, select "mm."
- 6. Select the "⑤REG" (register) line and while the cursor is on "EXEC" (execute) press the SET key again. The controller will be calibrated to read "1 pixel = 1 mm."

 Setting the register conditions for edge detection

1 SEARCH AREA

Select "①SEARCH AREA (MDL0)" and press the SET key to go to the setting screen.

(2) DTECT MODE

Select an image processing method for the edges.


3 SEARCH DIR


Specify a search direction. \Rightarrow For details, see page 4-8.

④ THRESHOLD

Specify a threshold value for binary conversion.

 \Rightarrow For details, see page 3-11.





Automatic setting

Select "AUTO-REG" from the upper function menu on the THRESHOLD setting screen. The controller will set the optimum value automatically.

(5) REF COORD (reference coordinates)

You can change the reference coordinates to any desired position.

(1) SCALE

Enter the actual value of the distance between coordinates 1 and 2. In this example, the distance is 10 mm. Therefore, enter "10."

(2) SCALE (UNIT)

Select unit of distance between coordinates 1 and 2. In this example, select "mm."

(13) REG (register)

While the cursor is on "EXEC" (execute) press the SET key again. The controller will be calibrated to treat 1 pixel = 1 mm.

- 6) Using the CBP value that was set in the calibration function, you can execute numeric calculations.
 - 1. Press the ESC key twice to show the menu tree. Select the "NUM-CALC" line for the same object type and measurement number, and press the SET key.

SELECT OBJECT TYPE COND	F C1 BRT
OBJECT TYPE COND	
☐ TYPE00 ↓ ↓ TYPE RUN COND	N00
IMAGE-ADJ	N01
MEAS0	N02
MEAS01(POSI-DEVIATION)	N03
IMG PRE-PROC	N04
EVALUATION COND	N05
	N06
MEAS(NEW)	N07
FINAL NUM.CALC	
SET=TO NEXT SUB-MENU ESC=BACK SEL=CHNG IMG TR	G=POPUP

2. Relay numbers N00 to N07 are displayed on the first screen. To display relay numbers N08 to N15, press the SET key while the cursor is on the "CHG-CALC" item.

NUME	RIC CAI	LC SCREEN	COND	SAVE		F	C1	BRT
[NO	8-N15】							
CHG-CALC								
①RUN A TEST (SET KEY)								
	TYPE	FORMULA						
N00								
N01								
N12								
N03								
N04								
N05								
N06								
N07								
SET=EXEC ESC=BACK SEL=CHNG IMG TRG=FUNC								

3. On the "NUMERIC CALC" screen, use the up and down arrow keys to move the cursor to a cell in the "TYPE" column on the desired relay number line. Press the SET key. A popup menu will appear and you can select the calculation result you want to output. In this example, select "DEV -x" (deviation on the X-axis)

NUMERIC CA	ALC SCREEN COND SAVE	F C1 BRT
[N00-N07]		
CHG-CALC		
①RUN A TI	EST (SET KEY)	
TYPE	FORMULA	
N00	CRD-X	
NOA	CRD-Y	
N01	DEV-x	
N12	DEV-y	
	ANGL-B	
N03		
	CNST [C]	
N04	NO	
1105		
N05		
N06		
N07		
SET=SELECT	TYPE ESC=BACK SEL=CHNG IMG TRG=F	UNC

4. Next, move the cursor to the "FORMULA" column and press the SET key. Another popup menu will appear allowing you to select the type of formula you want to use for calculations. In this case, select "CBP."

0-N07】			
CALC	٩T	(SET KEV)	
		OBJECT TYPE	7
		CNST	
		AVG	
		CBM	
		1	
	IN A TE TYPE 	IN A TEST TYPE FORMULA 	TYPE FORMULA OBJECT TYPE CALC RESULT CNST SUM AVG CBP

5. After completing these settings, deviation on X-axis will be output as a CBP value (in unit of mm).

Chapter 17: Communication (General Purpose Serial Interface)

The IV-S30J can communicate with a personal computer that transmits commands and receives responses to measurement execution commands.

17-1 List of processing functions

The following functions can be used for communication between the IV-S30J and a personal computer (using the general-purpose serial interface).

Cate- gory	Processing description	Code	Functions
t t	Measurement execution function 1	10	 Executes all measurement programs for a specified object type. (You can make measurements by specifying a camera.) Outputs the ladder results (Y0 to 15).
asuremen	Measurement execution function 2	11	 Executes all measurement programs for a specified object type. (You can make measurements by specifying a camera.) Outputs the ladder results (Y0 to 15) and the measurement data in block 0 for each measurement program.
Executing measurement	Measurement execution function 3	12	 Executes all measurement programs for a specified object type. (You can make measurements by specifying a camera.) Outputs the ladder results (Y0 to 15) and the measurement result from a specified block for a specified measurement number.
	Measurement execution function 4	14	 Executes all measurement programs for a specified object type. (You can make measurements by specifying a camera.) Outputs any numerical data selected by the IV-S30J.
	Measurement data reading 1	20	Reads the result of the last measurement - Outputs the ladder results (Y0 to 15).
	Measurement data reading 2	21	 Reads the result of the last measurement Outputs the ladder results (Y0 to 15) and the measurement data in block 0 for each measurement program.
Reading result	Measurement data reading 3	22	Reads the result of the last measurement - Outputs the ladder results (Y0 to 15) and the measurement result from a specified block for a specified measurement number.
Read	Measurement data reading 4	24	 Reads the results of the last measurement from a specified measurement code. Outputs any numerical data selected by the IV-S30J.
	Illumination reading	28	 Reads the amount of illumination measured by the lighting monitor function, and the evaluation result.
	Corrected light level reading	29	 Reads the corrected light level measured by the lighting monitor function, evaluation result and preset reference density.

Shown below is the relationship of each selection when code 10 to 14 are specified is shown below. The conditions below are what is shown when the "PARALLEL+SERIAL" is selected on the " \bigcirc MEAS INP I/F" on the "I/O CONDITIONS" selection screen.

MeasurementOutputstartselection		Serial output	Object type change	
General purpose serial port		Command codes 10 to 12	Command codes 10 to 12	
	None		Parallel	
Parallel port	Computer link	SHARP/MITSUBISHI/ OMRON/YOKOGAWA	Parallel	
	General-purpose serial	Response output from command codes 11	Parallel	

The conditions below are what is shown when the "TRIG CCD START" is selected on the "①MEAS
INP I/F" on the "I/O CONDITIONS" selection screen.

Measurement start	Output selection	Serial output	Object type change
	Parallel port		Parallel
Auto	General purpose serial port	Response output from command codes 11	Command codes 55
	None		Parallel
Parallel port	Computer link	SHARP/MITSUBISHI/ OMRON/YOKOGAWA	Parallel
	General-purpose serial port	Response output from command codes 11	Parallel
General-purpose serial port		Command codes 10 to 12	Command codes 10 to 12


Cate- gory	Processing function		Code	Function
	Operation lock	Read	50	- Read lock/unlock condition of the operation screen.
	status	Set	51	 Set lock/unlock for the operation screen.
	English or	Read	52	- Read the status from the English or Japanese display.
	Japanese display	Set	53	- Enter a change on the English or Japanese display.
	Object type	Read	54	 Read an object type number to measure when the measurement start input is turned ON.
	number	Set	55	 Assign an object type number to be executed when the measurement start input is turned ON.
tions	Image status	Read	56	 Read the image status being monitored (Output: Through/freeze, Brightness: Full/half).
condi	inage status	Set	57	 Change the status of the image being monitored (Output: Through/freeze, Brightness: Full/half).
Individual conditions	Output image	Read	58	 Read the status of the camera outputting an image for the specified object type.
Indivi	camera	Set	59	 Set the status of the camera that is outputting an image for the specified object type.
	Shutter speed	Read	5A	 Read the shutter speed setting for the specified object type.
		Set	5B	 Set shutter speed for the specified object type.
	Register a reference image Assign		5E	 Measurement program: Registers reference images for the specified object type and measurement number (register No. 0 only). Image calculation: Registers reference images used for image calculations of the specified object type.
Initializ	Initialize all		60	 Set all settable conditions to their initial values (global conditions, all object type conditions, and reference images).
Self-dia	Self-diagnostic		68	 Check the controller for a hardware error. Items to check: VRAM (read after write), SDRAM (read after write), etc.
Reset			69	- Reset the controller (the same as a power reset operation).
	I measurement	Read	70	- Read the coordinates detected by manual measurement.
coordir	nates	Set	71	- Set the coordinates for manual measurement.

17-2 Data flow

The data flow between the IV-S30J and a personal computer is shown below.


[1] Measurement execution 1: Command codes 10, 11, or 12

Select the measurement start input source = general purpose serial and parallel port




[2] Measurement execution 2: Response processing for command 11 Select the measurement start method = CCD trigger, parallel or serial output = general purpose serial

Note: When a CCD trigger is chosen as the measurement start input, the sample start must be set to parallel or auto.




- You can specify the response block on the "OBJECT TYPE I/O" screen \Rightarrow see page 16-23.
- Select the measurement start method = CCD trigger, start sampling & output results = general purpose serial



[3] Measurement execution 3: Command 14

• Select measurement start input source = general purpose serial and parallel port

- **[Procedure]** (1) Send packet number $0 \rightarrow After$ measuring, send back the measurement code for the first register and any specified data.
 - (2) Send the other packets, starting from number $1 \rightarrow$
 - Send back the measurement code for the next register and any specified data.
 - When there are no more measurement registers, send back the end code "F."




[(Response) measurement code]

Measurement code	Setting	Measurement code	Setting
0	MEASURE 0 CAMERA 1	5	MEASUREMENT 4
1	MEASURE 0 CAMERA 2	6	Distance and angle measurement
2	MEASUREMENT 1	7	Numerical calculation
3	MEASUREMENT 2	F	Quit
4	MEASUREMENT 3		


[4] Processing other than measurement execution processing

- Operation screen: Any command can be processed, regardless of the measurement I/O settings (measurement start, result output).
- Setting screens: Reading/writing a display image (commands 30, 31) and reading a binary image (command 34) are available.



17-3 Communication format

The communication formats of the commands and responses between the IV-S30J and a personal computer are outlined below.



*1 Station No.: 00 to 7F(H)


- *2 Processing code and text
 - They depend on the contents of communication. I See pages 17-1 and 17-7 and after.
 - On abnormal termination, no text is provided.
- *3 Termination code(H)
 - The termination code is a 2-digit hexadecimal number.
 - When an output is sent through the general purpose serial I/F, 00(H) is sent on normal termination.
- On abnormal termination, a code other than $00_{(H)}$ is sent. r > See page 19-3.
- *4 Checksum code (SCH and SCL)

To improve the reliability of the transmitted data, in addition to a parity check, error detection by a checksum is used for error detection.

When the IV-S30J does not need to complete a checksum for error detection, use an @ (at sign: ASCII code $40_{(H)}$) in each of the checksum codes SC_H and SC_L included in the command.

[Error detection using a checksum]


The ASCII code for each data byte, from the processing code to the end of text (prior to the checksum code), is added. The final value is compared to the checksum code which is treated the same way. If the two values are identical, the command is considered to be valid. I/F they are not identical, an error has occurred during transmission.



[Method for creating a checksum code]

The ASCII code for each byte of data, from the processing code to the end of text (prior to the checksum code) is added together. The lower 1 byte of this sum is divided into the upper 4 bits and the lower 4 bits. The hex character (0 to F) is converted to the ASCII code for that character and sent as one byte. Thus the checksum code consists of two bytes.

- Ex. 1 Command for the measurement execution function 1 (code 10(H))
- Ex. 2 Command for the measurement execution function 7 (code 1A_(H))



Note

- This manual uses the following notation to represent addresses and set values.								
Octal number(8)	Ex. 377 ₍₈₎							
Decimal numberNone	Ex. 255							
Hexadecimal number (H)	Ex. FF(H)							

17-4 Processing functions

[1] Measurement execution functions

(1) Measurement execution function 1: code 10(H)

This command will cause the IV-S30J to execute all of the measurement programs for a specified object type. (You can specify the camera to use for measurements.)

The results in the ladder outputs (Y00 to 15) will be sent back as the response.

On page 17-1 you can see how each command affects the various inputs and outputs.

:	Station No.	1	0	Object type	Execution camera	SC'S (H)¦(I	C CR
---	----------------	---	---	----------------	---------------------	----------------	------

Response

_		Station	T			Obiect	u	Final output		
	:	No.	1	0	RC¦RC (H)¦(L)	type	Executic camera	evaluation res	SC¦SC (H)¦(L)	CR

- Object type \rightarrow Object type to measure: 00 to 3F
- Execution camera number \rightarrow 0: Both cameras 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK
- Data flow ⇒ See page 17-3.


(2) Measurement execution function 2: code 11(H)

This command will cause the IV-S30J to execute all of the measurement programs for a specified object type. (You can specify the camera to use for measurements.)

The results in the ladder outputs (Y00 to 15) and the measurement data in block 0 of each measurement will be sent back as the response.

On page 17-1 you can see how each command affects the various inputs and outputs.

Command



Response

Response			Maggiura	<u> </u>		
: Station No. 1 1 RC RC (H) (L)	e type Camera Camera	Final output evaluation result D ['] Y1 ['] ···· ['] Y15	Camera 1 Camera 1 Camera 2 Camera 2	Measure- ment 1 Measure- ment 2 Moscure-	ment 3 Measure- ment 4	_

	ement 0			Data on				
Camera 1 data 2	Camera 2 data ②	measure- ment 1 ②	measure- ment 2 ②	measure- ment 3 ②	measure- ment 4 (2)	SC (H)	SC (L)	CR

1

- Object type \rightarrow Object type to measure: 00 to 3F
- Execution camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final Output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK
- (1) \rightarrow Measurement programs 0 to 4
 - 0 = none, 1 = positional deviation measurement, 2 = degree of match inspection,
 - 3 = lead inspection, 5 = area measurement by binary conversion,
 - 6 = object counting by binary conversion, 7 = object identification by binary conversion,
 - 8 = point measurement, 9 = multiple positions measurement, A = multiple degree of- inspections

- $(2) \rightarrow$ Measurement data

Only the data in block 0 of a measurement program is output. (For details about the data arrangement in a block, see the section "Measurement data blocks" in Chapter 18, "Computer link.")

- Data flow 🖒 See page 17-3.

(3) Measurement execution function 3 : code 12(H)

This command will cause the IV-S30J to execute all of the measurement programs for a specified object type. (You can specify the camera to use for measurements.)

The results in the ladder outputs (Y00 to 15) and the results from a specified block in a specified measurement will be sent back as the response.

On page 17-1 you can see how each command affects the various inputs and outputs.

Command

Statio	-	2	Object type	Execution camera	Measure- ment	Block No.	SC ¹ SC (H) ¹ (L)	CR
--------	---	---	----------------	---------------------	------------------	--------------	--	----

 Measurement Number → A measurement number that outputs numerical data (MEASURE 0 CAMERA 1: 0, MEASURE 0 CAMERA 2: 1, and MEASUREMENT 1 to 4: 2 to 5)
 Block → Specified block from which the data of a

specified measurement function will be output.

Response

	ponoo							•		
	Station No.¦	1	2	RC ¹ RC (H) ¹ (L)	Object type	ra Iti	Final Output evaluation result Y0'Y1' ···· 'Y15	Specified block data	SC'SC (H) (L)	CR

- Object type \rightarrow Object type to measure: 00 to 3F

- Execution camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK
- $(1) \rightarrow$ Specified block data (For details about the data arrangement in a block, see the section

"Measurement data blocks" in Chapter 18, "Computer link.")

- Data flow ⊨> See page 17-3.

(4) Measurement execution function 4: code 14(H)


This command will cause the IV-S30J to execute all of the measurement programs for a specified object type. (You can specify the camera to use for measurements.)

Any numerical data selected by the IV-S30J can be output as the response.

⇒ See page 16-26.

On page 17-1 you can see how each command affects the various inputs and outputs.

Command



- $(1) \rightarrow 0$: Execute/read, 1: Read

- Object type \rightarrow Object type to measure: 00 to 3F
- Execution camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Measurement code (response)

Measurement code	Setting	Measurement code	Setting
0	MEASURE 0 CAMERA 1	5	MEASUREMENT 4
1	MEASURE 0 CAMERA 2	6	Distance and angle measurement
2	MEASUREMENT 1	7	Numerical calculation
3	MEASUREMENT 2	F	Quit
4	MEASUREMENT 3		

- Specifications for any output data \Rightarrow See page 17-16.

- Data flow rightarrow See page 17-3.


[2] Result reading

Data from the last measurement is read. (No instruction is sent to execute an operation.) For details about the measurement data blocks, see the section "Measurement data blocks" in "Chapter 18: Computer link."

(1) Measurement data reading function 1: code 20(H)

This command will cause the IV-S30J to read the results of the last measurement. The results in the ladder outputs (Y00 to 15) will be sent back as the response. This command is effective regardless of the measurement input specified.

Command



Response

	:	Station No.	2 0	RC ¹ RC	Object type	ecutic	Final output evaluation res		SC¦SC	CR
--	---	----------------	-----	--------------------	----------------	--------	--------------------------------	--	-------	----

- Object type \rightarrow Object type for which the measurement was executed: 00 to 3F


- Executed camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK

(2) Measurement data reading function 2: code 21(H)

This command will cause the IV-S30J to read the results of the last measurement. The results in the ladder outputs (Y00 to 15) and the measurement data in block 0 of each measurement will be sent back as the response.

This command is effective regardless of the measurement input specified.

Command



- Object type \rightarrow Object type for which the measurement was executed: 00 to 3F

- Executed camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final Output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK
- (1) \rightarrow Measurement programs 0 to 4

0 = none, 1 = positional deviation measurement, 2 = degree of match inspection,
 3 = lead inspection, 5 = area measurement by binary

- conversion, 6 = object counting by binary conversion, 7 = object identification by
- binary conversion, 8 = point measurement, 9 = multiple positions measurement, A = multiple degree of inspections

- (2) \rightarrow Measurement data

Only the data in block 0 of a measurement program is output.

(3) Measurement data reading function 3: code 22(H)

This command will cause the IV-S30J to read the results of the last measurement. The results in the ladder outputs (Y00 to 15) and the measurement data in block 0 of each measurement will be sent back as the response.

This command is effective regardless of the measurement input specified.

Command


:	Station No.¦	2	2	Object type	Measure- ment	Block	SC ¹ SC (H)¦(L)	CR			
Res	sponse										
•	Station No.¦	2	2	RC'RC (H), (L)	Objec type		Fina evalua Y0¦Y1¦	l outpu tion re 	Specified block data	SC'SC (H)¦(L)	CR

- Object type \rightarrow Object type for which the measurement was executed: 00 to 3F
- Executed camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only
- Final Output evaluation result (Y0 to Y15) \rightarrow 0: NG or unspecified, 1: OK
- (1) \rightarrow Specified block data

(4) Measurement data reading function 4: code 24(H)

This command will cause the IV-S30J to read the results of the last measurement. Any numeric value data will be output as a response. \Rightarrow See page16-26. This command is effective regardless of the measurement input specified.

Command



- Object type \rightarrow Object type for which the measurement was executed: 00 to 3F

- Executed camera number \rightarrow 0: Both camera 1 and 2; 1: Camera 1 only; 2: Camera 2 only

[(Response) measurement code]


Measurement code	Setting	Measurement code	Setting
0	MEASURE 0 CAMERA 1	5	MEASUREMENT 4
1	1 MEASURE 0 CAMERA 2		Distance and angle measurement
2	MEASUREMENT 1	7	Numerical calculation
3	MEASUREMENT 2		
4	MEASUREMENT 3		

- Specification for any output data \Rightarrow See page 17-16.

(5) Illuminance level reading: code 28(H)

The illuminance level measured by the illuminance monitor function and the evaluation result are read.

Command



Response

:	Station No.¦	2 8	RC'RC (H)¦(L)	Object type	Result	Illuminance 10 ²¹ 10 ¹¹ 10 ⁰¹ 10 ⁻¹ 	SC'SC (H) (L)	CR
---	-----------------	-----	------------------	----------------	--------	--	------------------	----


- Camera No. → 0: camera 1, 1: camera 2

- Object type \rightarrow Object type for which the measurement was executed: 00 to 3F
- Result \rightarrow 0: NG, 1: OK
- Illuminance \rightarrow 000.0 to 255.0

(6) Corrected light level reading: code 29(H)

The corrected light level measured by the illuminance monitor function, the evaluation result and preset reference light level are read.

Command



- Camera No. \rightarrow 0: camera 1, 1: camera 2


Response

- Object type → Object type for which the measurement was executed: 00 to 3F

- Result \rightarrow 0: NG, 1: OK
- Corrected light level \rightarrow Corrected light level (-0 to 255.0)
- Reference light level → Light level used as the criterion (0 to 255.0)


[3] Setting, initialization, and diagnosis of the operation screen

Shown below are only the commands and responses of these processing functions.



Pr	rocess function	Process code	Communication format	
			■ Command	
	Read the image status	56	Station No. 5 6 SC'SC CR Response Station $I \rightarrow Output$ $I \Rightarrow Through$	
			$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
	Set the image status	57	$\begin{bmatrix} Station \\ No. \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\ $	
			■ Response	
			$\begin{array}{c c} Station \\ No. \\ \hline \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ $	
			Command Camera1 display	
	Read out image camera condition	58	58	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
Individual conditions			$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	
al co	Set output	59	Command Camera1 display	
Individua			$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
	image camera condition		■ Response 4 0 8 0	
	Condition			Station No. 5 9 RC RC SC SC RC (H) (L) (H) (L) CR 1 Camera 1 1 2 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
			Command	
	Read the	5.0	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
	shutter speed for each object	5A	Response	
	type		Station Shutter speed No. 5 A RC RC (H) (L)	
			Command	
	Set the shutter speed for each	5B	Station No. 5 B Sc SC CR (H) (L)	
	object type		■ Response	
			$ \begin{array}{ c c c c c c c } \hline Station & & & & & & & \\ \hline No. & & 5 & B & RC RC & SC SC \\ & & & & & \\ \hline H) & & \\ \hline H & & \\ H & & \\ \hline H & & \\ H & & \\ \hline H & & \\ H & & \\ \hline H & & \\ H & & \\ \hline H & & \\ H & & \\ \hline H & & \\ H & & \\ H & & \\ \hline H & & \\ H & $	


Communication (General Purpose Serial Interface)



Pr	ocess function	Process code	Communication format
	Read the manual measurement coordinates	70	■ Command $\begin{array}{c c c c c c c c c c c c c c c c c c c $
	Set the manual measurement coordinates	71	■ Command $\begin{array}{c c c c c c c c c c c c c c c c c c c $

[4] Setting numerical data of the any output measuring

Numerical data of the any setting of the response at measuring (code 14(H): page 17-8) and reading measurement data 4 (code 24(H): page 17-10) is as follows.



[Ex.] A numerical data of the any setting when outputting coordinate X and coordinate Y with the positional deviation measurements.

, 0,2	Registration 0 (Model 0)	Registration 0 (Model 1) I I I I I I	:	Registration N (Model 1) I I I I I I	,	0 3	Registration 0 (Model 0) I I I I I I	:	Registration N (Model 1) I I I I I I
-------	-----------------------------	---	---	---	---	-----	---	---	---

• Codes and number of bytes of output data

1. Result of each measurement program

0	utput data				Measurement program								
Kind of ou	utput	Output code	No. of bytes	Positional deviation measurement	Degree of match inspection	Lead inspection	Area measurement by binary conversion	Object counting by binary conversion	Object identification by binary conversion	Point measurement	Multiple positions measurement	Multiple degree of match inspections	
Degree of matc	h	01	2	0	0								
Coordinate X		02	2	0	0								
Coordinate Y		03	2	0	0								
Coordinate dev		04	2	0									
Coordinate dev	iation Y	05	2	0									
Angle		06	2	0									
Average light level 1		07	2		0								
Number of objects		08	2			0		0	0		0	0	
Distance	MAX.	09	2			0							
Distance	MIN.	0A	2			0							
Lead width	MAX.	0B	2			0							
	MIN.	0C	2			0							
Lead length/	MAX.	0D	2			0							
lead width 2	MIN.	0E	2										
Total area		10	4				0	0	0				
Area of each	CUR.	11							0				
Area of each label	MAX.	12	4										
	MIN.	13											
X coordinate of gravity	CTR. OF GRAVITY	14							0				
center/Distan- ce between	MAX. DIST.	15	2										
gravity centers X	MIN. DIST.	16											
Y coordinate of gravity	CTR. OF GRAVITY	17							0				
center/Distan- ce between	MAX. DIST.	18	2										
gravity centers Y	MIN. DIST.	19											

0	utput data			Measurement program								
Kind of ou	ıtput	Output code	No. of bytes	Positional deviation measurement	Degree of match inspection	Lead inspection	Area measurement by binary conversion	Object counting by binary conversion	Object identification by binary conversion	Point measurement	Multiple positions measurement	Multiple degree of match inspections
Fillet diameter	CUR.	1A							0			
X	MAX.	1B	2									
	MIN.	1C										
Fillet diameter	CUR.	1D	2						0			
Fillet diameter Y	MAX.	1E										
	MIN.	1F										
Main axis angle		20	2						0			
Perimeter		21	4						0			
Degree of matcl	h	22	2								0	0
Coordinate X		23	2								0	0
Coordinate Y		24	2								0	0
Average light le of light level diff	vel 1(total erences)	25	2									0
Average light level 2		28	1							0		
Black and white		29	1							0		
Counting white objects		2A	2							0		
Number of regis	sters	2B	2							0		
Center point X		2C	2						0			
Center point Y		2D	2						0			

2. Results of the distance and angle measurement

Kind	of output	Output code	No. of bytes	
Distance		30	2	
Angle		31	2	
Auxiliary 1	Coordinate X	32	Λ	
	Angle	33	4	
Auxiliary 2	Coordinate Y	34	4	
Auxiliary 2	Y slice length	35	4	

3. Numeric calculation results


Kind of output	Output code	No. of bytes
MEASURE 0 CAMERA 1		
MEASURE 0 CAMERA 2		
MEASUREMENT 1		
MEASUREMENT 2	40	4
MEASUREMENT 3		
MEASUREMENT 4		
Final calculation		

Chapter 18: Computer Link

A programmable controller (hereafter referred to as a PC) can be connected to the IV-S30J, so that the computer link can be used to have the IV-S30J execute measurements.

18-1 Compatible models

The IV-S30J is applicable with the computer links for the following models of Sharp, Mitsubishi, OMRON, and Yokogawa.




18-2 Data flow

Specify the CCD-TRIG (camera 1) or the PARALLEL (parallel interface) as the source of the MEAS INP I/F (measurement start input) signal.

⇒ See Chapter 16 "Setting the Input/Output Conditions."

The data flow for a measurement start input (CCD trigger/parallel) signal and an object type change command (parallel) is shown below.

IV-S30J



The block of measurement data to be written from the IV-S30J to the PC, in step ②, can be specified on the "OBJ-TYPE I/O" screen.

⇒ See page 16-23.

• When a Sharp PC is connected

The IV-S30J sends write enable command (EWR) to the PC in the following cases.

- When the power is applied to the IV-S30J.
- When a Sharp PC is selected.
- When a write mode nonconformity error (code 10_(H)) occurs after a result write command (WRG) is transmitted (when the power is disconnected from the PC).

• When a Mitsubishi, OMRON, or Yokogawa PC is connected

The data in items (2) and (3) are divided into packets for transmission.

18-3 Register setting

Use PC register (writing: up to 512 bytes) to provide the IV-S30J with a computer link.

Setting item	Applicable range of address	
Write register (up to 512 bytes)	- Sharp: 09000 to 99776 - Mitsubishi - OMRON: DM0000 to DM9999 - - Yokogawa: D00001 to D16384	► See page 16-22.

Enter the write start address in item "③WRITE TOP ADRS," on the "COMPUTER LINK" screen, under the "SELECT SYSTEM COND" screen.

Note 1: When a Sharp PC is used, specify an even address for the write start address.

Note 2: When 512 bytes are used for the write register in a Sharp PC, use one of the following write start addresses.

09000, 19000, 29000, 39000, 49000, 59000, 69000, 79000, 89000, 99000

• Write register map

The write register contains the following data.

Sharp	Mitsubis	shi	OMRO	N	Yokoga	wa	Contents	1
09000	D0000	L	DM0000	L	D00001	L	Termination code (00(н): normal termination, codes other than 00(н) abnormal termination ⊏>See page 19-3.)	
09001		Н		Н	00001	Н	Appended information (error code in an error response)]*/
09002	Doood	L	DMOOOA	L	Dooooo	L	Object type number (0 to 63: 00 to 3F(H))	
09003	D0001	н	DM0001	Н	D00002	н	Measurement number when outputting results (0 to 5)]*2
09004	D0002	L	DM0002	L	D00003	L	Result output (Y0 to Y15)]*(
09005	D0002	Н	DIVIOUUZ	Н	D00003	Н		
09006	D0003	L	DM0003	L	D00004	L	Measurement function 0 using camera 1	
09007	00003	Н	DIVIOUUS	Н	D00004	Н	Measurement function 0 using camera 2	*
09010	D0004	L	DM0004	L	D00005	L	Measurement function 1	
09011	00004	Н	DIVIOUU4	Н	00000	Н	Measurement function 2	*!
09012	D0005	L	DM0005	L	D00006	L	Measurement function 3	`
09013	20000	Н	Binocoo	Н	200000	Н	Measurement function 4	
09014	D0006	L	DM0006	L	D00007	L	Output data from measurement 0 camera 1 (block 0)	
09015		H		H		Н	:	
:		L		L		L	Output data from measurement 0 camera 2 (block 0)	
:		Н		Η		Н	:	
	: 	<u>.</u>	; 	<u>.</u>				i
	:	L	:	L	:	L	Output data from measurement 1 (block 0)	
•		Н		Н		Н		!
•		.	1	.		.	Output data from monour 2 (black 0)	: *(
•			:	L H	:	H	Output data from measurement 2 (block 0)	
•		ГП	ļ	ILL I		П		!
•	<u> </u>	L		Ĺ	İ	İ.	Output data from measurement 3 (block 0)	i
•	:	늡	:	늡	:	Н	· ·	
•	!		!		!		· · ·	!
•		_		İ.		1	Output data from measurement 4 (block 0)	i
•	:	Н	:	H	:	Н	· ·	
•	ļ	<u> </u>					•	!
19000		1		İī		1	Assigned block data	ił
19001	D0256	Ē	DM0256	뉴	D00257	Н		
				· ·				*
•	•		•	1	•			
•	•	:	•	i –	•	1		;

18

*1 to *7 \Rightarrow See the next page.

The register map shown above is established when the write start addresses have been set as shown below.

Manufacturer	Sharp	Mitsubishi	OMRON	Yokogawa
Write start address	09000	D0000	DM0000	D00001

Computer Link

- *1 When the termination code is 08_(H) (received an error response), the error code is contained in the appended information. (Example: 0A_(H) on a Sharp PC = parity error)
- *2 Measurement number when outputting the results
- $00_{(H)}$ = Measurement 0, Camera 1, $01_{(H)}$ = Measurement 0, Camera 2, $02_{(H)}$ = Measurement 1,
 - $03_{(H)}$ = Measurement 2, $04_{(H)}$ = Measurement 3, $05_{(H)}$ = Measurement 4
- *3 Result output (Y0 to Y15)

			H	I (09	900	5)			L (09004)							
Bit	7	6	5	4	3	2	1	0	7	6	5	4	3	2	1	0
`	۱ ۲15	ا ۲14	ا ۲13	۱ ۲12	и Y11	и 1) 19	Y8	۱ ۲7	۱ Y6	۱ Y5	۱ Y4	Y3	Y2	 Y1	Y0

*4 Measurement program for measurement 0

 $00_{(H)}$ = none, $01_{(H)}$ = positional deviation measurement

*5 Measurement programs for measurements 1 to 4

- $00_{(H)}$ = none, $01_{(H)}$ = positional deviation measurement, $02_{(H)}$ = degree of match inspection, $03_{(H)}$ = lead inspection, $05_{(H)}$ = area measurement by binary conversion, $06_{(H)}$ = object counting by binary conversion, $07_{(H)}$ = object identification by binary conversion, $08_{(H)}$ = point measurement, $09_{(H)}$ = multiple position measurement, $0A_{(H)}$ = multiple degree of match inspections
- When a block is specified
- The measurement data from measurement numbers 0 to 4 in block 0 is output. (Max. 496 bytes).
- Measurement numbers that have not been specified will not output any data. (The space will be filled by the next item. Max. 500 bytes.)
- See pages 18-6 to 18-13, for details about the measurement data in block 0.

• When "ANY" is selected for the output

- ⇒See page 18-16.
- *7 Assigned block data

When the SERIAL OUTPUT item is set to "BLOCK-ASSIGN," the IV-S30J will output the measurement result data in the specified block number. When the SERIAL OUTPUT item is set to "ANY," the nature of the output will depend on the output settings.

⇒ For details about how to specify measurement output, see pages 16-23 and 16-25.

- No data is output if block 0 (00) is specified.

 \Rightarrow For details about the measurement data block, see pages 18-5 to 18-15.

- The top address where the specified block of data is written will be an address made by adding 512 bytes to the top address for writing results.

	Sharp	Mitsubis	hi	OMRO	N	Yokogaw	va	Contents
Top address	09000	D0000	L	DM0000	L	D00001	L	Termination code
for writing results	09001	D0000	н		Н	D00001	н	Appended information
results				•		•		
		•				•	į	· ·
	•	•		•		•		•
	:		L		L		L	Output data from
	:	•	н	•	н	•	Н	measurement 4 (block 0)
		•				•		· ·
Top address	19000	D0256	L	DM0256	L	DOODEC	L	Assigned block data
for writing results	19001	D0250	Н	DIVIO230	Н	D00256	Н	
+ 512 bytes							ļ	
							: :	
							: :	

18-4 Measurement data blocks

[1] Number of blocks

The measurement functions vary in the number of measurement data blocks they use.

	Measurement function	Blocks	Page
	Positional deviation measurement	0, 1	18-6
	Degree of match inspection	0, 1	18-7
m	Lead inspection	0, 1	10-7
ogra	Area measurement by binary conversion	0	18-8
nt pr	Object counting by binary conversion	0	10-0
mer	Object identification (labeling) by binary conversion	0	18-8 to 10
Measurement program		0, 1 (when binary processing is selected)	40 44 45 40
Me	Point measurement	0 to 4 (when average density is selected)0 to 4	18-11 to 12
	Multiple positional measurement	0 to 4	18-13
	Multiple degree of match inspections	0 to 4	10-13
Di	stance and angle measurement	58	18-14
Nu	umerical calculation	51	18-15

[2] Contents of the measurement result block (for each measurement function) (1) Positional deviation measurement

Block		ltem		Sign (+/-)	No. of bytes	Decimal point (digit)		
		1st point	Х	None	2	1		
	Registration	(center coordinates)		None	2	1		
		2nd point	Х	None	2	1		
0	No. 0	(center coordinates)	Υ	None	2	1		
		Angular deviation	Provided*	2	1			
	Registration No. 1 to 7	The registration No. 1 to 7 contain the same data as the registration No. 0.						

* When a sign is provided, if the highest-order bit of the data is ON (1), a "-" minus sign is used, and if the bit is OFF (0), a "+" plus sign is used. The value (decimal) is expressed two's complement notation. (A two's complement number is obtained by inverting the 0s and 1s in a binary number and adding 1.)

Note: If a registration number has not been used yet, the data for the next registered number will be brought forward.

• Example of the data in block 0: Only registration No. 0

1 1	05280	-	LĒ Ē	11 Ē.						
Х	Y	Х	Y	Angular						
Center coordinates Center coordinates deviation										
X Y X Y Angular Center coordinates Center coordinates of 1st point of 2nd point										
Registration No. 0										

- These data are in hexadecimal. They are converted to the actual decimal measurements as shown below.

		Data (hexadecimal)	Decimal number	Measurement result (value)
Center coordinates	Х	820	2080	208.0
of 1st point	Y	528	1320	132.0
Center coordinates	Х	FA0	4000	400.0
of 2nd point	Υ	EB0	3760	376.0
Angular deviation		FF76	—138	—13.8

Block		Item			Sign (+/-)	No. of bytes	Decimal point (digit)			
		Degree of	1st poi	nt	Provided	2	None			
		match	2nd point		Provided	2	None			
	Registration	Deviation amount	1st	X	Provided	2	1			
1	No. 0		point	Υ	Provided	2	1			
			2nd	X	Provided	2	1			
			point	Υ	Provided	2	1			
	Registration No. 1 to 7		The registration No. 1 to 7 contain the same data as the registration No. 0.							

Note: If a registration number has not been used yet, the data for the next registered number will be brought forward.

(2) Degree of match inspection

Block		Item		Sign (+/-)	No. of bytes	Decimal point (digit)				
	Registration	Degree of match	1st point	Provided	2	None				
0		(positioning)	2nd point	Provided	2	None				
	Registration No. 1 to 15		Registration No. 1 to 15 contain the same data as the registration							

Block		ltem			Sign (+/-)	No. of bytes	Decimal point (digit)
		Coordinate	1st point	Х	None	2	1
				Y	None	2	1
	Registration No. 0		2nd point	Х	None	2	1
1				Y	None	2	1
		Average	1st point		None	2	1
		light level	2nd point		None	2	1
	Registration No. 1 to 15	Registratior No. 0.	n No. 1	to 15	contain the sa	ime data as	the registration

(3) Lead inspection

Block	ltem	1	Sign (+/-)	No. of bytes	Decimal point (digit)				
0	Registration No. 0	Number of objects	None	2	None				
	Registration No. 1 to 15	Registration No. 1 to 15 contain the same data as the registration No. 0.							

Block		ltem		Sign (+/-)	No. of bytes	Decimal point (digit)
			Maximum	None	2	1
		Distance	Minimum	None	2	1
		Distance	NG No.	None	2	None
			No. of NG	None	2	None
		1 suidth	Maximum	None	2	1
	Registration No. 0		Minimum	None	2	1
			NG No.	None	2	None
1			No. of NG	None	2	None
			Maximum	None	2	1
		Lead	Minimum	None	2	1
		length	NG No.	None	2	None
			No. of NG	None	2	None
	Registration No. 1 to 15					

Computer Link

(4) Area measurement by binary conversion

Block	Item		Sign (+/-)	No. of bytes	Decimal point (digit)	
0	Registration No. 0	Area	None	4	None	
	Registration No. 1 to 15	Registration No. 1 to 15 contain the same data as the registration No. 0.				

(5) Object counting by binary conversion

Block	lte	em	Sign (+/-)	No. of bytes	Decimal point (digit)	
0	Registration No. 0	No of labels Total area	None None	2	None None	
	Registration No. 1 to 3	Registration No. 1 to 3 contain the same data as the registration No. 0.				

(6) Object identification by binary conversion

Block		lte	m	Sign (+/0)	No. of bytes			
	Registration		No. of labels	None	2	None		
0	No. 0		Total area	None	4	None		
0	Registration No. 1 to 3	Registrat registrat No. 0.	ation No. 1 to 3 conta ion	ain the same data as the				
			Area of each label	None	4	None		
			X coordinate of gravity center	None	2	1		
		l abel 0	Y coordinate of gravity center	None	2	1		
10		Labor o	Spindle axis angle	Provided	2	1		
	Registration		Fillet diameter X	None	2	None		
	Ňo. 0		Fillet diameter Y	None	2	None		
			Peripheral	None	4	1		
		Label 1	abel 1 to 31					
11		Label 3	abel 32 to 63		0 to 12	7 contain		
12		Label 64 to 95		the same data as the label No. 0.		No. 0.		
13		Label 9	6 to 127					
20		Label 0		Label No.	0 to 12	7 contain		
21	Registration	Label 3	2 to 63	the same				
22	No. 1	Label 6	4 to 95	data as t -block 10.	he label	No. 0 of		
23		Label 9	6 to 127	DIOCK TO.				
30		Label 0		l abel No	0 to 13	27 contain		
31	Registration	Label 3	2 to 63	the same				
32	No. 2	Label 6	4 to 95	data as t -block 10.	he label	No. 0 of		
33		Label 9	abel 96 to 127					
40		Label 0		Label No.	0 to 12	7 contain		
41	Registration	Label 3	2 to 63	the same				
42	No. 3	Label 6	4 to 95	data as t block 10.	he label	No. 0 of		
43		Label 9	6 to 127					

To the next page

Block	ltem			Sign (+/0)	No. of bytes	Decimal point (digit)
		Label 0			4	
60	Registration No. 0 label unit area	to		None	to	None
		Label 127			4	
61	Registration No. 1 label unit area	Label 0 to 12	27			
62	Registration No. 2 label unit area	Label 0 to 12	27	Each labe		s the same
63	Registration No. 3 label unit area	Label 0 to 12	27		0011 00.	
		Label 0	Х	None	2	1
		Laber 0 Y		None	2	1
64	Registration No. 0 gravity center	to			to	
		Label 127	Х	None	2	1
			Y	None	2	1
65	Registration No. 1 gravity center	Label 0 to 12	27			
66	Registration No. 2 gravity center	Label 0 to 12	27	Each labe		s the same
66	Registration No. 3 gravity center	Label 0 to 12	27			
68	Registration No. 0 spindle angle	Label 0 to 127	1B	Provided	2	1
00	Registration No. 1 spindle angle	Label 0 to 127	1B	Provided	2	1
69	Registration No. 2 spindle angle	Label 0 to 127	1B	Provided	2	1
69	Registration No. 3 spindle angle	Label 0 to 127	1B	Provided	2	1
		Label 0	Х	None	2	None
		Laber 0	Y	None	2	None
70	Registration No.0 fillet dia.	to	•	to		
		Lobal 127	Х	None	2	None
		Label 127	Y	None	2	None
71	Registration No.1 fillet dia.	Label 0 to 12	27			
72	Registration No.2 fillet dia.	Label 0 to 12	27	data as bl		s the same
73	Registration No.3 fillet dia.	Label 0 to 12	27			
74	Registration No.0 peripheral length	Label 0 to 12	27	None	4	1
75	Registration No.1 peripheral length	Label 0 to 12	27			
76	Registration No.2 peripheral length	Label 0 to 12	27	data as bl		s the same
77	Registration No.3 peripheral length	Label 0 to 12	27			
		Label 0	Х	None	2	None
		Laber 0	Y	None	2	None
78	Registration No.0 center point	to			to	
		Labol 127	Х	None	2	None
		Label 127	Y	None	2	None
79	Registration No.1 center point	Label 0 to 12	27			
80	Registration No.2 center point	Label 0 to 12	27			s the same
81	Registration No.3 center point	Label 0 to 127		data as block 78.		

Block	Ite	em		Sign (+/0)	No. of bytes	Decimal point (digit)	
			Area of each label	None	4	None	
			X coordinate of gravity center	None	2	1	
			Y coordinate of gravity center	None	2	1	
		Label	Spindle axis angle	Provide- d	2	1	
82		0	Fillet diameter X	None	2	None	
	Registration No. 0		Fillet diameter Y	None	2	None	
	-		Peripheral	None	4	1	
			Center point X	None	2	None	
			Center point Y	None	2	None	
		Label 1 to 31		_			
83		Label 3	32 to 63			7 contains the	
84		Label 6	64 to 95	same dat	same data as label No		
85		Label 9	96 to 127				
86		Label () to 31	Label No. 0 to 127 contains the same data as label No. 0 in			
87	Registration No. 1	Label 3	32 to 63				
88		Label 6	64 to 95	block 82.			
89		Label 9	96 to 127				
90		Label () to 31				
91	Registration No. 2	Label 3	32 to 63			7 contains the el No. 0 in	
92	Registration No. 2	Label 6	64 to 95	block 82.	.a as iau		
93		Label 96 to 127]			
94		Label () to 31				
95	Registration No. 3	Label 3	32 to 63			7 contains the el No. 0 in	
96	กษฎเรแลแบบ ทบ. ว	Label 6	64 to 95	block 82.	a as idu		
97		Label 9	96 to 127				

(7) Point measurement

1. In the binary mode

Block		Item		Sign (+/0)	No. of bytes	Decimal point (digit)
	Registration No. 0 to 15	Black and white information	0 = black 1 = white	None	2	None
	Registration No. 16 to 31	Black and white information	0 = black 1 = white	None	2	None
0	:	:			:	
	Registration No. 240 to 255	Black and white information	0 = black 1 = white	None	2	None
	Registration	Evaluation information	0 = NG 1 = OK	None	1	None
	No. 0 to 7	Black and white information	0 = black 1 = white	None	1	None
	Registration	Evaluation information	0 = NG 1 = OK	None	1	None
1	No. 8 to 15	Black and white information	0 = black 1 = white	None	1	None
	:	:			:	
	Registration	Evaluation information	0 = NG 1 = OK	None	1	None
	No. 248 to 255	Black and white information	0 = black 1 = white	None	1	None

- Note: If a point number has not been used yet, the data for the next registered number will be brought forward.
- When an item does not have data in 2 byte units, the data will be increment (scrolled up) in units of two bytes.
- [Ex.] When "NO" data is registered at memory locations 16 to 31, the data at memory locations 32 and on are moved down to locations 16 and on.

• Data example: Only point No. 0 to 7 in block 0

	/	Data	Contents
F A White/ black information	White/black information	FA (H)	FA11110Point No.P7P6P5P4P3P2P1P0White/blackWhite White White White White BlackWhite Black White Black0: black, 1: white

2. In the average light level mode	vel mode	level	light	average	the	. In	2.
------------------------------------	----------	-------	-------	---------	-----	------	----

Block		Item	Data code	Sign (+/0)	No. of bytes	Decimal point (digit)	
0	Registration No. 0	Average densigy	20	None	2	None	
0	Registration No. 1 to 31	Registration No. 1 registration No. 0.	to 31 co	ntain the	e same o	data as	
1	Registration No. 32	Average densigy	20	None	2	None	
1	Registration No. 33 to 63	Registration No. 33 registration No. 0.	8 to 63 c	ontain th	ne same	data as	
2	Registration No. 64	Average densigy	20	None	2	None	
2	Registration No. 65 to 95	Registration No. 65 to 95 contain the same data as registration No. 0.					
3	Registration No. 96	Average densigy	20	None	2	None	
5	Registration No. 97 to 127	Registration No. 97 registration No. 0.	Registration No. 97 to 127 contain the same data as registration No. 0.				
	Registration No. 0 to 15	Evaluation information	0=NG 1=OK	None	2	None	
4	Registration No. 16 to 31	Evaluation information	0=NG 1=OK	None	2	None	
	:	:			:		
	Registration No. 112 to 127	Evaluation information	0=NG 1=OK	None	2	None	

Note: If a point number has not been used yet, the data for the next registered number will be brought forward.

(8) Multiple positional measurement

Block		ltem	Sigı (+/0		Decimal point (digit)
0	Registration No. 0	Number of objects detected	l Non	e 2	None
0	Registration No.1 to 3	Registration No. 1 to 3 contai registration No. 0.	n the sa	me data a	as
			0.		
Blook		Itom	Sign	No. of	Decimal

Block		Item		Sign (+/0)	No. of bytes	Decimal point (digit)
			Degree of match	None	2	None
		Detection 0	Coodin- ate X	None	2	None
1	Registration No. 0		Coodin- ate Y	None	2	None
		Average light level 1 (total of light level difference)*		None	2	None
		Detection 1 to 127	Details at are the sa			ects 1 to 127 t 0.
2	Registration No. 1					
3	Registration No. 2	Details about dete object 1(register N		cts 2 to 4	4 are the	same as for
4	Registration No. 3					

(9) Multiple degree of match inspections

Block		Item	Sign (+/0)	No. of bytes	Decimal point (digit)
0	Registration No. 0	Number of objects detected	None	2	None
0		Registration No. 1 to 3 contain registration No. 0.	the sam	e data a	S

Block		ltem		Sign (+/0)	No. of bytes	Decimal point (digit)	
			Degree of match	None	2	None	
	1 Registration No. 0	Detection 0	Coodin- ate X	None	2	None	
1			Coodin- ate Y	None	2	None	
		Average light leve of light level differ	None	2	None		
		Detection 1 to 127	Details about detected objects 1 to 127 are the same as for object 0.				
2	Registration No. 1		·				
3	Registration No. 2	Details about detected objects 2 to 4 are the same as for object 1(register No. 0).					
4	Registration No. 3						

* When light level matching is executed, the total difference in light level is output.

Block		Item		Data code	Sign (+/0)	No. of bytes	Decimal point (digit)		
			Distance	30	Provided	2	1		
		Registration No. 0	Angle	31	Provided	2	1		
	Measurement 0 Camera1		Auxiliary 1 (coordinate X /angle)	32/33	Provided	4	Float		
			Auxiliary 2 (coordinate Y /Y slice length)		Provided	4	Float		
58			Registration No. 1 to 15 contain the same data as registration No. 0.						
	Measurement 0 Camera 2	Registration No. 0 to 15	Registration No. 0 to 15 contain the same data as measurement 0, camera 1.						
	Measurement 1		Registration No measurement 0			e same	data as		
	Measurement 2		Registration No measurement 0			e same	data as		
	Measurement 3	Registration No. 0 to 15	Registration No. 0 to 15 contain the same data as measurement 0, camera 1.						
	Measurement 4		Registration No measurement 0			e same	data as		

(10) Distance and angle measurement

Note: Blank items are omitted and the remaining lines are moved up.

(11) Numerical calculation

Block		ltem		Data code	Sign (+/0)	No. of bytes	Decimal point (digit)	
	Measurement 0	Registration No. 0	Calculation result	40	Provided	4	2	
	Camera1		Registration N registration No	e data as				
	Measurement 0	Registration No. 0	Calculation result	41	Provided	4	2	
	Camera 2	Registration No. 1 to 15	Registration N registration No	lo. 1 to o. 0.	15 contain t	he same	e data as	
	Measurement 1	Registration No. 0	Calculation result	42	Provided	4	2	
	measurement 1	Registration No. 1 to 15	egistration Registration No. 1 to 15 contain the same data as lo. 1 to 15 registration No. 0.					
51	Measurement 2	Registration No. 0	Calculation result	43	Provided	4	2	
51		Registration No. 1 to 15	ion Registration No. 1 to 15 contain the same data as registration No. 0.					
	Measurement 3	Registration No. 0	Calculation result	44	Provided	4	2	
	Measurement 5		Registration N registration No		15 contain t	he same	e data as	
	Measurement 4	Registration No. 0	Calculation result	45	Provided	4	2	
	Measurement 4	Registration No. 1 to 15	on Registration No. 1 to 15 contain the same data as 15 registration No. 0.					
	Final	Registration No. 0	result	48	Provided	4	2	
	measurement		Registration N registration No		15 contain t	he same	e data as	

Note: Blank items are omitted and the remaining lines are moved up.

18-5 Specifications for any output data

When the serial output is set to "ANY" (page 16-26), the measurement results for the output data that is set to "YES" will be written into the write register map "output data from measurements 0 to 4 (block 0): *6 on page 18-3," in output-code order.

Measurement	Output	Registration	
		Degree of match for register number 0	
	Output code 01	Degree of match for register number 1	
	(degree of match)	to	
		Degree of match for register number 7	
		Coordinate X for register number 0	
Measurement 0	Output code 02	Coordinate X for register number 1	
Camera1	(coordinate X)	to	
Camera i		Coordinate X for register number 7	
	to	to	
	() utput codo (()	Numeric calculation result for register number 0	
		Numeric calculation result for register number 1	
		to	
	,	Numeric calculation result for register number 15	
Measurement 0 Camera2	The details of the ou for "MEASUREMEN"	tput codes and register numbers are the same as T 0, CAMERA1"	
Measurement 1	The details of the ou for "MEASUREMEN"	tput codes and register numbers are the same as T 0, CAMERA1"	
Measurement 2	The details of the ou for "MEASUREMEN"	tput codes and register numbers are the same as T 0, CAMERA1"	
Measurement 3	The details of the ou for "MEASUREMEN"	tput codes and register numbers are the same as T 0, CAMERA1"	
Measurement 4	The details of the ou for "MEASUREMEN"	tput codes and register numbers are the same as T 0, CAMERA1"	

- Data that are set to "NO" output do not output any signal (scrolled up).

- Set the next page for details about the output codes (type, number of bytes, related measurement programs)

nut data ayam	nlaa whan the			column is set to	VEC "
pul uala exam	pies when the	SERIAL	UUIFUI	column is set to) IES.

SHARP	Mitsubis	shi	OMRON	1	Output data	Details	Measurement item when SERIAL OUTPUT is set to "YES"	
09014	D0006	L	DM0006	L	00	$0100_{(H)}$: 00 = fixed value		
09015	D0000	Н	DIVIOUUU	Н	01	01 = output code (degree of match)		
09016	D0007	L	DM0007	L	78	2678 _(H) : 9848 _(D) = 98.48%	/	
09017	D0007	Н	DIVIOUUI	Н	26	2070 _(H) . 3040 _(D) = 30.4078	Register 0 (degree of	
09020	D0008	L	DM0008	L	00	0200 _(H) : 00 = fixed value (V coordinate Y	match, coordinate X,	
09021	D0000	Н	DIVIOUUU	Н	02	02 = output code (X coordinate)	deviation) for	
09022	D0009	L	DM0009	L	92	$-0992_{(H)}$: 2450 _(D) = 245.0 (coordinate value) measurement		
09023	D0009	Н	DIVIOU09	Н	09	$(0.992_{(H)})$. 2450 _(D) = 245.0 (coordinate value)	(position deviation	
09024	D0010	L	DM0010	L	00	0005 _(H) : 00 = fixed value,05 = output code measurement		
09025	DUUIU	Н	DIVIOUTO	Н	05	(coordinate Y deviation)		
09026	D00011	L	DM00011	L	FA	$0.0EA \div 2E0 = 2E0$ (doviation value)		
09027	DUUUTI	Н	DIVIOUUTI	Н	00	$00FA_{(H)}$: 250 _(D) = 25.0 (deviation value)		
09030	D00012	L	DM00012	L	01	0001 _(H) : 00 = fixed value	Register 0 (degree of	
09031	000012	Н	DIVIOUUTZ	Н	00	01 = output code (degree of match)	match) for measurement 3	
09032	D00013	L	DM00013	L	28	2628 • 9752 - 97 52%	(degree of match	
09033	200013	Н	210100013	Н	26	$-2628_{(H)}: 9752_{(D)} = 97.52\%$ (degree of main inspection)		

• Codes and number of bytes of output data 1. Result of each measurement program

0	utput data		1 0	Measurement program								
Kind of output		Output code	No. of bytes	Positional deviation measurement	Degree of match inspection	Lead inspection	Area measure-ment by binary conversion	Object counting by binary conversion	Object identifi- cation by binary conversion	Point measurement	Multiple positions measurement	Multiple degree of match inspections
Degree of matc	h	01	2	0	0							
Coordinate X		02	2	0	0							
Coordinate Y		03	2	0	0							
Coordinate devi		04	2	0								
Coordinate devi	ation Y	05	2	0								
Angle		06	2	0								
Average light le		07	2		0							
Number of obje		08	2			0		0	0		0	0
Distance	MAX.	09	2			0						
Diotairoo	MIN.	0A	2			0						
Lead width	MAX.	0B	2			0						
	MIN.	0C	2			0						
Lead length/	MAX.	0D	2			0						
lead width 2	MIN.	0E	2									
Total area		10	4				0	0	0			
Area of each	CUR.	11							0			
label	MAX.	12	4									
	MIN.	13										
X coordinate of gravity center/Distan-	CTR. OF GRAVITY	14							0			
ce between	MAX. DIST.	15	2									
gravity centers X	MIN. DIST.	16										
Y coordinate of gravity	CTR. OF GRAVITY	17							0			
center/Distan- ce between	MAX. DIST.	18	2									
gravity centers Y	MIN. DIST.	19										
	CUR.	1A							0			
Fillet diameter X	MAX.	1B	2									
	MIN.	1C										
	CUR.	1D							0			
Fillet diameter	MAX.	1E	2									
	MIN.	1F										

Output data					М	easure	ment	orogra	m		
Kind of output	Output code	No. of bytes	Positional deviation measurement	Degree of match inspection	Lead inspection	Area measure- ment by binary conversion	Object counting by binary conversion	Object identifi- cation by binary conversion	Point measurement	Multiple positions measurement	Multiple degree of match inspections
Main axis angle	20	2						0			
Perimeter	21	4						0			
Degree of match	22	2								0	0
Coordinate X	23	2								0	0
Coordinate Y	24	2								0	0
Average light level 1 (total of light level differences)	25	2									0
Average light level 2	28	1							0		
Black and white	29	1							0		
Counting white objects	2A	2							0		
Number of registers	2B	2							0		
Center point X	2C	2						0			
Center point Y	2D	2						0			

2. Results of distance and angle measurement

Kind	of output	Output code	No. of bytes
Distance		30	2
Angle		31	2
Auxiliary 1	Coordinate X	32	4
Auxiliary	Angle	33	4
Auxiliary 2	Coordinate X	34	4
	Y slice length	35	4

3. Results of numerical calculations

Kind of output	Output code	No. of bytes
MEASURE 0 CAMERA 1		
MEASURE 0 CAMERA 2		
MEASUREMENT 1		
MEASUREMENT 2	40	4
MEASUREMENT 3		
MEASUREMENT 4		
Final calculation		

18-6 Interface

The interface between the IV-S30J and a programmable controller from each manufacturer is described below.

IV-S30J		ogrammable	
-	for the IV-S30J See item [1] below.	– Sharp → – Mitsubishi → – OMRON → – Yokogawa	[2] [3] [4]

[1] Setting items for the IV-S30J

Item	Setting details
Communication speed(k bit/sec)	115.2, 57.6, 38.4, 19.2, 9.6, 4.8, 2.4
Data length (bit)	7, 8
Parity	None, odd, even
Stop bit	1, 2
Error check	Checksum
Station No.	Sharp: 00 to 37(8) Mitsubishi: 00 to 31 OMRON: 00 to 31 Yokogawa: 01 to 32
Write address (up to 512 bytes)	Sharp: 09000 to 99776 Mitsubishi: D0000 to D9999 OMRON: DM0000 to DM9999 Yokogawa: D00001 to D16384

[2] Connection with a Sharp PC


Applicable models

1. Control module:	JW-22CU (can be used with ROM version 2.2 or later)
	JW-70CUH/100CUH, JW-32CUH/33CUH JW-32CUH1/33CUH1/33CUH2/33CUH3
2. Basic module:	JW-1324K/1342K/1424K/1442K/1624K/1642K
3. CPU board:	Z-311J/312J
4. Link module:	JW-21CM, JW-10CM
5. Communication board:	Z-331J/332J

(1) Module setting

(1) When a JW-22CU or a JW-70CUH/100CUH and Z-311J/312J are used


Store the communication port conditions in system memory addresses #236 and #237. Bits D_0 to D_5 are stored in memory address #236.



In the initial state, addresses #236 and #237 are set to 000.

(2) When a JW-32CUH/33CUH or a JW-32CUH/33CUH1/33CUH2/33CUH3 is used 1. When communication port 1 (PG/COMM1 port) is used

Store the communication conditions in system memory addresses #234 and #235. Set bits D_0 to D_5 in memory address #234. Only an RS-422 cable can be connected to the PG/COMM1 port.




Enter the station No. for the current station.

In the initial state, addresses #234 and #235 are set to 000.

2. When communication port 2 (PG/COMM2 port) is used.

Store the communication conditions in system memory addresses #222, #236 and #237. Either RS-232 or RS-422 cable can be connected to the PG/COMM2 port.




In the initial state, addresses #222, #236 and #237 are set to 000.

③ When a JW-1324K/1342K/1424K/1442K/1624K/1642K is used

1. When the communication port is used

Store the communication conditions in system memory addresses #234, #236 and #237.




Enter the station No. for the current station.

In the initial state, addresses #234, #236 and #237 are set to 000.

2. When the MMI port is used

Store the communication conditions in system memory addresses #226 and #227. Set bits D_0 to D_5 in memory address #226.

Use of the MMI port ensures a one-to-one connection between the IV-S30J and the JW10.



In the initial state, addresses #226 and #227 are set to 000.

4 When a JW-21CM or JW-10CM is used

Set the switches (SW0 to SW4 and SW7) on the module as shown below.

Switch	Setting	Set value
SW0	Command mode	4
SW1	Station No. (upper bit)	01 to 37 ₍₈₎
SW2	Station No. (lower bit)	01 10 37 (8)
SW3-1	Invalid	OFF
SW3-2	4-wire system	ON
SW3-3	Invalid	OFF
SW3-4	Odd parity (OFF), even parity (ON) OFF or ON	OFF or ON
SW4	Transmission speed (k bit/sec) 19.2 (0) or 9.6 (1)	0 or 1
SW7	With a termination resistance	ON

(5) When a Z-331J/332J is used

Set the switches (SW0 to SW4 and SW7) on the board as shown below.

Switch	Setting	Set value
SW0	Computer link	4
SW1	Station No. (upper bit)	01 to 37 ₍₈₎
SW2	Station No. (lower bit)	011037(8)
SW3-1	Invalid	OFF
SW3-2	Only the 2-wire system can be used.	OFF
SW3-3	Invalid	OFF
SW3-4	Odd parity (OFF), even parity (ON)	OFF or ON
SW4	Transmission speed (k bit/sec) 19.2 (0), 9.6 (1)	0 or 1
SW7	With a termination resistance	ON

(2) Using memory


To allow the memory to be used by the IV-S30J, enter a result write start address in the following range.

Memory	Range (address)	
Register	09000 to 99776	

(3) Connections

(1) When a JW-22CU or JW-70CUH/100CUH is used

1. Communication through the RS-232C port JW-22CU JW-70CUH/100CUH Communication connector on (Communication port) the IV-S30J (RS232C/RS422) Pin No. Signal name Signal name Pin No. Connector 1 FG FG shield 3 RD 3 SD 2 2 SD RD 7 5 SG SG 12 Short-circuit terminal 14 15 m or less RS-232C



(2) When a JW-32CUH/33CUH or JW-32CUH1/33CUH1/33CUH2/33CUH3 is used 1. Communication through the RS-232C port

	Pin No.	Signal name		
(PG/COMM2 port)				
	/33CUH2/33CUH3			
	JW-32CUI	H1/33CUH1		
	JW-32CU	H/33CUH		

JW-32CUH/33CUH

Pin No.	Signal name		Pin No.	Signal name
Connector shield	FG	·····	1	FG
3	SD		4	RD
2	RD		2	SD
5	SG		7	SG
		15 m or less		


2. Communication through the RS-422 port (4-wire system)


Communication connector on the IV-S30J (RS232C/RS422)


			JW-32CU /33CUH2/	H1/33CUH1 33CUH3
 	n connector		PG/COM PG/COM	
Pin No.	Signal name		Pin No.	Signal name
4	TA	<u>A</u>	9	RD (+)
7	TB		10	RD (-)
8	RA		3	SD (+)
9	RB		11	SD (-)
Connector shield	FG	·	1	FG
		Shielded, twisted-pair cable		
		1 km or less		
		RS-422		

③ When a JW-1324K/1342K/1424K/1442K/1624K/1642K is used

The IV-S30J can only be connected to the RS-422 port. When the communication port is used, provide a 2-wire RS-422 system. When the MMI port is used, provide a 4-wire RS-422 system. **1. When the communication port is used**








(5) When a JW-21CM or JW-10CM is used - Communication through the RS-422 port (4-wire system)

6 When a Z-331J/332J is used - Communication through the RS-422 port (2-wire system)



[3] Connection with a Mitsubishi PC

Applicable models

A series computer link modules

- 1. AJ71C24-Sx (AnA or AnN)
 - In the case of the AnA, a computer link can be created if a CPU from the AnA series is used and the link module version is S6 or later.
- 2. A1SJ71C24(A1S)
 - When the A1SJ71C24-R2 is used, the station number is fixed at 00 because it does not have a station number switch.
- 3. A0J72C24S1(A0J2)

(1) Module setting


1 Example using an AJ71C24-Sx module

Item		Description
Transmission control procedure mode (RS-232C)		Format 1fi 1
Station No.		00 to 31
Transmission speed (kbit/sec)		19.2, 9.6
Parity		None, odd, even
Transmission code	Data bit	7/8 bits (ASCII)
I ransmission code	Stop bit	1, 2 bits
Checksum		Executed
Writing while running		Possible

• Switch setting

Ex.: To set as shown below: Mode: RS-232C, Station No.: 00, Transmission speed: 19.2 K bytes/sec. Parity: Even, Data bit: 7 bits, Stop bit: 2 bits

- 3 rotary DIP switches




- DIP switches

SW11 to 13	SW14 to 24
OFF	ON

(2) Example using an A1SJ71UC24-R4 module

• Switch setting

Ex.: To set as below: Mode: RS-422, Transmission speed: 19.2 K bytes/sec. Parity: Even, Stop bit: 2 bits



(2) Using memory

To allow the memory to be used by the IV-S30J, use a result write start address within the following range.

Memory	Range (address)	
D (data register)	0 to 9999/0 to 999900	


Note: To write data from the IV-S30J to a Mitsubishi PC, use the WW/QW write command. The range that can be written using the write command WW/QW is D0000 to D1023/D000000 to D008191, due to the limitation of Mitsubishi PCs. The write all address can be set within the range of limitation for Mitsubishi PCs.

 \Rightarrow See page 16-22.

(3) Connections

Shown below are the connections with a calculator link module.

1 Example of RS-232C connection



Note: Jumper the RS, CS, DR and CD lines. Do not jumper the SG.

Remarks

- For RS-232C communications, create the sequence program shown below in order to set "**no CD terminal check**" for the CD terminal check setting. For details, see the instruction manual for Mitsubishi's calculator link module. Xn7 TOP n1 H10B K1 K1

(2) Example of RS-422 communication

C	Communica on the IV-S3 RS232C/R		tor Shielded, twisted-pair cable	Calculator link	<
	Pin No.	Signal name		Signal name	
	Connector shield	FG	<u> </u> ≮∧	- FG	
	4	TA		RDA	
	7	TB		RDB	
	8	RA		SDA	
	9	RB		SDB	
	5	SG		SG	
			1 km max. RS-422 (4-wire system)		

[4] Connection with an OMRON PC • Applicable models

Host link modules

- 1. C500-LK203 (C1000H)
- 2. C200-LK201 (C200H RS-232C)
- 3. C200-LK202 (C200H RS-422)
- 4. CV CPU link port (CV1000, CVM1)
- 5. CV500-LK201 (CV1000, CVM1)
- 6. CS1W-SCU21


Remarks

- Start the OMRON PC in the monitor mode when turning ON the power. If the OMRON PC is started in any other mode, a computer link error will occur.

The operation mode is specified using the following items for each support tool: The initial mode setting switch on the memory module, or the monitor mode rising bits of the system setting (FUN49) instruction.

	Memory module initial setting switch			
Installed support tool	OFF The bit used to s mode in the sy (FUN49) instruction	ON		
	0	1 *1		
Support tools other than the programming console	Program mode	Monitor mode	Operation mode	
No support tool	Operation mode	Monitor mode	Operation mode	
Programming console	Programming	console setting	g mode *2	

*1 Insert the ladder program step shown below at address 000000.



*2 When the programming console is used, set the PC to the "monitor mode" using the switch.

For details, see the user's manual for the OMRON PLC module.

(1) Module setting

Item		Description	
Module No.		00 to 31*	
Transmission speed (k bit/s	sec)	19.2, 9.6	
Command level		1	
Parity		Odd or even	
Transmission code	Data bit	7 (ASCII)	
	Stop bit	2	
1:1/1:N procedure		1:N procedure	
Synchronous change-over switch		Internal synchronization	
CTS change-over switch		0 V (normally ON)	
5 V supply switch		OFF	

* Enter the unit number of the IV-S30J, as a component of CV500-LK201 system. When communication port 1 is used, the unit number is fixed at 00, and when communication port 2 is used, any number (00 to 31) can be used.

(2) Using memory


To allow the memory to be used by the IV-S30J, enter a result write start address within the following setting range.

Memory	Range (address)
DM (data register)	0 to 9999

Note: The IV-S30J uses [DM area write] command of C mode command. Concerning the limitation of address settings, see OMRON's PC manual.

(3) Connections

(1) Example of RS-232C communication




(2) Example of RS-422 communication

	tion connec (RS232C/R	S422)	Calculator link
Pin No.	Signal name	Shielded, twisted-pair cable	module Signal name
Connector shield	FG	····	- FG
4	TA		RDB(SD+)
7	TB		RDA(SD-)
8	RA	A	SDB(RD+)
9	RB		SDA(RD-)
			RS
			- CS
		<pre>1 km max. RS-422 (4-line system)</pre>	Pin numbers vary with the module to be used

8

18-7 Program examples


An example of measurements using the IV-S30J and a Sharp PC (JW70H) (2-point search for positional deviation measurement) is explained below, using data flow, a flowchart and a timing chart.




Note 1: The PC must be write enabled. A Mitsubishi, OMRON, or Yokogawa PC will operate in the same manner, but use different PC register and relay addresses.

Note 2: If the PC has not been connected to the object type input (parallel) on the IV-S30J, the object type No. is set to 0. To set different types, first enter the object type numbers (parallel) using the type input terminals on the IV-S30J.

(2) Flow chart



(3) Program



• Explanation of the program

The numbers 1 to 16 below correspond to the same numbers on the preceding page.

- 1. Turn on the power, and wait for 5 sec. (07377 is kept ON for only 1 scan after the power is turned ON.)
- 2. The camera is started. (00040 enters a measurement trigger.)
- 3. The trigger input (00007) is self-latched when the operation start has begin (00000 = ON).
- 4. The termination code of the write register is cleared.
- 5. The time-out detection timer monitoring the computer link is started.
- 6. Time-out error
- 7. A check is made for normal termination.
- 8. Normal termination $(09000 = 000_{(8)})$
- 9. A check is made for errors.
- 10. Occurrence of an error (09000 = 001 to 376(8))
- 11. The data in the result output relays Y0 to Y15 (16 points) on the IV-S30J is transferred from registers 09004 to 09005 to addresses]0412 and]0413.
- 12. A normal termination signal is output.
- 13. The judgment (OK/NG) of the result output relay Y0 is output.
- 14. The judgment (OK/NG) of the result output relay Y1 is output.
- 15. When a time-out or an error occurs, it is output.
- 16. When a time-out or an error occurs, it is reset.

(4) Timing chart

		1 scan time	
Operation start 00040 Start signal input 00007	 <u></u>		<u>_</u>
otari olginar input oooor			
Operation of the IV-S30J through a computer link	 Execution of measurement	Data writing IV-S30J ເ⊃ JW70H	
Normal termination 04100	 		
Y0, Y1	 	ОК	
Error output 00013			

Chapter 19: Troubleshooting

Item [1] shows problems which may occur when the IV-S30J measurement system is started. If any error (the termination code is not 00(H)) occurs during image processing on the IV-S30J, take the steps described in item [2].

Perform the recommended daily inspection following the maintenance procedures listed in item [3]. [1] Symptoms and checks

The following symptoms may not be malfunctions. Before asking us to repair your equipment, check the recommended parts.

Phenomenon		Checks
The power is not turned ON. (The power lamp on the IV-	1.	Make sure that the power cord has been connected properly to the DC power terminal block on the IV-S30J.
S30J does not light.)	2.	Make sure that the proper supply voltage is available and has not dropped.
After the power is first turned ON, no images or characters	1.	Make sure that the monitor cable has been connected correctly.
are displayed on the monitor.	2.	Make sure that the offset and gain are adjusted properly.
After the power is first turned ON, no characters are displayed on the monitor.	1.	Make sure that the message display and pattern display modes are not set to the non-display mode. Make sure that the title field is not filled with spaces.
	1.	The operation screen is always displayed in the freeze mode. Change the mode to the through mode on the lower menu section.*
After the newer is first turned	2.	Make sure that the lens iris is not closed.
After the power is first turned ON, no image is displayed on	3.	Make sure that the shutter speed has not been increased.
the monitor, or the image on	4.	Check the lens for contamination.
the display is abnormal.	5.	Check the CCD light receiving surface for contamination.
	6.	Make sure that the lens focus has been adjusted properly.
	7.	Make sure that the lighting equipment is providing adequate illumination.
The background is completely white (or black) even after the shutter speed is changed.		 Make sure that the monitor screen is not too bright or dark. (Changes in brightness cannot be sensed.) ⇒ Adjust the lens aperture or the illumination of the light source.
Operations cannot be carried out using the remote key pad.	1.	Make sure that the remote key pad cable has been correctly connected to the IV-S30J.
	1.	Make sure that the communication cable has been correctly connected.
	2.	Make sure that each terminal of the communication cable is properly connected.
General purpose serial communications cannot be	3.	Make sure that the communication conditions (standard, speed, and parity check) in the personal computer conform to those of the IV-S30J.
performed.	4.	Check the cable for disconnection and the connectors for contact failure.
	5.	Make sure that you waited about 15 seconds after you turned ON the power.
	6.	Make sure that the operation screen is displayed on the screen.
' ↓		* You can change to the through mode screen using the "TYPE RUN COND" screen.

- Continued on the following page -

RUN COND" screen.

Phenomenon		Checks
	1.	Make sure that the communication cable has been correctly connected.
	2.	Make sure that the communication cable route does not run near electrically noisy devices.
	3.	Make sure that each terminal of the camera cables is properly connected.
Communications through a computer link cannot be established.	4.	Make sure that the communication conditions (standard, speed, and parity check) in the personal computer conform to those of the IV-S30J.
	5.	Make sure that a compatible model, the station No. and result write start address have been set correctly.
	6.	Make sure that you waited about 15 seconds after you turned ON the power.
	7.	Make sure that the operation screen is displayed on the screen.
	1.	Make sure that measurement can be started by using the key pad to send a trigger signal.
	2.	Make sure that the camera cables have been correctly connected.
Measurement does not start even when a start trigger is given.	3.	Make sure that the device to send a trigger signal have been properly connected to the input terminals on the IV-S30J main housing.
	4.	Make sure that you waited about 15 seconds after you turned ON the power.
	5.	Make sure that the operation screen is displayed on the screen.
	1.	Make sure that the camera cables have been correctly connected.
Measurement results are not	2.	Make sure that the devices have been properly connected to the input terminals on the IV-S30J main housing.
output.	3.	Make sure that you waited about 15 seconds after you turned ON the power.
	4.	Make sure that the operation screen is displayed on the screen.
	1.	Make sure that the lighting equipment does not flicker.
	2.	Make sure that the lens has not fogged up.
	3.	Check the lens for contamination.
Measurement results are unstable, or NG results occur	4.	Make sure that the focus ring has not turned. (Make sure that the camera lock screw has been secured.)
frequently.	5.	Check whether the camera position has changed.
	6.	Make sure that the illuminance monitor window has been set to the intermediate illumination.
	7.	Make sure that the criteria have been set properly.

[2] Causes of termination codes (when an error occurs) and remedies When an abnormal termination code (other than 00(H)) is received, take the following measures.

Termi- nation code (H)		Cause	Remedy
	01	The specified processing code does not exist.	Check the processing code.
	02	The wrong number of data items was specified in the text.	Check the number of data items in the text.
S S	03	The text data is outside the acceptable range.	Check the text setting range.
Communication errors	04	The results of the check sums are not identical.	 Check the check sums. Check the communication environment for problems such as electric noise, which may come in on the communication line.
iunuu	05	The header code (:) was not attached to the head of the communication command.	Check whether the header code was attached to the head of the communication command.
Con	06	An asynchronous error has occurred.	 Check the communication environment for problems such as electric noise, which may come in on the communication line.
	07	The communication command contains an improper number of data items.	Check the number of data items in the communication command.
ik errors	08	An error response has been returned from the programmable controller. (Communications are performed normally.)	The error code is contained in the evaluation result area, and the error code is displayed on the monitor. Take the proper measures according to the error code (different models use different codes).
Computer link errors	09	A time-out has occurred during communication through the computer link.	 Make sure the power supply of the programmable controller and check the connections of the cables. Check the communication conditions and computer link settings.
	0A	Start address error (larger than the end address)	Check the address.
		SDRAM error	Replace the IV-S30J itself.
0		Flash memory error	
error:	12	No camera connected to the camera 1 connector.	Connect a camera.
Hardware errors	13	No camera connected to the camera 2 connector.	
2	14	VRAM error has occurred.	
Ï		Flash ROM delete error	Replace the IV-S30J itself.
		Flash ROM write error	
	1A	Flash ROM verify error	
	20	The measurement conditions for the specified object type have not been set.	
_ ر	21	The setting area is larger than the screen, due to positional correction.	
ng errors	22	Correction after binary conversion: The illuminance monitor function (system) has not been set.	Check the absorred setting
Processing		Correction after binary conversion: The threshold range has exceeded the specified range.	Check the abnormal setting.
<u> م</u>		No edge detection	
		A reference image has not been registered	
		Number of labels exceeds the specified amount	
		No setting for number o fimage lines	
	28	"0" subtraction error (numeric calculation	

Troubleshooting

na	ermi- ation code	Cause	Remedy
	(H)		
	29	Overflow (numerical calculation)	
	2A	No numerical calculation setting	
		No label (camera adjustment)	
	2C	The search area is smaller than the reference image. Equivalent label exceeded	
	2D 2E	Edge center point exceeded (lead inspection)	
	2E 2F	Unable to make a numerical calculation (point measurement)	
	30	Coordinates range exceeded (distance/angle measurement)	
	31	The lines are parallel (at the same angle) (cross point of two straight lines)	
	32	Divide by "0" (center of circle, vertically bisector, distance between point and line)	
	33	The two points are the same (two points on a straight line)	
	34	The CCD trigger has not been registered.	
	35	The CCD trigger is not being sampled by a serial interface signal.	
	36	The SIO trigger has not been set.	
	37	A start point has not been set. (Distance/angle measurement)	
	38	The auxiliary point conditions are not thoroughly specified. (Distance/angle measurement)	
Processing errors	39	Wrong conditions specified for a line or a point (distance / angle measurement)	Check the abnormal setting.
sing e	ЗA	The distance conditions are not thoroughly specified. (Distance/angle measurement)	
oces	3B	The angle conditions are not thoroughly specified. (Distance/angle measurement)	
	3C	Image reading/writing is impossible.	
	3D	The range of calculations using two images has exceeded the specified range.	
		The reference image cannot be registered from parallel input X6.	
		Exceeded the number of reference images registered Image not captured (CCD trigger)	
	40 41	The reference image rotation condition does not match.	
	41	The reference image edge is not registered yet.	
	43	CCD trigger disabled (through image).	
	-	Not a manual measurement	
		Binary mask conditions not set yet	
		No position correction conditions	
		- You assigned a non-existing register number or	
		model number to the position correction conditions.	
	10	- An angle has not been assigned for rotation	
	46	correction (only X and Y correction values have	
		been assigned.) - The rotation angle detection is set to "NO" for a 1-	
		point search, or this register number is used for the	
		angular correction in the rotation correction.	
	47	Number of objects to measure has not been set. (BGA/CSP)	
	48	In a multiple detection, the number of the edges exceeded the limit.	
	40	Unable to make a positional correction since there is no	
	49	edge.	

n	ermi- ation code	Cause	Remedy
	(H)		
	4A	No output data	
errors	4B	Object type conditions not set yet (numerical calculation)	
	4C	Number of objects detected or number of labels is too small (numerical calculation)	
ess	4D	Image capture mode does not match.	
Processing	4E	Cannot make two corrections in one step (same register number)	
	4F	Serial trigger disabled	
	50	The object type cannot be changed.	
	51	No corresponding block	Check the abnormal setting
errors	52	The output camera cannot be changed.	
eu	54	Image area is not appropriate	
ion	55	NG image not registered	
cat	56	Font not registered	
iu	57	Character strings not registered	
Ē	58	Menu tables not registered	
Communication	59	Area not registered (user menu)	
	5A	Title not registered (user menu)	
	5B	Initialization error (user menu)	
	5C	Number of data exceed the limit (any setting)	

[3] Maintenance

Check the equipment for the following items.

(1) Operation check


- Change the measurement number on the MAIN OPS MENU, and change the monitor screen to the freeze or through mode. Then, make sure that the image is normally displayed.

(2) Checks

- Check the illumination from the lighting equipment.
- Make sure that the monitor screen is in focus and that the aperture setting is proper.
- Check the cable insulation for breaks, and make sure that the cable connectors are not loose.
- Carefully wipe dust off the lens with a soft, dry cloth.
- If dust has landed on the CCD surfaces of this camera, wipe them with a clean cotton swab soaked in isopropyl alcohol. Move the cotton swab lightly and slowly in one direction. Change cotton swabs frequently. Do not clean more than one CCD surface with one cotton swab.

• Procedure for checking after cleaning

- 1 Mount the lens (mirror tube) on this camera.
- 2 Close the lens iris all the way.
- ③ Point the lens toward the light source, and check the monitor screen to make sure that there are no spots on the screen. (If the iris is open even a little, then even if spots exist, they will not be visible on the monitor screen. Fine adjustments to the iris are required.)



(3) When measurement errors and/or evaluation errors occur frequently, check:

- The illumination of the lighting equipment and lamps.
- The inspection object is within the window.
- The cables for looseness or disconnection.
- The lens for dirt and dust.
- The lens focus and aperture have not changed.
- The power is being supplied normally, and
- The parameters you set have been stored.

(If the parameters have changed, reset the parameters from the beginning.)

Alphabetical Index

[A]Absolute value of the differences3-20ALL-INIT (total initialization)2-22AND (evaluation)10-5Angle detection (DTECT ANGL)4-12Angular correction (standard/high precision)3-30Area measurement by binary conversion8-1Artifact processing3-15Automatic setting (threshold value)3-11AUTO-REG (condition setting)3-15Average light level method16-18

[B]

Binary area conditions	
Binary image display	
Binary image mask	
Binary method	16-18
Binary processing (fixed/threshold value correction)	
BLK WRT COMMAND (block write command)	16-22

[C]

[0]	
Calibrating the IV-S30J	16-28
Camera settings	2-17
CAMERA TYPE	2-17
Causes of termination codes (when an error occurs) and remedies	19-3
CCD trigger	
Change camera display mode	
Change the Japanese or English display mode	1-15
CHG-C1 (change camera 1)	1-12
CHG-C2 (change camera 2)	1-12
CHG-MEA (change measurement)	1-12
CHG-TYPE (change object type)	1-12
CHNG-REG (change registration)	1-12
Circle window	
Common operations for each menu	1-14
Communication (general purpose serial interface)	17-1
Communication format	17-5
Comparative calculations between images	3-20
Compatible models	18-1
Computer link output	16-23
Computer link setting	
Computer link	18-1
Configuration of set wizard	1-6
Configuration of the setting conditions	1-5
Connection with a Mitsubishi PC	
Connection with a Sharp PC	

Connection with an OMRON PC	18-29
Contents of the measurement result block (for each measurement function)	18-6
CONTR. PIXL (pixel contraction)	4-7
Contrast magnification rate	3-22
Contrast search (reference image)	3-16
Copying	3-37
Crosshair cursor display	2-12, 2-13

[D]

Data flow	17-3, 18-2
Data in specified blocks	16-23
Data length	18-19
Degree of match inspection	5-1
Description of the operation screen	1-10
Detection precision	
DISPLAY MODE	1-15
Distance and angle measurement	

[E]

Edge detection condition	4-7
Edge detection	3-14
Edge emphasis	
Edge extraction	
Editing operation screen	2-21
Eliminating binary noise	3-13, 7-6, 8-6, 9-7
Elliptical window	
Evaluation change display	2-10
Evaluation conditions	
Evaluation condition measurement	
Γ Area measurement by binary conversion	
Degree of match inspection	
Lead inspection	
Multiple degree of match inspection	12-7
Multiple positional measurement	11-9
Object counting by binary conversion	8-7
Object identification (labeling) by binary conversion	
Point measurements	10-7
Positional deviation measurement	4-9
Examples of a final output conditions ladder circuit	15-17
Existence inspection by point measurement	10-1
Expansion/contraction method of elimination noise in binary images	3-13
Extension functions	
External synchronization	2-19

[F]

Final numerical calculations	14-9
Final output conditions	15-11
Flow chart	
Full	

Full+half	 	 		2-18
Full∓halt	 	 	2	<u>2-</u> 1

[G]

Gain/offset adjustment	
General purpose serial output	16-21
Gray level change	
Gray scale processing	
Gray scale search	
Degree of match inspection	5-3
Multiple positional measurements	11-3
Positional deviation measurements	

[H]

Half	2-18
Halt on NG measurement	3-38
Histogram widening	
Horizontal edge	3-23
Horizontal line	3-6
How to display NG images	1-19
How to enter the setting screen	3-1

[I]

Illuminance (light level) monitor	3-34
Image adjustment	3-24
Image capture	
Image pre-processing	3-19
Image settings	3-9
Individual numerical calculations for each measuring program	14-1
Initialization	
Input & output / system settings	3-34
Interface	
Internal synchronization	2-19

[L]

Ladder circuit program creation	15-3
Lead Inspection	6-1
List of processing functions	17-1
LOCK (menu display)	1-15
Lock the menu display	1-15

[M]

MAIN OPS MENU	1-15
Maintenance	19-6
MANL-MEAS (manual measurement)	1-12, 2-13
Manually setting the object type	
Mask setting	3-26, 7-6, 8-6, 9-7
Measurement conditions	
۲ Area measurement by binary conversion	
Degree of match inspection	5-2

Distance and angle measurement	11-2
Lead inspection	. 6-2
Multiple degree of match inspection	12-2
Multiple position measurement	11-2
Object counting by binary conversion	. 8-2
Object identification (labeling) by binary conversion	. 9-2
Point measurements	10-2
Positional deviation measurement	. 4-2
MEA-CND (measurement conditions)	. 1-5
Measurement data blocks	18-5
Measurement processing cycle	15-2
Measurement start input and result output settings	16-5
Measurement start input interface 16-1, 7	16-4
Measurement start input	16-4
Menu bar 1-11, 7	1-12
Menu configuration	. 1-4
Message display	. 2-5
Method for selecting the menu configuration	. 1-2
Mid emphasis	3-22
Monitor output	. 2-2
Multiple degree of match inspection	12-1
Multiple positional measurements	11-1

[N]

IEXT-NG (display next NG image)1-	-22
IG image display screen1·	-19
IG image display 1-19 to	23
lumber of blocks	8-5
Jumeric calculation	
Area measurement by binary conversion	
Degree of match inspection	4-5
Distance and angle measurement 13-8, 14	
Lead inspection	4-5
Multiple degree of match inspection 12-8, 14	4-7
Multiple position measurement	4-7
Object counting by binary conversion	4-6
Object identification (labeling) by binary conversion	4-6
Point measurements 10-8, 14	4-7
Positional deviation measurement 4-10, 14	4-2
Jumerical calculation conditions14	4-1
Jumerical calculations (setting examples)14	4-2
Jumerical calculations	4-1

[O]

Object counting by binary conversion	8-1
Object identification and numbering function (labeling)	. 3-11
Object Identification by binary conversion	9-1
Operation cycle	. 15-1
Operation flow after the measurement start input is turned ON.	. 1-26

Operation flow	1-24
Operation main display	
Operation screen	1-10
Operation set menu	
Operations menu lock	1-15
Operations to return to the operation screen	1-14
Operation settings	
۲ Area measurement by binary conversion	
Degree of match inspection	5-2
Distance and angle measurement	13-2
Lead inspection	
Multiple degree of match inspection	12-2
Multiple positional measurements	11-2
Object counting by binary conversion	8-2
Object identification (labeling) by binary conversion	
Point measurements	10-2
Positional deviation measurement	4-2
Option	2-22
OR (evaluation)	10-5
Output conditions	
[Area measurement by binary conversion	
Degree of match inspection	5-9, 15-9
Distance and angle measurement	
Lead inspection	6-8, 15-9
Multiple degree of match inspection	
Multiple positional measurements	11-10, 15-10
Object counting by binary conversion	8-8, 15-10
Object identification (labeling) by binary conversion	
Point measurements	10-8, 15-10
Positional deviation measurement	4-10, 15-4
Output block assignment	16-23
Output code	17-16, 18-17
Output conditions	15-3
Output monitor	2-1

[P]

Parallel input X5	
Parallel input X6	
Parity check	16-21
Pattern display	
Pattern settings	
PC Function	
PC monitor screen	
PC scan cycle	
Pixel contraction	
Point condition	
Point measurement	10-1
Polygonal window	
Position correction	

Positional deviation measurement	4-1
Power ON and main loop processing	1-24
Power ON setting menu	1-15
Pre-processing	
Processing functions	17-7
Program examples (shape and positional deviation inspection)	15-16
Program examples	18-31

[R]

••	
RAM initialization	
Reading result	17-1, 17-9
READY'ON (I/O conditions)	
Rectangular window	3-4
RE-EXAM-NG (re-examine NG)	1-22
Reference image	4-5
Register coordinate position (window group move)	
Register a reference image	4-6
Register setting	
Remote keypad (IV-S30RK1)	1-16
Remote keypad specifications	1-16
Reset	17-2
RESET (condition settings)	
Result output	
Reference image (masking)	

[S]

SAVE	1-12
Saving data	1-14
Select "ANY" for the serial output	16-26
Select "YES" or "NO" for output data	16-27
SELECT CAMERA	2-17
Select output	
Self-diagnosis	2-22
Serial output	16-23, 16-26
Set serial block	16-25
Set wizard	1-2
Setting (operating) procedure	16-24
Setting and operating outline	1-1
Setting and operating procedures	1-1
Setting any data output	16-26
Setting distance and angle condition	13-2
Setting examples	14-11
Setting for serial communications	16-21
Setting items for the IV-S30J	18-19
Setting measurement conditions	3-1
Setting numerical data of any output measuring	17-16
Setting reference image area	4-4 to 5
Setting the conditions for each object type	3-1
Setting the data output	16-26

Setting the input/output conditions 16-1
Setting the measurement programs 1-13
Setting the operating and system conditions
Setting the operating conditions
Setting the shutter speed
Setting the system conditions
Setting window boundaries 3-11
Shading correction
Shutter speed 3-37
Smoothing (median, average) 3-23
Space filter
Specifications for any output data
Station No
STROBE OUT (strobe output) 16-3
Subtraction
Symptoms and checks 19-1
SYS-CND (system conditions) 1-5

[T]

Table of controller functions	1-29
Termination code	19-3
Threshold value automatic setting (edge detection)	3-15
Threshold value automatic setting (gray scale search)	
Threshold value correction	
Threshold value setting	
Through display	
Title registration	3-33
Troubleshooting	19-1

[V]

Variation difference	3-12
Variation rate	3-12
Vertical edge	3-23
Vertical line	3-6

[W]

Window group move	3-39
Window shape selection and settings	
Write address	16-22
[X]	
XY correction	3-30
[γ]	
γ (positive/negative)	3-22
[θ]	
$\boldsymbol{\theta}$ angle correction image display	