Change Log Version 1.0.6 (02.2023)

System relevant improvements.

- New: "Comelit" Door intercom system implemented
- New: "Siedle" Door intercom system implemented

Change Log Version 1.0.5 (06.2022)

PLEASE INSTALL THE UPDATE 1.0.5 WITH MOZILLA FIREFOX OR APPLE SAFARI
Note: The generic configuration function has been removed.

- New: "AKUVOX" Door intercom system implemented
- Implemented: The configuration of the front-door stations revised
- Implemented: Separate HTTP port configuration for the front-door stations
- Implemented: Updating the individual software components
- Implemented: Video proxy now accepts camera stream via HTTP
- Fixed: CONTROL L: Not all available buttons (door opener/light) were always displayed
- Fixed: Corrections to the syntax for DTMF control
- Fixed: Corrections to the syntax for HTTP(S) control
- Fixed: Network mask configuration: Not all valid network masks were accepted
- Fixed: Not all configured clients were always called
- Fixed: Firmware update can no longer be started in Chrome and Edge browser
- Improvement: Important security updates implemented

Change Log Version 1.0.4 (12.2020)

- New: "KOCH" Door intercom system implemented
- Implemented: Support of new ABB Welcome firmware version
- Implemented: Configuration out-door station: Only ASCII in names are allowed
- Implemented: Configuration out-door station: Validate IP Address field
- Fixed: Mobotix door and light control
- Fixed: Correction of syntax for DTMF control

Change Log Version 1.0.3 (03.2020)

- New: "MOBOTIX" door intercom system implemented.
- New: "AGFEO" door intercom system implemented.
- Implemented: Video proxy.

Change Log Version 1.0.2 (10.2019)

- New: Intercom in CONTROL **L** (under Windows/Linux).
- New: Encrypted communication with EIB**PORT**.
- New: Note on linked indoor stations when deleting outdoor stations.
- New: "Instant configuration" of the EIB**PORT** CONTROL **L** visualization project via token.

- **Fixed:** Restore function for backup files.

NOTE:
THIS FIRMWARE VERSION REQUIRES AT LAST **EIB PORT** FIRMWARE VERSION **3.8.0** FOR INTEGRATION INTO CONTROL **L**!

Change Log Version 1.0.1 (06.2019)
- **New:** "ABB/ Busch-Jaeger Welcome" door intercom system implemented.
- **New:** "DoorBird" door intercom system implemented.
- **New:** "2N" door intercom system implemented.

NOTE:
THIS FIRMWARE VERSION REQUIRES AT LAST THE **CONTROL T2** VERSION **1.1.17**!

Change Log Version 1.0.0
- Initial Version