Tecton/MX7



Accessory Catalog

Honeywell



SKU: MX7392BATT

Tecton Main Battery, Lithium Ion

Note: It can also be used

with MX7



SKU: MX7398BATTERY

Tecton Main Battery, Lithium Ion, 10-pack

Note: It can also be used

with MX7



SKU: MX7396BATTERY

Tecton CS Main Battery, Lithium Ion, Low-temperature

Note: It can also be used

with MX7CS



SKU: MX7390CHARGER

4 Unit Main Battery Charger with power supply and US power cord.

Note: US power cord included.



SKU: MX7395BATT

Tecton CS Main Battery, Lithium Ion, Low-temperature, 10-pack

Note: It can also be used

with MX7CS



SKU: MX7391CHARGER

4 Unit Main Battery Charger with power supply, C14 type power cord required

- AC power cord is not included.
 A country specific power cord must be purchased separately.
- When this product is shipped internationally it may be necessary to order and ship the appropriate internation AC power cable at the same time. This product has a C14 style AC power connector. Choose the proper C14 style cable from the international cables in the power cable section.





SKU: MX7402HANDLE

MX7 padded handle with rubber overmold and two finger trigger, includes wrist strap, for use with MX7 and MX7CS. Rated down to -22 deg F (-30 deg C.)



SKU: MX7504WRSTSTRAP

MX7 Wrist Strap 10 Pack





SKU: MX7490BOOT

Black rubber protective boot. Can be used with MX7388DSKCRDL & MX7008VMCRADLE



SKU: MX7491BOOT

Yellow rubber protective boot. Can be used with MX7388DSKCRDL & MX7008VMCRADLE



SKU: MX7404CASE

Tecton, TectonCS, MX7 & MX7CS Voice Application case with belt

Note: Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this case.



SKU: MX7412BELT

Gearkeeper retractor with belt for use with MX7411CASE.



SKU: MX7408CASE

Carry case for Tecton, TectonCS, MX7 & MX7CS without handle with Gearkeeper retractor

Note: Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this case.



SKU: MX7A413CASENHDL

Carry case for Tecton, TectonCS, MX7 & MX7CS with no handle, includes shoulder strap

Note:

- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this case.
- Large, tethered stylus can be ordered separately for this case, 9000A510STYLUS.



SKU: MX7411CASE

Carry case for Tecton, TectonCS, MX7 & MX7CS with handle. For use with retractor MX7412BELT

Note: Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this case.



SKU: MX7A414CASEHDL

Carry case for Tecton, TectonCS, MX7 & MX7CS with handle, includes shoulder strap

- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this case.
- Large, tethered stylus can be ordered separately for this case, 9000A510STYLUS.





SKU: MX7405HOLSTER

Holster for Tecton, TectonCS, MX7 & MX7CS with handle, belt not included

Note:

- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this holster.
- Belt must be ordered separately.



SKU: MX7410HOLSTER

Holster for Tecton, TectonCS, MX7 & MX7CS with handle and boot

Note:

- Boot and belt must be ordered separately
- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will fit in this holster.



SKU: MX7407HOLSTER

Holster for Tecton, TectonCS, MX7 & MX7CS with no handle, belt not included

Note:

- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will not fit in this holster
- Belt must be ordered separately.



SKU: MX7410HOLSTER

Adjustable nylon belt for holsters

Note:

- Boot and belt must be ordered separately
- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will fit in this holster.



SKU: MX7409HOLSTER

Holster for Tecton, TectonCS, MX7 & MX7CS with no handle and with boot

- Boot and belt must be ordered separately.
- Tecton, TectonCS, MX7 & MX7CS with rubber protective boot will fit in this holster.





SKU: MX7388DSKCRDL

Desktop cradle with spare battery charging, RS-232, USB client, and tethered scanner support. Power supply not included.

Note:

- Must order power supply 9000A321PSACUS or 9000A322PSACWW separately.
- Works with Tecton, TectonCS, MX7 & MX7CS ActivSync cables list in the Interface Cables section.
- Rated for operation bettween 32 deg F and 122 deg F (0 deg C and 50 deg C) and spare battery charging between 50 deg F and 104 deg F (10 deg C and 40 deg C).
- Cradle will perform "in-unit" battery trickle charging.
- Tecton, TectonCS, MX7 & MX7CS with a rubber boot will fit in the desktop cradle. The docking bay adapter cup must be removed before the Tecton, TectonCS, MX7 & MX7CS is placed in the desktop cradle.



SKU: MX7004DSKCRDL

Desktop cradle with spare battery charging, RS-232, USB client, and tethered scanner support. Includes AC/DC power supply. Power cord must be ordered separately.

Note:

- Works with Tecton, TectonCS, MX7 & MX7CS ActivSync cables list in the Interface Cables section.
- Rated for operation between 32 deg F and 122 F (Odeg C and 50 deg C) and spare battery charging between 50 deg F and 104 deg F (10 deg C and 40 deg C).
- Country specific power cord must be ordered separately.
- Tecton, TectonCS, MX7 & MX7CS with a rubber boot will fit in the desktop cradle. The docking bay adapter must be removed before the Tecton, TectonCS, MX7 & MX7CS is placed in the desktop cradle.



SKU: MX7003DSKCRDL

Desktop cradle with spare battery charging, RS-232, USB client, and tethered scanner support. Includes AC/DC power supply and US power cord.

Note:

- Works with Tecton, TectonCS, MX7 & MX7CS ActivSync cables list in the Interface Cables section.
- Rated for operation between 32 deg F and 122 F (Odeg C and 50 deg C) and spare battery charging between 50 deg F and 104 deg F (10 deg C and 40 deg C).
- Cradle will perform "in-unit" battery trickle charging.
- Tecton, TectonCS, MX7 & MX7CS with a rubber boot will fit in the desktop cradle. The docking bay adapter cup must be removed before the Tecton, TectonCS, MX7 & MX7CS is placed in the desktop cradle.



SKU: MX7007VMCRADLE

MX7 Passive vehicle cradle. Does not support charging or communication. U-Bracket included.

- RAM mount MX7A001RAMBRKT-R must be ordered separately.
- The cradle will not work with an MX7 that has a protective boot on it.
- The MX7 that has a protective boot on it cannot be mounted in the passive VM cradle.



SKU: MX7008VMCRADLE

Tecton, TectonCS, MX7 & MX7CS Active vehicle cradle. Supports MX7 charging, USB client and powered RS-232 connector.

Note:

- Must order power supply and cables separately.** See below
- Cradle will perform "in-unit" battery trickle charging.
- Tethered serial RS-232 barcode scanning supported.
- Rated for operation to 14 deg F and 122 deg F (-10 deg C and 50 deg C).
- The RAM Mount kit includes arm, clamp & base. All are size "C".



SKU: **MX7008VMCRADLE:

Note:

Must order power supply and cables separately.

- For 12 Volt DC operation, use 9000A079CBL 12ML3
- For 18-60 Volt DC input to 12V DC output use 9000301PWRSPLY
- For 60-110 Volt DC input to 12V DC output use 9000302PWRSPLY
- For 18-72 Volt DC input to 112V DC output use 9000304PWRSPLY
- For 110 Volt AC input to 12V DC Output with US Power Cord use 9000A321PSACUS
- For 110 Volt AC input to 12V DC Output without AC Power Coprd use 9000A322PSACWW



SKU: MX7A001RAMBRKT-R

RAM mount kit for MX7001VMCRADLE and MX8003VMCRADLE, passive vehicle cradle.

Attaches to U-Bracket.



SKU: MX7A002RAMBRKT

RAM mount kit for MX7008VMCRADLE.

Note:

• The RAM Mount kit includes arm, clamp & base. All are size "C".



Power Cables & Supplies



SKU: 9000301PWRSPLY

18V - 60V DC/DC power supply with cradle power cable

Note:

 Will work with the Active Cradle (MX7008VMCRADLE).



SKU: 9000A322PSACWW

AC/DC power supply, (C14 type power cord required), for use with charge/com cables and desk cradles MX7388DSKCRDL, MX7003DSKCRDL, or MX7004DSKCRDL".

Note:

- This power supply facilitates in-unit battery charging and is used in conjunction with the RS/232 and USB Active Sync cables or can be used with the MX7388DSKCRDL.
- Power Cord is not included.
- A country specific power cord must be ordered separately.
- Will work with the MX7 Active Cradle (MX7008VMCRADLE).



SKU: 9000302PWRSPLY

60V - 110V DC/DC power supply with cradle power cable

Note:

 Will work with the Active Cradle (MX7008VMCRADLE).



SKU: 9000090CABLE

AC power cable, C14 type, Schuko



SKU: 9000304PWRSPLY

Power adapter, 18-72V DC input to 12V DC output, includes cable.

Note:

 Will work with the Active Cradle (MX7008VMCRADLE).



SKU: 9000091CABLE

AC power cable, C14 type, Denmark



SKU: 9000A321PSACUS

AC/DC power supply with US power cord for use with MX7 Charge/Comm cables or

MX7 Desktop Cradle, MX7388D-SKCRDL

Note:

- This power supply facilitates in-unit battery charging and is used in conjunction with the RS/232 and USB Active Sync cables or can be used with the MX7388DSKCRDL.
- US power cord included.
- Will work with the MX7 Active Cradle (MX7008VMCRADLE).



SKU: 9000092CABLE

AC power cable, C14 type, Italy



SKU: 9000093CABLE

AC power cable, C14 type,
Switzerland



SKU: 9000A079CBL12ML3

Power Adapter, Bare Wire 12 VDC Note:

• Will work with the Active Cradle (MX7008VMCRADLE).



SKU: 9000094CABLE

AC power cable, C14 type, British

Interface Cables



SKU: MX7052CABLE

Tecton, TectonCS, MX7 & MX7CS. Charge/Comm Interface Cable, USB Client for ActiveSync

Note:

- The Charge/Comm cables facilitate Active Sync directly from the Tecton, TectonCS, MX7 & MX7CS". Computer.
- The charge/comm cables will also support in-unit battery charging. If in unit-battery charging is required, please order the appropriate power supply with each charge/comm cable.
- This cable connects to a PC USB port.



SKU: MX7058CABLE

Tecton, TectonCS, MX7 & MX7CS RS-232 Serial Adapter cable, 6in, for use with printers that provide their own source of power.



SKU: MX7060CABLE

Tecton, TectonCS, MX7 & MX7CS Headset coiled adapter cable, includes quick disconnect headset connector. A headset isstill required.



SKU: MX7055CABLE

Tecton, TectonCS, MX7 & MX7CS Charge/Comm Interface Cable, RS-232 Serial ActiveSync, D9 Female

Note:

- The Charge/Comm cables facilitate Active Sync directly from the Tecton, TectonCS, MX7 & MX7CS Computer.
- The charge/comm cables will also support in-unit battery charging. If in unit-battery charging is required, please order the appropriate power supply with each charge/ comm cable.
- This cable connects to a PC serial port.



SKU: HX2063CABLE

Cable, Vocollect TCO to LXE QD -Must also order MX7060CABLE or MX7070CABLE

Note:

This cable should be ordered when using a Vocollect Headset. It has a Vocollect headset connector on one end and the LXE 4-pin QX connector on the other. The total length of this cable is 6". One must also order MX7060CABLE to connect to the Tecton, TectonCS, MX7 & MX7CS.



SKU: MX7070CABLE

CBL ASSU, AUDIO, 6 INCH, MX7, includes quick disconnect headset connector.

Note:

 This is the Tecton, TectonCS, MX7 & MX7CS Headset coiled adapter cable which includes the quick disconnect headset connector. This new cable has the coiled section removed and the length has been reduced to 6".



SKU: MX7057CABLE

Tecton, TectonCS, MX7 & MX7CS RS-232 Serial Adapter cable, 6in, for use with printers that provide their own source of power. Non-RoHS.



SKU: MX7080CABLE

Headset coiled adapter cable, includes quick disconnect.



SKU: MX7090CABLE

Headset coiled adapater cable, includes quick disconnect headset connector for use with HX1501 headset, HX1502 headset, HX3601 HEADSET, HX3602 HEADSET, LWH330, RH750, RH760 AND RH770 not for use with LX-213. A headset is still required.





SKU: MX7A401HANDSTRAP

Replacement Tecton, TectonCS, MX7 and MX7CS Hand Strap





SKU: MX7A584STYLUS

Tecton, TectonCS, MX7 & MX7CS. Replacement Stylus, 10-pack



SKU: MX7A684PROTFILM

Touch screen Protectitive Film, 10 Pack



SKU: 9000A510STYLUS

Large tethered stylus which fit the Tecton, TectonCS, MX7 & MX7CS. carry cases, 5 pack

For more information about our products honeywellaidc.com

HSM Global

9680 Old Bailes Road Fort Mill, SC 29707 (1)(800) 582.4263 Servicio al Cliente USA (Ingles) (866) 460.8033 Soporte Técnico USA (Ingles) (888) 633.3762 www.honeywell.com

