

Red Hat Enterprise Linux 3

Certified Hardware

Systems and Components - Part III



Red Hat Enterprise Linux 3 Certified Hardware Systems and Components - Part III Edition 1.0

Copyright © 2012 Red Hat, Inc.

The text of and illustrations in this document are licensed by Red Hat under a Creative Commons Attribution–Share Alike 3.0 Unported license ("CC-BY-SA"). An explanation of CC-BY-SA is available at <http://creativecommons.org/licenses/by-sa/3.0/>. In accordance with CC-BY-SA, if you distribute this document or an adaptation of it, you must provide the URL for the original version.

Red Hat, as the licensor of this document, waives the right to enforce, and agrees not to assert, Section 4d of CC-BY-SA to the fullest extent permitted by applicable law.

Red Hat, Red Hat Enterprise Linux, the Shadowman logo, JBoss, MetaMatrix, Fedora, the Infinity Logo, and RHCE are trademarks of Red Hat, Inc., registered in the United States and other countries.

Linux® is the registered trademark of Linus Torvalds in the United States and other countries.

Java® is a registered trademark of Oracle and/or its affiliates.

XFS® is a trademark of Silicon Graphics International Corp. or its subsidiaries in the United States and/or other countries.

All other trademarks are the property of their respective owners.

1801 Varsity Drive
Raleigh, NC 27606-2072 USA
Phone: +1 919 754 3700
Phone: 888 733 4281
Fax: +1 919 754 3701

The Red Hat Enterprise Linux 3 Certified Hardware document provides the archived list of hardware certified for use with Red Hat Enterprise Linux 3.

1. Introduction	1
1.1. About this document	1
1.2. Background	1
2. Red Hat Enterprise Linux 3 Certified Systems	3
2.1. IBM	3
2.2. Intel Corporation	130
2.3. Itautec	149
2.4. KBS India	172
2.5. Keltron	174
2.6. KRAFTWAY	176
2.7. LG Electronics India Pvt. Ltd.	176
2.8. NEC	178
2.9. NEC/Bull	179
2.10. PCS Industries Limited	200
2.11. RadiSys Corporation	340
2.12. RLX Technologies	340
2.13. Sai InfoSystem (India) Ltd.	354
2.14. Samsung	373
2.15. Sun Microsystems, Inc.	381
2.16. Thales Computers	415
2.17. Unisys	415
2.18. VME	428
2.19. VMware	429
2.20. Wipro Limited	438
2.21. Zenith Computers Limited	494
3. Red Hat Enterprise Linux 3 Certified Components	501
3.1. Acer Inc.	501
3.2. Apple	504
3.3. Certance	505
3.4. Dell	508
3.5. Hewlett Packard	566
3.6. Intel Corporation	592
3.7. Promise Technology Inc.	592
3.8. Quantum	593
3.9. Sun Microsystems, Inc.	595
3.10. Winchester Systems, Inc.	598

Introduction

1.1. About this document

Red Hat is making it easier to search the Red Hat Hardware Catalog (<http://hardware.redhat.com>) for currently available hardware by archiving hardware certified on older versions of Red Hat Enterprise Linux. Hardware certified with Red Hat Enterprise Linux 3 is now listed in this file and has been removed from the Hardware Catalog. This file is attached to Knowledgebase article 69958 (<https://access.redhat.com/kbase/articles/69958>). Accessing archived certification entries in the Hardware Catalog will automatically redirect to Knowledgebase 69958.

1.2. Background

As described on the Red Hat Enterprise Linux Life Cycle page (<https://access.redhat.com/support/policy/updates/errata>), Red Hat Enterprise Linux 3 reached the end of its regular life cycle (end of Production Phase 3) in October 2010.

Red Hat Enterprise Linux 3 Certified Systems

2.1. IBM

2.1.1. BladeCenter Chassis (8677) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=198917>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.2. BladeCenter H Chassis (8852) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=198918>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.3. BladeCenter T Chassis (8720) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=198916>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.4. BladeCenter T Chassis (8730) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=198915>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.5. eServer e326m Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=175118>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.6. eServer OpenPower 710 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193006>

Summary

- *Version:* RHEL3-U4
- *Category:* Server
- *Platforms:* ppc64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.7. eServer xSeries 100 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=217496>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.8. eServer xSeries 100 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=181970>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.9. eServer xSeries 206m Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=217500>

Summary

- *Version:* RHEL3-U8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3

```
Make:          x206m
Model:         x206m
Vendor:        IBM
Category:      Server
Kernel Version: kernel-2.4.21-47.EL
File Uploaded: Jaguar_rhel3U8x86_cpuCedarMill13.6GHz_Memory8GB_20061117.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/a4ffe0721d4f3aed838bdf4a7d27ad85/
Jaguar_rhel3U8x86_cpuCedarMill13.6GHz_Memory8GB_20061117.noarch.rpmPlease note the following
failures:
WARNING: Kickstart file not found for required tests check.

0  PASSED  INFO
   PASSED  MEMORY
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.10. eServer xSeries 206m Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=180656>

Summary

- *Version:* RHEL3-U6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7754](#)¹ How do I get SAS and SATA controller working with Red Hat Enterprise Linux on the IBM eServer xSeries 206m, IBM eServer xSeries 260, IBM eServer xSeries 306m, IBM IntelliStation M Pro?

2.1.11. eServer xSeries 260 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=171284>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7869²](#) What is the procedure to get the latest "ServeRAID-8i" drivers for an IBM System x server?
- Red Hat Knowledge Base (Article): [7872³](#) What is the procedure to get the latest "SAS" drivers for a System x server?

2.1.12. eServer xSeries 306 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=165208>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.13. eServer xSeries 306 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148710>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-15 15:46:05-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5991
Detail Notes: 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-14 10:08:56-05

Detail 2:

Status: Compatible
Hardware Id: 5991
Detail Notes: 4GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-14 10:08:56-05

Detail 3:

Status: Compatible
Hardware Id: 5991
Detail Notes: Intel Corp. 82547EI Gigabit Ethernet Controller (LOM)

Intel Corp. 82541GI/PI Gigabit Ethernet Controller

(dual network cards)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-14 14:11:20-05

Detail 4:

Status: Compatible
Hardware Id: 5991
Detail Notes: ATI Radeon 7000/VE
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-14 14:12:31-05

Detail 5:

Status: Compatible
Hardware Id: 5991

Detail Notes: LG ATAPI CD-ROM CRN-8245B (24x)
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-14 14:19:48-05

Detail 6:
Status: Compatible
Hardware Id: 5991
Detail Notes: Intel 3.2 GHZ
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-14 14:20:31-05

Detail 7:
Status: Compatible
Hardware Id: 5991
Detail Notes: Intel Corp. 6300ESB SATA Storage Controller (rev 01)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-14 14:24:42-05

Detail 8:
Status: Compatible
Hardware Id: 5991
Detail Notes: Maxtor 6Y080M0

80GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-14 14:32:52-05

Additional Certification Notes

No additional certification notes provided

2.1.14. eServer xSeries 306m Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=217502>

Summary

- *Version:* RHEL3-U8
- *Category:* Server

- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         Puma 306m
Model:        eServer 306m -[306MXXX]-
Vendor:       IBM
Category:     Server
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: Puma_rhel13U8x86_cpuPresler3.4GHz_Memory8GB_20061115.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/aef0dadad470d506471b7b46fb38ead9/
Puma_rhel13U8x86_cpuPresler3.4GHz_Memory8GB_20061115.noarch.rpmPlease note the following
failures:
WARNING: Kickstart file not found for required tests check.

0  PASSED  INFO
   PASSED  MEMORY
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.15. eServer xSeries 306m Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=184306>

Summary

- *Version:* RHEL3-U6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7754](#)⁴ How do I get SAS and SATA controller working with Red Hat Enterprise Linux on the IBM eServer xSeries 206m, IBM eServer xSeries 260, IBM eServer xSeries 306m, IBM IntelliStation M Pro?

2.1.16. eServer xSeries 336 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187451>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.17. eServer xSeries 346 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=184219>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.18. eServer xSeries 366 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=165694>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.19. eServer xSeries 366 (Paxville) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=178841>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: eserver
Model: xSeries 366-8i
Vendor: IBM
Category: Server
Kernel Version: kernel-hugemem-2.4.21-37.EL

File Uploaded:

366DC-rhel3u6-32Bit-8i-FULL.results.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/76ffb2ae8923627056d41c76d0295a38/366DC-rhel3u6-32Bit-8i-FULL.results.rpm>

Please note the following failures:

WARNING: Kickstart file not found for required tests check.

```
0  FAILED  INFO
   PASSED VIDEO
   PASSED STORAGE
   FAILED  NETWORK
   PASSED  MEMORY
```

PASSED CORE

Additional Certification Notes

No additional certification notes provided

2.1.20. eServer xSeries 460 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=171898>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7869](#)⁵ What is the procedure to get the latest "ServeRAID-8i" drivers for an IBM System x server?
- Red Hat Knowledge Base (Article): [7872](#)⁶ What is the procedure to get the latest "SAS" drivers for a System x server?

2.1.21. eServer xSeries 460 (Paxville) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179144>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: eServer
Model: xSeries 460 (Paxville)
Vendor: IBM
Category: Server
Kernel Version: kernel-hugemem-2.4.21-37.EL

File Uploaded:

460DCS-rhel3u6-32Bit-64GB-SAS-6m-CMS.results.rpm
<https://bugzilla.redhat.com/hwcert/data/rpms/d72f2654d21209edf9386bf6cebbf117/460DCS-rhel3u6-32Bit-64GB-SAS-6m-CMS.results.rpm>

Please note the following failures:

WARNING: Kickstart file not found for required tests check.

```
0  FAILED  INFO
   PASSED STORAGE
   PASSED MEMORY
   PASSED CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.22. eServer BladeCenter 8852 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=221633>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.23. eServer BladeCenter 8852 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=221634>

Summary

- *Version:* RHEL3-U8
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         eServer BladeCenter
Model:        8852
Vendor:       IBM
Category:     Server
Kernel Version: kernel-2.4.21-47.EL
File Uploaded: rhcert-rhel3u8x64-hs21.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/e99fca146c406d8a7a58e8bd3fd6adc8/rhcert-
rhel3u8x64-hs21.rpmPlease note the following failures:
FAILED: Test list not found in kickstart file
```

```
0  PASSED  INFO
   PASSED  CORE2
```

Additional Certification Notes

No additional certification notes provided

2.1.24. eServer BladeCenter HS20 (7981) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=186987>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.25. eServer BladeCenter HS20 (8832) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148572>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-10-08 13:58:24-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5782

Detail Notes: This is a component designed to fit into a BladeCenter Chassis. The BladeCenter Chassis (8677-1xx) is required for operation.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-10-08 13:42:41-04

Detail 2:

Status: Compatible
Hardware Id: 5782

Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-10-08 13:42:41-04

Detail 3:

Status: Compatible
Hardware Id: 5782

Detail Notes: ServerWorks CSB6 RAID/IDE Controller (rev b0)<p>

Tested and certified as an IDE controller ONLY. All RAID functionality MUST be disabled through BIOS settings prior to installation.

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-10-08 13:42:41-04

Detail 4:
Status: Compatible
Hardware Id: 5782
Detail Notes: ** Optional **<p>
<p>
Requires addon scsi controller and drive enclosure blade module<p>
SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI
(rev 07)<p>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-08 13:42:41-04

Detail 5:
Status: Compatible
Hardware Id: 5782
Detail Notes: USB CD-ROM drive<p>
TEAC Model: CD-224E<p>
Part of Bladecenter Chassis<p>
Recognized as a SCSI CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-08 13:42:41-04

Detail 6:
Status: Compatible
Hardware Id: 5782
Detail Notes: USB Floppy drive <p>
TEAC Model: FD-05PUB<p>
Part of Bladecenter enclosure<p>
Recognized as a SCSI disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-10-08 13:42:41-04

Detail 7:
Status: Compatible
Hardware Id: 5782
Detail Notes: TOSHIBA MK4019GAXB<p>
40000 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-08 13:42:41-04

Detail 8:
Status: Compatible
Hardware Id: 5782
Detail Notes: IBM-ESXS Model: ST336732LC<p>
36400 MB<p>
Requires optional SCSI controller and drive enclosure
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-10-08 13:42:41-04

Detail 9:

Status: Compatible

Hardware Id: 5782

Detail Notes: 8 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-10-08 13:42:41-04

Detail 10:

Status: Compatible

Hardware Id: 5782

Detail Notes: Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)<p>

Quantity up to 2, depending on number of switch modules installed in chassis.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-10-08 13:42:41-04

Detail 11:

Status: Compatible

Hardware Id: 5782

Detail Notes: Optional Equipment:

<p>

73P9030 IBM BladeCenter (TM) Gigabit Ethernet Expansion Card<p>

<p>

Broadcom based Gigabit Ethernet card which provides two additional ethernet interfaces.

This option also requires that one or more additional ethernet switches be installed in the BladeCenter chassis.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-10-08 13:55:33-04

Detail 12:

Status: Compatible

Hardware Id: 5782

Detail Notes: ****NOTICE**** -- When installing or running the x86_64 port of Red Hat Enterprise

Linux (v.3), you must pass the option `acpi=noirq` to the kernel command line either via

`grub.conf` modification or at the boot: prompt at the start of the installation. Failure

to do so will result in a hang or crash early in the boot process! This option is not

necessary when running the x86 port of Red Hat Enterprise Linux (v.3) on this system. Red Hat

Enterprise Linux (v.3 Update 3) or newer is required for this system.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-10-08 13:56:33-04

Detail 13:

Status: Compatible

Hardware Id: 5782

Detail Notes: Optional Equipment:

```
<p>
48P7061 IBM HS20 Fibre Channel Expansion Card <p>
<p>
Qlogic 2300 based Fiber Channel SCSI HBA tested with the qla2300 kernel module. This option
also requires that one or more Fiber switches be installed in the Bladecenter chassis.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-08 13:57:01-04
```

Additional Certification Notes

No additional certification notes provided

2.1.26. eServer BladeCenter HS20 (8832) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148178>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2003-11-06 18:52:42-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5171

Detail Notes: This is a component designed to fit into a Bladecenter Chassis. The Bladecenter Chassis (8677-1xx) is required for operation.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2003-11-06 18:47:38-05

Detail 2:

Ease of Install: 4

Status: Compatible
Hardware Id: 5171
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-11-06 18:47:45-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: ServerWorks CSB6 RAID/IDE Controller (rev b0)<p>
Tested and certified as an IDE controller ONLY. All RAID functionality MUST be disabled
through BIOS settings prior to installation.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 18:50:24-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: ** Optional **<p>
<p>
Requires addon scsi controller and drive enclosure blade module<p>
SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI
(rev 07)<p>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 18:50:39-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: USB CD-ROM drive<p>
TEAC Model: CD-224E<p>
Part of BladeCenter Chassis<p>
Recognized as a SCSI CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-11-06 18:50:48-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: USB Floppy drive <p>
TEAC Model: FD-05PUB<p>
Part of BladeCenter enclosure<p>
Recognized as a SCSI disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2003-11-06 18:50:59-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: TOSHIBA MK4019GAXB<p>
40000 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-11-06 18:51:09-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: IBM-ESXS Model: ST336732LC<p>
36400 MB<p>
Requires optional SCSI controller and drive enclosure
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-11-06 18:51:16-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-11-06 18:51:33-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5171
Detail Notes: Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)<p>
Quantity up to 2, depending on number of switch modules installed in chassis.
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-11-06 18:51:42-05

Additional Certification Notes

No additional certification notes provided

2.1.27. eServer BladeCenter HS20 (8843) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148739>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-07 16:56:42-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: This is a component designed to fit into a Bladecenter Chassis. The Bladecenter Chassis (8677-1xx) is required for operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2005-01-07 14:33:19-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet (rev 02)<p>Quantity up to 4, with optional Ethernet expansion card installed in HS20 and optional switch modules installed in chassis. Quantity of 2 without optional components.
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-07 14:33:27-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: IBM-ESXS Model: ST336753LC<p>36401 MB<p>
Requires optional SCSI drive enclosure
Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-07 14:33:35-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-07 14:33:42-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: USB CD-ROM drive<p>
TEAC Model: CD-224E<p>
Part of Bladecenter Chassis<p>
Recognized as a SCSI CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-07 14:33:48-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-07 14:34:00-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual
Ultra320 SCSI (rev 08)<p>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-07 14:34:10-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6023
Detail Notes: *OPTIONAL*<p>
Qlogic 2312 FibreChannel Adapter (rev 02)
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-07 14:34:21-05

Detail 9:
Status: Compatible
Hardware Id: 6023
Detail Notes: USB Floppy drive <p>
TEAC Model: FD-05PUB<p>
Part of Bladecenter chassis<p>
Recognized as a SCSI disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-07 16:55:22-05

Detail 10:
Status: Compatible
Hardware Id: 6023
Detail Notes: IBM-ESXS Model: ST973401LC (Internal SCSI drive)
<p> Qty: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-07 16:56:09-05

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7636](#)⁷ We have intermittent system panics/hangs during boot on IBM HS20 8843 Blades, during boot on IBM HS20 8843 blades, x336, x346, x3550 and x3650 servers. Is there a fix or workaround for this issue?

2.1.28. eServer BladeCenter HS20 (8843) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148740>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2005-01-07 16:57:59-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: This is a component designed to fit into a Bladecenter Chassis. The Bladecenter Chassis (8677-1xx) is required for operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2005-01-07 14:34:56-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet (rev 02)
Quantity up to 4, with optional Ethernet expansion card installed in HS20 and optional switch modules installed in chassis. Quantity of 2 without optional components.
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-07 14:34:56-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: IBM-ESXS Model: ST336753LC
36401 MB
Requires optional SCSI drive enclosure
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-07 14:34:56-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-07 14:34:57-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: USB CD-ROM drive<p>
TEAC Model: CD-224E<p>
Part of BladeCenter Chassis<p>
Recognized as a SCSI CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-07 14:34:57-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: USB Floppy drive <p>
TEAC Model: FD-05PUB<p>
Part of BladeCenter enclosure<p>
Recognized as a SCSI disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-07 14:34:57-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-07 14:34:57-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: IBM-ESXS Model: ST973401LC
<p> Qty: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-07 14:34:57-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 6024
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual
Ultra320 SCSI (rev 08)<p>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-07 14:34:57-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 6024

Detail Notes: *OPTIONAL*<p>

Qlogic 2312 FibreChannel Adapter (rev 02)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-07 14:34:57-05

Detail 11:

Ease of Install: 1

Status: Waiting for Authorization

Hardware Id: 6024

Detail Notes: Red Hat Enterprise Linux (v.3 Update 4) or newer is required for installation and full hardware support. In addition, the kernel parameter `acpi=noirq` must be used when booting or installing the system to ensure proper operation.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7636⁸](#) We have intermittent system panics/hangs during boot on IBM HS20 8843 Blades, during boot on IBM HS20 8843 blades, x336, x346, x3550 and x3650 servers. Is there a fix or workaround for this issue?

2.1.29. eServer BladeCenter HS21 (8853) Dual Core Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=213446>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [2361](#)⁹ How do I get the Qlogic iSCSI Expansion Card working with Red Hat Enterprise Linux on IBM BladeCenter HS20, HS21, HS40, LS20, LS21 and LS41?

2.1.30. eServer BladeCenter HS40 (8839) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148308>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-04-01 11:02:30-05

Detail Data:

Detail 1:

Status: Compatible

Hardware Id: 5383

Detail Notes: **** Optional ****

<p>

Requires addon scsi controller and drive enclosure blade module<p>

SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 07)<p>

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-01 10:58:10-05

Detail 2:

Status: Compatible

Hardware Id: 5383

Detail Notes: USB CD-ROM drive<p>

TEAC Model: CD-224E<p>

Part of BladeCenter Chassis<p>

Recognized as a SCSI CD-ROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-01 10:58:21-05

Detail 3:

Status: Compatible
Hardware Id: 5383
Detail Notes: IBM-ESXS Model: ST336732LC<p>
36400 MB<p>
Requires optional SCSI controller and drive enclosure
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-01 10:54:33-05

Detail 4:

Status: Compatible
Hardware Id: 5383
Detail Notes: USB Floppy drive <p>
TEAC Model: FD-05PUB<p>
Part of Bladecenter enclosure<p>
Recognized as a SCSI disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-01 10:58:27-05

Detail 5:

Status: Compatible
Hardware Id: 5383
Detail Notes: TOSHIBA MK4019GAXB<p>
40000 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-01 10:59:13-05

Detail 6:

Status: Compatible
Hardware Id: 5383
Detail Notes: 16 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-01 10:59:43-05

Detail 7:

Status: Compatible
Hardware Id: 5383
Detail Notes: Four gigabit 10/100/1000 ethernet controllers / Intel 82545GM/82546EB
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-01 11:02:06-05

Detail 8:

Status: Compatible
Hardware Id: 5383

Detail Notes: ATI Technologies Inc Radeon RV100 QY [Radeon 7000/VE]
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-01 10:56:59-05

Detail 9:
Status: Compatible
Hardware Id: 5383
Detail Notes: This is a component designed to fit into a Bladecenter Chassis. The Bladecenter Chassis (8677-1xx) is required for operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-04-01 10:57:09-05

Detail 10:
Status: Compatible
Hardware Id: 5383
Detail Notes: ServerWorks CSB6 RAID/IDE Controller (rev b0)<p>
Tested and certified as an IDE controller ONLY. All RAID functionality MUST be disabled through BIOS settings prior to installation.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-04-01 10:57:43-05

Additional Certification Notes

No additional certification notes provided

2.1.31. eServer BladeCenter LS20 (8850) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161125>

Summary

- *Version:* RHEL3-U6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.32. eServer BladeCenter LS21 (7971) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=215516>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [2361](#)¹⁰ How do I get the Qlogic iSCSI Expansion Card working with Red Hat Enterprise Linux on IBM BladeCenter HS20, HS21, HS40, LS20, LS21 and LS41?
- Red Hat Knowledge Base (Article): [7863](#)¹¹ Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.1.33. eServer BladeCenter LS41 (7972) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=214873>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [2361](#)¹² How do I get the Qlogic iSCSI Expansion Card working with Red Hat Enterprise Linux on IBM BladeCenter HS20, HS21, HS40, LS20, LS21 and LS41?
- Red Hat Knowledge Base (Article): [7863](#)¹³ Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.1.34. eServer iSeries 270,800,810,820,825,830,840,870,890 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156400>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* powerpc

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.35. eServer pSeries p5 720 (9124-720) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=195351>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* ppc64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.36. eServer zSeries 800, 890, 900, 990 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=168983>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* s390

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.37. IBM eServer e325 (8835-32Z) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148176>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: AMD64 and Intel(R) EM64T
Created On: 2003-11-06 17:43:06-05
Returned On: mm-dd-yy
Last Touched On: 2003-11-06 17:54:22-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-11-06 17:43:34-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: LG CD-ROM CRN-8245B
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-11-06 17:44:13-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 17:46:17-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: IDE interface: Advanced Micro Devices [AMD] AMD-8111 IDE (rev 03)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 17:47:06-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: IC35L060AVV207-0<p>
40016 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-11-06 17:48:53-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5169
Detail Notes: 6 GB PC2700
Component Class: Memory
Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2003-11-06 17:49:24-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5169

Detail Notes: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet (rev 03)<p>

Qty. 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2003-11-06 17:53:29-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5169

Detail Notes: AMD Opteron(tm) Processor 242<p>

1.6 GHz<p>

Qty: 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2003-11-06 18:15:44-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5169

Detail Notes: USB Controller (2 controllers, 4 external ports)<p>

USB Controller: Advanced Micro Devices [AMD] AMD-8111 USB (rev 0b)<p>

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2003-11-06 18:36:33-05

Additional Certification Notes

No additional certification notes provided

2.1.38. IBM eServer e326 (8848-32Z) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148715>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2005-01-11 16:33:10-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5996
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-19 21:24:02-05

Detail 2:

Status: Compatible
Hardware Id: 5996
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-19 21:24:02-05

Detail 3:

Status: Compatible
Hardware Id: 5996
Detail Notes: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet (rev 03)<p>
Qty. 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-19 21:24:02-05

Detail 4:

Status: Compatible
Hardware Id: 5996
Detail Notes: USB Controller (2 controllers, 4 external ports)<p>
USB Controller: Advanced Micro Devices [AMD] AMD-8111 USB (rev 0b)<p>
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-12-19 21:24:02-05

Detail 5:

Status: Compatible
Hardware Id: 5996
Detail Notes: IBM-ESXS Model: ST336753LC (36401 MB)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-06 23:53:53-05

Detail 6:
Status: Compatible
Hardware Id: 5996
Detail Notes: CD-224E ATAPI CD/DVD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-06 23:54:09-05

Detail 7:
Status: Compatible
Hardware Id: 5996
Detail Notes: SATA Interface: Silicon Image SiI 3512 SATALink/SATAraid Serial ATA Controller (rev 01)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-06 23:54:24-05

Detail 8:
Status: Compatible
Hardware Id: 5996
Detail Notes: 4 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-06 23:54:44-05

Detail 9:
Status: Compatible
Hardware Id: 5996
Detail Notes: AMD Opteron(tm) Processor 246<p>2.0 GHz<p>
Qty: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-06 23:54:59-05

Additional Certification Notes

No additional certification notes provided

2.1.39. IBM eServer e326 (8848-51Y) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148738>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2005-01-11 16:32:31-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6022

Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-01-07 14:38:47-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6022

Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 07)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-07 14:39:01-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6022

Detail Notes: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet (rev 03)<p>

Qty. 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-07 14:39:07-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6022

Detail Notes: USB Controller (2 controllers, 4 external ports)<p>
USB Controller: Advanced Micro Devices [AMD] AMD-8111 USB (rev 0b)<p>
Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2005-01-07 14:39:11-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6022

Detail Notes: IBM-ESXS Model: ST336753LC (36401 MB)

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-01-07 14:39:17-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6022

Detail Notes: CD-224E ATAPI CD/DVD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-01-07 14:39:21-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6022

Detail Notes: SATA Interface: Silicon Image SiI 3512 SATAlink/SATARaid Serial ATA Controller (rev 01)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-07 14:39:27-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6022

Detail Notes: 4 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-01-07 14:39:33-05

Detail 9:

```
Ease of Install: 4
Status: Compatible
Hardware Id: 6022
Detail Notes: AMD Opteron(tm) Processor 246<p>
2.0 GHz<p>
Qty: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-07 14:39:39-05
```

Additional Certification Notes

No additional certification notes provided

2.1.40. IBM eServer xSeries 205 (8480-5AX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148307>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

```
Cpu Name: X86
Last Touched On: 2004-03-30 18:16:02-05
```

Detail Data:

Detail 1:

```
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-03-30 17:55:01-05
```

Detail 2:

```
Ease of Install: 4
```

Status: Compatible
Hardware Id: 5382
Detail Notes: Intel Pentium 4 CPU 2.00GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-30 18:04:05-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: IBM-ESXS Model: ST318305LW
18.2GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-03-30 18:11:11-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: 2GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-03-30 18:12:24-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: Broadcom Corporation NetXtreme BCM5702 Gigabit Ethernet (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-03-30 17:59:16-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: Intel Corp. 82801DB Ultra ATA (IDE) storage controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-03-30 18:09:18-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-03-30 17:59:38-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: Adaptec AIC-7892 U160 SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-03-30 18:11:44-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5382
Detail Notes: LTN486S CD-ROM reader
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-03-30 18:02:05-05

Additional Certification Notes

No additional certification notes provided

2.1.41. IBM eServer xSeries 206 (Type: 8482 Models: 1MU, 1RU, 2MU, 2RU) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148693>

Summary

- *Version:* Update 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-12-15 15:41:08-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5972
Detail Notes: Intel PRO/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-08 14:50:51-05

Detail 2:

Status: Compatible
Hardware Id: 5972
Detail Notes: ATI Radeon 7000
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-08 14:50:51-05

Detail 3:

Status: Compatible
Hardware Id: 5972
Detail Notes: SAMSUNG CD-ROM SC-148C
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-08 14:50:51-05

Detail 4:

Status: Compatible
Hardware Id: 5972
Detail Notes: Intel 2.8 GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-08 14:50:51-05

Detail 5:

Status: Compatible
Hardware Id: 5972
Detail Notes: Intel Corp. Enterprise Southbridge PATA (IDE) controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-08 14:50:51-05

Detail 6:

Status: Compatible
Hardware Id: 5972
Detail Notes: Adaptec AIC-7901A U320 (rev 03) SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-08 14:50:51-05

Detail 7:

Status: Compatible
Hardware Id: 5972
Detail Notes: IBM-ESXS Model: ST336607LC
36.4GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-08 14:50:51-05

Detail 8:

Status: Compatible
Hardware Id: 5972
Detail Notes: 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-08 14:50:51-05

Detail 9:

Status: Compatible
Hardware Id: 5972
Detail Notes: 4GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-08 14:50:51-05

Detail 10:

Status: Compatible
Hardware Id: 5972
Detail Notes: Note: Red Hat Enterprise Linux (v.3 Update 3)
required
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into
another category. Items listed in this group are subject to tests as determined by Red Hat,
Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-12-15 15:40:42-05

Additional Certification Notes

No additional certification notes provided

2.1.42. IBM eServer xSeries 206 (Type: 8482 Models: 34Z, 1MU, 1RU, 2MU, 2RU) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148306>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-03-30 17:24:21-05
Returned On: mm-dd-yy
Last Touched On: 2004-07-26 15:07:11-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5381
Detail Notes: Intel PRO/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-03-30 17:49:55-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5381
Detail Notes: ATI Radeon 7000
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-03-30 17:25:07-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5381
Detail Notes: SAMSUNG CD-ROM SC-148C
Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-03-30 17:26:42-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5381

Detail Notes: Intel 2.8 GHz

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-03-30 17:27:54-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5381

Detail Notes: Intel Corp. Enterprise Southbridge PATA (IDE) controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-03-30 17:30:40-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5381

Detail Notes: Adaptec AIC-7901A U320 (rev 03) SCSI controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-03-30 17:31:49-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5381

Detail Notes: IBM-ESXS Model: ST336607LC

36.4GB

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-03-30 17:37:35-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5381

Detail Notes: 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-03-30 17:38:05-05

```
Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5381
Detail Notes: 4GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-03-30 17:42:00-05
```

Additional Certification Notes

No additional certification notes provided

2.1.43. IBM eServer xSeries 225 (Type:8649 Models: 42X, 4AX, 4BX, 52X, 5AX, 5BX, 62X, 6AX, 6BX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148696>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

```
Additional Data:
```

```
Cpu Name: X86
Last Touched On: 2004-12-14 10:55:49-05
```

```
Detail Data:
```

```
Detail 1:
Status: Compatible
Hardware Id: 5975
Detail Notes: 1.44 Mb<br>
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-13 18:03:02-05
```

```
Detail 2:
Status: Compatible
Hardware Id: 5975
```

Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-12-13 18:06:09-05

Detail 3:

Status: Compatible

Hardware Id: 5975

Detail Notes: GCR-8482B 48X IDE CD-ROM drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-13 18:15:17-05

Detail 4:

Status: Compatible

Hardware Id: 5975

Detail Notes: LSI Logic 53C1030 Dual-channel Ultra 320 SCSI adapter

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-13 18:18:52-05

Detail 5:

Status: Compatible

Hardware Id: 5975

Detail Notes: 2.67 GHz Intel Xeon

(Quantity: 2)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-13 18:20:43-05

Detail 6:

Status: Compatible

Hardware Id: 5975

Detail Notes: IBM-ESXS Model: ST336607LW 36.4GB Ultra320 SCSI 10K RPM

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-13 18:25:39-05

Detail 7:

Status: Compatible

Hardware Id: 5975

Detail Notes: 8 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-13 18:28:11-05

Detail 8:

Status: Compatible

Hardware Id: 5975
Detail Notes: Broadcom NetXtreme BCM5703X Gigabit Ethernet (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-13 18:29:47-05

Additional Certification Notes

No additional certification notes provided

2.1.44. IBM eServer xSeries 226 (Type: 8648 Models: 2Bx, 2Ax, 1Bx, 1Ax, 0Ax, 0Bx) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148719>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-22 13:14:43-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 6001
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-22 13:10:39-05

Detail 2:

Status: Compatible
Hardware Id: 6001
Detail Notes: Intel(R) Xeon(TM) CPU 3.2GHz

Quantity: 2

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-22 13:10:39-05

Detail 3:
Status: Compatible
Hardware Id: 6001
Detail Notes: ATI Technologies Inc Radeon 7000M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-22 13:10:39-05

Detail 4:
Status: Compatible
Hardware Id: 6001
Detail Notes: 6 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-22 13:10:39-05

Detail 5:
Status: Compatible
Hardware Id: 6001
Detail Notes: Adaptec 7902 Dual-Channel U320 SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-22 13:10:39-05

Detail 6:
Status: Compatible
Hardware Id: 6001
Detail Notes: IBM-ESXS DTN036C3UCDY10FN (36401 MB)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-22 13:10:39-05

Detail 7:
Status: Compatible
Hardware Id: 6001
Detail Notes: BROADCOM Corporation NetXtreme BCM5721 Gigabit Ethernet (rev 01)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-22 13:10:39-05

Detail 8:
Status: Compatible
Hardware Id: 6001
Detail Notes: HL-DT-ST GCR-8482B 48x IDE CD-ROM

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-22 13:10:39-05

Detail 9:
Status: Compatible
Hardware Id: 6001
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-22 13:10:40-05

Additional Certification Notes

No additional certification notes provided

2.1.45. IBM eServer xSeries 226 Models: 2Bx, 2Ax, 1Bx, 1Ax, 0Ax, 0Bx) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148714>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-12-22 13:14:33-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5995
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-19 20:28:15-05

Detail 2:

Status: Compatible

Hardware Id: 5995

Detail Notes: Intel(R) Xeon(TM) CPU 3.2GHz

Quantity: 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-19 20:40:26-05

Detail 3:

Status: Compatible

Hardware Id: 5995

Detail Notes: ATI Technologies Inc Radeon 7000M

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-12-19 20:44:32-05

Detail 4:

Status: Compatible

Hardware Id: 5995

Detail Notes: 6 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-19 20:52:16-05

Detail 5:

Status: Compatible

Hardware Id: 5995

Detail Notes: Adaptec 7902 Dual-Channel U320 SCSI controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-19 20:53:22-05

Detail 6:

Status: Compatible

Hardware Id: 5995

Detail Notes: IBM-ESXS DTN036C3UCDY10FN (36401 MB)

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-19 20:55:00-05

Detail 7:

Status: Compatible

Hardware Id: 5995

Detail Notes: BROADCOM Corporation NetXtreme BCM5721 Gigabit Ethernet (rev 01)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-19 20:56:45-05

Detail 8:
Status: Compatible
Hardware Id: 5995
Detail Notes: HL-DT-ST GCR-8482B 48x IDE CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-19 20:57:08-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5995
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-19 21:03:50-05

Additional Certification Notes

No additional certification notes provided

2.1.46. IBM eServer xSeries 235 (Model: 8671-7AX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148216>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2003-12-15 17:40:24-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-12-15 17:38:46-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: LG CD-ROM CRD-8484B
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-12-15 17:39:03-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-12-15 17:39:10-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: 12 Gb
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-12-15 17:39:24-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: BROADCOM Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)
<p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-12-15 17:39:39-05

Detail 6:

Ease of Install: 4
Status: Compatible

```
Hardware Id: 5258
Detail Notes: Intel(R) XEON(TM) CPU 2.80GHz<br>
Qty: 2<br>
<b>NOTE:</b> OS reports 4 CPUs (wiht HyperThreading enabled)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2003-12-15 17:39:48-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: Vendor: IBM-ESXS Model: ST336732LC(36401 MB)<br>
Qty: 3
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation <b>to</b> from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-12-15 17:39:57-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5258
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2003-12-15 17:40:07-05
```

Additional Certification Notes

No additional certification notes provided

2.1.47. IBM eServer xSeries 236 (Model: 8841-21X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148736>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2005-01-17 16:51:20-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6020
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-07 14:41:38-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6020
Detail Notes: ATI Radeon 7000-M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-07 14:41:44-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6020
Detail Notes: HL-DT-ST CD-ROM GCR-84842B 48x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-07 14:41:48-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6020
Detail Notes: IBM ServeRAID 7k RAID Controller (Rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-07 14:41:53-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6020
Detail Notes: 8 GB
Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-01-07 14:41:56-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6020

Detail Notes: Broadcom Corporation NetXtreme BCM5721 Gigabit Ethernet PCI Express (rev 10)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-01-07 14:42:00-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6020

Detail Notes: Intel(R) XEON(TM) CPU 3.20GHz

Qty: 2

NOTE: OS reports 4 CPUS (wiht HyperThreading enabled)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-01-07 14:42:05-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6020

Detail Notes: Vendor: IBM-ESXS Model: ST336607 (34715 MB)

Qty: 3

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-01-07 14:42:23-05

Additional Certification Notes

No additional certification notes provided

2.1.48. IBM eServer xSeries 236 (Model: 8841-21X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148735>

Summary

- *Version: 3*

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-17 16:51:03-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-07 14:42:39-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: ATI Radeon 7000-M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-07 14:42:43-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: HL-DT-ST CD-ROM GCR-84842B 48x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-07 14:42:50-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: IBM ServeRAID 7k RAID Controller (Rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-07 14:42:54-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-07 14:42:58-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: Broadcom Corporation NetXtreme BCM5721 Gigabit Ethernet PCI Express (rev 10)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-07 14:43:03-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: Intel(R) XEON(TM) CPU 3.20GHz
Qty: 2
NOTE: OS reports 4 CPUS (with HyperThreading enabled)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-07 14:43:07-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6019
Detail Notes: Vendor: IBM-ESXS Model: ST336607 (34715 MB)
Qty: 3
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation **to** from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-07 14:43:12-05

Additional Certification Notes

No additional certification notes provided

2.1.49. IBM eServer xSeries 255 (Type: 8685, Models: 71X, 7RX, A1X, ARX, B1X, BRX, C1X, CRX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148560>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-21 18:25:15-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5766
Detail Notes: Make: Adaptec
Model: AIC-7899P
Kernel Module: aic7xxx
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-21 18:21:24-04

Detail 2:

Status: Compatible
Hardware Id: 5766
Detail Notes: Standard 3.5 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 3:

Status: Compatible
Hardware Id: 5766
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.

Modified On: 2004-09-21 18:21:24-04

Detail 4:

Status: Compatible
Hardware Id: 5766
Detail Notes: SAMSUNG CD-ROM SC-148C, ATAPI CD/DVD-ROM drive
ATAPI 48X CD-ROM drive, 128kB Cache
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 5:

Status: Compatible
Hardware Id: 5766
Detail Notes: Make:IBM
Model:ST336704LC
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 6:

Status: Compatible
Hardware Id: 5766
Detail Notes: Intel(R) Xeon(TM) CPU 1.60GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 7:

Status: Compatible
Hardware Id: 5766
Detail Notes: 3.6GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 8:

Status: Compatible
Hardware Id: 5766
Detail Notes: BROADCOM 5703 or BROADCOM 5701 (model dependant)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-21 18:26:32-04

Additional Certification Notes

No additional certification notes provided

2.1.50. IBM eServer xSeries 255 (Type: 8685, Models: 71X,7RX,A1X,ARX,B1X,BRX,C1X,CRX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153948>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-21 18:25:15-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5766
Detail Notes: Make: Adaptec
Model: AIC-7899P
Kernel Module: aic7xxx
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-21 18:21:24-04

Detail 2:

Status: Compatible
Hardware Id: 5766
Detail Notes: Standard 3.5 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 3:

Status: Compatible
Hardware Id: 5766
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.

Modified On: 2004-09-21 18:21:24-04

Detail 4:

Status: Compatible
Hardware Id: 5766
Detail Notes: SAMSUNG CD-ROM SC-148C, ATAPI CD/DVD-ROM drive
ATAPI 48X CD-ROM drive, 128kB Cache
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 5:

Status: Compatible
Hardware Id: 5766
Detail Notes: Make:IBM
Model:ST336704LC
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 6:

Status: Compatible
Hardware Id: 5766
Detail Notes: Intel(R) Xeon(TM) CPU 1.60GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 7:

Status: Compatible
Hardware Id: 5766
Detail Notes: 3.6GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-21 18:21:24-04

Detail 8:

Status: Compatible
Hardware Id: 5766
Detail Notes: BROADCOM 5703 or BROADCOM 5701 (model dependant)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-21 18:26:32-04

Additional Certification Notes

No additional certification notes provided

2.1.51. IBM eServer xSeries 305 (Type: 8673 Models: 72X,73X,82X,83X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148716>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-05 17:46:48-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5998
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-21 00:06:48-05

Detail 2:

Status: Compatible
Hardware Id: 5998
Detail Notes: CD-224E
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-21 00:06:48-05

Detail 3:

Status: Compatible
Hardware Id: 5998
Detail Notes: ServerWorks CSB5 IDE Controller (rev 93)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-21 00:06:48-05

Detail 4:

Status: Compatible
Hardware Id: 5998
Detail Notes: Intel(R) Pentium(R) 4 CPU 2.20GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-21 00:06:48-05

Detail 5:
Status: Compatible
Hardware Id: 5998
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-21 00:06:48-05

Detail 6:
Status: Compatible
Hardware Id: 5998
Detail Notes: BROADCOM Corporation NetXtreme BCM5703X Gigabit Ethernet (rev 02)

Qty: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-21 00:06:48-05

Detail 7:
Status: Compatible
Hardware Id: 5998
Detail Notes: ST340016A (40016 MB)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-21 00:08:00-05

Detail 8:
Status: Compatible
Hardware Id: 5998
Detail Notes: 4 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-21 00:14:37-05

Detail 9:
Ease of Install: 1
Status: Waiting for Authorization
Hardware Id: 5998
Detail Notes: Adaptec(R) 29160LP / single channel Wide Ultra160 SCSI (LVD 160MB/sec)<p>
73X and 83X models only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Additional Certification Notes

No additional certification notes provided

2.1.52. IBM eServer xSeries 330 (8675-4MX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148484>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-08-03 16:40:32-04

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5660
Detail Notes: Make: Intel
Model: EtherExpress Pro 100 (integrated)
Kernel Module: e100
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-03 16:39:38-04

Detail 2:
Status: Compatible
Hardware Id: 5660
Detail Notes: CRN-8241B IDE 24X
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-08-03 16:39:38-04

Detail 3:

Status: Compatible
Hardware Id: 5660
Detail Notes: Controller: Adaptec AIC-7892
Kernel Module: aic7xxx
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-03 16:39:38-04

Detail 4:
Status: Compatible
Hardware Id: 5660
Detail Notes: Make: IBM
Model: Katana 18 SCA
Capacity: 18GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-08-03 16:39:38-04

Detail 5:
Status: Compatible
Hardware Id: 5660
Detail Notes: Standard 1.44MB 3.5
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-08-03 16:39:38-04

Detail 6:
Status: Compatible
Hardware Id: 5660
Detail Notes: Two bay SCA drive cage (one available).
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-08-03 16:39:38-04

Detail 7:
Status: Compatible
Hardware Id: 5660
Detail Notes: Chipset: S3 Savage4/LT
Memory: 8MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-08-03 16:39:38-04

Detail 8:
Status: Compatible
Hardware Id: 5660
Detail Notes: Controller: Serverworks OSB4 On-Board IDE Controller
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-03 16:39:38-04

Detail 9:
Status: Compatible
Hardware Id: 5660
Detail Notes: Make: Intel
Model: Xeon
Speed: 1.4 GHz
Quantity: 1
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-08-03 16:39:39-04

Detail 10:
Status: Compatible
Hardware Id: 5660
Detail Notes: 4GB

The MXT memory compression is not supported by Red Hat. Please disable in the system BIOS prior to production use.
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-08-03 16:39:39-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7778¹⁴](#) Is MXT memory compression is supported by Red Hat on Red Hat Enterprise Linux 3?

2.1.53. IBM eServer xSeries 335 (Model: 8676-11X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148204>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2003-12-04 17:53:43-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: Intel(R) XEON(TM) CPU 2.40GHz

Qty: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2003-12-04 17:54:08-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: 1.44 Mb.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2003-12-04 17:54:22-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: IBM-ESXS ST373405LC (73407 MB)

Qty: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-12-04 17:54:15-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-12-04 17:53:54-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: 4 Gigs.
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-12-04 17:54:29-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: BROADCOM Corporation: Unknown device 16a7 (rev 02)

Qty: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-12-04 17:55:15-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-12-04 17:53:35-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5236
Detail Notes: LG CD-ROM CRN-8245B
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-12-04 17:54:01-05

Additional Certification Notes

No additional certification notes provided

2.1.54. IBM eServer xSeries 343 (Type: 8847 Models:14X,24X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148518>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-08 17:13:30-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5711
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 17:43:15-04

Detail 2:

Status: Compatible
Hardware Id: 5711
Detail Notes: CD-224E CD-ROM reader
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 17:43:15-04

Detail 3:

Status: Compatible
Hardware Id: 5711
Detail Notes: Intel 82801CA Ultra ATA Storage Controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 17:43:15-04

Detail 4:

Status: Compatible
Hardware Id: 5711
Detail Notes: Intel Xeon 2.4 GHZ <p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 17:43:15-04

Detail 5:

Status: Compatible
Hardware Id: 5711
Detail Notes: IBM ESXS Model CBR146C34810ESFN 73GB <p>
Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-07 17:43:15-04

Detail 6:

Status: Compatible

Hardware Id: 5711

Detail Notes: 12 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-07 17:43:15-04

Detail 7:

Status: Compatible

Hardware Id: 5711

Detail Notes: Intel 82546B Gigabit Ethernet Controller <p>
quantity: 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-07 17:43:15-04

Detail 8:

Status: Compatible

Hardware Id: 5711

Detail Notes: Intel 82801CA USB Controller (4 ports)

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-09-07 17:43:15-04

Additional Certification Notes

No additional certification notes provided

2.1.55. IBM eServer xSeries 345 Type: 8670 Models: 61X, 51X, 71X, 91X, G1X, K1X, L1X, M1X, F1X, J1X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148205>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-04-06 17:19:57-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5237
Detail Notes: 1.44M
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 2:

Status: Compatible
Hardware Id: 5237
Detail Notes: CD-224E, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 3:

Status: Compatible
Hardware Id: 5237
Detail Notes: ATI Technologies Inc Rage XL (rev 39)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-12-05 15:32:44-05

Detail 4:

Status: Compatible
Hardware Id: 5237
Detail Notes: LSI 53c1030
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-12-05 15:32:44-05

Detail 5:

Status: Compatible
Hardware Id: 5237
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 6:

Status: Compatible
Hardware Id: 5237
Detail Notes: Intel E1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-12-05 15:32:44-05

Detail 7:
Status: Compatible
Hardware Id: 5237
Detail Notes: Intel(R) XEON(TM) CPU 2.80GHz
<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Additional Certification Notes

No additional certification notes provided

2.1.56. IBM eServer xSeries 345 Type: 8670 Models: 61X,51X,71X,91X,G1X,K1X,L1X,M1X,F1X,J1X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153947>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-04-06 17:19:57-04

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5237

Detail Notes: 1.44M
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 2:
Status: Compatible
Hardware Id: 5237
Detail Notes: CD-224E, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 3:
Status: Compatible
Hardware Id: 5237
Detail Notes: ATI Technologies Inc Rage XL (rev 39)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-12-05 15:32:44-05

Detail 4:
Status: Compatible
Hardware Id: 5237
Detail Notes: LSI 53c1030
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-12-05 15:32:44-05

Detail 5:
Status: Compatible
Hardware Id: 5237
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Detail 6:
Status: Compatible
Hardware Id: 5237
Detail Notes: Intel E1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-12-05 15:32:44-05

Detail 7:
Status: Compatible
Hardware Id: 5237

Detail Notes: Intel(R) XEON(TM) CPU 2.80GHZ
<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2003-12-05 15:32:44-05

Additional Certification Notes

No additional certification notes provided

2.1.57. IBM eServer xSeries 346 (Type: 8840 Models: 01Y, 01U, 11Y, 11U, 21Y, 21U, 31Y, 31U, 41Y, 41U) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148649>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-22 12:42:28-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5882
Detail Notes: ATI 7000M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-16 17:13:11-05

Detail 2:

Status: Compatible
Hardware Id: 5882
Detail Notes: IDE DVD/CD-ROM

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 3:
Status: Compatible
Hardware Id: 5882
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:13:11-05

Detail 4:
Status: Compatible
Hardware Id: 5882
Detail Notes: Intel 3.2GHz Xeon with EM64T<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 5:
Status: Compatible
Hardware Id: 5882
Detail Notes: IBM 73.2GB 15KRPM U320 SCSI drive<p>
Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 6:
Status: Compatible
Hardware Id: 5882
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 7:
Status: Compatible
Hardware Id: 5882
Detail Notes: Broadcom 5721 10/100/1000 ethernet <p>
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-16 17:13:11-05

Detail 8:

Status: Compatible
Hardware Id: 5882
Detail Notes: Red Hat Enterprise Linux (v.3 Update 3) or newer update level required for either 32-bit or 64-bit operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-11-16 17:13:11-05

Detail 9:
Status: Compatible
Hardware Id: 5882
Detail Notes: LSI Logic 53C1020 U320 SCSI<p>
Tested with and without mirroring (RAID1) enabled.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:13:12-05

Detail 10:
Status: Compatible
Hardware Id: 5882
Detail Notes: 1.44M
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program. Must pass the rhr-core tests. Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-22 12:41:29-05

Detail 11:
Status: Compatible
Hardware Id: 5882
Detail Notes: Adaptec(R) AIC-7902 / dual channel Ultra320 SCSI controller (LVD 320MB/sec) - also used as the back-end SCSI controller for the ServRaid 7k
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-22 12:42:19-05

Additional Certification Notes

No additional certification notes provided

2.1.58. IBM eServer xSeries 346 (Type: 8840 Models: 01Y, 01U, 11Y, 11U, 21Y, 21U, 31Y, 31U, 41Y, 41U) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148650>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-12-22 12:40:45-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5883
Detail Notes: ATI 7000M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-16 17:24:56-05

Detail 2:

Status: Compatible
Hardware Id: 5883
Detail Notes: IDE DVD/CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 3:

Status: Compatible
Hardware Id: 5883
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:24:56-05

Detail 4:

Status: Compatible
Hardware Id: 5883
Detail Notes: Intel 3.2GHz Xeon with EM64T<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 5:

Status: Compatible
Hardware Id: 5883
Detail Notes: IBM 36.4GB 15kRPM U320 SCSI drive<p>
Quantity: 3
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 6:
Status: Compatible
Hardware Id: 5883
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 7:
Status: Compatible
Hardware Id: 5883
Detail Notes: Broadcom 5721 10/100/1000 ethernet <p>
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-16 17:24:56-05

Detail 8:
Status: Compatible
Hardware Id: 5883
Detail Notes: IBM ServeRAID 7K<p>
(optional)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:24:56-05

Detail 9:
Status: Compatible
Hardware Id: 5883
Detail Notes: Red Hat Enterprise Linux (v.3 Update 3) <p>
or newer update level required for either 32-bit<p>
or 64-bit operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into
another category. Items listed in this group are subject to tests as determined by Red Hat,
Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-12-22 12:38:42-05

Detail 10:
Status: Compatible
Hardware Id: 5883
Detail Notes: Adaptec(R) AIC-7902 / dual channel Ultra320 SCSI controller (LVD 320MB/sec) -
also used as the back-end SCSI controller for the ServRaid 7k
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-22 12:39:17-05

Detail 11:
Status: Compatible
Hardware Id: 5883
Detail Notes: 1.44M
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-22 12:40:05-05

Additional Certification Notes

No additional certification notes provided

2.1.59. IBM eServer xSeries 346 (Type: 8840 Models: 01Y,01U,11Y,11U,21Y,21U,31Y,31U,41Y,41U) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153951>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-22 12:42:28-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5882
Detail Notes: ATI 7000M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.

Modified On: 2004-11-16 17:13:11-05

Detail 2:

Status: Compatible
Hardware Id: 5882
Detail Notes: IDE DVD/CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 3:

Status: Compatible
Hardware Id: 5882
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:13:11-05

Detail 4:

Status: Compatible
Hardware Id: 5882
Detail Notes: Intel 3.2GHz Xeon with EM64T<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 5:

Status: Compatible
Hardware Id: 5882
Detail Notes: IBM 73.2GB 15kRPM U320 SCSI drive<p>
Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 6:

Status: Compatible
Hardware Id: 5882
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-16 17:13:11-05

Detail 7:

Status: Compatible
Hardware Id: 5882
Detail Notes: Broadcom 5721 10/100/1000 ethernet <p>
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-11-16 17:13:11-05

Detail 8:

Status: Compatible

Hardware Id: 5882

Detail Notes: Red Hat Enterprise Linux (v.3 Update 3) or newer update level required for either 32-bit or 64-bit operation.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-11-16 17:13:11-05

Detail 9:

Status: Compatible

Hardware Id: 5882

Detail Notes: LSI Logic 53C1020 U320 SCSI<p>

Tested with and without mirroring (RAID1) enabled.

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-11-16 17:13:12-05

Detail 10:

Status: Compatible

Hardware Id: 5882

Detail Notes: 1.44M

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-22 12:41:29-05

Detail 11:

Status: Compatible

Hardware Id: 5882

Detail Notes: Adaptec® AIC-7902 / dual channel Ultra320 SCSI controller (LVD 320MB/sec) - also used as the back-end SCSI controller for the ServRaid 7k

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-22 12:42:19-05

Additional Certification Notes

No additional certification notes provided

2.1.60. IBM eServer xSeries 346 (Type: 8840 Models: 01Y,01U,11Y,11U,21Y,21U,31Y,31U,41Y,41U) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153952>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-12-22 12:40:45-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5883
Detail Notes: ATI 7000M
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-16 17:24:56-05

Detail 2:

Status: Compatible
Hardware Id: 5883
Detail Notes: IDE DVD/CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 3:

Status: Compatible
Hardware Id: 5883
Detail Notes: Intel ICH5<p>
Tested as a PATA controller with CD/DVD-ROM driver only.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:24:56-05

Detail 4:

Status: Compatible
Hardware Id: 5883
Detail Notes: Intel 3.2GHz Xeon with EM64T<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 5:

Status: Compatible
Hardware Id: 5883
Detail Notes: IBM 36.4GB 15KRPM U320 SCSI drive<p>
Quantity: 3
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 6:

Status: Compatible
Hardware Id: 5883
Detail Notes: 8 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-16 17:24:56-05

Detail 7:

Status: Compatible
Hardware Id: 5883
Detail Notes: Broadcom 5721 10/100/1000 ethernet <p>
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-16 17:24:56-05

Detail 8:

Status: Compatible
Hardware Id: 5883
Detail Notes: IBM ServeRAID 7K<p>
(optional)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-16 17:24:56-05

Detail 9:

Status: Compatible
Hardware Id: 5883
Detail Notes: Red Hat Enterprise Linux (v.3 Update 3) <p>
or newer update level required for either 32-bit<p>
or 64-bit operation.
Component Class: Other
Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-12-22 12:38:42-05

Detail 10:

Status: Compatible

Hardware Id: 5883

Detail Notes: Adaptec® AIC-7902 / dual channel Ultra320 SCSI controller (LVD 320MB/sec) - also used as the back-end SCSI controller for the ServRaid 7k

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-22 12:39:17-05

Detail 11:

Status: Compatible

Hardware Id: 5883

Detail Notes: 1.44M

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-22 12:40:05-05

Additional Certification Notes

No additional certification notes provided

2.1.61. IBM eServer xSeries 360 (Model: 8686-3RX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148577>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2004-10-20 13:24:50-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5787
Detail Notes: S3 Inc. Savage 4 (rev 06)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-20 13:23:58-04

Detail 2:

Status: Compatible
Hardware Id: 5787
Detail Notes: ATAPI 24X CD-ROM drive, 128kB Cache, UDMA(33)
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-20 13:23:58-04

Detail 3:

Status: Compatible
Hardware Id: 5787
Detail Notes: Adaptec AIC-7892 Ultra 160/m SCSI host adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-20 13:23:58-04

Detail 4:

Status: Compatible
Hardware Id: 5787
Detail Notes: Intel Corporation Pentium 4 Xeon MP, 1.6 Ghz.

Quantity: 4

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-20 13:23:58-04

Detail 5:

Status: Compatible
Hardware Id: 5787
Detail Notes: IBM-PSG Model: ST318404LC 18 Gig.

Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-20 13:23:58-04

Detail 6:

Status: Compatible
Hardware Id: 5787
Detail Notes: 1.44M
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-10-20 13:23:58-04

Detail 7:
Status: Compatible
Hardware Id: 5787
Detail Notes: 8 Gigs
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-20 13:23:59-04

Detail 8:
Status: Compatible
Hardware Id: 5787
Detail Notes: Intel Corporation 82557 [Ethernet Pro 100] (rev 08)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-10-20 13:23:59-04

Additional Certification Notes

No additional certification notes provided

2.1.62. IBM eServer xSeries 365 (Type: 8861 Models: 1RX, 4RX Type: 8862 Models: 1RX, 2RX, 3RX, 4RX, 5RX, 6RX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148255>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-02-25 16:14:39-05
Returned On: mm-dd-yy
Last Touched On: 2004-10-29 13:48:52-04

Detail Data:

Detail 1:

Status: Waiting for Authorization

Hardware Id: 5321

Detail Notes: VGA compatible controller: ATI Technologies Inc Radeon RV100 QY [Radeon 7000/VE]

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Detail 2:

Status: Compatible

Hardware Id: 5321

Detail Notes: CD-224E CD-ROM reader

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-02-25 16:16:28-05

Detail 3:

Status: Compatible

Hardware Id: 5321

Detail Notes: Intel(R) Xeon(TM) MP CPU 2.50GHz<p>

Quantity: 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-02-25 16:18:23-05

Detail 4:

Status: Compatible

Hardware Id: 5321

Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 08)<p>

(Dual Channel, Capable of Hardware RAID 1 (mirroring))

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-25 16:20:53-05

Detail 5:

Status: Compatible

Hardware Id: 5321

Detail Notes: IDE interface: ServerWorks CSB6 RAID/IDE Controller (rev a0)<p>

Tested as an IDE controller with a CD-ROM attached only.

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-25 16:22:37-05

Detail 6:

Status: Compatible

Hardware Id: 5321

Detail Notes: IBM 73.4GB 10k RPM p/n 24P3713

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-02-25 16:29:51-05

Detail 7:
Status: Compatible
Hardware Id: 5321
Detail Notes: 1.44M floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-02-25 16:31:22-05

Detail 8:
Status: Compatible
Hardware Id: 5321
Detail Notes: 32 GB<p>
Memory mirroring also tested (16GB)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-02-25 16:32:27-05

Detail 9:
Status: Compatible
Hardware Id: 5321
Detail Notes: Ethernet controller: Broadcom Corporation NetXtreme BCM5704 Gigabit Ethernet
(rev 02)<p>
Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-02-25 16:33:48-05

Additional Certification Notes

No additional certification notes provided

2.1.63. IBM eServer xSeries 382 (Type: 8834 Models 21X,32X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148355>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: Intel(R) IPF
Created On: 2004-05-19 15:41:53-04
Returned On: mm-dd-yy
Last Touched On: 2004-05-20 16:01:13-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5459
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-05-19 15:42:10-04

Detail 2:

Status: Compatible
Hardware Id: 5459
Detail Notes: Itanium 2 (1.4GHz) Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-05-19 15:52:54-04

Detail 3:

Status: Compatible
Hardware Id: 5459
Detail Notes: Dual-Channel SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X
Fusion-MPT Dual Ultra320 SCSI (rev 07)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-19 15:53:58-04

Detail 4:

Status: Compatible
Hardware Id: 5459
Detail Notes: 16GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-05-19 15:57:27-04

Detail 5:

Status: Compatible
Hardware Id: 5459
Detail Notes: IDE interface: Intel Corp. 82801DB Ultra ATA Storage Controller (rev 02)
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-19 15:55:23-04

Detail 6:

Status: Compatible
Hardware Id: 5459
Detail Notes: PCI bridge: Intel Corp. 82801BA/CA/DB/EB PCI Bridge (rev 82)<p>
ISA bridge: Intel Corp. 82801DB LPC Interface Controller (rev 02)<p>
PIC: Intel Corp. 82870P2 P64H2 I/OxAPIC (rev 04)<p>
PCI bridge: Intel Corp. 82870P2 P64H2 Hub PCI Bridge (rev 04)<p>
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-05-19 15:58:57-04

Detail 7:

Status: Compatible
Hardware Id: 5459
Detail Notes: IBM-ESXS Model: ST336607LC (36GB) Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-05-19 15:57:07-04

Detail 8:

Status: Compatible
Hardware Id: 5459
Detail Notes: Ethernet controller: Intel Corp. 82546EB Gigabit Ethernet Controller (Copper)
(rev 01) Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-05-19 16:00:24-04

Detail 9:

Status: Compatible
Hardware Id: 5459
Detail Notes: Slimtype COMBO LSC-24081M (DVD/CD-RW/CD-ROM drive)
<p>
The use of ide-scsi on this system has been known to cause problems with writing CD's.
Problems may also exist when using it for reading as well. The ide-scsi module is
automatically loaded by the installer. You will need to follow the steps below after
installation to disable ide-scsi and use the drive as a normal IDE/ATAPI device.
<p>
1.) Modify /etc/elilo.conf and remove all instances of hda=ide-scsi (depending on system
configuration, it may be an ide device other than hda)
<p>
2.) Save this file and reboot your system.
<p>
3.) Verify that /dev/cdrom points to the IDE cdrom device from step 1, NOT /dev/scd0. (This
should automatically happen as a result of step 2)
<p>
Your CD/DVD drive should now function normally as a reader.
<p>
CD-Writing instructions:
<p>

Red Hat Enterprise Linux 3 supports writing of CD's through the ATAPI interface. To use `cdrecord` with an ATAPI device, you will need to modify the command line slightly:

```
<p>
Finding the location of your CD writer on the ATAPI bus:
<p>
cdrecord -dev=ATAPI --scanbus
<p>
Your command line output should look something like:
<p>
Cdrecord 2.0 (ia64-unknown-linux-gnu) Copyright (C)
<p>
scsibus0:
<p>
0,0,0 0) 'HL-DT-ST' 'RW/DVD GCC-4160N' '0012' Removable CD-ROM
<p>
0,1,0 1) *
<p>
0,2,0 2) *
<p>
0,3,0 3) *
<p>
0,4,0 4) *
<p>
0,5,0 5) *
<p>
0,6,0 6) *
<p>
0,7,0 7) *
<p>
```

Once you have found the location of the CD writer on the ATAPI bus, in this case 0,0,0, you are now ready to begin writing.

To use `cdrecord` to write a .iso file to a blank CD-R/CD-RW you would use a command like:

```
<p>
cdrecord -dev=ATAPI:0,0,0 /path/to/cdimage.iso
<p>
```

The ATAPI: in the dev= statement tells `cdrecord` to use ATAPI bus rather than its default of SCSI.

```
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-05-19 15:51:42-04
```

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7776](#)¹⁵ How do I solve problems with writing to a CD if I use the `ide-scsi` module on a IBM eServer xseries 450 (Model: 8688-5RX) running Red Hat Enterprise Linux 3?

2.1.64. IBM eServer xSeries 440 (Model: 8687-2RX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148496>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-08-17 16:05:41-04
Returned On: mm-dd-yy
Last Touched On: 2004-08-17 16:32:08-04

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5678
Detail Notes: S3 Inc. Savage 4 (rev 06)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-08-17 16:06:03-04

Detail 2:

Status: Compatible
Hardware Id: 5678
Detail Notes: LG CDRom CRN-8245B
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-08-17 16:06:50-04

Detail 3:

Status: Compatible
Hardware Id: 5678
Detail Notes: Adaptec AIC-7892 Ultra 160/m SCSI host adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-17 16:07:47-04

Detail 4:

Status: Compatible
Hardware Id: 5678
Detail Notes: Intel Corporation Pentium 4 Xeon MP, 1.5 Ghz.

Quantity: 8

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.

Component Notes: None
Modified On: 2004-08-17 16:08:42-04

Detail 5:
Status: Compatible
Hardware Id: 5678
Detail Notes: IBM-PSG Model: ST318404LC 18 Gig.

Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-08-17 16:10:20-04

Detail 6:
Status: Compatible
Hardware Id: 5678
Detail Notes: 1.44 MB floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-08-17 16:12:30-04

Detail 7:
Status: Compatible
Hardware Id: 5678
Detail Notes: 16 GB
<p>
The smp kernel shipped with RHEL 3 contains the needed Summit architecture support for this system so there is no need to install a separate Summit kernel as was the case in RHEL 2.1.
<p>
The hugemem kernel is recommended for systems with >12 GB of RAM for certain workloads, however, please read all documentation pertaining to the hugemem kernel before use.
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-08-17 16:20:48-04

Detail 8:
Status: Compatible
Hardware Id: 5678
Detail Notes: Broadcom NetExtreme BCM5700<p>
The Red Hat supplied tg3 driver was used for network testing and is the recommended driver for this system.
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-17 16:21:57-04

Detail 9:
Status: Compatible
Hardware Id: 5678
Detail Notes: USB support:<p>
<p>
If you require USB functionality, please install BIOS level 1.11 or newer. This BIOS level will enable proper functionality of the USB ports at the rear of the machine. However, due to some resource conflicts and other issues unresolvable in the RHEL 3 release cycle, the USB port on the front of the machine is not functional. Should you need this port to function

for a period of time, you may boot the uni-processor kernel. Note that this kernel will only support 1 CPU and 4GB of RAM so you will need to reboot with either the hugemem or smp kernels as appropriate to regain full usage of the CPUs and RAM.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-08-17 16:29:36-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7789¹⁶](#) How can I get my USB functionality working on IBM eServer xSeries 440 (Model: 8687-2RX) on Red Hat Enterprise Linux 3?

2.1.65. IBM eServer xSeries 445 Type: 8870 Models: 1RX, 2RX, 4RX, 12X, 22X, 42X, 3EX, 4EX, 3RY, 4RY Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148179>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2003-11-06 19:01:39-05
Returned On: mm-dd-yy
Last Touched On: 2004-04-15 17:38:03-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-11-06 19:01:54-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: HL-DT-STDVD-ROM GDR8081N
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-11-06 19:02:48-05

Detail 3:

Status: Compatible
Hardware Id: 5182
Detail Notes: Intel(R) Xeon(TM) MP CPU 2.80GHz
<p>
Qty. 8
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-30 11:11:30-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (rev 07)<p>
Dual Channel
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 19:10:03-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: IBM-ESXS Model: MAP3147NC <p>
146815 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2003-11-06 19:16:21-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: removable floppy disk drive.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2003-11-06 19:16:37-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5182

Detail Notes: BROADCOM Corporation: 5704 Gigabit Ethernet<p>

Qty: 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-03-30 11:12:01-05

Detail 8:

Status: Compatible

Hardware Id: 5182

Detail Notes: 32GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-04-08 10:59:27-04

Additional Certification Notes

No additional certification notes provided

2.1.66. IBM eServer xSeries 445 Type: 8870 Models: 1RX,2RX,4RX,12X,22X,42X,3EX,4EX,3RY,4RY Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153953>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)

Cpu Name: X86

Created On: 2003-11-06 19:01:39-05

Returned On: mm-dd-yy

Last Touched On: 2004-04-15 17:38:03-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-11-06 19:01:54-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: HL-DT-STDVD-ROM GDR8081N
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2003-11-06 19:02:48-05

Detail 3:

Status: Compatible
Hardware Id: 5182
Detail Notes: Intel(R) Xeon(TM) MP CPU 2.80GHz
<p>
Qty. 8
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-30 11:11:30-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (rev 07)<p>
Dual Channel
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 19:10:03-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5182
Detail Notes: IBM-ESXS Model: MAP3147NC <p>
146815 MB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2003-11-06 19:16:21-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5182

Detail Notes: removable floppy disk drive.

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2003-11-06 19:16:37-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5182

Detail Notes: BROADCOM Corporation: 5704 Gigabit Ethernet<p>

Qty: 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-03-30 11:12:01-05

Detail 8:

Status: Compatible

Hardware Id: 5182

Detail Notes: 32GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-04-08 10:59:27-04

Additional Certification Notes

No additional certification notes provided

2.1.67. IBM eServer xseries 450 (Model: 8688-5RX) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148249>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Cpu Name: Intel(R) IPF
Last Touched On: 2004-02-16 16:09:59-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5308
Detail Notes: Itanium 2 1.4GHz
<p>
Quantity 4
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-02-16 15:38:25-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5308
Detail Notes: VGA compatible controller: ATI Technologies Inc Rage XL (rev 39)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-02-16 15:38:58-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5308
Detail Notes: IDE interface: VIA Technologies, Inc. Bus Master IDE (rev 6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-16 15:39:08-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5308
Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (#2)
(rev 7)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-16 15:39:17-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5308
Detail Notes: Broadcom 5704 Gigabit Ethernet Adapter<p>

Quantity: 2
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-02-16 15:39:25-05

Detail 6:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5308
 Detail Notes: IBM-ESXS Model: ST336732LC (35GB)
 <p>

Quantity: 2
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-02-16 15:39:33-05

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5308
 Detail Notes: 32GB
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-02-16 15:39:51-05

Detail 8:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5308
 Detail Notes: HL-DT-STCD-RW/DVD Drive GCC-4160N<p><p>

The use of ide-scsi on this system has been known to cause problems with writing CD's. Problems may also exist when using it for reading as well. The ide-scsi module is automatically loaded by the installer. You will need to follow the steps below after installation to disable ide-scsi and use the drive as a normal IDE/ATAPI device.

<p>
 1.) Modify /etc/elilo.conf and remove all instances of hda=ide-scsi (depending on system configuration, it may be an ide device other than hda)<p>
 2.) Save this file and reboot your system.<p>
 3.) Verify that /dev/cdrom points to the IDE cdrom device from step 1, NOT /dev/scd0. (This should automatically happen as a result of step 2)<p>

<p>
 Your CD/DVD drive should now function normally as a reader.
 <p>

CD-Writing instructions:<p>

Red Hat Enterprise Linux 3 supports writing of CD's through the ATAPI interface. To use cdrecord with an ATAPI device, you will need to modify the command line slightly:<p>

Finding the location of your CD writer on the ATAPI bus: <p>
 cdrecord -dev=ATAPI --scanbus<p>

Your command line output should look something like:<p>

Cdrecord 2.0 (ia64-unknown-linux-gnu) Copyright (C)<p> 1995-2002 J�rg Schilling<p>

scsidev: 'ATAPI'<p>

devname: 'ATAPI'<p>

scsibus: -2 target: -2 lun: -2<p>

Warning: Using ATA Packet interface.<p>

Warning: The related libscg interface code is in pre alpha.<p>

```
Warning: There may be fatal problems.<p>
Using libscg version 'schily-0.7'<p>
scsibus0:<p>
  0,0,0    0) 'HL-DT-ST' 'RW/DVD GCC-4160N' '0012' Removable CD-ROM<p>
  0,1,0    1) *<p>
  0,2,0    2) *<p>
  0,3,0    3) *<p>
  0,4,0    4) *<p>
  0,5,0    5) *<p>
  0,6,0    6) *<p>
  0,7,0    7) *<p>
Once you have found the location of the CD writer on the ATAPI bus, in this case 0,0,0, you
are now ready to begin writing.<p>
To use cdrecord to write a .iso file to a blank CD-R/CD-RW you would use a command like:<p>
cdrecord -dev=ATAPI:0,0,0 /path/to/cdimage.iso<p>
The ATAPI: in the dev= statement tells cdrecord to use ATAPI bus rather than its default of
SCSI. <p>
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-02-16 16:09:51-05
```

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7776](#)¹⁷ How do I solve problems with writing to a CD if I use the ide-scsi module on a IBM eServer xseries 450 (Model: 8688-5RX) running Red Hat Enterprise Linux 3?

2.1.68. IBM eServer xseries 455 (Model: 8855-1RZ) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148310>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Cpu Name: Intel(R) IPF
Last Touched On: 2004-04-02 17:50:39-05

Detail Data:

Detail 1:

Status: Compatible

Hardware Id: 5388

Detail Notes: VGA compatible controller: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-04-02 17:48:19-05

Detail 2:

Status: Compatible

Hardware Id: 5388

Detail Notes: Broadcom 5704 Gigabit Ethernet Adapter<p>

Quantity: 2 per node, total of 4 tested.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-04-02 17:49:16-05

Detail 3:

Status: Compatible

Hardware Id: 5388

Detail Notes: SCSI storage controller: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (#2)
(rev 7)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-02 17:40:17-05

Detail 4:

Status: Compatible

Hardware Id: 5388

Detail Notes: IBM-ESXS Model: ST336732LC (35GB)

<p>

Quantity: 2

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-04-02 17:40:17-05

Detail 5:

Status: Compatible

Hardware Id: 5388

Detail Notes: Itanium 2 1.3GHZ

<p>

Quantity 8

<p>

2-node system was tested, 4 CPU's per node.

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-02 17:46:03-05

Detail 6:

Status: Compatible

Hardware Id: 5388

Detail Notes: IDE interface: VIA Technologies, Inc. VT82C586A/B/VT82C686/A/B/VT8233/A/C/VT8235 PIPC Bus Master IDE (rev 06)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-02 17:47:53-05

Detail 7:

Status: Compatible

Hardware Id: 5388

Detail Notes: 32GB (16 GB per node)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-04-02 17:50:10-05

Detail 8:

Ease of Install: 1

Status: Waiting for Authorization

Hardware Id: 5388

Detail Notes: HL-DT-STCD-RW/DVD Drive GCC-4160N

The use of ide-scsi on this system has been known to cause problems with writing CD's. Problems may also exist when using it for reading as well. The ide-scsi module is automatically loaded by the installer. You will need to follow the steps below after installation to disable ide-scsi and use the drive as a normal IDE/ATAPI device.

- 1.) Modify /etc/elilo.conf and remove all instances of hda=ide-scsi (depending on system configuration, it may be an ide device other than hda)
- 2.) Save this file and reboot your system.
- 3.) Verify that /dev/cdrom points to the IDE cdrom device from step 1, NOT /dev/scd0. (This should automatically happen as a result of step 2)

Your CD/DVD drive should now function normally as a reader.

CD-Writing instructions:

Red Hat Enterprise Linux 3 supports writing of CD's through the ATAPI interface. To use cdrecord with an ATAPI device, you will need to modify the command line slightly:

Finding the location of your CD writer on the ATAPI bus:

```
cdrecord -dev=ATAPI --scanbus
```

Your command line output should look something like:

```
Cdrecord 2.0 (ia64-unknown-linux-gnu) Copyright (C)
```

```
1995-2002 J&#65533;rg Schilling
```

```
scsidev: 'ATAPI'
```

```
devname: 'ATAPI'
```

```
scsibus: -2 target: -2 lun: -2
```

```
Warning: Using ATA Packet interface.
```

```
Warning: The related libscg interface code is in pre alpha.
```

```
Warning: There may be fatal problems.
```

```
Using libscg version 'schily-0.7'
```

```
scsibus0:
```

```
0,0,0 0) 'HL-DT-ST' 'RW/DVD GCC-4160N' '0012' Removable CD-ROM
```

```
0,1,0 1) *
```

```
0,2,0 2) *
```

```
0,3,0 3) *
```

```
0,4,0 4) *
```

```
0,5,0 5) *
```

```
0,6,0 6) *
```

```
0,7,0 7) *
```

Once you have found the location of the CD writer on the ATAPI bus, in this case 0,0,0, you are now ready to begin writing.

To use `cdrecord` to write a `.iso` file to a blank CD-R/CD-RW you would use a command like:

```
cdrecord -dev=ATAPI:0,0,0 /path/to/cdimage.iso
```

The ATAPI: in the `dev=` statement tells `cdrecord` to use ATAPI bus rather than its default of SCSI.

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the `rhrcore` tests.

Must pass the `rhrcdromdata` test.

Component Notes: None

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7776¹⁸](#) How do I solve problems with writing to a CD if I use the `ide-scsi` module on a IBM eServer xseries 450 (Model: 8688-5RX) running Red Hat Enterprise Linux 3?

2.1.69. IBM HS20 blade (8678-41X) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148177>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2003-11-06 18:03:29-05
Returned On: mm-dd-yy
Last Touched On: 2003-11-06 18:40:26-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: This is a component designed to fit into a Bladecenter Chassis. The Bladecenter Chassis (8677-1xx) is required for operation.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2003-11-06 18:03:44-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2003-11-06 18:12:27-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: ServerWorks CSB5 IDE Controller (rev 93)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-11-06 18:22:21-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: ** Optional **<p>
<p>
Requires addon scsi controller and drive enclosure blade module<p>

SCSI storage controller: LSI Logic / Symbios Logic 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI (rev 07)<p>

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2003-11-06 18:25:00-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5170

Detail Notes: USB CD-ROM drive<p>

TEAC Model: CD-224E<p>

Part of BladeCenter Chassis<p>

Recognized as a SCSI CD-ROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2003-11-06 18:32:13-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5170

Detail Notes: USB Floppy drive <p>

TEAC Model: FD-05PUB<p>

Part of BladeCenter enclosure<p>

Recognized as a SCSI disk drive.

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2003-11-06 18:32:47-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5170

Detail Notes: TOSHIBA MK4019GAXB<p>

40000 MB

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2003-11-06 18:39:52-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5170

Detail Notes: IBM-ESXS Model: ST336732LC<p>

36400 MB<p>

Requires optional SCSI controller and drive enclosure

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None
Modified On: 2003-11-06 18:40:07-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: 2 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-11-06 18:45:07-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5170
Detail Notes: Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)<p>
Quantity up to 2, depending on number of switch modules installed in chassis.
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-11-06 18:45:17-05

Additional Certification Notes

No additional certification notes provided

2.1.70. IBM Intellistation A Pro (Type: 6224 Models: 37U,38U,39U) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148417>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: AMD64 and Intel(R) EM64T
Created On: 2004-07-07 10:43:45-04
Returned On: mm-dd-yy

Last Touched On: 2004-07-07 16:24:04-04

Detail Data:

Detail 1:

Status: Compatible

Hardware Id: 5571

Detail Notes: Nvidia QuadroFX 3000

(2D video only using the XFree86 nv driver)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-07 10:46:28-04

Detail 2:

Status: Compatible

Hardware Id: 5571

Detail Notes: HL-DT-ST GCE-8483B

CDROM/CD-RW drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-07 10:59:51-04

Detail 3:

Status: Compatible

Hardware Id: 5571

Detail Notes: AMD-8111 busmaster IDE controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-07-07 11:41:22-04

Detail 4:

Status: Compatible

Hardware Id: 5571

Detail Notes: System tested with RHEL 3 x86 and x86_64 releases. Optional equipment (i.e. video cards) also tested.

Component Class: Other

Component Test: Determined on a case by case basis.

Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.

Modified On: 2004-07-07 11:51:08-04

Detail 5:

Status: Compatible

Hardware Id: 5571

Detail Notes: Nvidia Quadro4 280NVS

(2D video only using the XFree86 nv driver)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.
Modified On: 2004-07-07 10:44:31-04

Detail 6:
Status: Compatible
Hardware Id: 5571
Detail Notes: AMD Opteron model 246<p>
2.0 GHz<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-07 11:01:22-04

Detail 7:
Status: Compatible
Hardware Id: 5571
Detail Notes: AMD-8111 AC97 Audio
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-07 11:42:59-04

Detail 8:
Status: Compatible
Hardware Id: 5571
Detail Notes: 8GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-07 15:43:41-04

Detail 9:
Status: Compatible
Hardware Id: 5571
Detail Notes: Nvidia QuadroFX 1100

(2D video only using the XFree86 nv driver)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-07 10:45:52-04

Detail 10:
Status: Compatible
Hardware Id: 5571
Detail Notes: Adaptec AIC7902W dual channel U320 LVD SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-07 11:37:06-04

Detail 11:
Status: Compatible
Hardware Id: 5571
Detail Notes: IBM-ESXS DTN036W3UWDY10FN (36.4GB SCSI drive)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.

Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-07 11:46:04-04

Detail 12:
Status: Compatible
Hardware Id: 5571
Detail Notes: Broadcom BCM5703X 10/100/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-07 11:49:02-04

Additional Certification Notes

No additional certification notes provided

2.1.71. IBM Intellistation A Pro (Type: 6224 Models: 37U,38U,39U) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148448>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-07-22 17:37:06-04

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5616
Detail Notes: Nvidia QuadroFX 3000

(2D video only using the XFree86 nv driver)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-22 17:32:20-04

Detail 2:
Status: Compatible
Hardware Id: 5616
Detail Notes: HL-DT-ST GCE-8483B

CDROM/CD-RW drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-22 17:32:20-04

Detail 3:
Status: Compatible
Hardware Id: 5616
Detail Notes: AMD-8111 busmaster IDE controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-22 17:32:20-04

Detail 4:
Status: Compatible
Hardware Id: 5616
Detail Notes: System tested with RHEL 3 x86 and x86_64 releases. Optional equipment (i.e. video cards) also tested.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-07-22 17:32:20-04

Detail 5:
Status: Compatible
Hardware Id: 5616
Detail Notes: Nvidia Quadro4 280NVS

(2D video only using the XFree86 nv driver)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-22 17:32:20-04

Detail 6:
Status: Compatible
Hardware Id: 5616
Detail Notes: AMD Opteron model 246<p>2.0 GHz<p>
Quantity: 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.

Component Notes: None
Modified On: 2004-07-22 17:32:20-04

Detail 7:
Status: Compatible
Hardware Id: 5616
Detail Notes: AMD-8111 AC97 Audio
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-22 17:32:20-04

Detail 8:
Status: Compatible
Hardware Id: 5616
Detail Notes: Nvidia QuadroFX 1100

(2D video only using the XFree86 nv driver)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-22 17:32:20-04

Detail 9:
Status: Compatible
Hardware Id: 5616
Detail Notes: Adaptec AIC7902W dual channel U320 LVD SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-22 17:32:20-04

Detail 10:
Status: Compatible
Hardware Id: 5616
Detail Notes: IBM-ESXS DTN036W3UWDY10FN (36.4GB SCSI drive)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-22 17:32:20-04

Detail 11:
Status: Compatible
Hardware Id: 5616
Detail Notes: Broadcom BCM5703X 10/100/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-22 17:32:20-04

Detail 12:
Status: Compatible
Hardware Id: 5616
Detail Notes: 8GB

If you use > 4GB of RAM with the x86 release on this system, you need to manually install the i686 SMP kernel regardless of the number of processors installed.

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-07-22 17:36:40-04

Additional Certification Notes

No additional certification notes provided

2.1.72. IBM IntelliStation M Pro (Type: 6230) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153920>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2005-02-03 18:41:25-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6084

Detail Notes: nVidia Quadro4 580 XGL (rev a2)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-02-03 16:56:09-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6084

Detail Notes: HL-DT-ST GCR-8480B 48X ATAPI CD-ROM

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-03 17:48:59-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 6084
Detail Notes: Intel Pentium 4 3.0GHz

800MHz front side bus

HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 17:51:27-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6084
Detail Notes: Adaptec AIC 7901 U320 Single Channel SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-03 17:51:52-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6084
Detail Notes: Intel ICH5
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-03 17:52:40-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6084
Detail Notes: Standard 3.5 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 17:53:05-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6084
Detail Notes: IBM-ESXS ST336607LW 36GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-02-03 18:29:13-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6084

Detail Notes: Intel Kenai II CSA Gigabit Ethernet

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-02-03 18:30:21-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6084

Detail Notes: 4 GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-02-03 18:31:15-05

Additional Certification Notes

No additional certification notes provided

2.1.73. IBM System x3200 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=215455>

Summary

- *Version:* RHEL3-U8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.74. IBM System x3250 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=215471>

Summary

- *Version:* RHEL3-U8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.75. IntelliStation M Pro (6218) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187915>

Summary

- *Version:* RHEL3-U5
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.76. IntelliStation M Pro (6218) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=217492>

Summary

- *Version:* Update 8
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         scat
Model:        387493A
Vendor:       IBM
Category:     Desktop/Workstation
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: Shadowcat_rhelU8x86_cpuPresler3.6GHz_Meory8GB_20061115.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/94fd80a4af169a7f92f003a49d727c80/
Shadowcat_rhelU8x86_cpuPresler3.6GHz_Meory8GB_20061115.noarch.rpmPlease note the following
failures:
WARNING: Kickstart file not found for required tests check.
```

```
0  PASSED  INFO
   PASSED  MEMORY
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.77. IntelliStation M Pro (9229) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=222607>

Summary

- *Version:* Update 8
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.78. IntelliStation Z Pro (6223) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=218582>

Summary

- *Version:* Update 8
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [3523¹⁹](#) How do I get my HostRaid device working on Red Hat Enterprise Linux 4 update 4 and Red Hat Enterprise Linux3 update 8 on the IBM IntelliStation Z Pro (6223)?

2.1.79. S/390 Parallel Enterprise Servers Generation 5 and Generation 6 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161490>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* s390

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.80. Server x x3850 (8864) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=228833>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.81. System x3455 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=227187>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.82. System x3550 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203624>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         System X
Model:        x3550
Vendor:       IBM
Category:     Server
Kernel Version: kernel-hugemem-2.4.21-47.EL
File Uploaded: x3550R3_32.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/ae12a69454f86606881b3e865b56f03a/
x3550R3_32.rpmPlease note the following failures:
WARNING: Kickstart file not found for required tests check.

0  PASSED  INFO
   PASSED  MEMORY
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.83. System x3550 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=195553>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7827](#)²⁰ What is the procedure to get the latest IBM "networking" drivers for any x86 server?

2.1.84. System x3650 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203608>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         System X
Model:        x3650
Vendor:       IBM
Category:     Server
Kernel Version: kernel-hugemem-2.4.21-47.EL
File Uploaded: x3650R3_32.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/815f89900f9925453178bd518df226a0/
x3650R3_32.rpmPlease note the following failures:
WARNING: Kickstart file not found for required tests check.
```

```
0  PASSED  INFO
   PASSED  MEMORY
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.85. System x3650 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=196283>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7827²¹](#) What is the procedure to get the latest IBM "networking" drivers for any x86 server?

2.1.86. System x3655 Server**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=227681>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.87. System x3755 (8877) Server**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=217334>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7863](#)²² Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.1.88. System x3800 (8865) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194065>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7869](#)²³ What is the procedure to get the latest "ServeRAID-8i" drivers for an IBM System x server?

2.1.89. System x3850 (8863) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=208175>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.90. System x x3455 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=238478>

Summary

- *Version:* RHEL3-U8
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         System x
Model:        x3455
Vendor:       IBM
Category:     Server
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: x3455r2_364_LSI.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/1c1717412671fc83908c948a46f2466d/x3455r2\_364\_LSI.noarch.rpmPlease note the following failures:
WARNING: Kickstart file not found for required tests check.
```

```
0  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

2.1.91. System x x3500 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=201331>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.92. System x x3655 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=238919>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         System x
Model:        x3655
Vendor:       IBM
Category:     Server
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: x3655_R3_32_C.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/78e26e17991bf37f5fc48b23c7fb0eb0/x3655\_R3\_32\_C.noarch.rpm
Please note the following failures:
WARNING: Kickstart file not found for required tests check.
```

```
0  PASSED  INFO
   PASSED  CORE
1  PASSED  INFO
   PASSED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.1.93. System x x3800 (8866) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=234047>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.1.94. System x x3950 (8872) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=233518>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386

Additional Comments

2 nodes are supported on RHEL3 32-bit; 1 node is supported using RHEL3 64-bit.

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7869](#)²⁴ What is the procedure to get the latest "ServeRAID-8i" drivers for an IBM System x server?
- Red Hat Knowledge Base (Article): [7872](#)²⁵ What is the procedure to get the latest "SAS" drivers for a System x server?

2.1.95. System x x3950 (8878) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=234614>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

2 nodes are supported on RHEL3 32-bit; 1 node is supported using RHEL3 64-bit.

Additional Certification Notes

No additional certification notes provided

2.2. Intel Corporation

2.2.1. - SE7221BK1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=159734>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.2.2. Intel SE7320SP2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148441>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-07-20 19:09:29-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Generic 1.44M IDE Floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-15 18:34:06-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Intel Corp. 6300ESB USB2 Enhanced Host Controller (rev 02)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 18:34:57-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Vendor: Seagate Model: ST320014A, Ultra ATA/100 Disk drive

Qty: 1

Vendor: Hitachi Model: HDS722516VLAT80, Ultra ATA/100 Disk drive

Qty: 1

Vendor: Western Digital Model: WD360GD-00FN, SATA Disk drive

Qty: 1

Vendor: Seagate Model: ST3120026AS, SATA Disk drive

Qty:1

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-15 18:36:59-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Intel Corp. 6300ESB PATA Storage Controller (rev 02)

Note: Requires Red Hat Enterprise Linux Update 2 or later for proper installation and function

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 18:37:35-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Intel Corp. 6300ESB SATA Storage Controller (rev 02)

Note: Requires Red Hat Enterprise Linux Update 2 or later for proper installation and function

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 18:38:31-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: 8G
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-15 18:32:09-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: TEAC CD-552E, 52x IDE CDRom drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium. Must pass the rhr-core tests. Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 18:38:03-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller (rev 05)
Quantity: 1
Component Class: Network Interface
Component Test: Must complete a network install. Must pass the rhr-core tests. Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 18:32:50-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609

Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 18:33:07-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5609
Detail Notes: Intel(R) Xeon(TM) CPU 3.60Ghz

Quantity: 2

Hyperthreading capable<p>
NOTE: see knowledgebase for 64-bit OS support details.
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-15 15:50:19-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7492](#)²⁶ My 64-bit capable system is only listed as certified for X86; is it considered supported if running under a 64-bit Red Hat operating system?

2.2.3. Intel SE7501WV2-ATA Server

Original Catalog Posting URL

<http://hardware.redhat.com/show.cgi?id=148330>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-04-22 13:30:57-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412
Detail Notes: 12G
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-22 13:34:15-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-22 13:33:00-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412
Detail Notes: MATSHITADVD-ROM SR-8177, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-04-22 13:34:03-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412
Detail Notes: SAMSUNG SP8004H, ATA DISK drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-22 13:34:27-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412
Detail Notes: Intel Corp. 82546EB Gigabit Ethernet Controller (rev 01)

Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-22 13:35:11-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5412

Detail Notes: Vendor: SEAGATE Model: ST380021A, ATA DISK drive

Qty: 2

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-04-22 13:35:26-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5412

Detail Notes: Intel(R) Xeon(TM) CPU 3.20Ghz

Quantity: 2

Hyperthreading capable

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-22 13:35:37-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5412

Detail Notes: Intel Corp. 82801CA/CAM USB (Hub #1) (rev 02)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-22 13:36:30-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5412

Detail Notes: IDE interface: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

Installing and Booting Linux on the Promise Ultra TX2000 Lite Controller

1. Boot the system using Redhat Linux Bootable CD ROM Disk.

2. At the "boot:" prompt type:


```
expert ide0=0x1f0,0x3f6 ide1=0x170,0x376 ide2=0x1400,0x140a ide3=0x1410,0x140e<br>
```

3. Continue with the Red Hat installation as normal.

4. At the Boot Loader Configuration Menu type the following the Kernel Parameters field:


```
ide0=0x1f0,0x3f6 ide1=0x170,0x376 ide2=0x1400,0x140a ide3=0x1410,0x140e<br><br>
```

* Note: These values will be "appended" to lilo.conf or grub.conf.

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-06-07 11:55:40-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7794](#)²⁷ How do I install and boot Red Hat Enterprise Linux 3 on the Promise Ultra TX2000 Lite Controller?

2.2.4. Intel SE7501WV2-SCSI Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148389>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-04 11:29:10-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-04 11:17:53-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: 12G
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-04 10:58:10-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Intel SRCZCR RAID controller (module: gdth)

NOTE: Use of this RAID add on requires installation of RHEL 3 U1 or later for proper function.

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-04 11:01:10-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-06-04 11:01:33-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Generic 1.44M IDE Floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-06-04 11:11:49-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: SAMSUNG CD-ROM SN-124, ATAPI CDRom drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-06-04 11:12:35-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Intel Corp. 82546EB Gigabit Ethernet Controller (rev 01)

Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-04 11:13:01-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Intel(R) Xeon(TM) CPU 3.20Ghz

Quantity: 2

Hyperthreading capable
Component Class: CPU

Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-04 11:16:30-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Vendor: SEAGATE Model: ST318452LC, SCSI DISK drive

Qty: 2

Vendor: FUJITSU Model: MAM3184MC, SCSI DISK drive

Qty: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-04 11:15:39-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5529
Detail Notes: Intel Corp. 82801CA/CAM USB (Hub #1) (rev 02)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-04 11:16:58-04

Additional Certification Notes

No additional certification notes provided

2.2.5. Intel SR870BH2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149948>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Cpu Name: Intel(R) IPF
Last Touched On: 2005-02-02 11:51:50-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 6060
Detail Notes: ATI Technologies Inc Rage XL (rev 27) Video RAM: 8 MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-02 11:50:30-05

Detail 2:

Status: Compatible
Hardware Id: 6060
Detail Notes: Slimtype COMBO LSC-24081M, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-02 11:50:30-05

Detail 3:

Status: Compatible
Hardware Id: 6060
Detail Notes: 16G
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-02 11:50:30-05

Detail 4:

Status: Compatible
Hardware Id: 6060
Detail Notes: Vendor: MAXTOR Model: ATLASU320_18_SCA Rev: B810
Type: Direct-Access ANSI SCSI revision: 03
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-02 11:50:30-05

Detail 5:

Status: Compatible
Hardware Id: 6060
Detail Notes: LSI Logic / Symbios Logic (formerly NCR) 53c1030 (rev 08)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-02 11:50:30-05

Detail 6:

Status: Compatible
Hardware Id: 6060

Detail Notes: Intel Corp. 82546EB 2-port Gigabit Ethernet Controller (rev 01)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-02 11:50:30-05

Detail 7:
Status: Compatible
Hardware Id: 6060
Detail Notes: IA-64 Itanium 2 Quantity: 2 Speed: 1.6GHz Cache: 9 MB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-02 11:50:30-05

Additional Certification Notes

No additional certification notes provided

2.2.6. Intel SSH4 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148500>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-08-26 11:28:43-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-08-26 11:21:46-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: Adptec aic7902 Ultra320 SCSI adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-26 11:22:04-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: 24G
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-08-26 11:22:28-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: Intel(R) XEON(TM) MP CPU 3.0Ghz

Quantity: 4

Hyperthreading capable
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-08-26 11:23:03-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-08-26 11:23:19-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: ServerWorks CSB5 IDE Controller (rev 93)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-26 11:23:45-04

Detail 7:

Ease of Install: 4

Status: Compatible
Hardware Id: 5684
Detail Notes: Vendor: MAXTOR Model: ATLASU320_18_SCA
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-08-26 11:25:14-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: Generic 1.44Mb Floppy Disk drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-08-26 11:26:16-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: ServerWorks OSB4/CSB5 USB Controller (rev 05)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-26 11:26:25-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5684
Detail Notes: Intel Corp. 82544GC Gigabit Ethernet Controller (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-26 11:26:36-04

Detail 11:
Status: Compatible
Hardware Id: 5684
Detail Notes: Intel Corp. 82557/8/9 [Ethernet Pro 100] (rev 0d)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-26 11:30:58-04

Additional Certification Notes

No additional certification notes provided

2.2.7. Intel TIGPT1U Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148576>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-10-20 08:59:02-04
Returned On: mm-dd-yy
Last Touched On: 2004-10-20 09:07:37-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-20 08:59:18-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: TEAC CD-224E Slim 24x ATAPI CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-20 09:00:05-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: Intel Corp. 6300ESB PATA Storage Controller
Adaptec AIC-7901 U320 SCSI Storage Controller
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-20 09:01:22-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: Intel(R) Pentium(R) 4 CPU 3.00GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-20 09:02:07-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: (2X) MAXTOR ATLAS U320 36GB SCA
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-20 09:03:24-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: 4GB DDR333/DDR400 unbuffered 184-pin DDR SDRAM DIMM
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-20 09:06:28-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: Intel Corp. 82875P Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-10-20 09:06:38-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5786
Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-10-20 09:06:46-04

Additional Certification Notes

No additional certification notes provided

2.2.8. Park Value 845 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148664>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: All Architectures
Created On: 2004-12-02 16:20:41-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-02 16:25:59-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5930
Detail Notes: Intel Corp. 82845G/GL[Brookdale-G]/GE Chipset Integrated Graphics Device
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-02 16:20:52-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5930
Detail Notes: F565E ATAPI CDROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-02 16:21:45-05

Detail 3:

Ease of Install: 4
Status: Compatible

Hardware Id: 5930

Detail Notes: Intel Corp. 82801DB/DBL (ICH4/ICH4-L) UltraATA-100 IDE Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-02 16:22:12-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: Intel(R) Celeron(R) CPU 2.53GHz

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-02 16:22:40-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: Intel Corp. 82801DB/DBL/DBM (ICH4/ICH4-L/ICH4-M) AC'97 Audio Controller

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-12-02 16:23:04-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: Maxtor 6Y120P0

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-02 16:23:34-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: Standard 3.5" 1.44MB Floppy

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-02 16:24:03-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: 256MB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-02 16:24:43-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: 82845G/GL[Brookdale-G]/GE/PE Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-12-02 16:25:18-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5930

Detail Notes: Intel Corp. 82801BD PRO/100 VE (LOM) Ethernet Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-12-02 16:25:43-05

Additional Certification Notes

No additional certification notes provided

2.2.9. Server Platform SR870BN4 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153296>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* ia64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.2.10. SR4850 (Harwich) HW4 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=191741>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 4
Make: SR4850 (Harwich)
Model: HW4
Vendor: Intel
Category: Server
Kernel Version: kernel-2.4.21-40.EL

File Uploaded:

rhr2--HW4-Taroon_Update_7_results-1.noarch.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/70acec730523508fb5727e9cb9d11c84/rhr2--HW4-Taroon_Update_7_results-1.noarch.rpm

Please note the following failures:

WARNING: Kickstart file not found for required tests check.

FAILED: No MEMORY found in limits file for platform

```
0      INFO
1  FAILED  USB
   PASSED  INFO
   PASSED  CDROM
2  FAILED  USB
   PASSED  INFO
   PASSED  VIDEO
4  FAILED  NETWORK2
   PASSED  INFO
   PASSED  CORE2
   PASSED  MEMORY2
   PASSED  STORAGE2
5  FAILED  NETWORK2
   PASSED  INFO
6  FAILED  NETWORK2
   PASSED  USB
   PASSED  INFO
7  FAILED  NETWORK2
   FAILED  INFO
8  FAILED  NETWORK2
   PASSED  INFO
9  PASSED  INFO
   PASSED  NETWORK
```


Additional Certification Notes

No additional certification notes provided

2.3. Itautec

2.3.1. Itautec Servidor Itautec 1250 IDE Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148505>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-09-03 11:32:29-04
Returned On: mm-dd-yy
Last Touched On: 2004-12-16 15:41:34-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5693
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-03 11:33:38-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5693
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-09-03 11:34:33-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5693

Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-09-03 11:37:58-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5693

Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-09-03 11:43:15-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5693

Detail Notes: 4GB DDR200/266

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-03 18:17:09-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5693

Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-03 18:18:46-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5693

Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>

NOTE: Requires U2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-03 18:36:10-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5693
Detail Notes: IDE: Seagate ST340823A

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-07 13:36:31-04

Detail 9:
Status: Compatible
Hardware Id: 5693
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 13:36:55-04

Additional Certification Notes

No additional certification notes provided

2.3.2. Itautec Servidor Itautec 1250 SATA Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148512>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:41:41-05

Detail Data:

Detail 1:
Ease of Install: 4

Status: Compatible
Hardware Id: 5703
Detail Notes: SATA: Seagate ST380013AS

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-07 13:37:57-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 13:38:07-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 13:38:40-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-07 13:38:48-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 13:38:58-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: 4GB DDR200/266

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-07 13:39:05-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: Intel Corp. E7501 Chipset
SuperMicro X5DPA Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-07 13:39:14-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller
Intel Corp. 82541EI Gigabit Ethernet Controller
Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>
NOTE: Requires U2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-07 13:39:22-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5703
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)
SATA: Intel Corp. 82801EB (ICH5) Serial ATA 150 Storage Controller (rev 02)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 13:49:09-04

Additional Certification Notes

No additional certification notes provided

2.3.3. Itautec Servidor Itautec 1250 SCSI Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148513>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:41:56-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5704
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 13:40:31-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5704
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 13:40:38-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5704
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 13:40:44-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5704
Detail Notes: SATA: Seagate ST380013AS
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-07 13:40:55-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5704

Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-09-07 13:41:02-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5704

Detail Notes: 4GB DDR200/266

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-07 13:41:08-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5704

Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-07 13:41:17-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5704

Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>

NOTE: Requires U2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-07 13:41:23-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5704

Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

SCSI: Adaptec AIC-7902B U320 (rev 10)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-09-07 13:48:47-04

Additional Certification Notes

No additional certification notes provided

2.3.4. Itautec Servidor Itautec 1251, 2250, 2252 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153888>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:42:11-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel(R) Xeon(TM) CPU 2.80 GB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-18 14:38:42-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-18 14:38:48-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: ACER Model 656A-002
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-18 14:38:54-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: 4 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-18 14:39:21-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel 82551 10/100M Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-18 14:39:27-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Adaptec aic7902 Ultra320 SCSI adapter

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-18 14:39:53-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: SEAGATE Model: ST39173W
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-18 14:39:59-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel 82545EM Gigabit Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.

Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-18 14:40:05-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Standard Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-11-18 14:40:11-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel E7501 Chipset

SuperMicro X5DPL Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-11-18 14:40:17-05

Additional Certification Notes

No additional certification notes provided

2.3.5. Itautec Servidor Itautec 1251, 2250, 2252 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148651>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:42:11-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel(R) Xeon(TM) CPU 2.80 GB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-18 14:38:42-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-18 14:38:48-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: ACER Model 656A-002
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-18 14:38:54-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: 4 GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-18 14:39:21-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel 82551 10/100M Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-18 14:39:27-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5884

Detail Notes: Adaptec aic7902 Ultra320 SCSI adapter

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-18 14:39:53-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: SEAGATE Model: ST39173W
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-18 14:39:59-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel 82545EM Gigabit Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-18 14:40:05-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Standard Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-11-18 14:40:11-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5884
Detail Notes: Intel E7501 Chipset

SuperMicro X5DPL Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-11-18 14:40:17-05

Additional Certification Notes

No additional certification notes provided

2.3.6. Itautec Servidor Itautec 1252 IDE Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148514>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:41:49-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5705
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 13:43:00-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5705
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 13:43:07-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5705
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 13:43:13-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5705

Detail Notes: IDE: Seagate ST340823A

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-07 13:43:26-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5705

Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-09-07 13:43:32-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5705

Detail Notes: 4GB DDR200/266

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-07 13:43:39-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5705

Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-07 13:43:46-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5705

Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>

NOTE: Requires U2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-07 13:43:53-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5705
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 13:44:03-04

Additional Certification Notes

No additional certification notes provided

2.3.7. Itautec Servidor Itautec 1252 SATA Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148515>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:41:18-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 13:44:46-04

Detail 2:
Ease of Install: 4

Status: Compatible
Hardware Id: 5706
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 13:44:52-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

SATA: Intel Corp. 82801EB (ICH5) Serial ATA 150 Storage Controller (rev 02)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 13:45:18-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 13:45:26-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: SATA: Seagate ST380013AS

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-07 13:45:35-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-07 13:45:41-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5706
Detail Notes: 4GB DDR200/266
Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-07 13:45:47-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5706

Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-07 13:45:56-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5706

Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>

NOTE: Requires U2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-07 13:46:02-04

Additional Certification Notes

No additional certification notes provided

2.3.8. Itautec Servidor Itautec 1252 SCSI Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148516>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-16 15:42:03-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5707
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-07 13:46:51-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5707
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-07 13:46:59-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5707
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

SCSI: Adaptec AIC-7902B U320 (rev 10)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-07 13:47:23-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5707
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-07 13:47:32-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5707
Detail Notes: SATA: Seagate ST380013AS

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-07 13:47:41-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5707

Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-09-07 13:47:47-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5707

Detail Notes: 4GB DDR200/266

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-07 13:47:53-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5707

Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-07 13:48:01-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5707

Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>

NOTE: Requires U2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-07 13:48:06-04

Additional Certification Notes

No additional certification notes provided

2.3.9. Itautec Servidor Itautec 2150 IDE Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153909>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-21 15:23:42-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 6037
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-21 14:23:43-05

Detail 2:
Status: Compatible
Hardware Id: 6037
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-21 14:23:43-05

Detail 3:
Status: Compatible
Hardware Id: 6037
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-21 14:23:43-05

Detail 4:
Status: Compatible

Hardware Id: 6037
Detail Notes: IDE: Seagate ST340823A

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-21 14:23:43-05

Detail 5:
Status: Compatible
Hardware Id: 6037
Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-21 14:23:43-05

Detail 6:
Status: Compatible
Hardware Id: 6037
Detail Notes: 4GB DDR200/266
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-21 14:23:43-05

Detail 7:
Status: Compatible
Hardware Id: 6037
Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-01-21 14:23:43-05

Detail 8:
Status: Compatible
Hardware Id: 6037
Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller

Intel Corp. 82541EI Gigabit Ethernet Controller

Intel Corp. 82557/8/9 [Ethernet Pro 100]

<p>
NOTE: Requires U2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-21 14:23:43-05

Detail 9:
Status: Compatible
Hardware Id: 6037
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-21 14:23:43-05

Additional Certification Notes

No additional certification notes provided

2.3.10. Itautec Servidor Itautec 2150 SATA Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153908>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-21 15:23:35-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 6036
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-01-21 14:23:04-05

Detail 2:
Status: Compatible
Hardware Id: 6036
Detail Notes: 56X CD-ROM, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-21 14:23:04-05

Detail 3:

Status: Compatible
Hardware Id: 6036
Detail Notes: IDE: Intel Corp. 82801CA Ultra ATA Storage Controller (rev 02)

SATA: Intel Corp. 82801EB (ICH5) Serial ATA 150 Storage Controller (rev 02)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-21 14:23:04-05

Detail 4:
Status: Compatible
Hardware Id: 6036
Detail Notes: SMP(2x) Intel(R) Xeon(TM) CPU 3.06GHz (with HyperThreading)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-21 14:23:04-05

Detail 5:
Status: Compatible
Hardware Id: 6036
Detail Notes: SATA: Seagate ST380013AS

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-21 14:23:04-05

Detail 6:
Status: Compatible
Hardware Id: 6036
Detail Notes: Standard 1.44MB 3 1/2" Floppy (post-1991 82077)
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-21 14:23:04-05

Detail 7:
Status: Compatible
Hardware Id: 6036
Detail Notes: 4GB DDR200/266
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-21 14:23:04-05

Detail 8:
Status: Compatible
Hardware Id: 6036
Detail Notes: Intel Corp. E7501 Chipset

SuperMicro X5DPA Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-01-21 14:23:04-05

Detail 9:
Status: Compatible

```
Hardware Id: 6036
Detail Notes: Intel Corp. 82541GI/PI Gigabit Ethernet Controller<br>
Intel Corp. 82541EI Gigabit Ethernet Controller<br>
Intel Corp. 82557/8/9 [Ethernet Pro 100]<br>
<p>
<b>NOTE:</b> Requires U2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-21 14:23:04-05
```

Additional Certification Notes

No additional certification notes provided

2.4. KBS India

2.4.1. KBS Desktop Admire Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=160761>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

CPU : AMD Athlon 64 3200+ with Hyper Transport Technology with 640KB cache, 754 pin socket

MEMORY : 512 MB DDR 400

Video Adapter : Nvidia GE Force MX 4000

CDROM Drive : Combo Drive comprising of 16X DVD & 52X/32X/52X CD writer

Digital Audio Adapter : Integrated ADI AD1980

Fixed Hard Disk : 120 GB SATA, 7200 rpm

Note : Requires RHEL 3 - Update 3 and above

Controller Card : VIA VT 8237 (IDE and SATA Controller)

Floppy Disk Drive : 1.44 MB 3.5 Floppy Disk Drive
Network Interface : Add on : Realtek 8169 Gigabit LAN controller
Note : Requires RHEL 3 - Update 4
Motherboard : Based on VIA K8T800 chipset

Additional Certification Notes

No additional certification notes provided

2.4.2. KBS Desktop Elegance Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=160758>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4 540 J @ 3.2 GHz with HT Technology, LGA 775 with 1MB L2 Cache, 800 MHz FSB
RAM : 512 MB DDR400
Video Adapter : Integrated Intel Graphic Media accelerator 900
CDROM Drive : Combo Drive :16X DVD & 52X/32X/52X CDRW
Digital Audio Adapter : Integrated ALC 880 Audio Controller
Fixed Hard Disk : 120 GB SATA, 7200 rpm
Note : Requires RHEL3 Update-3 and above.
Controller Card : ICH6 (IDE and SATA Controller)
Floppy Disk Drive : 1.44 MB 3.5 Floppy Disk Drive
Network Interface : Integrated Intel 10/100 Ethernet Controller
Add on : Intel Gigabit Ethernet Controller
Motherboard : Based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.5. Keltron

2.5.1. Keltron KELIN 24G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148732>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2005-01-03 00:45:05-05

Returned On: mm-dd-yy

Last Touched On: 2005-01-03 00:53:07-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6016

Detail Notes: Intel Extreem Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-01-03 00:45:34-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6016

Detail Notes: Samsung : SH 152

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-01-03 00:45:54-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6016

Detail Notes: Intel 82801 DB I/O controller HUB (ICH4)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-03 00:46:17-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: Intel P4 - 2.4Ghz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-03 00:47:56-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: Dual Channel AC ?97
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-01-03 00:48:49-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: 80GB HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-03 00:49:14-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: Seagate : ST380011A
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-01-03 00:49:56-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: DDR333 - 256MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-03 00:50:59-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: Intel 845 GVSRL
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed separately.
Modified On: 2005-01-03 00:51:44-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 6016
Detail Notes: Intel Pro 10/100 Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-03 00:52:37-05

Additional Certification Notes

No additional certification notes provided

2.6. KRAFTWAY

2.6.1. G-SCALE ET10 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=163938>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* ia64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.7. LG Electronics India Pvt. Ltd.

2.7.1. LG (X)S1 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=155972>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

```
CPU : Intel Pentium 4 2.8GHz
MEMORY : 256MB DDR 333MHz
Video Adapter : Integrated Graphics
CDROM Drive : LG GCC 4521B Combo Drive
Digital Audio Adapter : Integrated 6 Channel Audio Realtek ALC202A
Fixed Hard Disk : Seagate ST340014A 40GB 7200RPM HDD
Floppy Disk Drive : Sony MPF920-Z 1.44MB
Network Interface : Integrated Intel Pro/100 LAN
Motherboard : Intel D845GVSRL
```

Additional Certification Notes

No additional certification notes provided

2.7.2. LG (X)S4 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=155981>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

```
CPU : Intel Pentium 4 3.0GHz
MEMORY : 256MB DDR 333MHz
Video Adapter : Integrated Graphics
```

CDROM Drive : LG GCC 4521B Combo Drive
Digital Audio Adapter : Integrated 6 Channel Audio ADI AD1985
Fixed Hard Disk : Seagate ST340011A 80GB 7200RPM HDD
Floppy Disk Drive : Sony MPF920-Z 1.44MB
Network Interface : Integrated Intel Pro/100 LAN
Motherboard : Intel D865GLC

Additional Certification Notes

No additional certification notes provided

2.7.3. LG (X)SA Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=155984>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : AMD Sempron 2200+
MEMORY : 256MB DDR 333MHz
Video Adapter : Integrated Graphics
CDROM Drive : LG GCC 4521B Combo Drive
Digital Audio Adapter : Integrated 6 Channel Audio. Via VT1617
Fixed Hard Disk : Seagate ST340014A 40GB 7200RPM HDD
Floppy Disk Drive : Sony MPF920-Z 1.44MB
Network Interface : Integrated VIA VT 6103 10/100 Mbps LAN
Motherboard : Gigabyte 7VM333M-RZ

Additional Certification Notes

No additional certification notes provided

2.8. NEC

2.8.1. Express5800 1020Ba Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148881>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* ia64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.8.2. Express5800 MD120La-R Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=195631>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9. NEC/Bull

2.9.1. Express5800 110Ba-e3 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148894>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.2. Express5800 110Eh Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149041>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.3. Express5800 120Ef Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148354>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.4. Express5800 120Eg Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148542>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.5. Express5800 120Eg Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=151530>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.6. Express5800 120Lg Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148543>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.7. Express5800 120Lh Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148521>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.8. Express5800 120Lh Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149072>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.9. Express5800 120Rd-1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148314>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.10. Express5800 120Re-1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149042>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.11. Express5800 120Re-1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149073>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.12. Express5800 120Rf-2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148305>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.13. Express5800 120Rg-2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149045>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.14. Express5800 140Hd Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149078>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.15. Express5800 140Rc-4 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149062>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.16. Express5800 180Rd-4 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148539>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.17. Express5800 420Ma Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=149046>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.9.18. NEC/Bull Express5800/120Ef Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153842>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-05-13 13:36:05-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: 256MB to 4GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-05-13 10:47:30-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: ATI Technologies

Rage XL PCI video(8MB)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-05-13 10:48:37-04

Detail 3:
Ease of Install: 4

Status: Compatible
Hardware Id: 5456
Detail Notes: Standard 3.5 1.44MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-05-13 10:50:15-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: Intel(R) Xeon 3.06Mhz

Qty:2

NOTE: Hyperthreading enabled, will appear to be 4 CPUs to the Operating System.
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-05-13 10:48:26-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: Intel(R)

Ethernet 82540EM(Gbit)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-05-13 10:49:20-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: IDE/ATAPI x48 CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-05-13 10:50:33-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: LSI Logic MegaRAID LD0 RAID5 34684R 1L20

HDD(18GB)x3 (RAID5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-13 10:50:49-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456

Detail Notes: Internal DAT

Internal AIT

Internal AIT(IDE)
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2005-01-05 10:59:32-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5456
Detail Notes: 100BASE-TX adapter

1000BASE-SX adapter

1000BASE-TX adapter
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-05 11:00:43-05

Additional Certification Notes

No additional certification notes provided

2.9.19. NEC/Bull Express5800/120Lg Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153874>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-27 10:51:43-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible

Hardware Id: 5746
Detail Notes: MIN: 512MB (256MB DDR266 x2)

MAX: 8GB (2GB x4)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-15 15:26:37-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: Intel Corp. 82557 10/100 Mbps

Intel Corp. 82540EM Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-15 15:27:34-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: Intel(R) Xeon(TM) CPU 3.20GHz (x2 SMP)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-15 15:28:13-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: MITSUMI FX48++W
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-15 15:28:36-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: ATI Technologies Rage XL PCI video(8MB)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-15 15:30:49-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: MITSUMI D353F3Z-2358
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-15 15:30:56-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: 879GB (146.5GB x6)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-15 15:31:02-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: Intel Corp. E7501 Chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-15 15:31:29-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5746
Detail Notes: LSI Logic MegaRAID
Adaptec AIC-7901A U320 (rev 03)
Intel 82801CA Ultra ATA Storage Controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-15 15:32:10-04

Additional Certification Notes

No additional certification notes provided

2.9.20. NEC/Bull Express5800/120Lh Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153869>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

Cpu Name: X86

Last Touched On: 2004-09-27 09:31:31-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5715

Detail Notes: LSI Logic MegaRAID
^M

Adaptec AIC-7902B U320

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-09-08 14:08:50-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5715

Detail Notes: 16GB (2GBx8)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-08 14:09:19-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5715

Detail Notes: Intel 82541GI Gigabit Ethernet Controller (x2)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-08 14:10:04-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5715

Detail Notes: Intel(R) Xeon(TM) CPU 3.60GHz

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-09-08 14:10:48-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5715

Detail Notes: IDE/ATAPI x48 CD-ROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-08 14:14:29-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: MITSUMI D353F3Z-2358
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-08 14:14:57-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: LSI Logic MegaRAID LD0 RAID5 70146R 1N17 (1ch) HDD(36GB)x3 (RAID5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-08 14:16:08-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: FX48++W CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-08 14:16:26-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: 879GB (146.5GB x6)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-08 14:17:04-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: Intel(R) E7520 (800MHz)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-08 14:18:22-04

```
Detail 11:
Ease of Install: 4
Status: Compatible
Hardware Id: 5715
Detail Notes: ATI Technologies Radeon 7000
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-20 14:54:19-04
```

Additional Certification Notes

No additional certification notes provided

2.9.21. NEC/Bull Express5800/120Rd-1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153836>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

```
Additional Data:
```

```
Cpu Name: X86
Last Touched On: 2004-05-13 13:28:12-04
```

```
Detail Data:
```

```
Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5392
Detail Notes: 12GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-07 10:51:42-04
```

```
Detail 2:
Ease of Install: 4
Status: Compatible
```

Hardware Id: 5392

Detail Notes: ATI Technologies Rage XL PCI video(8MB)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-04-07 10:53:23-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5392

Detail Notes: Standard 3.5 1.44MB

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-04-07 10:54:19-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5392

Detail Notes: IDE/ATAPI x24 CD-ROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-07 10:54:40-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5392

Detail Notes: LSI Logic MegaRAID

LSI Logic / Symbios Logic PowerEdge Expandable RAID Controller 4 (rev 01)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-07 10:56:03-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5392

Detail Notes: Intel Xeon 2GB, 2.40GB, 2.80GB, 3.06GB, or 3.20GB

Qty: 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-07 11:00:27-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5392

Detail Notes: (2x) Intel 82546EB Gb Ethernet

Optional NIC - 1000BASE-SX


```
Optional NIC - 1000BASE-T<br>
Optional NIC - 100BASE-TX
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-11 17:11:26-05
```

Additional Certification Notes

No additional certification notes provided

2.9.22. NEC/Bull Express5800/120Rf-2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153833>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-03-23 16:09:45-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: Standard 3.5 1.44MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-03-26 08:23:56-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: IDE/ATAPI x24 CD-ROM

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-03-26 08:24:06-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: Intel(R) Xeon (2.8GHz,3.05GHz, or 3.2GHz)

Qty:1-2

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-26 08:24:15-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: 512MB - 12GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-03-26 08:24:24-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: ATI Rage XL PCI Video(8MB)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-03-26 08:24:32-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: Intel 82546EB(Gbit)

Qty:2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-03-26 08:24:41-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5380
Detail Notes: LSI Logic MegaRAID LD0 RAID5 69372R 1L20(1ch)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-03-26 08:24:49-05

Additional Certification Notes

No additional certification notes provided

2.9.23. NEC/Bull Express5800/120Rg-2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153921>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2005-02-07 08:53:28-05
Returned On: mm-dd-yy
Last Touched On: 2005-02-07 09:07:28-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: ATI Radeon 7000
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-07 08:53:40-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: Adaptec AIC-7902

Option - Adaptec SCSI-CARD (29320ALP)

Option - MegaRAID U320-1/2
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-07 08:55:19-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: Intel Xeon 2.8GHz/3GHz/3.20GHz/3.60GHz (Qty:2)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-07 08:55:52-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: 876GB (146GB x6)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-07 08:56:34-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: MITSUMI D353F3-R3221
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-07 08:57:02-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: 1GB to 12GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-07 08:57:34-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: MITSUMI SR244W1
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-08 20:14:45-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: Intel Lindenhurst + ICH5R + PXH
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-08 20:15:26-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: Intel 82546GB (Qty:2)

Option - Intel 82545GM

Option - Intel 82544EI

Option - Intel 82550GY
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-08 20:15:54-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6086
Detail Notes: DAT (SONY SDT-11000)

DAT (HP C7438A)

AIT (SONY SDX-400V)

AIT (SONY SDX-700C)

AIT (SONY SDX-500V)

AIT(IDE) (SONY SDX-420V(AIT-1V))

LTO (HP C7377(LTC215))
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2005-02-08 20:18:28-05

Additional Certification Notes

No additional certification notes provided

2.10. PCS Industries Limited

2.10.1. PCS PRODiIGY 915GV Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161912>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4 2.8GHz , 512KB/1MB L2 Cache, 533MHz800MHz FSB, HT Enabled

MEMORY : 2048MB DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio
with RealTek ALC 655 CODEC

Fixed Hard Disk : 40GB SATA Hard Disk Drive

Note : Requires RHEL 3 U3 and above

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Realtek 8110S Gigabit Ethernet 10/100/1000 Mbps

Note : Requires RHEL 3 U4 and above

Motherboard : Intel 915GV Chipset based
AsusTek P5GV-TMX Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.2. PCS PRODiiGY 915GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161913>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4 2.8GHz , 512KB/1MB L2 Cache, 533MHz800MHz FSB, HT Enabled

MEMORY : 2048MB DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 655 CODEC

Fixed Hard Disk : 40GB SATA Hard Disk Drive
Note : Requires RHEL 3 U3 and above

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Realtek 8110S Gigabit Ethernet 10/100/1000 Mbps
Note : Requires RHEL 3 U4 and above

Motherboard : Intel 915GV Chipset based
AsusTek P5GV-TMX Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.3. PCS PRODIiGY 915GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161915>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3 Update 4

MEMORY : 2048MB DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 655 CODEC

Fixed Hard Disk : 40GB SATA Hard Disk Drive
 Note : Requires RHEL 3 U3 and above

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Realtek 8110S Gigabit Ethernet 10/100/1000 Mbps
 Note : Requires RHEL 3 U4 and above

Motherboard : Intel 915GV Chipset based
 AsusTek P5GV-TMX Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.4. PCS Industries Limited ERGO Colt 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157941>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.5. PCS Industries Limited ERGO Colt 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157948>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)

Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.6. PCS Industries Limited ORiiON 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157938>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.7. PCS Industries Limited SiirUS Compact UP XIII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157934>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz-3.8GHz, 512KB/1MB L2 Cache, 533MHZ/800MHZ FSB, HT Enabled

MEMORY : 2048MB (512MB to 4GB upgradeable) Non-ECC/ECC DDR2 (4 DIMM Slots)

Video Adapter : Integrated Intel MCH module supporting standard SVGA drivers with 8MB

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Fixed Hard Disk : Serial ATA Hard Disk Drive

Controller Card : Intel 82801FR I/O Controller Hub with Intel E7221 Chipset

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82551QM Fast Ethernet Controller (Intel PRO/100 Server Network Connection)

Motherboard : Intel SE7221BA1

Additional Certification Notes

No additional certification notes provided

2.10.8. PCS Industries Limited ERGO Challenger 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148433>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-15 00:38:50-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-15 00:49:40-04

Detail Data:

Detail 1:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601
 Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be available as an installation medium.
 Must pass the rhr-core tests.
 Must pass the rhr-cdromdata test.
 Component Notes: None
 Modified On: 2004-07-15 00:39:26-04

Detail 2:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-15 00:40:27-04

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-15 00:42:29-04

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-15 00:41:00-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-15 00:42:56-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5601

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 00:39:05-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5601
Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-15 00:39:48-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5601
Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-15 00:41:55-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5601
Detail Notes: 845GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 00:48:15-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5601
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 00:48:54-04

Additional Certification Notes

No additional certification notes provided

2.10.9. PCS Industries Limited ERGO Challenger 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148428>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-13 08:56:21-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-13 09:08:31-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-13 08:56:39-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-13 08:57:36-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB
Component Class: CPU

Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-13 08:58:13-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-13 09:03:36-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: Integrated Intel 82801EB AC'97 Audio
(6 channel Audio CODEC)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-13 09:04:09-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-13 09:04:46-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-13 09:06:02-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5595
Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-13 09:06:45-04

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5595
 Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-13 09:07:21-04

Detail 10:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5595
 Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-07-13 09:08:01-04

Additional Certification Notes

No additional certification notes provided

2.10.10. PCS Industries Limited ERGO Challenger 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148692>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
 Cpu Name: X86
 Created On: 2004-12-08 06:49:25-05
 Returned On: mm-dd-yy
 Last Touched On: 2004-12-09 03:31:47-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-08 06:51:59-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-08 06:52:49-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHz/533MHz/800MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-08 06:53:34-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-12-08 06:54:14-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-08 06:54:58-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5969
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-12-08 06:56:06-05

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5969
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-12-08 06:56:57-05

Detail 8:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5969
 Detail Notes: Intel 865GV Chipset based Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-12-08 06:57:48-05

Detail 9:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5969
 Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-12-08 06:58:47-05

Detail 10:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5969
 Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2004-12-09 03:30:53-05

Additional Certification Notes

No additional certification notes provided

2.10.11. PCS Industries Limited ERGO Challenger 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157034>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4, 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller

NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.12. PCS Industries Limited ERGO Challenger 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157942>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.13. PCS Industries Limited ERGO Challenger 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157949>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 -
Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.14. PCS Industries Limited ERGO Challenger GAG Desktop/ Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157958>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT
Enabled (Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 -
Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)
Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive
Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller
Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.15. PCS Industries Limited ERGO Challenger GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153701>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:51:40-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 03:49:06-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 03:49:06-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-01 03:49:06-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-01 03:49:06-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-01 03:49:06-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: Intel 915G Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-01 03:49:06-05

Detail 7:

Ease of Install: 4

```

Status: Compatible
Hardware Id: 6053
Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB,HT
Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-01 03:49:06-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: 2048MB (256MB to 4GB upgradeable)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-01 03:49:06-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6053
Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 03:49:06-05
    
```

Additional Certification Notes

No additional certification notes provided

2.10.16. PCS Industries Limited ERGO Challenger GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157616>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller

Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.17. PCS Industries Limited ERGO Challenger GVHZ Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157043>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.18. PCS Industries Limited ERGO Challenger GVSR Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148440>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-15 01:36:08-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-15 01:44:38-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 01:36:39-04

Detail 2:

Ease of Install: 4

Status: Compatible
Hardware Id: 5608
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 01:37:17-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: Intel P4, (1.7 ? 3.06) GHz, 400MHz/533MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-15 01:38:02-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 01:38:51-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-15 01:40:12-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-15 01:41:19-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5608
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-07-15 01:42:18-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5608

Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-07-15 01:43:19-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5608

Detail Notes: Intel 845GV Chipset based Intel D845GVSRL Mainboard

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-07-15 01:43:50-04

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5608

Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-07-15 01:44:26-04

Additional Certification Notes

No additional certification notes provided

2.10.19. PCS Industries Limited ERGO Challenger GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156813>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(P4 Processor 630-660)

Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3 Update 4

Memory : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.20. PCS Industries Limited ERGO Challenger GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156084>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel D915GVWB Mainboard based on Intel 915GV Chipset

Additional Certification Notes

No additional certification notes provided

2.10.21. PCS Industries Limited ERGO Classic 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148431>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-14 06:41:35-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-14 07:24:21-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5598
Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None

Modified On: 2004-07-14 06:55:31-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5598

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-14 06:41:54-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5598

Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-07-14 06:55:59-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5598

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-14 06:42:13-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5598

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-07-14 06:56:30-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5598

Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-07-14 07:23:52-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5598
 Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-07-14 06:42:35-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5598
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-14 07:18:02-04

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5598
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-14 06:52:09-04

Detail 10:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5598
 Detail Notes: 845GV Chipset based Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-14 07:18:34-04

Additional Certification Notes

No additional certification notes provided

2.10.22. PCS Industries Limited ERGO Classic 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148426>

Summary

- *Version: 3*

- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-13 08:09:23-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-13 08:26:26-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5593

Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-13 08:09:37-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5593

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-13 08:17:12-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5593

Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-13 08:19:11-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5593

Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-07-13 08:19:42-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: Integrated Intel 82801EB AC'97 Audio
 (6 channel Audio CODEC)
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-13 08:22:39-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-13 08:23:12-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-13 08:23:47-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-13 08:24:21-04

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-13 08:25:13-04

Detail 10:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5593
 Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps

Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-13 08:26:08-04

Additional Certification Notes

No additional certification notes provided

2.10.23. PCS Industries Limited ERGO Classic 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148690>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-12-08 06:39:17-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-09 03:28:18-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5965
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-08 06:40:37-05

Detail 2:

Ease of Install: 4
Status: Compatible

Hardware Id: 5965
 Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-12-08 06:41:25-05

Detail 3:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5965
 Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHz/533MHz/800MHz FSB
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-12-08 06:42:12-05

Detail 4:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5965
 Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-12-08 06:43:05-05

Detail 5:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5965
 Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-12-08 06:43:42-05

Detail 6:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5965
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-12-08 06:44:19-05

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5965
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-12-08 06:45:08-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5965
Detail Notes: Intel 865GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-08 06:46:00-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5965
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-08 06:47:21-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5965
Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-09 03:27:47-05

Additional Certification Notes

No additional certification notes provided

2.10.24. PCS Industries Limited ERGO Classic 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157033>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4, 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller

NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.25. PCS Industries Limited ERGO Classic 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157940>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller
Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.26. PCS Industries Limited ERGO Classic 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157951>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 -
Update 4
RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)
Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.27. PCS Industries Limited ERGO Classic GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157956>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.28. PCS Industries Limited ERGO Classic GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153699>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:47:12-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6051
Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 03:46:20-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6051
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 03:46:20-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6051
Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-02-01 03:46:20-05

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2005-02-01 03:46:20-05

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2005-02-01 03:46:20-05

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: Intel 915G Chipset based Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2005-02-01 03:46:20-05

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2005-02-01 03:46:20-05

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: 2048MB (256MB to 4GB upgradeable)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2005-02-01 03:46:20-05

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6051
 Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 03:46:20-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6051
Detail Notes: Integrated High Definition Audio with RealTek ALC 860 CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-04 00:41:08-05

Additional Certification Notes

No additional certification notes provided

2.10.29. PCS Industries Limited ERGO Classic GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157615>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller

Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.30. PCS Industries Limited ERGO Classic GVHZ Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157041>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.31. PCS Industries Limited ERGO Classic GVSR Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148437>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-15 01:19:11-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-15 01:28:30-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5605
Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 01:19:55-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5605
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 01:20:57-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5605
Detail Notes: Intel P4, (1.7 ? 3.06) GHz, 400MHz/533MHz FSB
Component Class: CPU

Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-07-15 01:22:37-04

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5605
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-15 01:23:13-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5605
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-15 01:24:01-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5605
 Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-15 01:24:43-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5605
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-15 01:25:24-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5605
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-15 01:26:14-04

Detail 9:

Ease of Install: 4

Status: Compatible
Hardware Id: 5605
Detail Notes: Intel 845GV Chipset based Intel D845GVSRL Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 01:27:09-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5605
Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 01:28:00-04

Additional Certification Notes

No additional certification notes provided

2.10.32. PCS Industries Limited ERGO Classic GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156811>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(P4 Processor 630-660)

Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3
Update 4

Memory : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics
subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel D915GVWB based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.33. PCS Industries Limited ERGO Classic GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156083>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled
MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC
Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel D915GVWB Mainboard based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.34. PCS Industries Limited ERGO Colt 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148432>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-14 07:53:39-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-14 08:00:46-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5599

Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation **to** from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-07-14 07:57:53-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5599

Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-07-14 08:00:25-04

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-07-14 07:54:58-04

Detail 4:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-14 07:58:30-04

Detail 5:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2004-07-14 07:53:55-04

Detail 6:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-14 07:55:58-04

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-14 07:59:09-04

Detail 8:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5599
 Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be available as an installation medium.
 Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-14 07:54:21-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5599
Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-14 07:57:08-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5599
Detail Notes: 845GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-14 07:59:46-04

Additional Certification Notes

No additional certification notes provided

2.10.35. PCS Industries Limited ERGO Colt 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148427>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-13 08:39:57-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-13 08:49:21-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5594

Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-13 08:41:13-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5594

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-13 08:42:46-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5594

Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-13 08:43:12-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5594

Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-07-13 08:44:07-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5594

Detail Notes: Integrated Intel 82801EB AC'97 Audio

(6 channel Audio CODEC)

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-07-13 08:45:17-04

Detail 6:

Ease of Install: 4

Status: Compatible
Hardware Id: 5594
Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-13 08:45:58-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5594
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-13 08:46:53-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5594
Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-13 08:47:34-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5594
Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-13 08:48:20-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5594
Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-13 08:49:00-04

Additional Certification Notes

No additional certification notes provided

2.10.36. PCS Industries Limited ERGO Colt 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148691>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-12-08 06:42:51-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-09 03:29:25-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-08 06:44:12-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-08 06:44:58-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHz/533MHz/800MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.

Component Notes: None
Modified On: 2004-12-08 06:45:52-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-12-08 06:47:07-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-08 06:48:00-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-08 06:49:18-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-08 06:50:16-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: Intel 865GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-08 06:51:50-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5967
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-12-08 06:52:38-05

Detail 10:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5967
 Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2004-12-09 03:28:55-05

Additional Certification Notes

No additional certification notes provided

2.10.37. PCS Industries Limited ERGO Colt 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157035>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4,2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz
 FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller

NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.38. PCS Industries Limited ERGO Colt GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157957>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT

Enabled (Pentium 4 processor 630-660)

Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.39. PCS Industries Limited ERGO Colt GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153700>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:48:40-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 03:47:42-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 03:47:42-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-01 03:47:42-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-01 03:47:42-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-01 03:47:42-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: Intel 915G Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-01 03:47:42-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB,HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-01 03:47:42-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6052
Detail Notes: 2048MB (256MB to 4GB upgradeable)
Component Class: Memory
Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-02-01 03:47:42-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6052

Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-02-01 03:47:42-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 6052

Detail Notes: Integrated High Definition Audio with RealTek ALC 860 CODEC

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2005-02-04 00:42:12-05

Additional Certification Notes

No additional certification notes provided

2.10.40. PCS Industries Limited ERGO Colt GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157614>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller

Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.41. PCS Industries Limited ERGO Colt GVHZ Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157042>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.42. PCS Industries Limited ERGO Colt GVSR Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148439>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-15 01:33:48-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-15 01:42:35-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-15 01:34:11-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-15 01:34:37-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: Intel P4, (1.7 ? 3.06) GHz, 400MHz/533MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-15 01:36:14-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-07-15 01:36:47-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-07-15 01:37:26-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-07-15 01:38:11-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5607

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-07-15 01:39:04-04

Detail 8:

Ease of Install: 4

Status: Compatible
Hardware Id: 5607
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-15 01:40:02-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5607
Detail Notes: Intel 845GV Chipset based Intel D845GVSRL Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 01:41:08-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5607
Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 01:42:08-04

Additional Certification Notes

No additional certification notes provided

2.10.43. PCS Industries Limited ERGO Colt GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156812>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(P4 Processor 630-660)

Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3 Update 4

Memory : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.44. PCS Industries Limited ERGO Colt GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156082>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel D915GVWB Mainboard based on Intel 915GV Chipset

Additional Certification Notes

No additional certification notes provided

2.10.45. PCS Industries Limited ERGO Compact 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148430>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-14 06:33:31-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-14 06:40:30-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-14 06:34:35-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5597

Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-14 06:35:03-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-14 06:35:34-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-14 06:40:10-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-14 06:36:31-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-14 06:37:04-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5597
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-14 06:37:51-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5597
 Detail Notes: 845GV Chipset based Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-14 06:38:26-04

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5597
 Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2004-07-14 06:33:56-04

Detail 10:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5597
 Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-07-14 06:39:01-04

Additional Certification Notes

No additional certification notes provided

2.10.46. PCS Industries Limited ERGO Compact 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148425>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-13 07:50:46-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-13 08:08:20-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5592

Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-13 07:52:07-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5592

Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-13 07:54:20-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5592

Detail Notes: Integrated Intel 82801EB AC'97 Audio
(6 channel Audio CODEC)

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-07-13 07:58:24-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5592

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-07-13 08:00:50-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5592
 Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-13 08:02:15-04

Detail 6:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5592
 Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be available as an installation medium.
 Must pass the rhr-core tests.
 Must pass the rhr-cdromdata test.
 Component Notes: None
 Modified On: 2004-07-13 07:52:50-04

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5592
 Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-13 07:56:56-04

Detail 8:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5592
 Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-13 07:59:09-04

Detail 9:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5592
 Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-13 08:01:27-04

Detail 10:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5592
 Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-07-13 08:04:17-04

Additional Certification Notes

No additional certification notes provided

2.10.47. PCS Industries Limited ERGO Compact 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148689>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-08 06:34:17-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-09 03:27:10-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5963

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-08 06:35:23-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5963

Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-08 06:36:02-05

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHz/533MHz/800MHz FSB
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-12-08 06:36:39-05

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-12-08 06:37:10-05

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-12-08 06:37:57-05

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-12-08 06:38:44-05

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-12-08 06:39:27-05

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5963
 Detail Notes: Intel 865GV Chipset based Mainboard

Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-08 06:40:05-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5963
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-08 06:40:51-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5963
Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-09 03:25:45-05

Additional Certification Notes

No additional certification notes provided

2.10.48. PCS Industries Limited ERGO Compact 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157032>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4, 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller
NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.49. PCS Industries Limited ERGO Compact 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157939>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.50. PCS Industries Limited ERGO Compact 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157947>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)

Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.51. PCS Industries Limited ERGO Compact GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157955>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.52. PCS Industries Limited ERGO Compact GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153697>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:43:01-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6049
Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 03:41:19-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6049
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 03:41:19-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6049
Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-02-01 03:41:19-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-02-01 03:41:19-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2005-02-01 03:41:19-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: Intel 915G Chipset based Mainboard

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2005-02-01 03:41:19-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-02-01 03:41:19-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: 2048MB (256MB to 4GB upgradeable)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-02-01 03:41:20-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6049

Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 03:41:20-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6049
Detail Notes: Integrated High Definition Audio with RealTek ALC 860 CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-04 00:38:29-05

Additional Certification Notes

No additional certification notes provided

2.10.53. PCS Industries Limited ERGO Compact GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157613>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller
Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.54. PCS Industries Limited ERGO Compact GVHZ Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157039>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled
MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2
CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive
Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC
Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD
Controller Card : Intel 82801EB I/O Controller Hub (ICH5)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.55. PCS Industries Limited ERGO Compact GVSR Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148438>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-15 01:22:29-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-15 01:32:27-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5606
Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 01:23:24-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5606
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 01:24:18-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5606
Detail Notes: Intel P4, (1.7 ? 3.06) GHz, 400MHz/533MHz FSB
Component Class: CPU

Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-07-15 01:25:30-04

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5606
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-15 01:26:58-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5606
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-15 01:28:08-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5606
 Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-15 01:29:10-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5606
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-15 01:29:46-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5606
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-15 01:30:41-04

Detail 9:

Ease of Install: 4

Status: Compatible
Hardware Id: 5606
Detail Notes: Intel 845GV Chipset based Intel D845GVSRL Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 01:31:25-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5606
Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 01:32:10-04

Additional Certification Notes

No additional certification notes provided

2.10.56. PCS Industries Limited ERGO Compact GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=154656>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive
Controller Card : Intel 82801FB I/O Controller Hub (ICH6)
Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive
Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Motherboard : Intel D915GVWB Mainboard based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.57. PCS Industries Limited ERGO Compact GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156806>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(P4 Processor 630-660)
Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3 Update 4

Memory : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.58. PCS Industries Limited ORiiON 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148429>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-14 06:05:44-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-14 06:13:56-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5596

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-14 06:06:00-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5596

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-14 06:06:25-04

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
 Component Class: CPU
 Component Test: Must pass the rhr-core tests.
 Must identify properly in /proc/cpuinfo.
 Component Notes: None
 Modified On: 2004-07-14 06:07:02-04

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-14 06:07:40-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-14 06:08:15-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-14 06:08:44-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-14 06:09:30-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5596
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-14 06:10:14-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5596
Detail Notes: 845GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-14 06:12:37-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5596
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-14 06:13:37-04

Additional Certification Notes

No additional certification notes provided

2.10.59. PCS Industries Limited ORiiON 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148424>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-13 06:51:47-04
Returned On: mm-dd-yy

Last Touched On: 2004-07-13 06:58:14-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-13 06:52:23-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Integrated Intel 82801EB AC'97 Audio
(6 channel Audio CODEC)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-13 06:53:56-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-13 06:55:46-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed separately.
Modified On: 2004-07-13 06:57:11-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-13 06:52:02-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-13 06:52:54-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-13 06:53:22-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-13 06:55:06-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-13 06:56:25-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5591
Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-13 06:57:51-04

Additional Certification Notes

No additional certification notes provided

2.10.60. PCS Industries Limited ORiiON 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148688>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-08 06:25:26-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-09 03:24:46-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-08 06:26:04-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-08 06:26:29-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHz/533MHz/800MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-08 06:26:56-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-12-08 06:27:28-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-08 06:28:02-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-08 06:29:08-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-08 06:29:43-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: Intel 865GV Chipset based Mainboard

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-12-08 06:30:27-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5960

Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller

Component Class: Network Interface

Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-08 06:30:57-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5960
Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-09 03:23:59-05

Additional Certification Notes

No additional certification notes provided

2.10.61. PCS Industries Limited ORiiON 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157030>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4,2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz
FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller

NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.62. PCS Industries Limited ORiiON 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157945>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)

Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.63. PCS Industries Limited ORiiON GAG Desktop/Workstation**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=157954>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHZ - 3.6GHZ, 2MB L2 Cache, 800MHZ FSB, HT Enabled (Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.64. PCS Industries Limited ORiiON GAG Desktop/Workstation**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=153698>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:45:02-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 03:43:49-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 03:43:49-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-01 03:43:49-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.

Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-01 03:43:49-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-01 03:43:49-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: Intel 915G Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-01 03:43:49-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB,HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-01 03:43:49-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: 2048MB (256MB to 4GB upgradeable)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-01 03:43:49-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6050
Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 03:43:49-05

Detail 10:
Ease of Install: 4
Status: Compatible

Hardware Id: 6050
Detail Notes: Integrated High Definition Audio with RealTek ALC 860 CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-04 00:39:37-05

Additional Certification Notes

No additional certification notes provided

2.10.65. PCS Industries Limited ORiiON GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157612>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller

Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.66. PCS Industries Limited ORiiON GVHZ Desktop/Workstation**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=157037>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.67. PCS Industries Limited ORiiON GVSR Desktop/Workstation**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=148436>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-15 01:07:12-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-16 07:57:44-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5604

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-15 01:09:49-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5604

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-15 01:11:13-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5604

Detail Notes: Intel P4, (1.7 ? 3.06) GHz, 400MHz/533MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-15 01:13:19-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5604

Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2004-07-15 01:14:04-04

Detail 5:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-07-15 01:14:47-04

Detail 6:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604
 Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-07-15 01:15:47-04

Detail 7:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2004-07-15 01:16:33-04

Detail 8:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604
 Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
 Component Class: Memory
 Component Test: Must pass the rhr-core tests.
 Component Notes: None
 Modified On: 2004-07-15 01:17:21-04

Detail 9:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604
 Detail Notes: Intel 845GV Chipset based Intel D845GVSR Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-07-15 01:18:47-04

Detail 10:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5604

Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 01:19:47-04

Additional Certification Notes

No additional certification notes provided

2.10.68. PCS Industries Limited ORiiON GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=154485>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB Mainboard based on Intel 915GV Chipset

Additional Certification Notes

No additional certification notes provided

2.10.69. PCS Industries Limited ORiiON GVWB Desktop/Workstation**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=156803>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

```
CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT
Enabled (P4 Processor 630-660)
Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3
Update 4

Memory : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860
CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB based on Intel 915G Chipset
```

Additional Certification Notes

No additional certification notes provided

2.10.70. PCS Industries Limited PRODiiGY 845GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148352>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-05-12 03:02:16-04
Returned On: mm-dd-yy
Last Touched On: 2004-05-12 03:12:36-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5454
Detail Notes: Intel Pentium 4, 1.7GHz - 3.06GHz, 400MHz/533MHz FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-05-12 03:05:48-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5454
Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-12 03:06:39-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5454
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-05-12 03:09:39-04

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
 Component Class: Digital Audio Adapter
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-audio tests.
 Component Notes: None
 Modified On: 2004-05-12 03:07:23-04

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: 845GV Chipset based Mainboard
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2004-05-12 03:10:34-04

Detail 6:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2004-05-12 03:08:11-04

Detail 7:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
 Component Class: Network Interface
 Component Test: Must complete a network install.
 Must pass the rhr-core tests.
 Must pass the rhr-net test.
 Component Notes: PXE booting must operate properly, if available.
 Modified On: 2004-05-12 03:11:34-04

Detail 8:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be avilable as an installation medium.
 Must pass the rhr-core tests.
 Must pass the rhr-cdromdata test.
 Component Notes: None
 Modified On: 2004-05-12 03:05:09-04

Detail 9:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5454
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-05-12 03:08:53-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5454
Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-05-12 03:02:40-04

Additional Certification Notes

No additional certification notes provided

2.10.71. PCS Industries Limited PRODiiGY 865G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148331>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-04-27 04:42:39-04
Returned On: mm-dd-yy
Last Touched On: 2004-04-27 04:52:35-04

Detail Data:

Detail 1:
Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-04-27 04:43:20-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-27 04:44:47-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Intel Pentium 4 (1.7GHz 3.2GHz) 400MHz/533MHz/800MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-27 04:45:49-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-27 04:46:47-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Integrated Intel 82801EB AC'97 Audio

(6 channel Audio CODEC)

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-04-27 04:47:44-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: 40GB to 160GB Upgradeable Ultra ATA/100 IDE

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-04-27 04:48:29-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-04-27 04:49:13-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-04-27 04:50:01-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: PCS P/N # 2971 (865GM2 MS-6743)

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-04-27 04:50:53-04

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5430

Detail Notes: Intel 82562EZ Fast Ethernet 10/100 Mbps

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-04-27 04:51:53-04

Additional Certification Notes

No additional certification notes provided

2.10.72. PCS Industries Limited PRODiiGY 865GV Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148687>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-12-08 06:13:49-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-09 03:22:35-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-08 06:14:24-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Intel 82801EB I/O Controller Hub (ICH5)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-08 06:14:54-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Intel Pentium 4, 1.7GHz - 3.2GHz, 400MHZ/533MHZ/800MHZ FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.

Component Notes: None
Modified On: 2004-12-08 06:15:36-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Integrated Intel 82801EB AC'97 Audio (5.1 Channel Audio CODEC)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-12-08 06:16:12-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-08 06:17:19-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-08 06:18:19-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Intel 865GV Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-08 06:18:50-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: RealTek Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-08 06:20:51-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5956
Detail Notes: Integrated Intel 865GV Chipset Featuring Intel Extreme Graphics 2
Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-09 03:22:21-05

Additional Certification Notes

No additional certification notes provided

2.10.73. PCS Industries Limited PRODiiGY 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157029>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4, 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 880 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x RealTek 8110S Gigabit Ethernet 10/100/1000 Mbps Controller

NOTE : Requires Update 4

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.74. PCS Industries Limited PRODiiGY 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157937>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.75. PCS Industries Limited PRODiiGY 915G Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157943>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 -
Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 861 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable SATA Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based AsusTek P5GD1-VM Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.76. PCS Industries Limited PRODiiGY GAG Desktop/ Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157953>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled (Pentium 4 processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - Update 4

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82562EZ Fast Ethernet 10/100Mbps Controller

Motherboard : Intel 915G Chipset based Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.77. PCS Industries Limited PRODiIGY GAG Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153696>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 03:18:40-05

Detail Data:

Detail 1:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6048
 Detail Notes: Integrated Intel Graphics Media Accelerator 900 Graphics subsystem
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2005-02-01 02:46:47-05

Detail 2:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6048
 Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be available as an installation medium.
 Must pass the rhr-core tests.
 Must pass the rhr-cdromdata test.
 Component Notes: None
 Modified On: 2005-02-01 02:47:21-05

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6048
 Detail Notes: Intel 82801FB I/O Controller Hub (ICH6)
 Component Class: Controller Card
 Component Test: Must make all required hardware available to the installation program.
 Must pass the rhr-core tests.
 Component Notes: Must pass all tests required for attached hardware.
 Modified On: 2005-02-01 02:48:59-05

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6048
 Detail Notes: 40GB to 160GB Upgradeable Hard Disk Drive
 Component Class: Fixed Disk Drive
 Component Test: Must be post install bootable.
 Must be available for installation to from the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-fdisk test.
 Component Notes: None
 Modified On: 2005-02-01 02:49:15-05

Detail 5:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6048
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2005-02-01 02:49:26-05

Detail 6:

Ease of Install: 4
 Status: Compatible

Hardware Id: 6048
Detail Notes: Intel 915G Chipset based Mainboard
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-01 02:49:42-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6048
Detail Notes: 1 x Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB,HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-01 02:50:00-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6048
Detail Notes: 2048MB (256MB to 4GB upgradeable)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-01 02:50:18-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6048
Detail Notes: 1 x Intel 82562EZ Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 02:50:40-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6048
Detail Notes: Integrated High Definition Audio with RealTek ALC 860 CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-04 00:37:07-05

Additional Certification Notes

No additional certification notes provided

2.10.78. PCS Industries Limited PRODiiGY GLC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157611>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel P4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel 865G Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : SoundMAX 4 XL with AudioESP subsystem using the Analog Devices AD1985 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547EI Gigabit Ethernet 10/100/1000 Mbps Controller

Motherboard : Intel 865G Chipset based Intel D865GLC Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.79. PCS Industries Limited PRODiiGY GVHZ Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157036>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4, 1.7GHz - 3.2GHz, 512KB/1MB L2 Cache, 400MHz/533MHz/800MHz FSB, HT Enabled

MEMORY : 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)

Video Adapter : Integrated Intel865GV Chipset Featuring Intel Extreme Graphics 2

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated Intel 82801EB AC'97 Audio CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable, PATA/SATA HDD

Controller Card : Intel 82801EB I/O Controller Hub (ICH5)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel 865GV Chipset based Intel D865GVHZ Mainboard

Additional Certification Notes

No additional certification notes provided

2.10.80. PCS Industries Limited PRODiiGY GVSR Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148422>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-07-13 00:52:47-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-13 01:12:42-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5587

Detail Notes: 40GB to 160GB Upgradeable, Ultra ATA/100 IDE

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-07-13 01:05:16-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5587

Detail Notes: Intel 845GV Chipset based Intel D845GVSR Mainboard

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-07-13 01:09:19-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5587

Detail Notes: Integrated Intel 845GV Chipset Featuring Intel Extreme Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-13 00:54:26-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5587

Detail Notes: Intel P4, (1.7 ? 3.06) GHZ, 400MHZ/533MHZ FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-07-13 01:02:45-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5587

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None
Modified On: 2004-07-13 01:05:48-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5587
Detail Notes: Intel 82562ET Fast Ethernet 10/100 Mbps Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-13 01:10:06-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5587
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-13 00:55:48-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5587
Detail Notes: Intel 82801DB I/O Controller Hub (ICH4)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-13 01:04:44-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5587
Detail Notes: 1024MB (256MB to 2GB upgradeable) DDR (2 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-13 01:07:26-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5587
Detail Notes: Integrated Intel 82801DB AC'97 Audio CODEC
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-07-13 01:12:28-04

Additional Certification Notes

No additional certification notes provided

2.10.81. PCS Industries Limited PRODiiGY GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156252>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

CPU : 1 x Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(P4 Processor 630-660)
Note: 64 bit installation on EM64T capable systems require a minimum of RHEL3
Update 4

Memory: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB based on Intel 915G Chipset

Additional Certification Notes

No additional certification notes provided

2.10.82. PCS Industries Limited PRODiiGY GVWB Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=156071>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 2.8GHz - 3.8GHz, 512KB/1MB L2 Cache, 533MHz/800MHz FSB, HT Enabled

MEMORY : 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)

Video Adapter : Integrated Intel Graphics Media Accelerator 900 Graphics subsystem

CDROM Drive : 52x IDE (ATAPI) CD-ROM Drive

Digital Audio Adapter : Integrated High Definition Audio with RealTek ALC 860 CODEC

Fixed Hard Disk : 40GB to 160GB Upgradeable Hard Disk Drive

Controller Card : Intel 82801FB I/O Controller Hub (ICH6)

Floppy Disk Drive : Standard 3.5" 1.44MB Floppy Drive

Network Interface : Intel 82562EZ Fast Ethernet 10/100 Mbps Controller

Motherboard : Intel D915GVWB Mainboard based on Intel 915GV Chipset

Additional Certification Notes

No additional certification notes provided

2.10.83. PCS Industries Limited SiiRUS Classic DP VI Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148733>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2005-01-04 02:50:20-05

Returned On: mm-dd-yy

Last Touched On: 2005-01-04 02:59:25-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: Integrated ATI Rage XL SVGA PCI Video controller with 8MB

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-01-04 02:50:39-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: 52X IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-01-04 02:51:01-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: SCSI storage controller - Integrated Dual Channel Ultra 320 SCSI Adapter
(Adaptec AIC-7902 with / Intel E7501 chipset)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-04 02:51:50-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: Standard 3.5 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2005-01-04 02:55:24-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: X5DP8-G2

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2005-01-04 02:57:14-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: Intel 82546EB Dual Port Gigabit Ethernet Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-01-04 02:57:58-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: 1-2, Intel Xeon , 1.8GHz-3.06GHz, 512KB/1MB - L2/L3 cache, 400/533 FSB, HT Enabled

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-01-04 03:24:25-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: Ultra 320 SCSI Hard Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-01-04 03:24:36-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6017

Detail Notes: 4096MB (512MB to 16GB upgradeable) Registered ECC DDR (8 DIMM Slots)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-01-04 03:25:41-05

Additional Certification Notes

No additional certification notes provided

2.10.84. PCS Industries Limited SiiRUS Classic DP VII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148332>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-04-27 04:58:30-04
Returned On: mm-dd-yy
Last Touched On: 2004-04-27 05:12:58-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: PCS P/N # P-2970 (E7501 Master ?LS2 MS-9138)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-04-27 05:08:06-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: Integrated ATI Rage XL SVGA PCI
Video controller with 8MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-27 04:58:55-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5431

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-04-27 04:59:30-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: 1-2, Intel Xeon (1.8GHz-3.06GHz), 400/533 FSB 512KB/1MB - L2/L3 cache, HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-04-27 05:00:49-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: <P>1 x Intel 82545 Gigabit Ethernet controller</P>
<P>1 x Intel 82540EM Gigabit Ethernet controller</P>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-27 05:08:24-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: Integrated Dual Channel Ultra 320 SCSI Adapter (Adaptec AIC-7902W/Intel E7501 chipset)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-04-27 05:08:41-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-27 05:12:17-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: Ultra 320 SCSI Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.

Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-27 05:10:21-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: 6144MB (512MB to 12 GB upgradeable)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-27 05:09:12-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5431
Detail Notes: <p>20/40 GB DAT Drive DDS-4</p>
<p>12/24 GB DAT Drive DDS-3</p>
<p>4/8 GB DAT Drive DDS-2</p>
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-15 02:42:51-04

Additional Certification Notes

No additional certification notes provided

2.10.85. PCS Industries Limited SiiRUS Classic DP XIX Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153695>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-08 00:40:38-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6090

Detail Notes: Integrated ATI Rage XL SVGA PCI Video controller with 8MB

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-02-08 00:35:00-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6090

Detail Notes: 52X IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-02-08 00:35:08-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6090

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2005-02-08 00:35:22-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6090

Detail Notes: Intel SE7520AF2

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed separately.

Modified On: 2005-02-08 00:35:41-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 6090

Detail Notes: Dual Intel 82546GB Gigabit Ethernet Controller
(Intel PRO/1000 Server Network Connection)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-02-08 00:36:16-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6090
Detail Notes: Integrated Dual channel Ultra 320 SCSI controller
(LSI Logic 53C1030 with Intel E7520 chipset on M/B)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-08 00:36:53-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6090
Detail Notes: Ultra 320 SCSI Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-08 00:37:32-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6090
Detail Notes: 20/40GB DAT Drive DDS-4 or 12/24GB DAT Drive DDS-3 or 4/8GB DAT Drive DDS-2
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2005-02-08 00:40:10-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6090
Detail Notes: 4096MB (512MB to 16GB upgradeable) Registered ECC DDR2 (8 DIMM Slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-08 02:49:30-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6090
Detail Notes: 1-2, Intel Xeon, 2.8GHz-3.8GHz, 1 MB - L2 cache, 800 FSB, HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-08 02:49:48-05

Additional Certification Notes

No additional certification notes provided

2.10.86. PCS Industries Limited SiiRUS Classic DP XIX Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=158060>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

```
CPU : 1 - 2, Intel Xeon, 2.8GHz - 3.8GHz, 1MB - L2 Cache, 800FSB, HT Enabled
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 -
update 4

RAM : 4096MB (512MB to 8GB upgradeable) Registered ECC DDR2(4 DIMM Slots)

Video Adapter : Integrated ATI Rage XL SVGA PCI Video controller with 8MB

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Fixed Hard Disk : Ultra 320 SCSI Hard Disk Drive

Controller Card : 6300ESB Storage Controller with Intel E7320 chipset

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Integrated Sual channel Ultra 320 SCSI controller ( LSI
Logic 53C1030 with Intel E7520 chipset on M / B )

Motherboard : Intel SE7520AF2

Tape : 20/40GB DAT Drive DDS-4 or 12/24GB DAT Drive DDS-3 or 4/8GB DAT Drive DDS-2
```

Additional Certification Notes

No additional certification notes provided

2.10.87. PCS Industries Limited SiiRUS Classic DP XVII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153694>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
 Last Touched On: 2005-02-03 00:38:49-05

Detail Data:

Detail 1:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6061
 Detail Notes: Integrated ATI Rage XL SVGA PCI Video controller with 8MB
 Component Class: 2D Video Adapter
 Component Test: Must complete an installation, either graphical or text.
 Must pass the rhr-core tests.
 Must pass the rhr-dd_x test @ each available color depth.
 Component Notes: 24 bpp testing is not required if 32 bpp is available.
 3D is not tested at this time.
 Modified On: 2005-02-03 00:28:44-05

Detail 2:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6061
 Detail Notes: 52X IDE (ATAPI) CD-ROM Drive
 Component Class: CD-ROM Drive
 Component Test: Must be available as an installation medium.
 Must pass the rhr-core tests.
 Must pass the rhr-cdromdata test.
 Component Notes: None
 Modified On: 2005-02-03 00:29:03-05

Detail 3:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6061
 Detail Notes: Standard 3.5" 1.44MB Floppy Drive
 Component Class: Floppy Disk Drive
 Component Test: Must be bootable and start the installation program.
 Must pass the rhr-core tests.
 Must pass the rhr-floppy test.
 Component Notes: None
 Modified On: 2005-02-03 00:29:32-05

Detail 4:

Ease of Install: 4
 Status: Compatible
 Hardware Id: 6061
 Detail Notes: Intel SE7320SP2
 Component Class: MotherBoard
 Component Test: Must pass rhr-core tests
 Component Notes: Any built in hardware must be listed seperately.
 Modified On: 2005-02-03 00:29:45-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6061
Detail Notes: 4096MB (512MB to 8GB upgradeable) Registered ECC DDR (4 DIMM Slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 00:37:46-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6061
Detail Notes: Intel 82541GB Gigabit Ethernet Controller
(Intel PRO/1000 Server Network Connection)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 00:38:05-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6061
Detail Notes: 6300ESB Storage Controller with Intel E7320 chipset
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-03 00:38:26-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6061
Detail Notes: 1-2, Intel Xeon, 2.8GHz-3.8GHz, 1MB - L2 cache, 800 FSB, HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 03:22:58-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6061
Detail Notes: Serial ATA Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 05:34:06-05

Additional Certification Notes

No additional certification notes provided

2.10.88. PCS Industries Limited SiiRUS Classic DP XVII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=158057>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

CPU : 1 - 2, Intel Xeon, 2.8GHz - 3.8GHz, 1MB - L2 Cache, 800FSB, HT Enabled
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - update 4

RAM : 4096MB (512MB to 8GB upgradeable) Registered ECC DDR(4 DIMM Slots)

Video Adapter : Integrated ATI Rage XL SVGA PCI Video controller with 8MB

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Fixed Hard Disk : Serial ATA Hard Disk Drive

Controller Card : 6300ESB Storage Controller with Intel E7320 chipset

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82541GB Gigabit Ethernet controller (Intel PRO/1000 Server Network Connection)

Motherboard : Intel SE7320SP2

Additional Certification Notes

No additional certification notes provided

2.10.89. PCS Industries Limited SiiRUS Classic DP XVIII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=158048>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

CPU : 1 - 2, Intel Xeon, 2.8GHz - 3.8GHz, 1MB - L2 Cache, 800FSB, HT Enabled
RAM : 4096MB (512MB to 12GB upgradeable) Registered ECC DDR(6 DIMM Slots)
Video Adapter : Integrated ATI Rage XL SVGA PCI Video controller with 8MB
CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive
Fixed Hard Disk : Ultra 320 SCSI Hard Disk Drive
Controller Card : Integrated Dual channel Ultra 320 SCSI controller (LSI Logic 53C1030 with Intel E7520 chipset on Motherboard)
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive
Network Interface : 1 x Intel 82541PI Gigabit Ethernet controller (Intel PRO/1000 Server Network Connection)
Motherboard : Intel SE7520BD2
Tape : 20/40GB DAT Drive DDS-4 or 12/24GB DAT Drive DDS-3 or 4/8GB DAT Drive DDS-2

Additional Certification Notes

No additional certification notes provided

2.10.90. PCS Industries Limited SiiRUS Classic DP XVIII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=158055>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

CPU : 1 - 2, Intel Xeon, 2.8GHz - 3.8GHz, 1MB - L2 Cache, 800FSB, HT Enabled
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 - update 4

RAM : 4096MB (512MB to 12GB upgradeable) Registered ECC DDR(6 DIMM Slots)
Video Adapter : Integrated ATI Rage XL SVGA PCI Video controller with 8MB
CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive
Fixed Hard Disk : Ultra 320 SCSI Hard Disk Drive
Controller Card : Integrated Dual channel Ultra 320 SCSI controller (LSI Logic 53C1030 with Intel E7520 chipset on Motherboard)
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive
Network Interface : 1 x Intel 82541PI Gigabit Ethernet controller (Intel PRO/1000 Server Network Connection)
Motherboard : Intel SE7520BD2
Tape : 20/40GB DAT Drive DDS-4 or 12/24GB DAT Drive DDS-3 or 4/8GB DAT Drive DDS-2

Additional Certification Notes

No additional certification notes provided

2.10.91. PCS Industries Limited SiiRUS Compact UP IX Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=158047>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

CPU : 1 x Intel Pentium 4, 1.8GHz - 3.2GHz, 512KB/1MB - L2 Cache, 400/533/800MHz FSB, HT Enabled

RAM : 2048MB (256MB to 4GB upgradeable) DDR(4 DIMM Slots)

Video Adapter : Integrated ATI Rage XL SVGA PCI Video controller with 8MB

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Fixed Hard Disk : Serial ATA Hard Disk Drive

Controller Card : FWE6300ESB storage controller with Intel E7210 chipset on Motherboard

```
Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : 1 x Intel 82547GI Gigabit Ethernet controller ( Intel
PRO/1000 Network Connection )
                   : 1 x Intel 82551QM Fast Ethernet controller ( Intel PRO/100
Network Connection )

Motherboard : Intel SE7210TP1-E Mainboard
```

Additional Certification Notes

No additional certification notes provided

2.10.92. PCS Industries Limited SiiRUS Compact UP VII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148497>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

```
Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-08-19 00:48:59-04
Returned On: mm-dd-yy
Last Touched On: 2004-08-19 01:07:10-04
```

Detail Data:

Detail 1:

```
Ease of Install: 4
Status: Compatible
Hardware Id: 5681
Detail Notes: Integrated ATI Rage XL SVGA PCI Video controller with 8MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-08-19 00:51:26-04
```

Detail 2:

```
Ease of Install: 4
```

Status: Compatible

Hardware Id: 5681

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-08-19 00:54:33-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5681

Detail Notes: <P>Integrated Single Channel Ultra 160 SCSI Controller</P><P>(Adaptec AIC-7892x w/ServerWorks GC-SL chipset)</P>

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-08-19 00:57:25-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5681

Detail Notes: <P>Intel Pentium 4 , 1.8GHZ-3.06GHZ 512KB/1MB - L2 cache</P><P>400/533 FSB, HT Enabled</P>

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-08-19 00:59:59-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5681

Detail Notes: Ultra 160 SCSI Hard Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-08-19 01:00:35-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5681

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-08-19 01:01:21-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5681

Detail Notes: 4096MB (256MB to 4GB upgradeable)

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-08-19 01:05:12-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5681
Detail Notes: PCS P/N # P-3092
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-08-19 01:06:01-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5681
Detail Notes: BroadcomBCM5702C Gigabit Ethernet controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-19 01:06:48-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5681
Detail Notes: <p>20/40 GB DAT Drive DDS-4 or </p><p>12/24 GB DAT Drive DDS-3 or<p><p>4/8 GB
DAT Drive DDS-2</p>
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-10 06:48:50-04

Additional Certification Notes

No additional certification notes provided

2.10.93. PCS Industries Limited SiiRUS Compact UP X Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148706>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-14 04:54:37-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-14 05:02:29-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5987

Detail Notes: Integrated ATI Rage XL - 8MB

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-12-14 04:54:52-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5987

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-14 04:55:20-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5987

Detail Notes: Integrated Single Channel Ultra 320 SCSI Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-14 04:55:56-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5987

Detail Notes: Intel Pentium 4 , 1.8GHz-3.2GHz, 512KB/1MB - L2 cache, 400/533/800 MHz FSB, HT Enabled

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-14 04:56:37-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5987
Detail Notes: Ultra 320 SCSI Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-14 04:57:50-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5987
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-14 04:58:33-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5987
Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR (4 DIMM slots)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-14 04:59:57-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5987
Detail Notes: PCS P/N # P-3638
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-14 05:00:52-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5987
Detail Notes: <p>1 x Intel 82547GI Gigabit Ethernet controller </p>
<p>1 x Intel 82541GI Gigabit Ethernet controller</p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-14 05:01:40-05

Additional Certification Notes

No additional certification notes provided

2.10.94. PCS Industries Limited SiiRUS Compact UP XI Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153693>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-01 02:15:04-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: Integrated ATI Rage XL SVGA PCI with 8MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-01 02:09:02-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: 52x IDE (ATAPI) CD-ROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-01 02:09:16-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: 40GB-160GB IDE/SATA
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None
Modified On: 2005-02-01 02:10:45-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-01 02:11:25-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: MSI E7210 Master-FARM MS-9149
PCS P/N # - P-3748
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-01 02:12:27-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: 1 x Intel Pentium 4 , 1.8GHz-3.2GHz, 512KB/1MB - L2 cache, 400/533/800 MHz FSB,
HT Enabled
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-01 02:12:45-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: 2048MB (256MB to 4GB upgradeable) DDR
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-01 02:12:58-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6047
Detail Notes: <p>1 x Intel 82547GI Gigabit Ethernet controller</p>
<p>1 x Intel 82541GI Gigabit Ethernet controller</p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-01 02:14:09-05

Detail 9:
Ease of Install: 4
Status: Compatible

Hardware Id: 6047
Detail Notes: Intel Hance Rapids ? FWE6300ESB & Promise 20378 SATA RAID controller w/Intel E7210 chipset on Motherboard
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-01 05:32:17-05

Additional Certification Notes

No additional certification notes provided

2.10.95. PCS Industries Limited SiiRUS Compact UP XIII Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157936>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

CPU : Intel Pentium 4 3.0GHz - 3.6GHz, 2MB L2 Cache, 800MHz FSB, HT Enabled
(Pentium 4 Processor 630-660)
Note : 64 bit installation on EM64T capable systems require a minimum of RHEL3 Update 4

RAM : 2048MB (512MB to 4GB upgradeable) Non-ECC/ECC DDR2 (4 DIMM Slots)

Video Adapter : Integrated Intel MCH module supporting standard SVGA drivers with 8MB

CDROM Drive : 52X IDE (ATAPI) CD-ROM Drive

Fixed Hard Disk : Serial ATA Hard Disk Drive

Controller Card : Intel 82801FR I/O Controller Hub with Intel E7221 Chipset

Floppy Disk Drive : Standard 3.5 1.44MB Floppy Drive

Network Interface : Intel 82551QM Fast Ethernet Controller
(Intel PRO/100 Server Network Connection)

Motherboard : Intel SE7221BA1

Additional Certification Notes

No additional certification notes provided

2.10.96. PCS Industries Limited SiiRUS Enterprise QP I Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148734>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2005-01-04 03:05:33-05

Returned On: mm-dd-yy

Last Touched On: 2005-01-04 03:14:10-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: Integrated ATI Rage XL Graphics controller with 4MB

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-01-04 03:05:53-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: 52x IDE (ATAPI) CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-01-04 03:06:28-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: SCSI storage controller - Integrated Dual Channel Ultra 320 SCSI Controller (Adaptec AIC-7902 w/ServerWorks Grand Champion HE chipset on Mainboard)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-01-04 03:07:00-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: Ultra 320 SCSI Hard Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-01-04 03:08:19-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: Standard 3.5" 1.44MB Floppy Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2005-01-04 03:08:45-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: Intel SSH4 (SPSH4/SRSH4) Platform

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2005-01-04 03:10:14-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: 1-4 x Intel Xeon MP , 1.4GHZ-3.0GHZ, 256KB/512KB - L2 cache, 512KB/1MB/2MB/4MB ? L3 cache, 400MHZ FSB, HT Enabled

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-01-04 03:13:36-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: 8096MB (1024MB to 24GB upgradeable) Reg. ECC DDR (12 DIMM slots)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-01-04 03:27:39-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6018

Detail Notes: <p>1 x Intel 82550PM 10/100 Fast Ethernet controller (Intel PRO/100+)</p>

<p>1 x Intel 82544GC Gigabit Ethernet controller (Intel PRO/1000 XT)</p>

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2005-01-04 03:29:05-05

Additional Certification Notes

No additional certification notes provided

2.11. RadiSys Corporation

2.11.1. RadiSys Corporation PFS-380 DPM3 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=453964>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.12. RLX Technologies

2.12.1. RLX Technologies RLX RackModule (1U rackable server) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148396>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-08 09:41:17-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5538
Detail Notes: Intel 82546EB dual port Gigabit Ethernet controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-08 09:00:23-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5538
Detail Notes: Up to two Intel P4 Xeon processors (2800MHz - 3200MHz)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-08 09:01:04-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5538
Detail Notes: ATI Rage XL 8MB PCI graphic controller
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.

Modified On: 2004-06-08 09:03:54-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538

Detail Notes: Intel E7501 chipset

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-06-08 09:20:43-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538

Detail Notes: Intel 82801CA IDE controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-06-08 08:59:43-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538

Detail Notes: Up to 12GB DDR PC2100 ECC memory

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-06-08 09:01:47-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538

Detail Notes: Up to two 3.5in ATA/100 IDE disk drives

80GB, 120GB or 160GB capacities.

Up to three 3.5in SCSI U320 disk drives

36GB, 72GB or 144GB capacities.

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-06-08 09:16:28-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538

Detail Notes: 3ware Escalade 8006-2LP ATA RAID Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-06-08 09:18:24-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5538
Detail Notes: Adaptec 2120S SCSI RAID controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-08 09:20:55-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5538
Detail Notes: Standard IDE CD-ROM Drive

Panasonic, Teac, or Sony.
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-06-08 09:39:08-04

Detail 11:
Ease of Install: 4
Status: Compatible
Hardware Id: 5538
Detail Notes: Standard 3.5" 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-06-08 09:40:07-04

Additional Certification Notes

No additional certification notes provided

2.12.2. RLX Technologies RM1100 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148744>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-19 09:22:50-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: Intel I/O Controller HUB PATA

Intel I/O Controller HUB SATA
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-19 09:00:50-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: Single Intel Celeron 2.66GHz or Intel Xeon w/EM64T 3.2GHZ
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-19 09:01:37-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: SATA: one or two 80 or 250GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-19 09:02:08-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: Intel 7721 Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-01-19 09:02:24-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: Dual Broadcom NetXtreme 5721 Gigabit Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-19 09:02:56-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: 4GB DDR2 400MHz

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-19 09:03:22-05

Detail 7:

Status: Not Supported
Hardware Id: 6033
Detail Notes: NOTE:

Optional PCI cards were not available at the time of testing.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2005-01-19 09:04:42-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6033
Detail Notes: TEAC CD-224E
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-19 09:04:48-05

Additional Certification Notes

No additional certification notes provided

2.12.3. RLX Technologies RM1400 Server**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=148742>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2005-01-18 08:39:41-05
Returned On: mm-dd-yy
Last Touched On: 2005-01-19 09:22:56-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: Intel 82801EB UltraATA Storage Controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-18 08:44:25-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: Single or Dual Intel Xeon w/EM64T 2.8 to 3.6GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-18 08:44:36-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: SATA: one or two 80 or 250GB, Not hot-swappable
SCSI: up to four Ultra 320; 36 or 146GB, Hot-swappable
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-18 08:46:10-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: Intel 7520 Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-01-18 09:43:47-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: Dual 82546GB Gigabit Ethernet Controller

Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-18 09:45:09-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: 8GB DDR2 400MHz

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-19 08:57:07-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6029
Detail Notes: TEAC CD-224E
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-19 08:57:27-05

Detail 8:
Status: Not Supported
Hardware Id: 6029
Detail Notes: NOTE:

Optional PCI cards were not available at the time of testing.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2005-01-19 08:58:28-05

Additional Certification Notes

No additional certification notes provided

2.12.4. RLX Technologies SB6400 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148745>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-01-19 09:22:45-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: Single or Dual Intel Xeon w/EM64T 2.8-3.6GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-01-19 09:11:17-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: ATA: one or two 30 or 60GB
SCSI: up to two 73GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-19 09:12:00-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: Intel 7520 Based
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-01-19 09:12:16-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: 8GB DDR2 400MHz
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-01-19 09:14:32-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: USB attached

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-01-19 09:16:32-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: Intel Enterprise Southbridge PATA

Optional: QLogic QLA2312 Dual Channel Fibre
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-01-19 09:22:24-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6034
Detail Notes: Dual Intel 82546GB Gigabit Ethernet Controller

Optional: PCI Dual Intel 82546GB Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-01-19 09:22:36-05

Additional Certification Notes

No additional certification notes provided

2.12.5. RLX Technologies Server Blade 1200MHz (Intel P3 based) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148395>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-08 08:44:49-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5537
Detail Notes: ALi M5229 Integrated IDE controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-08 08:44:30-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5537
Detail Notes: Make: Intel
Model: i82559 EtherExpress Pro100
Quantity: 3
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-08 08:44:30-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5537
Detail Notes: Make: Intel
Model: Pentium 3 (Tualatin)
Speed: 800MHZ
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-08 08:44:31-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5537
Detail Notes: 1 GB PC2100 DDR SDRAM w/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-08 08:44:31-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5537
Detail Notes: Make: Fujitsu
Model: MHS2060AT
Capacity: 60GB
Quantity: 2
Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-08 08:44:31-04

Additional Certification Notes

No additional certification notes provided

2.12.6. RLX Technologies Server Blade 800MHz (Intel P3 based) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148394>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-08 08:44:18-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5536
Detail Notes: ALi M5229 Integrated IDE controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-08 08:35:03-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5536
Detail Notes: Make: Intel

Model: i82559 EtherExpress Pro100
Quantity: 3
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-08 08:35:10-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5536
Detail Notes: **Make:** Intel
Model: Pentium 3 (Tualatin)
Speed: 800MHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-08 08:35:25-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5536
Detail Notes: 1 GB PC2100 DDR SDRAM w/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-08 08:36:00-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5536
Detail Notes: **Make:** Fujitsu
Model: MHS2060AT
Capacity: 60GB
Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation **to** from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-08 08:43:32-04

Additional Certification Notes

No additional certification notes provided

2.12.7. RLX Technologies ServerBlade 2800i Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148213>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2003-12-12 17:16:23-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5254
Detail Notes: Intel 82801CA IDE controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2003-12-12 17:15:48-05

Detail 2:

Status: Compatible
Hardware Id: 5254
Detail Notes: Two Intel 82544EI 1000Mb NICs
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2003-12-12 17:15:48-05

Detail 3:

Status: Compatible
Hardware Id: 5254
Detail Notes: Up to two Intel P4 Xeon processors (2800MHz - 3200MHz)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2003-12-12 17:15:48-05

Detail 4:

Status: Compatible
Hardware Id: 5254
Detail Notes: Up to 8GB DDR PC2100 ECC memory
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2003-12-12 17:15:48-05

Detail 5:

Status: Compatible
Hardware Id: 5254
Detail Notes: Up to two 2.5in ATA/100 IDE disk drives.

20GB or 60GB capacities available

20GB - Fujitsu MHS2020AT

60GB - Fujitsu MHS2060AT

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2003-12-12 17:15:48-05

Detail 6:

Status: Compatible

Hardware Id: 5254

Detail Notes: Intel 82801CA 10/100Mb NIC

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2003-12-12 17:15:48-05

Detail 7:

Status: Compatible

Hardware Id: 5254

Detail Notes: ATI Mach64 Rage XL w/8MB video memory

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2003-12-12 17:15:48-05

Detail 8:

Status: Compatible

Hardware Id: 5254

Detail Notes: Intel 82801CA USB Hub (USB connector part of VGA option card).

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2003-12-12 17:15:48-05

Additional Certification Notes

No additional certification notes provided

2.13. Sai InfoSystem (India) Ltd.

2.13.1. Sai InfoSystem (India) Ltd. Sunny S333 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148545>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-09-20 00:52:37-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-20 01:00:24-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-20 00:52:56-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: 52x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-20 00:53:21-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: Adaptec AIC-7901 Signal-Channel SCSI controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-20 00:53:49-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: Intel Pentium 4 HT (3.2 GHz)

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-20 00:54:25-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: 40 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-20 00:55:02-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: 1.44 MB Mini Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-20 00:57:14-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: 256 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-20 00:57:50-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: Intel Server Board SE7210TP1-E
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-20 00:58:24-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5748
Detail Notes: <p>Intel PRO/100+ Server Network Connection</p>
<p>Intel PRO/1000 Server Network Connection</p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-20 00:59:17-04

Additional Certification Notes

No additional certification notes provided

2.13.2. Sai InfoSystem (India) Ltd. Sunny S450 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148326>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-04-22 06:37:22-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-13 05:45:01-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5408
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-22 07:03:17-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5408
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.

Modified On: 2004-04-22 06:41:42-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: Dual Channel Adaptec AIC-7902W

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-22 07:00:19-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: 2048 MB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-04-22 07:04:27-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: 52x

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-22 06:42:18-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: Intel Server Board SE7501HG

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-04-22 07:06:06-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: Intel Xeon (3.06Ghz) x 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-22 06:44:00-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5408

Detail Notes: 73 GB

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-22 07:01:51-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5408
Detail Notes: Two Intel PRO1000+ Server Network Adapter
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-22 07:07:52-04

Additional Certification Notes

No additional certification notes provided

2.13.3. Sai InfoSystem (India) Ltd. Sunny S450 (MS2430-171) Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148573>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-10-11 01:27:11-04
Returned On: mm-dd-yy
Last Touched On: 2004-10-11 02:03:05-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-11 01:27:26-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: 52x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-11 01:28:33-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: Dual Channel Adaptec AIC-7902W
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-11 01:29:03-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: Intel Xeon (3.20Ghz) X 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-11 01:30:09-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: 18 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-11 01:30:50-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None

Modified On: 2004-10-11 01:31:34-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: 4096 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-11 01:52:11-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: Intel Server Board SE7501HG2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-10-11 02:01:08-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5783
Detail Notes: Two Intel PR01000+ Server Network Adapter
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-10-11 02:01:58-04

Additional Certification Notes

No additional certification notes provided

2.13.4. Sai InfoSystem (India) Ltd. Sunny S450 I2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148423>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: Intel(R) IPF

Created On: 2004-07-13 05:28:58-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-13 05:41:59-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5588

Detail Notes: Dual Channel LSI Logic 5C1030 Ultra320 SCSI Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-07-13 05:38:17-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5588

Detail Notes: ATI Rage XL (rev 27) Video RAM: 8 MB

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-07-13 05:29:20-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5588

Detail Notes: Intel Server Platform SR870BH2

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-07-13 05:39:58-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5588

Detail Notes: Slimtype COMBO LSC-24081M, ATAPI CD/DVD-ROM drive

Component Class: CD-ROM Drive

Component Test: Must be avilable as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-07-13 05:37:11-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5588

Detail Notes: Seagate 73 GB

Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-13 05:38:55-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5588
Detail Notes: Intel Corp. 82546EB 2-port Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-13 05:41:28-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5588
Detail Notes: IA-64 Itanium 2, Speed: 1.5GHz Cache: 6 MB X 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-13 05:37:36-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5588
Detail Notes: 1024 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-13 05:39:24-04

Additional Certification Notes

No additional certification notes provided

2.13.5. Sai InfoSystem (India) Ltd. Sunny S630 G2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148324>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-04-22 06:08:10-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-13 05:45:56-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5406
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-22 06:08:43-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5406
Detail Notes: 73 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation **to** from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-22 06:12:25-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5406
Detail Notes: 4096 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-22 06:14:53-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5406
Detail Notes: **<P>Intel Pro/100+ Server Network Connection</P>**
<P>Intel Pro/1000+ XT Network Connection</P>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-04-22 06:17:14-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5406

Detail Notes: 52x

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-22 06:09:17-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5406

Detail Notes: Intel Xeon (3Ghz) x 4

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-04-22 06:10:45-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5406

Detail Notes: 1.44 MB

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-04-22 06:13:04-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5406

Detail Notes: Intel Server Platform SPSH4

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-04-22 06:15:45-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5406

Detail Notes: Adaptec AIC-7902 Dual-Channel ULTRA 320

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-22 06:11:25-04

Additional Certification Notes

No additional certification notes provided

2.13.6. Sai InfoSystem (India) Ltd. Sunny S630 I2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148313>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: Intel(R) IPF

Created On: 2004-04-07 01:21:33-04

Returned On: mm-dd-yy

Last Touched On: 2004-07-13 05:46:35-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5391

Detail Notes: 52x

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-04-07 01:27:06-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5391

Detail Notes: LSI 5C390 Dual-Channel Ultra320 SCSI Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-04-07 01:28:32-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5391

Detail Notes: ATI Rage XL

Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-07 01:22:37-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel Itanium 2 (1.3Ghz) X 4
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-04-07 01:27:49-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 73 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-07 01:29:25-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-07 01:30:32-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 1024 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-07 01:31:19-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel Server Platform SR870BN4
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-04-07 01:32:08-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel 82540EM 10/100/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-07 01:33:38-04

Additional Certification Notes

No additional certification notes provided

2.13.7. Sai InfoSystem (India) Ltd. Sunny S630 I2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153835>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: Intel(R) IPF
Created On: 2004-04-07 01:21:33-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-13 05:46:35-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 52x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-04-07 01:27:06-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: LSI 5C390 Dual-Channel Ultra320 SCSI Controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-04-07 01:28:32-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-07 01:22:37-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel Itanium 2 (1.3Ghz) X 4
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-04-07 01:27:49-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 73 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-07 01:29:25-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-04-07 01:30:32-04

Detail 7:

Ease of Install: 4
Status: Compatible

```
Hardware Id: 5391
Detail Notes: 1024 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-07 01:31:19-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel Server Platform SR870BN4
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-04-07 01:32:08-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5391
Detail Notes: Intel 82540EM 10/100/1000
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-07 01:33:38-04
```

Additional Certification Notes

No additional certification notes provided

2.13.8. Sai InfoSystem (India) Ltd. Sunny S99 (DS3312-135) Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148596>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86
Created On: 2004-10-27 01:08:21-04
Returned On: mm-dd-yy
Last Touched On: 2004-11-01 00:19:29-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: Intel Media Accelerator 900
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-27 01:08:55-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: 52x
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-27 01:09:30-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: ATA IDE & SATA interfaces
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-27 01:10:10-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: Intel Pentium 4 (3.2Ghz) With 800 FSB & HT
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-27 01:11:22-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: Realtek ALC860
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-10-27 01:12:15-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: 40 GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-27 01:12:47-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: 1.44 MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-10-27 01:13:19-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: 256 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-27 01:14:05-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: Intel 915G Chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-10-27 01:15:01-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5822
Detail Notes: Realtek RTL8139
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-10-27 01:16:00-04

Additional Certification Notes

No additional certification notes provided

2.14. Samsung

2.14.1. Samsung SS210 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148559>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-30 08:55:18-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: Adptec aic7902 Ultra320 SCSI adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-21 09:46:44-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: 1GB/24GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-21 09:47:17-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: Xeon MP 2.0~3.0GHz(4way)
Hyperthreading capable

Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-21 09:47:53-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: 24X Slim Combo
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-21 09:48:08-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: ServerWorks CSB5 IDE Controller (rev 93)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-21 09:48:16-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: IBM 146G/73/36(10K RPM)

Default: 36G
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-21 09:48:58-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: ServerWorks OSB4/CSB5 USB Controller (rev 05)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-21 09:49:15-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5765
Detail Notes: Intel Corp. 82544GC Gigabit Ethernet Controller (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-21 09:49:29-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5765

Detail Notes: Intel Corp. 82557/8/9 [Ethernet Pro 100] (rev 0d)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-21 09:49:37-04

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5765

Detail Notes: ATI Technologies Inc Rage XL (8MB)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-09-30 08:54:19-04

Additional Certification Notes

No additional certification notes provided

2.14.2. Samsung SS370 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148557>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2004-10-15 17:48:07-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-20 15:12:53-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: Xeon MP 2.0 ~ 2.8GHz (4way or 8way)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-20 15:13:32-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: SCSI storage controller: LSI 53c1030 (rev 07)<p>
Dual Channel
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-20 15:14:00-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: Ultra 320 SCA 36/73/146GB

Default: Hitachi 36G
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-20 15:14:27-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: BROADCOM Corporation: 5704 Gigabit Ethernet<p>
Qty: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-20 15:14:56-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: 1GB/64GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-20 15:15:12-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5762
Detail Notes: DVDROM : HL-DT-STDVD-ROM GDR8081N
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-11 09:36:36-04

Additional Certification Notes

No additional certification notes provided

2.14.3. Samsung ZSS130 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148569>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-09-27 09:16:34-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-30 08:52:44-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: ATI Rage XL 8MB
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-27 09:17:04-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: 24X Slim Combo
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-27 09:17:30-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: Intel Corp. 82801EB/ER (ICH5/ICH5R) Ultra ATA 100 Storage Controller
LSI 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-27 09:20:08-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: Xeon DP (Nocona) 2.8-3.6GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-27 09:20:37-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: Seagate 36GB/73GB/146GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-27 09:21:12-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777

Detail Notes: 512MB / 6GB DDR-2/400
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-27 09:22:07-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: Intel E7520 (Lindenhurst)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-27 09:23:28-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: Intel 82546GB (Anvik-II) x2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-27 09:24:03-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5777
Detail Notes: 500W / Acpel
Component Class: Power Supply
Component Test: Must Pass all tests attached hardware
Component Notes: Power Supplies are not tested outside of full systems.
Modified On: 2004-09-27 09:24:48-04

Additional Certification Notes

No additional certification notes provided

2.14.4. Samsung ZSS230 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=177394>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

Product specifications are as follows:
Processors: Intel Xeon MP CPU 3.33GHz (4 Socket), L2 Cache: 1MB, L3 Cache: 8MB
Memory: 16G
HDD controller : LSI 53C1030
(Optional) Internal RAID: Intel SR0MBU42E
HDD Type: Seagate 300GB(10K RPM)
USB Ports: 5
Network Interface Controller:
Broadcom NetXtreme BCM5704 Gigabit Ethernet
Broadcom NetXtreme BCM5704 Gigabit Ethernet
Intel Pro1000 XT Gigabit Ethernet Controller
(Optional) Fiber channel HWFCM Intel FC Module for EMC AX100 storage
VGA: ATI Radeon 7000(Integrated) ATI® Radeon 7000
CDROM: TEAC 24X Slim DVD-ROM DW-224E

System has no configurable options.

Additional Certification Notes

No additional certification notes provided

2.14.5. Samsung ZSS230-D Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179540>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

Product specifications are as follows:
Processors: Intel Xeon MP 7040 (3.0GHz)*4 Socket, L2 Cache: 4MB
RAM: 16GB
HDD Controller: LSI 53C1030
HDD: Seagate 300G(10K RPM)
USB Ports: 5
Network Interface Cards: 2*Broadcom Gbit 5704, 1*Intel Gbit Pro1000 XT
VGA: ATI Radeon 7000(Integrated) ATI® Radeon 7000
CDROM: TEAC DW-224E CD-RW/DVD-ROM combo drive

Following are optional items:
Internal RAID(optional): Intel SR0MBU42E
Fibre Channel(optional card): HWFCM Intel FC Module
External HDD(optional): EMC AX100 storage (Fiber channel HWFCM Intel Module for

EMC AX100 Storage)

Their are no configurable options.

Additional Certification Notes

No additional certification notes provided

2.14.6. Samsung ZSS370X Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=171077>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Product specifications are as follows:
Processor: 8xIntel(R) Xeon(TM) MP CPU speed: 3.00GHz, L2 Cache: 512KB
FSB: 400MHz
Memory: 16GB
HDD controller: 2xSCSI U320(LSI Logic) 53c1030 (rev 07) Dual Channel
HDD: Ultra320 SCSI 2xST3300007LC (Seagate 300GB)
NIC: Broadcom 5704 Dual Gigabit 10/100/1000
VGA: ATI Radeon RV-100 (built-in)
CD/DVD ROM: MATSHITA DVD-ROM SR-8177 ATAPI CD/DVD-ROM drive
USB ports: 3
RAID(option card): IBM ServerRAID

System has no configurable options.

Additional Certification Notes

No additional certification notes provided

2.15. Sun Microsystems, Inc.

2.15.1. Java Workstation W1100z/W2100z Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=202028>

Summary

- *Version:* Update 7
- *Category:* Desktop/Workstation
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.2. Sun Fire V20z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153870>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-23 23:19:43-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: <P>BIOS version 1.26.04</P>

<P>AMD 8000 series chipset which includes AMD8131 + AMD 8111 and AMD8151</P>

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-10 17:11:42-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: <P>CD/Floppy</P>

<P>Optional: DVD/Floppy</P>

Component Class: Removable Storage Device
Component Test: Must pass the rhr-core tests.
Must pass the rhr-remdisk test.
Component Notes: The device is not required to be bootable or available during install.
Modified On: 2004-09-10 17:11:49-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: Trident Blade 3D PCI/AGP video card
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-10 17:11:55-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 16GB (8 x 2GB)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-10 17:12:01-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: Ultra320 SCSI dual port (LSI 22320-R) ? only in 133Mhz slot
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-10 17:12:34-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 1 x USB1.1 port, 1 x RS232 serial port, 1 x PS/2 port keyboard, 1 x PS/2 mouse.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-09-10 17:12:40-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 1 x 73GB Ultra320 SCSI disk + 1 x36GB Ultra320 SCSI disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-10 17:12:53-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: Dual Gigabit Ethernet (Intel PWLA8492 MT) ? Any slot

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-10 17:13:08-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: Intel Pro/1000 MT Quad Port PCI

<p>

NOTE: See knowledgebase for information regarding the 4th port.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-15 15:47:11-04

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: 2 x 2.2Ghz AMD Opteron Processor (248)

2 x 2.2Ghz AMD Opteron Processor (250)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-11-30 11:15:29-05

Detail 11:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: 2 x NetExtreme BCM5703 Gigabit Ethernet

1 x NetExtreme BCM5704 Gigabit Ethernet

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-12-13 10:46:10-05

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7034](#)²⁸ Why can't I use/see all of the ports on the Intel® PRO/1000 MT Quad Port Server Adapter(s)?

2.15.3. Sun Fire V20z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148523>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-09-23 23:19:43-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: <P>BIOS version 1.26.04</P>
<P>AMD 8000 series chipset which includes AMD8131 + AMD 8111 and AMD8151</P>
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-10 17:11:42-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: <P>CD/Floppy</P>
<P>Optional: DVD/Floppy</P>
Component Class: Removable Storage Device
Component Test: Must pass the rhr-core tests.
Must pass the rhr-remdisk test.
Component Notes: The device is not required to be bootable or available during install.
Modified On: 2004-09-10 17:11:49-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: Trident Blade 3D PCI/AGP video card
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-10 17:11:55-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 16GB (8 x 2GB)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-10 17:12:01-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: Ultra320 SCSI dual port (LSI 22320-R) ? only in 133Mhz slot
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-10 17:12:34-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 1 x USB1.1 port, 1 x RS232 serial port, 1 x PS/2 port keyboard, 1 x PS/2 mouse.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-09-10 17:12:40-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: 1 x 73GB Ultra320 SCSI disk + 1 x36GB Ultra320 SCSI disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-10 17:12:53-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5717
Detail Notes: Dual Gigabit Ethernet (Intel PWLA8492 MT) ? Any slot
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-10 17:13:08-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: Intel Pro/1000 MT Quad Port PCI

<p>

NOTE: See knowledgebase for information regarding the 4th port.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-15 15:47:11-04

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: 2 x 2.2Ghz AMD Opteron Processor (248)

2 x 2.2Ghz AMD Opteron Processor (250)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-11-30 11:15:29-05

Detail 11:

Ease of Install: 4

Status: Compatible

Hardware Id: 5717

Detail Notes: 2 x NetExtreme BCM5703 Gigabit Ethernet

1 x NetExtreme BCM5704 Gigabit Ethernet

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-12-13 10:46:10-05

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7034](#)²⁹ Why can't I use/see all of the ports on the Intel® PRO/1000 MT Quad Port Server Adapter(s)?

2.15.4. Sun Fire V20z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148325>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Where: Vendor (Self Certification) - Guildford, Surrey, United Kingdom
Cpu Name: AMD64 and Intel(R) EM64T
Created On: 2004-04-22 06:12:36-04
Returned On: mm-dd-yy
Last Touched On: 2004-04-22 12:42:03-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: <P>BIOS version 1.26.04</P>
<P>AMD 8000 series chipset which includes AMD8131 + AMD 8111 and AMD8151</P>
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-04-22 06:38:37-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: <P>CD/Floppy</P>
<P>Optional: DVD/Floppy</P>
Component Class: Removable Storage Device
Component Test: Must pass the rhr-core tests.
Must pass the rhr-remdisk test.
Component Notes: The device is not required to be bootable or available during install.
Modified On: 2004-04-22 06:43:51-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: Trident Blade 3D PCI/AGP video card
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-22 06:12:55-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 16GB (8 x 2GB)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-22 06:14:45-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: Ultra320 SCSI dual port (LSI 22320-R) ? only in 133Mhz slot
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-04-22 06:19:41-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 1 x USB1.1 port, 1 x RS232 serial port, 1 x PS/2 port keyboard, 1 x PS/2 mouse.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-04-22 06:47:29-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 1 x 73GB Ultra320 SCSI disk + 1 x36GB Ultra320 SCSI disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-04-22 06:16:54-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: Dual Gigabit Ethernet (Intel PWLA8492 MT) ? Any slot
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-04-22 06:23:02-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 2 x 2.2GHz AMD Opteron Processor (248)
2 x 2.4GHz AMD Opteron Processor (250)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-30 11:14:13-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5407

```
Detail Notes: 2 x NetExtreme BCM5703 Gigabit Ethernet<br>
1 x NetExtreme BCM5704 Gigabit Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-13 10:45:51-05
```

Additional Certification Notes

No additional certification notes provided

2.15.5. Sun Fire V20z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153838>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

```
Where: Vendor (Self Certification) - Guildford, Surrey, United Kingdom
Cpu Name: AMD64 and Intel(R) EM64T
Created On: 2004-04-22 06:12:36-04
Returned On: mm-dd-yy
Last Touched On: 2004-04-22 12:42:03-04
```

Detail Data:

Detail 1:

```
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: <P>BIOS version 1.26.04</P>
<P>AMD 8000 series chipset which includes AMD8131 + AMD 8111 and AMD8151</P>
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-04-22 06:38:37-04
```

Detail 2:

```
Ease of Install: 4
Status: Compatible
```

Hardware Id: 5407
Detail Notes: <P>CD/Floppy</P>
<P>Optional: DVD/Floppy</P>
Component Class: Removable Storage Device
Component Test: Must pass the rhr-core tests.
Must pass the rhr-remdisk test.
Component Notes: The device is not required to be bootable or available during install.
Modified On: 2004-04-22 06:43:51-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: Trident Blade 3D PCI/AGP video card
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-04-22 06:12:55-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 16GB (8 x 2GB)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-04-22 06:14:45-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: Ultra320 SCSI dual port (LSI 22320-R) ? only in 133Mhz slot
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-04-22 06:19:41-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 1 x USB1.1 port, 1 x RS232 serial port, 1 x PS/2 port keyboard, 1 x PS/2 mouse.
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into another category. Items listed in this group are subject to tests as determined by Red Hat, Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-04-22 06:47:29-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5407
Detail Notes: 1 x 73GB Ultra320 SCSI disk + 1 x36GB Ultra320 SCSI disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-04-22 06:16:54-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5407

Detail Notes: Dual Gigabit Ethernet (Intel PWLA8492 MT) ? Any slot

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-04-22 06:23:02-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5407

Detail Notes: 2 x 2.2GHz AMD Opteron Processor (248)

2 x 2.4GHz AMD Opteron Processor (250)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-11-30 11:14:13-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5407

Detail Notes: 2 x NetExtreme BCM5703 Gigabit Ethernet

1 x NetExtreme BCM5704 Gigabit Ethernet

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-12-13 10:45:51-05

Additional Certification Notes

No additional certification notes provided

2.15.6. Sun Fire V40z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148540>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-09-15 13:32:00-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-27 10:57:01-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5741
Detail Notes: Trident Microsystems Blade 3D PCI/AGP (rev 3a)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-15 13:35:48-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5741
Detail Notes: TEAC CD-224E Slim CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-15 13:37:40-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5741
Detail Notes: LSI 53c1030 PCI-X Fusion-MPT Dual Ultra320
LSI 53c895 (rev 02)
AMD 8111 IDE (rev 03)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-15 13:39:37-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5741
Detail Notes: Standard 3 1/2" 1.44MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-09-15 13:43:15-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5741

Detail Notes: (4x) AMD Opteron 848 @ 1.6GHz, 1.8GHz, 2.0GHz, 2.2GHz

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-09-15 13:53:13-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5741

Detail Notes: SEAGATE ST373307LC (Qty. x5)

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-15 13:53:20-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5741

Detail Notes: 512MB -> 64GB ECC DDR 333 SDRAM (16-slots, 4GB/DIMM max.)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-15 13:54:39-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5741

Detail Notes: Chipset: Advanced Micro Devices 8111/8131

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-09-15 14:05:16-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5741

Detail Notes: (2x) Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (built in)

(4x*) 82546EB Gigabit Ethernet Controller (optional)

<p>

* NOTE: Only three are usable, see knowledgebase for details.

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-15 14:16:43-04

Additional Certification Notes

No additional certification notes provided

2.15.7. Sun Fire V40z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148541>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

Additional Data:

Cpu Name: AMD64 and Intel(R) EM64T
Last Touched On: 2004-09-27 10:56:50-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: Trident Microsystems Blade 3D PCI/AGP (rev 3a)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-15 14:18:58-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: TEAC CD-224E Slim CD-ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-15 14:18:58-04

Detail 3:

Ease of Install: 4

Status: Compatible
Hardware Id: 5742
Detail Notes: LSI 53c1030 PCI-X Fusion-MPT Dual Ultra320

LSI 53c895 (rev 02)

AMD 8111 IDE (rev 03)
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-15 14:18:58-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: Standard 3 1/2" 1.44MB
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-09-15 14:18:58-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: (4x) AMD Opteron 848 @ 1.6GHz, 1.8GHz, 2.0GHz, 2.2GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-15 14:18:58-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: SEAGATE ST373307LC (Qty. x5)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-15 14:18:58-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: 512MB -> 64GB ECC DDR 333 SDRAM (16-slots, 4GB/DIMM max.)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-15 14:18:58-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5742
Detail Notes: Chipset: Advanced Micro Devices 8111/8131
Component Class: MotherBoard
Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-15 14:18:58-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5742

Detail Notes: (2x) Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (built in)
(4x) 82546EB Gigabit Ethernet Controller (optional)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-27 10:56:39-04

Additional Certification Notes

No additional certification notes provided

2.15.8. Sun Fire V60x Server Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148260>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2004-02-27 05:25:31-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: PCI IDE adapter

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-27 05:32:25-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: Intel Corp. 82546EB Gigabit Ethernet Controller (rev 01)

Quantity: 2

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-02-27 05:32:13-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: MATSHITADVD-ROM SR-8177, ATAPI CD/DVD-ROM drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-02-27 05:32:47-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: Adaptec aic7902 Ultra320 SCSI adapter

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-27 05:33:11-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: 1.44M

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-02-27 05:33:36-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5327

Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-02-27 05:32:36-05

Detail 7:

Ease of Install: 4

Status: Compatible
Hardware Id: 5327
Detail Notes: PCI USB adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-27 05:32:59-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5327
Detail Notes: Vendor: SEAGATE Model: ST336753LSUN36G Rev: 0249

Type: Direct-Access ANSI SCSI revision: 03

Quantity: 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-02-27 05:33:24-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5327
Detail Notes: Intel(R) XEON(TM) CPU 3.06 GHz

Qty: 2

Hyperthreading capable
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-02-27 05:34:16-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5327
Detail Notes: 1GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-02-27 05:34:31-05

Additional Certification Notes

No additional certification notes provided

2.15.9. Sun Fire V65x Server Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148261>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-02-27 05:48:59-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: Vendor: SEAGATE Model: ST336607LC36G Rev: 0249

Type: Direct-Access ANSI SCSI revision: 03

Quantity: 1
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-02-27 05:45:35-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: Intel Corp. 82546EB Gigabit Ethernet Controller (rev 01)

Quantity: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-02-27 05:45:48-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: PCI IDE adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-27 05:46:01-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: 1.44M

Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-02-27 05:46:17-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: Intel(R) XEON(TM) CPU 3.06 GHz

Qty: 2

Hyperthreading capable
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-02-27 05:47:05-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-02-27 05:47:22-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: MATSHITADVD-ROM SR-8177, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-02-27 05:47:36-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: PCI USB adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-27 05:48:14-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: Adaptec aic7902 Ultra320 SCSI adapter
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-02-27 05:48:34-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5328
Detail Notes: 2GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-02-27 05:47:56-05

Additional Certification Notes

No additional certification notes provided

2.15.10. Sun Fire X2100 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167620>

Summary

- *Version:* Update 5
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.11. Sun Fire X2100 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=201070>

Summary

- *Version:* Update 8
- *Category:* Server

- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7863](#)³⁰ Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.15.12. Sun Fire X2200 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=201068>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7863](#)³¹ Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.15.13. Sun Fire X4100 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=171254>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.14. Sun Fire X4100 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=287771>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.15. Sun Fire X4200 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=171257>

Summary

- *Version:* Update 7
- *Category:* Server
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.16. Sun Fire X4200 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=212598>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.17. Sun Fire X4200 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=224240>

Summary

- *Version:* Update 8
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7863](#)³² Is there a clock skew problem with AMD rev. F Opterons running Red Hat Enterprise Linux 3 i386 kernel?

2.15.18. Sun Fire X4600 M2 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=224084>

Summary

- *Version:* RHEL3.8
- *Category:* Server
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.19. Sun Microsystems Cobalt LX 50 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148262>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-02-27 06:21:22-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: Two Intel(R) 10/100 82557/8/9 Fast Ethernet Controllers
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-02-27 06:15:52-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5329

Detail Notes: ATAPI CDRom drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-02-27 06:16:05-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: Seagate ST336605LC 36GB
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-02-27 06:17:06-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: ATI Rage XL video controller with 8 MB of SDRAM
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-02-27 06:17:32-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: Intel Pentium III, 1.4 GHz, Quantity 2
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-02-27 06:18:30-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: 1.44M - Bay3 for SCSI configuration.
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-02-27 06:18:43-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5329
Detail Notes: PC133 Registered ECC SDRAM DIMM, installed in pairs
Installed RAM - 2GB
Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-02-27 06:18:59-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5329

Detail Notes: CSB5 controller includes USB and IDE controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-27 06:19:16-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5329

Detail Notes: Adaptec 7899 dual-channel Ultra-160 SCSI controller. (SCSI Board Only)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-27 06:19:50-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5329

Detail Notes: Promise Technology* PDC20267 Dual channel ATA-100 Controller. (ATA-100 board only)

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-02-27 06:20:27-05

Additional Certification Notes

No additional certification notes provided

2.15.20. Sun Microsystems W1100z/W2100z Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148524>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation

- *Platforms:* x86_64

Additional Comments

Additional Data:

Where: Vendor (Self Certification) - NC,USA
Cpu Name: AMD64 and Intel(R) EM64T
Created On: 2004-09-10 17:41:52-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-15 15:42:36-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: nVidia NVS280
nVidia FX500
nVidia FX1100
nVidia FX3000
<p>NOTE: Testing performed using nv or vesa driver.
See knowledgebase for information on nVidia driver support.
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-09-10 17:50:06-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: SAMSUNG CDRW/DVD SM-352F
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-10 17:50:11-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: 1-2 AMD Opteron 1.8+GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-10 17:50:30-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5718

Detail Notes: AMD 8111 AC97 Audio (rev 03)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-09-10 17:51:26-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: AMD AMD-8111 IDE

LSI 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI

Adaptec AIC-8902 U320 OEM SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-10 17:53:50-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: Chipset: [AMD] AMD-8111 PCI (rev 07)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-10 17:57:39-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: Upto 8GB

Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-09-10 18:03:03-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: Intel Corp. 82545EM Gigabit Ethernet Controller (Copper) (rev 01)

Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-09-10 18:03:12-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5718
Detail Notes: SEAGATE Model: ST373307LW SCSI (Qty: Up to 2)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None

Modified On: 2004-09-15 15:41:21-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [1067](#)³³ How does Red Hat Global Support Services handle non-Red Hat software, drivers, and uncertified hardware/hypervisors?

2.15.21. Sun Microsystems W1100z/W2100z Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148525>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2004-09-15 15:42:26-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5719

Detail Notes: nVidia NVS280

nVidia FX500

nVidia FX1100

nVidia FX3000

<p>

NOTE: Testing performed using nv or vesa driver.
See knowledgebase for information on nVidia driver support.

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-09-10 18:00:01-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: SAMSUNG CDRW/DVD SM-352F
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-09-10 18:00:01-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: 1-2 AMD Opteron 1.8+GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-09-10 18:00:01-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: AMD 8111 AC97 Audio (rev 03)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-09-10 18:00:01-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: AMD AMD-8111 IDE

LSI 53c1030 PCI-X Fusion-MPT Dual Ultra320 SCSI

Adaptec AIC-8902 U320 OEM SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-10 18:00:02-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: Chipset: [AMD] AMD-8111 PCI (rev 07)
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-09-10 18:00:02-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5719
Detail Notes: Upto 8GB

Component Class: Memory
Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-09-10 18:02:35-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5719

Detail Notes: Intel Corp. 82545EM Gigabit Ethernet Controller (Copper) (rev 01)
Broadcom Corporation NetXtreme BCM5703 Gigabit Ethernet (rev 02)

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-09-10 18:03:24-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5719

Detail Notes: SEAGATE Model: ST373307LW SCSI (Qty: Up to 2)

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-09-15 15:41:54-04

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [1067³⁴](#) How does Red Hat Global Support Services handle non-Red Hat software, drivers, and uncertified hardware/hypervisors?

2.15.22. Ultra 20 M2 Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=200902>

Summary

- *Version:* Update 8
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7741](#)³⁵ How do I get audio working on Red Hat Enterprise Linux 3 Update 8 on the Sun Ultra 20 M2?

2.15.23. Ultra 20 Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=164261>

Summary

- *Version:* Update 5
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.15.24. Ultra 40 M2 Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=216189>

Summary

- *Version:* Update 8
- *Category:* Desktop/Workstation
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7738](#)³⁶ How do I get audio working with Red Hat Enterprise Linux 3 Update 8 on the Sun Ultra 40 M2?

2.15.25. Ultra 40 Workstation Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=173340>

Summary

- *Version:* Update 7
- *Category:* Desktop/Workstation
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.16. Thales Computers

2.16.1. PENTXM PENTXM Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179552>

Summary

- *Version:* Update 6
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17. Unisys

2.17.1. Unisys ES3000 - 3020 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148630>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-07 12:04:02-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5858
Detail Notes: 24X IDE CD-ROM

8X DVD-ROM

24X IDE CD-RW/DVD ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-03 14:59:10-05

Detail 2:
Status: Compatible
Hardware Id: 5858
Detail Notes: 256MB - 12GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-03 14:59:10-05

Detail 3:
Status: Compatible
Hardware Id: 5858
Detail Notes: ATI Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-03 14:59:10-05

Detail 4:

Status: Compatible
Hardware Id: 5858
Detail Notes: Standard 1.44
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-11-03 14:59:10-05

Detail 5:
Status: Compatible
Hardware Id: 5858
Detail Notes: Primary: SCSI/RAID LSI Logic 1020/PERC4DI

Secondary: SCSI/RAID LSI Logic PERC4 SC/DC
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-03 14:59:10-05

Detail 6:
Status: Compatible
Hardware Id: 5858
Detail Notes: 1-2 Intel XEON CPUs

2.4-3.0GHz/512Kb 533 FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-03 14:59:10-05

Detail 7:
Status: Compatible
Hardware Id: 5858
Detail Notes: 6 SCSI Drives Maximum

18GB/36GB/72GB/146GB each
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-11-03 14:59:10-05

Detail 8:
Status: Compatible
Hardware Id: 5858
Detail Notes: Intel PRO 82544GC Gigabit EN

Optional:

2-4 (ports) Intel 100 Ethernet

1-4 (ports) Intel Pro 1000MT Ethernet

1-4 (ports) Intel Pro 1000MT Copper GB Ethernet

1-4 (ports) Intel 1000MF Fiber GB Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-03 14:59:10-05

Additional Certification Notes

No additional certification notes provided

2.17.2. Unisys ES3000 - 3020L Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148631>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-07 12:04:07-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5859
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-03 15:00:05-05

Detail 2:
Status: Compatible
Hardware Id: 5859
Detail Notes: 24X IDE CD-ROM

8X DVD-ROM

24X IDE CD-RW/DVD ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-11-03 15:00:05-05

Detail 3:
Status: Compatible
Hardware Id: 5859
Detail Notes: Primary: LSI PERC3/Di

Secondary: LSI PERC4 SC/DC

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-03 15:00:05-05

Detail 4:
Status: Compatible
Hardware Id: 5859
Detail Notes: 1.44 Mb
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-11-03 15:00:05-05

Detail 5:
Status: Compatible
Hardware Id: 5859
Detail Notes: 256MB - 12GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-11-03 15:00:05-05

Detail 6:
Status: Compatible
Hardware Id: 5859
Detail Notes: 1-2 Intel XEON CPUs

2.4-3.2GHz 533 FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-11-03 15:00:05-05

Detail 7:
Status: Compatible
Hardware Id: 5859
Detail Notes: 2 Maximum

- Broadcom 5703 GB EN

- Intel Pro 100+ Dual Port NIC

- Intel 1000MT Dual Port GB NIC

- Broadcom NetXtreme BCM5701 10/100/1000 Copper Ethernet
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-03 15:00:06-05

Additional Certification Notes

No additional certification notes provided

2.17.3. Unisys ES3000 - 3040 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148632>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-07 12:04:12-05

Detail Data:

Detail 1:
Status: Compatible
Hardware Id: 5860
Detail Notes: BROADCOM Corporation NetXtreme BCM5700 Gigabit Ethernet (rev 14)

Qty: 2
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-03 15:00:47-05

Detail 2:
Status: Compatible
Hardware Id: 5860
Detail Notes: ATI Technologies Inc Rage XL (rev 27)
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-11-03 15:00:47-05

Detail 3:
Status: Compatible
Hardware Id: 5860
Detail Notes: 12x24 Slim CD-ROM

8X DVD ROM

24X IDE CR-RW/DVD ROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None

Modified On: 2004-11-03 15:00:47-05

Detail 4:

Status: Compatible

Hardware Id: 5860

Detail Notes: Primary: SCSI/RAID LSI PERC3 QC

Secondary: SCSI/RAID LSI PERC4 SC/DC

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-11-03 15:00:47-05

Detail 5:

Status: Compatible

Hardware Id: 5860

Detail Notes: 1-4 Intel(R) 1.5-2.8GHz

400 MHz FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-11-03 15:00:47-05

Detail 6:

Status: Compatible

Hardware Id: 5860

Detail Notes: Maximum 8 drives:

18GB/36GB/72GB/146GB drives

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-11-03 15:00:47-05

Detail 7:

Status: Compatible

Hardware Id: 5860

Detail Notes: 1.44 MB

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-11-03 15:00:47-05

Detail 8:

Status: Compatible

Hardware Id: 5860

Detail Notes: 512MB - 32GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-11-03 15:00:47-05

Detail 9:

Status: Compatible

Hardware Id: 5860

Detail Notes: Dual Broadcom 570x GB

1-2 Broadcom NetXtreme 10/100/1000 MB

2-4 Intel 10/100 MB

1-4 Intel 1000MT Copper GB

2-3 Intel 1000MF Fiber GB
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-03 15:00:47-05

Additional Certification Notes

No additional certification notes provided

2.17.4. Unisys ES3000 - 3040L Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148633>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-12-07 12:04:17-05

Detail Data:

Detail 1:

Status: Compatible
Hardware Id: 5861
Detail Notes: Primary: SCSI LSI PERC3 DC

Secondary: SCSI RAID LSI PERC4 SC/DC
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-11-03 15:01:32-05

Detail 2:

Status: Compatible
Hardware Id: 5861
Detail Notes: 1-4 Intel(R) Xeon CPUs

2.0 - 3.0GHz with 400MHz FSB

Component Class: CPU
Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-11-03 15:01:32-05

Detail 3:

Status: Compatible

Hardware Id: 5861

Detail Notes: Maximum 5 SCSI Drives:
18GB/36GB/73GB/146GB each

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-11-03 15:01:32-05

Detail 4:

Status: Compatible

Hardware Id: 5861

Detail Notes: 1.44 Mb

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-11-03 15:01:32-05

Detail 5:

Status: Compatible

Hardware Id: 5861

Detail Notes: 512MB - 32GB

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-11-03 15:01:32-05

Detail 6:

Status: Compatible

Hardware Id: 5861

Detail Notes: ATI Technologies Inc Rage XL (rev 27)

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-11-03 15:01:33-05

Detail 7:

Status: Compatible

Hardware Id: 5861

Detail Notes: 24X IDE CD-ROM

8X IDE DVD ROM

24X IDE CD-RW/DVD ROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-11-03 15:01:33-05

Detail 8:

Status: Compatible

```
Hardware Id: 5861
Detail Notes: Dual Onboard Broadcom 5701<br>
Options:<br>
1-2 Intel Pro 100+ Dual Port <br>
1-2 Broadcom 5703 10/100/1000 Copper GB Ethernet<br>
1-4 (ports) Intel Pro 1000MT Copper GB Ethernet<br>
1-4 (ports) Intel Pro 1000MF Fiber GB Ethernet<br>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-11-03 15:01:33-05
```

Additional Certification Notes

No additional certification notes provided

2.17.5. Unisys ES3105 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179854>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17.6. Unisys ES3120 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179856>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* All

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17.7. Unisys ES3120L Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179857>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17.8. Unisys ES3140 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179858>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17.9. Unisys ES3140L Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179859>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

2.17.10. Unisys ES7000/410, 420 and 430 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148276>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Cpu Name: Intel(R) IPF
Last Touched On: 2004-03-12 18:32:43-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347

Detail Notes: Intel 1.3GHz or 1.5GHz Itanium 2;

Minimum 8, Maximum 16 per domain (Multiples of 4)

4 CPUs per processor module; Up to 4 processor modules per domain

RHEL3 only support 8 CPUs per partition (two partitions per domain)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-12 18:21:07-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: Intel Corp. 82544EI Gigabit Ethernet Controller (Copper) (rev 02)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-03-12 18:10:31-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: See CD-ROM DRIVE entry
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-03-12 18:10:16-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: Slim-line floppy/CD-RW combo drive
 floppy = Panasonic Industrial LKM-FH34-5,
LS-240
 CD-RW = Teac CD-W216E-93, ATAPI CD-RW SLIM LINE (16X/10X/24X)
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-03-11 14:05:51-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: Each processor module supports a minimum of 4GB and a maximum of 32GB per
processor module (128GB per domain)

RHEL3 only supports 32GB per partition (two partitions per domain).
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-03-12 18:20:03-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: PCIAM - 33/66/100MHZ PCI-X with two buses and four slots (MOD3000-PCI)

Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-03-11 14:08:05-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5347
Detail Notes: PCIXAM - 133MHz PCI-X with two buses and two slots.
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-03-11 14:09:24-05

Additional Certification Notes

No additional certification notes provided

2.18. VME

2.18.1. VME SBC Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=179551>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: VME
Model: SBC
Vendor:
Category: Server
Kernel Version: kernel-2.4.21-37.EL

File Uploaded:
rhr2-VME-SBC-Taroon_Update_6_results-2.noarch.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/837ab0a22a76f90478fbfc0f3a04a947/rhr2-VME-SBC-Taroon_Update_6_results-2.noarch.rpm

Please note the following failures:

WARNING: Kickstart file not found for required tests check.

```
0  FAILED  USB
   PASSED  INFO
   PASSED  VIDEO
   PASSED  CORE2
   PASSED  STORAGE
   PASSED  MEMORY2
   FAILED  NETWORK
   FAILED  MEMORY
   FAILED  CORE
```

Additional Certification Notes

No additional certification notes provided

2.19. VMware

2.19.1. ESX Server 2.1 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148342>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-05-03 14:27:19-04
Returned On: mm-dd-yy
Last Touched On: 2004-05-03 14:55:53-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: VMware SVGA II

Note: color depth is limited by HOST display
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-06-18 17:43:32-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Determined by HOST machine
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-05-03 14:32:29-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Virtual Intel 82371AB/EB/MB (PIIX4) IDE
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-03 14:34:30-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Virtual BusLogic BT-946C SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-05-03 14:36:35-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: VMware Virtual SCSI Disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation **to** from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-05-03 14:37:35-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: VMware Virtual Floppy
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.

Component Notes: None
Modified On: 2004-05-03 14:38:45-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: 256MB-3.6GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-05-03 14:39:22-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Virtual Intel 440BX Chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-05-03 14:40:15-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Virtual AMD PCnet32 Lance
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-05-03 14:41:13-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: Determined by HOST
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-05-03 14:44:16-04

Detail 11:
Ease of Install: 4
Status: Compatible
Hardware Id: 5441
Detail Notes: VMware Virtual IDE CDRom Drive, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-05-03 14:55:45-04

Additional Certification Notes

No additional certification notes provided

2.19.2. GSX Server 3.0 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148399>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-18 17:43:00-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: 256MB-3.6GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-17 17:10:44-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: VMware Virtual Floppy
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-06-17 17:10:52-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: VMware SVGA II<p>

Note: color depth is limited by HOST display
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-06-17 23:52:00-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Virtual Intel 440BX Chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-06-17 17:11:01-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Virtual AMD PCnet32 Lance
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-17 17:11:14-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Virtual Creative Labs Sound Blaster AudioPCI
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-06-17 17:17:56-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: VMware Virtual IDE CDROM Drive, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-06-17 17:19:03-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Determined by HOST machine

NOTE: RHEL3 Update 2 or later is required on host machine.
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-17 23:52:47-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Virtual Intel 82371AB/EB/MB (PIIX4) IDE
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-17 17:07:30-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Determined by HOST
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-06-17 17:11:24-04

Detail 11:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: Virtual BusLogic BT-946C SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-17 17:07:40-04

Detail 12:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: VMware Virtual SCSI Disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-17 17:10:23-04

Detail 13:

Ease of Install: 4
Status: Compatible
Hardware Id: 5546
Detail Notes: VMware Virtual IDE Disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-17 17:16:00-04

Additional Certification Notes

No additional certification notes provided

2.19.3. Workstation 4.5 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148400>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-06-18 17:42:49-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: 256MB-3.6GB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: VMware Virtual Floppy
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Virtual Intel 440BX Chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-06-17 17:19:12-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Virtual AMD PCnet32 Lance
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-17 17:19:12-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Virtual Creative Labs Sound Blaster AudioPCI
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: VMware Virtual IDE CDROM Drive, ATAPI CD/DVD-ROM drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Virtual Intel 82371AB/EB/MB (PIIX4) IDE
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-17 17:19:12-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Determined by HOST
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Virtual BusLogic BT-946C SCSI
Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-17 17:19:12-04

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: VMware Virtual SCSI Disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 11:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: VMware Virtual IDE Disk
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-17 17:19:12-04

Detail 12:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: VMware SVGA II

Note: color depth is limited by HOST display
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-06-17 23:56:45-04

Detail 13:

Ease of Install: 4
Status: Compatible
Hardware Id: 5547
Detail Notes: Determined by HOST machine

NOTE: RHEL3 Update 2 or later is required on host machine.
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-17 23:57:34-04

Additional Certification Notes

No additional certification notes provided

2.20. Wipro Limited

2.20.1. Wipro Limited NetPower 10120 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148574>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* All

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: Intel(R) IPF
Created On: 2004-10-19 01:22:05-04
Returned On: mm-dd-yy
Last Touched On: 2004-10-19 01:32:48-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: 8MB ATI Rage XL SVGA PCI
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-19 01:22:38-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: 24x SLIM TEAC CDRom Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-19 01:23:40-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: LSI Logic SCSI Controller/ Dual-Channel Ultra320 SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-19 01:25:07-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: Dual Intel Itanium processors 1.40GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-19 01:26:25-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: 36 GB Maxtor U320 HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-19 01:27:37-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: 4 GB DDR200 registered ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-19 01:28:57-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: Super I2DML-8G2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-10-19 01:30:41-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5784
Detail Notes: Intel(R) 82546EB Dual Port Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-10-19 01:32:03-04

Additional Certification Notes

No additional certification notes provided

2.20.2. Wipro Limited Netpower 1115 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148240>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-01-23 04:11:27-05

Returned On: mm-dd-yy

Last Touched On: 2004-01-23 05:53:51-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5298

Detail Notes: Integrated ATI RAGE* XL SVGA PCI video controller

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-01-23 04:48:16-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5298

Detail Notes: 52X Lite-on CDROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-01-23 04:51:24-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: P4 2.4 Ghz 533FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-01-23 04:55:54-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: Aopen 3202 Dual Channel SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-01-23 04:57:52-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: 36 GB Seagate U320 HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-01-23 05:01:25-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: 1.44 MB Mitsumi
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-01-23 05:05:07-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: 512 MB
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-01-23 05:36:11-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: Intel S875WP1-E
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-01-23 05:44:02-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5298
Detail Notes: </P>Intel PRO/100 connection</P>
<P>Intel PRO/1000 connection</P>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-01-23 05:52:46-05

Additional Certification Notes

No additional certification notes provided

2.20.3. Wipro Limited NetPower 1120 Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148388>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-06-04 09:03:08-04
Returned On: mm-dd-yy
Last Touched On: 2004-06-04 09:23:48-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: Super Micro P4SC8
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-06-04 09:20:16-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: UP to Intel P4 3.4GHz , 800FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-06-04 09:04:31-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: <p>Dual Onboard Intel Gigabit Ethernet Controllers </p><p> Intel 82547GI and Intel 825451</p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-06-04 09:23:00-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: <p>Adaptec 7902 Dual Channel Ultra 320 SCSI</p><p>2 x UDMA ATA 100/66 Bus Master IDE</p><p>2 x SATA Intel 6300ESB Controller </p>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-06-04 09:05:43-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: Seagate 36GB, U320 HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-06-04 09:06:40-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: Integrated ATI Rage XL video controller

Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-06-04 09:03:24-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: Mitsumi 1.44MB FDD
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-06-04 09:07:11-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: Lite-on 52X CDROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-06-04 09:03:51-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5528
Detail Notes: 1024MB DDR 400
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-06-04 09:07:47-04

Additional Certification Notes

No additional certification notes provided

2.20.4. Wipro Limited Netpower 7225Z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148241>

Summary

- *Version:* 3

- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-01-23 05:59:17-05

Returned On: mm-dd-yy

Last Touched On: 2004-01-23 06:16:21-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Integrated ATI Rage XL

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-01-23 06:00:41-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: 52X Lite-on CDR0M

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-01-23 06:02:48-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Intel P4 2.4Ghz 533 FSB X 2

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-01-23 06:04:25-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Ultra 320 SCSI Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-01-23 06:07:29-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Seagate 4*36GB HDD

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-01-23 06:09:39-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Mitsumi 1.44 MB Mini Floppy Disk Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-01-23 06:11:46-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: DDR 2GB ECC RAM

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-01-23 06:13:00-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: Intel SE7501HG2

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed separately.

Modified On: 2004-01-23 06:14:08-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5299

Detail Notes: </P>Intel PRO/100 connection</P>

</P>Intel PRO/1000 connection</P>

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-01-23 06:15:50-05

Additional Certification Notes

No additional certification notes provided

2.20.5. Wipro Limited Netpower 7226N2UCR Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=166561>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

```
+++ This bug was initially created as a clone of Bug #153706 +++
```

Additional Data:

Cpu Name: X86

Last Touched On: 2005-02-03 06:20:05-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6073

Detail Notes: ATI Rage XL 8MB Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-02-03 06:16:43-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6073

Detail Notes: Teac CD-224E CD-ROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-02-03 06:16:59-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6073

Detail Notes: Adaptec AIC-7902 Dual Channel Ultra320 SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-03 06:18:08-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Dual Intel Xeon Processors 3.4Ghz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 06:18:22-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Seagate 36GB SCSI HS Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 06:18:35-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: 1.44 MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 06:18:53-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: 2GB DDRII 400 REG W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 06:19:18-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: SuperMicro X6DH8-G2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-03 06:19:30-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Intel 82546GB Dual Port Gigabit Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 06:19:46-05

Additional Certification Notes

No additional certification notes provided

2.20.6. Wipro Limited NetPower 7226W Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148575>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-10-19 01:38:20-04
Returned On: mm-dd-yy
Last Touched On: 2004-10-19 03:03:35-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Addon - MX4000 64MB DDR with TV out
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-10-19 01:39:22-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Lite-on 52X CDRom
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-10-19 01:41:37-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Integrated Intel E82875P & Hance Rapid controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-10-19 01:43:26-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Dual Intel Xeon? Processors 3.0Ghz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-10-19 01:43:59-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: ADI AD1980 AC?97 audio CODEC (On-board)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-10-19 01:44:48-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: 80GB, 7200RPM HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-10-19 01:48:23-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: 1.44 MB Mitsumi
Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-10-19 01:50:12-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: DDR 1536 MB reg W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-10-19 01:53:17-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Asus NCCH-DL
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-10-19 02:24:01-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5785
Detail Notes: Intel(R) 82547GI CSA Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-10-19 03:03:08-04

Additional Certification Notes

No additional certification notes provided

2.20.7. Wipro Limited NetPower 7226WS Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153705>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-03 06:15:35-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Integrated ATI Rage XL SVGA PCI video controller
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-03 06:12:45-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Lite-on 52X CDROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-03 06:12:53-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Integrated Intel E7320 chipset & PC87427 controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-03 06:13:08-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Dual Intel Xeon? Processors 3.4Ghz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 06:13:29-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: 80GB SATA Hard disk drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.

Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 06:13:42-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Mitsumi 1.44 MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 06:13:54-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: 2GB DDR 333 REG W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 06:14:49-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Intel SE7320SP2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-03 06:15:02-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6072
Detail Notes: Integrated Intel 82541GB Gigabit Server controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 06:15:16-05

Additional Certification Notes

No additional certification notes provided

2.20.8. Wipro Limited NetPower 7226Z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148678>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-06 07:41:53-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-06 07:47:19-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Integrated ATI Rage XL

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-12-06 07:42:11-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Lite-on 52X CDRom

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-06 07:42:32-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Intel 82801ER & LSI 53C1030

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-06 07:43:02-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Dual Intel Xeon Processors 3.0GHz

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-06 07:43:39-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Seagate hard disk 36GB

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-06 07:44:10-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Mitsumi 1.44 MB Floppy Disk Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-06 07:45:12-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: 1024 MB DDR Registered W/ECC

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-06 07:45:59-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Intel SE7520BD2

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-12-06 07:46:28-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5944

Detail Notes: Intel(R) 82541PI And Marvell Yukon 88E8050 Gigabit Ethernet Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-06 07:47:02-05

Additional Certification Notes

No additional certification notes provided

2.20.9. Wipro Limited Netpower 7226ZVR Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153706>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-03 06:20:05-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: ATI Rage XL 8MB Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-03 06:16:43-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Teac CD-224E CD-ROM Drive

Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-03 06:16:59-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Adaptec AIC-7902 Dual Channel Ultra320 SCSI
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2005-02-03 06:18:08-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Dual Intel Xeon Processors 3.4Ghz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 06:18:22-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Seagate 36GB SCSI HS Hard Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 06:18:35-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: 1.44 MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 06:18:53-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: 2GB DDRII 400 REG W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 06:19:18-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: SuperMicro X6DH8-G2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-03 06:19:30-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 6073
Detail Notes: Intel 82546GB Dual Port Gigabit Controller
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 06:19:46-05

Additional Certification Notes

No additional certification notes provided

2.20.10. Wipro Limited NetPower 9420Z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148434>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-15 00:54:21-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-15 01:12:27-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: Integrated Ati Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 00:54:35-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: Intel Xeon 2.0GHz X 4
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-15 00:55:25-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: 36 GB Maxtor U320 HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-15 00:56:31-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: Lite-on 52X CDROM
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 00:54:59-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: Integrated Adaptec AIC 7902W
Server works GC-HE
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 00:55:50-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602

Detail Notes: 1.44 MB Mitsumi
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-15 00:56:59-04

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: DDR 1024 MB reg W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-15 00:58:08-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: Intel SRSH4
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 00:58:36-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5602
Detail Notes: <p>Intel 82550PM Integrated 10/100 Lan</p>
<p>Intel 82544GC Integrated GigaBit Lan</p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 00:59:29-04

Additional Certification Notes

No additional certification notes provided

2.20.11. Wipro Limited NetPower 9425Z Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148435>

Summary

- *Version:* 3
- *Category:* Server

- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-07-15 01:01:19-04
Returned On: mm-dd-yy
Last Touched On: 2004-07-15 01:11:23-04

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: Integrated Ati Rage XL
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-07-15 01:01:33-04

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: Lite-on 52X CDR0M
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-07-15 01:01:59-04

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: Intel Xeon 2.0GHz X 4
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-07-15 01:03:12-04

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: Integrated Adaptec AIC 7902W Server works GC-HE
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-07-15 01:04:41-04

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: 36 GB Maxtor U320 HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-15 01:05:30-04

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: 1.44 MB Mitsumi
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-07-15 01:06:10-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: DDR 1024 MB reg W/ECC
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-07-15 01:07:53-04

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: Intel SRSH4
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-07-15 01:09:59-04

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5603
Detail Notes: <P>Intel 82550PM Integrated 10/100 Lan</P>
<P>Intel 82544GC Integrated GigaBit Lan</P>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-07-15 01:11:03-04

Additional Certification Notes

No additional certification notes provided

2.20.12. Wipro Limited Wipro iValue 1400XP Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148698>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-14 04:11:46-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-14 04:22:41-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: Integrated S3 Graphics UniChrome 2D/3D Graphics

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-12-14 04:12:00-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: LITE-ON (LTN526) 52X CDROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-14 04:16:32-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: IDE HDD interface with ATA-100/66/33

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-12-14 04:17:12-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: AMD Athlon XP 2000+

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-12-14 04:18:30-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: AC'97 link controller integrated in VIA VT8235

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-12-14 04:19:06-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: Seagate Barracuda 80GB Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-14 04:19:49-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: Mitsumi D359M3D

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-14 04:20:23-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5979

Detail Notes: DDR 256 MB PC2100 (DDR266)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-14 04:20:53-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 5979
Detail Notes: MSI MS-6734
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-14 04:21:52-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 5979
Detail Notes: Integrated VIA VT6103 10/100 Ethernet LAN
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-14 04:22:32-05

Additional Certification Notes

No additional certification notes provided

2.20.13. Wipro Limited Wipro iValue 1800XP Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148722>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-12-28 01:06:29-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-28 01:19:07-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: Integrated Graphics shared memory
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-28 01:07:06-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: LITE-ON (LTN526) 52X CDROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-28 01:07:42-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: IDE HDD interface with ATA-100/66/33
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-28 01:09:11-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: AMD Athlon 3200+ CPU
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-28 01:09:59-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: AC'97 link controller integrated in VIA
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-12-28 01:12:18-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: Seagate 40GB Disk Drive
Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-28 01:13:13-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: Mitsumi 1.44MB floppy disk drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-28 01:14:16-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: DDR 512MB PC2700 (DDR333)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-28 01:15:18-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: MSI MS-6741
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-28 01:16:20-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6006
Detail Notes: Integrated VIA VT6103 10/100 Ethernet LAN
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-28 01:17:40-05

Additional Certification Notes

No additional certification notes provided

2.20.14. Wipro Limited Wipro iValue 403 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157610>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 3.4GHz HT, 478 socket

MEMORY : DDR 256 MB PC2700 (DDR333)

Video Adapter : Intel Integrated extreme graphics II

CDROM Drive : LITE-ON (LTN526) 52X CDROM Drive

Digital Audio Adapter : Onboard C-Media CMI9761A 6 channel audio

Fixed Hard Disk : Maxtor 80 GB SATA HDD

Note : Works with RHEL Update 3 onwards.

Controller Card : IDE interface with ATA-66/100 and SATA integrated by ICH5

Floppy Disk Drive : Mitsumi 1.44 MB FDD

Network Interface : Realtek 8101L onboard Lan controller

Motherboard : ECS 865GV-M

Additional Certification Notes

No additional certification notes provided

2.20.15. Wipro Limited Wipro iValue 4865GVA Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153707>

Summary

- *Version:* 3

- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2005-02-03 08:02:22-05

Returned On: mm-dd-yy

Last Touched On: 2005-02-03 08:27:31-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6082

Detail Notes: Integrated 3D /2D graphics on GMCH chipset with shared memory

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-02-03 08:14:41-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6082

Detail Notes: LITE-ON (LTN526) 52X CDROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-02-03 08:15:02-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6082

Detail Notes: IDE HDD interface with ATA-100/66/33

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-02-03 08:17:07-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6082

Detail Notes: Intel Pentium 4 3.4 GHZ

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-02-03 08:18:32-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: Onboard AC97 Audio
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-03 08:19:29-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: Seagate Barracuda 80 GB HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 08:20:23-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: Mitsumi 1.44 MB floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 08:22:26-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: 512MB DDR PC2700 (DDR333)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 08:24:20-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: Asrock P4i65GV
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-03 08:25:12-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 6082
Detail Notes: Intel Pro 100S Ethernet LAN adapter
Component Class: Network Interface

Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 08:27:07-05

Additional Certification Notes

No additional certification notes provided

2.20.16. Wipro Limited Wipro iValue 704 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157607>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 3.6GHZ, LGA 775
MEMORY : DDR 256 MB PC2700 (DDR333)
Video Adapter : Intel 915GV onboard graphics subsystem
CDROM Drive : LITE-ON (LTN526) 52X CDROM Drive
Digital Audio Adapter : Onboard Realtek ALC655 Audio
Fixed Hard Disk : Maxtor 80GB SATA HDD
Note : Works with RHEL Update 3 and above.
Controller Card : IDE interface with ATA-66/100 and SATA integrated by ICH6
Floppy Disk Drive : Mitsumi 1.44 MB FDD
Network Interface : Realtek 8110S gigabit on board Lan controller
Motherboard : Asus P5GV-TMX

Additional Certification Notes

No additional certification notes provided

2.20.17. Wipro Limited Wipro iValue 900.GX Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148498>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-08-19 01:31:19-04

Returned On: mm-dd-yy

Last Touched On: 2004-08-19 01:41:23-04

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: Intel(R) GMA900 onboard graphics subsystem

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-08-19 01:31:46-04

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: LITE-ON (LTN526) 52X CDROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-08-19 01:32:51-04

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: IDE HDD interface with UDMA 33, ATA-66/100 and support for SATA

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-08-19 01:33:37-04

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: LGA775 Intel Pentium 4 Processor (3.60Ghz)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-08-19 01:34:27-04

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: Intel(R) High Definition Audio subsystem with 6 channels (onboard)

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-08-19 01:35:15-04

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: Seagate ST380011A (80GB 7200RPM)

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-08-19 01:35:56-04

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: Mitsumi 1.44 Floppy Disk Drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-08-19 01:37:10-04

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682

Detail Notes: 512MB DDR PC3200 (DDR400) X 2

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-08-19 01:37:52-04

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5682
Detail Notes: Intel D915GAG
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-08-19 01:39:13-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5682
Detail Notes: Intel 82562EZ 10/100Mbps (Onboard)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-19 01:40:19-04

Additional Certification Notes

No additional certification notes provided

2.20.18. Wipro Limited Wipro iValue 901 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157604>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : AMD Athlon 64 3000+ socket 939
MEMORY : 256MB DDR PC2700 (DDR333)
Video Adapter : AGP MSI MX-4000 T64 64MB
CDROM Drive : LITE-ON (LTN526) 52X CDROM Drive
Digital Audio Adapter : Onboard AC 97 Audio
Fixed Hard Disk : Maxtor 80GB SATA HDD
NOTE : Requires RHEL3 - Update 3 and above
Controller Card : IDE with ATA-100/66/133 & SATA/150 integrated by VT8237 controller

Floppy Disk Drive : Mitsumi 1.44 MB floppy drive
Network Interface : Realtek 8110S Gigabit Onboard Lan Controller
Motherboard : MSI MS6702E

Additional Certification Notes

No additional certification notes provided

2.20.19. Wipro Limited Wipro ivalue WIV 4865.rh Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148293>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-03-17 07:54:27-05
Returned On: mm-dd-yy
Last Touched On: 2004-03-17 08:05:58-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: Onboard Intel(R) Extreme Graphics 2 Controller
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-03-17 07:54:58-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5366

Detail Notes: Lite-on LTN526 52X CDR0M
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-03-17 07:55:40-05

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: Intel P4 2.40GHz 800FSB
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-03-17 07:56:35-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: <P>2 x UDMA ATA 100/66 Bus Master IDE <P>
<P>2 x SATA 150 Controller <P>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-03-17 07:58:18-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: <P>SoundMAX 4 XL with AudioESP audio subsystem<P>
<P>using the Analog Devices AD1985 codec<P>
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-03-17 08:00:48-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: Seagate ST340014A , 40GB IDE HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-03-17 08:01:38-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5366
Detail Notes: Mitsumi 1.44MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-03-17 08:02:57-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5366

Detail Notes: 512MB DDR 400

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-03-17 08:03:55-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5366

Detail Notes: Intel DSG856GRH

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-03-17 08:04:42-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5366

Detail Notes: Onboard Intel 825457EI Gigabit Ethernet Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-03-17 08:05:33-05

Additional Certification Notes

No additional certification notes provided

2.20.20. Wipro Limited Wipro Super Genius WSG800.rh Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148294>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-03-17 08:07:37-05

Returned On: mm-dd-yy

Last Touched On: 2004-03-17 08:16:36-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Onboard Intel(R) Extreme Graphics 2 Controller

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-03-17 08:07:56-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Lite-on LTN526 52X CDROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-03-17 08:08:51-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Intel P4 2.40 GHZ 800FSB

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-03-17 08:09:26-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: <P>2 x UDMA ATA 100/66 Bus Master IDE <P>

<P>2 x SATA 150 Controller <P>

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-03-17 08:10:36-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: <P>SoundMAX 4 XL with AudioESP audio subsystem<P>
<P>using the Analog Devices AD1985 codec<P>

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-03-17 08:11:50-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Seagate ST340014A , 40GB IDE HDD

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-03-17 08:12:34-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Mitsumi 1.44MB FDD

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-03-17 08:13:21-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: 512MB DDR 400

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-03-17 08:14:16-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Intel DSG856GRH

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-03-17 08:15:02-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 5367

Detail Notes: Onboard Intel 825457EI Gigabit Ethernet Controller

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-03-17 08:16:01-05

Additional Certification Notes

No additional certification notes provided

2.20.21. Wipro Limited Wipro SuperGenius 1400XP Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148697>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-12-14 04:02:42-05

Returned On: mm-dd-yy

Last Touched On: 2004-12-14 04:10:19-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5976

Detail Notes: LITE-ON (LTN526) 52X CDROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-12-14 04:04:04-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5976

Detail Notes: IDE HDD interface with ATA-100/66/33

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-14 04:06:05-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: Integrated S3 Graphics UniChrome 2D/3D Graphics
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-14 04:06:37-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: AMD Athlon XP 2000+
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-14 04:06:47-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: AC'97 link controller integrated in VIA VT8235
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-12-14 04:07:21-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: Seagate Barracuda 80GB Disk Drive
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-14 04:07:54-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: Mitsumi D359M3D
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-14 04:08:20-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: DDR 256 MB PC2100 (DDR266)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-14 04:08:57-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: MSI MS-6734
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-14 04:09:25-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5976
Detail Notes: Integrated VIA VT6103 10/100 Ethernet LAN
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-14 04:09:59-05

Additional Certification Notes

No additional certification notes provided

2.20.22. Wipro Limited Wipro SuperGenius 1800XP Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148721>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-12-28 00:26:35-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-28 01:03:12-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6003
Detail Notes: Integrated Graphics shared memory
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-28 00:27:25-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6003
Detail Notes: LITE-ON (LTN526) 52X CDROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-28 00:31:39-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6003
Detail Notes: IDE HDD interface with ATA-100/66/33
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-28 00:52:09-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6003
Detail Notes: AMD Athlon 3200+ CPU
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-28 00:52:54-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6003
Detail Notes: AC'97 link controller integrated in VIA
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2004-12-28 00:53:40-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6003

Detail Notes: Seagate 40GB Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2004-12-28 00:55:01-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6003

Detail Notes: Mitsumi 1.44MB floppy disk drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2004-12-28 00:57:23-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6003

Detail Notes: DDR 512MB PC2700 (DDR333)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-12-28 00:58:39-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 6003

Detail Notes: MSI MS-6741

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-12-28 01:00:25-05

Detail 10:

Ease of Install: 4

Status: Compatible

Hardware Id: 6003

Detail Notes: Integrated VIA VT6103 10/100 Ethernet LAN

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Modified On: 2004-12-28 01:01:32-05

Additional Certification Notes

No additional certification notes provided

2.20.23. Wipro Limited Wipro SuperGenius 302 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153709>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86

Last Touched On: 2005-02-04 05:40:56-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: Intel Corp. 82865G Integrated Graphics Device

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2005-02-04 05:15:50-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: LITE-ON 52X CDROM Drive

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2005-02-04 05:16:07-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: IDE HDD interface with ATA-100/66/33

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-02-04 05:16:26-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: LGA775 Intel Pentium 4 Processor

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2005-02-04 05:18:09-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: ADI AD1888 CODEC

Component Class: Digital Audio Adapter

Component Test: Must pass the rhr-core tests.

Must pass the rhr-audio tests.

Component Notes: None

Modified On: 2005-02-04 05:18:52-05

Detail 6:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: Samsung 40GB Disk Drive

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.

Must pass the rhr-fdisk test.

Component Notes: None

Modified On: 2005-02-04 05:19:22-05

Detail 7:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: Mitsumi:D359M3D 1.44 MB floppy drive

Component Class: Floppy Disk Drive

Component Test: Must be bootable and start the installation program.

Must pass the rhr-core tests.

Must pass the rhr-floppy test.

Component Notes: None

Modified On: 2005-02-04 05:20:11-05

Detail 8:

Ease of Install: 4

Status: Compatible

Hardware Id: 6085

Detail Notes: DDR 512 MB PC2700 (DDR333)

Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2005-02-04 05:21:37-05

Detail 9:

Ease of Install: 4

Status: Compatible
Hardware Id: 6085
Detail Notes: GA-81865GM-775
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-04 05:21:57-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 6085
Detail Notes: Intel EtherExpress PRO/100 S Desktop Adapter
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-04 05:22:08-05

Additional Certification Notes

No additional certification notes provided

2.20.24. Wipro Limited Wipro SuperGenius 403 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157608>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 3.4GHZ HT, 478 socket
MEMORY : DDR 256 MB PC2700 (DDR333)
Video Adapter : Intel Integrated extreme graphics II
CDROM Drive : LITE-ON (LTN526) 52X CDRom Drive
Digital Audio Adapter : Onboard C-Media CMI9761A 6 channel audio
Fixed Hard Disk : Maxtor 80 GB SATA HDD
Note : Works with RHEL Update 3 onwards.

Controller Card : IDE interface with ATA-66/100 and SATA integrated by ICH5
Floppy Disk Drive : Mitsumi 1.44 MB FDD
Network Interface : Realtek 8101L onboard Lan controller
Motherboard : ECS 865GV-M

Additional Certification Notes

No additional certification notes provided

2.20.25. Wipro Limited Wipro SuperGenius 704 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157606>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

CPU : Intel Pentium 4 3.6GHz, LGA 775
MEMORY : DDR 256 MB PC2700 (DDR333)
Video Adapter : Intel 915GV onboard graphics subsystem
CDROM Drive : LITE-ON (LTN526) 52X CDROM Drive
Digital Audio Adapter : Onboard Realtek ALC655 Audio
Fixed Hard Disk : Maxtor 80GB SATA HDD
Note : Works with RHEL Update 3 and above.
Controller Card : IDE interface with ATA-66/100 and SATA integrated by ICH6
Floppy Disk Drive : Mitsumi 1.44 MB FDD
Network Interface : Realtek 8110S gigabit on board Lan controller
Motherboard : Asus P5GV-TMX

Additional Certification Notes

No additional certification notes provided

2.20.26. Wipro Limited Wipro SuperGenius 800.VXA Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153708>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2005-02-03 08:32:36-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Integrated 3D /2D graphics on GMCH chipset with shared memory
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2005-02-03 08:28:39-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: LITE-ON (LTN526) 52X CDROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: IDE HDD interface with ATA-100/66/33
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.

Modified On: 2005-02-03 08:28:39-05

Detail 4:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Intel Pentium 4 3.4 GHz
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 5:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Onboard AC97 Audio
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 6:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Seagate Barracuda 80 GB HDD
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Mitsumi 1.44 MB floppy drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 8:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: 512MB DDR PC2700 (DDR333)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2005-02-03 08:28:39-05

Detail 9:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Asrock P4i65GV

Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2005-02-03 08:28:39-05

Detail 10:

Ease of Install: 4
Status: Compatible
Hardware Id: 6083
Detail Notes: Intel Pro 100S Ethernet LAN adapter
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2005-02-03 08:28:39-05

Additional Certification Notes

No additional certification notes provided

2.20.27. Wipro Limited Wipro SuperGenius 900.GX Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148499>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Cpu Name: X86
Last Touched On: 2004-08-19 01:44:24-04

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Intel(R) GMA900 onboard graphics subsystem
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-08-19 01:42:07-04

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: LITE-ON (LTN526) 52X CDROM Drive
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 3:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: IDE HDD interface with UDMA 33, ATA-66/100 and support for SATA
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-19 01:42:07-04

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: LGA775 Intel Pentium 4 Processor (3.60Ghz)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Intel(R) High Definition Audio subsystem with 6 channels (onboard)
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Seagate ST380011A (80GB 7200RPM)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 7:

Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Mitsumi 1.44 Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: 512MB DDR PC3200 (DDR400) X 2
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-08-19 01:42:07-04

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Intel D915GAG
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-08-19 01:42:07-04

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5683
Detail Notes: Intel 82562EZ 10/100Mbps (Onboard)
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-08-19 01:42:07-04

Additional Certification Notes

No additional certification notes provided

2.20.28. Wipro Limited Wipro SuperGenius 901 Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=157605>

Summary

- *Version: 3*

- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

```
CPU : AMD Athlon 64 3000+ socket 939
MEMORY : 256MB DDR PC2700 (DDR333)
Video Adapter : AGP MSI MX-4000 T64 64MB
CDROM Drive : LITE-ON (LTN526) 52X CDROM Drive
Digital Audio Adapter : Onboard AC 97 Audio
Fixed Hard Disk : Maxtor 80GB SATA HDD
NOTE : Requires RHEL3 - Update 3 and above
Controller Card : IDE with ATA-100/66/133 & SATA/150 integrated by VT8237 controller
Floppy Disk Drive : Mitsumi 1.44 MB floppy drive
Network Interface : Realtek 8110S Gigabit Onboard Lan Controller
Motherboard : MSI MS6702E
```

Additional Certification Notes

No additional certification notes provided

2.21. Zenith Computers Limited

2.21.1. Zenith Computers Limited Zenith Premium Net Server Server

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148292>

Summary

- *Version:* 3
- *Category:* Server
- *Platforms:* i386

Additional Comments

```
Additional Data:
```

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)

Cpu Name: X86

Created On: 2004-03-17 06:18:36-05

Returned On: mm-dd-yy

Last Touched On: 2004-03-17 07:14:49-05

Detail Data:

Detail 1:

Ease of Install: 4

Status: Compatible

Hardware Id: 5365

Detail Notes: Integrated ATI Rage XL SVGA PCI video controller with 8MB of video memory

Component Class: 2D Video Adapter

Component Test: Must complete an installation, either graphical or text.

Must pass the rhr-core tests.

Must pass the rhr-dd_x test @ each available color depth.

Component Notes: 24 bpp testing is not required if 32 bpp is available.

3D is not tested at this time.

Modified On: 2004-03-17 06:28:00-05

Detail 2:

Ease of Install: 4

Status: Compatible

Hardware Id: 5365

Detail Notes: Samsung : 52x EIDE CDROM

Component Class: CD-ROM Drive

Component Test: Must be available as an installation medium.

Must pass the rhr-core tests.

Must pass the rhr-cdromdata test.

Component Notes: None

Modified On: 2004-03-17 06:29:05-05

Detail 3:

Ease of Install: 4

Status: Compatible

Hardware Id: 5365

Detail Notes: <P>Intel Xeon Processor,2.4 GHZ with HT Technology<P>

<P>(Upgradeable to 3.2 GHZ)

Component Class: CPU

Component Test: Must pass the rhr-core tests.

Must identify properly in /proc/cpuinfo.

Component Notes: None

Modified On: 2004-03-17 06:31:22-05

Detail 4:

Ease of Install: 4

Status: Compatible

Hardware Id: 5365

Detail Notes: U 320 SCSI Adaptec AIC - 7901 Controller

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program.

Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-03-17 06:40:51-05

Detail 5:

Ease of Install: 4

Status: Compatible

Hardware Id: 5365

Detail Notes: 36GB 10000rpm U 320 SCSI HDD

Component Class: Fixed Disk Drive

Component Test: Must be post install bootable.

Must be available for installation to from the installation program.

Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-03-17 06:42:08-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5365
Detail Notes: 1.44MB Floppy Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-03-17 07:06:18-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5365
Detail Notes: 1GB Registered ECC DDR 266 SDRAM
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-03-17 07:09:08-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5365
Detail Notes: Intel SE 7501BR2
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-03-17 07:11:14-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5365
Detail Notes: <P>Intel PRO 10/100 Mbps (Intel 82550)<P>
<P>Intel PRO 10/100/1000 Mbps (Intel 82480)<P>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-03-17 07:13:29-05

Detail 10:
Ease of Install: 4
Status: Compatible
Hardware Id: 5365
Detail Notes: 460 Watts SSI Power Supply
Component Class: Power Supply
Component Test: Must Pass all tests attached hardware
Component Notes: Power Supplies are not tested outside of full systems.
Modified On: 2004-03-17 07:28:35-05

Additional Certification Notes

No additional certification notes provided

2.21.2. Zenith Computers Limited Zenith Premium PC Desktop/Workstation

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148244>

Summary

- *Version:* 3
- *Category:* Desktop/Workstation
- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Cpu Name: X86
Created On: 2004-01-28 06:42:46-05
Returned On: mm-dd-yy
Last Touched On: 2004-01-28 06:55:36-05

Detail Data:

Detail 1:

Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: Onboard Intel Extreme Graphics 2
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-01-28 06:43:31-05

Detail 2:

Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: Samsung : 52x EIDE
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-01-28 06:44:23-05

Detail 3:

Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: Intel P4 , 2.4 GHz (UPgradeable upto 3.2GHz)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-01-28 06:45:52-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: </P>2 port ATA-100 Enhanced IDE Controller</P> and
</P>2 port ATA-150 SATA Controller</P>
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-01-28 06:48:18-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: Onboard AC97 Compatible , 3D sound
Component Class: Digital Audio Adapter
Component Test: Must pass the rhr-core tests.
Must pass the rhr-audio tests.
Component Notes: None
Modified On: 2004-01-28 06:49:34-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: 40 GB 7200rpm UDMA ATA-100
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-01-28 06:50:44-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: 1.44MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-01-28 06:51:50-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5303
Detail Notes: 256 MB DDR 400 SDRAM
Component Class: Memory

Component Test: Must pass the rhr-core tests.

Component Notes: None

Modified On: 2004-01-28 06:53:02-05

Detail 9:

Ease of Install: 4

Status: Compatible

Hardware Id: 5303

Detail Notes: Intel D865GVHZ

Component Class: MotherBoard

Component Test: Must pass rhr-core tests

Component Notes: Any built in hardware must be listed seperately.

Modified On: 2004-01-28 06:54:16-05

Detail 10:

Ease of Install: 1

Status: Waiting for Authorization

Hardware Id: 5303

Detail Notes: Intel pro/100 LAN

Component Class: Network Interface

Component Test: Must complete a network install.

Must pass the rhr-core tests.

Must pass the rhr-net test.

Component Notes: PXE booting must operate properly, if available.

Additional Certification Notes

No additional certification notes provided

Red Hat Enterprise Linux 3 Certified Components

3.1. Acer Inc.

3.1.1. Acer Inc. Altos G700 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153641>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Where: Red Hat Europe (Guildford, Surrey, United Kingdom)
Created On: 2004-12-07 02:09:49-05
Returned On: mm-dd-yy
Last Touched On: 2004-12-07 02:16:01-05
Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: Ati Integrated with 8 MB SDRAM
Component Class: 2D Video Adapter
Component Test: Must complete an installation, either graphical or text.
Must pass the rhr-core tests.
Must pass the rhr-dd_x test @ each available color depth.
Component Notes: 24 bpp testing is not required if 32 bpp is available.
3D is not tested at this time.
Modified On: 2004-12-07 02:10:01-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: 52X ATAPI
Component Class: CD-ROM Drive
Component Test: Must be available as an installation medium.
Must pass the rhr-core tests.
Must pass the rhr-cdromdata test.
Component Notes: None
Modified On: 2004-12-07 02:10:23-05

Detail 3:
Ease of Install: 4
```

Status: Compatible
Hardware Id: 5945
Detail Notes: On Board Adaptec Dual Channel Ultra 320 SCSI Controller
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-12-07 02:10:47-05

Detail 4:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: Intel Xeon 2.8 Ghz (512 KB L2 cache)
Component Class: CPU
Component Test: Must pass the rhr-core tests.
Must identify properly in /proc/cpuinfo.
Component Notes: None
Modified On: 2004-12-07 02:11:26-05

Detail 5:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: 36GB Ultra320 SCSI 10K RPM Hot-Swap HDD (*6)
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-12-07 02:12:13-05

Detail 6:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: 1.44 MB Floppy Disk Drive
Component Class: Floppy Disk Drive
Component Test: Must be bootable and start the installation program.
Must pass the rhr-core tests.
Must pass the rhr-floppy test.
Component Notes: None
Modified On: 2004-12-07 02:13:15-05

Detail 7:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: PC2100 DDR SDRAM Registered ECC (1GB*4)
Component Class: Memory
Component Test: Must pass the rhr-core tests.
Component Notes: None
Modified On: 2004-12-07 02:13:41-05

Detail 8:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: Acer OEM Motherboard Serverworks GC-LE chipset
Component Class: MotherBoard
Component Test: Must pass rhr-core tests
Component Notes: Any built in hardware must be listed seperately.
Modified On: 2004-12-07 02:14:28-05

Detail 9:
Ease of Install: 4
Status: Compatible
Hardware Id: 5945
Detail Notes: <p> Broadcom Integrated Gigabit Ethernet </p>
<p> Intel 10/100/1000 Gigabit Ethernet </p>
Component Class: Network Interface
Component Test: Must complete a network install.
Must pass the rhr-core tests.
Must pass the rhr-net test.
Component Notes: PXE booting must operate properly, if available.
Modified On: 2004-12-07 02:15:45-05

Additional Certification Notes

No additional certification notes provided

3.1.2. Acer Inc. Altos S205F Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153648>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2005-01-30 06:11:47-05
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 6046
Detail Notes: Approved for Red Hat Cluster Suite

(High Availability Clustering)

Component Class: Removable Storage Device
Component Test: Must pass the rhr-core tests.
Must pass the rhr-remdisk test.
Component Notes: The device is not required to be bootable or available during install.
Modified On: 2005-01-30 06:38:56-05

Detail 2:
Ease of Install: 4
Status: Compatible
Hardware Id: 6046
Detail Notes: Test Environment:

Operating System / Software Configuration:

Red Hat Enterprise Linux v.3 Update 2


```
Red Hat Cluster Suite for (X86) Update 2<br>
<br>
Hardware Configuration:<br>
Acer Altos R710<br>
QLogic Corp. QLA2312 Fibre Channel Adapter (rev 02)<br>
kernel module = qla2300.o
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into
another category. Items listed in this group are subject to tests as determined by Red Hat,
Inc. Please see the Program Information Pages for more detail.
Modified On: 2005-01-30 06:52:37-05
```

Additional Certification Notes

No additional certification notes provided

3.2. Apple

3.2.1. Apple Xserve RAID Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153601>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

```
Last Touched On: 2004-01-06 08:44:43-05
Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5286
Detail Notes: Dual Independent RAID controllers <br>
Dual 2GB copper Fibre Channel ports <br>
14 hot-swapable ATA-100 Apple Drive Modules<br>
180GB to 2.02TB of storage
Component Class: Other
Component Test: Determined on a case by case basis.
Component Notes: This class is reserved to list all hardware that does not properly fit into
another category. Items listed in this group are subject to tests as determined by Red Hat,
Inc. Please see the Program Information Pages for more detail.
Modified On: 2004-01-05 09:20:02-05
```

Additional Certification Notes

No additional certification notes provided

3.3. Certance

3.3.1. Certance CD72, CD72LWE, CD72LW1U, CD144LW1U Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153633>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

Last Touched On: 2004-09-07 16:45:05-04
Detail 1:
Status: Compatible
Hardware Id: 5708
Detail Notes: CD72, CD72LWE, CD72LW1U, CD144LW1U Tape Drives
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-07 16:42:01-04

Additional Certification Notes

No additional certification notes provided

3.3.2. Certance CL 400H - LTO Ultrium 2 Half-Height Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153643>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-12-07 12:28:45-05
Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5951
Detail Notes: Certance CL 400H - LTO Ultrium 2 Half-Height<br>
<ul>
<font size=-1><b>kernel module:</b></font> st.o
</ul>
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-12-07 12:28:26-05
```

Additional Certification Notes

No additional certification notes provided

3.3.3. Certance CL 400H - LTO Ultrium 2 Half-Height Component/ Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153644>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

```
Last Touched On: 2004-12-07 12:29:13-05
Detail 1:
```

Ease of Install: 4
 Status: Compatible
 Hardware Id: 5952
 Detail Notes: Certance CL 400H - LTO Ultrium 2 Half-Height

 kernel module: st.o

 Component Class: Tape Drive
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-tape test.
 Component Notes: None
 Modified On: 2004-12-07 12:29:22-05

Additional Certification Notes

No additional certification notes provided

3.3.4. Certance DAT432 Autoloader, CDL 432 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153598>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Where: Red Hat (Durham, NC USA)
 Created On: 2003-12-15 17:45:13-05
 Returned On: mm-dd-yy
 Last Touched On: 2004-09-07 16:43:41-04
 Detail 1:
 Ease of Install: 4
 Status: Compatible
 Hardware Id: 5259
 Detail Notes: DDS4 6-tape autoloader
 <p>
 NOTE:Tapes are manually changed through front panel controllis
 Component Class: Tape Drive
 Component Test: Must pass the rhr-core tests.
 Must pass the rhr-tape test.
 Component Notes: None
 Modified On: 2004-09-07 16:43:57-04

Additional Certification Notes

No additional certification notes provided

3.3.5. CL800 CL110x-SS Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=154258>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.3.6. CL800 CL110x-SS Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=154259>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* ia64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.4. Dell

3.4.1. 24X IDE CD-RW/DVD-ROM GCC-4243N Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167002>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-STCD-RW-DVD-ROM
Model: GCC-4243N
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

HL-DT-ST_CD-RW_DVD-ROM_GCC-4243N_RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/dcb70f4c5bc92af661a3f8dde4ffdd6/HL-DT-ST_CD-RW_DVD-ROM_GCC-4243N_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.2. 24X IDE CD-RW/DVD-ROM GCC-4244N Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167005>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-ST-CD-RW-DVD-ROM
Model: GCC-4244N
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

HL-DT-ST_CD-RW_DVD-ROM_GCC-4244N_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/c8d7b70d9591ae4052c80d705b09b24e/HL-DT-ST_CD-RW_DVD-ROM_GCC-4244N_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.3. 48X CD-RW GCE-8400B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167458>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-ST
Model: GCE-8400B
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

HL-DT-ST_GCE-8400B_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/31b4fdccfb156b8edad6fff160032ea5/HL-DT-ST_GCE-8400B_RHEL3U4-i386.rpm

```
0 PASSED INFO
  PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.4. 48X CDRW/DVD ROM combo TSH492B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167464>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         TSST_CD-RW_DVD-ROM
Model:        TSH492B
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL
```

File Uploaded:

```
TSST_CD-RW_DVD-ROM_TSH492B_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/920227b9bb5780a42667220925abcfac/TSST_CD-RW_DVD-ROM_TSH492B_RHEL3U4-i386.rpm
```

```
0 PASSED INFO
  PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.5. 8X DVD-ROM DV-28E-C Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=166993>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: TEAC-DVDROM
Model: DV-28E-C
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

TEAC_DVD-ROM_DV-28E-C_RHEL3U5_i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/4619de333061e02da59998b591033d0e/TEAC_DVD-ROM_DV-28E-C_RHEL3U5_i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.6. 8X Slim DVD-ROM GDR8082N Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167460>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         HL-DT-ST DVD-ROM
Model:        GDR8082N
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL
```

File Uploaded:

```
HL-DT-ST_DVD-ROM_GDR8082N_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/a6d69073e340ecd8d620ca5ab5e27e2b/HL-DT-ST_DVD-ROM_GDR8082N_RHEL3U5-i386.rpm
```

```
0  PASSED  INFO
   PASSED  CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.7. Adaptec ASC-39320 U320 Component/Peripheral**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=167245>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         SCSI_HDD
Model:        300GB
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL
```

File Uploaded:

```
Adaptec_ASC-39320_U320_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/36a79ebc42a045a26fb1d65f7d34f8c3/Adaptec_ASC-39320_U320_RHEL3U4-i386.rpm
```

```
0  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.8. Adaptec SCSI controller AHA-39160 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167417>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: SC1420
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

Adaptec_AHA-39160_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/e445525f07020a3a68c7aa661c308d24/Adaptec_AHA-39160_RHEL3-i386.rpm

0 PASSED INFO
PASSED STORAGE

Additional Certification Notes

No additional certification notes provided

3.4.9. Broadcom BCM95721 PCI-e NIC BCM95721 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=192997>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2800
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:

BCM5721-RHEL3U5-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/e046bb138cd342c899504deb1a3cecd/BCM5721-RHEL3U5-i386.rpm>

0 PASSED INFO
PASSED NETWORK

Additional Certification Notes

No additional certification notes provided

3.4.10. CERC SATA CERC SATA 6 channel Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167416>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 800

```
Vendor:          Dell
Category:       Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
CERC-SATA6ch_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/a2d9a2959a3b8b64cc459ca7ac54d4a9/CERC-
SATA6ch_RHEL3-i386.rpm

0  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.11. Dell Powervault 100T DAT72 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193045>

Summary

- *Version:* RHEL3-U6
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:        Red Hat Enterprise Linux
Version:        3
Make:           PowerEdge
Model:          2850
Vendor:         Dell
Category:       Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:
PV-100T_DAT72_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/cf586287fe704a5dd06319471be8514c/
PV-100T_DAT72_RHEL3-i386.rpm

0  PASSED  INFO
   PASSED  TAPE
```

Additional Certification Notes

No additional certification notes provided

3.4.12. Dell PowerVault 110T DLT VS160 DLT-VS160 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=192898>

Summary

- *Version:* RHEL3-U6
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerVault
Model: DLT-VS160
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-37.EL

File Uploaded:

PV110T-DLT-VS160-R3U6-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/f7492ee9cb98f49d2216bafe24340ee9/PV110T-DLT-VS160-R3U6-i386.rpm>

0 PASSED INFO
PASSED TAPE

Additional Certification Notes

No additional certification notes provided

3.4.13. Dell PowerVault 110T LTO 110T LTO Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193048>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2850
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:

PV-110T_LT01_RHEL3-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/230b61f456aac5db90c194d17ee21e3c/>

PV-110T_LT01_RHEL3-i386.rpm

0	PASSED	INFO
	FAILED	TAPE
1	PASSED	INFO
	FAILED	TAPE
2	PASSED	INFO
	FAILED	TAPE
3	PASSED	INFO
	PASSED	TAPE

Additional Certification Notes

No additional certification notes provided

3.4.14. Dell Powervault 110T LTO-3 110T LTO-3 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193050>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2850

```
Vendor:          Dell
Category:       Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:
PV-110T_LT03_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/43d87e7a34b6d1223aefd565b427840d/
PV-110T_LT03_RHEL3-i386.rpm

0  PASSED  INFO
   PASSED  TAPE
```

Additional Certification Notes

No additional certification notes provided

3.4.15. Dell PowerVault 110T LTO2 110T LTO2 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193049>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:        Red Hat Enterprise Linux
Version:        3
Make:           PowerEdge
Model:          2850
Vendor:         Dell
Category:       Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:
PV-110T_LT02_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/44ca910ea828273a378bca9071829323/
PV-110T_LT02_RHEL3-i386.rpm

0  PASSED  INFO
   PASSED  TAPE
```

Additional Certification Notes

No additional certification notes provided

3.4.16. Dell PowerVault 110T SDLT320 110T SDLT320 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193051>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2850
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL

File Uploaded:

PV-110T_SDLT320_RHEL3U5-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/380a8dbaa1d410f18d0ed05701a1ab48/>

PV-110T_SDLT320_RHEL3U5-i386.rpm

```
0 PASSED INFO
  FAILED TAPE
1 PASSED INFO
  PASSED TAPE
```

Additional Certification Notes

No additional certification notes provided

3.4.17. GCR-8240N GCR-8240N Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193005>

Summary

- *Version:* 3

- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-ST_CD-ROM
Model: GCR-8240N
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

HL-DT-ST_CD-ROM_GCR-8240N_RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/a9c9a821759190006a07344dc7ad1e07/HL-DT-ST_CD-ROM_GCR-8240N_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.18. HL GCR-8483B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193012>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL
Model: GCR-8483B
Vendor: Dell

Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
HL_GCR-8483B_RHEL3U5-i386.rpm
<https://bugzilla.redhat.com/hwcert/data/rpms/306f78cbf59da0eecf1899947c910bc9/>
HL_GCR-8483B_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDR0M

Additional Certification Notes

No additional certification notes provided

3.4.19. HL-DT-ST DVD-ROM GDR8163B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193008>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-ST_DVD-ROM
Model: GDR8163B
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
HL-DT-ST_DVD-ROM_GDR8163B_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/edb56c0ac36e77fe805c0db150a7c308/HL-DT-ST_DVD-ROM_GDR8163B_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED CDR0M

Additional Certification Notes

No additional certification notes provided

3.4.20. HL-DT-ST_CD-RW/DVD GCC-4481B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193000>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HL-DT-ST_CD-RW/DVD
Model: GCC-4481B
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

HL-DT-ST-CD-RW_DVD_GCC-4481B_RHEL3U4-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/b926bcb3f419a510b516e7c963401009/HL-DT-ST-CD-RW_DVD_GCC-4481B_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.21. HL-DT-ST_DVD-ROM GDR8164B Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193010>

Summary

- *Version:* Update 4
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         HL-DT-ST_DVD-ROM
Model:        GDR8164B
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
HL-DT-ST_DVD-ROM_GDR8164B_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/ec98043f851aa188940f2d9895bf1abb/HL-DT-ST_DVD-
ROM_GDR8164B_RHEL3U4-i386.rpm

0  PASSED  INFO
   PASSED  CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.22. HLDS GCC-4482B HH 48X CDRW/DVD Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203092>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         TSST
Model:        TS-H352C 16X XH515
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-smp-2.4.21-32.EL
File Uploaded: HLDS_GCC-4482B_48X_HK118-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/459e97688c6adab58f00e3578be8e9cc/
HLDS_GCC-4482B_48X_HK118-RHEL3-i386.rpm0  PASSED  INFO
```


PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.23. HLDS GCR-8485B 48X Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=197533>

Summary

- *Version:* Update 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: HLDS
Model: GCR-8485B 48X FK234
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-44.EL

File Uploaded:

HLDS-GCR-8485B_48X_FK234-RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/5ce039e665b5e903bf3fa0d637390973/HLDS-GCR-8485B_48X_FK234-RHEL3-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.24. HLDS GDR-8084N Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203101>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         HLDS
Model:        GDR-8084N
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL
File Uploaded: HLDS_GDR-8084N-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/41a7dbdc3f56077c7182833f6fc28045/
HLDS_GDR-8084N-RHEL3-i386.rpm0  PASSED  INFO
    PASSED  CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.25. Intel PRO1000PT single and dual copper Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=196162>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
```

```
Make: Intel
Model: PR01000Px
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:
Intel-PR01000Px-RHEL3-i386-X3959-U3867.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/b91353bfd544ae0f8d8150e00eb650c2/Intel-PR01000Px-
RHEL3-i386-X3959-U3867.rpm

0 PASSED NETWORK2
  PASSED INFO
```

Additional Certification Notes

No additional certification notes provided

3.4.26. Intel Pro/1000 MT Dual port 1000MT_Dual Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167010>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product: Red Hat Enterprise Linux
Version: 3
Make: IntelPro
Model: 1000MT_Dual
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL
```

```
File Uploaded:
IntelPro-1000MT_Dual-RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/39367053ed16fcc165e033819cdb78cd/
IntelPro-1000MT_Dual-RHEL3U5-i386.rpm
```

```
0 PASSED INFO
  PASSED NETWORK
```

Additional Certification Notes

No additional certification notes provided

3.4.27. Intel PRO1000PF PCI-E Single Port Fiber PRO1000PF Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193123>

Summary

- *Version:* RHEL3-U7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2900
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:

Intel-fiber-RHEL3-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/1fcfe7742cddbcefd9dbf490c6db9a2/Intel-fiber-RHEL3-i386.rpm>

0 PASSED NETWORK2
PASSED INFO

Additional Certification Notes

No additional certification notes provided

3.4.28. IntelPro 1000MF Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193014>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: IntelPro
Model: 1000MF
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

IntelPro_1000MF_RHEL3U5-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/a557d6be90d06c6c942e1f4b7a8df4d1/>

IntelPro_1000MF_RHEL3U5-i386.rpm

```
0 PASSED INFO
  PASSED NETWORK
```

Additional Certification Notes

No additional certification notes provided

3.4.29. IntelPro 1000MT Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167341>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: IntelPro
Model: 1000MT

```
Vendor:      Dell
Category:    Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
IntelPro_1000MT_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/61863ccd893fd1f269556c51cc908a56/
IntelPro_1000MT_RHEL3U5-i386.rpm

0  PASSED  INFO
   PASSED  NETWORK
```

Additional Certification Notes

No additional certification notes provided

3.4.30. IntelPro 1000P_Dual Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167241>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         IntelPro
Model:        1000P_Dual
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
IntelPro_1000P-Dual_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/05eaa7cfdd4aa4e240dafd635ae1a9ae/IntelPro_1000P-
Dual_RHEL3U5-i386.rpm

0  PASSED  INFO
   PASSED  NETWORK
```

Additional Certification Notes

No additional certification notes provided

3.4.31. IntelPro 100S Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167328>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: IntelPro
Model: 100S
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

IntelPro_100S_RHEL3U5-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/4d4143a2820c087c1af67c231efd380c/>

IntelPro_100S_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED NETWORK

Additional Certification Notes

No additional certification notes provided

3.4.32. Lite-On LTN486S Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193946>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         Lite-On
Model:        LTN486S
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
Lite-On_LTN486S-RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/db383cbf51b48869fccf46af746ca8e2/Lite-On_LTN486S-
RHEL3U5-i386.rpm

0  PASSED  INFO
   PASSED  CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.33. LITE-ON_CD-ROM LTN-489S Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193038>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         LITE-ON_CD-ROM
Model:        LTN-489S
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
LITE-ON_CD-ROM_LTN-489S_RHEL3U4-i386.rpm
```



```
https://bugzilla.redhat.com/hwcert/data/rpms/f9d953e5feb573863442b2e97ee8db26/LITE-ON_CD-ROM_LTN-489S_RHEL3U4-i386.rpm
```

```
0 PASSED INFO
  PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.34. LTN 4891S 48X Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203107>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         LTN
Model:        4891S 48X WH303 MF270
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-44.EL
File Uploaded: LTN-4891S_48X_WH303_MF270-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/97cc6781f426e9430663c173250ff5b5/
LTN-4891S_48X_WH303_MF270-RHEL3-i386.rpm0 PASSED INFO
  PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.35. PERC 320/DC Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167334>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PERC
Model: 320DC
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

PERC_320DC_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/b53dd54f6c0447e07ed2eb093007ee72/PERC_320DC_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED STORAGE

Additional Certification Notes

No additional certification notes provided

3.4.36. PERC Megaraid Controller PERC4/SC Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167419>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3

```
Make:          PowerEdge
Model:         2800
Vendor:        Dell
Category:      Component/Peripheral
Kernel Version: kernel-2.4.21-32.EL

File Uploaded:
PERC4SC_RHEL3-x86_64.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/6b821d6219b41ad778138bd8df59754b/PERC4SC_RHEL3-
x86_64.rpm

0  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.37. PERC/5E PERC 5E Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187767>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:       Red Hat Enterprise Linux
Version:       3
Make:          PV
Model:         MD1000
Vendor:        Dell
Category:      Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:
PV-MD1000-RHEL3U7-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/94d7017c3a646ae0956c5201f3fa3dda/PV-MD1000-
RHEL3U7-i386.rpm

0  FAILED  INFO
   FAILED  STORAGE
1  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.38. Philips SDR089 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203112>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         Philips
Model:        SDR089
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL
File Uploaded: Philips-SDR089-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/308ecc57a36eb8357985f6f9b15181e7/Philips-SDR089-RHEL3-i386.rpm0 PASSED INFO
PASSED CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.39. PowerEdge 2900 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193062>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2900
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:

Intel-fiber-RHEL3-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/1fcfe7742cddbcefd9dbf490c6db9a2/Intel-fiber-RHEL3-i386.rpm>

0 PASSED INFO

Additional Certification Notes

No additional certification notes provided

3.4.40. PowerVault 100T DAT72 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153629>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

Last Touched On: 2004-08-26 14:43:51-04

Detail 1:

Ease of Install: 4

Status: Certified

Hardware Id: 5687

Detail Notes: PowerVault 100T DAT 72

Component Class: Tape Drive

Component Test: Must pass the rhr-core tests.

Must pass the rhr-tape test.

Component Notes: None

Modified On: 2004-08-26 14:43:09-04

Additional Certification Notes

No additional certification notes provided

3.4.41. PowerVault 100T DDS4 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153632>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-09-03 18:14:16-04
Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5694
Detail Notes: PowerVault 100T DDS4
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-03 18:14:06-04
```

Additional Certification Notes

No additional certification notes provided

3.4.42. PowerVault 110T LTO2 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=148652>

Summary

- *Version:* 3
- *Category:* Component/Peripheral

- *Platforms:* i386

Additional Comments

Additional Data:

Where: Red Hat (Durham, NC USA)
Cpu Name: X86
Created On: 2004-11-18 15:42:14-05
Returned On: mm-dd-yy
Last Touched On: 2004-11-18 15:42:29-05

Detail Data:

Detail 1:
Ease of Install: 4
Status: Compatible
Hardware Id: 5885
Detail Notes: PowerVault 110T LT02 Tape Drive
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-11-18 15:42:24-05

Additional Certification Notes

No additional certification notes provided

3.4.43. PowerVault 110T SDLT320 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153639>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

Where: Red Hat (Durham, NC USA)
Created On: 2004-09-14 13:12:20-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-14 13:12:58-04
Detail 1:

Ease of Install: 4
Status: Certified
Hardware Id: 5740
Detail Notes: PowerVault 110T SDLT320
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-14 13:12:47-04

Additional Certification Notes

No additional certification notes provided

3.4.44. PowerVault 122T LTO-2 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153637>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

Where: Red Hat (Durham, NC USA)
Created On: 2004-09-13 11:46:39-04
Returned On: mm-dd-yy
Last Touched On: 2004-09-13 11:47:33-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5737
Detail Notes: PowerVault 122T LTO-2
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-09-13 11:47:15-04

Additional Certification Notes

No additional certification notes provided

3.4.45. PowerVault 22XS Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=207580>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         PowerVault
Model:        22XS
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-47.EL
File Uploaded: PV22XS-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/dc43279795bc84ad56907c59b1815a6b/PV22XS-
RHEL3-i386.rpm0 PASSED INFO
PASSED STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.4.46. PowerVault MD1000 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187755>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.4.47. PV110T LTO-2-L Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=192894>

Summary

- *Version:* RHEL3-U6
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted
```

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         PV110T
Model:        LTO-2-L
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-37.EL
```

```
File Uploaded:
```

```
PV110T-LTO-2-L_R3U6-i386.rpm
```

```
https://bugzilla.redhat.com/hwcert/data/rpms/0e78d3824f2463f6eb312f781e76d6e2/PV110T-LTO-2-L\_R3U6-i386.rpm
```

```
0  PASSED  INFO
   PASSED  TAPE
```

Additional Certification Notes

No additional certification notes provided

3.4.48. SAMSUNG 16X DVD-ROM SD-616T Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167134>

Summary

- *Version:* 3

- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung_DVD-ROM
Model: SD-616T
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

Samsung_DVD-ROM_SD-616T_RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/58f83bc269637a400a8df784b563e0c5/Samsung_DVD-ROM_SD-616T_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.49. SAMSUNG 48X CD-ROM SC-148A Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167042>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung-CD-ROM
Model: SC-148A
Vendor: Dell

Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
Samsung_CD-ROM_SC-148A-RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/5390ab1f390bc7e9d4f9d4b010719a22/Samsung_CD-ROM_SC-148A-RHEL3U5-i386.rpm

```
0 PASSED INFO
  PASSED CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.50. Samsung CD-RW/DVD SM-352F Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193944>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung_CD-RW_DVD
Model: SM-352F
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
Samsung_CD-RW_DVD_SM-352F_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/0db7c537110cac122ca07e498c39c690/Samsung_CD-RW_DVD_SM-352F_RHEL3U4-i386.rpm

Please note the following failures:
FAILED: No MEMORY found in limits file for platform

```
0 INFO
1 PASSED INFO
  PASSED CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.51. Samsung CDROM SN-124 Component/Peripheral**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=193942>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung-CDROM
Model: SN-124
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

Samsung_CD-ROM_SN-124_RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/20c33a4d5c8f91bdeb9308cab29cd7af/Samsung_CD-ROM_SN-124_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.52. Samsung_CD-ROM SN-124P Component/Peripheral**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=193016>

Summary

- *Version:* RHEL3-U5

- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung_CD-ROM
Model: SN-124P
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

Samsung_CD-ROM_SN-124P_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/c343ab7e041c3694bac92caef4d46de2/Samsung_CD-ROM_SN-124P_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.53. Samsung_CD-RW_DVD SN-324 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193042>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung_CD-RW_DVD
Model: SN-324
Vendor: Dell

Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
Samsung_CD-RW_DVD_SN-324_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/2b442eae1801e7967baca8de640fde8/Samsung_CD-RW_DVD_SN-324_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.54. Samsung_CD-RW_DVD SN-324S Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193040>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Samsung_CD-RW_DVD
Model: SN-324S
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:
Samsung_CD-RW_DVD_SN-324S_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/4bf80ce4c74c13afcd7732f63261f816/Samsung_CD-RW_DVD_SN-324S_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDROM

Additional Certification Notes

No additional certification notes provided

3.4.55. SAS HDD 300GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193940>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: SAS-HDD
Model: 300GB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:

SAS_HDD-300GB-RHEL3-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/c82d28da74ffad9c21db57a76a8366ba/SAS_HDD-300GB-RHEL3-i386.rpm

0 PASSED INFO
PASSED STORAGE2

Additional Certification Notes

No additional certification notes provided

3.4.56. SAS HDD 2.5" 72GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193938>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: SAS-HDD
Model: 72GB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL

File Uploaded:

SAS_HDD2.5-72GB-RHEL3-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/7668223ca38b65b7ae8be67a33aa41fc/SAS_HDD2.5-72GB-RHEL3-i386.rpm

```
0 PASSED INFO
  PASSED STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.4.57. SATA 250GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167326>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: SATA
Model: 250GB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

SATA_250GB_RHEL3U5-i386.rpm

```
https://bugzilla.redhat.com/hwcert/data/rpms/d3ea02c0d24c021af88f8d93ccf6fcdf/  
SATA_250GB_RHEL3U5-i386.rpm
```

```
0  PASSED  INFO  
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.58. SATA 750GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=211840>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted
```

```
Product:      Red Hat Enterprise Linux  
Version:      3  
Make:         SATA  
Model:        750GB  
Vendor:       Dell  
Category:     Component/Peripheral  
Kernel Version: kernel-hugemem-2.4.21-47.EL  
File Uploaded: SATA-750GB-RHEL3-i386-SAS5i.rpm  
https://bugdev.devel.redhat.com/hwcert/data/rpms/54cf4b3d96e027fe649530b6986a2147/SATA-750GB-  
RHEL3-i386-SAS5i.rpm0  PASSED  INFO  
                      PASSED  STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.4.59. SATA 500GB HDD HDS725050KLA360 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167024>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: SATA
Model: 500GB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

SATA-500GB-RHEL3U5_i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/d9ed63a244e6f6369a27bc37a08cd635/SATA-500GB-RHEL3U5_i386.rpm

0 PASSED INFO
PASSED STORAGE

Additional Certification Notes

No additional certification notes provided

3.4.60. SATA HDD 2.5" 40GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=196170>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         SATA HDD 2.5
Model:        40GB
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL
```

File Uploaded:

```
SATA_HDD-2.5-40GB_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/de4ea066499ea03567193351d9955841/
SATA_HDD-2.5-40GB_RHEL3-i386.rpm
```

```
0  PASSED  INFO
   PASSED  STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.4.61. SCSI RAID Controller PERC4/DC Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167637>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         PowerEdge
Model:        2600
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL
```

File Uploaded:

```
PERC4DC_RHEL3-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/71f5761b46b8f950f06dcdd991ccee98/PERC4DC_RHEL3-
i386.rpm
```

```
0  PASSED  INFO
   PASSED  STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.62. SCSI RAID controller PERC4e/DC Component/Peripheral**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=167421>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: PowerEdge
Model: 2850
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

PERC4eDC_RHEL3-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/8291574e1391a38c978af7935bc97230/PERC4eDC_RHEL3-i386.rpm

```
0 PASSED INFO
  PASSED STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.63. SCSI_HDD 300GB Component/Peripheral**Original Catalog Posting URL**

<https://hardware.redhat.com/show.cgi?id=167242>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: SCSI_HDD
Model: 300GB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

SCSI_HDD_300GB_RHEL3U4-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/36a79ebc42a045a26fb1d65f7d34f8c3/>

SCSI_HDD_300GB_RHEL3U4-i386.rpm

```
0 PASSED INFO
  PASSED STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.64. Seagate STT3401A PowerVault 100T, TR40, 20/40GB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167415>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Seagate
Model: STT3401A
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

Seagate_STT3401A_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/d352642efa1a9c888fcb958ec4d7cade/Seagate_STT3401A_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED TAPE

Additional Certification Notes

No additional certification notes provided

3.4.65. Standard_Floppy 1.44MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193018>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Standard_Floppy
Model: 1.44MB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

Standard_FDD_1.44MB_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/f5e7fb0b2faa13c6b21191087f99c38c/Standard_FDD_1.44MB_RHEL3U4-i386.rpm

0 PASSED INFO

PASSED FLOPPY

Additional Certification Notes

No additional certification notes provided

3.4.66. Standard_Slim_FDD 1.44MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193021>

Summary

- *Version:* RHEL3-U5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: Standard_Slim_FDD
Model: 1.44MB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

Standard_Slim_FDD_1.44MB_RHEL3U5-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/76eb51b794b3a0d24769e082cf17c506/Standard_Slim_FDD_1.44MB_RHEL3U5-i386.rpm

0 PASSED INFO
PASSED FLOPPY

Additional Certification Notes

No additional certification notes provided

3.4.67. TEAC 24X IDE CD-ROM CD-224E Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=166999>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: TEAC_CDR0M
Model: CD-224E
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

TEAC_CD-ROM_CD-224E-RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/a68542c5cb21901b8b1666f41669f29b/TEAC_CD-ROM_CD-224E-RHEL3U5-i386.rpm

```
0 PASSED INFO
  PASSED CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.68. TEAC DVD+RW DV-W58E Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167026>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         TEAC DVD+RW
Model:        DV-W58E
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
TEAC_DVD+RW_DV-W58E_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/206cf739a27ae47fc9f42665af790f2e/TEAC_DVD+RW_DV-
W58E_RHEL3U4-i386.rpm

0  PASSED  INFO
   PASSED  CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.69. Teac USB CD-ROM CD-210PU Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167137>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         USB_CD-ROM
Model:        CD-210PU
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:
USB_CD-ROM_CD-210PU_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/74075e977dbf644eb121e5e9b373f04e/USB_CD-
ROM_CD-210PU_RHEL3U4-i386.rpm

0  PASSED  INFO
   PASSED  CDR0M
```

Additional Certification Notes

No additional certification notes provided

3.4.70. Teac USB FLOPPY FD-05PUB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=167139>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         USB_FLOPPY
Model:        FD-05PUB
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL
```

File Uploaded:

```
USB_FLOPPY_FD-05PUB_RHEL3U4-i386.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/a628ca46c335b0fb06a34f137451861c/
USB_FLOPPY_FD-05PUB_RHEL3U4-i386.rpm
```

```
0  PASSED  INFO
   PASSED  FLOPPY
```

Additional Certification Notes

No additional certification notes provided

3.4.71. TEAC_CDROM CD-224E Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=166992>

Summary

- *Version:* 3

- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: TEAC_CDR0M
Model: CD-224E
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-32.EL

File Uploaded:

TEAC_CD-ROM_CD-224E-RHEL3U5-i386.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/a68542c5cb21901b8b1666f41669f29b/TEAC_CD-ROM_CD-224E-RHEL3U5-i386.rpm

0 PASSED INFO
PASSED CDR0M

Additional Certification Notes

No additional certification notes provided

3.4.72. TSST TS-H352C 16X Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203127>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: TSST
Model: TS-H352C 16X XH515
Vendor: Dell

```
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-44.EL
File Uploaded: TSST-TS_H352C_16X_XH515-RHEL3_i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/82e770b85ffcc2ff2e183f3dde6da90/TSST-
TS_H352C_16X_XH515-RHEL3_i386.rpm0 PASSED INFO
PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.73. TSST TS-H352C 16X XH515 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203126>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product: Red Hat Enterprise Linux
Version: 3
Make: TSST
Model: TS-H352C 16X XH515
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-44.EL
File Uploaded: TSST-TS_H352C_16X_XH515-RHEL3_i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/82e770b85ffcc2ff2e183f3dde6da90/TSST-
TS_H352C_16X_XH515-RHEL3_i386.rpm0 PASSED INFO
PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.74. TSST TS-L462C Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203116>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         TSST
Model:        TS-L462C
Vendor:       Dell
Category:     Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL
File Uploaded: TSST_TS-L462C-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/f513bbf4ba2e34202d84626da9a23f84/TSST_TS-
L462C-RHEL3-i386.rpm0  FAILED  INFO
    FAILED  CDROM
2  PASSED  INFO
    PASSED  CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.75. TSST TS-L462D Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203121>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
```

```
Make:          TSST
Model:         TS-L462D
Vendor:        Dell
Category:      Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.EL
File Uploaded: TSST_TS-L462D-RHEL3-i386.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/49a4b69c1a05eea90d804ff5ffee9d12/TSST_TS-
L462D-RHEL3-i386.rpm0 PASSED INFO
PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.76. USBCDROM DV28PU DV28PU Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193569>

Summary

- *Version:* RHEL3-U7
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:       Red Hat Enterprise Linux
Version:       3
Make:          PowerEdge
Model:         1955
Vendor:        Dell
Category:      Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-40.6.EL
```

```
File Uploaded:
USBCDROM-RHEL3-i386-DV28PU-GJ890.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/43063a4dc641118f28c5441c101630b6/USBCDROM-RHEL3-
i386-DV28PU-GJ890.rpm
```

```
0 PASSED INFO
PASSED CDROM
```

Additional Certification Notes

No additional certification notes provided

3.4.77. USB_Key 128MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193025>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: USB_Key
Model: 128MB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

USB_Key_128MB_RHEL3U4-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/9d3f59170743599fabb3fa757630042f/>

USB_Key_128MB_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED STORAGE

Additional Certification Notes

No additional certification notes provided

3.4.78. USB_Key 256MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193030>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: USB_Key
Model: 256MB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

USB_Key_256MB_RHEL3U4-i386.rpm

<https://bugzilla.redhat.com/hwcert/data/rpms/17e9178fdf9d7f6e01e9d9d4235ae7ef/>

USB_Key_256MB_RHEL3U4-i386.rpm

0 PASSED INFO
PASSED STORAGE

Additional Certification Notes

No additional certification notes provided

3.4.79. USB_Key 512MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193034>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: USB_Key
Model: 512MB
Vendor: Dell
Category: Component/Peripheral
Kernel Version: kernel-hugemem-2.4.21-27.EL

File Uploaded:

USB_Key_512MB_RHEL3U4-i386.rpm

```
https://bugzilla.redhat.com/hwcert/data/rpms/ce5426dfac6ace6c7427c53c0fe12cd3/  
USB_Key_512MB_RHEL3U4-i386.rpm
```

```
0 PASSED INFO  
PASSED STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.4.80. USB_Key 64MB Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=193023>

Summary

- *Version:* Update 5
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux  
Version:      3  
Make:         USB_Key  
Model:        64MB  
Vendor:       Dell  
Category:     Component/Peripheral  
Kernel Version: kernel-hugemem-2.4.21-32.EL
```

File Uploaded:

```
USB_Key_64MB_RHEL3U5-i386.rpm  
https://bugzilla.redhat.com/hwcert/data/rpms/aa99ae7f887d6a13d47fc47f8ac28fb3/  
USB_Key_64MB_RHEL3U5-i386.rpm
```

```
0 PASSED INFO  
PASSED STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.5. Hewlett Packard

3.5.1. Hewlett Packard HP DAT 72x6 Autoloader Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153620>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-05-14 10:41:34-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5457
Detail Notes: HP DAT 72x6 Autoloader
<BR>
Includes drive and changer
<BR>
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-05-14 10:41:22-04
```

Additional Certification Notes

No additional certification notes provided

3.5.2. Hewlett Packard hp StorageWorks DAT 72 Tape Drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153618>

Summary

- *Version:* 3

- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-04-23 12:22:20-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5428
Detail Notes: hp StorageWorks DAT 72 Tape Drive
<BR>
Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:22:12-04
```

Additional Certification Notes

No additional certification notes provided

3.5.3. Hewlett Packard hp StorageWorks dat40 tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153616>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-04-23 12:20:20-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5426
Detail Notes: hp StorageWorks dat40 tape drive
<BR>
```

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:20:10-04

Additional Certification Notes

No additional certification notes provided

3.5.4. Hewlett Packard hp StorageWorks dat40x6 autoloaders Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153619>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:23:45-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5429
Detail Notes: hp StorageWorks dat40x6 autoloaders

Includes drive and changer

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:23:37-04

Additional Certification Notes

No additional certification notes provided

3.5.5. Hewlett Packard hp StorageWorks DLT 40/80 GB tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153609>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-04-23 12:01:53-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5419
Detail Notes: hp StorageWorks DLT 40/80 GB tape drive<BR>
Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:01:03-04
```

Additional Certification Notes

No additional certification notes provided

3.5.6. Hewlett Packard hp StorageWorks SDLT 220 GB tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153612>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:14:44-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5422
Detail Notes: hp StorageWorks SDLT 220 GB tape drive

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:14:26-04

Additional Certification Notes

No additional certification notes provided

3.5.7. Hewlett Packard hp StorageWorks SDLT 320 GB tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153611>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:08:28-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5421
Detail Notes: hp StorageWorks SDLT 320 GB tape drive

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:08:19-04

Additional Certification Notes

No additional certification notes provided

3.5.8. Hewlett Packard HP StorageWorks SDLT 600 Tape Drive <! 56042 > Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153649>

Summary

- *Version:* Update 2
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2005-02-14 10:04:14-05
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 6092
Detail Notes: HP StorageWorks SDLT 600 Tape Drive

Tested on a HP Proliant DL380 G2 using Red Hat Enterprise Linux 3 Update 2
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2005-02-09 14:00:42-05

Additional Certification Notes

No additional certification notes provided

3.5.9. Hewlett Packard hp StorageWorks Ultrium 215 Tape Drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153615>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:19:05-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5425
Detail Notes: hp StorageWorks Ultrium 215 Tape Drive

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:18:53-04

Additional Certification Notes

No additional certification notes provided

3.5.10. Hewlett Packard hp StorageWorks Ultrium 230 Tape Drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153613>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:15:44-04

Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5423
Detail Notes: hp StorageWorks Ultrium 230 Tape Drive

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:15:40-04

Additional Certification Notes

No additional certification notes provided

3.5.11. Hewlett Packard hp StorageWorks Ultrium 460 Tape Drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153614>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-04-23 12:17:47-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5424
Detail Notes: hp StorageWorks Ultrium 460 Tape Drive

Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:17:04-04

Additional Certification Notes

No additional certification notes provided

3.5.12. Hewlett Packard HP StorageWorks Ultrium 960 Tape Drive <! 58025 > Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153645>

Summary

- *Version:* Update 2
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2005-01-12 16:26:38-05
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 6026
Detail Notes: HP StorageWorks Ultrium 960 Tape Drive <br>
Tested on a HP Proliant DL380 G2 using Red Hat Enterprise Linux 3 Update 2
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2005-01-12 14:06:19-05
```

Additional Certification Notes

No additional certification notes provided

3.5.13. Hewlett Packard hp StorageWorks Universal DLT VS 40/80 GB tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153610>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-04-23 12:04:55-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5420
Detail Notes: hp StorageWorks Universal DLT VS 40/80 GB tape drive<BR>
Tested with a Proliant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:04:48-04
```

Additional Certification Notes

No additional certification notes provided

3.5.14. Hewlett Packard hp StroageWorks dat24 tape drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153617>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-04-23 12:21:22-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5427
```

Detail Notes: hp Stroageworks dat24 tape drive

Tested with a ProLiant DL560
Component Class: Tape Drive
Component Test: Must pass the rhr-core tests.
Must pass the rhr-tape test.
Component Notes: None
Modified On: 2004-04-23 12:21:04-04

Additional Certification Notes

No additional certification notes provided

3.5.15. Hewlett Packard Modular Smart Array 20 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153640>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-09-24 12:18:29-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5776
Detail Notes: Tested on ProLiant DL560 G1 With RedHat Enterprise Linux AS 3.0
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation to from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-09-24 11:55:04-04

Additional Certification Notes

No additional certification notes provided

3.5.16. Hewlett Packard Modular Smart Array 20 <! 57220 > Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153647>

Summary

- *Version:* Update 2
- *Category:* Component/Peripheral
- *Platforms:* x86_64

Additional Comments

```
Last Touched On: 2005-01-13 10:37:24-05
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 6028
Detail Notes: Tested on ProLiant DL380 G4 With RedHat Enterprise Linux v. 3 Update 2
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation <b>to</b> from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2005-01-13 10:36:37-05
```

Additional Certification Notes

No additional certification notes provided

3.5.17. Hewlett Packard Modular Smart Array 500 G2 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153623>

Summary

- *Version:* 3
- *Category:* Component/Peripheral

- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-07-26 13:01:30-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5567
Detail Notes: Tested on ProLiant DL380 G3 With RedHat Enterprise Linux AS 3.0
Component Class: Fixed Disk Drive
Component Test: Must be post install bootable.
Must be available for installation <b>to</b> from the installation program.
Must pass the rhr-core tests.
Must pass the rhr-fdisk test.
Component Notes: None
Modified On: 2004-07-07 09:55:03-04
```

Additional Certification Notes

No additional certification notes provided

3.5.18. Hewlett Packard QLogic QLA2312 Fibre Channel Adapter Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153627>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-08-31 11:10:10-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5663
Detail Notes: Tested on ProLiant BL30p G1 With RedHat Enterprise Linux 3.0
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
```

Modified On: 2004-08-10 11:21:58-04

Additional Certification Notes

No additional certification notes provided

3.5.19. Hewlett Packard Smart Array 6402 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153631>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

Last Touched On: 2004-09-02 09:19:38-04

Detail 1:

Ease of Install: 4

Status: Certified

Hardware Id: 5690

Detail Notes: Tested on ProLiant DL560 G1 With RedHat Enterprise Linux v. 3

Component Class: Controller Card

Component Test: Must make all required hardware available to the installation program. Must pass the rhr-core tests.

Component Notes: Must pass all tests required for attached hardware.

Modified On: 2004-08-30 14:07:23-04

Additional Certification Notes

No additional certification notes provided

3.5.20. Hewlett Packard Smart Array 6404 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153630>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-09-02 09:19:29-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5689
Detail Notes: Tested on ProLiant DL560 G1 With RedHat Enterprise Linux v. 3
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-08-30 14:03:14-04
```

Additional Certification Notes

No additional certification notes provided

3.5.21. Hewlett Packard Smart Array SA642 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153625>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

```
Last Touched On: 2004-09-15 16:48:15-04
Detail 1:
Ease of Install: 4
Status: Certified
Hardware Id: 5569
Detail Notes: Tested on ProLiant DL380 G3 With RedHat Enterprise Linux AS 3.0
Component Class: Controller Card
Component Test: Must make all required hardware available to the installation program.
Must pass the rhr-core tests.
```

Component Notes: Must pass all tests required for attached hardware.
Modified On: 2004-09-15 16:48:13-04

Additional Certification Notes

No additional certification notes provided

3.5.22. HP Smart Array P600 Controller Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=162180>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

On Red Hat Enterprise Linux 3, the HP Smart Array P600 Controller is used with the HP StorageWorks Modular Smart Array 50 Enclosure or in an internal drive cage for SAS storage on HP Proliant servers.

The Modular Smart Array 50 is currently only for use with the Smart Array P600 Controller.

Quickspecs on the HP StorageWorks Modular Smart Array 50 Enclosure can be found here:
http://h18000.www1.hp.com/products/quickspecs/12245_na/12245_na.html

Additional Certification Notes

No additional certification notes provided

3.5.23. HP StorageWorks Modular Smart Array 50 Enclosure Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=164190>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.24. HP StorageWorks Ultrium 232 Tape Drive Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=161960>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.25. ProLiant FC1143/1243 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=211510>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral

- *Platforms:* x86_64 and i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        DL585 G2
Vendor:       Hewlett Packard
Category:     Component/Peripheral
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: QLA2422_hba_RH3_x64_amd.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/39c9f1df1c8fd53cd9d97d25ce52d924/
QLA2422_hba_RH3_x64_amd.rpm0  PASSED  INFO
    PASSED  STORAGE2
1  PASSED  INFO
    PASSED  STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.5.26. ProLiant HP Smart Array P800 Controller Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=215594>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

```
Red Hat Hardware Certification Submitted

Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        DL385 G2
Vendor:       Hewlett Packard
Category:     Component/Peripheral
Kernel Version: kernel-smp-2.4.21-47.EL
```

```
File Uploaded: P800_RH3_U8_x64_amd.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/755114b1747920b4b067cf5c5e944b83/
P800_RH3_U8_x64_amd.rpm0 PASSED INFO
PASSED STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.5.27. ProLiant ML370 G4 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=199952>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        ML370 G4
Vendor:       Hewlett Packard
Category:     Component/Peripheral
Kernel Version: kernel-2.4.21-40.EL
File Uploaded: rhr2-ProLiant-ML370_G4-Taroon_Update_7_results-1.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/98f50c2db199d628ca77679e43677a6b/rhr2-
ProLiant-ML370_G4-Taroon_Update_7_results-1.noarch.rpm0 PASSED INFO
PASSED STORAGE
PASSED STORAGE2
```

Additional Certification Notes

No additional certification notes provided

3.5.28. ProLiant NC1020 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194102>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.29. ProLiant NC150T Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194109>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: ProLiant
Model: DL320 G4
Vendor: Hewlett Packard
Category: Component/Peripheral
Kernel Version: kernel-2.4.21-40.EL

File Uploaded:

rhr2-ProLiant-nc150t-RH3_x86_results-1.noarch.rpm
https://bugzilla.redhat.com/hwcert/data/rpms/844d308d056214f297a28cf7008bd55f/rhr2-ProLiant-nc150t-RH3_x86_results-1.noarch.rpm

0 PASSED NETWORK2
PASSED INFO

Additional Certification Notes

No additional certification notes provided

3.5.30. ProLiant NC310f Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194126>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: ProLiant
Model: DL320 G4
Vendor: Hewlett Packard
Category: Component/Peripheral
Kernel Version: kernel-2.4.21-40.EL

File Uploaded:

rhr2-ProLiant-nc310f-RH3_x64_results-1.noarch.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/e09740a0aabe14937cb4748761c1a38d/rhr2-ProLiant-nc310f-RH3_x64_results-1.noarch.rpm

```
0 PASSED NETWORK2
  PASSED INFO
```

Additional Certification Notes

No additional certification notes provided

3.5.31. ProLiant NC340T Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194118>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.32. ProLiant NC360T Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=211515>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        DL585 G2
Vendor:       Hewlett Packard
Category:     Component/Peripheral
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: NC360T_RH3_x64_amd.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/027e37f53ef5f0cf8142cc7b683ed108/
NC360T_RH3_x64_amd.rpmPlease note the following failures:
FAILED: No MEMORY found in limits file for platform
```

```
0      INFO
2  PASSED  NETWORK2
      PASSED  INFO
```

Additional Certification Notes

No additional certification notes provided

3.5.33. ProLiant NC7170 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=194110>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

Product: Red Hat Enterprise Linux
Version: 3
Make: ProLiant
Model: DL320 G4
Vendor: Hewlett Packard
Category: Component/Peripheral
Kernel Version: kernel-2.4.21-40.EL

File Uploaded:

rhr2-ProLiant-nc7170-RH3_x64_results-1.noarch.rpm

https://bugzilla.redhat.com/hwcert/data/rpms/7320cf9558d2fd006f24a7284080abec/rhr2-ProLiant-nc7170-RH3_x64_results-1.noarch.rpm

```
0 PASSED NETWORK2
  PASSED INFO
```

Additional Certification Notes

No additional certification notes provided

3.5.34. ProLiant Smart Array E200 (SAE200) Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=203778>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.35. Smart Array P400 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=199951>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.5.36. Storage Works HP SC11Xe Host Bus Adapter Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=210240>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        DL320 G5
Vendor:       Hewlett Packard
Category:     Server
Kernel Version: kernel-smp-2.4.21-40.EL
File Uploaded: rhr2-ProLiant-DL320_G5-Taroon_Update_7_results-1.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/984c7411acdcd7d6001f007fea2fed75/rhr2-ProLiant-DL320_G5-Taroon_Update_7_results-1.noarch.rpmPlease note the following failures:
```

WARNING: Kickstart file not found for required tests check.

```
0 PASSED INFO
  PASSED TAPE
```

Additional Certification Notes

No additional certification notes provided

3.5.37. StorageWorks FC 2143 & FC2243 (AMD) Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=211508>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* x86_64 and i386

Additional Comments

Red Hat Hardware Certification Submitted

```
Product:      Red Hat Enterprise Linux
Version:      3
Make:         ProLiant
Model:        DL585 G2
Vendor:       Hewlett Packard
Category:     Component/Peripheral
Kernel Version: kernel-smp-2.4.21-47.EL
File Uploaded: L2A2860_AMD_RH3U8_x64.noarch.rpm
https://bugdev.devel.redhat.com/hwcert/data/rpms/8023419e45e07dbaab157847117e2c1b/
L2A2860_AMD_RH3U8_x64.noarch.rpm0 PASSED INFO
  FAILED STORAGE2
1 FAILED INFO
  FAILED STORAGE2
2 PASSED INFO
  FAILED STORAGE2
3 PASSED INFO
  PASSED STORAGE
4 PASSED INFO
  PASSED STORAGE
```

Additional Certification Notes

No additional certification notes provided

3.5.38. StorageWorks SB40c Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=214796>

Summary

- *Version:* Update 8
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.6. Intel Corporation

3.6.1. Server Board SE7520AF2 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153677>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.7. Promise Technology Inc.

3.7.1. FastTrak S150 SX4 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153635>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7532](#)¹ What devices do drives attached to a Promise SX8 controller use?

3.7.2. SATAII150 SX8 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153636>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7532](#)² What devices do drives attached to a Promise SX8 controller use?

3.8. Quantum

3.8.1. Quantum DAT72 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=177172>

Summary

- *Version:* Update 6
- *Category:* Component/Peripheral
- *Platforms:* ia64 and x86_64 and i386

Additional Comments

No additional comments provided

Additional Certification Notes

Please see the following references for important information regarding this certification:

- Red Hat Knowledge Base (Article): [7323³](#) Why do some Quantum Tape drives and loaders appear as Seagate or Certance?

3.8.2. Quantum DLT-S4 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187954>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.8.3. Quantum DLT-V4 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=187966>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.8.4. Quantum LTO 3 Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=188077>

Summary

- *Version:* Update 7
- *Category:* Component/Peripheral
- *Platforms:* i386 and x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9. Sun Microsystems, Inc.

3.9.1. Sun Microsystems StorEdge 3511 FC Array with SATA Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153650>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9.2. Sun Microsystems Sun StorEdge 3120 SCSI Array Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153654>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9.3. Sun Microsystems Sun StorEdge 3120 SCSI Array Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153655>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9.4. Sun Microsystems Sun StorEdge 3310 SCSI Array Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153652>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* i386

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9.5. Sun Microsystems Sun StorEdge 3310 SCSI Array Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153653>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.9.6. Sun Microsystems Sun StorEdge 3511 FC Array with SATA Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=153651>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* x86_64

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.10. Winchester Systems, Inc.

3.10.1. Winchester Systems, Inc. FlashDisk FC-3400 Series Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=181934>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided

3.10.2. Winchester Systems, Inc. FlashDisk SA-3400 Series Component/Peripheral

Original Catalog Posting URL

<https://hardware.redhat.com/show.cgi?id=181936>

Summary

- *Version:* 3
- *Category:* Component/Peripheral
- *Platforms:* All

Additional Comments

No additional comments provided

Additional Certification Notes

No additional certification notes provided
