

TOLEDO EDISON  
DAVIS-BESSE NUCLEAR POWER STATION UNIT NO. 1  
SEISMIC CATEGORY I PIPING  
SYSTEM SUPPORT AND HANGER DISCREPANCIES

-- SUMMARY REPORT --

REVISION 17

NOVEMBER 25, 1985

8512170217 851202  
PDR ADOCK 05000346  
G PDR

## TABLE OF CONTENTS

### Dispositioned Footnotes

Section 1.0	Auxiliary Feedwater Pump Turbine Steam Supply Piping System
Section 2.0	Auxiliary Feedwater System
Section 3.0	Low Pressure Injection System
Section 4.0	High Pressure Injection System
Section 5.0	Borated Water Storage Tank Supply System
Section 6.0	Service Water System
Section 7.0	Containment Sump - ECCS Supply System
Section 8.0	Hydrogen Dilution System
Section 9.0	Pressurizer Relief System
Section 10.0	Pressurizer Surge System
Section 11.0	Containment Spray System
Section 12.0	Miscellaneous Waste Drain System
Section 13.0	Spent Fuel Pool Piping System
Section 14.0	Makeup Water Treatment System
Section 15.0	Pressurizer Spray System
Section 16.0	Reactor Coolant System
Section 17.0	Quench Tank Drain System
Section 18.0	Component Cooling Water System
Section 19.0	Steam Generator Drain System
Section 20.0	Containment Building Vent System
Section 21.0	Refueling Canal System
Section 22.0	Hanger Location Discrepancies
Section 23.0	Main Feedwater System
Section 24.0	Steam Generator Vent System
Section 25.0	Pressurizer Sample System

DISPOSITIONED FOOTNOTES

- (1) Meets interim allowables, but not long-term allowables.
- (2) Re-work is necessary to meet long-term allowables.
- (3) Meets long-term allowables.
- (4) Meets long-term allowables, but nevertheless re-work will be completed.

SECTION 1.0

AUXILIARY FEEDWATER PUMP

TURBINE STEAM SUPPLY PIPING SYSTEM



REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H147	SWAY STRUT PULLED FROM WALL	03/01/85	85-0016	Y	SJO
A3	LOOSE ANCHOR BOLTS NUTS	03/13/85	85-0018	Y	GNF
EBD-19-H34	DEFORMED STANCHION	03/13/85	85-0019	Y	GNF
EBD-19-H32	NON-CODE WELD ON WRAPPER PLATE TO PIPING WELD	03/27/85	85-0026	Y	SJO
EBD-19-H58	DEFECTIVE MECHANICAL SNUBBER	04/11/85	85-0032	Y	SJO
EBD-19-H58	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	04/11/85	8685-79	Y	SJO
EBD-19-H144	HYDRAULIC SNUBBER PISTON ROD BROKEN	04/18/85	85-0038	Y	SJO
EBD-19-H136	TWELVE (12) ANCHOR BOLTS IN LIEU OF SEVEN (7) SPECIFIED	04/30/85	85-0042	Y	GNF
EBD-19-H54	WELD DETAIL INACCURATE	04/30/85	85-0043	Y	GNF
EBD-19-H142	LOOSE ANCHOR BOLT NUT	05/01/85	85-0045	Y	GNF
EBD-19-H51	WALL INTERFERENCE WITH SUPPORT MEMBER	05/08/85	85-0052A	Y	RAA
EBD-19-H50	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H49	SWAY STRUT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H142	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H66	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y	GNF
EBD-19-H132	LOOSE ANCHOR BOLTS, BASEPLATE GAP	05/16/85	85-0019A	Y	GNF
EBD-19-H32	LOOSE ANCHOR BOLTS, SNUBBER PIPE CLAMP MIS-ALIGNED, WASHERS MISSING	05/16/85	85-0019A	Y	SJO
EBD-19-H28	PIPE SADDLES DEFORMED	05/16/85	85-0019A	Y	SJO
EBD-19-H25	SHEARED BOLT	05/16/85	85-0019A	Y	SJO
EBD-19-H67	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y	GNF
EBD-19-H135	LOOSE ANCHOR BOLTS, ONE BOLT DID NOT TORQUE	05/16/85	85-0019A	Y	GNF
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED	05/16/85	85-0019A	Y	SJO
EBD-19-H26	WALL CRACK	05/16/85	85-0019A	Y	SJO

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H145	SWAY STRUT JAM NUT LOOSE, LOOSE ANCHOR BOLT	05/17/85	85-0067	Y	SJO
EBD-19-H62	SWAY STRUT JAM NUT LOOSE	05/17/85	85-0068	Y	SJO
EBB-2-H20	SUPPORT NOT SHOWN ON HANGER LOCATION DRAWING	05/17/85	85-0069	Y	SJO
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED, LOOSE ANCHOR BOLTS	05/17/85	85-0070	Y	SJO

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H51	ANCHOR BOLT INSTALLED AT AN ANGLE, BASEPLATE GAP	04/30/85	85-0044	Y	GNF
EBD-19-H59	BOLTS LONGER THAN SPECIFIED, GROUT 2" THICK IN LIEU OF 1"	05/02/85	85-0046	Y	GNF
EBD-19-H59	REMOTE RESERVOIR NOT SHOWN ON DRAWING	05/08/85	85-0048	Y	RAA
EBD-19-H51	INCORRECT SPRING SETTING	05/08/85	85-0052	Y	RAA
EBD-19-H50	CHIPPED CONCRETE AROUND BASEPLATE	05/08/85	85-0053	Y	GNF
EBD-19-H143	FIREPROOFING BROKEN AWAY	05/09/85	85-0054	Y	TWH
EBD-19-H147	ANCHOR BOLT INSTALLED AT AN ANGLE	05/09/85	85-0055	Y	GNF
EBD-19-H154	SHIM SIZE NOT PER DRAWING	05/09/85	85-0056	Y	RAA
EBD-19-H62	FIREPROOFING BROKEN AWAY	05/09/85	85-0057	Y	TWH
EBD-19-H60	WRONG SIZE SPRING HANGER	05/09/85	85-0058	Y	RAA
EBD-19-H141	BOOT SEAL TORN	05/10/85	85-0059	Y	TWH
EBD-19-H55	BASEPLATE ANCHOR BOLT WASHERS SIZE QUESTIONABLE	05/10/85	SR85-79	Y	GNF
EBD-19-H58	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	05/10/85	SR85-79	Y	SJO
EBD-20-H1	LOOSE ANCHOR BOLTS NUTS, BASEPLATE GAP	05/16/85	85-0064	Y	GNF
A3	BASE PLATE GAP	05/16/85	85-0065	Y	GNF
EBD-19-H147	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H142	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H145	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H144	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H70	SWAY STRUT JAM NUT LOOSE	05/21/85	85-0092	Y	SJO
EBD-19-H14	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y	GNF
EBD-19-H20	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y	GNF
EBD-19-H38	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y	SJO
EBD-19-H39	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y	SJO

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H132	BOLTS USED NOT REFLECTED ON DRAWING	05/21/85	85-092	Y	GNF
A221	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-17-H39	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H28	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H34	MISSING FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H39	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H35	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H29	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H21	TWO (2) BOLTS NOT MARKED FOR TORQUE TEST	05/21/85	SR85-79	Y	GNF
EBD-20-H1	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/21/85	SR85-79	Y	SJO
EBD-19-H25	UPPER GUIDE ANGLE BENT	05/22/85	85-0071	Y	RAA
EBD-19-H132	FIREPROOFING BROKEN	05/22/85	85-0072	Y	TWH
EBD-19-H133	FIREPROOFING BROKEN	05/22/85	85-0072	Y	TWH
EBD-19-H74	FLASHING MISSING ON INSULATION	05/24/85	85-0074	Y	SJO
EBD-19-H13	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H13A	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H15	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H16	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H19	THREE (3) OF FOUR (4) PINS HAVE NAILS IN LIEU OF COTTER KEYS	05/24/85	85-0074	Y	SJO
EBD-19-H32	SNUBBER PIPE CLAMP MIS-ALIGNED, SNUBBER JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H26	INSUL DWN, STRAPS LOOSE & MISSING	05/24/85	85-0074	Y	SJO
EBD-19-H33	SWAY STRUT ROTATES ON EXTENSION THREADS NOT BUSHING	05/24/85	85-0074	Y	SJO
EBD-19-H36	STRAPS LOOSE, INSULATION DOWN, (ALSO H37)	05/24/85	85-0074	Y	SJO

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H37	CORRESPONDS TO EBD-19-H36 ON 85-0074	05/24/85	85-0074	Y	SJD
EBD-19-H20	WASHER MISSING, NO FREE ROTATION ON BUSHING	05/24/85	85-0074	Y	SJD
EBD-19-H133	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/24/85	85-0074	Y	SJD
EBD-19-H65	SWAY STRUT MIS-ALIGNED	05/29/85	85-0082	Y	SJD
EBD-19-H24	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H22	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H135	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H132	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H133	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H65	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H66	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H6	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H8	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H10	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H67	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H131	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H150	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H23	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H74	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H21	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H26	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H12	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
A362	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H72	BASEPLATE GAP	06/06/85	85-0090	Y	GNF

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H55	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H49	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H52	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H53	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H54	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H50	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H56	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H51	BASEPLATE GAP	06/06/85	85-091	Y	GNF
EBD-19-H47	CONCRETE CRACKS	06/06/85	SR85-74	Y	GNF
EBD-19-H48	CONCRETE CRACKS	06/06/85	SR85-74	Y	GNF
AJ	CONCRETE CRACKS	06/06/85	SR85-74	Y	GNF
EBD-19-H141	CONCRETE CRACKS	06/06/85	SR85-74	Y	GNF
EBD-19-H133	ANGLE NOT WELDED PER DRAWING	07/10/85	85-0092A	Y	SJO
EBD 19-H132	WASHERS #1 x #2 DISHED (CONCAVE)	07/11/85	85-0092A	Y	GNF

REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H49	ANCHOR BOLTS PULLED OUT	05/14/85	85-0060	Y	GNF
EBD-19-H136	ONE INACTIVE BOLT	05/15/85	85-0042A	Y	GNF
EBD-19-H49	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/16/85	85-0093	Y	SJO
EBD-19-H52	SNUBBER REAR BUSHING NOT FREE TO MOVE	05/16/85	SR85-79	Y	SJO
EBD-19-H47	BASEPLATE ANCHOR BOLT WASHERS NOT SHOWN ON DRAWING	05/16/85	SR85-79	Y	GNF
EBD-19-H67	CLEARANCE GAP ON RESTRAINT NOT PER DRAWING	05/21/85	85-0092	Y	SJO
EBD-19-H150	PIPE CLAMP BOLTS LOOSE	05/21/85	85-0092	Y	SJO
EBD-19-H39	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y	SJO
EBD-19-H38	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y	SJO
EBD-19-H17	SWAY STRUT END BEARING DOES NOT MOVE FREELY	05/23/85	85-0092	Y	SJO
EBD-19-H14	CONCRETE AROUND BASEPLATE IS CHIPPED	05/23/85	SR85-73	Y	GNF
EBD-19-H132	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H22	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H20	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H12	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H26	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H67	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H68	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H65	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H148	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/05/85	85-0088	Y	SJO
EBD-20-H1	BROKEN FIREPROOFING	06/05/85	85-0089	Y	TWH
EBD-19-H154	BROKEN FIREPROOFING	06/05/85	85-0089	Y	TWH
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/06/85	85-0092	Y	SJO



REV. 17

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H18	SWAY STRUT ROTATES ON THREADS	06/06/85	85-0092	Y	SJO
EBD-19-H13A	SWAY STRUT EYELET CONTACTS PIPE CLAMP	06/11/85	85-0094	Y	SJO
EBD-19-H16	SWAY STRUT JAM NUT LOOSE, PIPE CLAMP LOOSE	06/11/85	85-0094	Y	SJO



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A004	NUT LOOSE	08/02/85	85-0124	USE-AS-IS (1), REWORK-ADD 2 PLATES AND 2 ANCHORBOLTS
EBD-19-H131	NUTS INSTALLED IMPROPERLY	08/21/85	85-0138	USE-AS-IS (3)
3A-EBD-19-H81	NON-STANDARD PIPE CLAMP, SWAY STRUT DIM INACCURATE	09/05/85	85-0220	USE-AS-IS (3)
3A-EBD-19-H80	WLDs UNSZ, BOLT SPACING OFF	09/06/85	85-0249	USE-AS-IS (3)
3A-EBD-19-H78	3/8" PLATE IN LIEU OF 1/2", INTERFERENCE WITH DUCT SUPPORT, WLDs UNSZ	09/06/85	85-0252	USE-AS-IS (3)
3A-EBD-19-H79	WLD DEFECTS & UNSZ	09/07/85	85-0274	USE-AS-IS (3)
3A-EBD-19-H134	NO INSPECTION HOLE IN STRUT, NON STD PIPE CLAMP	09/07/85	85-0282	USE-AS-IS (3)
3A-EBD-19-H100	3/4" STUD IN LIEU OF RED HD WLDs NOT PER DWG	09/09/85	85-0292	USE-AS-IS (3)
A-309	LOOSE BOLT	09/09/85	85-0296	USE-AS-IS (3)
3A-EBD-19-H103	WLD UNSZ, MEMBER SIZE INCORRECT	09/09/85	85-0301	USE-AS-IS (3)
3A-EBD-19-H128	BASEPLATE GAP, WELDS NOT PER DWG	09/09/85	85-0302	USE-AS-IS (3)
3A-EBD-19-H102	3/8" PLATE IN LIEU OF 1/2", WLD NOT PER DWG, WLD UNSZ	09/09/85	85-0303	USE-AS-IS (3)
3A-EBD-19-H84	WGRS MISSING, WLDs NOT PER DWG, GROUT BROKEN	09/09/85	85-0304	USE AS IS (3)
3A-EBD-19-H101	WLDs UNSZ, WLD NOT PER DWG, MISSING JAM NUTS, THDS STAKED, CLMP TWIST	09/09/85	85-0308	USE-AS-IS (3), REWORK-ADJ. CLAMP (4)
3A-EBD-19-H124	MISSING JAM NUT, CHIPPED CONCRETE	09/10/85	85-0310	USE-AS-IS (3)
3A-EBD-19-H125	WLDs UNSZ, WLD DETAILS INCORRECT	09/10/85	85-0311	USE-AS-IS (3)
3A-EBD-19-H105	THDS STAKED, MISSING JAM NUT, STRUT DIM INCORRECT, WLD UNSZ,	09/10/85	85-0312	USE-AS-IS (3)
3A-EBD-19-H83	DWG INCORRECT & LACKS DIMENSIONS, WLD UNSZ, WLD DETAILS INCORRECT	09/10/85	85-0313	
3A-EBD-19-H76	NON-STD CLAMP, WLD NOT PER DWG, MEMBER DEFLECTED	09/10/85	85-0319	USE-AS-IS (3)

| 17

| 17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
3A-EBD-19-H106	ROD END BUSHING BINDING, LOCAT DIM INCOR, WLD UNDSZ	09/10/85	85-0325	USE-AS-IS (3)
3A-EBD-19-H65	ROD EYE BUSHING BINDING LOCK RING ON LOAD BOLT MISSING	09/10/85	85-0330	REWORK-ADJUST CLAMP, ADD RING (4)
3A-EBD-19-H104	JAM NUTS & SPACER MISSING, WLD UNDSZ, THDS STAKED	09/10/85	85-0332	USE-AS-IS (3), REWORK-ADJ. PIVOT (4)
3A-EBB-2-H36	WLD SZS NOT ON DWG, NON-STD CLAMP, WLD UNDSZ, GROUT THKNSS, SPACER LOOSE	09/10/85	85-0334	USE-AS-IS (3)
3A-EBD-19-H77	THDS STAKED, WLD ALL AROUND VS 2 SIDES, MISSING JAM NUT, NON-STD CLAMP	09/10/85	85-0335	USE-AS-IS (3)
3A-EBB-2-H37	MEMBER SZ & LOC DIM NOT PER DWG, WLD DETAILS INCOR	09/10/85	85-0336	USE-AS-IS (3)
3A-EBD-19-H127	BASEPLATE GAP, MISSING WLDS, INTERFERENCE, DIM INCOR	09/10/85	85-0337	
3A-EBD-19-H123	JAM NUTS MISSING	09/10/85	85-0338	USE-AS-IS (3)
3A-EBD-19-H85	WLDS NOT PER DWG, STRUCT MEMBER ANGLE INCOR	09/10/85	85-0340	USE-AS-IS (3)
3A-EBB-2-H19	WLD UNDSZ, BASEPLATE GAP	09/11/85	85-0342	USE-AS-IS (3)
3A-EBD-19-H130	BASEPLATE GAP, WLD UNDSZ	09/11/85	85-0346	USE-AS-IS (3)
3A-EBD-19-H131	WLD UNDSZ	09/11/85	85-0347	USE-AS-IS (3)
3A-EBB-2-H30	MOD. CLAMP, NO JAM NUT, PLATE GAP, MOVE WELD	09/11/85	85-0348	USE-AS-IS (3)
3A-EBD-19-H151	MOREWELD, WELD DETAIL & UNDERSIZE, NO WASHER	09/12/85	85-0349	USE-AS-IS (3), REWORK-ADJUST (4)
3A-EBB-2-H27	JAM NUT ONE END, THREAD STAKED, UNDERSIZE WELD, MOD. CLAMP	09/11/85	85-0352	USE-AS-IS (3)
3A-EBD-19-H126	THINNER PLATE, WELD DETAIL & UNDERSIZE, CLEARANCE	09/11/85	85-0353	USE-AS-IS (3)
3A-EBD-19-H129	PLATE GAP, WELD DETAIL	09/11/85	85-0354	USE-AS-IS (3), REWORK- REGROUT UNDER BASEPLATE (4)
3A-EBD-19-H87	NO LOCKNUT, THD. STAKED, STIFF PL. NOT ON DWG	09/11/85	85-0358	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H86	CLEARANCE	09/11/85	85-0361	USE-AS-IS (3)
3A-EBD-19-H82	BAR ATTACHED TO SUPPORT, NO LOCKNUTS	09/11/85	85-0362	USE-AS-IS (3)
3A-EBD-19-H75		09/12/85	85-0363	USE-AS-IS (3)
3A-EBB-2-H21	ADD'L WELD, WELD DETAIL & UNDERSIZE, DIMENSIONS, CLEARANCE, GROUT THICK, EMBED	09/12/85	85-0364	USE-AS-IS (3)
3A-EBD-19-H108	NO WASHER, NO JAM NUT, THREAD STAKED	09/12/85	85-0370	USE-AS-IS (3)
3A-EBB-2-H22	WELD SIZE, TRVL SCALE MISSING, PLATE GAP, CONC. GOUGE	09/12/85	85-0372	USE-AS-IS (3)
3A-EBB-2-H23	WELD DETAIL, CLEARANCE, PL. NOT DETAILED	09/12/85	85-0373	USE-AS-IS (3)
3A-EBB-2-H26	WELD UNDERSIZE, PLATE GAP	09/12/85	85-0374	USE-AS-IS (3)
3A-EBB-2-H28	PLATE GAP, WELD UNDERSIZE	09/12/85	85-0378	USE-AS-IS (3)
3A-EBB-2-H29	NON-STD. CLAMP, THDS STAKED, ALL-AROUND VS. 2 SIDE WLD, BASEPLATE GAP	09/12/85	85-0380	USE-AS-IS (3)
3A-EBB-2-H31		09/12/85	85-0381	USE-AS-IS (3), REWORK-REPLACE LOAD BOLT (4)
3A-EBD-19-H151	WLDG UNDSZ, WSHRS MISSING	09/12/85	85-0383	USE-AS-IS (3), REWORK-REPLACE DAMAGED COMPONENTS (4)
3A-EBD-19-H107	JAM NUT LOOSE, END BUSHING JAMMED, WLDG MISSING & UNDERCUT	09/13/85	85-0385	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT, REPLACE ROD END (4)
3A-EBB-2-H16	WLD DEFECTS, ITEMS NOT PER SPEC, BASEPLATE DIM INCORRECT	09/13/85	85-0390	USE-AS-IS (3)
3JC-HCC-91-H16	WLD SZ NOT ON DWG, NO GROUT, WSHR MISSING	09/13/85	85-0391	USE-AS-IS (3)
3A-EBB-2-H18	WELD DEFECTS	09/13/85	85-0393	USE-AS-IS (3)
3A-EBB-2-H17	BASEPLATE GAPS, WLD DEFECTS	09/13/85	85-0394	USE-AS-IS (3)
3A-EBB-2-H10	WLD DEFECTS, CONCRETE CRACKS	09/13/85	85-0396	USE-AS-IS (3)
3A-EBD-19-H120	DETAIL 'A' INCOR DIM, NO WELD VS WELD PRESENT	09/14/85	85-0398	USE-AS-IS (3)
3A-EBD-19-H118	THD ENGAGEMENT, STRUT JAMMED	09/14/85	85-0399	USE-AS-IS (3), REWORK-REPLACE BUSHING (4)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H117	THDS STAKED, ANCHOR BOLTS LACK THD ENGAGEMENT	09/14/85	85-0401	USE-AS-IS (3)
33A-HCB-2-H111	WSHR MISSING, WLDS NOT PER DWG & UNDSZ	09/14/85	85-0414	USE-AS-IS (3)
3A-EBD-19-H122	ITEM DIM INCORRECT, WLDS UNDSZ & NOT PER DWG	09/14/85	85-0421	USE-AS-IS (3)
3A-EBD-19-H119	WLDS UNDSZ & NOT PER DWG	09/14/85	85-0422	USE-AS-IS (3)
3A-EBD-19-H110	STANCHION CLEARANCE, WELDS NOT PER DWG	09/14/85	85-0429	
3A-EBD-19-H153	THDS STAKED, NO SIGHT HOLE IN TOP OF STRUT	09/16/85	85-0431	USE-AS-IS (3)
3A-EBB-2-H8	THDS STAKED ON SWAY STRUT JAM NUT	09/16/85	85-0432	USE-AS-IS (3)
3A-EBB-2-H9		09/16/85	85-0433	USE-AS-IS (3)
3A-EBB-2-H6	WSHRS MISSING, STRUT BOUND, THDS STAKED, BASEPLATE GAP	09/16/85	85-0434	USE-AS-IS (3), REWORK-INSTALL WSHRS & ADJUST TOLERANCES (4)
3A-EBB-2-H7	BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0435	USE-AS-IS (3)
3A-EBD-19-HA39	BASEPLATE GAP UNACCEPTABLE DIMENSION NOT PER DWG	09/16/85	85-0436	USE-AS-IS (3)
3A-EBD-19-HA38	WELDS UNDSZ	09/16/85	85-0437	USE AS IS (3)
3A-EBB-2-H25	BASEPLATE NOT PER DWG BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0438	USE-AS-IS (3)
3A-EBD-19-H152	BASEPLATE GAP UNACCEPTABLE THDS STAKED, 'S' DIM NOT PER SPEC	09/16/85	85-0439	USE-AS-IS (3)
3A-EBD-19-H109	BASEPLATE DIM UNDSZ, STANCHION CLEARANCE NOT PER DWG, WLDS UNDERCUT & NOT PER DWG	09/17/85	85-0440	
3A-EBD-19-H116	ALL-ROUND WLDS NOT POSS, STRUT BOLT HAS BEEN STAKED	09/17/85	85-0441	USE-AS-IS (3)
3A-EBB-2-H3	WLDS NOT PER DWG, THDS STAKED ON SWAY STRUT JAM NUT, STRUT BOUND UP	09/17/85	85-0450	USE-AS-IS (3), REWORK-REPLACE CORRODED END (4)
3A-EBB-2-H2	THDS STAKED, STRUT BOUND UP, ITEM #2 HAS DEFORMED AREA	09/17/85	85-0451	USE-AS-IS (3), REWORK-REALIGN STRUT (4)
3A-EBD-19-H91	ITEM #1 HAS STRUCTURAL DAMAGE, WLDS UNDSZ	09/17/85	85-0460	USE-AS-IS (3)
3A-EBD-19-H89	WLDS CRACKED, ITEM #4 NOT PER DWG, WLD UNDSZ	09/17/85	85-0461	USE-AS-IS (3), REWORK-REPLACE CRACKED WELD (4)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBB-2-H5	SWAY STRUT BOUND UP, THDS STAKED	09/17/85	85-0465	USE-AS-IS (3)
3A-EBB-2-H4	JAM NUTS LOOSE, WLD UNDSZ	09/17/85	85-0466	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT (4)
3A-EBB-2-H7A	THDS STAKED, PIPE CLAMP LOOSE, WLD UNDSZ	09/17/85	85-0467	USE-AS-IS (3), REWORK-TIGHTEN LOOSE NUTS ON CLAMP (4)
3A-EBB-2-H6A	WSHRS INSTALLED WRONG, THDS STAKED, BASEPLATE GAP UNACCEPTABLE	09/17/85	85-0468	
3A-EBB-2-H12	PIPE CLAMP MIS-ALLIGNED, WLD MISSING, THDS STAKED	09/17/85	85-0470	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
3A-EBB-2-H14	CONCRETE FALLING OUT, WLD UNDSZ & NOT PER DWG	09/17/85	85-0471	
3A-EBB-2-H13	STRUT BOUND UP, THDS STAKED, WLD NOT PER DWG, "W" DIM INCORRECT	09/17/85	85-0472	USE-AS-IS (3), REWORK-REPLACE ROD END (4)
3A-EBB-2-H15	WLD UNDSZ, ITEM #7 INCORRECT DIM	09/17/85	85-0473	USE-AS-IS (3)
3A-EBB-2-H11	JAM NUT LOOSE, STRUT BOUND UP, WLD NOT PER DWG	09/17/85	85-0474	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT (4)
3A-EBD-19-H88	BASEPLATE GAP UNACC, LOCK NUTS MISSING, THDS STAKED	09/17/85	85-0475	USE-AS-IS (3)
3A-EBB-2-H1	SWAY STRUT BOUND UP & THDS STAKED, WLD NOT PER DWG	09/17/85	85-0478	
3A-EBB-2-H20	NON-STD CLAMP INSTALLED, WLD NOT PER DWG	09/17/85	85-0484	
3A-EBD-19-H121	BOLT NOT VERT, BOLT ROTATES, DIM MISSING FROM DWG, WLD NOT PER DWG, DIM DIFFERENCES	09/18/85	85-0489	
3A-EBD-19-H96	NO LOCK NUTS, SNB-CLAMP ORIENTATION EXCEEDS RECOM	09/18/85	85-0494	USE-AS-IS (3), REWORK-ADJUST (4)
3A-EBD-19-H94	BOM DESCRIP, WLD NOT COMPLETE PER DWG, CLEARANCE 1/32" VS 1/16"	09/18/85	85-0496	USE-AS-IS (3)
3A-EBD-19-H95	LOCKNUTS MISSING	09/18/85	85-0497	USE-AS-IS (3)
3A-EBD-19-H99	BASEPLATE GAPS, STRUT OFFSET, MISSING LOCK NUT, STRUT BODY LOOSE	09/18/85	85-0498	USE-AS-IS (3), REWORK-ADJUST CLAMP AND STRUT (4)



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H98	WLD MISSING ON FLG, WLD UNDSZ, CLEARANCE NOT PER DWG	09/18/85	85-0499	USE-AS-IS (3)
6C-EBD-14-H23A	BASEPLATE DIM NOT ON DWG, SWAY STRUT BOUND, PIPE CLAMP MIS-ALIGNED WITH STRUT	09/18/85	85-0507	USE-AS-IS (3), REWORK-ADJUST (4)
3A-EBD-19-H113	BASEPLATE DIM INCOR, WLD UNDSZ, CLEARANCE NOT PER DWG, UNDERCUT	09/18/85	85-0508	USE-AS-IS (3)
3A-EBD-19-H115	DIM PROBLEMS, WLD 3-SIDES VS ALL-ROUND ON LUGS, WLD UNDSZ	09/18/85	85-0509	USE-AS-IS (3)
3A-EBD-19-H97	STANCHION DAMAGED	09/18/85	85-0510	USE-AS-IS (3)
3A-EBD-19-H93	THDS STAKED, STRUT OFFSET, LOCKNUT MISSING, WLDS NOT PER DWG, 3 WSHRS/ANCHOR BLT	09/18/85	85-0511	USE-AS-IS (3), REWORK-ADJUST (4)
3A-EBD-19-H90	WLD UNDSZ	09/18/85	85-0512	USE-AS-IS (3)
6C-EBD-14-H71	BASEPLATE GAP	10/07/85	85-0522	USE-AS-IS (3)
3A-EBD-19-H112	TAP BOLTS REPLACED BY STUDS, WLD DETAIL, DIMENSION PROBLEMS	09/20/85	85-0545	USE-AS-IS (3)
M-1114-H16	DIM NOT PER DWG, STRUT BOUND UP	09/25/85	85-0685	USE-AS-IS (3)
M-1114-H3	WLD & DIM NOT PER DWG	09/25/85	85-0688	USE-AS-IS (3)
M-1114-H5	LOCKNUT & BOLT MISSING, DIM NOT PER DWG	09/25/85	85-0689	USE-AS-IS (3)
M-1114-H40	STRUT BOUND UP	09/25/85	85-0704	USE-AS-IS (3)
M-1114-H46	BASEPLATE GAP, DIMEN INCORR	09/23/85	85-0706	
M-1114-H22	NOT FULL BASEPLATE BEARING, DIM & WLDS NOT PER DWG, UNACC BOLT EDGE DISTANCE	09/25/85	85-0707	
M-1114-H2	DIM NOT PER DWG, LOCKWIRES NOT INSTALLED	09/25/85	85-0708	USE-AS-IS (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H1	WLD NOT PER DWG, LOCKWIRE NOT INSTALLED	09/25/85	85-0713	USE-AS-IS (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H6	DIMEN, WELD, & CLEARANCE NOT PER DWG.	09/26/85	85-0727	USE-AS-IS (3)
M-1114-H7	BOLT ANGLED, MISSING NUTS.	09/26/85	85-0728	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114-H47	DIMEN NOT PER DWG, MISSING LOCKWIRE, ROTATED CLAMP.	09/26/85	85-0729	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
M-1114-H4	PIPE ELEVATION INCORRECT, SPACERS ADDED TO CLAMP	10/01/85	85-0747	USE-AS-IS (3)
M-1114-H8	DIMEN & WELDS NOT PER DWG.	09/27/85	85-0767	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
M-1114-H23	DIMEN & WELDS NOT PER DWG.	09/28/85	85-0775	USE-AS-IS (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H24	DIMEN, WELDS, & BOLT NOT PER DWG, BOLT SPACING VIOLATION.	09/28/85	85-0776	USE-AS-IS (3)
M-1114-H25	DIMEN & WELD NOT PER DWG, MISSING LOCKWIRE.	09/28/85	85-0788	USE-AS-IS (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H26	SNUBBER UNSATISFACTORY.	09/30/85	85-0796	USE-AS-IS (3) WORK-INSTALL LOCKWIRE & ADJUST SNUBBER
M-1114-H29	WELDS & DIMEN NOT PER DWG, BRACKET NOT ROTATED PER DWG.	09/30/85	85-0798	
M-1114-H37	WLD UNDSZ, MISSING SPACER, BASEPLATE BEARING UNSAT	10/03/85	85-0839	USE-AS-IS, REWORK-INSTALL SPACER (4)
M-1114-H13	BOLT SPACING VIOLATION, BASEPLATE BEARING UNSAT	10/03/85	85-0840	USE-AS-IS (3)
M-1114-H36	BASEPLATE BEARING UNSAT	10/03/85	85-0841	USE-AS-IS (3)
M-1114-H11	BOLT SPACING NOT PER SPEC, BASEPLATE BEARING UNSAT & NOT PER DWG	10/03/85	85-0843	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT (4)
M-1114-H32	WLD NOT PER DWG, BOLT #4 REQUIRED & FULL TURNS	10/03/85	85-0844	USE-AS-IS (3)
M-1114-H15	BASEPLATE GAP	10/07/85	85-0922	USE-AS-IS (3)
M-1114-H38	UNDSZ WLD, INTERFERENCE WITH STRUT, MIN. BOLT SPACING VIOLATION	10/07/85	85-0944	USE-AS-IS (3)
M-1114-H41	BASEPLATE GAP, WLD UNDSZ, STRUT DIMEN. INCORRECT	10/07/85	85-0945	USE-AS-IS (3)
3A-EBD-19-H147	3/4" BOLTS VS. 1/2", BASEPLATE GAP, WLD UNDSZ, SIGHT HOLE MISSING	10/07/85	85-0946	USE-AS-IS (3)

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114-H17	BASEPLATE GAP, WLD UNDSZ, MIN BOLT SPACING VIOLATION	10/07/85	85-0947	USE-AS-IS (3), REWORK-SHIM BASEPLATE (4)
3A-EBD-19-H133	WLD DETAIL INCORRECT, PIPE CLAMP WASHERS TOO THICK, GAP IN FIREPROOFING	10/08/85	85-0955	USE-AS-IS (3), REWORK-RFR FIREPROOFING, INSTALL SPACER (4)
3A-EBD-19-H36	WLD DETAIL NOT ON DWG, WLD DETAIL INCORRECT	10/08/85	85-0956	USE-AS-IS (3)
3A-EBD-19-H132	3/4" BOLT VS 1/2", ADDITIONAL WASHER PLATES, MEMBER SIZE INCORRECT, WELD DETAIL	10/08/85	85-0957	
M-1114-H20	WLD DETAIL INCORRECT, LOOSE JAM NUT, BOLT MIN. DIST. VIOLATION	10/08/85	85-0959	USE-AS-IS (3), REWORK-TIGHTEN LOCKNUT (4)
A-221	WEEP HOLE CUT IN STANCHION, FIREPROOFING CRACKED, DIMEN INCORRECT	10/08/85	85-0962	USE-AS-IS (3), REWORK-REPAIR FIRE PROOFING (4)
3A-EBD-19-H47	DIMENSIONS WELD DETAIL & UNDERSIZE	10/09/85	85-0975	USE-AS-IS (3)
3A-EBD-19-H136	WELD DETAIL	10/09/85	85-0976	
3A-EBD-19-H53	DIMENSIONS WELD SYMBOL WELD DETAIL & SIZE	10/09/85	85-0977	USE-AS-IS (3)
3A-EBD-19-H48	WELD DETAIL & SIZE ANCHOR EMBED	10/09/85	85-0978	USE-AS-IS (3)
3A-EBD-19-H49	DIMENSIONS GUSSET INSTALLED HILTI VS. SHELL TYPE	10/09/85	85-0979	USE-AS-IS (3)
3A-EBD-19-H51	C.L. SETTING	10/09/85	85-0980	USE-AS-IS (3)
3A-EBD-19-H13	DIMENSION WELD DETAIL & UNDERSIZE THD STAKED BOLT LOOSE ON STRUT	10/09/85	85-0981	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
3A-EBD-19-H54	WELD DETAIL	10/09/85	85-0982	USE-AS-IS (3)
3A-EBD-19-H52	PL GAP DIMENSIONS	10/09/85	85-0985	USE-AS-IS (3)
3A-EBD-19-H50	WELD DETAIL PL GAP HILTI VS. SHELL	10/09/85	85-0987	

17

17



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H13A	DIMENSIONS, THD STAKED, WELD DETAIL	10/09/85	85-0993	USE-AS-IS (3)
3A-EBD-19-H57	WELD DETAIL	10/09/85	85-0994	USE-AS-IS (3)
3A-EBD-19-H23	WELD DETAIL & SIZE, DIMENSION, BOLT SPACE	10/09/85	85-1000	USE-AS-IS (3), REWORKGROUT OPEN HOLE (4)
3A-EBD-19-H20	WELD DETAIL, B/M PROBLEM, THREAD STAKED, DIMENSION	10/09/85	85-1001	USE-AS-IS (3)
3A-EBD-19-H56	DIMENSION CLEARANCE ANCHOR BOLT SPACE	10/09/85	85-1002	USE-AS-IS (3)
3A-EBD-19-H38	WELD DETAIL & SIZE	10/09/85	85-1007	USE-AS-IS (3)
3A-EBD-19-H22	WLD5 UNDSZ, PLATE DIMEN	10/09/85	85-1008	
M-1114-H19	DIMENSION PL. GAP VAM NOT LOOSE SPACER THREAD ENGAGE.	10/09/85	85-1009	USE-AS-IS (3), REWORK-TGHT LCKNT, INST SPACR, ADJ CLMP (4)
M-1114-H43	PL. GAP DIMENSION NOT LOOSE	10/09/85	85-1010	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
M-1114-H18	DIMENSION, STRUT BUSHING NO MOVEMENT	10/09/85	85-1011	USE-AS-IS (3), REWORK-REMOVE GROUT FROM BUSHING (4)
A-362	ANCHOR BOLT SPACE, WELD SIZE	10/09/85	85-1012	USE-AS-IS (3)
3A-EBD-19-H10	PL. GAP, DIMENSION, NO PL. THICK ON DRAWING, WELD DETAIL, INTERFERE	10/09/85	85-1013	USE-AS-IS (3), REWORK-ROTATE SNIBBER (4)
3A-EBD-19-H142	3/4" BOLT VS. 1/2", PL. GAP, WELD DETAIL	10/09/85	85-1014	USE-AS-IS (3)
3A-EBD-20-H1	WELD DETAIL, THREAD STAKED	10/09/85	85-1015	USE-AS-IS (3)
3A-EBD-19-H6	B/M PROBLEM, PL. THICK, WELD DETAIL	10/09/85	85-1016	USE-AS-IS (3)
3A-EBD-20-H2	WELD DETAIL	10/09/85	85-1017	USE-AS-IS (3)
A-001	BOLT SPACE, WELD SIZE	10/09/85	85-1025	USE-AS-IS (3)
3A-EBD-19-H59	WELD DETAIL & SIZE	10/09/85	85-1026	USE-AS-IS (3)

17

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
JA-EBD-19-H9	ATTACHMENT NOT CENTERED ON PLATE, SPRING SETTINGS	10/09/85	85-1028	USE-AS-IS (3)
JA-EBD-19-H11	MEMBER LENGTH, WELD SIZES	10/09/85	85-1029	USE-AS-IS (3)
JA-EBD-19-H34	ADDITIONAL MEMBER INSTALLED	10/09/85	85-1030	USE-AS-IS (3)
JA-EBD-19-H35	SWAY STRUT PROBLEMS	10/09/85	85-1031	USE-AS-IS (3)
JA-EBD-19-H74	WELD DEFECTS, MEMBER LENGTHS ANCHOR BOLT SPACING	10/09/85	85-1032	USE-AS-IS (3)
JA-EBD-19-H25	ANCHOR BOLTS SIZE INCREASED	10/09/85	85-1033	USE-AS-IS (3)
JA-EBD-19-H33	STAKED THREADS SWAY STRUT	10/09/85	85-1034	USE-AS-IS (3)
JA-EBD-19-H30	WELD SIZES	10/09/85	85-1035	USE-AS-IS (3)
JA-EBD-19-H28	WELD SIZES, MEMBER SIZE	10/09/85	85-1036	USE-AS-IS (3)
JA-EBD-19-H32	WELD SIZE	10/09/85	85-1037	USE-AS-IS (3)
JA-EBD-19-H60	WELD SIZES & TYPES, DIMENSION CHANGES	10/09/85	85-1041	USE-AS-IS (3)
JA-EBD-19-H72	WELDS, SPRING, WASHERS AT ANCHORS	10/09/85	85-1046	USE-AS-IS (3)
M-1114-H42	BOLT SPACING, WELD & STRUT PROBLEMS	10/09/85	85-1048	USE-AS-IS (3), REWORK-REMOVE GROUT, ADD SPCR, TIGHTN NUTS (4)
JA-EBD-19-H68	DIMENSIONS & WELD SIZES	10/09/85	85-1050	USE-AS-IS (3)
M-1114-H28	DIMENSIONS & WELDS	10/10/85	85-1051	
M-1114-H27	PIPE CLAMP	10/10/85	85-1052	USE-AS-IS (3), REWORK-REPLACE BUSHING, ADJ CLAMP (4)
JA-EBD-19-H16	DIMENSIONS & STRUT PROBLEMS	10/10/85	85-1053	USE-AS-IS (3)
JA-EBD-19-H17	ADDITIONAL WELD AT STRUT BRACKET	10/10/85	85-1054	USE-AS-IS (3)
JA-EBD-19-H150	SNUBBER, BASE PLATE & WELD PROBLEMS	10/10/85	85-1055	
JA-EBD-19-H144	WELD SIZES & SNUBBER PROBLEMS	10/10/85	85-1056	USE-AS-IS (3)
JA-EBD-19-H12	DIMENSIONS, WELD SIZE, SNUBBER PROBLEMS	10/10/85	85-1065	

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H21	NO WASHERS FOR ANCHOR BOLTS	10/10/85	85-1078	USE-AS-IS (3)
3A-EBD-19-H69	WELDS AND DIMENSIONS	10/10/85	85-1079	USE-AS-IS (3)
3A-EBD-19-H71	WELDS, ANCHOR BOLTS, SNUBBER PART NO.	10/10/85	85-1083	USE-AS-IS (3)
3A-EBD-19-H15	WELD DETAIL & SIZE	10/11/85	85-1100	USE-AS-IS (3)
3A-EBD-19-H8	DIMENSIONS, B/M PROBLEM, WELD DETAIL	10/11/85	85-1101	USE-AS-IS (3)
3A-EBD-19-H141	CONC. CRACK, CLEARANCE	10/11/85	85-1102	USE-AS-IS (3)
C-800A-489	FL. GAP, DIMENSION, EDGE DIST	10/11/85	85-1113	USE-AS-IS (3)
3A-EBD-19-H149	WELD SIZE, PIN-PIN, SPACER BOLT LOOSE	10/11/85	85-1128	
3A-EBD-19-H14	STUD VS. TAP BOLT, DIMENSIONS, WELD DETAIL & SIZE, NON STD CLAMP, SPACER MISSING	10/12/85	85-1131	USE-AS-IS (3), REWORK-INSTALL WSHR (4)
3A-EBD-19-H135	HILTI VS. TAP BOLT, WELD DETAIL & SIZE, DIMENSIONS, ADDITIONAL HOLES	10/12/85	85-1132	USE-AS-IS (3)
3A-EBD-19-H145	HILTI BOLT, DIMENSIONS, WELD SIZE	10/12/85	85-1133	USE-AS-IS (3)
3A-EBD-19-H18	WELD DETAIL, DIMENSIONS, CONDUIT CONTACT	10/12/85	85-1134	USE-AS-IS (3)
3A-EBD-19-H19	WELD DETAIL, CLEARANCE W/ PIPING, ATTACH TO HGR, THREAD STAKED, NONSTD END BRACK	10/12/85	85-1135	
3A-EBD-19-H66	NOT PER DRAWING	10/14/85	85-1158	
EBD-1-H4	BEAM ATT. WELD & PIN SIZE, CLAMP BOLT	10/16/85	85-1207	
3A-EBD-19-H65	BOLT SPACING, PLATE GAPS, WELD SIZE, SPALLING	10/17/85	85-1241	
EBB-1-5-R5	1-WELD REDUCED, 1-WELD LENGTH INCREASE	10/17/85	85-1242	
EBB-1-5-R9	WELD SIZE, SNUBBER LEAK-RES. EMPTY	10/17/85	85-1246	
A-004	BASEPLATE GAPS, WELD UNDERSIZE	10/18/85	85-1282	USE-AS-IS (3)
EBB-1-H2	ADDITIONAL WELD	10/18/85	85-1284	
EBB-1-H3	WELDS UNDERSIZE, BASEPLATE SIZE, WELD SYMBOL MISSING, NUTS ARE T.W. OR THD. STK.	10/18/85	85-1287	
EBB-1-SR3	CORROSION ON SNUBBER PISTON ROD	10/18/85	85-1288	

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
EBB-1-SR5	WELD UNDERSIZE, BASEPLATE SIZES, WELD SYMBOL MISSING	10/18/85	85-1289	
EBB-1-5-R8	WELD TYPE CHANGED, RUST IS PRESENT ON SNUBBER BEARINGS PREVENTING FREE MVT.	10/19/85	85-1313	
3A-EBD-19-H67	ANCHORBOLTS 5/8" NOT 1/2", BOLT SPACING IT-2 SHORTENED 1/4", WELDS USIZED, SPALL	10/19/85	85-1326	
EBB-1-H1	PIPE CLAMP - NO SPACER, STK. THD. GAP AT SPACER	10/19/85	85-1336	
EBB-1-SR7	ADDED WELD, WELD DETAIL NOT SHOWN ON DETAIL DRAWING	10/19/85	85-1337	
EBB-1-H5	WELD DETAIL NOT ON DRAWING, WELD TYPE CHANGE, GAPS ON CLAMP NOT PER DRAWING	10/19/85	85-1338	
EBB-1-5-R4	EASE PLATE NOT PER DWG., GAP, SNUBBER LEAKING & HAS NO NUMBER	10/23/85	85-1400	
EBB-1-H3	WELDS & CLAMPS NOT PER DRAWING, STAKED THREADS	10/23/85	85-1415	
EBB-1-SR-1	SNUBBER, BASE PLATE SIZE REDUCED. SHEAR LUG WELD, WELD UNDERSIZED, A.BLT. W/3WAS	10/24/85	85-1434	
EBB-1-SR-7	WELDS UNDERSIZED, STAKED CLAMP THREAD, SNUB. MUMT.	10/24/85	85-1435	
EBB-1-H2	WELDS UNDERSIZED, NOTCHED STEEL	10/24/85	85-1436	
EBB-1-H5	WELDS UNDERSIZED, SNUBBER MVMT. & BUSHING	10/24/85	85-1437	
EBB-1-SR-8	WELDS UNDERSIZED & TYPE CHANGED, SNUBBER LEAK	10/24/85	85-1438	
EBB-1-SR-9	SNUBBER SEAL	10/24/85	85-1439	
EBB-1-H4	WELD TYPE, BEAM ATT. PIN, SPRING SIZE	10/24/85	85-1440	
EBB-1-H1	SPRING W/T. STOPS, GAPS EXCESSIVE	10/24/85	85-1441	
EBB-1-SR-4	SNUBBER LEAK, WELDS UNDERSIZED, PLATE SIZES	10/24/85	85-1447	
EBB-1-SR6	BOLT SIZES, SNUBBER MOVEMENT, WELDS SIZES	10/25/85	85-1491	
EBB-1-SR2	WELD SIZES, LOOSE NUT ON CLAMP, PLATE SIZE	10/25/85	85-1492	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
EBB-1-SR6	BOLT, DIMEN., BASEPLATE & SNUBBER NOT PER DWG.	10/28/85	85-1508	
3A-EBD-19-H61	WELD NOT PER DRAWING	10/29/85	85-1519	USE-AS-IS (3)
3A-EBD-19-H62	WELD NOT PER DRAWING	10/29/85	85-1520	USE-AS-IS (3)
EBB-1-SR2	CLAMP & GAP NOT PER DRAWING	10/29/85	85-1530	
A-200	WSHRS, DIMENSIONS, WLD DETAIL & SZ, MTG BRACKET	11/04/85	85-1660	
IF-SB-SP9A3-A4-H9	WLD DETAIL	11/19/85	85-2244	
IF-SB-SP9A3-A4-H11	DIM	11/19/85	85-2246	
IF-SB-SP9A3-A4-H10	WLD DETAIL	11/19/85	85-2247	
IF-SB-SP9A3-A4-H13	STRAP DETAIL, WLD DETAIL	11/19/85	85-2248	
IF-SB-SP9A3-A4-H14	WLD DETAIL	11/19/85	85-2249	
IF-SB-SP9A3-A4-H15	DIM, WLD DETAIL, CLEARANCE	11/19/85	85-2250	
IF-SB-SP9A3-A4-H16	DIM, WLD DETAIL, CLEARANCE	11/19/85	85-2251	
IF-SB-SP9A3-A4-H5	PLATE GAP, BOLT TYPE	11/19/85	85-2252	
IF-SB-SP9A3-A4-H6	BOLT TYPE, WLD TYPE	11/19/85	85-2254	
IF-SB-SP9A3-A4-H7	WLD DETAIL	11/19/85	85-2255	
IF-SB-SP9A3-A4-A4	WLD DETAIL	11/19/85	85-2257	
IF-SB-SP9A3-A4-H8	WLD DETAIL	11/19/85	85-2258	
IF-SB-SP9A3-A4-A5	WLD DETAIL	11/19/85	85-2259	
IF-SB-SP9A3-A4-H1	BOLT TYPE	11/19/85	85-2260	
IF-SB-SP9A3-A4-H2	BOLT TYPE, PLATE GAP	11/19/85	85-2261	
IF-SB-SP9A3-A4-A1	BOLT TYPE, PLATE GAP	11/19/85	85-2262	
IF-SB-SP9A3-A4-H3	BOLT TYPE, WLD DETAIL, CLAMP BINDING	11/19/85	85-2263	
IF-SB-SP9A3-A4-H4	BOLT TYPE	11/19/85	85-2264	

17

17

SECTION 2.0  
AUXILIARY FEEDWATER SYSTEM



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
EBD-14-H76	CONCRETE CHIPPED	05/08/85	85-0049	USE-AS-IS (3), REWORK-REGROUT (4)
EBD-14-H80	BASEPLATE GAP/CONCRETE CHIPPED	05/08/85	85-0050	USE-AS-IS (1), REWORK-ADD SHIMS
EBD-14-H90	BASEPLATE GAP	05/08/85	85-0051	USE-AS-IS (1), REWORK-ADD SHIMS
EBD-14-H54	BOLT SZ INCORRECT	05/23/85	85-0073	USE-AS-IS (3)
EBD-14-H69	LOOSE BOLT	05/23/85	85-0075	USE-AS-IS (3)
EBD-14-H68	BOLT WILL NOT TORQUE	05/28/85	85-0076	USE-AS-IS (3)
EBD-14-H67	BOLT TYPE INCORRECT	05/28/85	85-0077	USE-AS-IS (3)
EBD-14-H77	BOLT SZ & QTY INCORRECT	06/25/85	85-0102	USE-AS-IS (3), REWORK-ADD NEW ANCHORBOLTS (2)
EBD-14-H91	BOLT SZ INCORRECT	07/10/85	85-0105	USE-AS-IS (3)
EBD-14-H90	INADEQUATE WLD REPAIR OF BASEPLATE	08/22/85	85-0140	USE-AS-IS (3)
M-1155-H5	WELD ALL AROUND VS. 2 SIDES, SNUBBER BUSHINGS BINDING, BORIC ACID ACCUM.	09/03/85	85-0185	USE-AS-IS (3), REWORK-REPLACE SNUB (4)
M-1155-H4	WELDED 3 SIDES VS. 1 SIDE	09/03/85	85-0187	USE-AS-IS (3)
6C-EBB-4-H12	BASEPLATE GAP INSTALLATION CRITERIA VIOLATED	09/04/85	85-0198	USE-AS-IS (3)
6C-EBB-4-H4	WELDS UNDERSIZE, UNDERCUT, OVERLAP, CLEARANCE IS 1/32"	09/04/85	85-0202	USE-AS-IS (3)
M-1155-H8	1 WSHR NEEDED EA SIDE VS 1 WSHR 1 SIDE ACTUAL	09/04/85	85-0203	USE-AS-IS (3), REWORK-INSTALL WASHER (4)
6C-EBB-4-H3	CLEARANCES WRONG SIZE, WRONG SIZE HILTI BOLT	09/04/85	85-0204	USE-AS-IS (3)
6C-EBB-4-H16	GAP WRONG SIZE, ITEM #2 DEFORMED, WELD DEFECTS	09/04/85	85-0205	USE-AS-IS (3)
6C-EBB-4-H8	WELD UNDERCUT > 1/32", GAP WRONG SIZE	09/04/85	85-0206	USE-AS-IS (3)
6C-EBB-4-H15	BASE OF RES. LEAKING, WELDS NOT PER DWG, WELD UNDERSIZE	09/04/85	85-0207	USE-AS-IS (3), REWORK-REBUILD RES TO STOP LEAKAGE (4)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1155-H2	GAPS OVERSIZE	09/04/85	85-0210	USE-AS-IS (3)
M-1155-H3	WLDs NOT PER DWG, BASEPLATE GAPS	09/05/85	85-0216	USE-AS-IS (3)
M-1155-H1	NUTS ON PIPE CLAMP DOES NOT HAVE FULL ENGAGEMENT	09/05/85	85-0217	REWORK-TIGHTEN NUTS (4)
6C-EBB-4-H9	WLD UNDSZ, ARC STRIKE, BASE METAL REDUCTION BASEPLATE GAP, ID TAG INCORRECT	09/05/85	85-0221	USE-AS-IS (3), REWORK-REPLACE TAG (4)
6C-EBB-4-H11	ANCHORBOLTS HAVE 3/4 WASHERS, BASEPLATE GAP, ARC STRIKES, UNDERCUT >1/32"	09/05/85	85-0222	USE AS IS (3), REWORK, REMOVE ARC STRIKES & PERFORM NDE
6C-EBB-4-H10	UNDERCUT >1/32", WLD UNDSZ, POROSITY IN WELD. JAM NUT MISSING, SPACER LOOSE	09/05/85	85-0223	USE-AS-IS (3)
6C-EBB-4-H17	5/8" ANCHORBOLTS IN LIEU OF 1/2", BOLT CUT OFF, BASEPLATE UNDSZ, ARC STRIKES	09/05/85	85-0224	USE-AS-IS (3), REWORK-REMOVE ARC STRIKES (4)
6C-EBD-14-H13	WLD UNDSZ, BOLTS AT ANGLE & INCORRECT, BASEPLATE GAP, HILTI BOLTS IN LIEU OF TAP	09/05/85	85-0225	
6C-EBD-14-H97	BASEPLATE GAP, WLD UNDSZ, WELD DETAIL INCORRECT	09/06/85	85-0226	USE-AS-IS (3)
6C-EBD-14-H10	CLAMP BOLT THDS STAKED, CLAMP BOLT SPACER LOOSE, JAM NUT MISSING	09/05/85	85-0227	USE-AS-IS (3)
6C-EBD-14-H95	PIPE CLAMP NOT PER DWG, BOLT THDS NOT ENGAGED	09/05/85	85-0238	USE-AS-IS (3), REWORK-READJUST PIPE CLAMP (4)
6C-EBD-14-H1	WLD UNDSZ, UNDERCUT > 1/32"	09/06/85	85-0245	USE-AS-IS (3)
6C-EBD-14-H14	WLD UNDSZ	09/06/85	85-0260	USE-AS-IS (3)
6C-EBD-14-H4	UNDERCUT > 1/32", NUT THDS NOT ENGAGED	09/06/85	85-0265	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
6C-EBD-14-H96	WELD UNDSZ & UNDERCUT PRESENT, DOUBLE NUTTED BOLTS, JAM NUTS MISSING	09/06/85	85-0266	USE-AS-IS (3)
6C-EBD-14-H3	WLDs NOT PER DWG & UNDSZ, MISSING JAM NUTS, THDS STAKED	09/10/85	85-0270	USE-AS-IS (3)
6C-EBD-14-H2	MISSING JAM NUTS & WLD, WELD DETAIL INCORRECT	09/10/85	85-0271	USE-AS-IS (3)
6C-EBB-4-H2	WLD UNDSZ, MEMBER SZ INCOR, THDS STAKED, MSNG JAM NUT, S DIM INCOR	09/07/85	85-0280	USE-AS-IS (3)

17



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-223	WELD UNDSZ & UNDERCUT PRESENT, BASEPLATE GAP	09/07/85	85-0281	USE-AS-IS (3)
6C-EBD-14-H8	"S" DIMENSION INCORRECT, THDS STAKED, MISSING JAM NUT, WELD DETAIL INCORRECT	09/07/85	85-0283	USE-AS-IS (3)
6C-EBD-14-H6	"S" DIMENSION INCOR & SPACER LOOSE, THDS STAKED, MISSING JAM NUT	09/07/85	85-0284	USE-AS-IS (3)
6C-EBD-14-H5	WLDs NOT PER DWG, WLD UNDSZ, MISSING JAM NUT	09/07/85	85-0285	USE-AS-IS (3)
6C-EBD-14-H7	WLD UNDSZ & UNDERCUT, ARC STRIKES, WLDs NOT PER DWG, THDS STAKED, MISSING JM NTS	09/07/85	85-0286	USE-AS-IS (3)
6C-EBD-14-H12	WLD UNDSZ	09/10/85	85-0293	USE-AS-IS (3)
6C-EBD-14-H9	THDS STAKED, MISSING JAM NUTS, WLDs NOT PER DWG	09/09/85	85-0294	USE-AS-IS (3)
6C-EBB-4-H14	NONSTD CLAMP, WELD UNDERSIZE, DIMENSIONS, B.O.M PROBLEM, LOCKNUT MISSING	09/12/85	85-0375	USE-AS-IS (3)
6C-EBD-14-H34	BASEPLATE GAPS, NUTS NOT PER SPEC, NON-STD PIPE CLAMP	09/13/85	85-0384	USE-AS-IS (3), REWORK-INSTALL LOCKBUT (4)
6C-EBD-14-H35	BOTH SWAY STRUTS LOCKED & NO WSHRS. NO WELDS VS WELDS PRESENT	09/14/85	85-0400	USE-AS-IS (3), REWORK-INSTALL WASHERS (4)
6C-EBD-14-H22	WLDs NOT PER DWG, #3 WRONG DIM, NO PIN TO PIN DIM ON DWG	09/17/85	85-0469	USE-AS-IS (3)
6C-EBD-14-H19A	PIN TO PIN DIM NOT INDICATED ON DWG	09/17/85	85-0479	USE-AS-IS (3), REWORK
6C-EBD-14-H18	ITEMS INCORRECT DIM'S, WLD NOT PER DWG	09/17/85	85-0480	USE-AS-IS (3)
6C-EBD-14-H33	NO CONCRETE ANCHORS SPEC'D, ITEMS INCOR DIM, WLDs NOT PER DWG	09/17/85	85-0481	USE-AS-IS (3), REWORK-RELOCATE GUIDE ANGLES
A-246	STIFF PLATES THICKER	09/18/85	85-0485	USE-AS-IS (3)
6C-EBD-14-H23	PIN-PIN DIM NOT ON DWG	09/18/85	85-0486	USE-AS-IS (3)
6C-EBD-14-H66	ANCHOR BOLT EDGE DIST DIFF FROM DWG, BASEPLATE GAP, THDS STAKED & NOT VISIBLE	09/18/85	85-0490	USE-AS-IS (3), REWORK-ADJUST (4)
6C-EBD-14-H94	STUDS & BLTS STAKED, 'S' DIM DIFF FROM CATALOG, NO SIGHT HOLE	09/18/85	85-0491	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-EBD-14-H91	1"HILTI VS 7/8 RED HEAD, WELD NOT PER DWG	09/18/85	85-0492	USE-AS-IS (3)
6C-EBD-14-H58	THDED ROD DBL NUTS, THDED ROD VS TAP BLTS, THDS STAKED, SPACER TACKED TO CLAMP	09/18/85	85-0493	USE-AS-IS (3)
6C-EBD-14-H61	THDS STAKED, BASEPLATE THICK NOT ON DWG, WLD NOT PER DWG, WLD UNDSZ	09/18/85	85-0495	USE-AS-IS (3)
6C-EBD-14-H21	LOCKNUT LOOSE, STRUT TURN BY HAND, PIN-PIN NOT ON DWG	09/18/85	85-0502	USE-AS-IS (3), REWORK-ADJUST (4)
6C-EBD-14-H20	WLDs NOT PER DWG, NO THD IN INSPECTION HOLE, NO INSPECTION HOLE	09/18/85	85-0503	
6C-EBD-14-H17A	PIPE CLAMP NOT TIGHT, SWAY STRUT LOOSE, ONLY ONE NUT/STRUT, PIN-PIN NOT ON DWG	09/18/85	85-0504	USE-AS-IS (3), REWORK-TIGHTEN (4)
6C-EBD-14-H23B	PIN-PIN NOT ON DWG	09/18/85	85-0506	USE-AS-IS (3)
6C-EBD-14-H37	STRUT BODY LOOSE, WSHR & LOCKNUTS MISSING, THDS STAKED, STRUT OFFSET	09/19/85	85-0517	USE-AS-IS (3), REWORK-ADJUST (4)
A-224	FULL LENGTH VS STITCH WLD ON DWG	09/19/85	85-0518	USE-AS-IS (3)
6C-EBD-14-H53	BASEPLATE GAP	09/19/85	85-0523	USE-AS-IS (3)
A-008	ANCHOR TO BE REMOVED	09/19/85	85-0524	REWORK (NON-SEISMIC)
6C-EBD-137-H18	WLD DETAIL, PLATEGAP	09/19/85	85-0525	USE-AS-IS (3)
6C-EBD-14-H56	PLATE GAP, SPACER LOOSE, THDS STAKED, CLAMP ID WRONG	09/19/85	85-0526	USE-AS-IS (3)
6C-EBD-14-H70	ANCHOR BOLT MISSING	09/19/85	85-0527	USE-AS-IS (3)
6C-EBD-14-H38	WLD NOT ON DWG, THD STAKED	09/19/85	85-0528	USE-AS-IS (3)
6C-EBD-14-H15		09/19/85	85-0529	USE-AS-IS (3), REWORK-TORQUE LOCKNUTS (4)
6C-EBD-14-H48	INSTALLED SECTION VS DWG, WLD DETAIL, CLEARANCE	09/20/85	85-0536	
6C-EBD-14-H57	PLATE GAP, THD STAKED, CLAMP ID WRONG	09/20/85	85-0537	USE-AS-IS (3)
6C-EBD-14-H93	PLATE GAP, ITEM # MISSING ON DWG, WLD UNDSZ	09/20/85	85-0538	USE-AS-IS (3)

DAVIS - BESEE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT N°BER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-EBD-14-H55	SPACER LOOSE, THD STAKED, CLAMP ID WRONG, WLD DETAIL, ITEM ROTATED	09/20/85	85-0539	USE-AS-IS (3)
6C-EBD-14-H68	THDS STAKED, THICKER BASEPLATE THAN DWG, GROUT NOT TO DWG	09/20/85	85-0542	USE-AS-IS (3)
6C-EBD-14-H39	PLATE GAP, WLD NOT DETAIL, ITEM # CALLOUT ON DWG	09/20/85	85-0543	USE-AS-IS (3)
A-282	WLD UNDSZ	09/20/85	85-0544	USE-AS-IS (3)
6C-EBD-14-H41	WLDs MISSING, UNDSZ & NOT PER DWG	09/20/85	85-0549	USE-AS-IS (3)
6C-EBD-14-H43	THDED ROD, WLD UNDSZ & DETAIL, BASE METAL REDUCTION	09/20/85	85-0550	USE-AS-IS (3)
6C-EBD-14-H44	BASEPLATE GAP, THD STAKED, LOCKNUT NOT TIGHT, CLAMP END BOUND UP, CLAMP ID WRONG	09/20/85	85-0551	USE-AS-IS (3), REWORK-TIGHTEN LOCKNUT (4)
6C-EBD-14-H67	BASEPLATE GAP, ANCHOR BOLT WRONG SZ, WLD DETAIL AND UNDSZ	09/20/85	85-0555	USE-AS-IS (3)
6C-EBD-14-H69	WLD UNDSZ & DETAIL, PLATE GAP, SHIM NOT ON DWG	09/20/85	85-0560	USE-AS-IS (3)
6C-EBD-14-H92	WLD DETAIL & UNDSZ	09/20/85	85-0563	USE-AS-IS (3)
6C-EBD-14-H75	WEEP HOLE MISSING, WLD DETAIL	09/20/85	85-0564	USE-AS-IS (3)
6C-EBD-14-H46		09/20/85	85-0566	USE-AS-IS (3)
6C-EBD-14-H17	WLD DETAIL, DIM DISCREP	09/20/85	85-0567	USE-AS-IS (3)
6C-EBD-14-H37A	LOCKNUTS MISSING, CLAMP DEFORMED, STRUT BOUND UP	09/20/85	85-0568	USE-AS-IS (3), REWORK-ADJUST PIPE CLAMP (4)
6C-EBD-14-H16	STRUT LOCKED, PIN-PIN NOT ON DWG, DIM PROBLEMS, WLD UNDSZ	09/20/85	85-0570	USE-AS-IS (3)
6C-EBD-14-H31B	WLD UNDSZ, LOCKNUT MISSING, THD STAKED, STRUT BOUND UP	09/20/85	85-0571	USE-AS-IS (3)
6C-EBD-14-H54	ANCHOR BOLTS MISSING, ANCHOR SZ, BASEPLATE GAP, BASEPLATE THICKNESS	09/20/85	85-0577	USE-AS-IS (3)
6C-EBD-14-H42	NO WLD DETAIL ON DWG, BASEPLATE THICKNESS, WLD DETAIL & UNDSZ	09/20/85	85-0578	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-EBD-14-H36	WLD UNDSZ, THD STAKED, WLD DETAIL, TRAPEZE OFFSET, JAM NUT LOOSE	09/20/85	85-0579	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT (4)
6C-EBD-4-H25A	LOCKNUT MISSING, ANCHOR IN CONTACT W/CONDUIT, WLD DETAIL	09/21/85	85-0597	
6C-EBD-14-H31	WLD DETAIL & UNDSZ	09/21/85	85-0601	USE-AS-IS (3)
6C-EBD-14-H60	WLD UNDSZ	09/21/85	85-0602	USE-AS-IS (3)
6C-EBD-14-H74	THD STAKED, ROD END BUSHING JAMMED	09/21/85	85-0606	USE-AS-IS (3), REWORK-FULLY ENGAGE ROD BUSHING
6C-EBD-14-H76	THD STAKED, LOCKNUT LOOSE, CLAMP LOOSE	09/21/85	85-0607	USE-AS-IS (3), REWORK-TORQUE LOCKNUT, TIGHTEN CLAMP (4)
6C-EBD-14-H45	SPACERS WELDED, NO JAM NUTS	09/21/85	85-0608	USE-AS-IS (3)
6C-EBD-14-H25	NO LOCKNUT, THD STAKED, STRUT CLAMP MIS-ALIGNED	09/21/85	85-0609	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
6C-EBD-14-H26	NO WSHR, WLD DETAIL, THD ENGAGEMENT, CLEARANCE	09/21/85	85-0610	USE-AS-IS (3), REWORK-REPLACE BOLT, INSTALL SHIMS (4)   17
6C-EBD-14-H24	NO LOCKNUT, THD STAKED, REAR BRACKET BUSHING MISSING	09/21/85	85-0614	USE-AS-IS (3), REWORK-INSTALL ROD END, ADJUST STRUT (4)
6C-EBD-14-H87	WLD UNDSZ	09/21/85	85-0615	USE-AS-IS (3)
6C-EBD-14-H80	SHIMS BEHIND BASEPLATE, WLD DETAIL & UNDSZ, UNDERCUT	09/21/85	85-0616	USE-AS-IS (3), REWORK-REMOVE ARC STRIKES (4)   17
M-1114-H45	DIMENSION, WLD DETAIL, NO LOCKNUT	09/23/85	85-0626	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
6C-EBD-14-H81	WLD DETAIL & UNDSZ	09/23/85	85-0631	USE-AS-IS (3)
6C-EBD-14-H83	WLD DETAIL & UNDSZ	09/23/85	85-0632	USE-AS-IS (3)   17
6C-EBD-14-H89	THD STAKED	09/23/85	85-0633	USE-AS-IS (3)
6C-EBD-14-H86	WLD DETAIL	09/23/85	85-0634	USE-AS-IS (3)
6C-EBD-14-H90	SHIM NOT ON DWG	09/23/85	85-0635	USE-AS-IS (3)
6C-EBD-14-H85	THD STAKED, SHOP WLD UNDSZ, BRACE NOT ON BOM	09/23/85	85-0636	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-EBD-14-H84	THD STAKED, WLD DETAIL	09/23/85	85-0637	USE-AS-IS (3)
6A-HBD-272-H1	THD STAKED, SPACER TACKED, WLD DETAIL	09/23/85	85-0639	USE-AS-IS (3)
6C-EBD-14-H64	BASEPLATE GAP, SUPPORT MOD NOT ON DWG	09/23/85	85-0640	USE-AS-IS (3)
6A-HBD-22-H4	THD STAKED, PLATE GAP	09/23/85	85-0642	USE-AS-IS (3)
6A-HBD-272-H2	JAM NUT LOOSE, THD STAKED	09/23/85	85-0643	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
6C-EBD-14-H78	WLD DETAIL	09/23/85	85-0645	USE-AS-IS (3)   17
6C-EBD-14-H77	HILTI BOLT VS TAP BOLT ON DWG, WLD DETAIL	09/23/85	85-0646	USE-AS-IS (3)
6C-EBD-14-H88	WLD DETAIL, PLATES NOT ON DWG, INTERNAL DWG DISCREP	09/23/85	85-0647	
6C-EBD-14-H72	WLD DETAIL, BASEPLATE GAP	09/23/85	85-0648	USE-AS-IS (3)   17
6C-EBD-14-H79	JAM NUT MISSING, WLD UNDSZ & DETAIL	09/23/85	85-0649	USE-AS-IS (3)
M-1114-H21	THD ENGAGEMENT, BOLT GAP, DIMENSIONS, SPACER MISSING, NO LOCKNUT	09/23/85	85-0651	
6C-EBD-14-H65	THD STAKED, THD ENGAGEMENT, BENT LOAD BOLT	09/23/85	85-0652	USE-AS-IS (3), REWORK-REPLACE LOAD BOLT AND ADJUST (4)
6C-EBD-14-H27	TAP BOLT MISSING, PLATE GAP	09/23/85	85-0653	USE-AS-IS (3)   17
6C-EBD-14-H59	PLATE GAP, WLD SZ, SHIM NOT ON DWG, BOM QUANTITY DISCREP	09/23/85	85-0654	USE-AS-IS (3)
41-HBC-35-H13	THD STAKED, JAM NUT MISSING, PLATE GAP	09/24/85	85-0667	USE-AS-IS (3)
41-HBC-35-H9	PLATE THICK, DIMENSION, WLD DETAIL	09/24/85	85-0668	USE-AS-IS (3)
6A-HBD-272-H3	WLD DETAIL & UNDSZ, DIMENSION, JAM NUT LOOSE	09/24/85	85-0669	USE-AS-IS (3)
6A-HBD-22-H3	DIMENSION, WLD NOT ON DWG, CLEARANCE, WLD DETAIL	09/24/85	85-0670	USE-AS-IS (3)
A-215	WLD UNDSZ, WSHRS UNDER NUT	09/24/85	85-0671	USE-AS-IS (3)
6A-HBD-22-H6	BOLT & SPACER LOOSE, NO LOCKNUT, THD STAKED, WLD NOT ON DWG, WLD DETAIL	09/24/85	85-0672	USE-AS-IS (3), REWORK-TIGHTEN BOLT, INSTALL LOCK NUT (4)



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6A-HBD-22-H7	WLDS NOT PER DWG, THDS STAKED, LOCK NUTS MISSING, CONC CRACKED	09/25/85	85-0678	USE-AS-IS (3)
6A-HBD-272-H6	BASEPLATE GAP, WLD & DIMS NOT PER DWG	09/25/85	85-0687	USE-AS-IS (3)
6A-HBD-272-H4	DIM NOT PER DWG, PIPE CLAMP, THDS STAKED, SPRING CAN DAMAGED	09/25/85	85-0701	USE-AS-IS (3)
6A-HBD-272-H5	THDS STAKED, WLDS & DIM & ITEM #4 NOT PER DWG	09/25/85	85-0703	USE-AS-IS (3)
6A-HBC-35-H55	WLDS & DIM NOT PER DWG, BOLT SPACING VIOLATION	09/26/85	85-0720	USE-AS-IS (3)
A-216	BASEPLATE GAP UNACC, ANCHOR BOLT INSTALLED @ ANGLE	09/26/85	85-0722	USE-AS-IS (3), REWORK-INSTALL BEVELED WSHR (4)
6A-HBD-22-H5	THDS STAKED, DIMEN & WELD NOT PER DWG, GAPS & SPACING UNACC, MISSING NO. ON BOM	09/26/85	85-0737	USE-AS-IS (3)
6A-HBD-22-H2	DIMEN & WELDS NOT PER DWG, CONC SPALLED.	09/26/85	85-0740	USE-AS-IS (3)
6A-HBC-35-H52	DIMEN, WELDS, & BOLTS NOT PER DWG.	09/26/85	85-0746	
A-217	BOLTS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0748	
6A-HBD-24-H2	MISSING WASHERS, WELDS NOT PER DWG, DAMAGED MEMBERS.	09/27/85	85-0761	USE-AS-IS (3)
6A-HBD-22-H8	BASEPLATE GAP UNACC, WELDS NOT PER DWG, THDS STAKED.	09/27/85	85-0766	USE-AS-IS (3)
6A-HBD-24-H1	DIMEN & WELDS NOT PER DWG, BASEPLATE GAP UNACC.	09/28/85	85-0785	
6A-HBC-35-H34	WLDS NOT PER DWG, CONCRETE BROKEN OUT, ANCHOR BOLTS NOT PER DWG	10/03/85	85-0806	USE-AS-IS (3)
6A-HBC-35-H32	WLDS NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0807	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
6A-HBC-35-H33	WLDS NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0808	USE-AS-IS (3)
M-1114-H9	C-C SPACING, UNDERSIZE WELD, SPACER MISSING, "S" DIM.	10/03/85	85-0851	USE-AS-IS (3), REWORK-INSTALL SPACER (4)
M-1114-H31	BOLT SPACE, CLEARANCE, DIMENSIONS, WELD DETAIL	10/03/85	85-0852	USE-AS-IS (3), REWORK-INSTALL SHIMS (4)

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114-H35	PLATE GAP, DIMENSIONS, WELD	10/03/85	85-0853	USE-AS-IS (3)
M-1114-H34	CLEARANCE, BOLT SPACING	10/03/85	85-0854	USE-AS-IS (3)
M-1114-H12	ANCHOR BOLT TORQUE, PLATE GAP	10/03/85	85-0855	USE-AS-IS (3), REWORK-REMOVE WOOD SHIM (4)
M-1114-H10	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0856	USE-AS-IS (3)
M-1114-H14	PLATE GAP, DIMENSIONS, CLAMP BOLT LOOSE, LOCKNUT LOOSE	10/04/85	85-0887	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT, ADJUST CLAMP (4)
M-1114-H39	PLATE GAP, STRUT ANGLE	10/04/85	85-0888	USE AS IS (3), REWORK-ADJUST CLAMP (4)
M-1114-H44	WELD DETAIL, PIN-PIN DIM.	10/04/85	85-0889	USE-AS-IS (3)
6A-HBC-35-H31	B/M PROBLEMS, WELD DETAIL, DIMENSIONS, CLEARANCE, WASHER MISSING, PLATE GAP	10/05/85	85-0913	USE-AS-IS (3)
6C-EBD-14-H28	WELDS, LUG CLEARANCES	10/16/85	85-1226	

SECTION 3.0

LOW PRESSURE INJECTION SYSTEM



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
GCB-1-H15	ROD END ATTACHMENT LOAD PIN LOOSE	08/21/85	85-0139	
33B-FCB-2-H1	MISSING JAM NUT, P CLAMP TWISTED, THDS ON BOLTS UPSET	08/30/85	85-0148	USE-AS-IS (3)
33B-CCB-6-H9	PART OF SUPPORT FLANGE REMOVED, WELD UNDERSIZE, GAP CLEARANCE.	09/02/85	85-0159	
33C-CCA-4-H4	LOOSE ANCHORBOLT, ROD END BINDING, INTERFERENCE WITH ADJACENT SUPPORT.	09/02/85	85-0161	USE-AS-IS (3)
33B-CCB-6-H10	ATTACHMENT NOT PER DWG., WELD UNDERSIZE, SNUBBER HEAD BOLT LOOSE	09/02/85	85-0162	USE-AS-IS (3), REWORK-TIGHTEN BOLT (4)
33B-CCB-6-H2	BOLTS STAKED IN PLACE	09/02/85	85-0163	USE-AS-IS (3)
33B-CCB-6-H4	GREASE FITTINGS CUT OFF OF ROD ENDS	09/02/85	85-0164	USE-AS-IS (3)
33C-CCA-4-H2	NON STANDARD PIPE CLAMP, MISSING WELD, SUPPORT INTERFERS W/ANOTHER SUPPORT.	09/03/85	85-0166	USE-AS-IS (3)
33C-CCA-4-H3	NON-STD PIPE CLAMP, MISSING & UNDRSZ WLDS, EDGE DISTANCE LESS THAN MINIMUM.	09/03/85	85-0176	USE-AS-IS (3)
33B-CCB-5-H4	UNDERSIZE WELD, AS-BUILT WELD TYPE NOT PER DWG.	09/03/85	85-0178	USE-AS-IS (3)
33B-CCB-5-H401	BOLTS HAVE ONE NUT ONLY, CLEARANCE GAP AND SHIMS INACCURATE.	09/03/85	85-0179	
33C-CCA-4-H10	NON-STD COMPS, 3/4in BLTS VS SPEC'D 5/8in, MMBRS LONGER THAN DES., WELD UNDRSZD	09/03/85	85-0184	USE-AS-IS (3)
33B-CCB-6-H11	WELD UNDERSIZE	09/02/85	85-0186	USE-AS-IS (3)
33B-CCB-6-H8	WELD UNDRSZ, AS-BUILT MEMBER LENGTH AND ANGLE NOT PER DWG.	09/03/85	85-0188	USE-AS-IS (3)
33B-CCA-6-H6	BOLT DOES NOT HAVE FULL THREAD	09/03/85	85-0189	USE-AS-IS (3)
33B-CCA-6-H5	WELD DETAIL MISSING FROM DWG, SNUBBER ELEVATION INCORRECT	09/03/85	85-0190	USE-AS-IS (3)
33C-CCA-4-H9	POOR QLTY WLDS, NON-STD COMPONENTS USED, MEMBER LOCATIONS INACCURATE.	09/03/85	85-0191	
33B-CCB-6-H7	WLD UNDRSZ, WLD DTL NOT PER DWG, MSSNG WLDS, BASEPLATE GAP, CLRNC GAP NOT PER DWG	09/03/85	85-0192	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-CCB-6-H3	ANCHORS HAVE > 2 WASHERS	09/04/85	85-0195	USE-AS-IS (3)
33B-CCA-6-H7	HILTIES W/O WASHERS, GAPS IN BASEPLATE, LOWER BASEPLATE NEEDS GROUT	09/04/85	85-0197	USE-AS-IS (3)
33B-GCB-2-H6	NO WLDS NEEDED VS ACTUAL WELDS, SWAY STRUT HAS NO MOVEMENT	09/04/85	85-0211	USE-AS-IS (3)
33C-CCA-4-H601	SHIM PLATE GOUGED, EXCESSIVE GAP, GAP COCKED	09/04/85	85-0214	
33B-HCB-11-H3	WASHERS MISSING, SWAY STRUT DOES NOT ROTATE	09/07/85	85-0273	
33A-GCB-8-H3	BASEPLATE GAP, BUSHING BINDING, LOCATION DIMENSION NOT PER DWG	09/10/85	85-0309	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
33B-GCB-10-H29	THDS STAKED, "S" DIM INCOR, INCORRECT SNUBBER ID, SNUBBER INSTALLED AT ANGLE	09/10/85	85-0315	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
33B-GCB-10-H28	BOLTS DOUBLENUTTED W/THD DAMAGE, MISSING WELD ON SADDLE	09/10/85	85-0316	USE-AS-IS (3)
A-064	NUTS DO NOT HAVE FULL ENGAGEMENT	09/10/85	85-0322	USE-AS-IS (3)
33A-GCB-8-H5	NO LOCKNUT, WELD DETAIL	09/12/85	85-0382	USE-AS-IS (3)
33B-GCB-10-H9	WLD NOT PER DWG, JAM NUT THDS STAKED, BUSHING BOUND UP	09/17/85	85-0442	USE-AS-IS (3)
33B-GCB-10-H6	BASEPLATE GAP EXCEEDS REQS, WLDS NOT POSS PER DWG, U BOLT THDS STAKED	09/17/85	85-0443	USE-AS-IS (3)
33B-GCB-10-H11	WLDS NOT POSS PER DWG, JAM NUTS THDS STAKED, BUSHINGS BOUND UP	09/17/85	85-0444	USE-AS-IS (3)
33B-GCB-10-H14	JAM NUTS THDS STAKED, SWAY STRUT BUSHING BOUND UP	09/17/85	85-0445	USE-AS-IS (3)
33B-GCB-10-H13	JAM NUTS MISSING, WLD ONE SIDE VS PRESENT ALL-ROUND	09/17/85	85-0446	USE-AS-IS (3)
33B-GCB-10-H15	WSHRS & JAM NUTS MISSING	09/17/85	85-0447	USE-AS-IS (3)
33B-GCB-10-H16	ITEM #4 WELD NOT PER DWG	09/17/85	85-0448	USE-AS-IS (3)
33B-GCB-10-H8	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0449	USE-AS-IS (3)
33B-GCB-10-H17	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0452	USE-AS-IS (3)

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-GCB-10-H12	WLDs NOT PER DWG	09/17/85	85-0454	USE-AS-IS (3)
33B-GCB-10-H7	WLD UNDSZ, WLDs NOT PER DWG	09/17/85	85-0455	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
33B-GCB-10-H18	NO JAM NUT, THD STAKED	09/17/85	85-0457	USE-AS-IS (3)
33B-GCB-2-H5	JAM NUTS MISSING, BUSHING BOUND UP	09/17/85	85-0458	USE-AS-IS (3)
33B-GCB-10-H5	JAM NUTS MISSING, SPACER BOLT LOOSE, BASEPLATE GAP EXCEED REQS	09/17/85	85-0459	USE AS IS (3), REWORK-INSTALL NUTS, TIGHTEN BOLT (4)
33B-GCB-10-H4	JAM NUTS MISSING, THDS STAKED, BASEPLATE GAP EXCEED REQS	09/17/85	85-0477	USE-AS-IS (3)
33B-GCB-2-H2	WLD UNDSZ, NO JAM NUTS, THD STAKED, PIPE CLAMP MOVED, SWAY STRUT BUSHING BOUND	09/18/85	85-0500	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
33B-GCB-2-H4	JAM NUT MISSING, THD STAKED, STRUT BUSHING BOUND	09/18/85	85-0501	USE-AS-IS (3)
33B-GCB-2-H3	RED HEADS VS WEJ-ITS, FLARE BEVEL VS FILLET WELD, WLD NOT PER DWG	09/18/85	85-0505	USE-AS-IS (3)
33B-GCB-2-H1	THDS STAKED, LUG WLD & JAM NUTS MISSING	09/19/85	85-0516	USE-AS-IS (3)
33B-GCB-10-H12	?	09/18/85	85-0532	USE-AS-IS (3)
A-040	HILTI INSTALLED VS WEJ-ITS ON DWG	09/20/85	85-0546	USE-AS-IS (3)
33C-CCB-2-H5	JAM NUTS MISSING, THDS STAKED	09/20/85	85-0547	
33B-GCB-1-H4	WLD UNDSZ, WSHRS MISSING, DIMENSION DISCREP	09/20/85	85-0556	USE-AS-IS (3)
33B-GCB-1-H3B	THD STAKED, DIMENSION	09/20/85	85-0557	USE-AS-IS (3)
33B-GCB-1-H10	DIMENSION, THD STAKED	09/20/85	85-0558	USE-AS-IS (3)
33B-GCB-1-H6	NO WSHR, THD STAKED, CLAMP BOLT LOOSE, DIMENSIONS	09/20/85	85-0559	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
33B-GCB-1-H8	CLEARANCE, EXTRA WLD, WLD UNDSZ	09/20/85	85-0569	USE-AS-IS (3)
33C-GCB-10-H20	NO JAM NUTS, THD STAKED	09/20/85	85-0572	USE-AS-IS (3)
33C-GCB-10-H21	NO JAM NUTS, THDS STAKED	09/20/85	85-0573	USE-AS-IS (3)

17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-GCB-10-H23	WLD UNDSZ	09/20/85	85-0574	USE-AS-IS (3)
33C-GCB-7-H1	DIMENSIONS, WLD DETAIL, PIPE CLAMP LOOSE	09/20/85	85-0580	USE-AS-IS (3), REWORK-REPLACE SPACER, TIGHTEN NUT (4)
33B-GCB-1-H7	WEAR ON WELD, WLD UNDSZ, WSHRS MISSING, PLATE GAP, DIMENSIONS	09/20/85	85-0583	USE-AS-IS (3)
33B-GCB-1-H3	DIMENSIONS, SPACERS TACKED, THD STAKED	09/20/85	85-0587	USE-AS-IS (3), REWORK-READJUST HANGER ROD (2)
33B-GCB-1-H9	WLD UNDSZ	09/20/85	85-0588	USE-AS-IS (3)
33A-GCB-4-H6	PLATE GAP, WLD DETAIL & UNDSZ	09/21/85	85-0593	USE-AS-IS (3)
33B-GCB-1-H5	JAM NUT LOOSE, THD STAKED, DIMENSION	09/21/85	85-0595	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
34-HCB-9-H10	BOLT SPACING, WLD DETAIL	09/21/85	85-0598	USE-AS-IS (3)
34-HCB-9-H21	WLD DETAIL	09/21/85	85-0599	USE-AS-IS (3)
34-HCB-9-H30	NO WSHR, DIMENSIONS, WLD UNDSZ	09/21/85	85-0600	USE-AS-IS (3)
33A-HCB-3-H14	DIMENSION, THD STAKED	09/21/85	85-0603	USE-AS-IS (3)
33A-HCB-3-H16	PLATE NOT ON DWG	09/21/85	85-0604	USE-AS-IS (3)
33A-HCB-3-H2	INSUFF THD ENGAGEMENT	09/21/85	85-0605	REWORK-ADJUST (4)
33C-GCB-10-H24	NO JAM NUT, THD STAKED	09/21/85	85-0611	USE-AS-IS (3)
33C-GCB-10-H25	NO JAM NUT, THD STAKED	09/21/85	85-0612	USE-AS-IS (3)
33C-GCB-10-H19	NO JAM NUT, THD STAKED, SPRING SETTING	09/21/85	85-0613	USE-AS-IS (3), REWORK-RESET SPRING (4)
33B-GCB-1-H13	CLEARANCE	09/21/85	85-0617	USE-AS-IS (3)
33B-GCB-1-H11	CLEARANCE, WLD DETAIL	09/21/85	85-0618	USE-AS-IS (3)
33B-GCB-1-H37	NO WSHRS, CLAMP BOLT LOOSE, THD STAKED, WLD UNDSZ	09/21/85	85-0619	USE-AS-IS (3)
33B-GCB-1-H39	THREAD STAKED, PIPE CLAMP GAP	09/21/85	85-0620	USE-AS-IS (3)
33B-GCB-1-H39	THREAD STAKED	09/21/85	85-0621	USE-AS-IS (3)

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-GCB-1-H16	BOM DIMENSION, THD STAKED, CONCRETE CRACKED	09/21/85	85-0622	USE-AS-IS (3)
33A-GCB-1-H15	NO WSHRS, JAM NUT LOOSE, WLD DETAIL & UNDSZ, STRUT DAMAGE, STRUT BOUND UP	09/21/85	85-0623	USE-AS-IS (3), REWORK-REPLACE STRUT MEMBER AND AJUST (4)
33A-HCB-3-H15	ADDED PLATE NOT ON DWG	09/23/85	85-0625	USE-AS-IS (3)
34-HCB-9-H31	MISSING LOCKNUT, THD STAKED, MISSING WSHR	09/23/85	85-0627	USE-AS-IS (3)
A-073	DIMENSIONAL, WLD UNDSZ	09/23/85	85-0628	USE-AS-IS (3)
34-HCB-9-H16	LOCKNUT MISSING, STRUT BINDING, WLD DETAIL	09/23/85	85-0629	USE-AS-IS (3)
A-044	BOLT LENGTH & BASEPLATE GAP, WLD UNDSZ & DETAIL, EXTRA PLATE	09/23/85	85-0630	
33B-GCB-1-H14	DIMENSION, WLD DETAIL & UNDSZ, CLEARANCE	09/23/85	85-0638	USE-AS-IS (3)
A-045	BASEPLATE GAP, ANCHOR BOLT TYPE, DWG DETAIL	09/23/85	85-0641	USE-AS-IS (3)
33A-GCB-6-H7	ANGLE BEARING, STIFF FLATE ADDED TO ANGLE, THD ENGAGEMENT	09/23/85	85-0656	USE-AS-IS (3)
33A-GCB-6-H10	INTERNAL DWG DISCREP, BOLT NOT TIGHT, FLATE GAP	09/23/85	85-0657	
33A-GCB-6-H15	WLD UNDSZ, DIMENSION	09/23/85	85-0658	USE-AS-IS (3)
33A-HCB-3-H3	PLATE GAP, DIMENSION, PLATE THICKNESS	09/23/85	85-0659	
33A-GCB-6-H9	PLATE GAP, STRUT BOUND, NO WSHRS	09/23/85	85-0660	USE-AS-IS (3), REWORK-INSTALL SHIMS
33C-HCB-9-H14	JAM NUT STRIPPED, NO JAM NUT, THD STAKED, SHIM ON CLAMP	09/24/85	85-0662	USE-AS-IS (3)
33C-HCB-9-H15	NO JAM NUT, THD STAKED	09/24/85	85-0663	USE-AS-IS (3)
33C-HCB-9-H12	NO JAM NUT	09/24/85	85-0664	USE-AS-IS (3)
33C-HCB-9-H13	ADDITIONAL WELD, WLD DETAIL	09/24/85	85-0665	USE-AS-IS (3)
33C-GCB-10-H22	JAM NUTS MISSING	09/25/85	85-0673	USE-AS-IS (3)
33B-COB-6-H1	JAM NUTS MISSING	09/25/85	85-0674	USE-AS-IS (3)
33A-HCB-3-H5	EDGE BOLT SPACING VIOLATIONS, ITEM #7 DIM NOT PER DWG	09/25/85	85-0675	USE-AS-IS (3)

| 17

| 17



SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-3-H1	WSHRS MISSING, 4 WSHRS/BOLT, LOOSE NUT	09/25/85	85-0683	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
33A-HCB-3-H4	WLDs NOT PER DWG	09/25/85	85-0686	USE-AS-IS (3)
33A-GCB-8-H14	WLDs NOT PER DWG	09/25/85	85-0695	USE-AS-IS (3)
33A-GCB-8-H8	NO BEARING SURFACE AT BASEPLATE, WLDs NOT PER DWG	09/25/85	85-0696	
33B-GCB-10-H34		09/25/85	85-0700	
33B-CCB-6-H13	JAM NUTS MISSING & SPACERS, THDS STAKED	09/25/85	85-0702	USE-AS-IS (3)
33C-GCB-7-H2	GAPS UNACC, DIM NOT PER DWG, SPACER MISSING, ORIENT NOT PER DWG	09/25/85	85-0716	USE-AS-IS (3), REWORK-INSTALL SPACER, REALIGN CLAMP (4)
33B-HCC-35-H21	GAPS UNACC, MISSING JAM NUTS, THDS STAKED, WLD NOT PER DWG	09/25/85	85-0717	USE-AS-IS (3)
33B-HCC-35-H3	BASEPLATE GAPS UNACC, WLDs NOT PER DWG	09/25/85	85-0718	USE-AS-IS (3)
34-HCB-9-H17	DIM NOT PER DWG	09/26/85	85-0721	USE-AS-IS (3)
A-254	BASEPLATE GAPS UNACC, VOID IN CONC, WELDS & DIMEN NOT PER DWG.	09/26/85	85-0726	
33C-GCB-7-H6	DIMEN NOT PER DWG.	09/26/85	85-0734	USE-AS-IS (3)
33B-GCB-10-H27	MISSING PC#12 & JAM NUTS, THDS STKD, STRUT BOUND, DIMEN NOT PER DWG.	09/26/85	85-0738	USE-AS-IS (3), REWORK-ADJUST PIPE CLAMP (4)
33B-GCB-10-H2:	MISSING JAM NUTS, CLAMP NOT SEATED PROPERLY, STRUT BOUND.	09/26/85	85-0739	USE-AS-IS (3)
A-071	DIMEN NOT PER DWG.	09/26/85	85-0741	USE-AS-IS (3)
33B-HCC-35-H5	WELDS & CLEAR. NOT PER DWG.	09/26/85	85-0745	USE-AS-IS (3)
33C-GCB-7-H3	WELDS & DIMEN NOT PER DWG, LOOSE CLEVIS, SNUBBER DAMAGED.	09/26/85	85-0749	USE-AS-IS (3), REWORKREALIGN SNUBBER/CLAMP (4)
33B-HCC-35-H2	WELDS NOT PER DWG, ARC STRIKES	09/26/85	85-0750	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
33B-HCC-35-H4	WELDS NOT PER DWG.	09/26/85	85-0751	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-HCC-26-H13	WELDS NOT PER DWG.	09/27/85	85-0759	USE-AS-IS (3)
33B-HCC-34-H1	DIMEN & WELD NOT PER DWG.	09/27/85	85-0760	USE-AS-IS (3)
33C-GCB-7-H13	DIMEN & WELDS NOT PER DWG.	09/27/85	85-0764	USE-AS-IS (3)
33B-HCC-35 H17	BOLTS NOT PER DWG, LOOSE BOLT, ITEM #4 ON WELD.	09/27/85	85-0768	USE-AS-IS (3)
33B-HCC-35-H1	WELD NOT PER DWG.	09/27/85	85-0769	USE-AS-IS (3)
33B-HCC-35-H7	WELD NOT PER DWG.	09/27/85	85-0770	USE-AS-IS (3)
33B-HCC-35-H23	NOT PER DWG.	09/27/85	85-0771	USE-AS-IS (3)
33B-HCC-35-H22	WELD NOT PER DWG.	09/27/85	85-0772	USE-AS-IS (3)
33B-HCC-35-H6	WELD NOT PER DWG.	09/27/85	85-0773	USE-AS-IS (3)
33C-GCB-7-H11	DIMEN & WELDS NOT PER DWG, MISSING WASHERS.	09/27/85	85-0774	USE-AS-IS (3)
33C-HCB-24-H5A		09/28/85	85-0777	USE-AS-IS (3), REWORK-INSTALL LOCKWIRE & SPACER (4)
M-1156-H1	DIMEN NOT PER DWG, THD ENGAGE UNACC.	09/28/85	85-0778	USE-AS-IS (3), REWORK-ADJUST STRUT
33B-GCB-1-H21	THDS OF ROD NOT VISIBLE, WELDS NOT PER DWG.	09/28/85	85-0779	USE-AS-IS (3), REWORK-ADJUST ROD (4)
33B-GCB-1-H22	WELDS NOT PER DWG, GREASE FITTINGS DAMAGED, SNUBBER LEAKING.	09/28/85	85-0780	USE-AS-IS (3), REWORK, REWORK FITTINGS & REPAIR SEALS
33B-HCC-35-H18	BASEPLATE GAPS UNACC, WELDS NOT PER DWG.	09/28/85	85-0782	USE-AS-IS (3)
33B-HCC-26-H12	WELDS NOT PER DWG.	09/28/85	85-0783	USE-AS-IS (3)
33A-GCB-8-H1	WELDS NOT PER DWG, BASEPLATE GAP UNACC.	09/28/85	85-0784	USE-AS-IS (3)
A-084	DIMEN NOT PER DWG.	09/28/85	85-0786	USE-AS-IS (3)
A-083	WELDS & DIMEN NOT PER DWG.	09/28/85	85-0787	USE-AS-IS (3)
34-HCB-9-H16	WELDS NOT PER DWG.	09/28/85	85-0789	USE-AS-IS (3)
33C-GCB-7-H5	WELDS & DIMEN NOT PER DWG. IMPROPER SPRING SETTING.	09/30/85	85-0790	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT, ADJUST SPRING (4)



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-041	WELDS NOT PER DWG, BOLT #7 COULD NOT BE TORQUED, STUDS CUT.	09/30/85	85-0791	
33C-GCB-7-H4	BOLTS, DIMEN, & WELDS NOT PER DWG, ITEMS NOT PER BOM.	09/30/85	85-0792	USE AS IS (3)
33C-GCB-7-H10	MISSING WELDS & DIMEN, CLEARANCE NOT PER DWG.	09/30/85	85-0793	USE-AS-IS (3)
33B-GCB-1-H17	WELD NOT PER DWG.	09/30/85	85-0794	USE-AS-IS (3)
33B-GCB-1-H18	DIMEN & WELDS NOT PER DWG.	09/30/85	85-0795	USE-AS-IS (3)
33B-GCB-1-H32	WELDS NOT PER DWG.	09/30/85	85-0797	USE-AS-IS (3)
33B-HCC-34-H2	CLAMP ROTATED, THDS STAKED.	09/30/85	85-0799	USE-AS-IS (3)
35-HCC-27-H20	DIMEN & ITEMS NOT PER DWG.	09/30/85	85-0800	USE-AS-IS (3), REWORK-ADD OR REPLACE WASHERS (4)
35-HCC-27-H21	WELDS & DIMEN NOT PER DWG.	10/01/85	85-0801	USE-AS-IS (3), REWORK-ADD SPACER (4)
34-HCB-9-H19	WELDS NOT PER DWG, HEAVY CORROSION, DIMENSIONS NOT PER DWG	10/03/85	85-0804	USE-AS-IS (3), REWORK-REMOVE RUST & PAINT (4)
34-HCB-9-H20	WELDS NOT PER DWG & DEFECTS	10/03/85	85-0805	USE-AS-IS (3)
33B-GCB-1-H41	WELDS NOT PER DWG	10/03/85	85-0809	USE-AS-IS (3)
33B-GCB-1-H2	WASHERS MISSING, BASEPLATE GAP UNACC, WELDS NOT PER DWG	10/03/85	85-0810	USE-AS-IS (3)
33B-GCB-1-H1	WELDS NOT PER DWG, BASEPLATE GAP UNACC	10/03/85	85-0811	USE-AS-IS (3)
33B-GCB-1-H40	PLATE DIMENSIONS NOT PER DWG	10/03/85	85-0812	USE-AS-IS (3)
A-222	BASEPLATE NOT ACC, NO THD ENGAGEMENT ON BOLTS, CONCRETE SPALLING	10/03/85	85-0826	USE-AS-IS (3)
33B-GCB-10-H31	WASHERS MISSING, WELDS UNDSZ	10/03/85	85-0827	USE-AS-IS (3)
33B-GCB-10-H37	WELDS NOT PER DWG, ITEMS NOT PER BOM	10/03/85	85-0828	
33B-GCB-10-H33	DIM NOT PER DETAIL	10/03/85	85-0829	USE-AS-IS (3)
33B-GCB-1-H23	BOLT STKD & THDS IN SHEAR, LOCK NUT LOOSE, WELDS NOT PER DWG, NO ID ON SPRING CAN	10/03/85	85-0834	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
338-HCC-34-H5	BOLTS NOT PER BOM, WLDS NOT PER DWG	10/03/85	85-0836	USE-AS-IS (3)
338-HCC-34-H4	FROZEN LOCKNUT, BOLT SPACING, DIM & WLDS NOT PER DWG	10/03/85	85-0837	USE-AS-IS (3)
338-GCB-1-H26	WLDS & DIM NOT PER DWG & BOM, THDS STAKED	10/03/85	85-0838	USE-AS-IS (3)
338-GCB-10-H40	BASEPLATE GAPS UNACC, ARC STRIKES ON PIPE NEAR WELD	10/03/85	85-0842	USE-AS-IS (3), REWORK-REMOVE ARC STRIKES (4)
A-167	CONC CRACKED	10/03/85	85-0845	USE-AS-IS (3)
338-GCB-1-H36	WSHR MISSING, ITEM #4 NOTCHED	10/03/85	85-0846	USE-AS-IS (3)
A-211	BUSSET PLATES, WLDS & PIPE SADDLE NOT PER DWG, BASEPLATE GAP UNACC	10/03/85	85-0847	USE-AS-IS (3)
338-GCB-10-H36	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0848	USE-AS-IS (3)
338-GCB-7-H12	DIMENSIONS, WELD DETAIL B/M PROB.	10/03/85	85-0849	USE-AS-IS (3)
338-GCB-10-H41	WELD DETAIL	10/03/85	85-0857	USE-AS-IS (3)
338-GCB-10-H38	WELD SIZE, TRUNNION LENGTH & THICK	10/04/85	85-0883	USE-AS-IS (3)
338-GCB-10-H42	TRUNNION LENGTH & THICK	10/04/85	85-0884	USE-AS-IS (3)
A-043	DIMENSION, WELD DETAIL	10/04/85	85-0885	
338-GCB-10-H1	BOLT NOT INSTALLED, PLATE WELD TO EMBELL, WELD DETAIL & UNDERSZ, ITEM ROTATED	10/04/85	85-0886	USE-AS-IS (3)
338-GCB-1-H27	MISALIGNMENT OF 3 DEG., THD STAKED, DIMEN. INCORRECT	10/05/85	85-0923	USE-AS-IS (3)
338-GCB-1-H24	BASEPLATE GAP, LOOSE JAMNUT, STRUT @ 6 DEG. ANGLE & IS BOUND UP	10/05/85	85-0924	USE-AS-IS (3), REWORK-TIGHTEN NUT (4)
338-GCB-1-H33	MEMBER LOCATION DIMENSIONS INCORRECT	10/05/85	85-0925	USE-AS-IS (3)
338-GCB-10-H32	WELDS UNDSZ	10/05/85	85-0926	USE-AS-IS (3)
338-GCB-1-H34	WLD MISSING, THDS STAKED, STRUT BOUND	10/05/85	85-0927	USE-AS-IS (3)
338-GCB-1-H25	MISSING WASHERS, WLD DETAIL MISSING, WLD UNDSZ, SWAY STRUT BOUND 1005	10/05/85	85-0928	USE-AS-IS (3)

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
37B-GCB-1-H31	THDS STAKED, MEMBER DIMEN. INCORRECT	10/05/85	85-0929	USE-AS-IS (3)
33B-GCB-10-H35	DWG DETAILS INCORRECT	10/05/85	85-0930	
A-059	LACK FULL AND ENGAG., BASEPLATE GAP, MEMBER INSTALLED NOT PER DWG.	10/08/85	85-0963	USE-AS-IS (3)
33C-HCC-129-H2	ANCHORBOLT TYPES CHANGED WELD LENGTH SHORTENED	10/17/85	85-1269	USE-AS-IS (3)
33C-HCC-129-H2	1 13/16" GROUT WELDS UNDERSIZED OR NOT SYMBOL SHOWN, SUPPORT CONFIG. CHANGE	10/17/85	85-1270	USE-AS-IS (3)
M-1166-H2	WELD UNDERSIZE, WELD TYPE CHANGED	10/17/85	85-1271	
33C-HCC-129-H3	INSTALLED AS 4" CHANNELS NOT T2X2, WELDS	10/17/85	85-1274	USE-AS-IS (3)
33B-GCB-10-H39	ANCHOR BOLTS NUTS RUSTED, WELD NOT PER DWG., PLAN INCORRECT	10/28/85	85-1518	USE-AS-IS (3)
M-CCB-10-2-A2	DIMWENSION, MODIFIED TEE, WLD DETAIL & SZ	11/06/85	85-1763	

17

17

SECTION 4.0

HIGH PRESSURE INJECTION SYSTEM

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H47	WELD UNDERSIZE, PIPE CLAMP DETAIL	08/30/85	85-0149	USE-AS-IS (3)
33C-CCB-2-H40	WELD DETAIL, BOLT LOCATION ON ANGLE INCORRECT	08/30/85	85-0151	USE-AS-IS (3)
33C-CCB-2-H45	WELDS UNDERSIZE AND CONTAIN AREAS OF UNDERCUT, WELD SIZE MISSING	09/02/85	85-0152	USE-AS-IS (3)
33C-CCB-2-H43	WELDS UNDERSIZE, WELD SIZE MISSING	09/02/85	85-0153	USE-AS-IS (3)
33C-CCB-2-H46	PLATE DIM INCORRECT, MEMBER SIZES INCORRECT. BOLT LOCATION NOT PER DWG	09/02/85	85-0154	
33C-CCB-2-H44	GAP DIM INACCURATE	09/02/85	85-0155	USE-AS-IS (3)
33C-CCB-2-H260	MEMBER SIZES INCORRECT, 1 SIDE WELD VS. DESIGNED 3 SIDES.	09/02/85	85-0156	USE-AS-IS (3)
33C-CCB-2-H36	WELD UNDER SIZE AND CONTAINS AREAS OF UNDERCUT	09/02/85	85-0157	USE-AS-IS (3)
33C-CCB-2-H41	ONE SIDE WELD VS. 3 SIDES	09/02/85	85-0158	USE-AS-IS (3)
A-256	WELD UNDERSIZE	09/02/85	85-0160	USE-AS-IS (3)
33C-CCB-2-H51	SPRING SETTING QUESTIONABLE	09/02/85	85-0165	USE-AS-IS (3)
33C-CCB-2-H37	MISSING WELD SYMBOL, BOLT LOCATION INACCURATE	09/03/85	85-0167	USE-AS-IS (3)
33C-CCB-2-H38	ANCHORBOLT LOCATION INACCURATE	09/03/85	85-0168	USE-AS-IS (3)
33C-CCB-2-H32	CLEARANCE GAP INCORRECT, WELD UNDERSIZE.	09/03/85	85-0169	USE-AS-IS (3)
33C-CCB-2-H27	MEMBER SIZE IS INACCURATE, WELDS MISSING	09/03/85	85-0170	USE-AS-IS (3)
33C-CCB-2-H30	SUP MEMBER LOCAT. IS INACCURATE, WLD MISSING & POOR QLTY Wlds, 3 WASHERS/1 BOLT	09/03/85	85-0171	USE-AS-IS (3)
33C-CCB-2-H49	WELDS UNDERSIZE, NO CLEARANCE & PAINT ON GRAPHITE SURFACE	09/03/85	85-0172	USE-AS-IS (3)
33C-CCB-2-H48	WELDS UNDERSIZE, WELDS ONE SIDE VS. 3, PAINT ON GRAPHITE SURFACE	09/03/85	85-0173	USE-AS-IS (3)
33C-CCB-2-H42	WELD UNDRSZ, WELD SZ NOT ON DWG, BOLT DOES NOT HAVE FULL THREAD ENGAGEMENT	09/03/85	85-0174	USE-AS-IS (3)
A-257	WELD UNDERSIZE, WELD NOT ON DWG.	09/03/85	85-0175	USE-AS-IS (3)

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H50	UNDERSIZE WELD, NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/02/85	85-0177	USE-AS-IS (3)
33C-CCB-2-H52	LOOSE ANCHORBOLT, WELDS UNDERSIZE.	09/03/85	85-0180	USE-AS-IS (3)
33C-CCB-2-H53	WELDS UNDERSIZE	09/03/85	85-0181	USE-AS-IS (3)
33C-CCB-2-H55	ITEM I.D. ON DWG INCORRECT	09/03/85	85-0182	USE-AS-IS (3)
33C-CCB-2-H56	CLRNCE GAPS NOT PER DWG, MISSING WELD, NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/03/85	85-0183	USE-AS-IS (3), REWORK-SHIM (4)
33C-CCB-2-H54	WELDS UNDSZ, STRUCT MEMBER LENGTHS & INSTALLED ANGLES NOT PER DWG.	09/03/85	85-0193	USE-AS-IS (3)
33C-CCB-2-H34	FLD WELDS NOT WELDED PER DWG	09/04/85	85-0196	USE-AS-IS (3)
A-255	UNDERSIZE WELD	09/04/85	85-0199	USE-AS-IS (3)
33C-CCB-2-H33	FIELD WELDS UNDERSIZE, FIELD WELDS NOT WELDED PER DWG.	09/04/85	85-0200	USE-AS-IS (3)
33C-CCB-2-H35	ANCHORS HAVE > 2 WASHERS, BEARING GAP WRONG DIM.	09/04/85	85-0201	USE-AS-IS (3)
33C-CCB-2-H29	WELDS UNDERSIZE, WELD MISSING	09/04/85	85-0208	USE-AS-IS (3)
33C-CCB-2-H28	LOAD FLANGE ANGLED	09/04/85	85-0209	USE-AS-IS (3)
33C-HCB-2-H43	SHIMS WRONG, CLEARANCE IS REVERSE OF DETAIL DWG.	09/04/85	85-0213	USE-AS-IS (3)
33C-HCB-2-H42	WLD UNDSZ, MEMBER SIZE LARGER THAN DRAWING	09/05/85	85-0215	USE-AS-IS (3)
33C-CCB-2-H14	WLD UNDSZ, MEMBERS LONGER TAN SPECIFIED	09/05/85	85-0218	USE-AS-IS (3)
A-053	BASEPLATE GAPS, WLD UNDSZ, FULL PEN WELD NOT FLUSH	09/06/85	85-0228	USE-AS-IS (3)
33C-CCB-2-H7	BASEPLATE GAP, WLD UNDSZ & NOT PER DWG, 1/2" DROP IN ANCHORS	09/05/85	85-0229	USE-AS-IS (3)
33C-HCC-124-H6	BUSHING FROZEN, MISSING JAM NUT, CLAMP BOLT THDS STAKED, WLD NOT PER DWG	09/05/85	85-0230	USE-AS-IS (3)
33C-CCB-2-H6	DIMENSIONS NOT PER DWG	09/05/85	85-0231	USE-AS-IS (3)



SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-HCC-124-H4	SPACERS INACCURATE, WLD PROBLEMS	09/05/85	85-0232	USE-AS-IS (3)
33C-CCB-2-H20	WLD UNDSZ	09/05/85	85-0233	
33C-HCC-91-H1	BASEPLATE GAP, WLDs WRONG SIZE	09/05/85	85-0235	USE-AS-IS (3)
33C-HCC-124-H5	SPACERS & JAM NUT MISSING, WELD PROBLEMS	09/05/85	85-0236	USE-AS-IS (3), REWORK-ADD BUSHING SPACERS (4)
33C-CCB-19-H1	NON-STD PIPE CLAMP, BASEPLATE GAP, INTERFERENCE WITH CONDUIT	09/05/85	85-0237	
A-392	WELDS NOT PER DWG	09/05/85	85-0241	USE-AS-IS (3)
33C-HCB-2-H41	WLDs NOT PER DWG, GROUT CRACKED, WASHERS MISSING	09/06/85	85-0243	USE-AS-IS (3)
33C-HCB-2-H37	JAM NUT MISSING	09/06/85	85-0246	USE-AS-IS (3)
33C-HCB-2-H39	WLDs UNDSZ & DETAILS INCORRECT, VOID IN GROUT	09/06/85	85-0247	USE-AS-IS (3)
33C-HCB-2-H38	WLD DETAIL INCORRECT	09/06/85	85-0248	USE-AS-IS (3)
33C-CCB-12-H1	BUTT WELD IN LIEU OF FILLET, 2 NUTS INSTALLED PER ANCHORBOLT	09/06/85	85-0251	USE-AS-IS (3)
33C-CCB-2-H19	BASEPLATE GAP, WLD UNDSZ & INCORRECT DETAIL	09/06/85	85-0253	USE-AS-IS (3)
A-046	WELD UNDSZ	09/06/85	85-0254	USE-AS-IS (3)
A-048	WELD UNDSZ	09/06/85	85-0255	
A-047	WELD UNDSZ	09/06/85	85-0256	USE-AS-IS (3)
A-190	ANCHORBOLTS HAVE 3 WASHERS, BASEPLATE GAPS	09/06/85	85-0257	
33C-HCB-2-H6	NO WASHERS ON TAP BOLTS, 1/2" STUD IN LIEU OF 1/2" TAP BOLT, WLD UNDSZ	09/06/85	85-0258	USE-AS-IS (3)
33C-HCC-124-H7	WELD UNDSZ & DETAIL INCORRECT	09/06/85	85-0259	USE-AS-IS (3)
33C-HCB-2-H40	WLDs UNDSZ	09/06/85	85-0261	USE-AS-IS (3)
33C-HCC-91-H2	BEAMS WRONG SIZE	09/06/85	85-0268	USE-AS-IS (3)
33C-HCC-91-H3	NO WASHERS, BASEPLATE GAP, WLDs UNDSZ	09/06/85	85-0269	USE-AS-IS (3)



SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H13	WELD NOT PER DWG	09/07/85	85-0276	USE-AS-IS (3)
33C-CCB-2-H21	BEAM NOT PER DWG	09/07/85	85-0277	USE-AS-IS (3)
33C-CCB-2-H21	NON STANDARD CLAMP, MISSING JAM NUT, WLD UNDSZ, THDS STAKED, GROUT CRACKED/BROKKN	09/09/85	85-0291	USE-AS-IS (3), REWORK-GROUT UNDER BASEPLATE (4)
33C-CCB-2-H24	WLD UNDSZ, DETAIL NOT CORRECT, TWO NUTS PER STUD	09/09/85	85-0300	USE-AS-IS (3)
A-051	WELDS UNDSZ	09/09/85	85-0305	USE-AS-IS (3)
33C-CCB-2-H16	DIM NOT ON DWG, MISSING JAM NUTS, NON STANDARD CLAMP, CLEVIS CONTACTING CLAMP	09/09/85	85-0307	USE-AS-IS (3), REWORK-INSTALL SPACER (4)
33C-CCB-2-H11	WLD UNDSZ, 1/2" TAP BOLTS IN LIEU OF 1/2" STUDS, WLD DETAIL NOT PER DWG	09/10/85	85-0314	USE-AS-IS (3)
33C-CCB-2-H9	ARC STRIKES PRESENT, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0317	USE-AS-IS (3), REWORK-REMOVE ARC STRIKES & PERFORM NDE
A-050	WLD UNDSZ	09/10/85	85-0318	USE-AS-IS (3)
33C-CCB-2-H10	WSHRS MISSING, BOLTS IN LIEU OF STUDS (4 IN LIEU OF 6), WLD NOT PER DWG	09/10/85	85-0320	USE-AS-IS (3)
33C-CCB-2-H12	STRUT DIM INCORRECT, THDS STAKED, NON-STD CLAMP, MISSING JAM NUT & WELD	09/10/85	85-0321	USE-AS-IS (3)
33A-GCB-8-H4	MISSING WASHERS, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0326	USE-AS-IS (3)
33A-GCB-8-H2	WLD DETAIL NOT PER DESIGN, MEMBER LOCAT DIM NOT PER DWG	09/10/85	85-0327	USE-AS-IS (3)
33A-GCB-8-H6	PIPE CLAMP LOOSE, WLD OVERSZ BY 1/8"	09/10/85	85-0328	USE-AS-IS (3), REWORK TIGHTEN CLAMP (4)
33A-GCB-8-H11	WLD ALL AROUND VS 2 SIDES	09/10/85	85-0329	USE AS IS (3)
33C-CCB-12-H2	WLD NOT PER DWG, BASEPLATE GAP, LOCKNUTS FROZEN, ITEMS MISSING FROM BOM	09/10/85	85-0331	USE-AS-IS (3)
33C-CCB-19-H3	MEMBER DIM & LOC INCORRECT, WLD DETAILS INCORRECT, WASHERS MISSING	09/10/85	85-0333	USE-AS-IS (3), REWORK-MOVE CLAMP, INSTALL WSHRS (4)
33C-CCB-2-H15	NON-STD CLAMP, JAM NUT MISSING, MISSING WELD	09/10/85	85-0339	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H17	DINSON, UNDERCUT, HOLE IN MEMBER, WELD DETAIL, NO COCKNUT, NON STD CLAMP	09/11/85	85-0355	USE-AS-IS (3)
33C-HCC-91-H6	WELD DETAIL	09/11/85	85-0359	USE-AS-IS (3)
33C-HCC-91-H6	WELD DETAIL	09/11/85	85-0360	USE-AS-IS (3)
33C-HCC-91-H9	WELD DETAIL & UNDERSIZE	09/12/85	85-0365	USE-AS-IS (3)
33C-HCC-91-H10	WELD DETAIL, SQ. HD BOLT VS. HEX	09/12/85	85-0366	USE-AS-IS (3)
33C-HCC-91-H5	WELD DETAIL & UND. SIZE	09/12/85	85-0367	USE-AS-IS (3)
33C-HCC-91-H7	WELD DETAIL	09/12/85	85-0368	USE-AS-IS (3)
33C-HCC-91-H4	WELD DETAIL, BIGGER WELD, HGR ASSEMBLY LOOSE	09/12/85	85-0376	USE-AS-IS (3), REWORK-ADJUST (4)
33C-CCB-19-H2	CONC. CHIP., WELD QUALITY, NONSTD CLAMP, NO COCKNUT, DIMENSIONS	09/12/85	85-0377	USE-AS-IS (3)
33C-HCC-91-H12	ORIENTATION ON DWG, WELD DETAIL & UNDERSIZE, COPING, CLEARANCE	09/12/85	85-0379	USE-AS-IS (3)
A-054	PIPE HOLE MADE W/TORCH NOT DRILL, WLDS NOT PER DWG & UNDSZ, SUPP NOT PER DWG	09/13/85	85-0388	
33C-HCC-91-H13	WELD DEFECTS	09/13/85	85-0392	USE-AS-IS (3)
33C-HCC-91-H14	WLD UNDSZ, BASEPLATE SPACING VIOLATION	09/14/85	85-0397	USE-AS-IS (3)
33C-HCC-91-H15	WLDS NOT PER DWG, CORROSION ON BASEPLATE NUTS	09/17/85	85-0483	USE-AS-IS (3), REWORK-REPLACE NUTS (4)
33C-CCB-2-H184		09/18/85	85-0487	USE-AS-IS (3)
33C-CCB-19-H13	HGR BINDING, JAM NUTS MISSING	09/18/85	85-0488	USE-AS-IS (3), REWORK-ADJUST (4)
33C-CCB-19-H9	ITEMS REVERSED ON DWG, WLD UNDSZ, WLD DETAIL NOT POSS	09/19/85	85-0519	USE-AS-IS (3)
33C-CCB-19-H11	WLD UNDSZ, GAPS, WLD DETAIL MISSING ON DWG, CLEARANCE, NO WASHER	09/19/85	85-0520	USE-AS-IS (3), REWORK-REMOVE ARC STRIKES (4)
A-055	SADDLE LENGTH, WLD UNDSZ, DWG DETAIL DISCREP	09/19/85	85-0521	USE-AS-IS (3)

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H1	DIMS, WLD DETAIL, SADDLE LENGTH, DWG REFERENCE	09/20/85	85-0535	USE-AS-IS (3)
33C-CCB-19-H7	WLD UNDSZ, WLD DETAIL, SHIMS NOT ON DWG, BASEPLATE THICKER THAN DWG	09/20/85	85-0540	USE-AS-IS (3)
33C-CCB-2-H2	EXTRA GROUT, CLEARANCE, DIMENSION PROBLEMS, NO WSHRS, WLD DETAIL	09/20/85	85-0541	
33C-CCB-3-H2	DIM DISCREP, WLD DETAIL	09/20/85	85-0552	USE-AS-IS (3)
A-056	DIMENSION DISCREP	09/20/85	85-0553	USE-AS-IS (3)
A-057	DIMENSION DISCREP	09/20/85	85-0554	
33C-CCB-2-H4	LOCKMUT & WSHR MISSING, WLD DETAIL	09/20/85	85-0561	USE-AS-IS (3)
33C-CCB-3-H1	DIM PROBLEMS, WLD DETAILS, ARC STRIKE, BASEPLATE CRACK	09/20/85	85-0576	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
33C-CCB-2-H3	WLD DETAIL, DIM PROBLEM	09/20/85	85-0584	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (2)
33C-CCB-19-H5	WLD UNDSZ	09/20/85	85-0585	USE-AS-IS (3)
33C-CCB-19-H8	WLD UNDSZ & DETAIL, PLATE GAP	09/20/85	85-0586	USE-AS-IS (3)
33C-CCB-2-H6		09/20/85	85-0589	USE-AS-IS (3)
33C-CCB-19-H6		09/21/85	85-0594	USE-AS-IS (3)
33C-CCB-3-H4	DIMENSION, MORE WELD, THD STAKED	09/21/85	85-0596	USE-AS-IS (3)
33C-CCB-2-H23	SHIM DIM, PLATE GAP, WLD DETAIL & UNDSZ	09/23/85	85-0644	
33C-CCB-2-H22	ANCHOR BOLT SPACING WITH OTHER BOLT, DIMENSIONS, PLATE BEARING	09/23/85	85-0650	
33C-CCB-3-H6	WLD DETAIL, DIMENSIONS	09/23/85	85-0655	USE-AS-IS (3)
31-HCC-36-H2	PLATE GAP, WLD DETAIL	09/24/85	85-0666	USE-AS-IS (3)
31-HCC-36-H5	BOLT SPACING, WLD & DIMENSIONS NOT PER DWG	09/25/85	85-0679	USE-AS-IS (3)
31-HCC-36-H6	WLD UNDSZ	09/25/85	85-0680	USE-AS-IS (3)
31-HCC-36-H3	WSHRS MISSING, BASEPLATE GAP UNACC, WLD PER DWG NOT POSSIBLE	09/25/85	85-0681	USE-AS-IS (3)

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
31-HCC-36-H4	WSHRS MISSING, ITEMS 2&3 AND DIMENSIONS NOT PER DWG	09/25/85	85-0682	USE-AS-IS (3)
33C-CCB-2-H18	WLDS NOT PER DWG, GAPS UNACC, MISSING WSHRS & LOCKNUTS	09/25/85	85-0699	USE-AS-IS (3)
33C-CCB-3-H3	NOT FULL BASEPLATE BEARING, DIM & WLDS NOT PER DWG	09/25/85	85-0705	USE-AS-IS (3)
31-HCC-36-H10	DIMEN & WELD NOT PER DWG.	09/25/85	85-0709	USE-AS-IS (3)
31-HCC-36-H8	WLDS & ITEM #3 NOT PER DWG	09/25/85	85-0710	USE-AS-IS (3)
31-HCC-36-H7	BASEPLATE GAP UNACC, ITEM #5 NOT PER DWG	09/25/85	85-0712	USE-AS-IS (3)
33C-CCB-19-H12	WLDS & DIM NOT PER DWG, STRUT BOUND UP, BOLT SPACING VIOLATION	09/25/85	85-0719	USE-AS-IS (3)
31-HCC-36-H11	BOLT SPAC, THDS, DIM, BRACKETS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0723	USE-AS-IS (3)
31-HCC-36-H12	BOLT SPAC & WELDS NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0724	USE-AS-IS (3)
31-HCC-36-H13	WELDS & DIMEN NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0725	USE-AS-IS (3)
31-HCC-36-H14	GAP UNACC, DIMEN & WELDS NOT PER DWG, PIN STAKED, STRUT BOUND.	09/26/85	85-0730	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
31-HCC-36-H16	WELD NOT PER DWG.	09/26/85	85-0731	USE-AS-IS (3)
31-HCC-36-H17	WELD & DIMEN NOT PER DWG.	09/26/85	85-0732	USE-AS-IS (3)
31-HCC-36-H15	WELD & DIMEN NOT PER DWG.	09/26/85	85-0733	USE-AS-IS (3), REWORK-REPLACE ROD (4)
31-HCC-36-H19	WELDS & DIMEN NOT PER DWG, PINS & THDS STAKED.	09/26/85	85-0735	USE-AS-IS (3)
31-HCC-36-H18		09/26/85	85-0736	USE-AS-IS (3)
31-HCC-36-H9	WELDS NOT PER DWG.	09/23/85	85-0742	USE-AS-IS (3)
A-068	WELDS NOT PER DWG, CONC CHIPPED.	09/27/85	85-0762	
31-HCC-36-H20	ABANDONED ANCHORS, WELDS & DIMEN NOT PER DWG.	09/27/85	85-0763	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-191	GROUT LOOSE, DIMENSIONS, WRAPPER THICK, PLATE THICK	10/04/85	85-0861	USE-AS-IS (3)
M-1117-H27	DIMENSIONS	10/11/85	85-1116	USE-AS-IS (3)
M-1117-H26	ADDITIONAL PLATE, DIMENSION	10/11/85	85-1117	USE-AS-IS (3)
M-1117-H9	DIMENSION	10/11/85	85-1119	USE-AS-IS (3)
M-1117-H10	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1120	USE-AS-IS (3)
M-1117-H11	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1121	USE-AS-IS (3)
M-1117-H12	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1122	USE-AS-IS (3)
M-1117-H25	TACK WELD, B/M PROBLEM	10/11/85	85-1123	USE-AS-IS (3)
35-HCC-21-H6	PLATE GAP, DIMENSION	10/11/85	85-1129	USE-AS-IS (3)
35-HCC-21-H14	PLATE GAP	10/11/85	85-1130	USE-AS-IS (3)
35-HCC-21-H10	WELD VS TACK ON SHIM	10/12/85	85-1136	USE-AS-IS (3)
35-HCC-21-H15	WELD DETAIL & SIZE, DIMENSION	10/12/85	85-1137	USE-AS-IS (3)
35-HCC-21-H9	WELD DETAIL, DIMENSION	10/12/85	85-1138	USE-AS-IS (3)
35-HCC-21-H12	PL. GAP, WELD DETAIL	10/12/85	85-1139	USE-AS-IS (3)
35-HCC-21-H11	EDGE DISTANCE, WELD DETAIL, DIMENSION	10/12/85	85-1140	USE-AS-IS (3)
C-800A-511	DIMENSIONS FOR ANCHOR BOLT LOCATION	10/12/85	85-1144	USE-AS-IS (3)
35-HCC-75-H8	WELD SIZE	10/12/85	85-1145	USE-AS-IS (3)
M-1117-H3	DRAWING DETAIL	10/12/85	85-1146	USE-AS-IS (3)
35-HCC-21-H7	DIMENSIONS, WELD SIZE	10/12/85	85-1147	USE-AS-IS (3)
M-1117-H5	DIMENSION	10/12/85	85-1148	USE-AS-IS (3)
M-1117-H7	DIMENSION, C-C BOLT SPACE	10/12/85	85-1149	USE-AS-IS (3)
35-HCC-21-H8	WELD DETAIL	10/12/85	85-1152	USE-AS-IS (3)
M-1117-H4	C-C BOLT SPACE, DIMENSION, BOLT DETAIL, CLAMP BOLT LOOSE	10/12/85	85-1153	USE-AS-IS (3), REWORK-TIGHTEN BOLTS (4)

| 17

| 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
FSK-M-CCB-11-3-H(A )	MATERIAL & CONFIGURATION -- DETAIL A	10/12/85	85-1154	USE-AS-IS (3)
FSK-M-CCB-11-3-H(B )	MATERIAL & CONFIGURATION -- DETAIL B	10/12/85	85-1155	USE-AS-IS (3)
M-1117-H6	C-C BOLT SPACE, NO WEEP HOLD, DIMENSION	10/12/85	85-1156	USE-AS-IS (3)
35-HCC-75-H6	DIMENSIONS, WELD DETAIL	10/14/85	85-1166	USE-AS-IS (3)
A-212	FILLET WELD CHANGED TO FLARE BEVEL	10/14/85	85-1167	USE-AS-IS (3)
A-205	SHIMS UNDER BASE PLATE	10/14/85	85-1168	
35-HCC-21-H16	MEMBER LENGTHS SHORTENED WELD SIZE	10/14/85	85-1170	USE-AS-IS (3)
A-308	PIPE LOCATION	10/22/85	85-1375	USE-AS-IS (3)
CCA-18-1-H2	DIMEN., CLEAR, NOT PER DWG., RUST & FRICTION MARKS ON CYLINDER	10/28/85	85-1498	USE-AS-IS (3), REWORK-ADJUST CLAMP, ADD WSHRS & LOCKWIRE (4)
CCA-18-1-H1	MEMBER NOT PER DRAWING, LOOSE NUT	10/28/85	85-1499	USE-AS-IS (3), REWORK-TIGHTEN NUTS (4)
CCA-18-1-H3A	BOLT & SPRING TRAVEL SETTINGS NOT PER DRAWING	10/28/85	85-1516	
CCA-18-1-H3B	WRONG MATERIAL	10/28/85	85-1517	USE-AS-IS (3)



SECTION 5.0

BORATED WATER STORAGE TANK SUPPLY

(COMMON SUCTION FOR HPI AND LPI SYSTEMS)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-GCB-2-H7	WLD UNDSZ, WLD MISSING, SPR SETTING OFF	09/05/85	85-0219	USE-AS-IS (3)
33A-HCB-1-H1	ANCHORBOLTS OFF, BASEPLATE GAPS, JAM NUT NOT INSTALLED	09/05/85	85-0234	USE-AS-IS (3)
33B-GCB-2-H11	WELD NOT PER SPEC	09/05/85	85-0239	REWORK-ADD WELD (1,2)
33B-GCB-2-H10	WLDs UNDERSIZE	09/05/85	85-0240	USE-AS-IS (3)
33B-GCB-2-H8	ITEMS NOT PER DWG, BEAM UNDSZ	09/05/85	85-0242	USE-AS-IS (3)
33B-GCB-2-H9	WELD UNDSZ, SWAY STRUT BINDING	09/06/85	85-0244	USE-AS-IS (3)
33A-HCB-2-H20	WLD UNDSZ	09/06/85	85-0250	USE-AS-IS (3)
33A-HCB-2-H19	ANCHORBOLTS DEFORMED, BASEPLATE BOWED	09/05/85	85-0262	USE-AS-IS (3), REWORK-INSTALL BEVELED WASHERS (4)
33A-HCB-2-H18	PIPE TO PLATE WELD INACCURATE	09/05/85	85-0263	USE-AS-IS (3)
33A-GCB-4-H3	WASHERS INTERFERE WITH WELD, JAM NUT MISSING	09/06/85	85-0264	USE-AS-IS (3)
33A-HCB-2-H21	WLD UNDSZ	09/06/85	85-0267	USE-AS-IS (3)
33A-GCB-4-H2	ACTUAL WELD VS NO WELD SPECIFIED	09/06/85	85-0272	USE-AS-IS (3)
33A-GCB-4-H1	GAP > 1/8", NO WELD SPECIFIED VS. ACTUAL WELD	09/07/85	85-0275	USE-AS-IS (3)
33A-HCB-2-H22	WASHERS NOT INSTALLED PER PROC, EDGE DIM NOT PER DWG	09/07/85	85-0278	USE-AS-IS (3)
33A-GCB-4-H5	ROD END BUSHING BIND, WLDs NOT PER DWG	09/09/85	85-0287	USE-AS-IS (3)
33A-GCB-4-H4	THDS STAKED, MISSING JAM NUT	09/09/85	85-0288	USE-AS-IS (3)
33A-HCB-2-H17	WLDs NOT PER DWG	09/09/85	85-0289	USE-AS-IS (3)
33A-HCB-2-H17A	ROD END BUSHING BIND, MISSING JAM NUT, WLD NOT PER DWG, SWAY STRUT INTERFERENCE	09/09/85	85-0290	USE-AS-IS (3)
33B-HCB-3-H12	WLD UNDSZ	09/09/85	85-0295	USE-AS-IS (3)
33A-HCB-3-H9	3/8" PLATE IN LIEU OF 1/4", WLDs UNDSZ & NOT PER DWG	09/09/85	85-0297	USE-AS-IS (3)
33A-HCB-3-H6	WLD UNDSZ	09/09/85	85-0298	USE-AS-IS (3)

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-3-H13	WLDs NOT PER DWG	09/09/85	85-0299	USE-AS-IS (3)
33A-HCB-2-H33	WLD UNDSZ, SWAY STRUT BINDING, MEMBER DIM INCOR, INTERFERENCE W/OTHER SUPPORT	09/09/85	85-0306	USE-AS-IS (3)
A-039	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0323	USE-AS-IS (3), REWORK-REPLACE WASHERS (4)
A-038	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0324	USE-AS-IS (3)
33A-HCB-2-H4	NO WASHERS, MISSING JAM NUT, THDS STAKED, DIM NOT PER SPEC	09/11/85	85-0343	USE-AS-IS (3)
33A-HCB-2-H16	1/2" DIM NOT PER SPEC, LOCKNUT & JAM NUTS MISSING	09/11/85	85-0344	USE-AS-IS (3), REWORK-TIGHTEN NUTS (4)
33A-HCB-2-H5	1/2" DIM NOT PER SPEC, THDS STAKED, LOCKNUT MISSING	09/11/85	85-0345	USE-AS-IS (3)
33A-HCB-2-H29	WELD UNDERSIZE	09/11/85	85-0350	USE-AS-IS (3)
33A-HCB-2-H27	1/2" G.P., NO LOCK NUT	09/11/85	85-0351	USE-AS-IS (3)
33A-HCB-2-H6	WELD DETAIL & UNDERSIZE, ARC STRIKE, UNDERCUT, DIMENSION	09/12/85	85-0369	USE-AS-IS (3)
33A-HCB-2-H28	WELD UNDERSIZE & DETAIL, DIMENSIONS, AND STAKED, FIG 88 ROTATED	09/12/85	85-0371	USE-AS-IS (3)
33A-HCB-2-H9	BASEPLATE GAP, THDS STAKED, WLDs UNDSZ	09/14/85	85-0402	USE-AS-IS (3)
33A-HCB-2-H44	ANCHOR BOLTS NOT TORQUED, WLDs UNDSZ	09/14/85	85-0403	USE-AS-IS (3), REWORK - STAMP HANGER # ON SUPPORT (4)
33A-HCB-2-H12	BASEPLATE GAP, THDS STAKED	09/14/85	85-0404	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
33A-HCB-2-H11	THDS STAKED, WLD UNDSZ	09/14/85	85-0405	USE-AS-IS (3), REWORK
33A-HCB-2-H15	GROUT THCK NOT PER DWG, WLD UNDSZ	09/14/85	85-0406	USE-AS-IS (3)
33A-HCB-2-H10	BASEPLATE GAP, WLD UNDSZ & NOT PER DWG	09/14/85	85-0407	USE-AS-IS (3)
33A-HCB-2-H31	NO DWG SPECS ON BASEPLATE, WLD UNDSZ	09/14/85	85-0408	USE-AS-IS (3), REWORK-
33A-HCB-2-H1	ANCHORS NOT PER DWG	09/14/85	85-0409	USE-AS-IS (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-2-H14	WLD UNDSZ, THDS STAKED	09/14/85	85-0410	USE-AS-IS (3)
33A-HCB-2-H30	BASEPLATE GAP, WLD NOT PER DWG	09/14/85	85-0411	USE-AS-IS (3)
33A-HCB-2-H26	ITEM UNDSZ	09/14/85	85-0412	USE-AS-IS (3)
33A-HCB-2-H24	WLD UNDSZ	09/14/85	85-0413	USE-AS-IS (3)
33A-HCB-2-H32	WLD NOT PER DWG	09/14/85	85-0415	USE-AS-IS (3)
33A-HCB-2-H25	WLDS NOT PER DWG	09/14/85	85-0416	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
33A-HCB-2-H3	WSHRS & JAM NUTS MISSING, LUGS UNDSZ, THDS STAKED, WLD UNDSZ	09/14/85	85-0417	USE-AS-IS (3)
33A-HCB-2-H23	ITEM #1 WRONG DIM, SHIMS INSTALLED INCOR, WLD UNDSZ	09/14/85	85-0418	USE-AS-IS (3)
33A-HCB-2-H8	THDS STAKED, CLAMP INCOR DIM	09/14/85	85-0419	USE-AS-IS (3)
33A-HCB-2-H13	WLDS NOT PER DWG & UNDSZ, BASEPLATE GAP	09/14/85	85-0420	USE-AS-IS (3)

SECTION 6.0  
SERVICE WATER SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBB-7-H1	WLDs NOT PER DWG	09/14/85	85-0423	USE-AS-IS (3), REWORK-TIGHTEN (4)
41-HBB-7-H3	DETAILS & ITEMS INCORRECT	09/14/85	85-0424	USE-AS-IS (3)
41-HBB-7-H2	DETAILS INCOR, LOCK NUTS MISSING, CLAMP MISALIGNED	09/14/85	85-0425	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
41-HBC-35-H40	WLDs NOT PER DWG, LOOSE JAM NUT	09/14/85	85-0426	USE-AS-IS (3), REWORK-TIGHTEN JAM NUT (4)
41-HBC-35-H39	WLDs NOT PER DWG	09/14/85	85-0427	USE-AS-IS (3)
41-HBC-35-H41	WLDs NOT PER DWG, STRUT IS BOUND	09/14/85	85-0428	USE-AS-IS (3)
41-HBC-35-H36	WLDs NOT PER DWG	09/17/85	85-0462	USE-AS-IS (3)
41-HBB-7-H4	WLD SYMBOL NOT ON DWG, CLEARANCE, WLD DETAIL	09/19/85	85-0531	USE-AS-IS (3)
41-HBB-7-H5	WLD DETAIL, LOCKNUT MISSING, STRUT BINDING, INSTALLED SECTION VS DWG	09/19/85	85-0533	USE-AS-IS (3), REWORK-REALIGN PIPE CLAMP (4)
41-HBB-7-H6	WLD DETAIL, STRUT BINDING, LOCKNUT MISSING, PLATE THICKNESS	09/19/85	85-0534	USE-AS-IS (3), REWORK-REALIGN PIPE CLAMP (4)
41-HBC-35-H38		09/20/85	85-0548	USE-AS-IS (3)
A-197	BASEPLATE GAP	09/20/85	85-0575	USE-AS-IS (3)
41-HBC-35-H50	NO WLD SYMBOL ON DWG	09/20/85	85-0581	USE-AS-IS (3)
A-312	WLD UNDSZ, PLATE GAP	09/20/85	85-0582	USE-AS-IS (3)
41-HBC-35-H49	DIMENSION	09/21/85	85-0592	USE-AS-IS (3)
41-HBC-35-H12	THDS STAKED, WLDs NOT PER DWG, BOLTS BENT, ORIENTATION DISCREP ON DWG	09/25/85	85-0676	USE-AS-IS (3), REWORK-REPLACE BOLTS (4)
41-HBC-35-H8	THDS STAKED, WLDs NOT PER DWG	09/25/85	85-0677	USE-AS-IS (3)
A-141	WSHRS MISSING, BASEPLATE GAP, WLDs NOT PER DWG	09/25/85	85-0684	USE-AS-IS (3)
41-HBC-35-H3	WSHRS MISSING, BASEPLATE GAP, THDS STAKED	09/25/85	85-0690	USE-AS-IS (3)
41-HBC-35-H2	THDS STAKED	09/25/85	85-0691	USE-AS-IS (3)



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
41-HBC-35-H1	BOLTS INSTALLED IN EMBED PLATE, WLDG UNDSZ	09/25/85	85-0692	USE-AS-IS (3)
41-HBC-35-H5	THDS STAKED, WSHRS MISSING, ITEM #3 NOT PER DWG	09/25/85	85-0693	USE-AS-IS (3)
41-HBC-35-H10	WLDG NOT PER DWG	09/25/85	85-0697	USE-AS-IS (3)
41-HBC-35-H54	THDS STAKED, DIM NOT PER DWG, LOOSE SPACER	09/25/85	85-0714	USE-AS-IS (3)
41-HBC-35-H53	THDS STAKED, CLAMP JAMMED	09/25/85	85-0715	USE-AS-IS (3)
A-198	NO WELD DET.	09/26/85	85-0744	USE-AS-IS (3)
41-HBC-44-H1	BASEPLATE GAP UNACC.	09/26/85	85-0752	USE-AS-IS (3)
41-HBC-35-H7	WELDS & DIMEN NOT PER DWG, MISSING WASHERS, DAMAGED STEEL MEMBER.	09/26/85	85-0753	USE-AS-IS (3)
41-HBC-44-H2	DIMEN & WELDS NOT PER DWG.	09/26/85	85-0754	
41-HBC-35-H10A	BASEPLATE GAP UNACC, WELD NOT PER DWG.	09/26/85	85-0755	USE-AS-IS (3)
41-HBC-35-H11	THDS STAKED, DIMEN NOT PER DWG.	09/27/85	85-0765	USE-AS-IS (3)
A-007	WELD ALL-ROUND VS TWO SIDES	09/30/85	85-0781	USE-AS-IS (3)
41-HBC-46-H52	MEMBER SIZE, WELD DETAIL	10/04/85	85-0868	
41-HBC-47-H53	THD STAKED, DIMENSIONS	10/04/85	85-0870	
41-HBC-47-H10	THD STAKED	10/04/85	85-0871	USE-AS-IS (3)
A-153	SADDLE PLATE THICK	10/04/85	85-0872	USE-AS-IS (3)
A-155	SADDLE PLATE THICK, WELD UNDERSIZE	10/04/85	85-0873	USE-AS-IS (3)
A-151	WELD NOT GROUND & UNDERSIZE	10/04/85	85-0874	
A-152	PLATE SIZE, WELD UNDERSIZE	10/04/85	85-0875	USE-AS-IS (3)
A-149	SADDLE PLATE THICK	10/04/85	85-0876	USE-AS-IS (3)
A-150	SADDLE PLATE THICK	10/04/85	85-0877	USE-AS-IS (3)
41-HBC-47-H52	MEMBER SIZE, WELD SIZE 1/4 DETAIL	10/04/85	85-0878	
A-159	WELD UNDERSIZE	10/04/85	85-0879	

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-156	PLATE DIMENSION, WELD UNDERSIZE	10/04/85	85-0860	
41-HBC-46-H10	THD STAKED	10/04/85	85-0881	USE-AS-IS (3)
A-160	WELD UNDERSIZE	10/04/85	85-0882	
41-HBC-46-H32	SHIM DETAIL	10/05/85	85-0896	
41-HBC-46-H33	SHIM DETAIL	10/05/85	85-0897	
41-HBC-47-H33	SHIM DETAIL	10/05/85	85-0898	
41-HBC-47-H32	PLATE GAP, 8 BOLTS VS. 10, 2 BOLTS VS. 4, WELD DETAIL & UNDERSZ	10/05/85	85-0899	
41-HBC-46-H34	SHIM DETAIL, WELD DETAIL	10/05/85	85-0900	
41-HBC-47-H34	WELD DETAIL	10/05/85	85-0901	
41-HBC-46-H37	SHIM DETAIL	10/05/85	85-0902	
41-HBC-46-H36	SHIM DETAIL	10/05/85	85-0903	
41-HBC-46-H35	SHIM DETAIL	10/05/85	85-0904	
41-HBC-47-H35	PLATE GAP, WELD DETAIL & UNDERSIZE	10/05/85	85-0905	
41-HBC-46-H25	SHIMS NOT PER SPEC	10/07/85	85-0948	USE-AS-IS (3)
41-HBC-47-H24	WLD DETAIL NOT ON DWG, EXCESS WLD METAL	10/07/85	85-0949	USE-AS-IS (3)
41-HBC-46-H24	SHIMS NOT PER SPEC	10/07/85	85-0950	USE-AS-IS (3)
41-HBC-47-H23	BASEPLATE GAP, WLD MISSING	10/07/85	85-0951	USE-AS-IS (3)
41-HBC-47-H25	BASEPLATE GAP, SHIMS NOT PER SPEC	10/07/85	85-0952	USE-AS-IS (3)
41-HBC-46-H29	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/08/85	85-0965	USE-AS-IS (3), REWORK-WELD SHIM PLATES (4)
41-HBC-46-H31	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/08/85	85-0966	USE-AS-IS (3), REWORK-WELD SHIM PLATES (4)
41-HBC-47-H30	SHIM NOT SHOWN ON DWG.	10/08/85	85-0967	USE-AS-IS (3)
41-HBC-46-H30	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/08/85	85-0968	USE-AS-IS (3), REWORK-WELD SHIM PLATES (4)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBC-47-H15	WLD DETAIL INCORRECT, MEMBER LOCATION NOT PER DWG.	10/08/85	85-0969	USE-AS-IS (3)
41-HBC-46-H15	SHIM SIZE NOT ON DWG, WLD DETAIL INCORRECT	10/08/85	85-0970	USE-AS-IS (3)
41-HBC-46-H50	CLEARANCE WELD DETAIL & UNDERSIZE B/M PROBLEMS	10/07/85	85-0974	
41-HBC-47-H16	WELD DETAIL & SIZE CLEARANCE	10/09/85	85-0984	
41-HBC-47-H11	B/M PROBLEM DIMENSIONS WELD DETAIL & SIZE UNDERCUT	10/09/85	85-0986	
41-HBC-46-H28	SHIM DETAIL	10/09/85	85-0989	
41-HBC-47-H27	LUG SIZE DIMENSION	10/09/85	85-0990	
41-HBC-46-H27	SHIM DETAIL	10/09/85	85-0991	
41-HBC-47-H26	WELD DETAIL & SIZE, UNDERCUT, PL. GAP	10/09/85	85-0992	
41-HBC-46-H22	WELD DETAIL & SIZE, DIMENSION	10/09/85	85-0995	
41-HBC-47-H22	WELD DETAIL & SIZE	10/09/85	85-0996	
41-HBC-47-H49	WELD DETAIL, PL. GAP, DIMENSION	10/09/85	85-0997	
41-HBC-46-H49	WELD DETAIL	10/09/85	85-0998	
41-HBC-47-H29	BOLT SPACE WELD DETAIL & SIZE PL. GAP SHIM INSTALLED	10/09/85	85-1005	
41-HBC-46-H26	WELD SIZE SHIM DETAIL LUG SIZE	10/09/85	85-1006	
41-HBC-46-H1	WELD DETAIL	10/09/85	85-1018	USE-AS-IS (3)
41-HBC-47-H1	WELD DETAIL, CLEARANCES	10/09/85	85-1019	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBC-46-H47	WELD SIZE	10/09/85	85-1039	
41-HBC-47-H46	WELD SIZE	10/09/85	85-1040	
41-HBC-46-H46	WELD SIZES	10/09/85	85-1042	
41-HBC-47-H45	WELD SIZES	10/09/85	85-1043	USE-AS-IS (3)
41-HBC-46-H45	WELD SIZES	10/09/85	85-1044	USE-AS-IS (3)
41-HBC-47-H47	BASE PLATE SHIMS & GAPS, WELDS	10/09/85	85-1045	
41-HBC-47-H7	WELD PROBLEMS	10/10/85	85-1066	
41-HBC-47-H6	WELD PROBLEMS	10/10/85	85-1067	
41-HBC-47-H18	WELD SIZES ON LUGS	10/10/85	85-1068	USE-AS-IS (3)
41-HBC-47-H19	WELD SIZES	10/10/85	85-1069	
41-HBC-46-H18	WELD MISSING	10/10/85	85-1070	USE-AS-IS (3)
41-HBC-46-H19	WELDS ON LUGS	10/10/85	85-1071	
41-HBC-46-H20	WELD SIZES & TYPES	10/10/85	85-1072	
41-HBC-47-H21	WELD SIZES	10/10/85	85-1073	USE-AS-IS (3)
41-HBC-46-H21	WELD SIZES, END OF BEAM CLIPPED	10/10/85	85-1074	
41-HBC-46-H7		10/10/85	85-1077	
41-HBC-47-H4	SHIMS UNDER BASE PLATE	10/10/85	85-1084	USE-AS-IS (3)
41-HBC-47-H9	WELD SIZE, DIMENSIONS	10/10/85	85-1085	
41-HBC-47-H3	WELD SIZES, DIMENSIONS	10/10/85	85-1086	
41-HBC-47-H51	WRAPPER PLATE THK. INCREASED	10/10/85	85-1087	
41-HBC-46-H4	SHIM DETAIL	10/10/85	85-1092	USE-AS-IS (3)
41-HBC-46-H13	WELD DETAIL	10/10/85	85-1093	
41-HBC-46-H2	WELD DETAIL, DIMENSION	10/10/85	85-1094	USE-AS-IS (3)
41-HBC-47-H12	WELD DETAIL	10/10/85	85-1095	

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBC-47-H13	DIMENSION, WELD DETAIL	10/10/85	85-1096	
41-HBC-47-H17	3 WASHERS ON BOLT, PL. GAP, WELD DETAIL & SIZE	10/11/85	85-1103	
41-HBC-47-H20	WELD SIZE & DETAIL	10/10/85	85-1108	
41-HBC-46-H38	MEMBER SIZE, ANCHOR BOLT, PLATE GAP, WELD DETAIL, DIMENSION QUANTITIES VS. B/M	10/15/85	85-1178	
41-HBC-47-H41	SHIM DETAIL	10/15/85	85-1181	
41-HBC-47-H40	DRAWING CONFLICT/ SHIM	10/15/85	85-1182	
41-HBC-46-H40	DRAWING CONFLICT/SHIM	10/15/85	85-1183	
41-HBC-46-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1184	
41-HBC-47-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1185	
41-HBC-47-H38	SHIM DETAIL, DRAWING CONFLICT/SHIM	10/15/85	85-1186	
41-HBC-46-H44	SHIM DETAIL	10/15/85	85-1187	
41-HBC-47-H43	SHIM DETAIL	10/15/85	85-1188	
41-HBC-47-H42	SHIM DETAIL	10/15/85	85-1189	USE-AS-IS (3)

SECTION 7.0

CONTAINMENT SUMP -- ECCS SUPPLY



SYSTEM: CTMT SUMP - ECCS SUPPLY

DAVIS - BESSC PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-HCB-1-H4	WASHERS MISSING, WLDS NOT PER DWG	09/13/85	85-0386	USE-AS-IS (3)
33A-GCB-8-H12	PIPE CLAMP NOT TIGHT, WLD UNDSZ	09/13/85	85-0387	USE-AS-IS (3), REWORK-TIGHTEN (4)
33B-HCB-1-H2	ITEMS NOT PER DWG, NO WSHRS UNDER ANCHOR BOLTS	09/13/85	85-0395	USE-AS-IS (3), REWORK-ADJUST (4)
33C-GCB-7-H7	WLDS NOT PER DWG	09/17/85	85-0456	USE-AS-IS (3)
33C-GCB-7-H9		09/17/85	85-0463	USE-AS-IS (3)
33A-GCB-8-H13	ITEM #15 NOT PER DWG	09/17/85	85-0464	USE AS IS (3)
33C-GCB-7-H8	BASEPLATE UNACC, SWAY STRUT BOUND	09/17/85	85-0476	USE-AS-IS (3)
33B-HCB-1-H3	BASEPLATE UNACC BEARING SURFACE	09/17/85	85-0482	USE-AS-IS (3)
10B-HCC-69-H22	NUT MISSING	09/19/85	85-0515	REWORK-REPLACE NUT (4)
A-323	MIN. BOLT SPACING VIOLATION	10/07/85	85-0938	
46-HBB-2-H4	INPROPER SHIM, UNDSZ & MISSING WLDS, CLR GAP INCORRECT, WLD DETAIL MISSING	10/07/85	85-0939	
46-HBB-2-H1	WLDS UNDSZ, BOLT LOCATION INCORRECT	10/07/85	85-0943	USE-AS-IS (3)
46-HBB-2-H2	NO WELD SYMBOL	10/09/85	85-0988	

SECTION 8.0  
HYDROGEN DILUTION SYSTEM

SYSTEM: HYDROGEN DILUTION  
DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
29-HBC-73-H5	JAM NUT MISSING, CLAMP NEEDS REALIGN, BUSHING FREE TO ROTATE	09/19/85	85-0514	
29-HBB-15-H10	ITEMS 1&2 NOT PER DWG, WLDS NOT PER DWG	10/03/85	85-0813	
29-HBB-15-H9	WLDS NOT PER DWG, BASEPLATE GAP	10/03/85	85-0831	
29-HCB-43-H1	WLDS NOT PER DWG, WLD GAPS, SLAG ON WLDS, CAULKING UNDER BASEPLATE,	10/03/85	85-0833	USE-AS-IS (3)
29-HBB-15-H8	WSHR MISSING, DIM NOT PER DWG	10/03/85	85-0835	USE-AS-IS (3), REWORK-INSTALL WSHRS (4)
29-HBB-15-H7	DIMENSIONS	10/04/85	85-0863	USE-AS-IS (3)

SECTION 9.0  
PRESSURIZER RELIEF SYSTEM

SYSTEM: PRESSURIZER RELIEF SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
30-CCA-8-H4	THD STAKED	10/05/85	85-0909	USE-AS-IS (3)
30-CCA-8-H5	PLATE GAP, WELD UNDERSIZE, THD STAKED	10/05/85	85-0910	USE-AS-IS (3)
30-GCC-8-H9	PLATE GROUTED, WELD DETAIL & UNDERSIZE, WASHER MISSING, NO I.D. TAG	10/05/85	85-0911	USE-AS-IS (3), REWORK-ADD WASHER (4)
30-GCC-8-H16	PLATE GROUTED, DIMENSION, WELD DETAIL & UNDERSZ, CLAMP BOLT/SPACER LOOSE, THD STK	10/05/85	85-0912	USE-AS-IS (3), REWORK-TIGHTEN LOOSE NUTS (4)
30-GCC-8-H5	WELD DETAIL & UNDERSIZE, CONCRETE SPALLING	10/05/85	85-0914	USE-AS-IS (3)
30-GCC-8-H13	PLATE GROUTED, PLATE GAP, WELD DETAIL & SIZE, FLUID LEAK	10/05/85	85-0919	
30-GCC-8-H10	BLT ANGLE, PL. GAP, NO SNAPPING, STRUT BINDING, CL. SPACER BOLT LOOSE	10/05/85	85-0920	USE-AS-IS (3), REWORK-(2), FURTHER INSPECTION REQUIRED
30-GCC-8-H6	PL. OVERLAPS CONC., PL GAP & GROUTED, WELD DET. & UNDERSZ, THD STKD, LOOSE NUT,	10/05/85	85-0921	USE-AS-IS (3), REWORK-(2), FURTHER INSPECTION REQUIRED
30-GCC-8-H4	THDS STAKED, BASEPLATE 8X8 VS 10 X 10, WLD UNDSZ	10/07/85	85-0935	USE-AS-IS (3)
30-GCC-8-H3	THDS STAKED, 5/8" HILTI VS. 1/2" WET-IT, WLD MISSING, CLAMP SPACER LOOSE	10/07/85	85-0936	USE-AS-IS (3)
30-GCC-8-H17	MISSING BUSHING WASHERS, LOOSE SPACERS, WLD UNDSZ, MIN. THD ENGAGEMENT	10/07/85	85-0941	USE-AS-IS (3), REWORK-REPLACE MISSING WASHERS (4)
30-GCC-8-H1	GROUT ALONG BASEPLATE, WLD DETAILS INCORRECT	10/08/85	85-0960	USE-AS-IS (3)
30-GCC-8-H2	BOLT MIN. DIST. VIOLATION, GROUT ALONG BASEPLATE	10/08/85	85-0961	USE-AS-IS (3)
M-1140-H1	BOLT MIN. DIST. VIOLATION, LOOSE JAM NUT, BASEPLATE GAP	10/08/85	85-0964	USE-AS-IS (3), REWORK-TIGHTEN NUTS (4)
30-CCA-8-H6	PL. THICK	10/09/85	85-1020	USE-AS-IS (3)
A-304	WELD DETAIL & SIZE	10/09/85	85-1021	USE-AS-IS (3)
A-307	WELD SIZE	10/09/85	85-1022	
FSK-M-CCB-25-1-A1	MATERIAL CHANGE, WELD ADDED, DIMENSIONS	10/22/85	85-1387	
M-1142-H22	ANCHOR BOLT THD. ENGAGE & WELD NOT PER DRAWING	10/29/85	85-1531	

(17)

SYSTEM: PRESSURIZER RELIEF SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1142-H23	WELD NOT PER DRAWING	10/29/85	85-1532	
CCA-B-H1	HILTI VS WEJ-IT, WLD UNDSZ, PLATE GROUTED	11/04/85	85-1688	
CCA-B-H2	WLD UNDSZ, BOLT MIN. EDGE DIST	11/04/85	85-1690	

17



SECTION 10.0  
PRESSURIZER SURGE SYSTEM

SYSTEM: PRESSURIZER BURGE SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PSU-H1	BASEPLATE GAP, SPRING LOAD COLUMN MISALIGNED	10/07/85	85-0937	
3A-EB0-19-H154	WLD8 UNDSZ, SHIM TACK WELDED	10/07/85	85-0940	USE-AG-19 (3)
PSU-R1	WLD8 UNDSZ, BASEPLATE GP, MISSING ID TAG	10/07/85	85-0942	
PSU-R3	BASEPLATE GAP, WLD UNDSZ	10/08/85	85-0958	
PSU-R2	TAG PL-GAP THREAD STAKED CLAMP BOLT LOOSE	10/09/85	85-1003	

SECTION 11.0  
CONTAINMENT SPRAY SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
34-HCB-4-H17	GAPS NOT PER DWG, ITEM NOT PER DWG, WLDS NOT PER DWG, PIPE GOUGED	10/03/85	85-0814	
34-HCB-4-H21	SUPP NOT PAINTED, WLDS ARE: UNDSZ, NOT POSS, & NOT PER DWG	10/03/85	85-0815	USE-AS-IS (3), REWORK-PAINT SUPPORT (4)
34-HCB-4-H27	WLDS NOT PER DWG	10/03/85	85-0816	USE-AS-IS (3)
34-HCB-4-H33	WLDS NOT PER DWG, THDS STAKED	10/03/85	85-0817	USE-AS-IS (3)
34-HCB-4-H35	WLDS NOT PER DWG	10/03/85	85-0818	USE-AS-IS (3)
34-HCB-4-H22	ANCHOR BOLTS STAKED, WLDS UNDSZ & NOT PER DWG	10/03/85	85-0819	USE-AS-IS (3)
34-HCB-4-H34	WLDS NOT PER DWG	10/03/85	85-0820	USE-AS-IS (3)
30-BCC-8-H8	WSHRS INSTALLED INCORR, BASEPLATE GAP GROUTED	10/03/85	85-0821	USE-AS-IS (3), REWORK-INSTALL WASHERS & LOCKWIRE (4)
30-BCC-8-H7	WLDS UNDSZ, PIPE CLAMP BINDING, BASEPLATE DIM INCORR	10/03/85	85-0822	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
34-HCB-4-H5	WLDS NOT PER DWG & NOT POSS	10/03/85	85-0823	USE-AS-IS (3)
34-HCB-4-H7	WLDS NOT PER DWG	10/03/85	85-0824	USE-AS-IS (3)
34-HCB-4-H6	WLDS NOT PER DWG & NOT POSS	10/03/85	85-0825	USE-AS-IS (3)
34-HCB-4-H28		10/03/85	85-0830	USE-AS-IS (3), REWORK-ADJUST RODS (4)
34-HCB-4-H9	WLDS NOT PER DWG & UNDSZ, SLAG ON WLDS	10/03/85	85-0832	USE-AS-IS (3)
34-HCB-4-H44	PLATE SPE, DIMENSIONS, NO SIGHT HOLE, CLAMP LOCATION, WELDSZ VS. DWG, "5" DIMENSIO	10/03/85	85-0858	USE-AS-IS (3), REWORK-MOVE PIPE CLAMP (4)
34-HCB-4-H15	WELD DETAIL	10/03/85	85-0859	USE-AS-IS (3), REWORK-REMOVE ADDIT WIRE & PIPE ON SUPP (4)
34-HCB-4-H16	CLEARANCE, WELD DETAIL & UNDERSIZE	10/04/85	85-0860	
34-HCB-4-H10	WELD DETAIL, SLAG	10/04/85	85-0862	USE-AS-IS (3)
34-HCB-4-H8	WELD DETAIL, BASE METAL REDUCTION, SLAG, UNDSZ, OVERLAP, CLEARANCE	10/04/85	85-0864	USE-AS-IS (3)
34-HCB-4-H42	WELD DETAIL & SIZE, CLEARANCE	10/04/85	85-0865	USE-AS-IS (3)

17

17

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
34-HCB-4-H4	LD DETAIL & SIZE	10/04/85	85-0866	USE-AS-IS (3)
34-HCB-4-H29	NO TACK WELD	10/04/85	85-0867	REWORK-TACKWELD (4)
A-077	CAULKING COVERS GAP	10/04/85	85-0869	USE-AS-IS (3)
34-HCB-4-H11	ARC STRIKE, WELD DETAIL & UNDERSIZE, CLEARANCE	10/05/85	85-0906	USE-AS-IS (3), REWORK-REMOVE ARC STRIKE (4)
34-HCB-4-H32	DWG SHOWS NO WELD SIZE, DIMENSIONS, WELD DETAIL, FLUID LEAKAGE	10/05/85	85-0908	USE-AS-IS (3)
34-HCB-4-H40	WELD DETAIL & SIZE, NO SITE HOLE, THD STAKED, LOOSE NUT	10/05/85	85-0915	USE-AS-IS (3), REWORK-TIGHTEN CLAMP BOLT (4)
34-HCB-4-H14	WELD DETAIL & SIZE	10/05/85	85-0916	USE-AS-IS (3), REWORK-REMOVE PIPE SECTIONS (4)
34-HCB-4-H30	MEMBER SIZE, WELD DETAIL, CLEARANCE	10/05/85	85-0917	USE-AS-IS (3)
34-HCB-4-H13	WELD DETAIL & SIZE	10/05/85	85-0918	USE-AS-IS (3), REWORK-REMOVE PIPE SECTIONS (4)
34-HCB-4-H20	BASEPLATE 1/2" VS 1", 4 BOLTS VS 6, UNDSZ MISSING WELDS	10/07/85	85-0934	USE-AS-IS (3)
34-HCB-4-H19	UNDSZ WLD, WLD DETAIL NOT ON DWG, MEMBER SIZE INCORRECT	10/07/85	85-0953	USE-AS-IS (3)
34-HCB-4-H41	WELD DETAIL & SIZE	10/09/85	85-0983	USE-AS-IS (3)
34-HCB-4-H18	PL. GAP	10/11/85	85-1115	USE-AS-IS (3)
34-HCB-4-H19A	NO B.O.M., WELD & DIMEN. NOT PER DRAWING, MISSING BOLT LOCATIONS	10/29/85	85-1515	USE-AS-IS (3)

17

SECTION 12.0

MISCELLANEOUS WASTE DRAIN SYSTEM



SYSTEM: MISC WASTE DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
unidentified	EXTRA HANGER	10/04/85	85-0891	

SECTION 13.0

SPENT FUEL POOL PIPING SYSTEM

SYSTEM: SPENT FUEL POOL PIPING

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE *	NCR/SR NUMBER	DISPOSITION
unidentified	EXTRA HANGER	10/04/85	85-0892	USE-AS-IS (3)
A-219	ANCHOR LOCATION	10/04/85	85-0894	

SECTION 14.0

MAKEUP WATER TREATMENT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
10B-HCB-23-H7	READHEAD VS. WEJIT WELD DETAIL DIMENSION EXTRA HOLES IN PLATE	10/09/85	85-1004	

SECTION 15.0  
PRESSURIZER SPRAY SYSTEM



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PS-H7	WELD SIZE, UNDERCUT, PL-GAP	10/09/85	85-1023	
PS-H6	WELD DETAIL & SIZE, PL. GAP, UNDERCUT	10/09/85	85-1024	
PS-H5	PIPE CLAMP	10/10/85	85-1057	
PS-H4	PIPE CLAMP	10/10/85	85-1058	
PS-H21	BASE PLATE GAPS	10/10/85	85-1059	
PS-H20	WELD TYPES, DIMENSIONS, GROUT ADDED	10/10/85	85-1060	
PS-H23	DIMENSIONS FOR PIPE OFFSET	10/10/85	85-1061	
PS-H10	WELD TYPE, BASE PLATE & BOLTS	10/10/85	85-1062	
PS-H9	WELDS, SLAG & GROUT	10/10/85	85-1063	
PS-H8	WELD TYPE & GROUT ADDED	10/10/85	85-1064	
PS-H22	PIPE CLAMP	10/10/85	85-1075	
PS-H27	WELDS & SNUBBER PROBLEMS	10/10/85	85-1076	
PS-H19	BENT ROD, ANCHOR BOLT SPACING	10/10/85	85-1080	
PS-H18	WELD, SNUBBER SETTING, PIPE OFFSET, BASE PLATE	10/10/85	85-1081	
PS-H17	WELDS, PIPE OFFSET, SNUBBER ASS	10/10/85	85-1082	
PS-H1	WELD DETAIL & SIZE, PL. GAP	10/10/85	85-1097	
PS-H2	TORQUE FAILS 1 BOLT, WELD DETAIL, PL. GAP	10/10/85	85-1098	
PS-H3	PL. GAP, WELD DETAIL	10/10/85	85-1099	
PS-H13	GROUT, THREAD ENGAGEMENT, J WASHER ON BOLT, PL GAP, WELD SYMBOL	10/10/85	85-1104	
PS-H12	GROUT, WELD SYMBOL	10/10/85	85-1105	
PS-H14	GROUT, HILTI VS. WEJ-IT, WELD SYMBOL	10/10/85	85-1106	
PS-H11	GROUT	10/10/85	85-1107	
PS-H32	WELD DETAIL	10/10/85	85-1110	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PS-H33	PL. GAP, WELD SYMBOL	10/10/85	85-1111	
PS-H34	MIN. EDGE DIST, GROUTED, THREAD STAKED	10/10/85	85-1112	
PS-H31	GROUT, WELD DETAIL	10/11/85	85-1114	
PS-H35	WLD DETAIL, LOCKNUT LOOSE	10/11/85	85-1118	
PS-H30	C-C ANCHOR SPACING, WLD DETAIL & SIZE	10/11/85	85-1124	
PS-H29	GROUT, WELD DETAIL & SIZE, CLAMP BEARING, SPACER MISSING, GREASE FITTING DAMAGE	10/11/85	85-1125	
PS-H15	WELD SIZE, P-P DIMENSIONS, DIMENSIONS, TAG	10/11/85	85-1126	
PS-H16	DIMENSION, DRAWING NOTE, THREAD ENGAGEMENT, GROUT	10/11/85	85-1127	
PS-H37	DIMENSION, WELD DETAIL, GREASE FITTING DAMAGE	10/12/85	85-1141	
PS-H28	WELD SIZE & DETAIL, GREASE FITTING DAMAGE, EXTRA PLATE	10/12/85	85-1142	
PS-H36	ANCHOR BOLT NO TORQUE, PC GAP, WELD DETAIL & SIZE, BOLT MISSING, GREASE FIT. DAM	10/12/85	85-1143	
M-CCA-7-1-H16	WLD DETAIL, EDGE DISTANCE, DIMENSION	11/11/85	85-1881	
M-CCA-7-1-H13	WLD SZ & DETAIL	11/11/85	85-1882	
M-CCA-7-1-H15	WLD SZ, DIMENSION	11/11/85	85-1883	
M-CCA-7-1-H14	DIMENSIONS	11/11/85	85-1884	
M-CCA-7-1-A5	DIMENSION	11/11/85	85-1885	
M-CCA-7-1-A2	WLD DETAIL, MEMBER SZ	11/11/85	85-1886	
M-CCA-7-1-H2	DIMENSION	11/12/85	85-1981	
M-CCA-7-1-H6	DIMENSION, GAP	11/12/85	85-1982	
M-CCA-7-1-H7	DIMENSION, GAP	11/12/85	85-1983	

SECTION 16.0  
REACTOR COOLANT SYSTEM

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
40-CCB-16-45	THREAD ENGAGE, WELD DETAIL & SIZE, HILTI VS. WEJ-IT, DIMENSIONS	10/12/85	85-1150	
40-CCB-16-41	DIMENSION	10/12/85	85-1151	
40-CCB-16-H2	CLEARANCE, DIMENSION, WELD DETAIL	10/14/85	85-1159	
40-CCB-16-H3	PL. GAP, ANCHOR BOLT NO TORQUE, DIMENSION, WELD DETAIL	10/14/85	85-1160	
40-CCB-16-H4	THREAD STAKED, "W" DIMENSION	10/14/85	85-1161	
40-CCB-16-H8	DIMENSION, WELD DETAIL	10/14/85	85-1162	
A-260	THREAD ENGAGE, WELD DETAIL, DIMENSION	10/14/85	85-1163	
40-CCB-23-H1	BOLT SPACING, WELDS, CLEARANCE DIMENSIONS	10/16/85	85-1224	
40-CCB-16-H7	WELDS, DIMENSIONS	10/16/85	85-1225	
A-261	WELDS, PIPE LOCATIONS	10/16/85	85-1227	
40-CCA-18-H1	BOLT EDGE DISTANCE, WELD SIZE, PLATE SHAPE	10/16/85	85-1235	
40-CCA-18-H2	BOLT EDGE DISTANCE, GROUT THK. OVERSIZE SHIM ADDED, WELDS UNDERSIZED LOG PLAN REV	10/17/85	85-1260	
40-CCB-23-H2		10/17/85	85-1261	
40-CCB-16-H6	IT-2 LENGTH DECREASED, IT-10 SIZE INCR. WELDS UNDERSIZED	10/17/85	85-1262	
M-1113-H3	BOLT SPRING, PIPE STRAP TRIMMED	10/17/85	85-1263	
M-1113-H2	1/8" GAP NOT PER DRAWING	10/17/85	85-1272	USE-AG-IS (3)
M-1113-H1	STRAP TRIMMED, BASEPLATE WELDED IN LIEU OF 2-BOLTS.	10/17/85	85-1273	
31-CCB-16-H9	BASEPLATE GAPS, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1307	
31-CCB-16-H10	BASEPLATE WARPAGE, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1308	
M-1113-H7	ANCHOR BOLT SPACING	10/19/85	85-1314	

SYSTEM: REACTOR COOLANT SYSTEM  
DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1113-H9	ANCHORBOLT SPACING & PLATE GAPS	10/19/85	85-1315	
M-1113-H11	1-BOLT IS 3/4" NOT 5/8", BOLT SPACING BASEPLATE GAPS	10/19/85	85-1316	
M-1113-H12	GAP NOT PER DRAWING	10/19/85	85-1317	
M-1113-H13	ANCHOR BOLT SPACING	10/19/85	85-1318	
M-1113-H15	WELD UNDERSIZED	10/19/85	85-1319	
M-1113-H17	BOLT SPACING, WELDS UNDERSIZED, PLATE SIZE NOT PER DRAWING	10/19/85	85-1320	
M-1113-H18	WELDS UNDERSIZED	10/19/85	85-1321	
M-1113-H20	INSTALLATION NOT PER DRAWING, WELD DELETED	10/19/85	85-1322	
M-1113-H21	LOOSE NUT ON U-BOLT	10/19/85	85-1323	
M-1113-H22	INSTALLATION NOT PER DRAWING	10/19/85	85-1324	
31-CCB-23-H4	STRUT "W" INCREASE 1/2" STAKED THD. ON ROD ALL CLAMP THD. ARE STAKED	10/19/85	85-1325	
FSK-M-CCA-3-1-H1	WELD NOT PER STANDARD DETAIL	10/19/85	85-1327	
FSK-M-CCA-3-2-H7	REV. PIPE LOC. & CLEARANCE	10/21/85	85-1350	
FSK-M-CCA-3-2-H10	SUPPORT CONFIGURATION	10/21/85	85-1351	
31-CCA-18-H4	UNDERSIZE WELD, GROUT THICKNESS	10/21/85	85-1352	
31-CCA-18-H8	1-ANCHORBOLT NOT FULL THREAD ENGAGEMENT SPRING CAN SPACING, WELDS, PLATE GAPS	10/21/85	85-1353	
31-CCB-16-H11		10/21/85	85-1354	
31-CCB-23-H5	CLEARANCE INCREASED, WELD DELETED	10/21/85	85-1355	
31-CCA-18-H13		10/21/85	85-1356	
31-CCB-23-H3	BOLT SPACING, WELDS UNDERSIZED GROUT THICKNESS	10/21/85	85-1357	
31-CCA-18-H9	WELD TYPES, SECTION A-A NOT PER DRAWING. BASE PLATE GAPS	10/21/85	85-1358	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
31-CCA-18-H12	BOLT EDGE DISTANCE, PIPE LOCATION	10/21/85	85-1359	
31-CCB-16-H12		10/21/85	85-1360	
FSK-M-CCA-3-2-A1	BASEPLATE GAPS	10/21/85	85-1361	
M-1113-H32	BOLT SPACING, WELD DELETED	10/21/85	85-1372	
M-1113-H30	ANCHORBOLT SPACING	10/21/85	85-1373	
M-1113-H26	BOLT SPACING, WELD UNDERSIZED	10/21/85	85-1374	
31-CCB-18-H10	CLEARANCE REDUCED, WLDS UNDSZ	10/22/85	85-1388	
31-CCA-18-H11	WLDS UNDSZ	10/22/85	85-1389	
31-CCA-18-H5	WLDS UNDSZ	10/22/85	85-1390	
31-CCA-18-H6	SNUBBER SETTING	10/22/85	85-1391	
M-11131-H28	WELDS, DIMEN., & BOLT SPACING NOT PER DWG., BASE PLATE GAP UNACCEPTABLE.	10/23/85	85-1401	
M-11131-H35	GAP NOT PER DRAWING	10/23/85	85-1402	
M-11131-H36	GAP NOT PER DRAWING	10/23/85	85-1403	
M-11131-H37	BOLT SPACING, GROUT, & U-BOLT, NOT PER DRAWING	10/23/85	85-1404	
M-11131-H38	U-BOLT NOT PER DRAWING	10/23/85	85-1405	
M-11131-H40	ANCHOR BOLT SPACING & GROUT NOT PER DRAWING	10/23/85	85-1406	
M-11131-H41	DIMENSION NOT PER DRAWING	10/23/85	85-1407	
M-11131-H42	DIMENSION & CLAMP NOT PER DRAWING	10/23/85	85-1408	
M-11131-H43	LOOSE NUTS & U-BOLT NOT PER DRAWING	10/23/85	85-1409	
M-11131-H44	ANCHOR BOLT SPACING, GROUT, WELDS, & U-BOLT NOT PER DRAWING	10/23/85	85-1410	
M-11131-H45	U-BOLT NOT PER DRAWING	10/23/85	85-1411	
M-11131-H46	WELD & U-BOLT NOT PER DRAWING	10/23/85	85-1412	



SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-11131-H47	WELD & CLEAR. NOT PER DRAWING	10/23/85	85-1413	
M-11131-H49	WELDS NOT PER DRAWING	10/23/85	85-1414	
31-CCA-18-H3	CLEAR, DIMEN., WELDS NOT PER DRAWING	10/23/85	85-1419	
CCB-21-H23	SUPPORT OFFSET, NON-STANDARD PIPE CLAMP	10/24/85	85-1433	
F-CCA-2-1-H2	WELD UNDERSIZED, STRAP CLEARANCE	10/24/85	85-1442	
F-CCA-2-1-H3	WELD UNDERSIZED, STRAP CLEARANCE	10/24/85	85-1443	
F-CCA-2-1-H4	SNUB. MVMT., PLATE GAPS, WELD NOT ON DRAWING	10/24/85	85-1444	
F-CCA-2-1-H1	SNUBBER MOVEMENT	10/24/85	85-1445	
31-CCB-21-H18	WELDS UNDERSIZED, CLIP ANGLE SIZE INCREASED	10/24/85	85-1446	
F-CCB-8-11-H14	STRAP DIMENSIONS, STEEL NOTCHED, WELDS & MEM. SIZE	10/24/85	85-1448	
F-CCB-8-11-H13	SUPPORT GREIT, MEMBER SIZES	10/24/85	85-1449	
M-1113-H54	BOLT SPACING, WELDS UNDERSIZED, SNUBBER MATERIAL	10/25/85	85-1457	
M-1113-H51	BOLT SPACING, UNDERSIZE WELDS, GROUT ADDED	10/25/85	85-1458	
M-1113-H57	BOLT SPACING, GROUT ADDED	10/25/85	85-1459	
M-1113-H23	WELDS UNDERSIZED	10/25/85	85-1460	
M-1113-H50	WELDS UNDERSIZED	10/25/85	85-1461	
M-1113-H53	BOLT SPACING, BASE PLATE GROUTED	10/25/85	85-1462	
M-1113-H55	BOLT SPACING, CLAMP BOLT LOOSE, GROUT AL`ED	10/25/85	85-1463	
M-1143-H46	WELDS UNDERSIZED, PLATE EDGE DISTANCE & GAPS	10/25/85	85-1464	
M-1143-H49	ANCHOR BOLT SPACING	10/25/85	85-1465	
M-1143-H10	ANCHOR BOLT SPACING, WELDS UNDERSIZED	10/25/85	85-1466	
M-1143-H12	ANCHOR BOLT SPACING, WELDS UNDERSIZED	10/25/85	85-1467	
M-1143-H14	MEMBER - 6 SHORTENED	10/25/85	85-1468	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1143-H15	MEMBER - 2 INCREASED 1 1/2"	10/25/85	85-1469	
M-1143-H17	BOLT SPACING, PLATE GAPS, WELD UNDERSIZED	10/25/85	85-1470	
M-1143-H18	BASE PLATE NOT INSTALLED, EXIST PLATE USED	10/25/85	85-1471	
F-CCB-28-4-H5	WELD UNDERSIZED	10/25/85	85-1473	
F-CCB-28-4-H6	WELD SIZES, MEMBER SUBSTITUTION	10/25/85	85-1474	
F-CCB-28-4-H7	WELD SIZE NOT ON DRAWING, MEMBER SIZE INCREASED	10/25/85	85-1475	
CCB-21-H15	BOLTS W/3 WASHERS, WELD UNDERSIZED, CLR REDUCED	10/25/85	85-1478	
CCB-21-H16	WELD UNDERSIZED	10/25/85	85-1479	
CCB-21-H17	WELD UNDERSIZED, LUG CLR., ARC. STRIKE ON P.P.	10/25/85	85-1480	
A-252	BOLT SPACING, ARC. STRIKE ON PRESS PIPE	10/25/85	85-1481	
CCB-21-H10	WELD UNDERSIZED	10/25/85	85-1482	
F-CCB-26-4-H1	BASE PLATE GAP, BOLT SPACING, WELD SIZE & UNDERCUT	10/25/85	85-1483	
F-CCB-26-4-H3	WELD UNDERSIZED, PLATE GAPSG, WELD SIZE & UNDERCUT	10/25/85	85-1484	
F-CCB-28-4-H10	WELD SIZES, MATERIAL SIZE, BOLT SPACING	10/25/85	85-1488	
F-CCB-28-4-H9	WELD SIZES NOT PER OR ON DRAWING	10/25/85	85-1489	
F-CCB-28-4-H8	WELD SIZES NOT PER OR ON DRAWING	10/25/85	85-1490	
M-1143-H13	ITEM-2 SHORTENED (ANGLE)	10/25/85	85-1493	
HBD-164-2-H32	DIMENSION & MEMBERS NOT PER DRAWING	10/28/85	85-1500	
FSK-M-H50-164-2-A6		10/28/85	85-1501	
CCA-(28" ID)-4-	MISSING LOCKWIRE, DIMEN. NOT PER DWG., MISSING DETAIL	10/28/85	85-1502	
CCA(28ID)-4-H2	DIMEN. NOT ON DWG.	10/28/85	85-1503	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
CCA(28ID)-4-H1	MISSING LOCK WIRE	10/28/85	85-1504	
CCA(28ID)-3-H1	DIMEN. NOT PER DWG., INCOMPLETE DET., MISSING LOCKWIRE	10/28/85	85-1505	
CCA(28ID)-3-H2	INCOMPLETE DIMEN. ON DWG.	10/28/85	85-1506	
CCA(28ID)-3-H3	MISSING LOCK WIRE	10/28/85	85-1507	
CCB-7-1-H8	DIMEN. & GROUT NOT PER DRAWING	10/28/85	85-1509	
CCB-7-1-H7	BASEPLATE GAP UNACCEPTABLE, CRACKED CONC.	10/28/85	85-1510	
CCB-7-1-H2	WELD NOT PER DRAWING	10/28/85	85-1511	
CCB-7-1-H1	WELD NOT PER DRAWING	10/28/85	85-1512	
HCC-56-1-H5	WELD NOT PER DRAWING	10/28/85	85-1513	
HCC-56-1-H6	WELD, DIMEN., & PLATE NOT PER DRAWING	10/28/85	85-1514	
31-CCB-21-H12	BASE PLATE GAP UNACCEPTABLE, WELD NOT PER DWG., NO B.O.M.	10/29/85	85-1521	
31-CCB-21-H11	WASHERS, CLEAR., & WELDS NOT PER DRAWING	10/29/85	85-1522	
31-CCB-21-H14	WASHERS, GAPS NOT PER DRAWING, WARPED MEMBER	10/29/85	85-1524	
31-CCB-21-H9	WELDS NOT PER DRAWING	10/29/85	85-1525	
31-CCB-21-H7	GROUT & WELD NOT PER DRAWING	10/29/85	85-1526	
31-CCB-21-H13	WELD, CLEAR, & WASHERS NOT PER DRAWING	10/29/85	85-1527	
CCB-8-15-A1	MEMBERS & WELD NOT PER DRAWING	10/29/85	85-1528	
CCB-8-15-H2	MISSING WASHERS & LOCKWIRE, PAINT ON SNUBBER	10/29/85	85-1529	
M-1113-H56	BOLT SPACING, WELDS, & SNUBBER NOT PER DRAWING	10/29/85	85-1533	
CCB-8-15-H4	DIMENSION NOT PER DRAWING	10/29/85	85-1542	
CCB-8-15-H3	MEMBERS, WELD, & DIMEN. NOT PER DRAWING	10/29/85	85-1543	
CCB-8-15-H1	MISSING WASHERS & LOCK WIRE, PAINT ON SNUBBER, WELD & MEMBER NOT PER DRAWING	10/29/85	85-1544	

SYSTEM: REACTOR COOLANT SYSTEM  
DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
CCB-8-15-H10	MEMBER & WELD NOT PER DRAWING	10/29/85	85-1550	
M-1113-H60	GROUT & WELDS NOT PER DRAWING, LOOSE CLAMP, SPACER & LOAD PIN	10/29/85	85-1551	
CCB-8-15-H9	MEMBERS, DIMENS., & WELDS NOT PER DRAWING	10/29/85	85-1552	
CCB-8-15-H7	WELDS NOT PER DRAWING	10/29/85	85-1553	
CCB-8-15-H6	BOLTS NOT PER DRAWING	10/29/85	85-1554	
CCB-8-15-H5	DIMEN. & WELD NOT PER DRAWING	10/29/85	85-1555	
M-1113-H24	BOLT, SPACING, & GROUT NOT PER DRAWING	10/29/85	85-1556	
M-1113-H61	SPACING, GROUT, & WELD NOT PER DRAWING, LOOSE CLAMP	10/29/85	85-1557	
M-1113-H59	WELD NOT PER DRAWING	10/29/85	85-1558	
M-1113-H58	SPACING & GROUT NOT PER DRAWING, GAP UNACCEPTABLE	10/29/85	85-1559	
CCB-7-4-H11	WELD, CONFIG., & CLEAR. NOT PER DRAWING	10/29/85	85-1560	
CCB-7-4-H12	MATERIAL & CLEAR. NOT PER DRAWING	10/29/85	85-1561	
CCB-7-4-H13	SPACING, WELDS, MATERIAL, & CLEAR. NOT PER DRAWING	10/29/85	85-1562	
CCB-7-4-H14	WELD & DIMEN. NOT PER DRAWING	10/29/85	85-1563	
CCB-7-4-H15	WELD, DIMEN, MATERIAL, CLEAR. NOT PER DRAWING	10/29/85	85-1564	
CCB-7-4-H16	DIMENSION & CLEARANCE NOT PER DRAWING	10/29/85	85-1565	
CCB-7-4-H17	DIMEN. & CLEAR. NOT PER DRAWING	10/29/85	85-1566	
HCC-56-5-H10	INCORRECT WELD SYMBOL	10/29/85	85-1567	
HCC-56-5-H11	INCORRECT WELD SYMBOL	10/29/85	85-1568	
HCC-56-5-H13	WELD NOT PER DRAWING	10/29/85	85-1569	
HCC-56-5-H14	WELD NOT PER DRAWING	10/29/85	85-1570	
CCB-27-3-H1	WELD NOT PER DRAWING	10/29/85	85-1571	

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
CCB-7-4-H16	MEMBER, WELD, DIMEN., & CLEAR. NOT PER DRAWING	10/29/85	85-1572	
FSK-M-CCB-8-7-H21	GROUT NOT ON DWG	10/30/85	85-1577	
FSK-M-HBD-426-3-A1	GROUT NOT ON DWG, WLD SYMBOL	10/30/85	85-1578	
FSK-M-CCB-22-3-H28	DIMENSIONS, THD ENGAGEMENT	10/31/85	85-1586	
FSK-M-CCB-22-3-H27	DIMENSIONS, WLD SZ & DETAIL	10/31/85	85-1589	
FSK-M-CCB-22-3-H26	DIMENSIONS	10/31/85	85-1590	
FSK-M-CCB-22-3-H25	DIMENSIONS, PG ATTACHMENT DETAIL, PLATE NOT ON DWG	10/31/85	85-1591	
FSK-M-CCB-22-3-H24	DIMENSIONS, WLD SZ & DETAIL	10/31/85	85-1592	
FSK-M-CCB-22-3-H23	DIMENSIONS, WLD DETAIL, THD ENGAGEMENT	10/31/85	85-1593	
FSK-M-CCB-22-3-H22	DIMENSIONS, WLD SZ & DETAIL, THD ENGAGEMENT	10/31/85	85-1594	
FSK-M-CCB-22-3-H21	DIMENSIONS, WLD SZ & DETAIL	10/31/85	85-1596	
FSK-M-CCB-22-3-H20	DIMENSIONS, WLD DETAIL	10/31/85	85-1597	
FSK-M-CCB-22-3-A4	DIMENSIONS, WLD DETAIL	10/31/85	85-1598	
FSK-M-CCB-26-3-H8	NO BOM	10/31/85	85-1599	
FSK-M-HBD-426-2-A5	NO BOM, WLD DETAIL & SZ	10/31/85	85-1600	
FSK-M-CCB-8-23-H3	CLEARANCE, PLATE GROUTED	10/31/85	85-1601	
FSK-M-HBD-426-2-H29	NO SKETCH	10/31/85	85-1603	
FSK-M-HCC-56-A-H1	WLD SZ	10/31/85	85-1604	
FSK-M-CCB-8-14-H2	WLD SZ, PLATE GROUTED	10/31/85	85-1605	
FSK-M-CCB-8-23-H1	PLATE GROUTED, CLEARANCE	10/31/85	85-1606	
FSK-M-CCB-28-3-H7	NO BOM, WLD SZ, PLATE GROUTED	10/31/85	85-1607	
FSK-M-HBB-3-3-A2	PLATE GROUTED, WLD SZ	10/31/85	85-1608	
FSK-M-CCB-28-3-H9	NO SKETCH, CLEARANCE	10/31/85	85-1609	



REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
FSK-M-CCB-8-14-A1	NO BASE PLATE, WLD DETAIL, NO BOM	10/31/85	85-1610	
FSK-M-CCB-28-3-H11	NO SKETCH, CLEARANCE	10/31/85	85-1611	
FSK-M-HCC-56-4-H12	WLD DETAIL & SZ, NO BOM	10/31/85	85-1612	
FSK-M-HBB-3-3-H20	NO BOM, WLD DETAIL & SZ, PLATE GROUTED	10/31/85	85-1613	
FSK-M-CCB-8-14-H1	DIMENSION, WELD DETAIL & SZ, NO BOM	10/31/85	85-1614	
FSK-M-CCB-28-3-H10	NO BOM, DIMENSION, WLD SZ	10/31/85	85-1615	
FSK-M-HCC-56-6-H7	WELD DETAIL	10/31/85	85-1616	
FSK-M-HCC-56-6-H9	WELD DETAIL	10/31/85	85-1617	
FSK-M-HCC-56-6-H8	DIMENSION, WLD DETAILS & SZ	10/31/85	85-1618	
FSK-M-CCB-8-23-H	ANCHORS REMOVED	10/31/85	85-1619	
FSK-M-HCB-12-4	ANCHOR LOCATION, ADDITIONAL SUPP	10/31/85	85-1620	
FSK-M-CCB-8-9-H	ADDITIONAL SUPPS	10/31/85	85-1621	
FSK-M-CCB-7-19-H9	PLATE GROUTED	11/01/85	85-1622	
FSK-M-CCB-26-2-H4	PLATE GROUTED	11/01/85	85-1623	
FSK-M-CCB-22-5-H18	ADDED MATL, WLD DETAIL	11/01/85	85-1624	
FSK-M-CCB-26-2-H6	PLATE GROUTED	11/01/85	85-1626	
FSK-M-CCB-26-2-H5	PLATE GROUTED	11/01/85	85-1627	
FSK-M-HCC-56-3-H9	PLATE GROUTED, WLD DETAIL, ADDITIONAL SUPP	11/01/85	85-1628	
FSK-M-HCC-56-3-H10	PLATE GAP	11/01/85	85-1629	
FSK-M-HCC-56-3-H11	PLATE GAP	11/01/85	85-1630	
FSK-M-H6D-426-H1	PLATE GROUTED	11/01/85	85-1631	
FSK-M-CCB-7-19-H11	BEARING OF ANGLE	11/01/85	85-1633	
FSK-M-CCB-22-5-A3	PLATE THICK & GAP, DIMENSION, WLD DETAIL & SZ	11/01/85	85-1637	
FSK-M-CCB-22-5-A3	THD STAKED	11/01/85	85-1638	



SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
FSK-M-CCB-22-5-H17	WLD DETAIL	11/01/85	85-1639	
FSK-M-CCB-22-5-H15	THD STAKED, WLD SZ & DETAIL	11/01/85	85-1640	
FSK-M-CCB-26-9-H	INCOMPLETE DIMENSION INFO	11/01/85	85-1646	
FSK-M-CCB-26-8-A7	DIMENSION	11/01/85	85-1647	
FSK-M-CCB-8-20-H2	DIMENSIONS	11/04/85	85-1650	
FSK-M-CCB-8-20-H1	DIMENSIONS, WLD VS BOLT	11/04/85	85-1651	
FSK-M-CCB-8-20-H3	WLD SZ, ANC ANGLE, DIMENSIONS	11/04/85	85-1652	
FSK-M-HBB-4-2-H16	DIMENSION, WLD SZ & DETAIL, CLEARANCE	11/04/85	85-1653	
FSK-M-HBB-4-2-H17	DIMENSION, WLD DETAIL & SZ, CLEARANCE	11/04/85	85-1654	
FSK-M-HBB-4-2-H18	DIMENSION, WLD SZ & DETAIL, CLEARANCE	11/04/85	85-1655	
FSK-M-HBB-4-2-H19	DIMENSION, WLD SZ & DETAIL, CLEARANCE	11/04/85	85-1656	
FSK-M-HBB-4-2-A3	DIMENSION	11/04/85	85-1657	
FSK-M-HBB-4-2-A2	DIMENSION	11/04/85	85-1658	
FSK-M-HBB-4-2-H15	DIMENSION, WLD DETAIL, CLEARANCE	11/04/85	85-1659	
FSK-M-CCB-26-8-A6	DIMENSION	11/04/85	85-1661	
FSK-M-HCC-56-9-H5	DIMENSION	11/04/85	85-1664	
FSK-M-CCB-22-2-H2	DIMENSION, THD ENGAGEMENT	11/04/85	85-1665	
FSK-M-HCD-15-18-A4	DIMENSION, WLD SZ & DETAIL	11/04/85	85-1666	
FSK-M-CCB-28-7-H13	DIMENSION	11/04/85	85-1669	
FSK-M-CCB-28-7-H12	DIMENSIONS	11/04/85	85-1670	
FSK-M-CCB-26-8-A5	DWG DIMENSIONS INCOMPLETE, BASEPLATE	11/04/85	85-1671	
FSK-M-HCC-81-1-H3	WLDs NOT PER DWG	11/04/85	85-1672	
FSK-M-CCB-8-8-H/H4	WLDs NOT PER DWG & UNDSZ, NO WLD HOLE	11/04/85	85-1677	
FSK-M-CCB-8-8-H/H3	WLDs UNDSZ	11/04/85	85-1678	

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	MCR/SR NUMBER	DISPOSITION
FSK-M-CCB-8-8-H/H2	WLDs NOT PER DWG, WSHRS MISSING, CORROSION ON TUBE MOUNTING	11/04/85	85-1679	
FSK-M-CCB-8-8-H/H1	WLDs NOT PER DWG, CORROSION ON TRASITION TUBE, WSHRS MISSING	11/04/85	85-1680	
FSK-M-CCB-28-7-H10	WLDs NOT PER DWG	11/04/85	85-1681	
FSK-M-CCB-28-7-A2	PLATE DIM, WLDs NOT PER DWG	11/04/85	85-1682	
FSK-M-CCA-18-1-H1	NO BOM, WLD UNDSZ, JAM NUT LOOSE	11/04/85	85-1683	
FSK-M-CCA-18-2-H7	WLDs UNDSZ & INCORR SYMBOL	11/04/85	85-1684	
FSK-M-CCA-18-2-H6	WLD UNDSZ, NO BOM	11/04/85	85-1685	
M-CCA-18-2-H5	NO BOM, WLD DETAIL, CLEARANCE, CRACKED GROUT	11/04/85	85-1686	
M-CCA-18-2-H4	NO BOM, WLD SZ	11/04/85	85-1687	
M-CCB-28-7-H11	DWG DISCREP, DIM, THD STAKED, WLD DETAIL	11/04/85	85-1689	
M-HBD-426-4-A4	DIM, WLD SZ & DETAIL	11/04/85	85-1692	
M-CCB-8-9-H-A1	NO WSHR, DIM, TEE MOD, WLD DETAIL	11/05/85	85-1694	
M-CCB-8-9-A2	WLD DETAIL	11/05/85	85-1695	
M-CCB-8-9-A3	NO WSHR, DIM, WLD DETAIL & SZ	11/05/85	85-1696	
M-CCB-8-9-H-A4	MODIFIED TEE, DIM, WLD DETAIL	11/05/85	85-1697	
M-CCB-8-9-H-H1	NO WSHR, WLD SZ, DIM	11/05/85	85-1698	
M-CCB-8-9-H2	NO WSHR, DIM	11/05/85	85-1699	
M-CCB-8-9-H3	NO WSHR, DIM	11/05/85	85-1700	
M-CCB-8-9-H4	DIM, NO WSHR, WLD DETAIL	11/05/85	85-1701	
M-CCB-8-9-H5	NO WSHR, DIMENSION, PLATE GAP, WLD DETAIL	11/05/85	85-1702	
M-CCB-8-9-H6	DIMENSION, WLD SZ	11/05/85	85-1703	
M-HBB-4-1-H3	DIMENSION, CONC CRACK	11/05/85	85-1704	
M-CCB-28-1-H7	DWG DETAIL	11/05/85	85-1705	

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-CCB-28-1-H8	WLD SZ	11/05/85	85-1706	
M-CCB-28-1-H9	DWG DETAIL, WLD DETAIL	11/05/85	85-1707	
M-CCB-28-1-H6	WLD DETAIL, SHIM ROTATED	11/05/85	85-1708	
M-HBB-4-1-H4	DIMENSION	11/05/85	85-1709	
M-HBB-4-1-A1	WLD DETAIL, DWG DETAIL	11/05/85	85-1710	
M-HBB-4-3-A1	WLD DETAIL	11/05/85	85-1711	
M-HBB-4-3-H5	CLEARANCE	11/05/85	85-1712	
M-HBB-4-3-H4	WLD DETAIL CLEARANCE	11/05/85	85-1713	
M-HBB-4-3-H6	WLD DETAIL, CLEARANCE	11/05/85	85-1714	
M-HBB-4-3-H2	WLD DETAIL, CLEARANCE	11/05/85	85-1715	
M-CCB-8-19-H1	DIMENSION, NO WSHR, WLD SZ & DETAIL	11/05/85	85-1716	
M-HBB-4-3-H3	WLD DETAIL & SZ, CLEARANCE	11/05/85	85-1717	
M-CCB-8-26-H3	BASEPLATE GAP, WEJIT VS HILTI	11/05/85	85-1718	
M-CCB-8-26-H1	BASEPLATE GAP, WEJIT VS HILTI	11/05/85	85-1719	
M-CCB-8-26-A1	MODIFIED TEE, ADDITIONAL PLATE, WEJIT VS HILTI	11/05/85	85-1720	
M-CCB-8-26-H4	DIMENSION, CLEARANCE	11/05/85	85-1721	
M-CCB-8-26-H2	WLD DETAIL, BASEPLATE GAP, EDGE DISTANCE, C-C DIMENSION	11/05/85	85-1722	
M-CCB-8-26-A2	STRUC TEE, WEJIT VS HILTI	11/05/85	85-1723	
M-CCB-8-9-H-47	DIMENSION, WLD SZ & DETAIL	11/05/85	85-1724	
M-CCB-8-9-H8	DIMENSION, WLD DETAIL & SZ, GAP, MODIFIED TEE	11/05/85	85-1725	
M-CCB-8-9-H9	MEMBER SZ, DIM, WLD DETAIL, NO WSHR, GAP	11/05/85	85-1726	
M-CCB-8-9-H10	NO WSHRS, PLATE THICKNESS, DIM	11/05/85	85-1727	
M-CCB-8-9-H11	NO WSHRS, PLATE GAP, DIM, SHIM INSTALLED	11/05/85	85-1728	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-CCB-8-9-H12	NO WSHR, PLATE GAP, DIM, WLD DETAIL	11/05/85	85-1729	
M-CCB-8-9-H13	NO WSHR, PLATE GAP, WLD DETAIL & SZ	11/05/85	85-1730	
M-CCB-8-9-H-H14	NO WSHR, PLATE GAP, DIM	11/05/85	85-1731	
M-CCB-8-19-H2	DIM, WLD DETAIL, ANGLE SZ, SPACER, CLEARANCE	11/05/85	85-1732	
M-HCC-56-10-H10	PLATE GROUTED, WLD DETAIL, CONC CRACK	11/05/85	85-1733	
M-HCC-56-10-H12	WLD DETAIL, NO PAINT	11/05/85	85-1734	
M-HCC-56-7-A3	C-C SPACING	11/05/85	85-1735	
M-HCB-42-5-H27	THD STAKED, THD ENGAGEMENT	11/05/85	85-1736	
M-HCB-42-H26	THD STAKED, DIM	11/05/85	85-1737	
M-HCB-42-5-H25	THD STAKED, THD ENGAGEMENT, DIM	11/05/85	85-1738	
M-HCB-42-5-H23	THD STAKED, WLD DETAIL, DIM	11/05/85	85-1739	
M-HCB-42-5-H24	THD STAKED, THD ENGAGEMENT, DIM	11/05/85	85-1740	
M-HCB-42-5-A8	THD ENGAGEMENT, WLD SZ, MODIFIED TEE, DIM	11/05/85	85-1741	
M-HCB-42-5-H28	THD STAKED	11/05/85	85-1742	
M-HCC-56-7-H5	DIM, DWG DETAIL	11/05/85	85-1743	
M-HCC-56-7-H4	DIM, DWG DETAIL	11/05/85	85-1744	
M-CCB-22-4-H1	DIM, WLD DETAIL	11/05/85	85-1746	
M-CCB-22-4-H2	WLD DETAIL & SZ, DIM, CLEARANCE	11/05/85	85-1747	
M-CCB-22-4-H3	MEMBER SZ, DIM	11/05/85	85-1748	
M-CCB-22-4-H4	MODIFIED TEE, WLD DETAIL & SZ	11/05/85	85-1749	
M-CCB-22-4-H5	MEMBER SZ, DIM	11/05/85	85-1750	
M-CCB-22-4-H6	MEMBER SZ, WLD DETAIL, DIM	11/05/85	85-1751	
M-CCB-22-4-H8	WLD DETAIL, DIMENSIONS, BEARING	11/05/85	85-1752	
M-CCB-28-5-H16	WLD SZ	11/05/85	85-1754	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-HCC-56-7-H6	DIM, DWG DETAIL	11/05/85	85-1755	
M-CCB-22-4-H7	SHIM DETAIL, MEMBER SIZE, WLD DETAIL CLEARANCE	11/05/85	85-1756	
M-CCB-22-2-H3	DWG DETAILS, DIM	11/05/85	85-1757	
M-CCB-28-5-H19	WLD DETAIL, CONN DETAIL	11/05/85	85-1758	
M-CCB-28-5-H18	WLD SZ, DIM	11/05/85	85-1759	
M-CCB-27-1-H1	DIM, MODIFIED TEE	11/05/85	85-1760	
M-HCB-42-5-H29	WLD SZ & DETAIL	11/05/85	85-1761	
M-CCA-21-1-H1	WLD SZ, CLEARANCE, DWG DETAIL, NO LOCKING DEVICE	11/06/85	85-1764	
M-CCA-21-3-H1	WLD SZ, CLEARANCE, DIMENSION, NO LOCKING DEVICE, DWG DETAIL	11/06/85	85-1765	
M-CCA-21-2-H1	WLD SZ, CLEARANCE, DWG DETAIL, NO LOCKING DEVICE, DIMENSION	11/06/85	85-1766	
M-CCA-21-4-H1	WLD SZ, CLEARANCE, DWG DETAIL, NO LOCKING DEVICE, DIMENSION	11/06/85	85-1767	
M-CCB-26-6-ES1	WLD DETAIL, DIMENSION, ANG. BOLT SZ, EXTRA HOLE	11/06/85	85-1768	
M-HCC-56-8-H-H1	GOUGE, CLEARANCE, WLD DETAIL	11/06/85	85-1769	
M-CCB-26-6-ES2	WLD DETAIL, DIMENSION, BOLT SZ, EXTRA HOLES	11/06/85	85-1770	
FBK-M-HCC-81-3-A1	DIMENSION, WLD SZ & DETAIL, MODIFIED T	11/05/85	85-1771	
M-HCC-56-8-A1	WLD DETAIL & SZ	11/06/85	85-1772	
M-HCC-56-8-H-H4	WLD SZ & DETAIL	11/06/85	85-1773	
M-HCC-56-8-H2	DWG DETAIL, WLD DETAIL & SZ	11/06/85	85-1774	
M-H88-3-1-A3	NO WSHR, BOLT TYPE, DIMENSION, MODIFIED TEE	11/06/85	85-1775	
M-H88-3-1-H14	DIMENSION, WLD DETAIL	11/06/85	85-1776	
M-HCC-81-4-H1	MEMBER DETAIL, WLD SZ, DIMENSION, CONC CRACK, CLEARANCE	11/06/85	85-1777	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR TIMEINDEX

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-CCB-7-10-H6	WLD DETAIL	11/06/85	85-1778	
M-CCB-7-10-H5	CONNECTION DETAIL	11/06/85	85-1779	
M-CCB-24-2-A2	DWG DETAIL	11/06/85	85-1780	
M-CCB-28-5-H12	WLD DETAIL	11/07/85	85-1794	
M-CCB-27-2-H11	NO WSHR, LOCKNUT, ALL THREAD VS BOLT	11/07/85	85-1795	
M-CCB-7-10-H7	DIMENSIONS	11/07/85	85-1796	
M-CCB-27-2-H13	DIMENSIONS	11/07/85	85-1797	
M-CCB-27-2-H14	NO WEEP HOLE, WLD DETAIL	11/07/85	85-1798	
M-CCB-27-2-H12	NUT MISSING, WLD DETAIL, SPRING MOUNT	11/07/85	85-1799	
M-CCB-7-10-H4	DIMENSIONS, WLD DETAIL	11/07/85	85-1800	
M-CCB-28-5-H14	WLD SZ & DETAIL, DIMENSION	11/07/85	85-1801	
M-CCA-6-1-H1	STUD CUT, DIMENSION, WLD DETAIL	11/07/85	85-1802	
M-CCA-6-1-H12	STUD CUT, DIMENSION	11/07/85	85-1803	
M-CCA-6-1-H3	STUD CUT, DIMENSION	11/07/85	85-1804	
M-CCB-7-9-H8	DIMENSIONS	11/08/85	85-1815	
M-CCB-7-9-H13	DIMENSION, WLD DETAILS	11/08/85	85-1816	
M-CCB-7-9-H12	DIMENSION, WLD SZ & DETAIL	11/08/85	85-1817	
M-CCB-7-9-H11	DIMENSION	11/08/85	85-1818	
M-CCB-7-9-H9	DIMENSION	11/08/85	85-1819	
M-CCB-7-9-HA1	WLD DETAIL	11/08/85	85-1820	
M-CCB-7-9-H10	DIMENSION	11/08/85	85-1821	
M-CCA-14-1-H1	WLD DETAIL, SHIM PLATE, GAP	11/08/85	85-1822	
M-HCB-42-4-A10	PLATE GROUTED	11/09/85	85-1838	
M-HCB-42-4-H30	WLD DETAIL	11/09/85	85-1839	



REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBFR	DISPOSITION
M-HCB-42-4-A9	PLATE GROUTED, WLD DETAIL	11/09/85	85-1840	
M-HCB-42-4-H5	MEMBER GOUGED, WLD DETAIL	11/09/85	85-1841	
M-HCB-42-4-H4	PLATE GROUTED, WLD DETAIL	11/09/85	85-1842	
M-HCB-42-4-H3	PLATE GROUTED, WLD DETAIL	11/09/85	85-1843	
M-HCB-42-2-H2	PLATE GROUTED, WLD DETAIL	11/09/85	85-1844	
M-HCB-42-4-H1	PLATE GROUTED, WLD DETAIL	11/09/85	85-1845	
M-HBD-95-7-A3	WLD DETAIL, DIMENSIONS, ADDITIONAL MEMBER	11/09/85	85-1847	
M-CCB-7-8-H16	WLD SZ & DETAIL, DIMENSION	11/12/85	85-1965	
M-CCB-7-8-A2	WLD SZ, MODIFIED TEE, PLATE GROUTED	11/12/85	85-1966	
M-CCB-7-8-H14	WLD DETAIL, PLATE GROUTED	11/12/85	85-1967	
M-CCB-7-8-H15	WLD SZ, DIMENSION, PLATE GROUTED	11/12/85	85-1968	
M-CCB-7-8-H20	PLATE GROUTED	11/12/85	85-1972	
M-CCB-7-8-H17	WLD SZ, NO LOCKNUT, PLATE GROUTED, ABANDONED BOLT	11/12/85	85-1975	
M-CCB-7-8-A3	WLD SZ, MODIFIED TEE, PLATE GROUTED	11/12/85	85-1976	
M-CCB-7-8-H19	WLD SZ, BOLT SZ, GROUTED PLATE	11/12/85	85-1977	
M-CCB-7-8-H21	DIMENSION, PLATE GROUTED	11/12/85	85-1978	
M-CCB-7-8-H18	WLD SZ & DETAIL, DIMENSION, GAP, GROUTED PLATE	11/12/85	85-1980	
M-CCB-7-5-H10	WLD DETAIL, DIMENSION	11/12/85	85-1984	
CCB-7-6-H3	DIM, WLDs, & GAPS NOT PER DWG	11/14/85	85-2040	
CCB-7-6-H1	WLD NOT PER DWG, NOT FULL THD ENGAGEMENT, ROD BENT, CLAMP	11/14/85	85-2041	
HCB-42-1-H4	MEMBER & ANCHOR BOLT LOCATIONS NOT PER DWG	11/14/85	85-2042	
CCB-7-6-H2	DIM & WLDs NOT PER DWG, WSHRS & SCREW MISSING, BOLTS,	11/14/85	85-2044	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
CCB-7-6-H4	DIM, LOCATION & WLDS NOT PER DWG	11/14/85	85-2050	
CCB-7-6-H5	WLDS & DIM NTO PER DWG	11/14/85	85-2051	
HCB-42-1-H2	LOCATION & GAP PROBLEMS W/PG-41	11/14/85	85-2052	
HCB-42-1-H3	PG-43 WLDS & DIM NOT PER DWG	11/14/85	85-2053	
HCB-42-1-A1	DIM & WLDS NOT PER DWG	11/13/85	85-2059	
HCC-81-5-H29	WLD NOT PER DWG	11/13/85	85-2060	
CCB-7-32-A4	DIM, MEMBERS & WLDS NOT PER DWG	11/15/85	85-2066	
CCB-7-6-ES1	WLDS, DIM, & MEMBERS NOT PER DWG, GAP UNACC	11/14/85	85-2077	
CCB-7-6-H6	DIM, WLDS, & MATERIAL NOT PER DWG	11/14/85	85-2078	
CCB-7-6-H7	DIM NOT PER DWG	11/14/85	85-2079	
CCB-7-6-H8	WLDS, DIM, & DEFLECT NOT PER DWG	11/14/85	85-2080	
CCB-7-6-H9	DIM NOT PER DWG	11/14/85	85-2084	
HCB-42-2-H8	WLDS & ANCHOR BOLTS NOT PER DWG	11/14/85	85-2085	
HCB-42-2-H9	CLEAR & WLDS NOT PER DWG	11/14/85	85-2086	
HCB-42-2-H7	CLEAR & WLDS NOT PER DWG	11/14/85	85-2087	
HCB-42-2-H10	WLDS NOT ON DWG	11/14/85	85-2088	
HCB-42-2-H6	WLLT & DIM NOT ON DWG	11/14/85	85-2089	
HCB-42-2-H5	WLDS & DIM NOT ON DWG	11/14/85	85-2090	
CCB-7-3-H25	WLD & DIM NOT ON DWG	11/14/85	85-2091	
CCB-7-3-H26	DIM & WLD NOT PER DWG	11/14/85	85-2092	
CCB-7-3-H27	DIM & WLD NOT PER DWG	11/14/85	85-2093	
CCB-7-3-H28	DIM & WLD NOT PER DWG	11/14/85	85-2094	
CCB-7-3-A5	DIM & WLD NOT PER DWG	11/14/85	85-2095	
CCB-7-16-A5	ANCHORS, DIM, & WLDS NOT PER DWG	11/14/85	85-2096	

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
IF-PT-RC2B1-H2	DIM, WLDS, & ANCHORS NOT PER DWG, MISSING LOCK WIRE	11/15/85	85-21	
IF-PSH-RC02B4-A1	DIM NOT ON DWG, ANCHORS NOT PER DWG	11/15/85	85-2102	
IF-PT-RC2B1-H3	ORIENTATION, WLDS, ANCHORS NOT PER DWG, MISSING LOCKWIRE	11/15/85	85-2112	
IF-PSH-RC02B4-H3	WLD LOCATION NOT ON DWG	11/15/85	85-2113	
IF-PSH-RC3B4-H2	LOCATION NOT ON DWG, ANCHORS NOT PER DWG	11/15/85	85-2114	
CCB-7-21-H19	MEMBER NOT PER DWG	11/15/85	85-2115	
HCB-42-2-H11	GAP UNACC, WLDS & CLEAR NOT PER DWG	11/15/85	85-2116	
IF-PT-RC2B1-A1	LOCATION NOT PER DWG, GAP UNACC	11/15/85	85-2117	
IF-PSH-RC02B4-H1	WLD NOT PER DWG, MISSING LOCKWIRE	11/15/85	85-2118	
IF-PT-RC2B1-H1	WLDS, ORIENT, & ANCHORS NOT PER DWG, GAP UNACC	11/15/85	85-2119	
CCB-7-32-H22	DIM & GAP UNACC	11/15/85	85-2120	
CCB-7-21-H21	DIM NO PER DWG	11/15/85	85-2121	
CCB-7-21-H20	DIM NOT PER DWG	11/15/85	85-2122	
CCB-7-32-H23	DIM NOT PER DWG	11/15/85	85-2123	
CCB-7-32-H24	DIM NOT PER DWG	11/15/85	85-2124	
HCH-42-2-H13	ANCHOR BOLTS & WLDS NOT PER DWG	11/15/85	85-2125	
HCB-42-2-H14	ANCHOR BOLTS & WLDS NOT PER DWG	11/15/85	85-2127	
HCB-42-2-H15	WLD, CLEAR, DIM, & ANCHORS NOT PER DWG	11/15/85	85-2128	
HCB-42-2-H16	WLDS & ANCHORS NOT PER DWG	11/15/85	85-2129	
CCB-27-4-H1	WLDS NOT PER DWG, TUBE STEEL MISSING PAINT	11/16/85	85-2130	
CCB-27-4-H2	WLDS NOT PER DWG	11/16/85	85-2144	
IF-LT-RC14-3-H22	PG-51 DIM NOT PER DWG	11/16/85	85-2156	
IF-LT-RC14-3-H25	WLD & DIM ON PG-45 NOT PER DWG	11/16/85	85-2157	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
IF-LT-RC14-3-H19	WLD & DIM NOT PER DWG	11/16/85	85-2158	
IF-LT-RC14-3-H24	SHIMS NO PER DWG	11/16/85	85-2159	
IF-LT-RC14-3-H23	PG-51 DIM NOT PER DWG	11/16/85	85-2160	
IF-LT-RC14-3-H16	DIM NOT PER DWG	11/16/85	85-2162	
HBD-95-6-A1	WSHRS, DIM, & WLDS NOT PER DWG	11/16/85	85-2162	
HBB-4-4-H4	WLD NOT PER DWG, BOLT LOOSE	11/16/85	85-2163	
HCB-42-3-H19	WLDS & CLEAR NOT PER DWG	11/16/85	85-2164	
HCB-42-2-H17	BOLT SPACING, DIM, & CLEAR NOT PER DWG	11/16/85	85-2165	
HCB-42-2-H12	BEARING UNACC, WLDS, DIM & CLEAR NOT PER DWG	11/16/85	85-2166	
HCB-42-3-H18	DIM & WLDS NOT PER DWG	11/16/85	85-2167	
IF-LI-214-H10	BOLT TYPE, WLD DETAIL, DIM, CLEARANCE	11/18/85	85-2183	
HCC-56-13-H48	THD STAKED	11/18/85	85-2184	
HCC-56-13-H49	THD STAKED	11/18/85	85-2185	
HCC-56-12-H2	DIM, WLD DETAIL	11/18/85	85-2186	
HCC-56-14-H52	WLD DETAIL	11/18/85	85-2187	
HSC-162-4-A1	WLD DETAIL, MODIFIED TEE	11/18/85	85-2188	
HSC-162-4-H2	WLD DETAIL	11/18/85	85-2189	
HCC-56-12-H1	WLD DETAIL	11/18/85	85-2190	
IF-LI-214-A6	WLD DETAIL, DIM	11/18/85	85-2209	
HCC-56-2-H2	WLD DETAIL	11/18/85	85-2213	
IF-LI-214-H28	WLD DETAIL, DIM	11/18/85	85-2214	
IF-LI-214-H23	CLEARANCE	11/18/85	85-2215	
IF-LI-214-H22	PG-45 VS PG-44, CLEARANCE	11/18/85	85-2216	
IF-LI-214-H25	STUD VS BOLT, PG-44 VS PG-45	11/18/85	85-2217	

17

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
IF-LI-214-H24	PG-45 VS PG-44, CLEARANCE	11/18/85	85-2218	
IF-LI-214-H26	WLD DETAIL, PG-44 VS PG-45, DIM	11/18/85	85-2219	
IF-LI-214-H27	WLD DETAIL, PG-45 VS PG-44, DIM, CLEARANCE	11/18/85	85-2220	
IF-LI-214-H30	BOLT TYPE, WLD DETAIL, DIM	11/18/85	85-2222	
IF-LI-214-H29	WLD DETAIL, PG-44 VS PG-45, DIM	11/18/85	85-2223	
HSC-162-3-H1	DIM	11/18/85	85-2224	
IF-LI-214-H16	WLD DETAIL, DIM, CLEARANCE	11/18/85	85-2225	
IF-LI-214-H15	WLD DETAIL, DIM	11/18/85	85-2227	
IF-LI-214-H14	WLD DETAIL, DIM, CLEARANCE	11/18/85	85-2228	
IF-LI-214-H13	WLD DETAIL, DIM, CLEARANCE	11/18/85	85-2229	
HCC-56-13-H46	WLD DETAIL	11/18/85	85-2230	
HCC-56-14-H51	WLD DETAIL, THD STKD, SPACER LOOSE	11/18/85	85-2231	
HCC-56-14-H53	WLD DETAIL	11/18/85	85-2232	
HCC-56-13-H50	WLD DETAIL	11/18/85	85-2233	
HSC-162-4-H1	WLD DETAIL	11/18/85	85-2234	
HSC-162-4-H3	DBL NUTS, MODIFIED TEE, WLD DETAIL, DIM	11/18/85	85-2235	
HSC-162-3-A1	WLD DETAIL & SZ, DWG DETAIL	11/18/85	85-2236	
IF-LI-214-A5	BOLT TYPE, WLD DETAIL, DIM	11/19/85	85-2239	
IF-LI-214-H11	BOLT TYPE, WLD DETAIL, DIM	11/19/85	85-2240	
IF-LI-214-H12	BOLT TYPE, WLD DETAIL, DIM	11/19/85	85-2241	
HSC-162-3-H2	PLATE THICKNESS, WLD DETAIL, DIM	11/19/85	85-2242	
HSC-162-3-H3	DIM, CLEARANCE	11/19/85	85-2243	
IF-LI-214-H1	DIM, WLD DETAIL	11/19/85	85-2265	
IF-LI-214-H8	DIM, WLD DETAIL, CLEARANCE	11/19/85	85-2266	

17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
I/F-LI-214-A3	DIM, WLD DETAIL	11/19/85	85-2267	
I/F-LT-RC14-3-H27	WLD & DIM NOT PER DWG	11/20/85	85-2274	
I/F-LT-RC14-3-H26	DIM & WLD NOT PER DWG	11/20/85	85-2275	
I/F-LT-RC14-3-H20	DIM & WLD NOT PER DWG	11/20/85	85-2276	
I/F-LT-RC14-3-H28	DIM & WLD NOT PER DWG	11/20/85	85-2277	
I/F-LT-RC14-3-A3	DIM & WLD NOT PER DWG	11/20/85	85-2278	
I/F-LT-SP981-85-H8	WLD & ORIENT NOT PER DWG	11/20/85	85-2279	
I/F-LT-SP981-85-A3	WLD & ORIENT NOT PER DWG	11/20/85	85-2280	
I/F-LT-SP981-85-H10	WLD & ORIENT NOT PER DWG, CLEARANCE	11/20/85	85-2281	
I/F-LT-SP981-85-H9	DIM NOT PER DWG	11/20/85	85-2282	
I/F-LT-SP981-85-H7	WLD NOT PER DWG	11/20/85	85-2283	
I/F-LT-SP981-85-H6	WLD, DIM, & ORIENT NOT PER DWG, NUTS MISSING	11/20/85	85-2284	
I/F-LT-SP981-85-H5	DIM NOT PER DWG, NUTS MISSING	11/20/85	85-2285	
I/F-LT-SP981-85-H3	ORIENT & WLD NOT PER DWG, ANGLED ANCHOR	11/20/85	85-2286	
I/F-LT-SP981-85-H1	WLD NOT PER DWG	11/20/85	85-2287	
I/F-LT-SP981-85-A6	MEMBER, WLD, & DIM NOT PER DWG	11/20/85	85-2294	
I/F-LT-SP981-85-H11	WLD, DIM, & CLEAR NOT PER DWG	11/20/85	85-2295	
I/F-LT-SP981-85-H3	DIM & ORIENT NOT PER DWG	11/20/85	85-2296	
I/F-LT-SP981-85-H16	DIM NOT PER DWG	11/20/85	85-2297	
I/F-LT-SP981-85-H12	WLD, DIM, & MEMBERS NOT PER DWG	11/20/85	85-2298	
I/F-LT-SP981-85-H15	WLD NOT PER DWG	11/20/85	85-2299	
I/F-LT-SP981-85-H15	WLD, DIM, & MEMBERS NOT PER DWG, NUTS MISSING	11/20/85	85-2300	
I/F-LT-SP981-85-H4	DIM NOT PER DWG	11/20/85	85-2302	



SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
I/F-LT-SP9B1-B5-A5	DIM NOT PER DWG	11/20/85	85-2303	
I/F-PT-RC2A5-A1	BASEPLATE GROUTED, NO HGR. DET.	11/20/85	85-2306	
I/F-PT-RC2A5-H3	BASEPLATE GROUTED, NO HGR. DET.	11/20/85	85-2307	
I/F-PT-RC2A5-H2	BASEPLATE GROUTED, NO HGR. DET.	11/20/85	85-2308	
I/F-PT-RC2A5-H1	WLDs NOT PER DWG, SPACER MISSING, NUT LOOSE	11/20/85	85-2309	
I/F-PT-RC2A1-A1	BASEPLATE GROUTED	11/20/85	85-2310	
I/F-PT-RC2A1-H3	BASEPLATE GROUTED, WLD & CLEAR NOT PER DWG	11/20/85	85-2311	
I/F-PT-RC2A1-H2	NO SPACER, WLD NOT PER DWG	11/20/85	85-2312	
I/F-PT-RC2A1-H1	MEMBER & WLD NOT PER DWG, BASEPLATE GROUTED	11/20/85	85-2313	
I/F-LT-SP9B1-B5-H20	WLDs & DIM NOT PER DWG	11/20/85	85-2317	
I/F-LT-SP9B1-B5-H17	WLDs NOT ON/PER DWG	11/20/85	85-2318	
I/F-LT-RC14-1-H13	WLDs NOT PER DWG	11/21/85	85-2319	
I/F-LT-RC14-1-H27	BOLTS & ATTACH NOT ON DWG	11/21/85	85-2321	
I/F-LT-RC14-1-H14	WLD NOT ON DWG	11/21/85	85-2322	
I/F-LT-RC14-1-H23	WLD NOT ON DWG	11/21/85	85-2323	
I/F-LT-RC14-1-H13	WLD NOT ON DWG	11/21/85	85-2324	
I/F-LT-RC14-1-H22	WLD NOT ON DWG	11/21/85	85-2325	
I/F-LT-RC14-1-H21	WLD NOT ON DWG	11/21/85	85-2326	
I/F-LT-RC14-1-H12	WLD NOT ON DWG	11/21/85	85-2327	
I/F-LT-RC14-1-H24	WLD & DIM NOT ON DWG	11/21/85	85-2328	
I/F-LT-RC14-1-H5	WLD DETAIL, PHILLIPS VS WEJ-IT	11/21/85	85-2331	
I/F-LT-RC14-1-H6	WLD DETAIL, PHILLIPS VS WEJ-IT	11/21/85	85-2332	
I/F-LT-RC14-1-H7	WLD DETAIL, PHILLIPS VS WEJ-IT	11/21/85	85-2333	
I/F-LT-RC14-1-H8	WLD DETAIL, PHILLIPS VS WEJ-IT	11/21/85	85-2334	

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCF/SR NUMBER	DISPOSITION
I/F-LT-RC14-1-A2	THD ENGAGEMENT, BOLT SKEW, WLD DETAIL, PHILLIPS VS WEJ-IT	11/21/85	85-2335	
I/F-LT-RC14-1-H3	BOLT SKEW, WLD DETAIL	11/21/85	85-2336	
I/F-LT-RC14-1-H2	PHILLIPS VS WEJ-IT, GAP, WLD DETAIL	11/21/85	85-2337	
I/F-LT-RC14-1-A5	PHILLIPS VS WEJ-IT, ATTACH DETAIL	11/21/85	85-2338	
I/F-LT-RC14-1-A4	PHILLIPS VS WEJ-IT, ATTACH DETAIL	11/21/85	85-2339	
I/F-LT-RC14-1-A3	PHILLIPS VS WEJ-IT, ATTACH DETAIL	11/21/85	85-2340	
I/F-LT-RC14-1-H9	MODIFIED STRAP, PL GAP, WLD DETAIL, DIM, BOLT SKEWED	11/21/85	85-2341	
I/F-LT-RC14-1-H1	PHILLIPS VS WEJ-IT, BOLT SKEWED, DIM, WLD DETAIL	11/21/85	85-2342	
I/F-LT-RC14-1-H19	PHILLIPS VS WEJ-IT, ATTACH DETAIL	11/21/85	85-2343	
I/F-LT-RC14-1-H25	SHIM ADDED, WLD DETAIL	11/21/85	85-2344	
I/F-LT-RC14-1-H17	WLD DETAIL	11/21/85	85-2345	
I/F-LT-RC14-1-H26	WLD DETAIL	11/21/85	85-2346	
IF-LT-RC14-H9	BOLT TYPE, WLD DETAIL, DIM, CLEARANCE	11/20/85	85-2352	
M-CCB-8-24-H5	WLD DETAIL, CLEARANCE	11/20/85	85-2375	
M-CCB-8-24-H6	INSTALL DETAIL	11/20/85	85-2376	
M-CCB-8-24-H7	WLD DETAIL	11/20/85	85-2377	
M-CCB-8-24-H8	DIM	11/20/85	85-2378	
M-CCB-8-24-H9	WLD DETAIL	11/20/85	85-2379	
I/F-LT-RC14-3-H6	WLD SZ, DIM	11/22/85	85-2392	
I/F-LT-RC14-3-H10	DIM, PIPE STRAP VS GUIDE	11/22/85	85-2393	
I/F-LT-RC14-3-H14	PG-45 VS PG-46	11/22/85	85-2394	
I/F-LT-RC14-3-H13	DIM, PG-45 VS PG-46	11/22/85	85-2395	

17

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
I/F-LT-RC14-3-H15A	DIM	11/22/85	85-2397	
M-CCB-8-25-H14	CLEARANCE, PIPE CLAMP	11/22/85	85-2398	
I/F-LT-RC14-3-H5	WLD SZ, DIM	11/22/85	85-2422	
I/F-LT-RC14-3-H3	GAP	11/22/85	85-2423	
I/F-LT-RC14-3-A1	PG-45 VS ANCHOR	11/22/85	85-2424	
M-CCB-8-25-H12	WLDs & DIMS NOT ON DWG	11/22/85	85-2425	
M-CCB-8-25-H13	WLDs & DIMS NOT ON DWG	11/22/85	85-2426	
M-CCB-8-25-H10	WLDs NOT ON DWG	11/22/85	85-2427	
M-CCB-8-25-H11	WLDs & DIMS NOT ON DWG	11/22/85	85-2428	
I/F-LT-RC14-3-H1	DIMS NOT PER DWG	11/22/85	85-2429	
I/F-LT-RC14-3-H3	DIM NOT PER DWG	11/22/85	85-2430	
M-CCB-8-25-H15	CLEARANCE, ANGLE VS BEAM	11/22/85	85-2431	
I/F-LT-RC14-2-A1	DIM NOT PER DWG	11/22/85	85-2435	
I/F-LT-RC14-2-H1	DIM, WLD SZ	11/22/85	85-2436	
M-HCC-56-9-H	DWG DETAILS	11/22/85	85-2441	
M-CCB-8-25-H16	BAR VS PLATE, PLATE SZ, WLD SZ NOT ON/PER DWG	11/25/85	85-2455	
M-CCB-8-25-H17	WLD DETAIL, DIM, CLEARANCE	11/25/85	85-2456	
M-CCB-8-25-H18	WLD SZ & LENGTH	11/25/85	85-2457	
M-CCB-8-25-A2	DIM, BOLT SPACING, WLD DETAIL NOT ON DWG	11/25/85	85-2458	
M-HSC-162-1-A1	THD ENGAGEMENT, PLATE SZ, ANCHOR BOLT SPACING	11/25/85	85-2468	
M-HSC-162-1-H2	WLD SZ, DIM, CLEARANCE	11/25/85	85-2469	

17

SECTION 17.0

QUENCH TANK DRAIN SYSTEM

SYSTEM: QUENCH TANK DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
40-HCB-22-H2	WELD DETAIL	10/14/85	85-1165	
40-HCB-22-H1	ANCHORBOLT SPACING, WELDS, PIPE LOC, DIMENSIONS	10/16/85	85-1204	
A-393	ANCHORBOLT, WELDS, DIMENSIONS	10/16/85	85-1205	
40-HCB-22-H3	ANCHORBOLT LOCATION, WELD. GAP DIMENSION	10/16/85	85-1206	

SECTION 18.0

COMPONENT COOLING WATER SYSTEM



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	ICR/SR NUMBER	DISPOSITION
A-124	WELD CHANGES, BOLT SPACING VIOLATIONS AND STIFFENER DIMENSIONS	10/14/85	85-1169	
36-HBB-12-H4	MEMBER LENGTHS AND WELD SIZES AND CONFIGURATIONS	10/14/85	85-1171	
36-HBB-12-H7	DIMENSIONS, WELD DETAIL & SIZE	10/15/85	85-1177	
36-HBB-12-H9	ANCHORBOLTS, PLATE SIZE DIMENSION	10/16/85	85-1199	
36-HBB-1-H4	BASEPLATE GAPS, MEM. WELDS & DIMENSIONS	10/16/85	85-1209	
A-126	WRAPPER PLATE LENGTH, DRAWING ERRORS	10/16/85	85-1210	
36-HBB-12-H8	ANCHORBOLTS, WELDS	10/16/85	85-1215	
A-125	WELDS, GROUT MISSING (PARTIAL)	10/16/85	85-1229	
36-HBB-1-H3	WELDMENTS UNDERSIZED	10/16/85	85-1230	
36-HBB-12-H3	WELDS AND CLEARANCE DIMENSION	10/16/85	85-1231	
A-122	BOLT LOCATIONS, WELDS UNDERSIZED, DIMENSIONS	10/17/85	85-1249	
A-335	LOC. DIM.'S WELDS UNDERSIZED BOLT LOC. SUPPORT EL.	10/17/85	85-1268	
36-HBB-4-H204	WELDS UNDERSIZED, PLATES TACK WELDED TO SUPPORT, BASE PLATE GAPS	10/18/85	85-1279	
36-HBB-3-H205	ANCHOR BOLTS W/3-WASHERS, WELDS ARE UNDERSIZE, BASE PLATE GAPS	10/18/85	85-1280	
36-HBB-3-H112	MATERIAL SIZE REDUCED, PLATE GAPS, LOOSE L.NUT	10/18/85	85-1281	
36-HBB-4-H201		/ /	85-1283	
36-HCB-40-H1	WELDS UNDERSIZE & ADDITIONAL WELD	10/18/85	85-1285	
36-HBB-4-H205	WELDS UNDERSIZE, BASE PLATE GAPS, ANCHOR BOLT W/3-WASHERS	10/18/85	85-1286	
36-HBB-4-H208		/ /	85-1290	
36-HBB-3-H106	MATERIAL SIZE DECREASED	10/18/85	85-1291	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
36-HBB-3-H203	WELDS UNDERSIZE, PLATES ADDED UNDER CHANNELS	10/18/85	85-1292	
36-HBB-4-H206	WELDS UNDERSIZE	10/18/85	85-1293	
36-HBB-3-H204	WELDS UNDERSIZE, SPACERS ADDED, BOLT SPACING	10/18/85	85-1294	
36-HBB-3-H206	WELDS UNDERSIZED, 1-ANCHOR BOLT NUT BOT. OUT & 3/4" INST. NOT 5/8"	10/18/85	85-1295	
36-HBB-3-H207	WELDS UNDERSIZED, INSTALLED BOLTS ARE 3/4" NOT 5/8" ALL W/3-WASHERS	10/18/85	85-1296	
36-HBB-3-H209	5/8" SPACERS ADDED, WELDS UNDERSIZED, BOLT SPACING	10/18/85	85-1297	
36-HBB-3-H211	MATERIAL SIZE INCREASED, WELDS UNDERSIZED WEST IT-2 NOT PER DRAWING	10/18/85	85-1298	
36-HBB-4-H209	PLATES ADDED, WELDS UNDERSIZED, BOLT EDGE DISTANCE INCREASED	10/18/85	85-1299	
36-HBB-4-H208	BOLT SPACING, WELD DELETED	10/18/85	85-1300	
36-HBB-4-H207	WELDS UNDERSIZED	10/18/85	85-1301	
36-HBB-3-H210		10/18/85	85-1302	
36-HBB-3-H201	3-WASHERS ON ANCHOR BOLTS, PLATE GAPS	10/18/85	85-1303	
36-HBB-4-H200	MATERIAL CHANGED, WELD UNDERSIZED	10/18/85	85-1304	
36-HBB-4-H202	3-WASHERS ON ANCHOR BOLTS	10/18/85	85-1305	
36-HBB-12-H6	WELD DELETED, PLATE CUT TO AVOID INTF. SNUBBER PLATE & TAG PLAGE DO NOT AGREE	10/18/85	85-1306	
36-HBB-3-H111	MATERIAL SIZE REDUCED, NOT FULL THD. ENGAGEMENT 1-BOLT	10/19/85	85-1328	
36-HBB-4-H214	WELDS UNDERSIZED	10/19/85	85-1331	
36-HBB-4-H217	WELDS UNDERSIZED	10/19/85	85-1332	
36-HBB-3-H219	WELD UNDERSIZED, IT-3 ROATED 180 DEGREES	10/19/85	85-1333	
36-HBB-4-H216	WELDS UNDERSIZE	10/19/85	85-1334	

SYSTEM: COMPONENT COOLING WATER

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
36-HBB-3-H224	WELD SYMBOL MISSING, WELD UNDERSIZED, ANCHOR BOLT SIZE INCREASED	10/19/85	85-1335	
36-HBB-3-H218	WELD UNDERSIZED, HOLES EXIST IN IT-1, ANCHOR BOLTS TRIMMED	10/19/85	85-1339	
36-HBB-4-H215	WASHER PLATE THK. DECREASED, WELD UNDERSIZED, ANCHOR BOLTS TRIMMED	10/19/85	85-1340	
36-HBB-4-H213	3 WASHER ON ANCHOR BOLTS, UNDERSIZE WELDS, WASHER PLATE THK. REDUCED	10/19/85	85-1341	
36-HBB-3-H217	ANCHOR BOLTS NOT PER CATALOG	10/19/85	85-1342	
36-HBB-3-H223	ANCHOR BOLTS TRIMMED, WELDS ARE UNDERSIZE AND NOT PER DRAWING	10/21/85	85-1347	
36-HBB-3-H222	BASEPLATE SIZE INCREASED, WELDS ARE UNDERSIZED	10/21/85	85-1348	
36-HBB-3-H214	BASEPLATE SIZE INCREASED, WELD UNDERSIZED, PLATE ADDED FOR STABILITY	10/21/85	85-1349	
36-HBB-3-H216	WELD NOT ON DRAWING, UNDERSIZED WELD	10/21/85	85-1362	
36-HBB-3-H212		/ /	85-1363	
36-HBB-3-H116	1/2" HILTI'S INSTALLED NOT WEJ-ITS, BOLT-1 TRIMMED, BAR ADDED TO STABILIZE SPT.	10/21/85	85-1364	
36-HBB-4-H211	BOLT WITH NO WASHER, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1365	
36-HBB-3-H215	BOLTS NOT PER DRAWING, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1367	
36-HBB-4-H210	PLATE GAPS, BOLT TRIMMED, WELDS UNDERSIZED	10/21/85	85-1368	
36-HBB-3-H213	PLATE SIZE INCREASED, WELD DELETED	/ /	85-1369	
36-HBB-4-H221	WELDS NOT PER DRAWING & UNDERSIZED	10/21/85	85-1370	
36-HBB-4-H220	WELDS NOT PER DRAWING	10/21/85	85-1371	
36-HBB-4-H219	ROD NOT PER DRAWING, STAKED THREADS	10/23/85	85-1416	
C-857-A-12b	ANCHOR BOLTS SPACING UNACCEPTABLE, DIMEN. NOT PER DRAWING	10/23/85	85-1417	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
36-HBB-4-H219	BASE PLATE GAP UNACCEPTABLE, WELD & DIMEN. NOT PER DRAWING	10/23/85	85-1418	
HBB-3-H221	WELDS UNDERSIZED, STAKED THREADS, GROUT 3-SIDES	10/25/85	85-1455	
A-125	WELDS UNDERSIZED, PLATE THK. INCREASED	10/25/85	85-1456	
HBB-3-H220	ANCHORBOLTS W/2 NUTS, BOLT W/3-WASHERS, 1/2 PAINTED	10/25/85	85-1472	
CCB-28-6-H3	STRAP DIMENSION	11/13/85	85-2030	
CCB-28-6-H2	SHIM NOT PER DWG	11/13/85	85-2031	
CCB-28-6-H1	GAP UNACC, DIMEN & BOLT SPACING NOT PER DWG	11/13/85	85-2032	
CCB-28-2-H7	WLDs & DIM NOT PER DWG, GAP UNDER PIPE	11/13/85	85-2038	
CCB-28-2-H8	WLD & DIM NOT PER DWG	11/13/85	85-2039	
CCB-28-2-H10	WLDs, DIM, PAINT, & GAP NOT ACCEPTABLE	11/13/85	85-2040	

SECTION 19.0

STEAM GENERATOR DRAIN SYSTEM

SYSTEM: STEAM GENERATOR DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1147-H7	ANCHOR SPACING, SHIM INSTALLED, EMBED.	10/15/85	85-1172	
M-1147-H4	DIMENSIONS	10/15/85	85-1173	
7-EBB-5-H3	WELD SIZE & DETAIL	10/15/85	85-1174	
M-1147-H5	DIMENSION, WELD DETAIL	10/15/85	85-1175	
M-1147-H6	DIMENSION	10/15/85	85-1176	
7-EBB-5-H8	THREAD STAKED, BASE PLATE GROUTED, GREASE FITTING DAMAGE	10/15/85	85-1179	
7-EBB-5-H7	NO WASHER, BASE PL. GROUTED, DIMENSION, WELD SIZE, SNAP RING DAMAGED	10/15/85	85-1180	
M-1147-H8	ADDITIONAL ANGLE	10/15/85	85-1190	
7-EBB-5-H12	WELDS, GAP	10/16/85	85-1196	
7-EBB-5-H10	ANCHORBOLTS, WELDS, LOOSE CLAMP BOLT	10/16/85	85-1197	
7-EBB-5-H14	WELD SIZE	10/16/85	85-1198	
7-EBB-5-H16	ANCHORBOLT, WELDS, STAKED THREAD	10/16/85	85-1201	
7-EBB-5-H15	ARC STRIKE ON PIPE, WELDS	10/16/85	85-1202	
M-1147-H2	ANCHORBOLT SPACING, ADDED WELD	10/16/85	85-1203	
7-EBB-5-H13	PIN TO PIN, WELDS, CLAMP TO PIPE DIMENSION	10/16/85	85-1208	
7-EBB-5-H17	WELDMENTS UNDERSIZED	10/16/85	85-1211	
M-1147-H1	ANCHORBOLT EMB., BASEPLATE GAPS, DIMENSIONS	10/16/85	85-1212	
M-1147-H9	ANCHORBOLT & BASEPLATE SIZE, WELDS, DIMENSIONS	10/16/85	85-1213	
M-1147-H10	ADDED WELD	10/16/85	85-1214	
7-EBB-5-H18	WELDS UNDERSIZE	10/16/85	85-1216	
7-EBB-5-H11	PLATE GROUTED, WELDS, SNUBBER & CLAMP	10/16/85	85-1218	
M-1147-H13	ANCHORBOLT EMB, WELDS, DIMENSIONS	10/16/85	85-1219	



REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1147-H14	ATTACHMENT LOCATION ON BASEPLATE	10/16/85	85-1220	
M-1147-H12	WELD, BOLT EMB., DIMENSIONS, PLATE SIZE	10/16/85	85-1221	
M-1147-H15	ANCHORBOLT SPACING, WELD, PIPE LOCATION	10/16/85	85-1222	
M-1147-H11	ANCHORBOLT EMB. AND EDGE DISTANCE	10/16/85	85-1223	
7-EBB-5-H4	WELDS, GAP INCREASED	10/16/85	85-1232	
7-EBB-5-H5	WELDS, MATERIAL SIZE	10/16/85	85-1233	
7-EBB-5-H6	WELDS UNDERSIZED	10/16/85	85-1234	
M-1147-H17	BOLT EMB. & LOCATIONS, WELD DETAIL	10/17/85	85-1243	
M-1147-H16	BOLT THREAD ENGAGEMENT & LOCATION DIMENSION & LENGTH	10/17/85	85-1244	
M-1147-H18	WELD TYPE, MEM. LOCATION DIMENSION & LENGTH	10/17/85	85-1245	
7-EBB-5-H27	WELDS UNDERSIZED, LOCATING DIMENSIONS	10/17/85	85-1248	
7-EBB-5-H26	BOLT SIZE, WELD LENGTH, GAPS INCREASED	10/17/85	85-1250	
7-EBB-5-H9	WELDS UNDERSIZE, PIPE CLEARANCES	10/17/85	85-1252	
M-1147-H19	BASE PLATE SIZE, SUPPORT DIMENSIONS, WELD TYPES	10/17/85	85-1253	
7-EBB-5-H33	WELD SYMBOL MISSING, WELDS UNDERSIZE, SUPPORT DIMENSIONS	10/17/85	85-1254	
7-EBB-5-H20	WELD UNDERSIZE, MEMBER LENGTH SHORTENED	10/17/85	85-1256	
7-EBB-5-H21	WELDS UNDERSIZED AND MISSING SYMBOL	10/17/85	85-1257	
7-EBB-5-H34	WELD LENGTH DECREASED	10/17/85	85-1258	
7-EBB-5-H32	WELDMENTS UNDERSIZED	10/17/85	85-1259	
7-EBB-5-H24		10/17/85	85-1264	
7-EBB-5-H25	STANCHION LENGTH INCREASED 1/4 in	10/17/85	85-1265	
7-EBB-5-H23		10/17/85	85-1266	

SYSTEM: STEAM GENERATOR DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
7-EBB-5-H22	W4 INSTALLED INSTEAD OF M4-2 MEM. 'S WELD UNDERSIZED MEM. LTH. CLAMP 5-DIM.	10/17/85	85-1267	
M-1142-H7	LOCATION DIMENSION, WELD UNDERSIZE, GAPS REDUCED	10/25/85	85-1476	
M-1142-H10	DIMENSION SHORTENED, NO WEEP HOLE, WELD UNDERSIZED	10/25/85	85-1477	
CCA(36"10)-2-H	WELDS UNDERSIZED, LOCK WIRE MISSING	10/25/85	85-1486	
CCA(36"10)-2-H	SNUBBER INTERFERENCE, DIMENSIONS SHORTEN, WELD SIZES	10/25/85	85-1487	
CCA-20-1-H7	MISSING LOCKWIRE, WELD NOT PER DRAWING	10/29/85	85-1523	
CCA-20-1-H1	WELDS NOT PER DRAWING, MISSING LOCK WIRE	10/29/85	85-1534	
CCA-20-1-H3	WELDS & WASHERS NOT PER DRAWING, MISSING LOCK WIRE	10/29/85	85-1535	
CCA-20-1-H5	WELDS, GAP, WASHERS, & BOLT NOT PER DRAWING	10/29/85	85-1536	
CCA-20-H12	WELDS & SHIM NOT PER DRAWING	10/29/85	85-1537	
CCA-20-1-H2		10/29/85	85-1538	
CCA-20-1-H6	WELD NOT PER DRAWING	10/29/85	85-1539	
CCA-20-1-H8	WELD NOT PER DRAWING	10/29/85	85-1540	
CCA-20-1-H10	WELD NOT PER DRAWING	10/29/85	85-1541	
M-CCB-24-2-A2	FLAME CUT HOLE, # WSHRS, THD ENGAGEMENT, NUT MISSING, NO GROUT	11/07/85	85-1805	
M-EBB-5-3-H2	FAINT SPATTER, NO LOCKWIRE	11/09/85	85-1849	
M-EBB-5-3-H1	DIMENSION	11/09/85	85-1850	
M-EBB-5-5-H5	DIMENSION, WLD DETAIL, MISC HARDWARE PROBS	11/09/85	85-1851	
M-EBB-5-3-H3	WLD SZ	11/09/85	85-1859	
M-EBB-5-6-H1	PAINT SPATTER, NO LOCKWIRE	11/09/85	85-1860	
M-EBB-5-6-H2	PAINT SPATTER, NO LOCKWIRE	11/09/85	85-1861	

SYSTEM: STEAM GENERATOR DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-EBB-5-5-A1	MODIFIES CLAMP, MISC HARDWARE PROBS	11/09/85	85-1862	
M-EBB-5-5-H4	ANGULARITY, MISC HARDWARE PROBS	11/09/85	85-1863	
M-EBB-5-8-A3	MEMBER ROTATED, DIMENSION LOCATION	11/12/85	85-1926	
M-EBB-5-8-H6	WLD DETAIL, DIMENSION	11/12/85	85-1927	
M-EBB-5-8-A2	MODIFIED TEE, WLD SZ, DIMENSION, THD ENGAGEMENT	11/12/85	85-1928	
M-EBB-5-8-H5	WLD SZ, DIMENSION	11/12/85	85-1929	
M-EBB-5-12-H4	WLD DETAIL, NO LOCKWIRE, THD STAKED	11/12/85	85-1956	
M-EBB-5-13-H1	ADAPTION, NO LOCKWIRE, THD STAKED	11/12/85	85-1957	
M-EBB-5-19-A1	DIMENSION	11/12/85	85-1969	
M-EBB-5-19-A1	DIMENSION	11/12/85	85-1970	
M-EBB-5-2-H2	DIMENSION, WLD DETAIL & SZ	11/12/85	85-1973	
M-EBB-5-2-H3	ADDITIONAL PLATE, NO LOCKWIRE, CLAMPATTACH	11/12/85	85-1974	
M-EBB-5-2-H1	DWG DETAIL, DIMENSION, WLD SZ	11/12/85	85-1979	
M-EBB-5-12-H1	WLD CLEARANCE	11/12/85	85-2007	
EBB-5-8-H7	CLAMP THDS PROB, WLD & PG-41 NOT PER DWG	11/13/85	85-2061	
EBB-5-8-H8	WLD & LOCATION NOT PER DWG	11/13/85	85-2062	
EBB-5-15-H10	WLD & DIM NOT PER DWG, NO BOM	11/15/85	85-2099	
EBB-5-15-H9	WLD & DIM NOT PER DWG, NO BOM	11/15/85	85-2100	
EBB-5-15-H1	GROUT, DIM, & WLD NOT PER DWG	11/15/85	85-2103	
EBB-5-15-H2	GROUT, DIM, & WLD NOT PER DWG	11/15/85	85-2104	
EBB-5-15-A1	MEMBER DIM NOT PER DWG	11/15/85	85-2105	
EBB-5-15-H4	GROUT & WLD NOT PER DWG	11/15/85	85-2106	
EBB-5-15-H5	GROUT & WLD NOT PER DWG	11/15/85	85-2107	

17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
EBB-5-15-A2	GROUT & WLDS NOT PER DWG	11/15/85	85-2108	
EBB-5-15-H6	GROUT & WLDS NOT PER DWG, MISSING BOM	11/15/85	85-2109	
EBB-5-15-H7	GROUT, WLDS, & PG-45 NOT PER DWG	11/15/85	85-2110	
EBB-5-15-H8	NO BOM	11/15/85	85-2111	
EBB-5-16-A1	DIM NOT PER DWG	11/16/85	85-2131	
EBB-5-16-H2	WLD NOT PER DWG	11/16/85	85-2132	
EBB-5-16-H5	GROUT NOT PER DWG	11/16/85	85-2133	
EBB-5-7-H9	GAP UNKNOWN UNDER BASEPLATE	11/16/85	85-2134	
EBB-5-7-H8	ANCHOR SPACING UNACC, BASEPLATE GAP UNKNOWN DUE TO GROUT	11/16/85	85-2135	
EBB-5-7-H7	WLD NOT PER DWG, GAP UNKNOWN	11/16/85	85-2136	
EBB-5-7-H6	ANCHOR SPACING UNACC, WLDS NOT PER DWG	11/16/85	85-2137	
EBB-5-7-H5	MISSING LOCK DEVICE ON LOAD PIN	11/16/85	85-2138	
EBB-5-7-H4	ORIENT & WLDS NOT PER DWG, MISSING LOCKWIRE, SNUBBER CONE VIOLATION	11/16/85	85-2139	
EBB-5-7-H3	ORIENT & WLDS NOT PER DWG, MISSING LOCKWIRE	11/16/85	85-2140	
EBB-5-16-H7	NO BOM	11/16/85	85-2141	
EBB-5-7-H10	BASEPLATE BEARING UNKNOWN DUE TO GROUT, THD STKD	11/16/85	85-2142	
EBB-5-7-H1	SUPPORT ATTACHED TO EMBEDDED PLATE NOT PER DWG	11/16/85	85-2143	
EBB-5-16-H2	MISSING BOM, WLDS & CLEAR NOT PER DWG	11/16/85	85-2145	
EBB-5-16-H1	MISSING BOM, WLDS & CLEAR NOT PER DWG	11/16/85	85-2146	
EBB-5-16-H9	WLD NOT ON DWG, THDS STKD	11/16/85	85-2147	
EBB-5-16-A2	NO BOM, WLDS NOT PER DWG	11/16/85	85-2148	
EBB-5-16-H4	WLDS NOT PER DWG	11/16/85	85-2149	

SYSTEM: STEAM GENERATOR DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
EBB-5-16-H8	NO BOM, WLDS, GROUT & DIM NOT PER DWG	11/16/85	85-2150	
M-EBB-5-17-H9	WLD NOT PER DWG, MISSING LOCKWIRE, BOLTS STKD	11/18/85	85-2172	
EBB-5-17-H10	DIM & WLDS NOT PER DWG	11/18/85	85-2173	
EBB-5-17-H12	WLDS, DIM, & MEMBERS NOT PER DWG	11/18/85	85-2174	
EBB-5-17-A3	SHIM NOT PER DWG, WLDS NOT ON DWG	11/18/85	85-2175	
EBB-5-17-A1	WLDS & DIM NOT PER DWG, GAP UNACC	11/18/85	85-2176	
EBB-5-17-H13	WLDS & DIM NOT PER DWG, BASEPLATE & GAP UNACC	11/18/85	85-2177	
EBB-17-H2	DIM & WLD NOT PER DWG	11/18/85	85-2178	
EBB-5-17-H3	THDS STKD ON CLAMP BOLTS	11/18/85	85-2179	
EBB-5-17-H1	WLDS NOT PER DWG, MISSING LOCKWIRES, THDS STKD ON CLAMP	11/18/85	85-2180	
EBB-5-17-H5	SHIM SZ, WLD DETAIL, DIM, WLD SZ, GAP, PLATE GROUTED	11/18/85	85-2182	
EBB-5-17-H8	WLD DETAIL, DIM, PLATE GROUTED	11/18/85	85-2191	
EBB-5-17-H11	NO LOCKWIRE, THD STKD	11/18/85	85-2192	
EBB-5-17-H14	DIM, PLATE GROUTED	11/18/85	85-2193	
EBB-5-17-H15	SHIM ADDED, WLD UNDSZ	11/18/85	85-2194	
EBB-5-17-A2	WLD SZ	11/18/85	85-2195	
EBB-5-17-A4	PLATE THICKNESS, PLATE GROUTED, DWG DETAIL, WLD SZ, DIM	11/18/85	85-2196	
EBB-5-17-H6	DIM	11/18/85	85-2197	
EBB-5-17-H7	WLD SZ, DIM	11/18/85	85-2198	
EBB-5-7-A1	PLATES ADDED, WLD DETAIL	11/18/85	85-2200	
HCB-34-9-H46	BOLT SPACING, PLATE BEARING	11/19/85	85-2201	
HCB-34-9-H47	WLD DETAIL, UNDERCUT, DWG DETAIL	11/18/85	85-2202	

17

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
HC8-34-9-H50	PLATE GROUTED	11/18/85	85-2203	
HC8-34-9-H51	ANC BOLT SPACING, GROUTED PLATE	11/18/85	85-2204	
EB8-5-7-H11	WLD DETAIL, UNDERCUT, LACK OF FUSION	11/18/85	85-2211	
EB8-5-7-H-A2	PLATE GROUTED, LOCKNUT MISSING, DWG DETAIL	11/18/85	85-2212	
EB8-5-16-H6	WLD & CLEAR NOT PER DWG	11/20/85	85-2305	
EB8-5-15-H3	GROUT & WLD NOT PER DWG	11/20/85	85-2305	
I/F-LT-SP981-85-H19	WLD SZ	11/20/85	85-2348	
I/F-LT-SP981-85-H18	PG-44 VS PG-46	11/20/85	85-2349	
I/F-LT-SP981-85-H14	WLD DETAIL & SZ	11/20/85	85-2351	
IF-88-SP9A1-A2-A1	BOLT TYPE, WLD DETAIL	11/20/85	85-2353	
IF-88-SP9A1-A2-H6	DIM, GAP, WLD DETAIL	11/20/85	85-2356	
IF-88-SP9A1-A2-H2	WLD DETAIL, GAP, DIM	11/20/85	85-2357	
IF-88-SP9A1-A2-H5	BOLT TYPE, GAP, WLD DETAIL	11/20/85	85-2358	
IF-88-SP9A1-A2-H3	DIM, GAP, WLD DETAIL	11/20/85	85-2359	
IF-88-SP9A1-A2-A2	WLD DETAIL, BOLT TYPE	11/20/85	85-2360	
IF-88-SP9A1-A2-H1	WLD DETAIL	11/20/85	85-2361	
IF-88-SP9A1-A2-H4	DIM, GAP, WLD DETAIL	11/20/85	85-2362	
IF-88-SP983-84-A2	WLD DETAIL, DIM	11/21/85	85-2364	
IF-88-SP983-84-H5	WLD DETAIL, DIM	11/21/85	85-2365	
IF-88-SP983-84-H6	WLD DETAIL, DIM	11/21/85	85-2366	
IF-88-SP983-84-H2	WLD DETAIL, DIM	11/21/85	85-2367	
IF-88-SP983-84-A3	WLD DETAIL, DIM	11/21/85	85-2368	
IF-88-SP983-84-H7	WLD DETAIL, DIM	11/21/85	85-2369	
IF-88-SP983-84-H4	WLD DETAIL, DIM	11/21/85	85-2370	



REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
IF-SB-SP983-B4-H3	WLD DETAIL, DIM	11/21/85	85-2371	
IF-SB-SP983-B4-H12	WLD DETAIL, DIM	11/21/85	85-2372	
IF-SB-SP983-B4-A1	WLD DETAIL, DIM, MODIFIED TEE	11/21/85	85-2373	
IF-SB-SP983-B4-H:	WLD DETAIL	11/21/85	85-2374	
IF-LT-SP981-B5-H21	MEMBER SZ, WLD DETAIL & SZ	11/20/85	85-2380	
IF-SB-SP983-B4-H14	WLD DETAIL, DIM	11/21/85	85-2381	
IF-SB-SP983-B4-H13	WLD DETAIL	11/21/85	85-2382	
IF-SB-SP983-B4-H11	WLD DETAIL, DIM	11/21/85	85-2383	
IF-SB-SP983-B4-A4	DIM	11/21/85	85-2384	
IF-SB-SP983-B4-H10	DIM	11/21/85	85-2385	
IF-SB-SP983-B4-H15	WLD DETAIL	11/21/85	85-2386	
IF-SB-SP983-B4-H9	DIM	11/21/85	85-2387	
IF-SB-SP983-B4-H8	DIM	11/21/85	85-2388	
IF-SB-SP983-B4-H16	WLD DETAIL	11/21/85	85-2389	
I/F-LT-RC14-3-H12	MISSING WLD, GAP	11/22/85	85-2396	
I/F-LT-SP9A1-A5-H5	DIM	11/22/85	85-2399	
I/F-LT-SP9A1-A5-H3	DIM	11/22/85	85-2400	
I/F-LT-SP9A1-A5-H14	DIM	11/22/85	85-2401	
I/F-LT-SP9A1-A5-H13	DIM	11/22/85	85-2402	
I/F-LT-SP9A1-A5-H10	DIM	11/22/85	85-2403	
I/F-LT-SP9A1-A5-H12	DIM	11/22/85	85-2404	
I/F-LT-SP9A1-A5-H11	DIM	11/22/85	85-2405	
I/F-LT-SP9A1-A5-H4	PIPE CLAMP BOUND	11/22/85	85-2406	
I/F-LT-SP9A1-A5-H2	DIM	11/22/85	85-2407	

17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
I/F-LT-SP9A1-A5-H1	DIM	11/22/85	85-2408	
I/F-LT-SP9A1-A5-H9	PIPE/CLAMP GAP	11/22/85	85-2409	
I/F-LT-SP9A1-A5-H7	NUT MISSING, GAP	11/22/85	85-2410	
I/F-LT-SP9A1-A5-H6	GAP	11/22/85	85-2411	
I/F-LT-SP9A1-A5-H8	GAP	11/22/85	85-2412	
I/F-LT-SP9A1-A5-H14	WLDs NOT PER DWG	11/22/85	85-2413	
I/F-LT-SP9A1-A2-H9	WLDs NOT PER DWG	11/22/85	85-2414	
I/F-LT-SP9A1-A2-H13	WLDs & DIM NOT PER DWG	11/22/85	85-2415	
I/F-SB-SP9A1-A2-A3	WLDs NOT PER DWG, SHELL TYPE ANCHORS VS HILTIS	11/22/85	85-2416	
I/F-SB-SP9A1-A2-H7	GAPS, DIMS NOT ON DWG	11/22/85	85-2417	
I/F-SB-SP9A1-A2-H12	WLDs, DIMS NOT ON DWG	11/22/85	85-2418	
I/F-SB-SP9A1-A2-H11	GAP BETWEEN PIPE & ANGLE, WLDs & DIMS NOT ON DWG	11/22/85	85-2419	
I/F-SB-SP9A1-A2-H10	WLDs & DIMS NOT ON DWG, GAP	11/22/85	85-2420	
I/F-SB-SP9A1-A2-H8	WLDs & DIMS NOT ON DWG	11/22/85	85-2421	
I/F-SB-SP9B1-B2-H6	DIM, WLD SYMBOL NOT ON DWG	11/25/85	85-2459	
I/F-SB-SP9B1-B2-H7	WLD SYMBOL NOT ON DWG	11/25/85	85-2460	
I/F-SB-SP9B1-B2-A2	DIM, WLD DETAIL NOT ON DWG	11/25/85	85-2461	
I/F-SB-SP9B1-B2-A1	WLD DETAIL NOT ON DWG, WSHRS MISSING	11/25/85	85-2462	
I/F-SB-SP9B1-B2-H4	WLD DETAIL NOT ON DWG	11/25/85	85-2463	
I/F-SB-SP9B1-B2-H3	WSHRS MISSING, WLD DETAIL NOT ON DWG	11/25/85	85-2464	
I/F-SB-SP9B1-B2-H5	WLD DETAIL NOT ON DWG, BOLT INSTALLED AT ANGLE	11/25/85	85-2465	
I/F-SB-SP9B1-B2-H11	WLD DETAIL	11/25/85	85-2466	

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
I/F-88-SP981-82-A3	WLD DETAIL, DIM	11/25/85	85-2467	
I/F-88-SP981-82-H8	WLD DETAIL NOT ON DWG	11/25/85	85-2470	
I/F-88-SP981-82-H12	WLD DETAIL NOT ON DWG	11/25/85	85-2471	
I/F-88-SP981-82-H2	WLD DETAIL NOT ON DWG	11/25/85	85-2472	
I/F-88-SP981-82-H1	WLD DETAIL/DIM NOT ON DWG	11/25/85	85-2473	
I/F-88-SP981-82-H9	DIM, WLD DETAIL	11/25/85	85-2474	
I/F-88-SP981-82-H13	DIM, WLD DETAIL	11/25/85	85-2475	
I/F-88-SP981-82-H10	LOCATION, LENGTH, WLD DETAILS MISSING	11/25/85	85-2476	
I/F-88-SP981-82-H14	WLD DETAIL MISSING	11/25/85	85-2477	

17

SECTION 20.0

CONTAINMENT BUILDING VENT SYSTEM

SYSTEM: CONTAINMENT BUILDING VENT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
40-HCB-12-H2	MATERIAL CHANGE, WELD, STRUT ANGLE	10/16/85	85-1200	
40-HCB-12-H4	WELD TYPE & SIZE, MEM. LENGTH SHORTENED	10/17/85	85-1247	
40-HCB-12-H3		10/18/85	85-1277	
40-HCB-12-H6	LOC. OF ATT. ON BASEPLATE GAPS, WELDS	10/18/85	85-1278	
HCB-12-4-H36	WLD DETAIL, LOOSE BOLT, CLEARANCE	11/18/85	85-2181	
HCB-34-3-A2	MODIFIED YEE, MEMBER TYPE, DIM	11/19/85	85-2237	
HCB-34-3-H1	INSERT UNDER PLATE, GAP UNDER PLATE	11/19/85	85-2238	
CCB-17-1-H6	WLD DETAIL, CLEARANCE	11/19/85	85-2268	
CCB-17-1-H5	DIM, PLATE GAP, WLD DETAIL, CLEARANCE	11/19/85	85-2269	
CCB-17-1-H7	BOLT TYPE, DIM, WLD DETAIL, PLATE GAP	11/19/85	85-2270	
CCB-17-1-H8	BOLT TYPE, DIM, WLD DETAIL	11/19/85	85-2271	
M-CCB-17-1-A3	DIM, WLD DETAIL, PL. ADDED	11/20/85	85-2363	

17

SECTION 21.0  
REFUELING CANAL SYSTEM



REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-069	ANCHOR BOLT SPACING	10/22/85	85-1386	
IF-LI-214-H18	CLEAR NOT PER DWG	11/16/85	85-2152	
IF-LI-214-H20	WLD NOT ON DWG, DIM NOT PER DWG	11/16/85	85-2153	
IF-LI-214-H19	WLD & DIM NOT ON DWG	11/16/85	85-2154	
IF-LI-214-H17	ANCHOR BLTS & PG-45 NOT PER DWG, WLD & DIM NOT ON DWG	11/16/85	85-2155	
I/F-LI-214-H5	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2288	
I/F-LI-214-H6	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2289	
I/F-LI-214-H3	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2290	
I/F-LI-214-H2	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2291	
I/F-LI-214-H7	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2292	
I/F-LI-214-H4	BOLTS, WLDS, & DIM NOT PER DWG	11/20/85	85-2293	
I/F-LI-214-A1	BOLTS, WLDS, & DIM NOT ON/PER DWG	11/20/85	85-2314	
I/F-LI-214-A4	BOLTS, WLDS, & DIM NOT ON/PER DWG	11/20/85	85-2315	
I/F-LI-214-A2	BOLTS, WLDS, & DIM NOT ON/PER DWG	11/20/85	85-2316	

SECTION 22.0

HANGER LOCATION DISCREPANCIES

SYSTEM: HANGER LOCATION DISCREPANCIES

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-BCB-9-H5	HANGER LOCATION	10/19/85	85-1312	
33B-BCB-10-H16	HANGER LOCATION	10/22/85	85-1381	
33B-BCB-10-H17	HANGER LOCATION	10/22/85	85-1382	
A-221	HANGER LOCATION	10/22/85	85-1383	
33C-CCB-3-H2	HANGER LOCATION	10/22/85	85-1384	
33C-HCC-91-H10	HANGER LOCATION	10/21/85	85-1393	
33C-HCC-91-H5	HANGER LOCATION	10/21/85	85-1394	
33C-HCC-91-H3	HANGER LOCATION	10/21/85	85-1395	
33C-CCB-12-H3	HANGER LOCATION	10/21/85	85-1396	
33C-CCB-12-H1	HANGER LOCATION	10/21/85	85-1397	
HL-2330	HANGER LOCATION	10/21/85	85-1398	
33A-HCB-2-H14	HANGER LOCATION	10/23/85	85-1420	
33A-HCB-2-H6	HANGER LOCATION	10/23/85	85-1421	
41-HBC-53-H54	HANGER LOCATION	10/23/85	85-1422	
6C-EBD-14-H95	HANGER LOCATION	10/23/85	85-1423	
33C-CCB-2-H36	HANGER LOCATION	10/23/85	85-1424	
A-255	HANGER LOCATION	10/23/85	85-1425	
33C-CCB-2-H45	DISTANCE FROM IPE ELBOW	10/30/85	85-1575	
IF-LI-214	ADDITIONAL HANGER	11/18/85	85-2199	
EBB-5-7-H	ADDED SUPP	11/18/85	85-2210	
I/F-LT-RC14-1	ADDITIONAL HANGER NOT ON ISO	11/21/85	85-2329	
I/F-LT-RC14-1-H1	WLDs NO ON DWG, BOLTS NOT PER DWG	11/21/85	85-2330	
I/F-LT-RC14-1-H4	SUPP NO INSTALLED	11/21/85	85-2347	
M-CCB-24-2-H	MISSING SUPP	11/22/85	85-2474	

SECTION 23.0

MAIN FEEDWATER SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
SR-23	WELDS UNDERSIZED, GAPS	10/24/85	85-1428	
EBB-3-SR-21	WELDS, LOCATION & SIZE DIMENSIONS, GAPS	10/24/85	85-1429	
EBB-3-SR-20	WELD REDUCED, MEM. SHORTENED	10/24/85	85-1430	
EBB-3-H7	ANCHORBOLTS W/3-WASHERS, BEAM ATT. W/PIN	10/24/85	85-1431	
EBB-3-H6	WELD REDUCED, BEAM ATT. W/PIN, B.PLATE GAPS	10/24/85	85-1432	
H8	ANCHOR BOLT W/3 WASHERS, STAKED THREADS, GROUT CRACK	10/24/85	85-1450	
SR-22	WELDS UNDERSIZED, STAKED THREADS, BOLT MATERIAL & TYPE	10/24/85	85-1451	
EBB-3-SR26B	DIMENSION NOT PER DRAWING	10/29/85	85-1545	
EBB-3-SR-24B	WELDS NOT PER DRAWING	10/29/85	85-1546	
EBB-3-H10	WELDS NOT PER DRAWING	10/29/85	85-1547	
EBB-3-SR25B	MEMBERS & DIMEN. NOT PER DRAWING	10/29/85	85-1548	
EBB-3-H9	WELDS NOT PER DRAWING	10/29/85	85-1549	
EBB-3-SR25A	WLD DETAIL & SZ	10/30/85	85-1574	
EBB-3-SR24A	WLD SZ & DETAIL, EDGE DISTANCE	10/30/85	85-1576	
EBB-3-H12	WLD NOT PER DWG	11/04/85	85-1674	
EBB-3-SR24D	WLD UNDSZ & NOT PER DWG, INCCOR BOLTS	11/04/85	85-1675	
EBB-3-H11	INCORRECT WLD SYMBOLS	11/04/85	85-1676	
EBB-3-SR24C	WLD DETAIL & SZ, DIMENSIONS, TORQUE NOT MET, BOLT SZ, GAP	11/09/85	85-1853	

SECTION 24.0

STEAM GENERATOR VENT SYSTEM



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTON FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
FSK-M-1142-H6	PART # NOT ON DWG, DIMENSION, WLD SZ & DETAIL	10/30/85	85-1579	
FSK-M-1142-H9	WELD DIMENSION, DETAIL	10/30/85	85-1582	
FSK-M-1142-H8	DIMENSIONS, CLEARANCE	10/30/85	85-1584	
FSK-M-CCA-20-2-H1	LOCKNUT & WSHRS MISSING, WLD DETAIL & SZ	11/01/85	85-1641	
FSK-M-CCA-20-2-H4	WLD SZ & DETAIL, LOCKWIRE & WSHRS MISSING, BOLT LOOSE	11/01/85	85-1642	
FSK-M-CCA-20-2-H2	DIMENSIONS, WLD DETAIL	11/01/85	85-1643	
FSK-M-CCA-20-2-H3	LOCKNUT & SCALE LOOSE, WLD DETAIL	11/01/85	85-1644	
FSK-M-CCA-20-2-H5	DIMENSION, UNDERCUT	11/01/85	85-1645	
FSK-M-CCA-20-2-H6	TAG PAINTED, LOCKWIRE & WSHR MISSING, CLAMP LOOSE, WLD SZ	11/04/85	85-1662	
FSK-M-CCA-20-2-H9	NO SHIM, DIMENSION, WLD DETAIL	11/04/85	85-1663	
FSK-M-CCA-20-2-H7	WLDs NOT PER DWG, PLATE GAP, DIMENSION	11/04/85	85-1667	
FSK-M-CCA-20-2-H8	WLDs NOT PER DWG, THD ENGAGEMENT	11/04/85	85-1668	
M-EBB-5-22-H10	GROUT PLATE, BOLT SZ, WLD SZ, BOLT/NUT MISSING & LOOSE	11/08/85	85-1806	
M-EBB-5-22-H30	NO BOM	11/08/85	85-1807	
M-EBB-5-22-H29	NO BOM, WLD SYMBOL, ROD BENT, LOCK NUT LOOSE	11/08/85	85-1808	
M-EBB-5-22-H28	PLATE GROUTED, WLD SZ, BOLT SZ	11/08/85	85-1809	
M-EBB-5-22-H27	AWC. WILL NOT TORQUE, PLATE GROUTED, WLD SZ	11/08/85	85-1810	
M-EBB-5-22-H24	PLATE GROUTED, WLD SZ	11/08/85	85-1811	
M-EBB-5-22-H25	WLD SZ	11/08/85	85-1813	
M-EBB-5-22-H26	GROUT BEHIND BASEPLATE	11/08/85	85-1814	
M-HCB-74-2-H45	WLD SZ, CLEARANCE	11/09/85	85-1827	
M-HCB-74-2-H43	NO BOM, WLD SZ	11/09/85	85-1828	

17

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-HCB-34-2-H42	BASEPLATE GROUTED	11/09/85	85-1829	
M-HCB-34-2-H41	NO BOM, WLD SZ, CLEARANCE	11/09/85	85-1830	
M-HCB-34-2-H37	WLD SZ, NO BOM	11/09/85	85-1831	
M-HCB-34-2-H39	BASEPLATE GROUTED	11/09/85	85-1832	
M-HCB-34-2-H36	NO BOM, WLD SZ, CLEARANCE	11/09/85	85-1833	
M-HCB-34-2-H44	WLD DETAIL, NO BOM, BASEPLATE GROUTED	11/09/85	85-1834	
M-HCB-34-2-H38	NO BOM, WLD SZ, CLEARANCE	11/09/85	85-1835	
M-1142-H5	DIMENSIONS, WLD DETAIL, PLATEGAP, THD ENGAGEMENT, C-C SPACING	11/09/85	85-1837	
M-CCA-20-2-A1	WLD DETAIL, GAPS, BOLT TYPE	11/09/85	85-1846	
M-HCB-34-10-A2	MEMBER TYPE, DIMENSIONS	11/09/85	85-1848	
M-HCB-34-7-A2	DIMENSION, # OF PLATES	11/09/85	85-1857	
M-HCB-34-7-H12	DIMENSION, CLEARANCE	11/09/85	85-1858	
M-EBB-5-24-H34	PLATE GROUTED, WLD SZ & OVER LAP, WLD SYMBOL	11/09/85	85-1864	
M-EBB-5-24-H31	PLATE GROUTED	11/09/85	85-1865	
M-EBB-5-24-H32	PLATE GROUTED	11/09/85	85-1866	
M-EBB-5-24-H33	PLATE GROUTED, WLD SZ	11/09/85	85-1867	
M-EBB-5-24-A12	COMPLIANCE W/DWG	11/09/85	85-1868	
M-EBB-5-5-H2	NO LOCKWIRE, THD STAKED, INSTALL DETAIL NOT PER DWG	11/09/85	85-1869	
M-EBB-5-23-A9	WLD DETAIL, NO FULL THD ENGAGE, PLATE GROUTED	11/11/85	85-1879	
M-EBB-5-23-H22	WLD SZ & DETAIL, PLATE GROUTED	11/11/85	85-1880	
M-HCB-34-2-H40	NO BOM, BASEPLATE GROUTED, WLD SZ & DETAIL	11/09/85	85-1936	
HCB-34-9-H52	WLD DETAIL	11/18/85	85-2209	
HCB-34-9-H53	PLATE GROUTED, CLEARANCE	11/18/85	85-2208	

SYSTEM: STEAM GENERATOR VENT

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
HCB-34-9-HA19	C-C SPACING, ANC TYPE	11/18/85	85-2207	
HCB-34-9-HA20	PLATE GROUTED, WLD DETAIL	11/18/85	85-2208	
M-EBB-5-23-H15	BASEPLATE BEARING, WLD NOT PER DWG	11/22/85	85-2432	
M-EBB-5-23-H16	BOLT SIZE, BASEPLATE BEARING	11/22/85	85-2433	
M-EBB-5-23-H23	WLD SZ, WLD DETAIL, BASEPLATE BEARING	11/22/85	85-2437	
M-EBB-5-23-H4	WLD NOT PER DWG, BASEPLATE BEARING	11/22/85	85-2438	
M-EBB-5-23-H5	MATERIAL NOT PER DWG, BASEPLATE BEARING	11/22/85	85-2439	
M-EBB-5-23-H17	ANCHOR BOLT TORQUE, BASEPLATE BEARING	11/22/85	85-2440	
M-EBB-5-23-H18	BASEPLATE GAP, WLD SZ, ANCHOR BOLT SZ, WLD NOT PER DWG	11/25/85	85-2448	
M-EBB-5-23-H19	PLATE GROUTED, DIM, WLD SZ, CLEARANCE	11/25/85	85-2449	
M-EBB-5-23-H20	DIM, NO BOM, WLD SZ	11/25/85	85-2450	
M-EBB-5-23-H21	PLATE GROUTED, WLD SZ, ANCHOR BOLT SZ	11/25/85	85-2451	
M-EBB-5-23-H6	PLATE GROUTED, WLD SZ	11/25/85	85-2452	
M-EBB-5-23-H7	PLATE GROUTED ANCHOR BOLT SZ	11/25/85	85-2453	
M-EBB-5-23-H8	PLATE GROUTED, ANCHOR BOLT SZ, WLD SZ	11/25/85	85-2454	

17

SECTION 25.0  
PRESSURIZER SAMPLE SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
FSK-M-CCA-11-2-H1	PLATE GAP, WLD SZ & DETAIL, ANC BOLT LOCATION	10/30/85	85-1585	
FSK-M-CCA-11-2-H1A	WLD SZ & DETAIL	10/30/85	85-1586	
FSK-M-CCA-11-2-4	WLD SZ & DETAIL, TEE DETAIL, ANC BOLT LOCATION	10/30/85	85-1587	
FSK-M-CCA-11-2-43	WLD DETAIL & SZ	11/01/85	85-1634	
FSK-M-CCA-11-2-H23	WLD DETAIL	11/01/85	85-1635	
FSK-M-CCA-11-2-4	WLD DETAIL	11/01/85	85-1636	
M-CCA-14-1-H2	WLD DETAIL	11/08/85	85-1823	
M-CCA-14-1-H3	MEMBER DETAILS, WLD DETAIL & SZ, DIMENSIONS	11/08/85	85-1824	
M-1143-H5	DIMENSION, PIN TYPE	11/09/85	85-1854	
M-1143-H4	EMBEDMENT	11/09/85	85-1855	
M-1143-H3	DIMENSION	11/09/85	85-1856	
M-CCA-19-1-H6	WLD DETAIL	11/11/85	85-1877	
M-CCA-19-1-H5	DIMENSION	11/11/85	85-1887	
M-CCA-19-1-H1	DIMENSION	11/11/85	85-1888	
M-CCA-19-1-H2	DIMENSION	11/11/85	85-1889	
M-CCA-19-1-H4	DIMENSION, WLD DETAIL	11/11/85	85-1890	
M-CCA-19-1-H3	DIMENSION, WLD SZ & DETAIL, MEMBER TYPE	11/11/85	85-1891	
M-CCA-19-1-H7	DIMENSION	11/11/85	85-1892	
CCA-11-1-H24	DIM NOT PER DWG	11/14/85	85-2043	
CCA-11-1-H30	BOLTS, DIM, & WLDs NOT PER DWG	11/14/85	85-2048	
CCA-11-1-H28	WLDs & CLEAR NOT PER DWG	11/14/85	85-2054	
CCA-11-1-H27	DIM NOT PER DWG	11/14/85	85-2055	
CCA-11-1-44	LOCATION NOT ON DWG, DIM & WLD NOT PER DWG, CONC SPALLING	11/14/85	85-2058	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SF NUMBER	DISPOSITION
CCA-19-1-H14	DIM NOT ON DWG	11/13/85	85-2063	
CCA-11-1-H25	DIM NOT ON DWG	11/14/85	85-2064	
CCA-11-1-H29	WLDS & DIM NOT ON DWG	11/14/85	85-2065	
CCA-11-1-H26	DIM & MEMBERS NOT PER DWG	11/14/85	85-2067	
CCA-11-1-H32	DIM & SPRING NOT PER DWG	11/14/85	85-2068	
CCA-11-1-H31	BOLTS, DIM, & WLDS NOT PER DWG	11/14/85	85-2069	
CCA-19-1-A3	DIM NOT PER DWG, NUT MISSING	11/14/85	85-2070	
CCA-19-1-H2	DIM NOT ON DWG	11/14/85	85-2071	
CCA-19-1-H18	DIM NOT ON DWG, LOOSE CLAMP	11/14/85	85-2072	
CCA-19-1-H16	DIM NOT ON DWG	11/14/85	85-2073	
CCA-19-1-H20	DIM NOT ON DWG	11/14/85	85-2074	
CCA-11-1-A30	BLTS, WSHRS, DIM, & WLDS NOT PER DWG, MISSING NUT	11/14/85	85-2075	
CCA-19-1-H17	DIM NOT ON DWG	11/14/85	85-2076	

17

DAVIS - BEGGE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 17

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SF NUMBER	DISPOSITION
CCA-19-1-H14	DIM NOT ON DWG	11/13/85	85-2063	
CCA-11-1-H25	DIM NOT ON DWG	11/14/85	85-2064	
CCA-11-1-H29	WLDs & DIM NOT ON DWG	11/14/85	85-2065	
CCA-11-1-H26	DIM & MEMBERS NOT PER DWG	11/14/85	85-2067	
CCA-11-1-H32	DIM & SPRING NOT PER DWG	11/14/85	85-2068	
CCA-11-1-H31	BOLTS, DIM, & WLDs NOT PER DWG	11/14/85	85-2069	
CCA-19-1-A3	DIM NOT PER DWG, NUT MISSING	11/14/85	85-2070	
CCA-19-1-H2	DIM NOT ON DWG	11/14/85	85-2071	
CCA-19-1-H18	DIM NOT ON DWG, LOOSE CLAMP	11/14/85	85-2072	
CCA-19-1-H16	DIM NOT ON DWG	11/14/85	85-2073	
CCA-19-1-H20	DIM NOT ON DWG	11/14/85	85-2074	
CCA-11-1-A30	BLTS, WSHRS, DIM, & WLDs NOT PER DWG, MISSING NUT	11/14/85	85-2075	
CCA-19-1-H17	DIM NOT ON DWG	11/14/85	85-2076	

17