



SAFEGUARDS INFORMATION

JUN 30 2005

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

L-2005-071
10 CFR 50.4(b)(4)
10 CFR 50.54(p)(2)
10 CFR 73.21

Re: Florida Power and Light Company
St. Lucie Units 1 and 2, Docket Nos. 50-335, 50-389
Turkey Point Units 3 and 4, Docket Nos. 50-250, 50-251

FPL Energy Seabrook, LLC
Seabrook Station, Docket No. 50-443

Florida Power and Light Company & FPL Energy Seabrook Physical Security Plan,
Training and Qualification Plan, and Safeguards Contingency Plan – Revision 1

In accordance with 10 CFR 50.4(b)(4), "Security plan and related submissions," and 10 CFR 50.54(p)(2), "Conditions of licenses," Florida Power and Light Company (FPL), the licensee for St. Lucie Nuclear Plant, Units 1 and 2, and Turkey Point Nuclear Plant, Units 3 and 4, and FPL Energy Seabrook, LLC (FPL Energy Seabrook), the licensee for Seabrook Station, hereby submit Revision 1 to the Florida Power and Light Company & FPL Energy Seabrook Physical Security Plan, Training and Qualification Plan and Safeguards Contingency Plan. The effective date of Revision 1 is June 30, 2005.

Florida Power & Light Company and FPL Energy Seabrook have concluded that these changes do not decrease the safeguards effectiveness of the Physical Security Plan, Training and Qualification Plan, and Safeguards Contingency Plan.

One (1) CD-ROM containing Safeguards Information is included in this submission. The CD-ROM labeled "FPL/FPL Energy Seabrook PSP, Revision 1, Safeguards Information" contains the following four (4) files:

- 001 FPL FPL Energy Seabrook Submittal Letter L-2005-071.pdf, SGI – decontrolled upon separation
- 002 FPL FPL Energy Seabrook PSP.pdf, SGI
- 003 Changes to FPL FPL Energy Seabrook PSP.pdf, SGI
- 004 CD Index.pdf (includes individual file size), SGI – decontrolled upon separation

* IES3

SAFEGUARDS INFORMATION

(Enclosure contains Safeguards Information. Upon separation this page is decontrolled.)

SAFEGUARDS INFORMATION

St. Lucie Units 1 and 2, Docket Nos. 50-335 and 50-389
Turkey Point Units 3 and 4, Docket Nos. 50-250 and 50-251
FPL Energy Seabrook Unit 1, Docket No. 50-443
L-2005-071, Page 2

Should you have questions regarding our submittal, please contact Richard Maier, Nuclear Security Manager at (561) 691-7137.

Very truly yours,



J. A. Stall
Senior Vice President, Nuclear
And Chief Nuclear Officer

Enclosure – A single SGI CD-ROM labeled “FPL/FPL Energy Seabrook PSP, Revision 1.

cc: Regional Administrator, Region I (With Enclosure)
Regional Administrator, Region II (With Enclosure)
USNRC Project Manager, St. Lucie and Turkey Point (Without Enclosure)
Senior Resident Inspector, USNRC, St. Lucie (Without Enclosure)
Senior Resident Inspector, USNRC, Turkey Point (Without Enclosure)
USNRC Project Manager, Seabrook Station (Without Enclosure)
Senior Resident Inspector, USNRC, Seabrook Station (Without Enclosure)

SAFEGUARDS INFORMATION

(Enclosure contains safeguards information. Upon separation this page is decontrolled.)