



OHIO HISTORIC INVENTORY

RPR Number:



Form containing fields for: 1. No. LOR-02036-21, 2. County Lorain, 4. Present Name(s) Evans House, 5. Historic or Other Name(s) Russell-Evans House, 6. Specific Address or Location 154 Groveland, 19a. Design Sources, 35. Plan Shape L-shaped, 17. Original/Most significant construct, 17b. Substantial alteration/addition, 37. Window Type(s) 1 over 1, 38. Building Dimensions, 39. Endangered? YES Alterations, 40. Chimney Placement Center, 41. Distance from & Frontage on Road 30', 51. Condition of Property: Good/Fair, 52. Historic Outbuildings & Dependencies Structure Type, Date, Associated Activity, 53. Affiliated Inventory Numbers Historic (OHI) Archaeological (OAI), 42. Further Description of Important Interior and Exterior Features, 43. History and Significance, 44. Description of Environment and Outbuildings, 45. Sources of Information.

LOR-0203
6-21
Lorain
2. County
Evans House
4. Present or Historic Name(s)
154 Groveland
6. Specific Address or Location

1. No. <b>LOR-02036-21</b>	4. Present Name(s) <b>Evans House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s) <b>Russell-Evans House</b>

8. Site Plan with North Arrow

54. Farmstead Plan :



Door Selection:  
**Single off center**

Door Position:  
**Flush**

Orientation:  
**Gable end axis**

Symmetry:  
**Bilateral symmetry**

Report Associated With Project:

NADB #:



1. No. <b>LOR-02036-21</b>	4. Present Name(s) <b>Evans House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s) <b>Russell-Evans House</b>

*42. Further Description of Important Interior and Exterior Features (Con't)*

elevation, towards the front of the house, two 1/1 double hung windows are at the first story. At the second story, 6/6 double hung windows are at the left, while a 1/1 double hung replacement window is to the right. At the east-facing gabled side, a 1/1 double hung window is at the first and second stories, facing both east and south. The east-facing windows do not line up; the lower window is to the right and the upper window is to the left.

*43. History and Significance (Con't)*

(or Sallie) Lee also lived with Eliza Russell in 1920. This home was vacant from 1935-36 and then occupied by the Oberlin Men's Club and Levi Frederic Glenn in 1937. Levi was an African American laborer and employee of Oberlin College. In 1939 Gertrude I. Prinne (nee Spencer) was listed here as well as Mrs. Frances Winfield. Mrs. Prinne was also listed in 1942 along with Robert N. Turner and his wife Geraldine, a domestic. Robert was a garage worker and employee of Oberlin Scrap Metal. It is unclear who resided here from 1943-47. In 1948 Charles L. Cain, a laborer, lived here with his wife Alice. Robert F. Hunter also lived here in 1948 with his wife Elberta M. and their two children. Robert was the pastor of the Oberlin Christian & Missionary Alliance Church. The next known occupants were Cephas M. Clayton and his wife Faythe N. in 1956. Cephas was an employee for Steel & Tube and lived here with their four children. The next known occupants were Metter and Mary Evans in 1970. Metter was a construction worker. The current owner is listed as Mary L. Evans, Trustee.

*44. Description of Environment and Outbuildings (Con't)*

*45. Sources (Con't)*

Staff, (1833-1960).' Oberlin College, 1961.; Lorain County Court House, Auditor Property Record, Internet, <http://www.loraincounty.com/auditor/index.shtml>, Accessed 2008. 'Aunt Julia, Born a Slave,' Oberlin Weekly News, 24 June 24 1914, p. 1; Bigglestone, William E. 'They Stopped in Oberlin.' Oberlin: Oberlin College, 2002.