
The Walled Garden Borthwickshiels, Hawick

Historic Buildings Report

AOC 21382 16th July 2009



Walled Garden, Borthwickshiels, Hawick Historic Buildings Report

P Campbell Fraser Borthwickshiels Hawick Scottish Borders
NT 437 155
21382
Diana Sproat
Diana Sproat

15th July 2009

This document has been prepared in accordance with AOC standard operating procedures.Author: Diana SproatDate: 30th June 2009Approved by: Clare WatsonDate: 15th July 2009Draft/Final Report Stage: Final DraftDate: 16th July 2009

Date of Report:

Enquiries to: AOC Archaeology Group Edgefield Industrial Estate Edgefield Road Loanhead EH20 9SY Tel. 0131 440 3593 Fax. 0131 440 3422 e-mail. admin@aocarchaeology.com



www.aocarchaeology.com

Contents

		Pa	age			
List	of Fig	ures	2			
List	List of Plates					
List	of Ap	pendices	2			
Sum	mary		3			
1	Introduction					
	1.1	Background	4			
	1.2	Site Location	4			
2	Obje	ctives	4			
3	Meth	odology	4			
	3.1	Archive research	4			
	3.3	Architectural appraisal	4			
4	4 Results		4			
	4.1	Historical background	4			
	4.2	Architectural Appraisal	5			
5	Discussion					
6	Recommendations					
7	Refer	rences	6			
	7.1	Bibliographical references	6			
	7.2	Cartographic references	6			
Арр	Appendix 1					
Арр	endix	2	9			

List of Figures

Figure 1: Site location plan Figure 2: Extract from Roy's map 1747-55 Figure 3: Extract from Stobie's map 1770 Figure 4: Extract from Thompson's map 1832 Figure 5: Extract from Tennant's map 1840 Figure 6: Extract from Crawford and Brooke's map 1843 Figure 7: Extract from Mitchell's map 1851 Figure 8: Extract from Ordnance Survey map 1858

List of Plates

- Plate 1: General view of the north wall from the north-west
- Plate 2: Detail of the demolished profile of the north wall
- Plate 3: General view of the exterior (north-facing side) of the north wall
- Plate 4: General view of the east wall from the south-east
- Plate 5: General view of the east wall to the south from the east
- Plate 6: Detail of the entrance in the east wall from the east
- Plate 7: Detail of the finial to the entrance in the east wall
- Plate 8: General view of the west wall from the NEE
- Plate 9: General view of the west wall from the north-east
- Plate 10: Detail of the entrance in the west wall from the east

List of Appendices

Appendix 1: Digital Photographic Register Appendix 2: DES Entry

Summary

A Level 1 building record was required of the walled garden at Borthwickshiels, near Hawick, in the Scottish Borders as a condition of planning permission prior to the erection of a new house within the garden. The garden was probably built in the mid 19th century.

No further historic building recording is recommended.

1 Introduction

1.1 Background

1.1.1 Mr P Campbell Fraser commissioned AOC Archaeology Group to undertake a Level 1 survey of the walled garden at Borthwickshiels, near Hawick, in the Scottish Borders. This work was required as a condition on the planning permission prior to the erection of a new house within the garden, adjacent o the present gardener's cottage.

1.2 Site Location

1.2.1 Borthwickshiels is located to the west of Hawick and is centred on National Grid Reference NT 437 155.

2 Objectives

2.1 The objectives of this survey were to create a permanent record of walled garden prior to the development.

3 Methodology

3.1 Archive research

3.2.1 A simple map regression exercise was undertaken on the site using publicly accessible maps from the National Map Library of Scotland. This allowed the garden to be placed into its historical and functional context. The full collection of historical Ordnance Survey maps was consulted along with all other maps available that pre-date the Ordnance Survey maps.

3.3 Architectural appraisal

3.3.1 An architectural appraisal of the walled garden was undertaken with comment on condition, construction, general form and function and any evidence for phasing or historic and architectural details. This written record was supplemented by black and white print and digital photography, a record of which can be found in Appendix 1 at the end of this report. All photographs were taken using a 35mm SLR camera and a tripod was used where necessary. A 1 m or 2 m ranging pole was used in all shots for scale. A selection of digital photographs has been used to illustrate the report in the form of plates.

4 Results

4.1 Historical background

4.1.1 The present Borthwickshiels House was largely constructed in the 18th century and has undergone a large amount of restoration and remodelling in the 19th and 20th centuries, although the original house may have been much earlier with references to a house as early as the 12th century (*Campbell Fraser pers. Comm.*). It was probably remodelled for Alexander Scott circa 1731 and in 1837 the house was heavily remodelled by John Smith, including the additions of pavilions to the east and west (Cruft et al 2008, 127). Further work

was then undertaken in 1913 by J P Alison and again in 1959 following the discovery of dry rot (*ibid*). The walled garden probably dates to the early-mid 19th century; perhaps at the same time as the 1837 remodelling by John Smith was being undertaken. In 1913, the adjacent gardener's cottage was remodelled by Alison (*ibid*).

- 4.1.2 Cartographically, the house appears on the early maps. It appears on General Roy's Military Map of Scotland dating to 1747-55 (probably its first depiction) and also on Stobie's 1770 map (Figures 2 & 3). It is then also depicted on Thomson's 1832 map and on Tennant's 1840 map (Figures 4 & 5). On the latter, it is annotated as being owned by 'George Pott esq)'. Crawford & Brookes' 1843 map shows the Borthwickshiels estate in detail for the first time, and the walled garden is also depicted (Figure 6). It is shown as it stands today with three sides adjoining a curved hedge to the south side. The 1851 map by Mitchell does not show the walled garden but it serves to illustrate that Borthwickshiels was a large house of significance at this time and it would have required a large garden to complete it (Figure 7).
- 4.1.3 The First Edition Ordnance Survey map of 1858 shows the walled garden in even more detail, marking out the quadrangles of the gardens within the walled area (Figure 8). A small pond has also been added to the west of the walled garden with a small stream leading out of it to the south-east.

4.2 Architectural Appraisal

4.2.1 The walled garden is relatively well-preserved. The north part of the wall is constructed of stone rubble held together with a lime mortar and with a curved concrete coping (a modern addition to protect the wallheads) (Plates 1 – 3). The east wall, however, is drystone construction, reducing in height to the south end of the wall adjacent to the hedge (Plates 4 & 5). There are two entrances in this wall. The southernmost of these has a 1950s upturned baluster which was created to appear like decorative finials to the gate piers (Plates 6 & 7). The west wall is a roughly coursed lime-mortared wall with a small slate pitch and zinc flashings coping, effectively creating a boundary wall to the adjacent gardener's cottage (Plates 8 & 9). A small square-headed entrance leads through to the bottom of the gardener's cottage. The doorway has a replacement concrete lintel and a wrought iron gate which were inserted during the 1950s according to the present owner (Plate 10).

5 Discussion

5.1 The walled garden was probably constructed in the middle of the 19th century and may have coincided with the 1837 renovations undertaken by John Smith. However, the different methods of construction used may suggest it was built in stages or - more likely - the drystone wall was a possible field boundary which was utilised for the purposes of the walled garden when the remainder of it was built.

6 **Recommendations**

6.1 No further historic building recording is recommended.

7 References

7.1 Bibliographical references

Cruft, K, Dunbar, J & Fawcett R 2008 *The Buildings of Scotland: Borders*, Yale University Press: New Haven & London

7.2 Cartographic references

1747-55	General Roy	Military Map of Scotland
1770	Matthew Stobie	A Map of Roxburghshire or Teviotdale
1832	John Thomson	Roxburghshire
1840	N Tennant	Map of the County of Roxburgh
1843	Crawford & Brooke Roxburgh, Berwick, S	Map embracing extensive portions of the Counties of Selkirk & Midlothian and Part of Northumberland.
1851	T Mitchell	Map of the County of Selkirk and District of Melrose
1858	Ordnance Survey	





Figure 1: Site location



AOC Archaeology


Group



(Reproduced by kind permission of the National Map Library of Scotland)



Archaeology Group



(Reproduced by kind permission of the National Map Library of Scotland)

Figure 3: Extract from Stobie's map, 1770

Group



(Reproduced by kind permission of the National Map Library of Scotland)

Figure 4: Extract from Thomson's map, 1832






(Reproduced by kind permission of the National Map Library of Scotland)

Figure 5: Extract from Tennant's map, 1840






(Reproduced by kind permission of the National Map Library of Scotland)

Figure 6: Extract from Crawford and Brooke's map, 1843






(Reproduced by kind permission of the National Map Library of Scotland)

Figure 7: Extract from Mitchell's map, 1851





(Reproduced by kind permission of the National Map Library of Scotland)

Figure 8: Extract from Ordnance Survey map, 1858





Plate 1: General view of the north wall from the north-west



Plate 2: Detail of the demolished profile of the north wall



Plate 3: General view of the exterior (north-facing side) of the north wall



Plate 4: General view of the east wall from the south-east



Plate 5: General view of the east wall to the south from the east



Plate 6: Detail of the doorway in the east wall from the east




Plate 7: Detail of the finial to the doorway in the east wall



Plate 8: General view of the west wall from the NEE



Plate 9: General view of the west wall from the north-east



Plate 10: Detail of the doorway in the west wall from the east

Walled garden, Borthwickshiels, Hawick Appendix 1

Black & White and Colour Digital Photographic record



Detail	Description	From	Date
-	General views of the garden	NW	26/06/09
E Wall	General view	NE	"
N Wall	Detail of the E end	NE	"
N Wall	General view	NE	"
N Wall	Detail of the exterior side	Ν	"
N wall	General view of interior side	SE	"
E Wall	Detail of doorway to N	W	"
E Wall	Detail of doorway to N	E	u
E Wall	Detail of exterior to S by gate	E	"
E Wall	General view	SE	u
E Wall	General view to S	SE	"
E Wall	General view to N	SE	u
E Wall	Detail of doorway	E	u
E Wall	General view to S	NW	u
E Wall	Finial detail to doorway to S	W	"
E Wall	Detail of doorway	W	u
Hedge	General views	NNW	u
W Wall	General view of interior side	NE	u
W Wall	General view of exterior side	W	u
W Wall	Detail of doorway	W	"
W Wall	Detail of doorway	E	"
W Wall	General view of interior side to N		
	- E Wall N Wall N Wall N Wall E Wall Hedge W Wall W Wall W Wall	 General views of the garden E Wall General view N Wall Detail of the E end N Wall General view N Wall Detail of the exterior side N wall General view of interior side E Wall Detail of doorway to N E Wall Detail of doorway to N E Wall Detail of exterior to S by gate E Wall General view E Wall General view to S E Wall General view to N E Wall General view to S E Wall Detail of doorway E Wall Detail of doorway E Wall General view to S E Wall Detail of doorway Hedge General views W Wall General view of interior side W Wall General view of exterior side W Wall Detail of doorway W Wall Detail of doorway W Wall Detail of doorway 	General views of the gardenNWE WallGeneral viewNEN WallDetail of the E endNEN WallGeneral viewNEN WallDetail of the exterior sideNN wallGeneral view of interior sideSEE WallDetail of doorway to NWE WallDetail of doorway to NEE WallDetail of doorway to NEE WallDetail of exterior to S by gateEE WallGeneral viewSEE WallGeneral view to SSEE WallGeneral view to NSEE WallGeneral view to SSEE WallGeneral view to SSEE WallGeneral view to SNWE WallGeneral view to SNWE WallGeneral view to SNWE WallGeneral view to SNWW WallGeneral view of interior sideWW WallGeneral viewsNNWW WallGeneral view of interior sideWW WallGeneral view of exterior sideWW WallGeneral view of exterior sideWW WallDetail of doorwayWW WallDe

The Walled Garden at Borthwickshiels, Hawick Appendix 2

Discovery and Excavation in Scotland (DES) Entry



LOCAL AUTHORITY:	Scottish Borders Council
PROJECT TITLE/SITE NAME	Borthwickshiels
PROJECT CODE:	AOC 21382
PARISH:	Roberton
NAME OF CONTRIBUTOR:	Diana Sproat
NAME OF ORGANISATION:	AOC Archaeology Group
TYPE(S) OF PROJECT:	Historic Building Recording
NMRS NO(S):	None.
SITE/MONUMENT TYPE(S):	None.
SIGNIFICANT FINDS:	None.
NGR (2 letters, 6 figures)	NT 437 155
START DATE (this season)	26 th June 2009
END DATE (this season)	26 th June 2009
PREVIOUS WORK (incl. DES ref.)	None.
MAIN (NARRATIVE) DESCRIPTION: (May include information from other fields)	An historic building recording survey was undertaken of the walled garden within the Borthwickshiels estate near Hawick prior to the erection of a new house within it. The walled garden was probably built in the mid19th century at the same time as the house was remodelled by John Smith.
PROPOSED FUTURE WORK:	None.
CAPTION(S) FOR ILLUSTRS:	None.
SPONSOR OR FUNDING BODY:	P Campbell Fraser
ADDRESS OF MAIN CONTRIBUTOR:	AOC Archaeology Group, Edgefield Road Industrial Estate, Edgefield Road, Loanhead, Midlothian, EH20 9SY
EMAIL ADDRESS:	edinburgh@aocarchaeology.com
ARCHIVE LOCATION (intended/deposited)	Archive to be deposited in NMRS.

